| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CENTURY : VG20 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (3000) | VG20 | 67.11-68.5<br>68.5-69.3<br>69.3-69.8<br>69.8-70.2<br>70.2-73.2 | | | | 67.11-73.2 | 1 | | | CUP | 67.11-73.2 | 7/8 | (R)<br>(L) | | CUP | 67.11-69.9<br>69.9-69.12<br>69.12-73.2 | | | 67.11-73.2 | | | | 67.11-68.8<br>68.8-70.2<br>70.2-73.2 | 13/16<br>7/8 | | CK-3101<br>CK-3105 |
| (3400) | VG21 | 73.3-75.5<br>75.5-77.1 | | | TK-T316<br>TK-T316 | 73.3-77.1 | 1 11/16 | DISC | SP-207 | | 73.3-75.5<br><br>75.5-77.1 | | (R)<br>(L)<br>(R)<br>(L) | | | 73.3-75.5<br><br>75.5-77.1 | (1)<br>(2)<br>(1)BH-T525<br>(2)BH-T526 | BH-94005 | 73.3-74.5<br>74.5- | | (オートマチック) | | 73.3-74.5 | 7/8 | | CK-3105 |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CENTURY : VG30, 40 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (3400) | VG30 | 77.1-78.11 | 15/16 | | TK-T316 | 77.1-78.11 | 1 11/16 | DISC | SP-207 | | 77.1-78.11 | | (R)<br>(L) | | CUP | 77.1-78.11 | (1)BH-T525<br>(2)BH-T526 | BH-94005 | | | (オートマチック) | | | | | |
| | VG35 | 78.11-82.9 | 7/8 | | TK-T317 | 78.11-82.9 | 2 1/4 | DISC | SP-219 | | 78.11-82.9 | 15/16 | (R)WC-50047<br>(L)WC-50047 | WK-309 | CUP | 78.11-82.9 | (1)BH-T525<br>(2)BH-T526 | BH-94005 | | | (オートマチック) | | | | | |
| (4000) | E-VG40・45 | 82.10-87.8<br>87.9-89.5<br>89.5-97.1 | 1<br>1<br>1 | | TK-T030<br>TK-T302<br>TK-T303 | 82.10-92.12<br>92.12-97.1 | 60.3<br>44.4 | DISC<br>DISC | MP-10<br>MP-37 | CPM-10 | 82.10-97.1 | | DISC | | | 82.10-87.8<br><br><br>87.9-92.12<br><br><br>92.12-96.9<br><br><br>96.9-97.1 | (1)BH-95006<br>(2)BH-02163<br><br><br>(1)BH-95006<br>(2)BH-02163<br><br><br>(1)BH-95006<br>(2)<br><br>(1)<br>(2) | (C)BH-31264<br>(R)BH-02343<br>(L)BH-02343<br>(C)BH-94019<br>(R)BH-02343<br>(L)BH-02343<br>(C)BH-94019<br>(R)<br>(L)<br>(C)<br>(R)<br>(L) | | | (オートマチック) | | | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CENTURY : 50, 60 ser.(1997.4-) | | | | | | | | | | | | | | | | | | | | | | | | | |
| (5000) E－GZG50<br>＜GF－は98．11～＞<br>＜TA－は00．4～＞ | 97.4-00.4<br>00.4-17.1 | 1<br>1 | | TK-T407<br>TK-T408 | 97.4-17.1 | 42.8 | DISC | SP-286 | CPS-286 | 97.4-17.1 | 38.1 | DISC | MP-67 | | 97.4-00.4<br>00.4-17.1 | BH-T767 | (R)BH-T755<br>(L)BH-T755<br>(R)BH-T755<br>(L)BH-T755 | | | (オートマチック) | | | | | |
| DAA－UWG60 | 18.6- | | | キットナシ | 18.6- | 1 | DISC | SP-400 | CPS-400 | 18.6- | | MD-453 | SP-402 | CPS-402 | 18.6- | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CELSIOR : 10 ser. | | | | | | | | | | | | | | | | | | | | | | | | | |
| (4000) E－UCF10 | 89.11-92.8 | 1 | | TK-T305 | 89.11-92.8 | 44.4 | DISC | MP-37 | | 89.11-92.8 | 38.1 | DISC | MP-38 | | 89.11-92.8 | BH-T583 | (R)BH-T524 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| E－UCF11 | 92.8-94.10 | 1 1/16 | | TK-T326 | 92.8-94.10 | 44.4 | DISC | MP-47 | | 92.8-94.10 | 40.4 | DISC | MP-54 | | | | (L)BH-T524 | | | | | | | | |
| | | | | | <ｱﾝﾁｽｷｯﾄﾞ無> | | | | | <ｱﾝﾁｽｷｯﾄﾞ無> | | | | | 92.8-94.10 | BH-T583 | (R)BH-T584 | | | | | | | | |
| | | | | | 89.11-92.8 | 44.4 | DISC | MP-37 | | 89.11-92.8 | 38.1 | DISC | MP-38 | | | | (L)BH-T584 | | | | | | | | |
| | | | | | 92.8-94.10 | 44.4 | DISC | MP-47 | | 92.8-94.10 | 40.4 | DISC | MP-54 | | | | | | | | | | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CELSIOR : 20 ser. | | | | | | | | | | | | | | | | | | | | | | | | | |
| (4000) E－UCF20・21<br>＜GF－は98．8～＞ | 94.10-96.8<br>96.8-97.7<br>97.7-00.8 | 1<br>1<br>1 | | TK-T376<br>TK-T407<br>TK-T408 | 94.10-00.8 | 42.8 | DISC | SP-286 | CPS-286 | 94.10-97.7<br>97.7-00.8 | 38.1 | DISC<br>DISC | MP-67<br>MP-66 | | 94.10-97.7<br><br>97.7-00.8 | BH-T658<br><br>BH-T767 | (R)BH-T659<br>(L)BH-T659<br>(R)BH-T755<br>(L)BH-T755 | | | (オートマチック) | | | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CELSIOR : 30 ser. | | | | | | | | | | | | | | | | | | | | | | | | | |
| (4300) UA－UCF30・31 | 00.8-03.7<br>03.7- | | | | 00.8- | | DISC | SP-112 | CPS-112 | 00.8- | | DISC | SP-113 | CPS-112 | 00.8- | BH-T908 | (R)BH-T928<br>(L)BH-T928 | | | (オートマチック) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CROWN : 60, 70 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | (ｻｲｽﾞ確認) | | | | | | | | | | | | | |
| (2000) | RS60 | STD | 71.2-72.10 | 13/16 | | MK-4400 | 71.2-74.9 | 1 1/8 | (R-1)WC-1017 | | CUP | 71.2-74.9 | 3/4 | (R)WC-50033 | WK-043 | CUP | 71.2-73.6 | BH-02220 | BH-31304 | 71.2-72.12 | 3/4 | | RS-31400-M | 71.2-72.12 | 3/4 | CC-70071 | CK-41480 |
| | | | 72.10-74.9 | 15/16 | | TK-9302 | | | (R-2)WC-2016 | | | | | (L)WC-50033 | | | 73.6-74.9 | BH-02220 | BH-02221 | 73.1-74.9 | 3/4 | | | 73.1-73.8 | 3/4 | CC-70073 | CK-3108 |
| | | | | | | | | | (L-1)WC-3017 | | | 74.5-74.9 | 13/16 | (R)WC-50034 | WK-106 | CUP | | | | | | | | 73.8-74.9 | 3/4 | CC-70090 | CK-3108 |
| | | | | | | | | | (L-2)WC-4016 | | | | | (L)WC-50034 | | | | | | | | | | | | | |
| | RS66V(バン) | | 71.2-72.10 | 13/16 | | MK-4400 | 71.2-74.9 | 1 1/8 | (R-1)WC-1017 | | CUP | 71.2-72.10 | 13/16 | (R)WC-50034 | WK-106 | CUP | 71.2-74.9 | BH-02220 | BH-02210 | 71.2-72.12 | 3/4 | | RS-31400-M | 71.2-72.12 | 3/4 | CC-70071 | CK-41480 |
| | | | 72.10-74.9 | 15/16 | | TK-9302 | | | (R-2)WC-2016 | | | | | (L)WC-50034 | | | | | | 73.1-74.9 | 3/4 | | | 73.1-73.8 | 3/4 | CC-70073 | CK-3108 |
| | | | | | | | | | (L-1)WC-3017 | | | 72.10-74.9 | 3/4 | (R)WC-50033 | WK-043 | CUP | | | | | | | | 73.8-74.9 | 3/4 | CC-70090 | CK-3108 |
| | | | | | | | | | (L-2)WC-4016 | | | | | (L)WC-50033 | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | (ｻｲｽﾞ確認) | | | | | | | | | | | | | |
| | MS60 | STD | 71.2-72.10 | 13/16 | | MK-4400 | 71.2-74.9 | 1 1/8 | (R-1)WC-1017 | | CUP | 71.2-74.9 | 3/4 | (R)WC-50033 | WK-043 | CUP | 71.2-73.6 | BH-02220 | BH-31304 | 71.2-72.12 | 3/4 | | RS-31400-M | 71.2-72.12 | 3/4 | CC-22020 | CK-41480 |
| | | | 72.10-74.9 | 15/16 | | TK-9302 | | | (R-2)WC-2016 | | | | | (L)WC-50033 | | | 73.6-74.9 | BH-02220 | BH-02221 | 73.1-74.9 | 3/4 | | | 73.1-74.9 | 3/4 | CC-70091 | CK-3108 |
| | | | | | | | | | (L-1)WC-3017 | | | 74.5-74.9 | 13/16 | (R)WC-50034 | WK-106 | CUP | | | | | | | | | | | |
| | | | | | | | | | (L-2)WC-4016 | | | | | (L)WC-50034 | | | | | | | | | | | | | |
| | | DX･オーナーDX | 71.2-72.12 | 15/16 | | TK-9301 | 71.2-74.9 | 2 1/8 | DISC | SP-212 | | 71.2-74.9 | 3/4 | (R)WC-50033 | WK-043 | CUP | 71.2-73.6 | BH-02220 | BH-31304 | 71.2-72.12 | 3/4 | | RS-31400-M | 71.2-72.12 | 3/4 | CC-22020 | CK-41480 |
| | | | 73.1-74.9 | 15/16 | | TK-9302 | | | | | | | | (L)WC-50033 | | | 73.6-74.9 | BH-02220 | BH-02221 | 73.1-74.9 | 3/4 | | | 73.1-74.9 | 3/4 | CC-70091 | CK-3108 |
| | | スーパーDX | 71.2-72.12 | 15/16 | | TK-9301 | 71.2-74.9 | 2 1/8 | DISC | SP-212 | | 71.2-74.9 | 3/4 | (R)WC-50033 | WK-043 | CUP | 71.2-73.6 | BH-02220 | BH-31304 | 71.2-72.12 | 3/4 | | RS-31400-M | 71.2-72.12 | 3/4 | CC- | CK- |
| | | スーパーサルーン | 73.1-74.9 | 15/16 | | TK-9302 | | | | | | | | (L)WC-50033 | | | 73.6-74.9 | BH-02220 | BH-02221 | 73.1-74.9 | 3/4 | | | 73.1-74.9 | 3/4 | CC-70091 | CK-3108 |
| | | SL | 73.1-74.9 | 15/16 | | TK-9302 | 73.1-74.9 | 2 1/8 | DISC | SP-212 | | 73.1-74.9 | 3/4 | (R)WC-50033 | WK-043 | CUP | 73.1-73.6 | BH-02220 | BH-31304 | 73.1-74.9 | 3/4 | | | 73.1-74.9 | 3/4 | CC-70091 | CK-3108 |
| | | | | | | | | | | | | | | (L)WC-50033 | | | 73.6-74.9 | BH-02220 | BH-02221 | | | | | | | | |
| | MS62(ワゴン) | | 71.2-72.12 | 15/16 | | TK-9301 | 71.2-74.9 | 2 1/8 | DISC | SP-212 | | 71.2-74.9 | 3/4 | (R)WC-50033 | WK-043 | CUP | 71.2-73.6 | BH-02220 | BH-31304 | 71.2-72.12 | 3/4 | | RS-31400-M | 71.2-72.12 | 3/4 | CC-22020 | CK-41480 |
| | | | 73.1-74.9 | 15/16 | | TK-9302 | | | | | | | | (L)WC-50033 | | | 73.6-74.9 | BH-02220 | BH-02221 | 73.1-74.9 | 3/4 | | | 73.1-74.9 | 3/4 | CC-70091 | CK-3108 |
| (2600) | MS65 | DX | 72.4-72.12 | 15/16 | | TK-9301 | 72.4-74.9 | 2 1/8 | DISC | SP-212 | | 72.4-74.9 | 3/4 | (R)WC-50033 | WK-043 | CUP | 72.4-73.6 | BH-02220 | BH-31304 | 72.4-72.12 | 3/4 | | RS-31400-M | 72.4-72.12 | 3/4 | CC-22020 | CK-41480 |
| | | | 73.1-74.9 | 15/16 | | TK-9302 | | | | | | | | (L)WC-50033 | | | 73.6-74.9 | BH-02220 | BH-02221 | 73.1-74.9 | 3/4 | | | 73.1-74.9 | 3/4 | CC-70091 | CK-3108 |
| | | スーパーDX | 71.2-72.12 | 15/16 | | TK-9301 | 71.2-74.9 | 2 1/8 | DISC | SP-212 | | 71.2-74.9 | 3/4 | (R)WC-50033 | WK-043 | CUP | 71.2-73.6 | BH-02220 | BH-31304 | 71.2-72.12 | 3/4 | | RS-31400-M | 71.2-72.12 | 3/4 | CC- | CK- |
| | | スーパーサルーン | 73.1-74.9 | 15/16 | | TK-9302 | | | | | | | | (L)WC-50033 | | | 73.6-74.9 | BH-02220 | BH-02221 | 73.1-74.9 | 3/4 | | | 73.1-74.9 | 3/4 | CC-70091 | CK-3108 |
| (2000) | MS66V(バン) | | 71.2-72.10 | 13/16 | | MK-4400 | 71.2-74.9 | 1 1/8 | (R-1)WC-1017 | | CUP | 71.2-72.10 | 13/16 | (R)WC-50034 | WK-106 | CUP | 71.2-74.9 | BH-02220 | BH-02210 | 71.2-72.12 | 3/4 | | RS-31400-M | 71.2-72.12 | 3/4 | CC-22020 | CK-41480 |
| | | | 72.10-74.9 | 15/16 | | TK-9302 | | | (R-2)WC-2016 | | | | | (L)WC-50034 | | | | | | 73.1-74.9 | 3/4 | | | 73.1-74.9 | 3/4 | CC-70091 | CK-3108 |
| | | | | | | | | | (L-1)WC-3017 | | | 72.10-74.9 | 3/4 | (R)WC-50033 | WK-043 | CUP | | | | | | | | | | | |
| | | | | | | | | | (L-2)WC-4016 | | | | | (L)WC-50033 | | | | | | | | | | | | | |
| (2000) | MS70 | DX･SL | 71.2-72.12 | 15/16 | | TK-9301 | 71.2-74.9 | 2 1/8 | DISC | SP-212 | | 71.2-74.9 | 3/4 | (R)WC-50033 | WK-043 | CUP | 71.2-73.6 | BH-02220 | BH-31304 | 71.2-72.12 | 3/4 | | RS-31400-M | 71.2-72.12 | 3/4 | CC-22020 | CK-41480 |
| | | オーナーDX | 73.1-74.9 | 15/16 | | TK-9302 | | | | | | | | (L)WC-50033 | | | 73.6-74.9 | BH-02220 | BH-02221 | 73.1-74.9 | 3/4 | | | 73.1-74.9 | 3/4 | CC-70091 | CK-3108 |
| | | スーパーDX | 71.2-72.12 | 15/16 | | TK-9301 | 71.2-74.9 | 2 1/8 | DISC | SP-212 | | 71.2-74.9 | 3/4 | (R)WC-50033 | WK-043 | CUP | 71.2-73.6 | BH-02220 | BH-31304 | 71.2-72.12 | 3/4 | | RS-31400-M | 71.2-72.12 | 3/4 | CC- | CK- |
| | | スーパーサルーン | 73.1-74.9 | 15/16 | | TK-9302 | | | | | | | | (L)WC-50033 | | | 73.6-74.9 | BH-02220 | BH-02221 | 73.1-74.9 | 3/4 | | | 73.1-74.9 | 3/4 | CC-70091 | CK-3108 |
| (2600) | MS75 | DX | 72.4-72.12 | 15/16 | | TK-9301 | 72.4-74.9 | 2 1/8 | DISC | SP-212 | | 72.4-74.9 | 3/4 | (R)WC-50033 | WK-043 | CUP | 72.4-73.6 | BH-02220 | BH-31304 | 72.4-72.12 | 3/4 | | RS-31400-M | 72.4-72.12 | 3/4 | CC-22020 | CK-41480 |
| | | | 73.1-74.9 | 15/16 | | TK-9302 | | | | | | | | (L)WC-50033 | | | 73.6-74.9 | BH-02220 | BH-02221 | 73.1-74.9 | 3/4 | | | 73.1-74.9 | 3/4 | CC-70091 | CK-3108 |
| | | スーパーDX | 71.2-72.12 | 15/16 | | TK-9301 | 71.2-74.9 | 2 1/8 | DISC | SP-212 | | 71.2-74.9 | 3/4 | (R)WC-50033 | WK-043 | CUP | 71.2-73.6 | BH-02220 | BH-31304 | 71.2-72.12 | 3/4 | | RS-31400-M | 71.2-72.12 | 3/4 | CC- | CK- |
| | | スーパーサルーン | 73.1-74.9 | 15/16 | | TK-9302 | | | | | | | | (L)WC-50033 | | | 73.6-74.9 | BH-02220 | BH-02221 | 73.1-74.9 | 3/4 | | | 73.1-74.9 | 3/4 | CC-70091 | CK-3108 |

| Models | TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CROWN : 80, 90 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000L. P. G) | RS80 | STD | 7410-7611 | 7/8 | | TK-9337 | 7410-7611 | 1 | (R-1)WC-51002<br>(R-2)WC-52002<br>(L-1)WC-53002<br>(L-2)WC-54002 | WK-307 | CUP | 7410-7611 | 1 | (R)WC-50048<br>(L)WC-50048 | WK-308 | CUP | 74.10-76.11 | BH-02220 | BH-02221 | 7410-7611 | 5/8 | MC-10051 | MK-4300 | 7410-7511<br>7511-7611 | 13/16<br>7/8 | CC-70094<br>CC-70103 | CK-3107<br>CK-3110 |
| | | DX－A | 7511-7611 | 15/16 | | TK-9336 | 7511-7611 | 2 1/8 | DISC | SP-212 | | 7511-7611 | 15/16 | (R)WC-50047<br>(L)WC-50047 | WK-309 | CUP | 75.11-76.11 | BH-02220 | BH-02221 | 7511-7611 | 5/8 | MC-10051 | MK-4300 | 7511-7611 | 7/8 | CC-70103 | CK-3110 |
| (2000) | MS80 | STD | 7410-7611 | 7/8 | | TK-9337 | 7410-7611 | 1 | (R-1)WC-51002<br>(R-2)WC-52002<br>(L-1)WC-53002<br>(L-2)WC-54002 | WK-307 | CUP | 7410-7611 | 1 | (R)WC-50048<br>(L)WC-50048 | WK-308 | CUP | 74.10-76.11 | BH-02220 | BH-02221 | 7410-7611 | 5/8 | MC-10050 | MK-4300 | <フロアシフト車><br>7410-7611<br><コラムシフト車><br>74.10-76.6<br>76.6-76.11 | 3/4<br>3/4<br>13/16 | CC-70091<br>CC-70091<br>CC- | CK-3108<br>CK-3108<br>CK-3113 |
| | | DX・DX－A・スーパーDX<br>スーパーサルーン | 7410-7611 | 15/16 | | TK-9336 | 7410-7611 | 2 1/8 | DISC | SP-212 | | 7410-7611 | 15/16 | (R)WC-50047<br>(L)WC-50047 | WK-309 | CUP | 74.10-76.11 | BH-02220 | BH-02221 | 7410-7611 | 5/8 | MC-10050 | MK-4300 | <フロアシフト車><br>7410-7611<br><コラムシフト車><br>74.10-76.6<br>76.6-76.11 | 3/4<br>3/4<br>13/16 | CC-70091<br>CC-70091<br>CC- | CK-3108<br>CK-3108<br>CK-3113 |
| (2000)<br>(2600) | MS82<br>MS83 | DX | 75.1-76.11 | 15/16 | | TK-9336 | 75.1-76.11 | 2 1/8 | DISC | SP-212 | | 75.1-76.11 | 15/16 | (R)WC-50047<br>(L)WC-50047 | WK-309 | CUP | 75.1-76.11 | BH-02220 | BH-02221 | 75.1-76.11 | 5/8 | MC-10050 | MK-4300 | <フロアシフト車><br>75.1-76.11<br><コラムシフト車><br>75.1-76.6<br>76.6-76.11 | 3/4<br>3/4<br>13/16 | CC-70091<br>CC-70091<br>CC- | CK-3108<br>CK-3108<br>CK-3113 |
| (2600) | MS85 | スーパーサルーン | 7410-7611 | 15/16 | | TK-9336 | 7410-7611 | 2 1/8 | DISC | SP-212 | | 7410-7611 | 15/16 | (R)WC-50047<br>(L)WC-50047 | WK-309 | CUP | 74.10-76.11 | BH-02220 | BH-02221 | 7410-7611 | 5/8 | MC-10050 | MK-4300 | 74.10-76.6<br>76.6-76.11 | 3/4<br>13/16 | CC-70091<br>CC- | CK-3108<br>CK-3113 |
| | | ロイヤルサルーン | 7410-7511<br>7511-7611 | 7/8<br>7/8 | | TK-9337<br>TK-9350 | 7410-7611 | | DISC | SP-217 | CPS-217+CPS-217B | 7410-7611 | 1 11/16 | DISC | SP-218 | | 74.10-76.11 | BH-02220 | (C)BH-02221<br>(R)BH-T822<br>(L)BH-T822 | | | (オートマチック) | | | | | |
| (2000) | MS87V（バン） | STD・DX・スーパーDX | 75.1-76.11<br>76.11-78.2<br>78.2-79.8 | 7/8<br>7/8<br>7/8 | | TK-9337<br>TK-9356<br>TK-9381 | 75.1-78.2<br><br><br><br>78.2-79.8 | 1<br><br><br><br>2 1/4 | (R-1)WC-51002<br>(R-2)WC-52002<br>(L-1)WC-53002<br>(L-2)WC-54002<br>DISC | WK-307<br><br><br><br>SP-219 | CUP | 75.1-78.2<br><br>78.2-79.8 | 1<br><br>7/8 | (R)WC-50048<br>(L)WC-50048<br>(R)WC-50054<br>(L)WC-50054 | WK-308<br><br>WK-405 | CUP<br><br>CUP | 75.1-78.2<br><br>78.2-79.8 | BH-02220<br><br>BH-02360 | BH-02210<br><br>BH-02210 | 75.1-79.8 | 5/8 | MC-10050 | MK-4300 | <フロアシフト車><br>75.1-76.11<br>76.11-78.2<br>78.2-79.8<br><コラムシフト車><br>75.1-76.6<br>76.6-79.8 | 3/4<br>13/16<br>13/16<br>3/4<br>13/16 | CC-70091<br>CC-70106<br>CC-70112<br>CC-70091<br>CC- | CK-3108<br>CK-3113<br>CK-3113<br>CK-3108<br>CK-3113 |
| (2000)<br>(2600) | MS90<br>MS95 | DX・スーパーDX | 7410-7611 | 15/16 | | TK-9336 | 7410-7611 | 2 1/8 | DISC | SP-212 | | 7410-7611 | 15/16 | (R)WC-50047<br>(L)WC-50047 | WK-309 | CUP | 74.10-76.11 | BH-02220 | BH-02221 | 7410-7611 | 5/8 | MC-10050 | MK-4300 | <フロアシフト車><br>7410-7611<br><コラムシフト車><br>74.12-76.6<br>76.6-76.11 | 3/4<br>3/4<br>13/16 | CC-70091<br>CC-70091<br>CC- | CK-3108<br>CK-3108<br>CK-3113 |
| | | スーパーサルーン（コラムシフト） | 7410-7611 | 15/16 | | TK-9336 | 7410-7611 | 2 1/8 | DISC | SP-212 | | 7410-7611 | 15/16 | (R)WC-50047<br>(L)WC-50047 | WK-309 | CUP | 74.10-76.11 | BH-02220 | BH-02221 | 7410-7611 | 5/8 | MC-10050 | MK-4300 | 74.12-76.6<br>76.6-76.11 | 3/4<br>13/16 | CC-70091<br>CC- | CK-3108<br>CK-3113 |
| | | スーパーサルーン（フロアシフト） | 7410-7611 | 15/16 | | TK-9336 | 7410-7611 | | DISC | SP-217 | CPS-217+CPS-217B | 7410-7611 | 15/16 | (R)WC-50047<br>(L)WC-50047 | WK-309 | CUP | 74.10-76.11 | BH-02220 | BH-02221 | 7410-7611 | 5/8 | MC-10050 | MK-4300 | 7410-7611 | 3/4 | CC-70091 | CK-3108 |

| Models | TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CROWN : 100 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000L. P. G) | RS100<br>RS105 | STD | 76.11-79.8 | 7/8 | | TK-9356 | 76.11-79.8 | 1 | (R-1)WC-51002<br>(R-2)WC-52002<br>(L-1)WC-53002<br>(L-2)WC-54002 | WK-307 | CUP | 76.11-79.8 | 1 | (R)WC-50048<br>(L)WC-50048 | WK-308 | CUP | 76.11-78.2<br>78.2-79.8 | BH-02220<br>BH-02361 | BH-02221<br>BH-02221 | 76.11-79.8 | 5/8 | MC-10051 | MK-4300 | 76.11-79.8 | 7/8 | CC-70103 | CK-3110 |
| | | DX・DX－A | 76.11-78.2<br>78.2-79.8 | 15/16<br>7/8 | | TK-9336<br>TK-9381 | 76.11-78.2<br>78.2-79.8 | 2 1/8<br>2 1/4 | DISC<br>DISC | SP-212<br>SP-219 | | 76.11-78.2<br>78.2-79.8 | 15/16<br>7/8 | (R)WC-50047<br>(L)WC-50047<br>(R)WC-50054<br>(L)WC-50054 | WK-309<br>WK-405 | CUP<br>CUP | 76.11-78.2<br>78.2-79.8 | BH-02220<br>BH-02360 | BH-02221<br>BH-02221 | 76.11-79.8 | 5/8 | MC-10051 | MK-4300 | 76.11-79.8 | 7/8 | CC-70103 | CK-3110 |
| (2000) | MS100 | STD | 76.11-79.3 | 7/8 | | TK-9356 | 76.11-79.3 | 1 | (R-1)WC-51002<br>(R-2)WC-52002<br>(L-1)WC-53002<br>(L-2)WC-54002 | WK-307 | CUP | 76.11-79.3 | 1 | (R)WC-50048<br>(L)WC-50048 | WK-308 | CUP | 76.11-78.2<br>78.2-79.3 | BH-02220<br>BH-02361 | BH-02221<br>BH-02221 | 76.11-79.3 | 5/8 | MC-10050 | MK-4300 | <コラムシフト車><br>76.11-79.3<br><フロアシフト車><br>78.2-79.3 | 13/16<br><br>13/16 | CC-<br><br>CC-70112 | CK-3113<br><br>CK-3113 |
| | | DX・DX－A<br>スーパーDX | 76.6-78.2<br>78.2-79.3 | 15/16<br>7/8 | | TK-9336<br>TK-9381 | 76.6-78.2<br>78.2-79.3 | 2 1/8<br>2 1/4 | DISC<br>DISC | SP-212<br>SP-219 | | 76.6-78.2<br>78.2-79.3 | 15/16<br>7/8 | (R)WC-50047<br>(L)WC-50047<br>(R)WC-50054<br>(L)WC-50054 | WK-309<br>WK-405 | CUP<br>CUP | 76.6-78.2<br>78.2-79.3 | BH-02220<br>BH-02360 | BH-02221<br>BH-02221 | 76.6-79.3<br><LPG車><br>78.2-79.3 | 5/8<br><br>5/8 | MC-10050<br><br>MC-10073 | MK-4300<br><br>MK-4300 | <コラムシフト車><br>76.11-79.3<br><フロアシフト車><br>76.6-76.11<br>76.11-78.2<br>78.2-79.3<br><LPG車><br>78.2-79.3 | 13/16<br><br>3/4<br>13/16<br>13/16<br><br>7/8 | CC-<br><br>CC-70091<br>CC-70106<br>CC-70112<br><br>CC-70114 | CK-3113<br><br>CK-3108<br>CK-3113<br>CK-3113<br><br>CK-3114 |
| | | スーパーサルーン（リヤードラム） | 76.6-78.2 | 15/16 | | TK-9336 | 76.6-78.2<br><ハードトップ フロアシフト車><br>76.6-78.2 | 2 1/8<br><br>DISC | DISC<br><br>SP-217 | SP-212<br><br>CPS-217+CPS-217B | | 76.6-78.2 | 15/16 | (R)WC-50047<br>(L)WC-50047 | WK-309 | CUP | 76.6-78.2 | BH-02220 | BH-02221 | 76.6-78.2 | 5/8 | MC-10050 | MK-4300 | <コラムシフト車><br>76.6-78.2<br><フロアシフト車><br>76.6-76.11<br>76.11-78.2 | 13/16<br><br>3/4<br>13/16 | CC-<br><br>CC-70091<br>CC-70106 | CK-3113<br><br>CK-3108<br>CK-3113 |
| | | スーパーサルーン（四輪ディスク） | 76.11-78.2<br>78.2-79.3 | 7/8<br>7/8 | | TK-9355<br>TK-9383 | 76.11-78.2<br>78.2-79.3 | <br>2 1/4 | DISC<br>DISC | SP-217<br>SP-219 | CPS-217+CPS-217B | 76.11-79.3 | 1 11/16 | DISC | SP-218 | | 76.11-78.2<br><br>78.2-79.3 | BH-02220<br><br>BH-02360 | (C)BH-02221<br>(R)BH-T822<br>(L)BH-T822<br>(C)BH-02221<br>(R)BH-T822<br>(L)BH-T822 | 76.11-79.3 | 5/8 | MC-10050 | MK-4300 | <コラムシフト車><br>76.11-78.2<br><フロアシフト車><br>76.11-78.2<br>78.2-79.3 | 13/16<br><br>13/16<br>13/16 | CC-<br><br>CC-70106<br>CC-70112 | CK-3113<br><br>CK-3113<br>CK-3113 |
| (2600) | MS101 | スーパーサルーン（リヤードラム） | 76.11-78.2 | 15/16 | | TK-9336 | 76.11-78.2 | 2 1/8 | DISC | SP-212 | | 76.11-78.2 | 15/16 | (R)WC-50047<br>(L)WC-50047 | WK-309 | CUP | 76.11-78.2 | BH-02220 | BH-02221 | 76.11-78.2 | 5/8 | MC-10050 | MK-4300 | 76.11-78.2 | 13/16 | CC-70106 | CK-3113 |
| | | スーパーサルーン（四輪ディスク） | 76.11-78.2 | 7/8 | | TK-9355 | 76.11-78.2 | | DISC | SP-217 | CPS-217+CPS-217B | 76.11-78.2 | 1 11/16 | DISC | SP-218 | | 76.11-78.2 | BH-02220 | (C)BH-02221<br>(R)BH-T822<br>(L)BH-T822 | 76.11-78.2 | 5/8 | MC-10050 | MK-4300 | 76.11-78.2 | 13/16 | CC-70106 | CK-3113 |
| | | ロイヤルサルーン | 76.11-78.2<br>78.2-79.3 | 7/8<br>7/8 | | TK-9355<br>TK-9383 | 76.11-78.2<br>78.2-79.3 | <br>2 1/4 | DISC<br>DISC | SP-217<br>SP-219 | CPS-217+CPS-217B | 76.11-79.3 | 1 11/16 | DISC | SP-218 | | 76.11-78.2<br><br>78.2-79.3 | BH-02220<br><br>BH-02360 | (C)BH-02221<br>(R)BH-T822<br>(L)BH-T822<br>(C)BH-02221<br>(R)BH-T822<br>(L)BH-T822 | 76.11-78.2<br>78.2-79.3 | 5/8 | MC-10050<br>(オートマチック) | MK-4300 | 76.11-78.2 | 13/16 | CC-70106 | CK-3113 |
| (2000)<br>(2600) | MS102<br>MS107<br>MS103 | | 76.11-78.2<br>78.2-79.8 | 15/16<br>7/8 | | TK-9336<br>TK-9381 | 76.11-78.2<br>78.2-79.8 | 2 1/8<br>2 1/4 | DISC<br>DISC | SP-212<br>SP-219 | | 76.11-78.2<br><br>78.2-79.8 | 15/16<br><br>7/8 | (R)WC-50047<br>(L)WC-50047<br>(R)WC-50054<br>(L)WC-50054 | WK-309<br>WK-405 | CUP<br>CUP | 76.11-78.2<br>78.2-79.8 | BH-02220<br>BH-02360 | BH-02221<br>BH-02221 | 76.11-79.8 | 5/8 | MC-10050 | MK-4300 | <コラムシフト車><br>76.11-79.8<br><フロアシフト車><br>76.11-78.2<br>78.2-79.8 | 13/16<br><br>13/16<br>13/16 | CC-<br><br>CC-70106<br>CC-70112 | CK-3113<br><br>CK-3113<br>CK-3113 |
| (2000) | MS105 | STD | 79.3-79.8 | 7/8 | | TK-9356 | 79.3-79.8 | 1 | (R-1)WC-51002<br>(R-2)WC-52002<br>(L-1)WC-53002<br>(L-2)WC-54002 | WK-307 | CUP | 79.3-79.8 | 1 | (R)WC-50048<br>(L)WC-50048 | WK-308 | CUP | 79.3-79.8 | BH-02361 | BH-02221 | 79.3-79.8 | 5/8 | MC-10050 | MK-4300 | <コラムシフト車><br>79.3-79.8<br><フロアシフト車><br>79.3-79.8 | 13/16<br><br>13/16 | CC-<br><br>CC-70112 | CK-3113<br><br>CK-3113 |
| | | DX・DX－A<br>スーパーDX | 77.7-78.2<br>78.2-79.8 | 15/16<br>7/8 | | TK-9336<br>TK-9381 | 77.7-78.2<br>78.2-79.8 | 2 1/8<br>2 1/4 | DISC<br>DISC | SP-212<br>SP-219 | | 77.7-78.2<br><br>78.2-79.8 | 15/16<br><br>7/8 | (R)WC-50047<br>(L)WC-50047<br>(R)WC-50054<br>(L)WC-50054 | WK-309<br>WK-405 | CUP<br>CUP | 77.7-78.2<br>78.2-79.8 | BH-02220<br>BH-02360 | BH-02221<br>BH-02221 | 77.7-79.8 | 5/8 | MC-10050 | MK-4300 | <コラムシフト車><br>77.7-79.8<br><フロアシフト車><br>77.7-78.2<br>78.2-79.8 | 13/16<br><br>13/16<br>13/16 | CC-<br><br>CC-70106<br>CC-70112 | CK-3113<br><br>CK-3113<br>CK-3113 |
| (2000) | MS105 | スーパーサルーン（リヤードラム） | 77.7-78.2<br>78.2-79.8 | 15/16<br>7/8 | | TK-9336<br>TK-9383 | 77.7-78.2<br>78.2-79.8 | 2 1/8<br>2 1/4 | DISC<br>DISC | SP-212<br>SP-219 | | 77.7-78.2<br><br>78.2-79.8 | 15/16<br><br>1 11/16 | (R)WC-50047<br>(L)WC-50047<br>DISC | WK-309<br><br>SP-218 | CUP | 77.7-78.2<br>78.2-79.8 | BH-02220<br>BH-02360 | BH-02221<br>(C)BH-02221<br>(R)BH-T822<br>(L)BH-T822 | 77.7-79.8 | 5/8 | MC-10050 | MK-4300 | <コラムシフト車><br>77.7-79.8<br><フロアシフト車><br>77.7-78.2<br>78.2-79.8 | 13/16<br><br>13/16<br> | CC-<br><br>CC-70106<br>CC-70112 | CK-3113<br><br>CK-3113<br> |
| | | スーパーサルーン（四輪ディスク） | 77.7-78.2<br>78.2-79.8 | 7/8<br>7/8 | | TK-9355<br>TK-9383 | 77.7-78.2<br>78.2-79.8 | <br>2 1/4 | DISC<br>DISC | SP-217<br>SP-219 | CPS-217+CPS-217B | 77.7-79.8 | 1 11/16 | DISC | SP-218 | | 77.7-78.2<br><br>78.2-79.8 | BH-02220<br><br>BH-02360 | (C)BH-02221<br>(R)BH-T822<br>(L)BH-T822<br>(C)BH-02221<br>(R)BH-T822<br>(L)BH-T822 | 77.7-79.8 | 5/8 | MC-10050 | MK-4300 | <コラムシフト車><br>77.7-79.8<br><フロアシフト車><br>77.7-78.2<br>78.2-79.8 | 13/16<br><br>13/16<br>13/16 | CC-<br><br>CC-70106<br>CC-70112 | CK-3113<br><br>CK-3113<br>CK-3113 |

| Models | TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| (2600) | MS106 | スーパーサルーン<br>ロイヤルサルーン | 78.2-79.8 | 7/8 | | TK-9383 | 78.2-79.8 | 2 1/4 | DISC | SP-219 | | 78.2-79.8 | 1 11/16 | DISC | SP-218 | | 78.2-79.8 | BH-02360 | (C)BH-02221<br>(R)BH-T822<br>(L)BH-T822 | 78.2-79.8 | 5/8 | MC-10050 | MK-4300 | 78.2-79.8 | 13/16 | CC-70112 | CK-3113 |
| (2200ディーゼル) | LS100 | STD | 77.10-79.8 | 7/8 | | TK-9356 | 77.10-79.8 | 1 | (R-1)WC-51002<br>(R-2)WC-52002<br>(L-1)WC-53002<br>(L-2)WC-54002 | WK-307 | CUP | 77.10-79.8 | 1 | (R)WC-50048<br>(L)WC-50048 | WK-308 | CUP | 77.10-78.2<br>78.2-79.8 | BH-02220<br>BH-02361 | BH-02221<br>BH-02221 | 77.10-78.1<br>78.1-79.8 | 5/8<br>5/8 | MC-10072 | MK-4300<br>MK-4300 | 77.10-79.8 | 7/8 | CC-70119 | CK-3110 |
| | | DX・DXーA<br>スーパーDX | 77.10-78.2<br>78.2-79.8 | 15/16<br>7/8 | | TK-9336<br>TK-9381 | 77.10-78.2<br>78.2-79.8 | 2 1/8<br>2 1/4 | DISC<br>DISC | SP-212<br>SP-219 | | 77.10-78.2<br>78.2-79.8 | 15/16<br>7/8 | (R)WC-50047<br>(L)WC-50047<br>(R)WC-50054<br>(L)WC-50054 | WK-309<br>WK-405 | CUP<br>CUP | 77.10-78.2<br>78.2-79.8 | BH-02220<br>BH-02360 | BH-02221<br>BH-02221 | 77.10-78.1<br>78.1-79.8 | 5/8<br>5/8 | MC-10072 | MK-4300<br>MK-4300 | 77.10-79.8 | 7/8 | CC-70119 | CK-3110 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CROWN : 110 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000L. P. G) | RS110 | STD・タクシー | 79.9-83.7 | 7/8 | | TK-9405 | 79.9-83.7 | 1 | (R-1)WC-51002<br>(R-2)WC-52002<br>(L-1)WC-53002<br>(L-2)WC-54002 | WK-307 | CUP | 79.9-83.7 | 1 | (R)WC-50048<br>(L)WC-50048 | WK-308 | CUP | 79.9-83.7 | BH-02361 | BH-02394 | 79.9-83.7 | 5/8 | MC-10091 | MK-4300 | 79.9-80.10<br>80.10-83.6<br>83.6-83.7 | 7/8<br>7/8<br>13/16 | CC-70123<br>CC-70127<br>CC-70145 | CK-3110<br>CK-3122<br>CK-3144 |
| | | DX・DX－A | 79.9-83.7 | 7/8 | | TK-9403 | 79.9-83.7 | 2 1/4 | DISC | SP-219 | CPS-219 | 79.9-83.7 | 7/8 | (R)WC-50054<br>(L)WC-50054 | WK-405 | CUP | 79.9-83.7 | BH-02360 | BH-02394 | 79.9-83.7 | 5/8 | MC-10091 | MK-4300 | 79.9-80.10<br>80.10-83.6<br>83.6-83.7 | 7/8<br>7/8<br>13/16 | CC-70123<br>CC-70127<br>CC-70145 | CK-3110<br>CK-3122<br>CK-3144 |
| (2000) | GS110<br>GS110G(ワゴン) | DX・スーパーDX<br>カスタムエディション<br>スーパーエディション | 81.8-83.7 | 7/8 | | TK-9403 | 81.8-83.7 | 2 1/4 | DISC | SP-219 | CPS-219 | 81.8-83.7 | 7/8 | (R)WC-50054<br>(L)WC-50054 | WK-405 | CUP | 81.8-83.7 | BH-02360 | BH-02394 | 81.8-83.7 | 5/8 | MC-10072 | MK-4300 | 81.8-83.7 | 13/16 | CC-70133 | CK-3144 |
| | | スーパーサルーン | 81.8-83.7 | 7/8 | | TK-9409 | 81.8-83.7 | 2 1/4 | DISC | SP-219 | CPS-219 | 81.8-83.7 | 1 11/16 | DISC | SP-218 | | 81.8-83.7 | BH-02360 | (C)BH-02394<br>(R)BH-02343<br>(L)BH-02343 | 81.8-83.7 | 5/8 | MC-10072 | MK-4300 | 81.8-83.7 | 13/16 | CC-70133 | CK-3144 |
| | GS117V(バン) | STD・DX<br>スーパーDX | 82.8-83.7 | 7/8 | | TK-9403 | 82.8-83.7 | 2 1/4 | DISC | SP-219 | CPS-219 | 82.8-83.7 | 7/8 | (R)WC-50054<br>(L)WC-50054 | WK-405 | CUP | 82.8-83.7 | BH-02360 | BH-02210 | 82.8-83.7 | 5/8 | MC-10072 | MK-4300 | 82.8-83.7 | 13/16 | CC-70133 | CK-3144 |
| | MS110 | STD | 79.9-83.7 | 7/8 | | TK-9405 | 79.9-83.7 | 1 | (R-1)WC-51002<br>(R-2)WC-52002<br>(L-1)WC-53002<br>(L-2)WC-54002 | WK-307 | CUP | 79.9-83.7 | 1 | (R)WC-50048<br>(L)WC-50048 | WK-308 | CUP | 79.9-83.7 | BH-02361 | BH-02394 | 79.9-83.7 | 5/8 | MC-10090 | MK-4300 | <フロアシフト車><br>79.9-80.12<br>80.12-81.8<br>81.8-83.7<br><コラムシフト車><br>79.9-80.10<br>80.10-83.7 | <br>13/16<br>13/16<br>13/16<br><br>13/16<br>13/16 | <br>CC-70112<br>CC-70112<br>CC-70133<br><br>CC-70106<br>CC-70133 | <br>CK-3113<br>CK-3144<br>CK-3144<br><br>CK-3113<br>CK-3144 |
| | MS110<br>MS110G(ワゴン) | DX・DX－A・スーパーDX<br>カスタムエディション<br>スーパーエディション | 79.9-83.7 | 7/8 | | TK-9403 | 79.9-83.7 | 2 1/4 | DISC | SP-219 | CPS-219 | 79.9-83.7 | 7/8 | (R)WC-50054<br>(L)WC-50054 | WK-405 | CUP | 79.9-83.7 | BH-02360 | BH-02394 | 79.9-83.7 | 5/8 | MC-10090 | MK-4300 | <フロアシフト車><br>79.9-80.12<br>80.12-81.8<br>81.8-83.7<br><コラムシフト車><br>79.9-80.10<br>80.10-83.7 | <br>13/16<br>13/16<br>13/16<br><br>13/16<br>13/16 | <br>CC-70112<br>CC-70112<br>CC-70133<br><br>CC-70106<br>CC-70133 | <br>CK-3113<br>CK-3144<br>CK-3144<br><br>CK-3113<br>CK-3144 |
| (2000) | MS110 | スーパーサルーン | 79.9-81.8 | 7/8 | | TK-9409 | 79.9-81.8 | 2 1/4 | DISC | SP-219 | CPS-219 | 79.9-81.8 | 1 11/16 | DISC | SP-218 | | 79.9-81.8 | BH-02360 | (C)BH-02394<br>(R)BH-02343<br>(L)BH-02343 | 79.9-81.8 | 5/8 | MC-10090 | MK-4300 | <フロアシフト車><br>79.9-80.12<br>80.12-81.8<br><コラムシフト車><br>79.9-80.10<br>80.10-81.8 | <br>13/16<br>13/16<br><br>13/16<br>13/16 | <br>CC-70112<br>CC-70112<br><br>CC-70106<br>CC-70133 | <br>CK-3113<br>CK-3144<br><br>CK-3113<br>CK-3144 |
| | | スーパーエディション(ターボ)<br>スーパーサルーン(ターボ) | 80.10-83.7 | 7/8 | | TK-9409 | 80.10-83.7 | 2 1/4 | DISC | SP-219 | CPS-219 | 80.10-83.7 | 1 11/16 | DISC | SP-218 | | 80.10-83.7 | BH-02360 | (C)BH-02394<br>(R)BH-02343<br>(L)BH-02343 | | | (オートマチック) | | | | | |
| (2000L. P. G) | MS110 | DX・DX－A | 79.12-83.7 | 7/8 | | TK-9403 | 79.12-83.7 | 2 1/4 | DISC | SP-219 | CPS-219 | 79.12-83.7 | 7/8 | (R)WC-50054<br>(L)WC-50054 | WK-405 | CUP | 79.12-83.7 | BH-02360 | BH-02394 | 79.12-83.7 | 5/8 | MC-10090 | MK-4300 | 7912-8010<br>80.10-83.7 | 13/16<br>13/16 | CC-70106<br>CC-70133 | CK-3113<br>CK-3144 |
| (2800) | MS112 | スーパーサルーン | 79.9-81.8 | 7/8 | | TK-9409 | 79.9-81.8 | 2 1/4 | DISC | SP-219 | CPS-219 | 79.9-81.8 | 1 11/16 | DISC | SP-218 | | 79.9-81.8 | BH-02360 | (C)BH-02394<br>(R)BH-02343<br>(L)BH-02343 | | | (オートマチック) | | | | | |
| | | ロイヤルサルーン | 79.9-83.7 | 7/8 | | TK-9409 | 79.9-83.7 | 2 1/4 | DISC | SP-219 | CPS-219 | 79.9-83.7 | 1 11/16 | DISC | SP-218 | | 79.9-83.7 | BH-02360 | (C)BH-02394<br>(R)BH-02343<br>(L)BH-02343 | 79.9-81.8<br>81.8-83.7 | 5/8 | MC-10090<br>(オートマチック) | MK-4300 | 79.9-80.12<br>80.12-81.8 | 13/16<br>13/16 | CC-70112<br>CC-70112 | CK-3113<br>CK-3144 |
| (2000) | MS117V(バン) | STD・DX<br>スーパーDX | 79.9-82.8 | 7/8 | | TK-9403 | 79.9-82.8 | 2 1/4 | DISC | SP-219 | CPS-219 | 79.9-82.8 | 7/8 | (R)WC-50054<br>(L)WC-50054 | WK-405 | CUP | 79.9-82.8 | BH-02360 | BH-02210 | 79.9-82.8 | 5/8 | MC-10090 | MK-4300 | <フロアシフト車><br>79.9-80.12<br>80.12-81.8<br>81.8-82.8<br><コラムシフト車><br>79.9-80.10<br>80.10-82.8 | <br>13/16<br>13/16<br>13/16<br><br>13/16<br>13/16 | <br>CC-70112<br>CC-70112<br>CC-70133<br><br>CC-70106<br>CC-70133 | <br>CK-3113<br>CK-3144<br>CK-3144<br><br>CK-3113<br>CK-3144 |
| (2200ディーゼル) | LS110 | STD | 79.9-83.7 | 7/8 | | TK-9405 | 79.9-83.7 | 1 | (R-1)WC-51002<br>(R-2)WC-52002<br>(L-1)WC-53002<br>(L-2)WC-54002 | WK-307 | CUP | 79.9-83.7 | 1 | (R)WC-50048<br>(L)WC-50048 | WK-308 | CUP | 79.9-83.7 | BH-02361 | BH-02394 | 79.9-83.7 | 5/8 | MC-10072 | MK-4300 | <フロアシフト車><br>79.9-80.12<br>80.12-81.8<br>81.8-83.7<br><コラムシフト車><br>79.9-80.10<br>80.10-81.8<br>81.8-83.7 | <br>7/8<br>7/8<br>7/8<br><br>7/8<br>7/8<br>7/8 | <br>CC-70124<br>CC-70124<br>CC-70134<br><br>CC-70124<br>CC-70134<br>CC-70134 | <br>CK-3110<br>CK-3121<br>CK-3122<br><br>CK-3110<br>CK-3110<br>CK-3122 |
| | | タクシー | 79.9-83.7 | 7/8 | | TK-9405 | 79.9-83.7 | 1 | (R-1)WC-51002<br>(R-2)WC-52002<br>(L-1)WC-53002<br>(L-2)WC-54002 | WK-307 | CUP | 79.9-83.7 | 1 | (R)WC-50048<br>(L)WC-50048 | WK-308 | CUP | 79.9-83.7 | BH-02361 | BH-02394 | 79.9-83.7 | 5/8 | MC-10072 | MK-4300 | 79.9-80.10<br>80.10-81.8<br>81.8-83.7 | 7/8<br>7/8<br>7/8 | CC-70124<br>CC-70134<br>CC-70134 | CK-3110<br>CK-3110<br>CK-3122 |

| Models | TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | | | | | | | | | | | | | | | <フロアシフト車> | | | |
| (2200ディーゼル LS110 | DX・DX－A | 79.9-83.7 | 7/8 | | TK-9403 | 79.9-83.7 | 2 1/4 | DISC | SP-219 | CPS-219 | 79.9-83.7 | 7/8 | (R)WC-50054 | WK-405 | CUP | 79.9-83.7 | BH-02360 | BH-02394 | 79.9-83.7 | 5/8 | MC-10072 | MK-4300 | 79.9-80.12 | 7/8 | CC-70124 | CK-3110 |
| LS110G(ワゴン) | スーパーDX | | | | | | | | | | | | (L)WC-50054 | | | | | | | | | | 80.12-81.8 | 7/8 | CC-70124 | CK-3121 |
| | | | | | | | | | | | | | | | | | | | | | | | 81.8-83.7 | 7/8 | CC-70134 | CK-3122 |
| | | | | | | | | | | | | | | | | | | | | | | | <コラムシフト車> | | | |
| | | | | | | | | | | | | | | | | | | | | | | | 79.9-80.10 | 7/8 | CC-70124 | CK-3110 |
| | | | | | | | | | | | | | | | | | | | | | | | 80.10-81.8 | 7/8 | CC-70134 | CK-3110 |
| | | | | | | | | | | | | | | | | | | | | | | | 81.8-83.7 | 7/8 | CC-70134 | CK-3122 |
| | カスタムエディション | 79.9-83.7 | 7/8 | | TK-9403 | 79.9-83.7 | 2 1/4 | DISC | SP-219 | CPS-219 | 79.9-83.7 | 7/8 | (R)WC-50054 | WK-405 | CUP | 79.9-83.7 | BH-02360 | BH-02394 | 79.9-83.7 | 5/8 | MC-10072 | MK-4300 | 79.9-80.12 | 7/8 | CC-70124 | CK-3110 |
| | スーパーエディション | | | | | | | | | | | | (L)WC-50054 | | | | | | | | | | 80.12-81.8 | 7/8 | CC-70124 | CK-3121 |
| | | | | | | | | | | | | | | | | | | | | | | | 81.8-83.7 | 7/8 | CC-70134 | CK-3122 |
| | スーパーサルーン | 81.8-82.8 | 7/8 | | TK-9409 | 81.8-82.8 | 2 1/4 | DISC | SP-219 | CPS-219 | 81.8-82.8 | 1 11/16 | DISC | SP-218 | | 81.8-82.8 | BH-02360 | (C)BH-02394<br>(R)BH-02343<br>(L)BH-02343 | | | (オートマチック) | | | | | |
| (2400ディーゼル) | スーパーDX | 82.8-83.7 | 7/8 | | TK-9403 | 82.8-83.7 | 2 1/4 | DISC | SP-219 | CPS-219 | 82.8-83.7 | 7/8 | (R)WC-50054 | WK-405 | CUP | 82.8-83.7 | BH-02360 | BH-02394 | 82.8-83.7 | 5/8 | MC-10072 | MK-4300 | 82.8-83.7 | 7/8 | CC-70134 | CK-3122 |
| LS111 | スーパーエディション | | | | | | | | | | | | (L)WC-50054 | | | | | | | | | | | | | |
| | スーパーサルーン | 82.8-83.7 | 7/8 | | TK-9409 | 82.8-83.7 | 2 1/4 | DISC | SP-219 | CPS-219 | 82.8-83.7 | 1 11/16 | DISC | SP-218 | | 82.8-83.7 | BH-02360 | (C)BH-02394<br>(R)BH-02343<br>(L)BH-02343 | 82.8-83.7 | 5/8 | MC-10072 | MK-4300 | 82.8-83.7 | 7/8 | CC-70134 | CK-3122 |
| | | | | | | | | | | | | | | | | | | | | | | | <フロアシフト車> | | | |
| (2200ディーゼル LS117V(バン) | STD・DX | 79.9-83.7 | 7/8 | | TK-9403 | 79.9-83.7 | 2 1/4 | DISC | SP-219 | CPS-219 | 79.9-83.7 | 7/8 | (R)WC-50054 | WK-405 | CUP | 79.9-83.7 | BH-02360 | BH-02210 | 79.9-83.7 | 5/8 | MC-10072 | MK-4300 | 79.9-80.12 | 7/8 | CC-70124 | CK-3110 |
| | | | | | | | | | | | | | (L)WC-50054 | | | | | | | | | | 80.12-81.8 | 7/8 | CC-70124 | CK-3121 |
| | | | | | | | | | | | | | | | | | | | | | | | 81.8-83.7 | 7/8 | CC-70134 | CK-3122 |
| | | | | | | | | | | | | | | | | | | | | | | | <コラムシフト車> | | | |
| | | | | | | | | | | | | | | | | | | | | | | | 79.9-80.10 | 7/8 | CC-70124 | CK-3110 |
| | | | | | | | | | | | | | | | | | | | | | | | 80.10-81.8 | 7/8 | CC-70134 | CK-3110 |
| | | | | | | | | | | | | | | | | | | | | | | | 81.8-83.7 | 7/8 | CC-70134 | CK-3122 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CROWN : 120 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000L. P. G) | E−YS120 | STD | 83.8-87.8 | 7/8 | | TK-9405 | 83.8-87.8 | 1 | (R-1)WC-51002<br>(R-2)WC-52002<br>(L-1)WC-53002<br>(L-2)WC-54002 | WK-307 | CUP | 83.8-87.8 | 1 | (R)WC-50048<br>(L)WC-50048 | WK-308 | CUP | 83.8-87.8 | BH-02457 | BH-02394 | 83.9-86.9<br>86.9-87.8 | 5/8<br>5/8 | MC-10142<br>MC-10142 | MK-4300<br>MK-4353 | 83.8-87.8 | 13/16 | CC-70145 | CK-3144 |
| | | STD・DX | 83.8-87.8 | 7/8 | | TK-9403 | 83.8-87.8 | 2 1/4 | DISC | SP-219 | CPS-219 | 83.8-87.8 | 7/8 | (R)WC-50054<br>(L)WC-50054 | WK-405 | CUP | 83.8-87.8 | BH-02361 | BH-02394 | 83.8-86.9<br>86.9-87.8 | 5/8<br>5/8 | MC-10142<br>MC-10142 | MK-4300<br>MK-4353 | 83.8-87.8 | 13/16 | CC-70145 | CK-3144 |
| | E−MS120 | DX・スーパーDX | 83.8-87.8 | 7/8 | | TK-9403 | 83.8-87.8 | 2 1/4 | DISC | SP-219 | CPS-219 | 83.8-87.8 | 7/8 | (R)WC-50054<br>(L)WC-50054 | WK-405 | CUP | 83.8-87.8 | BH-02361 | BH-02394 | 83.8-86.9<br>86.9-87.8 | 5/8<br>5/8 | | MK-4300<br>MK-4353 | 83.8-87.8 | 13/16 | CC-70133 | CK-3144 |
| (2000) | E−MS120 | スーパーサルーンエクストラ(ターボ)<br>スーパーエディション(ターボ) | 83.8-85.9 | 15/16 | | TK-9443 | 83.8-85.9 | 2 1/4 | DISC | SP-219 | CPS-219 | 83.8-85.9 | 42.8 | DISC | SP-238 | | 83.8-85.9 | BH-02361 | (C)BH-02394<br>(R)BH-02343<br>(L)BH-02343 | | | (オートマチック) | | | | |
| | E−GS120 | STD | 83.8-87.8 | 7/8 | | TK-9405 | 83.8-87.8 | 1 | (R-1)WC-51002<br>(R-2)WC-52002<br>(L-1)WC-53002<br>(L-2)WC-54002 | WK-307 | CUP | 83.8-87.8 | 1 | (R)WC-50048<br>(L)WC-50048 | WK-308 | CUP | 83.8-87.8 | BH-02457 | BH-02394 | 83.8-86.9<br>86.9-87.8 | 5/8<br>5/8 | MC-10133<br>MC-10133 | MK-4300<br>MK-4353 | 83.8-87.8 | 13/16 | CC-70133 | CK-3144 |
| | | STD・DX・スーパーDX<br>スーパーエディション<br>スーパーセレクト | 83.8-87.8 | 7/8 | | TK-9403 | 83.8-87.8 | 2 1/4 | DISC | SP-219 | CPS-219 | 83.8-87.8 | 7/8 | (R)WC-50054<br>(L)WC-50054 | WK-405 | CUP | 83.8-87.8 | BH-02361 | BH-02394 | 83.8-86.9<br>86.9-87.8 | 5/8<br>5/8 | MC-10133<br>MC-10133 | MK-4300<br>MK-4353 | 83.8-87.8 | 13/16 | CC-70133 | CK-3144 |
| | | スーパーサルーン<br>スーパーサルーンエクストラ | 83.8-87.8 | 7/8 | | TK-9403 | 83.8-87.8 | 2 1/4 | DISC | SP-219 | CPS-219 | 83.8-87.8 | 42.8 | DISC | SP-238 | | 83.8-87.8 | BH-02361 | (C)BH-02394<br>(R)BH-02343<br>(L)BH-02343 | 83.8-86.9<br>86.9-87.8 | 5/8<br>5/8 | MC-10133<br>MC-10133 | MK-4300<br>MK-4353 | 83.8-87.8 | 13/16 | CC-70133 | CK-3144 |
| | E−GS120G(ワゴン) | スーパーDX<br>スーパーサルーン | 83.8-87.8 | 7/8 | | TK-9403 | 83.8-87.8 | 2 1/4 | DISC | SP-219 | CPS-219 | 83.8-87.8 | 7/8 | (R)WC-50054<br>(L)WC-50054 | WK-405 | CUP | 83.8-87.8 | BH-02361 | BH-02394 | 83.8-86.9<br>86.9-87.8 | 5/8<br>5/8 | MC-10133<br>MC-10133 | MK-4300<br>MK-4353 | 83.8-87.8 | 13/16 | CC-70133 | CK-3144 |
| | E−GS121 | ロイヤルサルーン<br>スーパーエディション | 83.8-85.9<br>85.9-87.8 | 7/8<br>15/16 | | TK-9403<br>TK-T005 | 83.8-87.8 | 2 1/4 | DISC | SP-219 | CPS-219 | 83.8-87.8 | 42.8 | DISC | SP-238 | | 83.8-87.8 | BH-02361 | (R-1)BH-95008<br>(L-1)BH-95008<br>(R-2)BH-94011<br>(L-2)BH-94011 | 83.8-86.9<br>86.9-87.8 | 5/8<br>5/8 | MC-10133<br>MC-10133 | MK-4300<br>MK-4353 | 83.8-87.8 | 13/16 | CC-70133 | CK-3144 |
| (2000) | L−GS126V(バン) | STD・DX・スーパーDX | 83.8-87.8 | 7/8 | | TK-9403 | 83.8-87.8 | 2 1/4 | DISC | SP-219 | CPS-219 | 83.8-87.8 | 7/8 | (R)WC-50054<br>(L)WC-50054 | WK-405 | CUP | 83.8-87.8 | BH-02361 | BH-02210 | 83.8-86.9<br>86.9-87.8 | 5/8<br>5/8 | MC-10133<br>MC-10133 | MK-4300<br>MK-4353 | 83.8-87.8 | 13/16 | CC-70133 | CK-3144 |
| (2800)<br>(3000) | E−MS123<br>E−MS125 | ロイヤルサルーン<br>ロイヤルサルーンG | 83.8-85.9<br>85.9-87.8 | 15/16<br>15/16 | | TK-9443<br>TK-T005 | 83.8-87.8 | 2 1/4 | DISC | SP-219 | CPS-219 | 83.8-87.8 | 42.8 | DISC | SP-238 | | 83.8-87.8 | BH-02361 | (R-1)BH-95008<br>(L-1)BH-95008<br>(R-2)BH-94011<br>(L-2)BH-94011 | | | (オートマチック) | | | | |
| (2400ディーゼル) | N−LS120 | STD | 83.8-87.8 | 7/8 | | TK-9405 | 83.8-87.8 | 1 | (R-1)WC-51002<br>(R-2)WC-52002<br>(L-1)WC-53002<br>(L-2)WC-54002 | WK-307 | CUP | 83.8-87.8 | 1 | (R)WC-50048<br>(L)WC-50048 | WK-308 | CUP | 83.8-87.8 | BH-02457 | BH-02394 | 83.8-86.9<br>86.9-87.8 | 5/8<br>5/8 | MC-10133<br>MC-10133 | MK-4300<br>MK-4353 | 83.8-87.8 | 13/16 | CC-70133 | CK-3144 |
| | | STD・DX<br>スーパーDX(ターボ)<br>スーパーエディション(ターボ)<br>スーパーセレクト(ターボ) | 83.8-87.8 | 7/8 | | TK-9403 | 83.8-87.8 | 2 1/4 | DISC | SP-219 | CPS-219 | 83.8-87.8 | 7/8 | (R)WC-50054<br>(L)WC-50054 | WK-405 | CUP | 83.8-87.8 | BH-02361 | BH-02394 | 83.8-86.9<br>86.9-87.8 | 5/8<br>5/8 | MC-10133<br>MC-10133 | MK-4300<br>MK-4353 | 83.8-87.8 | 13/16 | CC-70133 | CK-3144 |
| | | スーパーサルーンエクストラ(ターボ) | 83.8-87.8 | 7/8 | | TK-9403 | 83.8-87.8 | 2 1/4 | DISC | SP-219 | CPS-219 | 83.8-87.8 | 42.8 | DISC | SP-238 | | 83.8-87.8 | BH-02361 | (C)BH-02394<br>(R)BH-02343<br>(L)BH-02343 | 83.8-85.9<br>85.9-87.8 | 5/8 | MC-10133<br>(オートマチック) | MK-4300 | 83.8-85.9 | 13/16 | CC-70133 | CK-3144 |
| | N−LS120G(ワゴン) | スーパーDX(ターボ)<br>スーパーサルーン(ターボ) | 83.8-87.8 | 7/8 | | TK-9403 | 83.8-87.8 | 2 1/4 | DISC | SP-219 | CPS-219 | 83.8-87.8 | 7/8 | (R)WC-50054<br>(L)WC-50054 | WK-405 | CUP | 83.8-87.8 | BH-02361 | BH-02394 | 83.8-86.9<br>86.9-87.8 | 5/8<br>5/8 | MC-10133<br>MC-10133 | MK-4300<br>MK-4353 | 83.8-87.8 | 13/16 | CC-70133 | CK-3144 |
| | N−LS126V(バン) | STD・DX | 83.8-87.8 | 7/8 | | TK-9403 | 83.8-87.8 | 2 1/4 | DISC | SP-219 | CPS-219 | 83.8-87.8 | 7/8 | (R)WC-50054<br>(L)WC-50054 | WK-405 | CUP | 83.8-87.8 | BH-02361 | BH-02210 | 83.8-86.9<br>86.9-87.8 | 5/8<br>5/8 | MC-10133<br>MC-10133 | MK-4300<br>MK-4353 | 83.8-87.8 | 13/16 | CC-70133 | CK-3144 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CROWN : 130 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000L. P. G) | E−YS130 | STD(ドラム車) | 87.9-91.10 | 7/8 | | TK-T025 | 87.9-89.8 | 1 | (R-1)WC-51002<br>(R-2)WC-52002<br>(L-1)WC-53002<br>(L-2)WC-54002 | WK-307 | CUP | 87.9-89.8 | 1 | (R)WC-50048<br>(L)WC-50048 | WK-308 | CUP | 87.9-91.10 | BH-02544 | BH-02394 | 87.9-89.8<br>89.8-91.10 | 5/8<br>5/8 | MC-T409<br>MC-T409 | MK-4353 | 87.9-88.5<br>88.5-91.3<br>91.3-91.10 | 13/16<br>13/16<br>13/16 | CC-70145<br>CC-70145<br>CC-T317 | CK-3144<br>CK-3144<br>CK-T201 |
| | | | | | | | | | | | | 89.8-90.12<br>90.12-91.10 | 1<br>1 | | WK-308<br>WK-795 | CUP<br>CUP | | | | | | | | | | | | |
| | | | | | | | 89.8-91.10 | 1 | | WK-307 | CUP | | | | | | | | | | | | | | | | |
| | | STD(ディスク車) | 87.9-95.12 | 15/16 | | TK-T325 | 87.9-91.10 | 60.6 | DISC | SP-249 | CPS-249B | 87.9-89.8 | 7/8 | (R)WC-50054<br>(L)WC-50054 | WK-405 | CUP | 87.9-95.12 | BH-02543 | BH-02394 | 87.9-89.8 | 5/8 | | MK-4353 | 87.9-88.5 | 13/16 | CC-70145 | CK-3144 |
| | | DX | | | | | 91.10-95.12 | 60.6 | DISC | SP-249 | CPS-249 | | | | | | | | | 89.8-91.10 | 5/8 | MC-T409 | | 88.5-91.3 | 13/16 | CC-70145 | CK-3144 |
| | | | | | | | | | | | | 89.8-95.5 | 15/16 | (R)WC-50047<br>(L)WC-50047 | WK-764 | CUP | | | | 91.10-95.12 | 5/8 | MC-T412 | | 91.3-95.12 | 13/16 | CC-T317 | CK-T201 |
| | | | | | | | | | | | | 95.5-95.12 | 15/16 | (R)WC-50047<br>(L)WC-50047 | WK-309 | CUP | | | | | | | | | | | |
| | E−GS130・130H | DX・スーパーDX<br>ロイヤルサルーン | 89.8-95.12 | 15/16 | | TK-T325 | 89.8-91.10<br>91.10-95.12 | 60.6<br>60.6 | DISC<br>DISC | SP-249<br>SP-249 | CPS-249B<br>CPS-249 | 89.8-95.5<br>95.5-95.12 | 15/16<br>15/16 | (R)WC-50047<br>(L)WC-50047<br>(R)WC-50047<br>(L)WC-50047 | WK-764<br>WK-309 | CUP<br>CUP | 89.8-95.12 | BH-02543 | BH-02394 | 89.8-91.10<br>91.10-94.3<br>94.3-95.12 | 5/8<br>5/8<br>5/8 | MC-T410<br>MC-T339<br>MC-T339 | MK-4353 | 89.8-91.3<br>91.3-95.12 | 13/16<br>13/16 | CC-70133 | CK-3144<br>CK-T201 |
| | E−MS130 | DX・スーパーDX | 87.9-89.8 | 15/16 | | TK-T325 | 87.9-89.8 | 60.6 | DISC | SP-249 | CPS-249B | 87.9-89.8 | 7/8 | (R)WC-50054<br>(L)WC-50054 | WK-405 | CUP | 87.9-89.8 | BH-02543 | BH-02394 | 87.9-89.8 | 5/8 | MC-T408 | MK-4353 | 87.9-88.5<br>88.5-89.8 | 13/16<br>13/16 | CC-70133<br>CC-70133 | CK-3144<br>CK-3144 |
| (2000) | E−GS130 | STD(ドラム車) | 87.9-89.8 | 7/8 | | TK-T025 | 87.9-89.8 | 1 | (R-1)WC-51002<br>(R-2)WC-52002<br>(L-1)WC-53002<br>(L-2)WC-54002 | WK-307 | CUP | 87.9-89.8 | 1 | (R)WC-50048<br>(L)WC-50048 | WK-308 | CUP | 87.9-89.8 | BH-02544 | BH-02394 | 87.9-89.8 | 5/8 | MC-T410 | MK-4353 | 87.9-88.5<br>88.5-89.8 | 13/16<br>13/16 | CC-70133<br>CC-70133 | CK-3144<br>CK-3144 |
| | | | <1GEエンジン車> | | | | | | | | | | | | | | | | | | | | | | | | |
| | | STD(ディスク車) | 87.9-89.8 | 15/16 | | TK-T325 | 87.9-91.10 | 60.6 | DISC | SP-249 | CPS-249B | 87.9-95.12 | 7/8 | (R)WC-50054<br>(L)WC-50054 | WK-405 | CUP | 87.9-95.12 | BH-02543 | BH-02394 | 87.9-91.10<br>91.10-94.3<br>94.3-95.12 | 5/8<br>5/8<br>5/8 | MC-T410<br>MC-T339 | MK-4353 | 87.9-88.5<br>88.5-91.3<br>91.3-95.12 | 13/16<br>13/16<br>13/16 | CC-70133<br>CC-70133 | CK-3144<br>CK-3144<br>CK-T201 |
| | | DX・SDX・スーパーエディション | <1GFEエンジン車> | | | | 91.10-95.12 | 60.6 | DISC | SP-249 | CPS-249 | | | | | | | | | | | | | | | | |
| | | スーパーサルーン | 88.9-91.10 | 1 | | TK-T045 | | | | | | | | | | | | | | | | | | | | | |
| | | スーパーサルーンエクストラ | 91.10-94.7 | 1 | | TK-T366 | | | | | | | | | | | | | | | | | | | | | |
| | | | 94.7-95.12 | 1 | | TK-T366 | | | | | | | | | | | | | | | | | | | | | |
| | | | <1GEエンジン車> | | | | | | | | | | | | | | | | | | | | | | | | |
| | | 四輪ディスク車 | 87.9-89.8 | 15/16 | | TK-T325 | 87.9-89.8 | 60.6 | DISC | SP-249 | CPS-249B | 87.9-89.8 | 42.8 | DISC | SP-238 | | 87.9-89.8 | BH-02543 | (C)BH-02394<br>(R)BH-02343<br>(L)BH-02343 | 87.9-89.8 | 5/8 | MC-T410 | MK-4353 | 87.9-88.5<br>88.5-89.8 | 13/16<br>13/16 | CC-70133<br>CC-70133 | CK-3144<br>CK-3144 |
| | | スーパーサルーン | <1GFEエンジン車> | | | | | | | | | | | | | | | | | | | | | | | | |
| | | スーパーサルーンエクストラ | 88.9-89.8 | 1 | | TK-T045 | | | | | | | | | | | | | | | | | | | | | |
| (2000) | E−GS130G・W | スーパーDX | <1GEエンジン車> | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | 87.9-89.8 | 15/16 | | TK-T325 | 87.9-91.10 | 60.6 | DISC | SP-249 | CPS-249B | 87.9-99.4 | 7/8 | (R)WC-50054 | WK-405 | CUP | 87.9-99.4 | BH-02543 | BH-02394 | 87.9-91.10 | 5/8 | MC-T410 | MK-4353 | 87.9-88.8 | 13/16 | CC-70133 | CK-3144 |
| | <GF−は98．9〜> | スーパーサルーンエクストラ | <1GFEエンジン車> | | | | 91.10-99.4 | 60.6 | DISC | SP-249 | CPS-249 | | | (L)WC-50054 | | | | | | 91.10-94.3 | 5/8 | | | 88.8-91.3 | 13/16 | CC-70133 | CK-3144 |
| | | ロイヤルエクストラ | 87.9-91.10 | 1 | | TK-T045 | | | | | | | | | | | | | | 94.3-95.12 | 5/8 | | | 91.3-95.12 | 13/16 | | CK-T201 |
| | | | 91.10-94.7 | 1 | | TK-T366 | | | | | | | | | | | | | | 95.12-99.4 | | (オートマチック) | | | | | |
| | | | 94.7-98.3 | 1 | | TK-T366 | | | | | | | | | | | | | | | | | | | | | |
| | | | 98.3-99.4 | 1 | | TK-T366 | | | | | | | | | | | | | | | | | | | | | |
| | | ロイヤルサルーン | 87.9-91.10 | 1 | | TK-T045 | 87.9-91.10 | 60.6 | DISC | SP-249 | CPS-249B | 87.9-91.10 | 7/8 | (R)WC-50054<br>(L)WC-50054 | WK-405 | CUP | 87.9-91.10 | BH-02543 | BH-02394 | | | (オートマチック) | | | | | |
| | | | <1GEエンジン車> | | | | | | | | | | | | | | | | | | | | | | | | |
| | E−GS131・131H | スーパーセレクト | 87.9-89.8 | 15/16 | | TK-T325 | 87.9-91.10 | 60.6 | DISC | SP-249 | CPS-249B | 87.9-91.10 | 42.8 | DISC | C-227P | CPC-227B | 87.9-88.3 | BH-02543 | (R-1)BH-95010<br>(L-1)BH-95010<br>(R-2)BH-94011<br>(L-2)BH-94011 | 87.9-91.10<br>91.10-95.12 | 5/8 | MC-T410<br>(オートマチック) | MK-4353 | 87.9-88.8<br>88.8-91.3<br>91.3-91.10 | 13/16<br>13/16<br>13/16 | CC-70133<br>CC-70133 | CK-3144<br>CK-3144<br>CK-T201 |
| | | スーパーエディション | <1GFEエンジン車> | | | | 91.10-95.12 | 60.6 | DISC | SP-249 | CPS-249 | 91.10-95.12 | | DISC | C-227P | CPC-227 | | | | | | | | | | | |
| | | スーパーサルーン | <1GGEエンジン車> | | | | | | | | | | | | | | | | | | | | | | | | |
| | | スーパーサルーンエクストラ | <1GGZEエンジン車> | | | | | | | | | | | | | | | | | | | | | | | | |
| | | ロイヤルサルーン | 87.9-91.10 | 1 | | TK-T045 | | | | | | | | | | | 88.3-89.8 | BH-02543 | (R-1)BH-T513<br>(L-1)BH-T513<br>(R-2)BH-94011<br>(L-2)BH-94011 | | | | | | | | |
| | | | 91.10-94.7 | 1 | | TK-T366 | | | | | | | | | | | | | | | | | | | | | |
| | | | 94.7-95.12 | 1 | | TK-T366 | | | | | | | | | | | | | | | | | | | | | |
| | | | <アンチスキッド付> | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | 87.9-89.8 | 1 | | TK-T046 | | | | | | | | | | | 89.8-95.12 | BH-02543 | (R-1)BH-T513<br>(L-1)BH-T513<br>(R-2)BH-T565<br>(L-2)BH-T565 | | | | | | | | |
| | | | 89.8-91.10 | 1 | | TK-T305 | | | | | | | | | | | | | | | | | | | | | |
| | L−GS136V(バン) | STD・DX | 87.9-91.10 | 15/16 | | TK-T325 | 87.9-91.10 | 60.6 | DISC | SP-249 | CPS-249B | 87.9-99.4 | 7/8 | (R)WC-50054 | WK-405 | CUP | 87.9-99.4 | BH-02543 | BH-02210 | 87.9-91.10 | 5/8 | MC-T410 | MK-4353 | 87.9-88.8 | 13/16 | CC-70133 | CK-3144 |
| | <Tーは89．8〜> | スーパーDX | 91.10-94.7 | 1 | | TK-T366 | 91.10-99.4 | 60.6 | DISC | SP-249 | CPS-249 | | | (L)WC-50054 | | | | | | 91.10-94.3 | 5/8 | | | 88.8-91.3 | 13/16 | CC-70133 | CK-3144 |
| | <GAーは95．12〜> | | 94.7-98.3 | 1 | | TK-T366 | | | | | | | | | | | | | | 94.3-97.10 | 5/8 | | | 91.3-99.4 | 13/16 | | CK-T201 |
| | | | 98.3-99.4 | 1 | | TK-T366 | | | | | | | | | | | | | | 97.10-99.4 | 5/8 | | MK-T244 | | | | |
| (2400ディーゼル) | | STD(ドラム車) | 87.9-91.10 | 7/8 | | TK-T025 | 87.9-90.8 | 1 | (R-1)WC-51002<br>(R-2)WC-52002<br>(L-1)WC-53002<br>(L-2)WC-54002 | WK-307 | CUP | 87.9-89.8<br>89.8-90.12<br>90.12-91.10 | 1<br>1<br>7/8 | (R)WC-50048<br>(L)WC-50048 | WK-308<br>WK-308<br>WK-405 | CUP<br>CUP<br>CUP | 87.9-91.10 | BH-02544 | BH-02394 | 87.9-91.10 | 5/8 | MC-T410 | MK-4353 | 87.9-88.8<br>88.8-91.3<br>91.3-91.10 | 13/16<br>13/16<br>13/16 | CC-70133<br>CC-70133 | CK-3144<br>CK-3144<br>CK-T201 |
| | Q−LS130 | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | <Yーは93．8〜> | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | 90.8-91.10 | 1 | | WK-307 | CUP | | | | | | | | | | | | | | | | |
| | | STD(ディスク車) | 87.9-91.10 | 15/16 | | TK-T325 | 87.9-91.10 | 60.6 | DISC | SP-249 | CPS-249B | 87.9-95.12 | 7/8 | (R)WC-50054 | WK-405 | CUP | 87.9-95.12 | BH-02543 | BH-02394 | 87.9-91.10 | 5/8 | MC-T410 | MK-4353 | 87.9-88.8 | 13/16 | CC-70133 | CK-3144 |
| | | DX・スーパーDX | 91.10-94.7 | 1 | | TK-T366 | 91.10-95.12 | 60.6 | DISC | SP-249 | CPS-249 | | | (L)WC-50054 | | | | | | 91.10-95.12 | | (オートマチック) | | 88.8-91.3 | 13/16 | CC-70133 | CK-3144 |
| | | スーパーエディション | 94.7-95.12 | 1 | | TK-T366 | | | | | | <STDタクシー仕様車> | | | | | | | | | | | | 91.3-91.10 | 13/16 | | CK-T201 |
| | | スーパーセレクト | | | | | | | | | | 89.8-91.10 | 15/16 | | WK-764 | CUP | | | | | | | | | | | |
| | | スーパーサルーンエクストラ | 87.9-89.8 | 15/16 | | TK-T325 | 87.9-89.8 | 60.6 | DISC | SP-249 | CPS-249B | 87.9-89.8 | 42.8 | DISC | SP-238 | | 87.9-89.8 | BH-02543 | (C)BH-02394<br>(R)BH-02343<br>(L)BH-02343 | | | (オートマチック) | | | | | |
| | Q−LS131・131H | スーパーセレクト | 89.8-91.10 | 15/16 | | TK-T325 | 89.8-91.10 | 60.6 | DISC | SP-249 | CPS-249B | 89.8-91.10 | | DISC | C-227P | CPC-227B | 89.8-95.12 | BH-02543 | (R-1)BH-T513<br>(L-1)BH-T513<br>(R-2)BH-T565<br>(L-2)BH-T565 | 89.8-91.10<br>91.10-95.12 | 5/8 | MC-T410<br>(オートマチック) | MK-4353 | 89.8-91.3<br>91.3-91.10 | 13/16<br>13/16 | CC-70133 | CK-3144<br>CK-T201 |
| | <Yーは93．8〜> | スーパーエディション | 91.10-94.7 | 1 | | TK-T366 | 91.10-95.12 | 60.6 | DISC | SP-249 | CPS-249 | 91.10-95.12 | 42.8 | DISC | C-227P | CPC-227 | | | | | | | | | | | |
| | | スーパーサルーンエクストラ | 94.7-95.12 | 1 | | TK-T366 | | | | | | | | | | | | | | | | | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | Q－LS130G・W(ワゴン)<br><Y－は93．8～><br><KD－は95．12～> | | 87.9–91.10<br>91.10–94.7<br>94.7–98.3<br>98.3–99.4 | 15/16<br>1<br>1<br>1 | | TK–T325<br>TK–T366<br>TK–T366<br>TK–T366 | 87.9–91.10<br>91.10–99.4 | 60.6<br>60.6 | DISC<br>DISC | SP–249<br>SP–249 | CPS–249B<br>CPS–249 | 87.9–99.4 | 7/8 | (R)WC–50054<br>(L)WC–50054 | WK–405 | CUP | 87.9–99.4 | BH–02543 | BH–02394 | | | (オートマチック) | | | | | |
| | S－LS136V(バン) | STD・DX | 87.9–91.10<br>91.10–94.8 | 15/16<br>1 | | TK–T325<br>TK–T366 | 87.9–91.10<br>91.10–94.8 | 60.6<br>60.6 | DISC<br>DISC | SP–249<br>SP–249 | CPS–249B<br>CPS–249 | 87.9–94.8 | 7/8 | (R)WC–50054<br>(L)WC–50054 | WK–405 | CUP | 87.9–94.8 | BH–02543 | BH–02210 | 87.9–91.10<br>91.10–94.3<br>94.3–94.8 | 5/8<br>5/8<br>5/8 | MC–T410<br>MC–T415<br>MC–T415 | MK–4353 | 87.9–88.8<br>88.8–91.3<br>91.3–94.8 | 13/16<br>13/16<br>13/16 | CC–70133<br>CC–70133 | CK–3144<br>CK–3144<br>CK–T201 |
| (2500) | E－JZS131 | スーパーセレクト<br>スーパーサルーンエクストラ<br>アスリートL<br>ロイヤルサルーン | 90.8–91.10<br>91.10–95.8<br><アンチスキッド付><br>90.8–91.10<br>91.10–95.12 | 1<br>1 1/16<br><br>1<br>1 1/16 | | TK–T045<br>TK–T332<br><br>TK–T305<br>TK–T332 | 90.8–91.10<br>91.10–95.12 | 60.6<br>60.6 | DISC<br>DISC | SP–249<br>SP–249 | CPS–249B<br>CPS–249 | 90.8–91.10<br>91.10–95.12 | 42.8 | DISC<br>DISC | C–227P<br>C–227P | CPC–227B<br>CPC–227 | 90.8–95.12 | BH–02543 | (R–1)BH–T513<br>(L–1)BH–T513<br>(R–2)BH–T565<br>(L–2)BH–T565 | | | (オートマチック) | | | | | |
| | E－JZS130G(ワゴン)<br><GF－は98．9～> | スーパーサルーンエクストラ<br>ロイヤルサルーン | 90.8–91.10<br>91.10–94.7<br>94.7–98.3<br>98.3–99.4 | 1<br>1<br>1<br>1 | | TK–T045<br>TK–T366<br>TK–T366<br>TK–T366 | 90.8–91.10<br>91.10–99.4 | 60.6<br>60.6 | DISC<br>DISC | SP–249<br>SP–249 | CPS–249B<br>CPS–249 | 90.8–91.10<br><br>91.10–95.5<br><br>95.5–99.4 | 7/8<br><br>15/16<br><br>15/16 | (R)WC–50054<br>(L)WC–50054<br>(R)WC–50047<br>(L)WC–50047<br>(R)WC–50047<br>(L)WC–50047 | WK–405<br><br>WK–764<br><br>WK–309 | CUP<br><br>CUP<br><br>CUP | 90.8–99.4 | BH–02543 | BH–02394 | | | (オートマチック) | | | | | |
| (3000) | E－MS135・137 | アスリートL<br>ロイヤルサルーン<br>ロイヤルサルーンG | 87.9–91.10<br><アンチスキッド付><br>87.9–89.8<br>89.8–91.10 | 1<br><br>1<br>1 | | TK–T045<br><br>TK–T046<br>TK–T305 | 87.9–91.10 | 60.6 | DISC | SP–249 | CPS–249B | 87.9–91.10 | 42.8 | DISC | C–227P | CPC–227B | 87.9–88.3<br><br><br><br>88.3–89.8<br><br><br><br>89.8–91.10 | BH–02543<br><br><br><br>BH–02543<br><br><br><br>BH–02543 | (R–1)BH–95010<br>(L–1)BH–95010<br>(R–2)BH–94011<br>(L–2)BH–94011<br>(R–1)BH–T513<br>(L–1)BH–T513<br>(R–2)BH–94011<br>(L–2)BH–94011<br>(R–1)BH–T513<br>(L–1)BH–T513<br>(R–2)BH–T565<br>(L–2)BH–T565 | | | (オートマチック) | | | | | |
| | E－JZS133・135 | ロイヤルサルーン<br>ロイヤルサルーンG | 91.10–95.12 | 1 1/16 | | TK–T332 | 91.10–95.12 | 60.6 | DISC | SP–249 | CPS–249 | 91.10–95.12 | 42.8 | DISC | C–227P | CPC–227 | 91.10–95.12 | BH–02543 | (R–1)BH–T513<br>(L–1)BH–T513<br>(R–2)BH–T565<br>(L–2)BH–T565 | | | (オートマチック) | | | | | |
| (4000) | E－UZS131 | ロイヤルサルーンG | 89.8–91.10 | 1 | | TK–T305 | 89.8–91.10 | 60.6 | DISC | SP–249 | CPS–249B | 89.8–91.10 | 42.8 | DISC | C–227P | CPC–227B | 89.8–91.10 | BH–02543 | (R–1)BH–T513<br>(L–1)BH–T513<br>(R–2)BH–T565<br>(L–2)BH–T565 | | | (オートマチック) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CROWN : 140 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000) | E−GS141 | | 93.8-95.8 | 1 1/16 | | TK-T332 | 93.8-95.8 | 60.6 | DISC | SP-249 | CPS-249 | 93.8-95.8 | 42.8 | DISC | C-227P | CPC-227 | 93.8-95.8 | BH-02543 | (R-1)BH-T513<br>(L-1)BH-T513<br>(R-2)BH-T565<br>(L-2)BH-T565 | | | (オートマチック) | | | | | |
| (2400ディーゼル) | Q−LS141<br><Y−は93．8〜> | | 91.10-94.7<br>94.7-95.8 | 1<br>1 | | TK-T366<br>TK-T366 | 91.10-95.8 | 60.6 | DISC | SP-249 | CPS-249 | 91.10-95.8 | 42.8 | DISC | C-227P | CPC-227 | 91.10-95.8 | BH-02543 | (R-1)BH-T513<br>(L-1)BH-T513<br>(R-2)BH-T565<br>(L-2)BH-T565 | | | (オートマチック) | | | | | |
| (2500) | E−JZS141 | | 91.10-95.8 | 1 1/16 | | TK-T332 | 91.10-95.8 | 60.6 | DISC | SP-249 | CPS-249 | 91.10-95.8 | 42.8 | DISC | C-227P | CPC-227 | 91.10-95.8 | BH-02543 | (R-1)BH-T513<br>(L-1)BH-T513<br>(R-2)BH-T565<br>(L-2)BH-T565 | | | (オートマチック) | | | | | |
| (3000) | E−JZS143・145 | | 91.10-95.8 | 1 1/16 | | TK-T332 | 91.10-95.8 | 60.6 | DISC | SP-249 | CPS-249 | 91.10-95.8 | 42.8 | DISC | C-227P | CPC-227 | 91.10-95.8 | BH-02543 | (R-1)BH-T513<br>(L-1)BH-T513<br>(R-2)BH-T565<br>(L-2)BH-T565 | | | (オートマチック) | | | | | |
| | E−JZS147・149 | マジェスタ | 91.10-95.8<br><トラクションコントロール付><br>91.10-95.8 | 1 1/16 | | TK-T332 | 91.10-95.3<br>95.3-95.8 | 44.4<br>44.4 | DISC<br>DISC | MP-47<br>MP-71 | | 91.10-95.8 | 42.8 | DISC | MP-48 | | 91.10-95.8 | BH-T669 | (R)BH-T574<br>(L)BH-T574 | | | (オートマチック) | | | | | |
| (4000) | E−UZS141・147<br>E−UZS143(4WD)<br>E−UZS145(4WD・4WS) | マジェスタ | 91.10-95.8 | | | | 91.10-95.3<br>95.3-95.8 | 44.4<br>44.4 | DISC<br>DISC | MP-47<br>MP-71 | | 91.10-95.8 | 42.8 | DISC | MP-48 | | <UZS141・147><br>91.10-95.8<br><br><UZS143・145><br>92.10-95.8 | BH-T669 | (R)BH-T574<br>(L)BH-T574<br><br>(R)BH-T574<br>(L)BH-T574 | | | (オートマチック) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CROWN : 150 ser.(95.8-) | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000)<br>(2000LPG) | E−GS151<br>＜GF−は98．8～＞ | | 95.12-99.9<br>＜ｱﾝﾁｽｷｯﾄﾞ付＞<br>95.12-01.8 | 1<br><br>1 | | TK-T378<br><br>TK-T412 | 95.12-98.8<br>98.8-01.8<br>＜LPG車＞<br>95.12-01.2 | | DISC<br>DISC<br><br>DISC | SP-204<br>SP-102<br><br>SP-204 | CPS-204<br>CPS-102<br><br>CPS-204 | 95.12-98.8<br>98.8-01.8<br>＜LPG車＞<br>95.12-01.2 | | DISC<br>DISC<br><br>DISC | SP-263<br>SP-295<br><br>SP-263 | CPS-263<br>CPS-295<br><br>CPS-263 | 95.12-01.8 | BH-T765 | (R)BH-T594<br>(L)BH-T594 | 95.12-01.8 | 5/8 | MC-T402 | MK-T244 | 95.12-01.8 | 13/16 | | CK-T201 |
| | E−GS151H<br>＜GF−は98．8～＞ | | 95.8-99.9<br>＜ｱﾝﾁｽｷｯﾄﾞ付＞<br>95.8-01.8 | 1<br><br>1 | | TK-T378<br><br>TK-T412 | 95.8-01.8<br>＜LPG車＞<br>95.12-01.2 | | DISC<br><br>DISC | MP-121<br><br>SP-204 | <br><br>CPS-204 | 95.8-01.8<br>＜LPG車＞<br>95.12-01.2 | | DISC<br><br>DISC | MP-67<br><br>SP-263 | <br><br>CPS-263 | 95.8-01.8 | BH-T765 | (R)BH-T594<br>(L)BH-T594 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (2400ディーゼル) | KD−LS151 | | 95.12-99.9 | 1 | | TK-T377 | 95.12-99.9 | | DISC | SP-204 | CPS-204 | 95.12-99.9 | | DISC | SP-263 | CPS-263 | 95.12-99.9 | BH-T765 | (R)BH-T594<br>(L)BH-T594 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | KD−LS151H | | 95.8-99.9 | 1 | | TK-T377 | 95.8-99.9 | | DISC | MP-121 | CPM-121 | 95.8-99.9 | | DISC | MP-67 | | 95.8-99.9 | BH-T765 | (R)BH-T594<br>(L)BH-T594 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (2500) | E−JZS151<br>＜GF−は98．8～＞ | | 95.8-01.8 | 1 | | TK-T412 | 95.8-01.8 | | DISC | MP-121 | CPM-121 | 95.8-01.8 | | DISC | MP-67 | | 95.8-01.8 | BH-T765 | (R)BH-T594<br>(L)BH-T594 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | E−JZS153(4WD)<br>＜GF−は98．8～＞ | | 95.12-01.8 | 1 | | TK-T412 | 95.12-01.8 | | DISC | MP-121 | CPM-121 | 95.12-01.8 | | DISC | MP-67 | | 95.12-01.8 | BH-T691 | (R)BH-T594<br>(L)BH-T594 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (3000) | E−JZS155<br>＜GF−は98．8～＞ | ロイヤルサルーン・ロイヤルサルーンG<br>ロイヤルツーリング<br>パトロールカー | 95.8-97.7<br>97.7-01.8 | 1<br>1 | | TK-T412<br>TK-T431 | 95.8-01.8 | | DISC | MP-121 | CPM-121 | 95.8-01.8 | | DISC | MP-67 | | 95.8-01.8 | BH-T765 | (R)BH-T594<br>(L)BH-T594 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | | マジェスタ | 95.8-97.7<br>97.7-99.9<br>＜油圧ﾌﾞｰｽﾀｰ＞<br>95.8-97.7 | 1<br>1 | | TK-T412<br>TK-T410 | 95.8-99.9 | | DISC | MP-77 | CPM-77 | 95.8-99.9 | | DISC | MP-66 | | 95.8-99.9 | BH-T669 | (R)BH-T736<br>(L)BH-T736 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | GF−JZS157(4WD) | | 98.8-99.9 | 1 | | TK-T412 | 98.8-99.9 | | DISC | MP-121 | CPM-121 | 98.8-99.9 | | DISC | MP-67 | | 98.8-99.9 | BH-T691 | (R)BH-T594<br>(L)BH-T594 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (4000) | E−UZS151・157<br>＜GF−は98．8～＞ | マジェスタ | 95.8-99.9 | | | | 95.8-99.9 | | DISC | MP-77 | CPM-77 | 95.8-99.9 | | DISC | MP-66 | | 95.8-99.9 | BH-T669 | (R)BH-T574<br>(L)BH-T574 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | E−UZS155(4WD)<br>＜GF−は98．8～＞ | マジェスタ | 95.11-99.9 | | | | 95.11-99.9 | | DISC | MP-77 | CPM-77 | 95.11-99.9 | | DISC | MP-66 | | 95.11-99.9 | BH-T670 | (R)BH-T574<br>(L)BH-T574 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CROWN : 170 ser.(99.8-) | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000) | GH-GS171・171W<br><TA-は00. 8～> | 含むパトロールカー | 99.9-05.7 | | | | 99.9-05.7 | | DISC | MP-121 | CPM-112 | 99.9-05.7 | | DISC | MP-79 | CPM-79 | 99.9-05.7 | BH-T830 | (R)BH-T864<br>(L)BH-T864 | | | (オートマチック) | | | | | |
| (2500) | GH-JZS171・171W<br><TA-は00. 8～> | ターボ無 | 99.9-07.6<br><VSC付><br>99.9-07.6 | | | | 99.9-07.6 | | DISC | MP-121 | CPM-112 | 99.9-07.6 | | DISC | MP-79 | CPM-79 | 99.9-07.6 | BH-T830 | (R)BH-T864<br>(L)BH-T864 | | | (オートマチック) | | | | | |
| | | ターボ車 | 99.9-01.8<br>01.8-03.12 | | | | 99.9-03.12 | | DISC | MP-77 | CPM-77 | 99.9-03.12 | | DISC | MP-79 | CPM-79 | 99.9-03.12 | BH-T830 | (R)BH-T864<br>(L)BH-T864 | | | (オートマチック) | | | | | |
| | GH-JZS173(4WD)<br>GH-JZS173W(4WD)<br><TA-は00. 8～> | 含むパトロールカー | 99.9-07.6 | | | | 99.9-07.6 | | DISC | MP-121 | CPM-121 | 99.9-07.6 | | DISC | MP-79 | CPM-79 | 99.9-07.6 | BH-T691 | (R)BH-T864<br>(L)BH-T864 | | | (オートマチック) | | | | | |
| (3000) | GH-JZS175・175W<br>YA-JKS175<br><TA-は00. 8～> | 含むパトロールカー | 99.9-07.6 | | | | 99.9-07.6 | | DISC | MP-121 | CPM-112 | 99.9-07.6 | | DISC | MP-79 | CPM-79 | 99.9-07.6 | BH-T830 | (R)BH-T864<br>(L)BH-T864 | | | (オートマチック) | | | | | |
| | GH-JZS177<br><TA-は00. 8～> | マジェスタ | 99.9-01.8<br>01.8-04.6 | | | | 99.9-04.6 | | DISC | MP-77 | CPM-77 | 99.9-04.6 | | DISC | MP-87 | | 99.9-04.6 | BH-T753 | (R)BH-T766<br>(L)BH-T766 | | | (オートマチック) | | | | | |
| | GH-JZS179(4WD)<br><TA-は00. 8～> | | 99.9-01.8<br>01.8-03.12 | | | | 99.9-03.12 | | DISC | MP-121 | CPM-121 | 99.9-03.12 | | DISC | MP-79 | CPM-79 | 99.9-03.12 | BH-T691 | (R)BH-T864<br>(L)BH-T864 | | | (オートマチック) | | | | | |
| (4000) | GH-UZS171・175<br><TA-は00. 8～> | マジェスタ | 99.9-01.8<br>01.8-04.6 | | | | 99.9-04.6 | | DISC | MP-77 | CPM-77 | 99.9-04.6 | | DISC | MP-87 | | 99.9-04.6 | BH-T753 | (R)BH-T766<br>(L)BH-T766 | | | (オートマチック) | | | | | |
| | GH-UZS173(4WD) | マジェスタ | 99.9-01.8<br>01.8-04.6 | | | | 99.9-04.6 | | DISC | MP-77 | CPM-77 | 99.9-04.6 | | DISC | MP-87 | | 99.9-04.6 | BH-T670 | (R)BH-T766<br>(L)BH-T766 | | | (オートマチック) | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CROWN : 180 ser.(03.12-) | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2500) | UA－GRS180　除くパトロールカーアスリート<br>＜CBA－は04．2～＞<br>＜DBA－は04．8～＞ | 03.12-08.2 | | | キットセッテイナシ | 03.12-08.2 | | DISC | MP-112 | CPM-112 | 03.12-05.11<br>05.11-08.2 | | DISC<br>DISC | SP-418<br>MP-117 | CPM-117<br>CPM-117 | 03.12-08.2 | | (R)<br>(L) | | | (オートマチック) | | | | | |
| | 除くアスリート | 03.12-08.2 | | | キットセッテイナシ | 03.12-08.2 | | DISC | MP-112 | CPM-112 | 03.12-05.11<br>05.11-08.2 | | DISC<br>DISC | SP-417<br>MP-113 | CPM-113<br>CPM-113 | 03.12-08.2 | | (R)<br>(L) | | | (オートマチック) | | | | | |
| | パトロールカー | 05.10-10.10 | | | キットセッテイナシ | 05.10-10.10 | | DISC | MP-112 | CPM-112 | 05.10-05.11<br>05.11-10.10 | | DISC<br>DISC | SP-417<br>MP-113 | CPM-113<br>CPM-113 | 05.10-10.10 | | (R)<br>(L) | | | (オートマチック) | | | | | |
| | CBA－GRS181 除くパトロールカーアスリート<br>＜DBA－は04．8～＞ | 04.8-08.2 | | | キットセッテイナシ | 04.8-08.2 | | DISC | MP-112 | CPM-112 | 04.8-05.11<br>05.11-08.2 | | DISC<br>DISC | SP-418<br>MP-117 | CPM-117<br>CPM-117 | 04.8-08.2 | | (R)<br>(L) | | | (オートマチック) | | | | | |
| | 除くアスリート | 04.8-08.2 | | | キットセッテイナシ | 04.8-08.2 | | DISC | MP-112 | CPM-112 | 04.8-05.11<br>05.11-08.2 | | DISC<br>DISC | SP-417<br>MP-113 | CPM-113<br>CPM-113 | 04.8-08.2 | | (R)<br>(L) | | | (オートマチック) | | | | | |
| | パトロールカー | 05.10-10.10 | | | キットセッテイナシ | 05.10-10.10 | | DISC | MP-112 | CPM-112 | 05.10-05.11<br>05.11-10.10 | | DISC<br>DISC | SP-417<br>MP-113 | CPM-113<br>CPM-113 | 05.10-10.10 | | (R)<br>(L) | | | (オートマチック) | | | | | |
| (3000) | UA－GRS182　除くパトロールカーアスリート<br>＜CBA－は04．2～＞<br>＜DBA－は04．8～＞ | 03.12-08.2 | | | キットセッテイナシ | 03.12-08.2 | | DISC | MP-112 | CPM-112 | 03.12-05.11<br>05.11-08.2 | | DISC<br>DISC | SP-418<br>MP-117 | CPM-117<br>CPM-117 | 03.12-08.2 | | (R)<br>(L) | | | (オートマチック) | | | | | |
| | 除くアスリート | 03.12-08.2 | | | キットセッテイナシ | 03.12-08.2 | | DISC | MP-112 | CPM-112 | 03.12-05.11<br>05.11-08.2 | | DISC<br>DISC | SP-417<br>MP-113 | CPM-113<br>CPM-113 | 03.12-08.2 | | (R)<br>(L) | | | (オートマチック) | | | | | |
| | パトロールカー | 05.10-10.10 | | | キットセッテイナシ | 05.10-10.10 | | DISC | MP-112 | CPM-112 | 05.10-05.11<br>05.11-10.10 | | DISC<br>DISC | SP-417<br>MP-113 | CPM-113<br>CPM-113 | 05.10-10.10 | | (R)<br>(L) | | | (オートマチック) | | | | | |
| | UA－GRS183（4WD）<br>＜CBA－は04．2～＞<br>＜DBA－は04．8～＞ | 03.12-08.2 | | | キットセッテイナシ | 03.12-08.2 | | DISC | MP-112 | CPM-112 | 03.12-05.11<br>05.11-08.2 | | DISC<br>DISC | SP-417<br>MP-113 | CPM-113<br>CPM-113 | 03.12-08.2 | | (R)<br>(L) | | | (オートマチック) | | | | | |
| | DBA－GRS184 | 05.10-08.2 | | | キットセッテイナシ | 05.10-08.2 | | DISC | SP-112 | CPS-112 | 05.10-05.11<br>05.11-08.2 | | DISC<br>DISC | SP-418<br>MP-117 | CPM-117<br>CPM-117 | 05.10-08.2 | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| (4300) | DBA－UZS186 | 03.12-08.2 | | | キットセッテイナシ | 03.12-08.2 | | DISC | MP-112 | CPM-112 | 03.12-05.11<br>05.11-08.2 | | DISC<br>DISC | SP-418<br>MP-117 | CPM-117<br>CPM-117 | 03.12-07.1<br>07.1-08.2 | (R)<br>(L)<br>(R)<br>(L) | (R)<br>(L)<br>(R)<br>(L) | | | (オートマチック) | | | | | |
| | DBA－UZS187（4WD） | 03.12-08.2 | | | キットセッテイナシ | 03.12-08.2 | | DISC | MP-112 | CPM-112 | 03.12-05.11<br>05.11-08.2 | | DISC<br>DISC | SP-418<br>MP-117 | CPM-117<br>CPM-117 | 03.12-07.1<br>07.1-08.2 | (R)<br>(L)<br>(R)<br>(L) | (R)<br>(L)<br>(R)<br>(L) | | | (オートマチック) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CROWN : 200 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2500) | DBA－GRS200 | ロイヤルサルーン | 08.2-12.12 | 7/8 | TD-T931 | ｷｯﾄｾｯﾃｲﾅｼ | 08.2-12.12 | | DISC | MP-112 | | 08.2-12.12 | | DISC | MP-113 | CPM-113 | 08.2-12.12 | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | | アスリート | 08.2-12.12 | 7/8 | TD-T931 | ｷｯﾄｾｯﾃｲﾅｼ | 08.2-12.12 | | DISC | MP-112 | | 08.2-12.12 | | DISC | MP-117 | CPM-117 | 08.2-12.12 | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | | パトロールカー | 10.10- | 7/8 | TD-T931 | ｷｯﾄｾｯﾃｲﾅｼ | 10.10- | | DISC | MP-112 | CPM-112 | 10.10-14.6<br>14.6- | | DISC<br>DISC | MP-113<br>SP-462 | CPM-113<br>CPM-113 | 10.10- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | DBA－GRS201 4WD | ロイヤルサルーン | 08.2-12.12 | 7/8 | TD-T931 | ｷｯﾄｾｯﾃｲﾅｼ | 08.2-12.12 | | DISC | MP-112 | | 08.2-12.12 | | DISC | MP-113 | CPM-113 | 08.2-12.12 | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | | アスリート | 08.2-12.12 | 7/8 | TD-T931 | ｷｯﾄｾｯﾃｲﾅｼ | 08.2-12.12 | | DISC | MP-112 | | 08.2-12.12 | | DISC | MP-117 | CPM-117 | 08.2-12.12 | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | | パトロールカー | 10.10- | 7/8 | TD-T931 | ｷｯﾄｾｯﾃｲﾅｼ | 10.10- | | DISC | MP-112 | CPM-112 | 10.10-14.6<br>14.6- | | DISC<br>DISC | MP-113<br>SP-462 | CPM-113<br>CPM-113 | 10.10- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (3000) | DBA－GRS202 | | 08.2-12.12 | 7/8 | TD-T931 | ｷｯﾄｾｯﾃｲﾅｼ | 08.2-12.12 | | DISC | MP-112 | | 08.2-12.12 | | DISC | MP-113 | CPM-113 | 08.2-12.12 | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | | パトロールカー | 10.10- | 7/8 | TD-T931 | ｷｯﾄｾｯﾃｲﾅｼ | 10.10- | | DISC | MP-112 | CPM-112 | 10.10-14.6<br>14.6- | | DISC<br>DISC | MP-117 | CPM-117 | 10.10- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | DBA－GRS203 4WD | | 08.2-12.12 | 7/8 | TD-T931 | ｷｯﾄｾｯﾃｲﾅｼ | 08.2-12.12 | | DISC | MP-112 | | 08.2-12.12 | | DISC | MP-113 | CPM-113 | 08.2-12.12 | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (3500) | DBA－GRS204 | | 08.2-12.12 | 7/8 | TD-T931 | ｷｯﾄｾｯﾃｲﾅｼ | 08.2-12.12 | | DISC | SP-112 | CPS-112 | 08.2-12.12 | | DISC | SP-412 | CPS-412 | 08.2-12.12 | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | DAA－GWS204 | ハイブリッド | 08.5-12.12 | | | ｷｯﾄｾｯﾃｲﾅｼ | 08.5-12.12 | | DISC | SP-112 | CPS-112 | 08.5-12.12 | | DISC | MP-117 | CPM-117 | 08.2-12.12 | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (4300) | DBA－UZS207 | マジェスタ | 09.3-13.7 | 7/8 | TD-T931 | ｷｯﾄｾｯﾃｲﾅｼ | 09.3-13.7 | | DISC | MP-112 | | 09.3-13.7 | | DISC | MP-117 | CPM-117 | 09.3-13.7 | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (4600) | DBA－URS206 | マジェスタ | 09.3-13.7 | | | ｷｯﾄｾｯﾃｲﾅｼ | 09.3-13.7 | | DISC | SP-112 | CPS-112 | 09.3-13.7 | | DISC | MP-117 | CPM-117 | 09.3-13.7 | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CROWN : 210, 220 ser.(12.12-) | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000) | DBA－ARS210 | | 15.9-18.6 | | | キットセッテイナシ | 15.9-18.6 | | DISC | MP-112 | CPM-112 | 15.9-18.6 | | DISC | SP-462 | CPM-113 | 15.9-18.6 | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| | 3BA－ARS220 | | 18.6- | | | キットセッテイナシ | 18.6- | | DISC | | CPM-116 | 18.6- | | DISC | | CPM-113 | 18.6- | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| | | パトロールカー | 21.6- | | | キットセッテイナシ | 21.6- | | DISC | | CPM-116 | 21.6- | | DISC | | | 21.6- | (R)<br>(L) | (R)<br>(L) | | | | | | | | |
| (2500) | DAA－AWS210 | ハイブリッド | 13.1-18.6 | | | キットセッテイナシ | 13.1-18.6 | | DISC | MP-112 | CPM-112 | 13.1-14.6<br>14.6-18.6 | | DISC<br>DISC | MP-113<br>SP-462 | CPM-113<br>CPM-113 | 13.1-18.6 | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| | DAA－AWS211 | ハイブリッド | 14.7-18.6 | | | キットセッテイナシ | 14.7-18.6 | | DISC | MP-112 | CPM-112 | 14.7-18.6 | | DISC | SP-462 | CPM-113 | 14.7-18.6 | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| | DAA－AWS215 | マジェスタ | 14.7-18.4 | | | キットセッテイナシ | 14.7-18.4 | | DISC | MP-112 | CPM-112 | 14.7-18.4 | | DISC | SP-462 | CPM-113 | 14.7-18.4 | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| | DBA－GRS210 | アスリート<br>ロイヤル・ロイヤルサルーン | 12.12-18.6 | 7/8 | TD-T931 | キットセッテイナシ | 12.12-18.6 | | DISC | MP-112 | CPM-112 | 12.12-14.6<br>14.6-18.6 | | DISC<br>DISC | MP-113<br>SP-462 | CPM-113<br>CPM-113 | 12.12-18.6 | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| | | パトロールカー | 16.4- | | | キットセッテイナシ | 16.4- | | DISC | MP-112 | CPM-112 | 16.4- | | DISC | SP-462 | CPM-113 | 16.4- | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| | DBA－GRS211 4WD | アスリート<br>ロイヤル・ロイヤルサルーン | 12.12-18.6 | 7/8 | TD-T931 | キットセッテイナシ | 12.12-18.6 | | DISC | MP-112 | CPM-112 | 12.12-14.6<br>14.6-18.6 | | DISC<br>DISC | MP-113<br>SP-462 | CPM-113<br>CPM-113 | 12.12-13.7<br>13.7-18.6 | (R)<br>(L)<br>(R)<br>(L) | (R)<br>(L)<br>(R)<br>(L) | | | (オートマチック) | | | | | |
| | | パトロールカー | 16.4- | | | キットセッテイナシ | 16.4- | | DISC | MP-112 | CPM-112 | 16.4- | | DISC | SP-462 | CPM-113 | 16.4- | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| (3500) | DBA－GRS214 | アスリート<br>ロイヤル・ロイヤルサルーン | 12.12-18.6 | 7/8 | TD-T931 | キットセッテイナシ | 12.12-18.6 | | DISC | SP-112 | CPS-112 | 12.12-13.8<br>13.8-18.6 | | DISC<br>DISC | SP-412 | CPS-412<br>CPS-412 | 12.12-18.6 | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| | | パトロールカー | 16.4- | | | キットセッテイナシ | 16.4- | | DISC | SP-112 | CPS-112 | 16.4- | | DISC | | CPS-412 | 16.4- | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| | DAA－GWS214 | マジェスタ | 13.9-18.4 | | | キットセッテイナシ | 13.9-18.4 | | DISC | SP-112 | CPS-112 | 13.9-18.4 | | DISC | | CPS-412 | 13.9-18.4 | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| | 6AA－GWS224 | | 18.6- | | | キットセッテイナシ | 18.6- | | DISC | | CPS-400 | 18.6- | | DISC | | | 18.6- | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CROWN : 20, 30 ser.(2018.6-) | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2500) | 6AA－AZSH20 | | 18.6- | | | キットセッテイナシ | 18.6- | | DISC | | CPM-116 | 18.6- | | DISC | | | 18.6- | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| | 6AA－AZSH21 | 4WD | 18.6- | | | キットセッテイナシ | 18.6- | | DISC | | CPM-116 | 18.6- | | DISC | | | 18.6- | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| | | パトロールカー | 21.6- | | | キットセッテイナシ | 21.6- | | DISC | | CPM-116 | 21.6- | | DISC | | | 21.6- | (R)<br>(L) | (R)<br>(L) | | | | | | | | |
| | 6AA－AZSH32 | | 23.11- | | | キットセッテイナシ | 23.11- | | DISC | | | 23.11- | | DISC | | | 23.11- | | | | | | | | | | |
| | 5AA－AZSH35 | | 22.9- | | | キットセッテイナシ | 22.9- | | DISC | | | 22.9- | | DISC | | | 22.9- | | | | | | | | | | |
| | 6AA－AZSH36 | | 23.8- | | | キットセッテイナシ | 23.8- | | DISC | C-815P | | 23.8- | | DISC | | | 23.8- | | | | | | | | | | |
| | 6LA－AZSH37 | | 23.12- | | | キットセッテイナシ | 23.12- | | DISC | | | 23.12- | | DISC | SP-482 | | 23.12- | | | | | | | | | | |
| | 6AA－AZSH38 | | 25.2- | | | キットセッテイナシ | 25.2- | | DISC | | | 25.2- | | DISC | | | 25.2- | | | | | | | | | | |
| | | G | 25.2- | | | キットセッテイナシ | 25.2- | | DISC | | | 25.2- | | DISC | SP-482 | | 25.2- | | | | | | | | | | |
| | | RS･Z | 25.2- | | | キットセッテイナシ | 25.2- | | DISC | | | 25.2- | | DISC | SP-482 | | 25.2- | | | | | | | | | | |
| (3500) | ZBA－KZSM30 | | 23.11- | | | キットセッテイナシ | 23.11- | | MD-446 | | CPS-400 | 23.11- | | DISC | | | 23.11- | | | | | | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CROWN SEDAN : 10 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000) | ZA－GBS12<br>TA－GXS12 | 01.8- | 1 | | TK-T377 | 01.8- | 60.6 | DISC | SP-299 | CPS-299 | 01.8- | 15/16 | (R)WC-T746<br>(L)WC-T746 | WK-1003 | CUP | 01.8- | BH-T821 | BH-T822 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (2000LPG) | TA－GXS10<br>TA－YXS10 | 01.8-<br><ｱﾝﾁｽｷｯﾄﾞ付><br>01.8- | 1 5/16<br>1 | | TK-T325<br><br>TK-T377 | 01.8- | 60.6 | DISC | SP-299 | CPS-299 | 01.8- | 15/16 | (R)WC-T746<br>(L)WC-T746 | WK-1003 | CUP | 01.8- | BH-T821 | BH-T822 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CROWN COMFORT, COMFORT : 10 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) | E－SXS11Y | 教習車 | <生徒側><br>96.4-01.8 | 15/16 | | TK-T403 | 96.4-97.1 | 60.6 | DISC | SP-251 | CPS-249 | 96.4-01.8 | 15/16 | (R)WC-T747 | WK-836 | CUP | 96.4-01.8 | BH-T821 | BH-T822 | 96.4-01.8 | 5/8 | | MK-T244 | 96.4-01.8 | 13/16 | | CK-T201 |
| | ＜GF－は99．1～＞ | | <ｱﾝﾁｽｷｯﾄﾞ付><br>97.1-01.8 | 1 | | TK-T404 | 97.1-01.8 | 60.6 | DISC | SP-299 | CPS-299 | | | (L)WC-T747 | | | | | | | | | | | | | |
| | | | <教官側><br>96.4-01.8 | | | TK-T446 | | | | | | | | | | | | | | | | | | | | | |
| (2000)<br>(2000LPG) | TA－SXS13Y<br>E－YXS11Y | 教習車 | <生徒側><br>96.4-08.8 | 15/16 | | TK-T403 | 96.4-97.1<br>97.1-06.7 | 60.6<br>60.6 | DISC<br>DISC | SP-251<br>SP-299 | CPS-249<br>CPS-299 | 96.4-08.8 | 15/16 | (R)WC-T747<br>(L)WC-T747 | WK-836 | CUP | 96.4-08.8 | BH-T821 | BH-T822 | <SXS><br>01.8-07.9 | 5/8 | | MK-T244 | <SXS><br>01.8-07.9 | 13/16 | | CK-T201 |
| | ＜GF－は99．1～＞<br>＜TA－は01．8～＞<br>＜ABA－は04．6～＞ | | <ｱﾝﾁｽｷｯﾄﾞ付><br>97.1-08.8<br><教官側><br>96.4-08.8 | 1 | | TK-T404<br>TK-T446 | 06.7- | 60.6 | DISC | SP-199 | CPS-299 | | | | | | | | | <YXS><br>96.4-08.8 | 5/8 | MC-T451 | MK-T236 | <YXS><br>96.4-08.8 | 13/16 | CC-T317 | CK-T201 |
| (2000LPG) | E－GXS10<br>E－YXS10<br>＜GF－は99．1～＞<br>＜TA－は01．8～＞<br>＜ABA－は04．6～＞ | | 95.12-08.8<br><ｱﾝﾁｽｷｯﾄﾞ付><br>97.1-08.8 | 15/16<br><br>1 | TD-T911<br><br>TD-T919 | TK-T325<br><br>TK-T377 | 95.12-97.1<br>97.1-06.7<br>06.7- | 60.6<br>60.6 | DISC<br>DISC<br>DISC | SP-251<br>SP-299<br>SP-199 | CPS-249<br>CPS-299<br>CPS-299 | 95.12-97.1<br><br>97.1-98.5<br><br>98.5-01.8<br><br>01.8-08.8 | 15/16<br><br>15/16<br><br>15/16<br><br>15/16 | (R)WC-T747<br>(L)WC-T747<br>(R)WC-T746<br>(L)WC-T746<br>(R)WC-50047<br>(L)WC-50047<br>(R)WC-T746<br>(L)WC-T746 | WK-836<br><br>WK-884<br><br>WK-309<br><br>WK-1003 | CUP<br><br>CUP<br><br>CUP<br><br>CUP | 95.12-08.8 | BH-T821 | BH-T822 | 95.12-08.8 | 5/8 | MC-T451 | MK-T236 | 95.12-08.8 | 13/16 | CC-T317 | CK-T201 |
| | E－YXS11<br>＜GF－は99．1～＞<br>＜TA－は01．8～＞<br>＜ABA－は04．6～＞ | | 95.12-08.8<br><ｱﾝﾁｽｷｯﾄﾞ付><br>97.1-08.8 | 15/16<br><br>1 | TD-T911<br><br>TD-T919 | TK-T325<br><br>TK-T377 | 95.12-97.1<br>97.1-06.7<br>06.7- | 60.6<br>60.6 | DISC<br>DISC<br>DISC | SP-251<br>SP-299<br>SP-199 | CPS-249<br>CPS-299<br>CPS-299 | 95.12-97.1<br><br>97.1-98.5<br><br>98.5-01.8<br><br>01.8-08.8 | 15/16<br><br>15/16<br><br>15/16<br><br>15/16 | (R)WC-T747<br>(L)WC-T747<br>(R)WC-T746<br>(L)WC-T746<br>(R)WC-50047<br>(L)WC-50047<br>(R)WC-T746<br>(L)WC-T746 | WK-836<br><br>WK-884<br><br>WK-309<br><br>WK-1003 | CUP<br><br>CUP<br><br>CUP<br><br>CUP | 95.12-08.8 | BH-T821 | BH-T822 | 95.12-08.8 | 5/8 | MC-T451 | MK-T236 | 95.12-08.8 | 13/16 | CC-T317 | CK-T201 |
| | DBA－TSS10・11 | | 08.8- | 1 | TD-T919 | TK-T377 | 08.8- | | DISC | SP-199 | CPS-299 | 08.8- | 15/16 | (R)WC-T746<br>(L)WC-T746 | WK-1003 | CUP | 08.8- | BH-T821 | BH-T822 | 08.8- | 5/8 | | MK-T244 | 08.8- | 13/16 | CC-T330 | CK-T232 |
| | DBA－TSS11Y・13Y | 教習車 | <生徒側><br>07.9- | 1 | | TK-T404 | 07.9- | | DISC | SP-199 | CPS-299 | 07.9-08.8 | 15/16 | (R)WC-T747<br>(L)WC-T747 | WK-836 | | 07.9- | BH-T821 | BH-T822 | 07.9- | 5/8 | | MK-T244 | 07.9-08.7 | 13/16 | CC-T330 | CK-T201 |
| | | | <教官側><br>07.9- | | | TK-T446 | | | | | | 08.8- | 15/16 | (R)WC-T746<br>(L)WC-T746 | WK-1003 | | | | | | | | | 08.8- | 13/16 | CC-T330 | CK-T232 |
| (2400ディーゼル) | KD－LXS11 | | 95.12-99.8<br><ｱﾝﾁｽｷｯﾄﾞ付><br>97.1-99.8 | 15/16<br><br>1 | TD-T911<br><br>TD-T919 | TK-T325<br><br>TK-T377 | 95.12-97.1<br>97.1-01.8 | 60.6<br>60.6 | DISC<br>DISC | SP-251<br>SP-299 | CPS-249<br>CPS-299 | 95.12-97.1<br><br>97.1-98.5<br><br>98.5-99.8 | 15/16<br><br>15/16<br><br>15/16 | (R)WC-T747<br>(L)WC-T747<br>(R)WC-T746<br>(L)WC-T746<br>(R)WC-50047<br>(L)WC-50047 | WK-836<br><br>WK-884<br><br>WK-309 | CUP<br><br>CUP<br><br>CUP | 95.12-01.8 | BH-T821 | BH-T822 | 95.12-99.8 | 5/8 | MC-T452 | MK-T244 | 95.12-99.8 | 13/16 | CC-70171 | CK-T201 |
| | KD－LXS11Y | 教習車 | <生徒側><br>96.4-99.8<br><ｱﾝﾁｽｷｯﾄﾞ付><br>97.1-99.8<br><教官側><br>96.4-99.8 | 15/16<br><br>1 | | TK-T403<br><br>TK-T404<br><br>TK-T446 | 96.4-97.1<br>97.1-01.8 | 60.6<br>60.6 | DISC<br>DISC | SP-251<br>SP-299 | CPS-249<br>CPS-299 | 96.4-99.8 | 15/16 | (R)WC-T747<br>(L)WC-T747 | WK-836 | CUP | 96.4-99.8 | BH-T821 | BH-T822 | 96.4-99.8 | 5/8 | MC-T452 | MK-T244 | 96.4-99.8 | 13/16 | CC-70171 | CK-T201 |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| JPN TAXI : 10 ser. | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1500LPG) DAA－NTP10 | 17.10- | | | | 17.10- | | DISC | MP-116 | CPM-116 | 17.10- | 13/16 | (R)WC-T809<br>(L)WC-T809 | WK-1092 | CUP | 17.10- | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| ARISTO : 140 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (3000) | E－JZS147 | 91.10-95.8 | 1 1/16 | | TK-T332 | <ﾀｰﾎﾞ車><br>91.10-93.8 | 44.4 | DISC | MP-47 | | <ﾀｰﾎﾞ車><br>91.10-95.8 | 42.8 | DISC | MP-48 | | 91.10-97.8 | BH-T669 | (R)BH-T574 | | | (ｵｰﾄﾏﾁｯｸ) | | | | |
| | | 95.8-97.8 | 1 | | TK-T412 | 93.8-95.3 | 44.4 | DISC | MP-47 | | 95.8-97.8 | | DISC | MP-66 | | | | (L)BH-T574 | | | | | | | | |
| | | <油圧ﾌﾞｰｽﾀｰ><br>91.10-97.8 | | | | 95.3-95.8<br>95.8-97.8 | | DISC<br>DISC | MP-71<br>MP-77 | <br>CPM-77 | <除くﾀｰﾎﾞ車><br>91.10-95.8 | 42.8 | <br>DISC | <br>MP-48 | | | | | | | | | | | | |
| | | | | | | <除くﾀｰﾎﾞ車><br>91.10-95.3 | 44.4 | DISC | MP-47 | | 95.8-97.8 | | DISC | MP-66 | | | | | | | | | | | | |
| | | | | | | 95.3-95.8 | | DISC | MP-71 | | | | | | | | | | | | | | | | | |
| | | | | | | 95.8-97.8 | | DISC | MP-77 | CPM-77 | | | | | | | | | | | | | | | | |
| (4000) | E－UZS143(4WD) | 92.10-97.8 | | | | 92.10-95.3 | 44.4 | DISC | MP-47 | | 92.10-95.8 | 42.8 | DISC | MP-48 | | 92.10-95.8 | | (R)BH-T574 | | | (ｵｰﾄﾏﾁｯｸ) | | | | |
| | | | | | | 95.3-95.8 | | DISC | MP-71 | | 95.8-97.8 | | DISC | MP-66 | | | | (L)BH-T574 | | | | | | | | |
| | | | | | | 95.8-97.8 | | DISC | MP-77 | CPM-77 | | | | | | 95.8-97.8 | BH-T670 | (R)BH-T574 | | | | | | | | |
| | | | | | | | | | | | | | | | | | | (L)BH-T574 | | | | | | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| ARISTO : 160 ser.(97.8-) | | | | | | | | | | | | | | | | | | | | | | | | | |
| (3000) E-JZS160・161<br><GF-は99．8～><br><GH・TA-は00．7～> | 97.8-00.7<br>00.7- | | | | 97.8- | | DISC | MP-77 | CPM-77 | 97.8- | | DISC | MP-80 | | 97.8- | BH-T753 | (R)BH-T766<br>(L)BH-T766 | | | (オートマチック) | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| PROGRES : 10 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2500) | GF－JCG10<br>＜TA－は01．4～＞ | 98.5- | | | | <4速AT車><br>98.5-<br>01.4-<br><5速AT車><br>01.4- | | DISC<br>DISC<br>DISC | MP-121<br>MP-121<br>MP-121 | CPM-121<br>CPM-112<br>CPM-112 | 98.5- | | DISC | MP-80 | | 98.5- | BH-T830 | (R)BH-T864<br>(L)BH-T864 | | | (オートマチック) | | | | |
| | GH－JCG15(4WD)<br>＜TA－は00．5～＞ | 99.12- | | | | 99.12- | | DISC | MP-121 | CPM-121 | 99.12- | | DISC | MP-80 | | 99.12- | BH-T691 | (R)BH-T864<br>(L)BH-T864 | | | (オートマチック) | | | | |
| (3000) | GF－JCG11<br>＜TA－は01．4～＞ | 98.5- | | | | <4速AT車><br>98.5-01.4<br>01.4-<br><5速AT車><br>01.4- | | DISC<br>DISC<br>DISC | MP-121<br>MP-121<br>MP-121 | CPM-121<br>CPM-112<br>CPM-112 | 98.5- | | DISC | MP-80 | | 98.5- | BH-T830 | (R)BH-T864<br>(L)BH-T864 | | | (オートマチック) | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| ORIGIN : 10 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (3000) | GF－JCG17 | 00.7- | | | | 00.7- | | DISC | MP-121 | CPM-112 | 00.7- | | DISC | MP-80 | | 00.7- | BH-T830 | (R)BH-T864<br>(L)BH-T864 | | | (オートマチック) | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| BREVIS : 10 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2500) | TA－JCG10 | 01.5- | | | | 01.5- | | DISC | MP-121 | CPM-112 | 01.5- | | DISC | MP-80 | | 01.5- | BH-T830 | (R)BH-T864<br>(L)BH-T864 | | | (オートマチック) | | | | | |
| | TA－JCG15(4WD) | 01.10- | | | | 01.10- | | DISC | MP-121 | CPM-121 | 01.10- | | DISC | MP-80 | | 01.10- | BH-T691 | (R)BH-T864<br>(L)BH-T864 | | | (オートマチック) | | | | | |
| (3000) | TA－JCG11 | 01.5- | | | | 01.5- | | DISC | MP-121 | CPM-112 | 01.5- | | DISC | MP-80 | | 01.5- | BH-T830 | (R)BH-T864<br>(L)BH-T864 | | | (オートマチック) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| ALTEZZA : 10 ser.(98.10-) | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000) | GF－GXE10<br>＜TA－は00．5～＞ | 15インチホイール車 | 98.10- | 1 | | TK-T441 | 98.10-<br>＜ﾃﾞｨｽﾁｬｰｼﾞ付＞<br>98.10-02.8<br>02.8- | | DISC<br><br>DISC<br>DISC | MP-121<br><br>MP-121<br>MP-121 | CPM-121<br><br>CPM-121<br>CPM-121 | 98.10- | | DISC | MP-87 | | 98.10-00.5<br><br>00.5- | BH-T774<br><br>BH-T830 | (R)BH-T773<br>(L)BH-T773<br>(R)BH-T864<br>(L)BH-T864 | 98.10-00.5<br>00.5- | 5/8 | (ｵｰﾄﾏﾁｯｸ) | MK-T244 | 00.5-00.10<br>00.10- | | | CK-T229<br>CK-T229 |
| | | 17インチホイール車 | 00.5- | 1 1/16 | | | 00.5- | | DISC | MP-77 | CPM-77 | 00.5- | | DISC | MP-79 | CPM-79 | 00.5- | BH-T830 | (R)BH-T864<br>(L)BH-T864 | 00.5- | 5/8 | | MK-T244 | 00.5-00.10<br>00.10- | | | CK-T229<br>CK-T229 |
| | TA－GXE10W | 15インチホイール車 | 01.6-<br>＜ﾄﾗｸｼｮﾝｺﾝﾄﾛｰﾙ付＞<br>01.6- | 1 | | TK-T441 | 01.6- | | DISC | MP-121 | CPM-121 | 01.6- | | DISC | MP-87 | | 01.6- | BH-T830 | (R)BH-T864<br>(L)BH-T864 | 01.6- | 5/8 | | MK-T244 | 01.6-00.10<br>00.10- | | | CK-T229<br>CK-T229 |
| | | 17インチホイール車 | 01.6-<br>＜ﾄﾗｸｼｮﾝｺﾝﾄﾛｰﾙ付＞<br>01.6- | 1 1/16 | | | 01.6- | | DISC | MP-77 | CPM-77 | 01.6- | | DISC | MP-79 | CPM-79 | 01.6- | BH-T830 | (R)BH-T864<br>(L)BH-T864 | 01.6- | 5/8 | | MK-T244 | 01.6-00.10<br>00.10- | | | CK-T229<br>CK-T229 |
| | TA－GXE15W(4WD) | | 02.1- | | | | 02.1- | | DISC | MP-77 | CPM-77 | 02.1- | | DISC | MP-79 | CPM-79 | 02.1- | | (R)BH-T864<br>(L)BH-T864 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | GF－SXE10<br>＜GH－は01．5～＞ | MT | 98.10- | 1 1/16 | | | 98.10- | | DISC | MP-77 | CPM-77 | 98.10- | | DISC | MP-79 | CPM-79 | 98.10-00.5<br><br>00.5- | BH-T774<br><br>BH-T830 | (R)BH-T773<br>(L)BH-T773<br>(R)BH-T864<br>(L)BH-T864 | 98.10- | 5/8 | | MK-T244 | 98.10-00.5<br>00.5- | 7/8 | CC-70127 | CK-3122<br>CK-T229 |
| | | AT | 98.10-<br>＜17ｲﾝﾁﾎｲｰﾙ＞<br>98.10- | 1<br><br>1 1/16 | | TK-T441 | 98.10-01.5<br>01.5-02.12<br>0212-<br>＜17ｲﾝﾁﾎｲｰﾙ＞<br>98.10- | | DISC<br>DISC<br>DISC<br><br>DISC | MP-121<br>MP-121<br>MP-121<br><br>MP-77 | CPM-121<br>CPM-121<br>CPM-121<br><br>CPM-77 | 98.10-<br>＜17ｲﾝﾁﾎｲｰﾙ＞<br>98.10- | | DISC<br><br>DISC | MP-87<br><br>MP-79 | <br><br>CPM-79 | 98.10-00.5<br><br>00.5- | BH-T774<br><br>BH-T830 | (R)BH-T773<br>(L)BH-T773<br>(R)BH-T864<br>(L)BH-T864 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (3000) | TA－JCE10W | | 01.6- | | | | 01.6- | | DISC | MP-77 | CPM-77 | 01.6- | | DISC | MP-79 | CPM-79 | 01.6- | BH-T830 | (R)BH-T864<br>(L)BH-T864 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | TA－JCE15W(4WD) | | 01.6-<br>＜VSC付＞<br>01.6- | 1 1/16 | | | 01.6- | | DISC | MP-77 | CPM-77 | 01.6- | | DISC | MP-79 | CPM-79 | 01.6- | | (R)BH-T864<br>(L)BH-T864 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |

| Models | TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| SOARER : 10 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000) | E−GZ10 | Vα・Vβ・VR・VX・GT | 81.2–85.12 | 15/16 | | TK-9417 | 81.2–85.12 | 2 1/4 | DISC | SP-229 | CPS-219 | 81.2–82.5<br>82.5–85.12 | 1 11/16<br>1 11/16 | DISC<br>DISC | SP-218<br>SP-218 | | 81.2–85.4<br><br><br><br>85.4–85.12 | (1)BH-02424<br>(2)BH-96002<br><br><br><br>BH-02475 | (R-1)BH-95001<br>(L-1)BH-95001<br>(R-2)BH-02343<br>(L-2)BH-02343<br>(R-1)BH-95001<br>(L-1)BH-95001<br>(R-2)BH-02343<br>(L-2)BH-02343 | 81.2–81.6<br>81.6–83.5<br>83.5–85.12 | 5/8<br>5/8<br>5/8 | MC-10115<br>MC-10110<br>MC-10141 | MK-4312<br>MK-4312<br>MK-4312 | 81.2–85.12 | 13/16 | CC-70133 | CK-3144 |
| | E−MZ10 | Vβ・VR・ターボ | 81.7–85.12 | 15/16 | | TK-9419 | 81.7–85.12 | 2 1/4 | DISC | SP-229 | CPS-219 | 81.7–82.5<br>82.5–85.12 | 1 11/16<br>1 11/16 | DISC<br>DISC | SP-218<br>SP-218 | | 81.7–85.4<br><br><br><br>85.4–85.12 | (1)BH-02424<br>(2)BH-96002<br><br><br><br>BH-02475 | (R-1)BH-95001<br>(L-1)BH-95001<br>(R-2)BH-02343<br>(L-2)BH-02343<br>(R-1)BH-95001<br>(L-1)BH-95001<br>(R-2)BH-02343<br>(L-2)BH-02343 | | | (オートマチック) | | | | |
| (2800) | E−MZ11 | GT・GTエクストラ<br>GTリミテッド | 81.2–85.1 | 15/16 | | TK-9417 | 81.2–85.1 | 2 1/4 | DISC | SP-229 | CPS-219 | 81.2–82.5<br>82.5–85.12 | 1 11/16<br>1 11/16 | DISC<br>DISC | SP-218<br>SP-218 | | 81.2–85.1 | (1)BH-02424<br>(2)BH-96002 | (R-1)BH-95001<br>(L-1)BH-95001<br>(R-2)BH-02343<br>(L-2)BH-02343 | 81.2–83.5<br>83.5–85.1 | 5/8<br>5/8 | MC-10074<br>MC-10102 | MK-4300<br>MK-4300 | 81.2–85.1 | 13/16 | CC-70133 | CK-3144 |
| (3000) | E−MZ12 | GT・GTリミテッド | 85.1–85.12 | 15/16 | | TK-9417 | 85.1–85.12 | 2 1/4 | DISC | SP-229 | CPS-229 | 85.1–85.12 | 1 11/16 | DISC | SP-218 | | 85.1–85.4<br><br><br><br>85.4–85.12 | (1)BH-02424<br>(2)BH-96002<br><br><br><br>BH-02475 | (R-1)BH-95001<br>(L-1)BH-95001<br>(R-2)BH-02343<br>(L-2)BH-02343<br>(R-1)BH-95001<br>(L-1)BH-95001<br>(R-2)BH-02343<br>(L-2)BH-02343 | 85.1–85.2<br>85.2–85.12 | 5/8<br>5/8 | MC-10102<br>MC-10141 | MK-4300<br>MK-4312 | 85.1–85.12 | 13/16 | CC-70133 | CK-3144 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| SOARER : 20 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000) | E－GZ20 | VZ・VX | 86.1-91.4 | 15/16 | | TK-T017 | 86.1-91.4 | 2 3/8 | DISC | A-226P | CPC-226 | 86.1-91.4 | 1 1/2 | DISC | A-227P | | 86.1-91.4 | BH-02489 | (R)BH-02568 | 86.1-86.12 | 5/8 | | MK-4300 | 86.1-88.8 | 13/16 | CC-70133 | CK-3144 |
| | | | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | | | | | | (L)BH-02568 | 86.12-87.4 | 5/8 | | MK-4353 | 88.8-91.3 | 13/16 | CC-70133 | CK-3144 |
| | | | 88.12-91.4 | 1 | | TK-T304 | | | | | | | | | | | | | | 87.4-88.1 | 5/8 | | MK-4353 | 91.3-91.4 | 13/16 | | CK-T201 |
| | | | | | | | | | | | | | | | | | | | | 88.1-91.4 | 5/8 | | MK-4353 | | | | |
| | | GT・GTツインターボ | 86.1-87.1 | 1 | | TK-T018 | 86.1-91.4 | 2 3/8 | DISC | A-226P | CPC-226 | 86.1-91.4 | 1 1/2 | DISC | A-227P | | 86.1-91.4 | BH-02489 | (R)BH-02568 | 86.1-86.12 | 5/8 | | MK-4300 | 86.1-88.8 | 13/16 | CC-70133 | CK-3144 |
| | | GTツインターボL | 87.1-91.4 | 1 | | TK-T034 | | | | | | | | | | | | | (L)BH-02568 | 86.12-87.4 | 5/8 | | MK-4353 | 88.8-91.3 | 13/16 | | CK-3144 |
| | | | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | | | | | | | 87.4-88.1 | 5/8 | | MK-4353 | 91.3-91.4 | 13/16 | | CK-T201 |
| | | | 87.1-91.4 | 1 | | TK-T019 | | | | | | | | | | | | | | 88.1-91.4 | 5/8 | | MK-4353 | | | | |
| (3000) | E－MZ20・21 | GT・GTリミテッド | 86.1-87.1 | 1 | | TK-T018 | 86.1-91.4 | 2 3/8 | DISC | A-226P | CPC-226 | 86.1-91.4 | 1 1/2 | DISC | A-227P | | 86.1-91.4 | BH-02489 | (R)BH-02568 | 86.1-91.4 | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | | | 87.1-88.1 | 1 | | TK-T034 | | | | | | | | | | | | | (L)BH-02568 | 87.1-87.4 | 5/8 | | MK-4353 | 87.1-91.4 | 7/8 | CC-70181 | CK-3143 |
| | | | <GT> | | | | | | | | | | | | | | | | | 87.4-88.1 | 5/8 | | MK-4344 | | | | |
| | | | 88.1-91.4 | 1 | | TK-T034 | | | | | | | | | | | | | | 88.1-91.4 | 5/8 | | MK-4353 | | | | |
| | | | <GTL> | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | 88.1-91.4 | 1 | | TK-T019 | | | | | | | | | | | | | | | | | | | | | |
| | | | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | 86.1-91.4 | 1 | | TK-T019 | | | | | | | | | | | | | | | | | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| SOARER : 30 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2500) | E－JZZ30 | 91.5-98.3 | 1 1/16 | | TK-T332 | <15インチホイール> | | | | | | | | | | | | | | | | | | | | |
| | ＜GF－は99．8～＞ | 98.3-00.12 | 1 1/16 | | TK-T437 | 91.5-00.12 | 44.4 | DISC | MP-37 | | 91.5-94.1 | 42.8 | DISC | MP-43 | | 91.5-96.9 | (R)BH-T555 | (R)BH-T692 | 91.5-91.12 | 5/8 | MC-T404 | | 91.5-96.8 | 13/16 | | CK-T202 |
| | | <油圧ﾌﾞｰｽﾀｰ> | | | | <16インチホイール> | | | | | 94.1-00.12 | 42.8 | DISC | MP-43 | | | (L)BH-T556 | (L)BH-T692 | 91.12-94.3 | 5/8 | MC-T404 | | 96.8-00.12 | 7/8 | CC-70181 | CK-T223 |
| | | 91.5-96.8 | | | | 91.5-94.1 | 44.4 | DISC | MP-37 | | | | | | | 96.9-00.12 | (R)BH-T555 | (R) | 94.3-00.12 | 5/8 | MC-T404 | | | | | |
| | | | | | | 94.1-00.12 | 44.4 | DISC | MP-37 | | | | | | | | (L)BH-T556 | (L) | | | | | | | | |
| (3000) | E－JZZ31 | 94.1-98.3 | 1 1/16 | | TK-T332 | <15インチホイール> | | | | | | | | | | | | | | | | | | | | |
| | ＜GF－は99．8～＞ | 98.3-00.12 | 1 1/16 | | TK-T437 | 94.1-00.12 | 44.4 | DISC | MP-37 | | 94.1-00.12 | 42.8 | DISC | MP-43 | | 94.1-96.9 | (R)BH-T555 | (R)BH-T692 | | | (オートマチック) | | | | | |
| | | | | | | <16インチホイール> | | | | | | | | | | | (L)BH-T556 | (L)BH-T692 | | | | | | | | |
| | | | | | | 96.8-00.12 | 44.4 | DISC | MP-37 | | | | | | | 96.9-00.12 | (R)BH-T555 | (R) | | | | | | | | |
| | | | | | | | | | | | | | | | | | (L)BH-T556 | (L) | | | | | | | | |
| (4000) | E－UZZ30・31 | 91.5-94.1 | 1 1/16 | | TK-T332 | 91.5-97.9 | 44.4 | DISC | MP-37 | | 91.5-94.1 | 42.8 | DISC | MP-43 | | 91.5-96.9 | (R)BH-T555 | (R)BH-T692 | | | (オートマチック) | | | | | |
| | | <油圧ﾌﾞｰｽﾀｰ> | | | | | | | | | 94.1-97.9 | 42.8 | DISC | MP-43 | | | (L)BH-T556 | (L)BH-T692 | | | | | | | | |
| | | 91.5-97.9 | | | | | | | | | | | | | | 96.9-97.9 | (R)BH-T555 | (R) | | | | | | | | |
| | | | | | | | | | | | | | | | | | (L)BH-T556 | (L) | | | | | | | | |
| (4000) | E－UZZ32 | 91.5-94.1 | 1 1/16 | | TK-T332 | 91.5-96.8 | 44.4 | DISC | MP-37 | | 91.5-94.1 | 42.8 | DISC | MP-43 | | 91.5-96.8 | (R)BH-T555 | (R)BH-T692 | | | (オートマチック) | | | | | |
| | | <油圧ﾌﾞｰｽﾀｰ> | | | | | | | | | 94.1-96.8 | 42.8 | DISC | MP-43 | | | (L)BH-T556 | (L)BH-T692 | | | | | | | | |
| | | 91.5-96.8 | | | | | | | | | | | | | | | | | | | | | | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| SOARER : 40 ser. | | | | | | | | | | | | | | | | | | | | | | | | | |
| (4300) UA－UZZ40 | 01.4- | | | | 01.4- | | DISC | MP-77 | CPM-77 | 01.4- | | DISC | MP-80 | | 01.4- | BH-T753 | (R)BH-T766<br>(L)BH-T766 | | | (オートマチック) | | | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| AVALON : 10 ser. | | | | | | | | | | | | | | | | | | | | | | | | | |
| (3000) E－MCX10 | 95.3-96.8<br>96.8-00.2 | 1<br>1 | | TK-T370<br>TK-T414 | 95.3-97.9<br>97.9-00.2 | | DISC<br>DISC | C-322P<br>A-678P | | 95.3-00.2 | | DISC | | | 95.3-96.8<br><br>96.8-00.2 | (R)BH-T634<br>(L)BH-T635<br>(R)<br>(L) | (R)<br>(L)<br>(R)<br>(L) | | | (オートマチック) | | | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| PRONARD : 20 ser.(00.2-) | | | | | | | | | | | | | | | | | | | | | | | | | |
| (3000) GH－MCX20 <TA－は00．8～> | 00.2- | | | | 00.2- | | DISC | A-678P | | 00.2- | | DISC | | | 00.2- | (R) (L) | (R) (L) | | | (オートマチック) | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| AVENSIS : 250, 270 ser.(03.7-) | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000) | UA－AZT250<br>UA－AZT250W<br>＜CBA－は04．2～＞ | 03.7- | | | | 03.7-03.10<br>03.10- | | DISC<br>DISC | | | 03.7-03.10<br>03.10- | | DISC<br>DISC | | | 03.7-06.10<br><br><J仕様><br>06.2- | (R)<br>(L)<br><br>(R)<br>(L) | (R)BH-T918<br>(L)BH-T918<br><br>(R)BH-T918<br>(L)BH-T918 | | | (ｵｰﾄﾏﾁｯｸ) | | | | |
| | UA－AZT255(4WD)<br>UA－AZT255W(4WD)<br>＜CBA－は04．2～＞ | 03.7- | | | | 03.7-03.10<br>03.10- | | DISC<br>DISC | | | 03.7-03.10<br>03.10- | | DISC<br>DISC | | | 03.7-06.10<br><br><J仕様><br>06.2- | (R)<br>(L)<br><br>(R)<br>(L) | (R)BH-T918<br>(L)BH-T918<br><br>(R)BH-T918<br>(L)BH-T918 | | | (ｵｰﾄﾏﾁｯｸ) | | | | |
| | DBA－ZRT272W | 11.9- | | | | 11.9- | | DISC | | | 11.9- | | DISC | | | 11.9- | (R)<br>(L) | (R)<br>(L) | | | | | | | | |
| (2400) | CBA－AZT251<br>CBA－AZT251W | 05.9- | | | | 05.9- | | DISC | | | 05.9- | | DISC | | | 05.9-06.10<br><br><J仕様><br>06.2- | (R)<br>(L)<br><br>(R)<br>(L) | (R)BH-T918<br>(L)BH-T918<br><br>(R)BH-T918<br>(L)BH-T918 | | | (ｵｰﾄﾏﾁｯｸ) | | | | |

| Models | TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CORONA : 80 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | <コラムシフト車> | | | |
| (1500) | RT80 | STD・DX | 70.2-71.1 | 3/4 | | MK-4002 | 70.2-71.1 | 7/8 | (R)WC-31011<br>(L)WC-31012 | WK-545 | CUP | 70.2-71.1 | 5/8 | (R)WC-50031<br>(L)WC-50031 | WK-045-R | CUP | 70.2-71.1 | BH-02064 | BH-02121 | 70.2-71.1 | 5/8 | MC-10041 | MK-3001 | 70.2-71.1 | 15 | CC-20051 | FC-31480-B |
| | | | | | | | | | | | | | | | | | | | | | | | | <フロアシフト車> | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | 70.2-71.1 | 15 | CC-40381 | FC-31480-B |
| | | タクシー | 70.7-71.1 | 3/4 | | MK-4002 | 70.2-71.1 | 7/8 | (R)WC-32011<br>(L)WC-32012 | WK-048 | CUP | 70.2-71.1 | 11/16 | (R)WC-50011<br>(L)WC-50011 | | CUP | 70.2-71.1 | BH-02064 | BH-02121 | 70.2-71.1 | 5/8 | MC-10041 | MK-3001 | 70.2-71.1 | 15 | CC-20051 | FC-31480-B |
| | | | | | | | | | | | | | | | | | | | | | | | | <コラムシフト車> | | | |
| (1600) | RT81 | STD・DX | 71.2-73.7 | 3/4 | | MK-4002 | 71.2-72.7 | 7/8 | (R)WC-31011<br>(L)WC-31012 | WK-545 | CUP | 71.2-72.7 | 5/8 | (R)WC-50031<br>(L)WC-50031 | WK-045-R | CUP | 71.9-72.7<br>72.8-73.7 | BH-02064<br>BH-95002 | BH-02121<br>BH-02121 | 71.2-73.7 | 5/8 | MC-10041 | MK-3001 | 71.2-73.7 | 15 | CC-20051 | FC-31480-B |
| | | | | | | | 72.8-73.7 | 13/16 | (R-1)WC-1066<br>(R-2)WC-2056<br>(L-1)WC-3066<br>(L-2)WC-4056 | WK-082 | CUP | 72.8-73.7 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | | | | | | | | <フロアシフト車><br>71.2-71.8 | 15 | CC-40381 | FC-31480-B |
| | | | | | | | | | | | | | | | | | | | | | | | | 71.9-73.7 | 15 | CC-23010 | FC-31480-B |
| | | タクシー | 71.2-73.7 | 3/4 | | MK-4002 | 71.2-72.7 | 7/8 | (R)WC-32011<br>(L)WC-32012 | WK-048 | CUP | 71.2-72.7 | 11/16 | (R)WC-50011<br>(L)WC-50011 | | CUP | 71.2-72.7<br>72.8-73.7 | BH-02064<br>BH-95002 | BH-02121<br>BH-02121 | 71.2-73.7 | 5/8 | MC-10041 | MK-3001 | 71.2-73.7 | 15 | CC-20051 | FC-31480-B |
| | | | | | | | 72.8-73.7 | 15/16 | (R)WC-5176<br>(L)WC-5376 | WK-105 | CUP | 72.8-73.7 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | | | | | | | | | | | | |
| | | | | | | | <F=2リーディング><br>71.9-72.7 | 15/16 | (R)WC-5176<br>(L)WC-5376 | WK-105 | CUP | <F=2リーディング><br>71.9-72.7 | 7/8 | (R)WC-50035<br>(L)WC-50035 | WK-545 | CUP | <F=2リーディング><br>71.9-72.7 | BH-95002 | BH-02121 | | | | | | | | |
| | RT82 | DX・SL | 70.2-70.9 | 7/8 | | TK-9304 | 70.2-70.9 | 2 | DISC | A-16P | | 70.2-70.9 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 70.2-70.9 | BH-02221 | BH-02121 | 70.2-70.9 | 5/8 | MC-10041 | MK-3001 | 70.2-70.9 | 3/4 | CC-70071 | CK-41480 |
| (1700) | RT84 | ドラム車 | 70.10-73.7 | 3/4 | | MK-4002 | 70.10-72.7 | 7/8 | (R)WC-31011<br>(L)WC-31012 | WK-545 | CUP | 70.10-72.7 | 5/8 | (R)WC-50031<br>(L)WC-50031 | WK-045-R | CUP | 70.10-72.7<br>72.8-73.7 | BH-02064<br>BH-95002 | BH-02121<br>BH-02121 | 70.10-73.7 | 5/8 | MC-10041 | MK-3001 | 70.10-73.7 | 3/4 | CC-70071 | CK-41480 |
| | | | | | | | 72.8-73.7 | 15/16 | (R)WC-5176<br>(L)WC-5376 | WK-105 | CUP | 72.8-73.7 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | | | | | | | | | | | | |
| | | タクシー | 71.2-72.7 | 3/4 | | MK-4002 | 71.2-72.7 | 7/8 | (R)WC-32011<br>(L)WC-32012 | WK-048 | CUP | 71.2-72.7 | 11/16 | (R)WC-50011<br>(L)WC-50011 | | CUP | 71.2-72.7 | BH-02064 | BH-02121 | 71.2-72.7 | 5/8 | MC-10041 | MK-3001 | 71.2-72.7 | 3/4 | CC-70071 | CK-41480 |
| | | | | | | | <F=2リーディング><br>71.9-72.7 | 15/16 | (R)WC-5176<br>(L)WC-5376 | WK-105 | CUP | <F=2リーディング><br>71.9-72.7 | 7/8 | (R)WC-50035<br>(L)WC-50035 | WK-545 | CUP | <F=2リーディング><br>71.9-72.7 | BH-95002 | BH-02121 | | | | | | | | |
| (1700) | RT84 | ディスク車 | 70.10-72.7<br>70.10-72.7<br>72.8-73.7 | 7/8<br>7/8<br>7/8 | | MK-4401<br>TK-9304<br>TK-9305 | 70.10-73.7 | 2 | DISC | A-16P | | 70.10-73.7 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 70.10-73.7 | BH-02221 | BH-02121 | 70.10-73.7 | 5/8 | MC-10041 | MK-3001 | 70.10-73.7 | 3/4 | CC-70071 | CK-41480 |
| | | | | | | | | | | | | | | | | | | | | | | | | <コラムシフト車> | | | |
| (1500) | RT86V(バン) | | 70.2-71.1 | 3/4 | | MK-4002 | 70.2-71.1 | 7/8 | (R)WC-31011<br>(L)WC-31012 | WK-545 | CUP | 70.2-71.1 | 11/16 | (R)WC-50011<br>(L)WC-50011 | | CUP | 70.2-71.1 | BH-02064 | BH-02123 | 70.2-71.1 | 5/8 | MC-10041 | MK-3001 | 70.2-71.1 | 15 | CC-20051 | FC-31480-B |
| | | | | | | | | | | | | | | | | | | | | | | | | <フロアシフト車> | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | 70.2-71.1 | 15 | CC-40381 | FC-31480-B |
| | PT86V(バン) | | 70.2-73.7 | 3/4 | | MK-4002 | 70.2-72.7 | 7/8 | (R)WC-31011<br>(L)WC-31012 | WK-545 | CUP | 70.2-72.7 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 70.2-72.7<br>72.8-73.7 | BH-02064<br>BH-95002 | BH-02123<br>BH-02123 | 70.2-73.7 | 5/8 | MC-10041 | MK-3001 | 70.2-73.7 | 15 | CC-20051 | FC-31480-B |
| | | | | | | | 72.8-73.7 | 15/16 | (R-1)WC-1066<br>(R-2)WC-2056<br>(L-1)WC-3066<br>(L-2)WC-4056 | WK-082 | CUP | 72.8-73.7 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | <コラムシフト車> | | | |
| (1600) | RT87V(バン) | | 71.2-73.7 | 3/4 | | MK-4002 | 71.2-72.7 | 7/8 | (R)WC-31011<br>(L)WC-31012 | WK-545 | CUP | 71.2-71.8 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 71.2-72.7<br>72.8-73.7 | BH-02064<br>BH-95002 | BH-02123<br>BH-02123 | 71.2-73.7 | 5/8 | MC-10041 | MK-3001 | 71.2-73.7 | 15 | CC-20051 | FC-31480-B |
| | | | | | | | 72.8-73.7 | 15/16 | (R-1)WC-1066<br>(R-2)WC-2056<br>(L-1)WC-3066<br>(L-2)WC-4056 | WK-082 | CUP | 71.9-72.7<br>72.8-73.7 | 11/16<br>13/16 | (R)WC-50011<br>(L)WC-50011<br>(R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | | | | | | | | <フロアシフト車><br>71.2-71.8<br>71.9-73.7 | 15<br>15 | CC-40381<br>CC-23010 | FC-31480-B<br>FC-31480-B |
| (1700) | RT88V(バン) | | 71.9-73.7 | 3/4 | | MK-4002 | 71.9-72.7 | 7/8 | (R)WC-31011<br>(L)WC-31012 | WK-545 | CUP | 71.9-72.7 | 11/16 | (R)WC-50011<br>(L)WC-50011 | | CUP | 71.9-72.7<br>72.8-73.7 | BH-02064<br>BH-95002 | BH-02123<br>BH-02123 | 71.9-73.7 | 5/8 | MC-10041 | MK-3001 | 71.9-73.1 | 3/4 | CC-70071 | CK-41480 |
| | | | | | | | 72.8-73.7 | 15/16 | (R-1)WC-1066<br>(R-2)WC-2056<br>(L-1)WC-3066<br>(L-2)WC-4056 | WK-082 | CUP | 72.8-73.7 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | | | | | | | | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CORONA : 90 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1500) | RT90 | | 70.9-71.1 | 3/4 | | MK-4002 | 70.9-71.1 | 7/8 | (R)WC-31011<br>(L)WC-31012 | WK-545 | CUP | 70.9-71.1 | 5/8 | (R)WC-50031<br>(L)WC-50031 | WK-045-R | CUP | 70.9-71.1 | BH-02064 | BH-02121 | 70.9-71.1 | 5/8 | MC-10041 | MK-3001 | <コラムシフト車><br>70.9-71.1<br><フロアシフト車><br>70.9-71.1 | 15<br><br>15 | CC-20051<br><br>CC-40381 | FC-31480-B<br><br>FC-31480-B |
| (1600) | RT91 | | 71.2-73.7 | 3/4 | | MK-4002 | 71.2-72.7<br><br>72.8-73.7 | 7/8<br><br>15/16 | (R)WC-31011<br>(L)WC-31012<br>(R-1)WC-1066<br>(R-2)WC-2056<br>(L-1)WC-3066<br>(L-2)WC-4056 | WK-545<br><br>WK-082 | CUP<br><br>CUP | 71.2-72.7<br><br>72.8-73.7 | 5/8<br><br>13/16 | (R)WC-50031<br>(L)WC-50031<br>(R)WC-50059<br>(L)WC-50059 | WK-045-R<br><br>WK-492 | CUP<br><br>CUP | 71.2-72.7<br>72.7-73.7 | BH-02064<br>BH-95002 | BH-02121<br>BH-02121 | 71.2-73.7 | 5/8 | MC-10041 | MK-3001 | <コラムシフト車><br>71.2-73.7<br><フロアシフト車><br>71.2-71.8<br>71.9-73.7 | 15<br><br>15<br>15 | CC-20051<br><br>CC-40381<br>CC-23010 | FC-31480-B<br><br>FC-31480-B<br>FC-31480-B |
| (1900) | RT93 | | 71.2-72.7<br>71.2-72.7 | 7/8<br>7/8 | | MK-4401<br>TK-9304 | 71.2-72.7 | 2 | DISC | A-16P | | 71.2-72.7 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 71.2-72.7 | BH-02221 | BH-02121 | 71.2-72.7 | 5/8 | MC-10041 | MK-3001 | 71.2-72.7 | 3/4 | CC-70071 | CK-41480 |
| (1700) | RT94 | ドラム車 | 70.9-72.7 | 3/4 | | MK-4002 | 70.9-72.7 | 7/8 | (R)WC-31011<br>(L)WC-31012 | WK-545 | CUP | 70.9-72.7 | 5/8 | (R)WC-50031<br>(L)WC-50031 | WK-045-R | CUP | 70.9-72.7 | BH-02064 | BH-02121 | 70.9-72.7 | 5/8 | MC-10041 | MK-3001 | 70.9-72.7 | 3/4 | CC-70071 | CK-41480 |
| | | ディスク車 | 70.9-72.7<br>70.9-72.7<br>72.8-73.7 | 7/8<br>7/8<br>7/8 | | MK-4401<br>TK-9304<br>TK-9305 | 70.9-73.7 | 2 | DISC | A-16P | | 70.9-73.7 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 70.9-73.7 | BH-02221 | BH-02121 | 70.9-73.7 | 5/8 | MC-10041 | MK-3001 | 70.9-73.7 | 3/4 | CC-70071 | CK-41480 |
| (2000) | RT95 | | 72.8-73.7 | 7/8 | | TK-9305 | 72.8-73.7 | 2 | DISC | A-16P | | 72.8-73.7 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 72.8-73.7 | BH-02221 | BH-02121 | 72.8-73.7 | 5/8 | MC-10041 | MK-3001 | 72.8-73.7 | 3/4 | CC-70071 | CK-41480 |

| Models | TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CORONA : 100-120 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1600) | TT100 | STD・DX(ドラム車) | 73.8-76.4 | 13/16 | | TK-9345 | 73.8-76.4 | 7/8 | (R-1)WC-51000<br>(R-2)WC-52000<br>(L-1)WC-53000<br>(L-2)WC-54000 | WK-054 | CUP | 73.8-76.4 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 73.8-76.4 | BH-02209 | BH-02214 | 73.8-74.2<br>74.2-76.4 | 5/8<br>5/8 | MC-10042<br>MC-10046 | MK-4300<br>MK-4300 | 73.8-76.4 | 3/4 | CC-70090 | CK-3108 |
| | | STD・DX(ディスク車)<br>GL | 73.8-76.4 | 7/8 | | TK-9307 | 73.8-76.4 | 2 | DISC | A-16P | | 73.8-76.4 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 73.8-73.12<br>73.12-76.4 | BH-02210<br>BH-02235 | BH-02214<br>BH-02214 | 73.8-74.2<br>74.2-76.4 | 5/8<br>5/8 | MC-10042<br>MC-10046 | MK-4300<br>MK-4300 | 73.8-76.4 | 3/4 | CC-70090 | CK-3108 |
| | | SL | 75.10-76.4 | 15/16 | | TK-9308 | 75.10-76.4 | 2 1/8 | DISC | SP-212 | | 75.10-76.4 | 7/8 | (R)WC-50035<br>(L)WC-50035 | WK-545 | CUP | 75.10-76.4 | BH-02235 | BH-02214 | 75.10-76.4 | 5/8 | MC-10046 | MK-4300 | 75.10-76.4 | 3/4 | CC-70090 | CK-3108 |
| | TT106V(バン) | STD(ドラム車) | 75.11-77.1<br>77.1-78.8 | 13/16<br>13/16 | | TK-9345<br>TK-9370 | 75.11-78.8 | 7/8 | (R-1)WC-51000<br>(R-2)WC-52000<br>(L-1)WC-53000<br>(L-2)WC-54000 | WK-054 | CUP | 75.11-77.1<br><br>77.1-78.8 | 3/4<br><br>13/16 | (R)WC-50060<br>(L)WC-50060<br>(R)WC-50059<br>(L)WC-50059 | WK-491<br><br>WK-492 | CUP<br><br>CUP | 75.11-78.8 | BH-02209 | BH-02214 | 75.11-78.8 | 5/8 | MC-10046 | MK-4300 | 75.11-76.4<br>76.5-77.8<br>77.8-78.8 | 3/4<br>3/4<br>13/16 | CC-70090<br>CC-70102<br>CC-70109 | CK-3108<br>CK-3108<br>CK-3113 |
| | | STD(ディスク車) | 77.1-78.8 | 7/8 | | TK-9359 | 77.1-78.8 | 2 | DISC | A-16P | | 77.1-78.8 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 77.1-78.8 | BH-02235 | BH-02214 | 77.1-78.8 | 5/8 | MC-10046 | MK-4300 | 77.1-77.8<br>77.8-78.8 | 3/4<br>13/16 | CC-70102<br>CC-70109 | CK-3108<br>CK-3113 |
| | | DX(ドラム車) | 73.8-77.1<br>77.1-78.8 | 7/8<br>7/8 | | TK-9345<br>TK-9370 | 73.8-78.8 | 7/8 | (R-1)WC-51000<br>(R-2)WC-52000<br>(L-1)WC-53000<br>(L-2)WC-54000 | WK-054 | CUP | 73.8-77.1<br><br>77.1-78.8 | 3/4<br><br>13/16 | (R)WC-50060<br>(L)WC-50060<br>(R)WC-50059<br>(L)WC-50059 | WK-491<br><br>WK-492 | CUP<br><br>CUP | 73.8-74.4<br>74.4-78.8 | BH-02209<br>BH-02209 | BH-31380<br>BH-02214 | 73.8-74.2<br>74.2-78.8 | 5/8<br>5/8 | MC-10042<br>MC-10046 | MK-4300<br>MK-4300 | 73.8-76.4<br>76.5-77.8<br><コラムシフト車><br>77.8-78.8<br><フロアシフト車><br>77.8-78.8 | 3/4<br>3/4<br><br>13/16<br><br>13/16 | CC-70090<br>CC-70102<br><br>CC-70109<br><br>CC-70110 | CK-3108<br>CK-3108<br><br>CK-3113<br><br>CK-3113 |
| | | DX(ディスク車) | 73.8-77.1<br>77.1-78.8 | 13/16<br>7/8 | | TK-9307<br>TK-9359 | 73.8-78.8 | 2 | DISC | A-16P | | 73.8-78.8 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 73.8-73.12<br>73.12-74.4<br>74.4-78.8 | BH-02210<br>BH-02235<br>BH-02235 | BH-31380<br>BH-31380<br>BH-02214 | 73.8-74.2<br>74.2-78.8 | 5/8<br>5/8 | MC-10042<br>MC-10046 | MK-4300<br>MK-4300 | 73.8-76.4<br>76.5-77.8<br><コラムシフト車><br>77.8-78.8<br><フロアシフト車><br>77.8-78.8 | 3/4<br>3/4<br><br>13/16<br><br>13/16 | CC-70090<br>CC-70102<br><br>CC-70109<br><br>CC-70110 | CK-3108<br>CK-3108<br><br>CK-3113<br><br>CK-3113 |
| | TT110 | DX(ドラム車) | 73.8-76.4 | 13/16 | | TK-9345 | 73.8-76.4 | 7/8 | (R-1)WC-51000<br>(R-2)WC-52000<br>(L-1)WC-53000<br>(L-2)WC-54000 | WK-054 | CUP | 73.8-76.4 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 73.8-76.4 | BH-02209 | BH-02214 | 73.8-74.2<br>74.2-76.4 | 5/8<br>5/8 | MC-10042<br>MC-10046 | MK-4300<br>MK-4300 | 73.8-76.4 | 3/4 | CC-70090 | CK-3108 |
| (1600) | TT110 | DX・GL(ディスク車) | 73.8-76.4 | 7/8 | | TK-9307 | 73.8-76.4 | 2 | DISC | A-16P | | 73.8-76.4 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 73.8-73.12<br>73.12-76.4 | BH-02210<br>BH-02235 | BH-02214<br>BH-02214 | 73.8-74.2<br>74.2-76.4 | 5/8<br>5/8 | MC-10042<br>MC-10046 | MK-4300<br>MK-4300 | 73.8-76.4 | 3/4 | CC-70090 | CK-3108 |
| | | SL | 75.10-76.4 | 15/16 | | TK-9308 | 75.10-76.4 | 2 1/8 | DISC | SP-212 | | 75.10-76.4 | 7/8 | (R)WC-50035<br>(L)WC-50035 | WK-545 | CUP | 75.10-76.4 | BH-02235 | BH-02214 | 75.10-76.4 | 5/8 | MC-10046 | MK-4300 | 75.10-76.4 | 3/4 | CC-70090 | CK-3108 |
| | TT120 | STD・DX(ドラム車) | 76.5-77.1<br>77.1-78.8 | 13/16<br>13/16 | | TK-9345<br>TK-9370 | 76.5-78.8 | 7/8 | (R-1)WC-51000<br>(R-2)WC-52000<br>(L-1)WC-53000<br>(L-2)WC-54000 | WK-054 | CUP | 76.5-77.1<br><br>77.1-78.8 | 3/4<br><br>13/16 | (R)WC-50060<br>(L)WC-50060<br>(R)WC-50059<br>(L)WC-50059 | WK-491<br><br>WK-492 | CUP<br><br>CUP | 76.5-78.8 | BH-02209 | BH-02214 | 76.5-78.8 | 5/8 | MC-10046 | MK-4300 | <フロアシフト車><br>76.5-77.8<br><コラムシフト車><br>76.5-77.8<br>77.8-78.8 | 3/4<br><br>3/4<br>13/16 | CC-70102<br><br>CC-70102<br>CC-70109 | CK-3108<br><br>CK-3108<br>CK-3113 |
| | | STD・DX(ディスク車)<br>GL | 76.5-77.1<br>77.1-78.8 | 7/8<br>7/8 | | TK-9307<br>TK-9359 | 76.5-78.8 | 2 | DISC | A-16P | | 76.5-78.8 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 76.5-78.8 | BH-02235 | BH-02214 | 76.5-78.8 | 5/8 | MC-10046 | MK-4300 | <フロアシフト車><br>76.5-77.8<br><コラムシフト車><br>76.5-77.8<br>77.8-78.8 | 3/4<br><br>3/4<br>13/16 | CC-70102<br><br>CC-70102<br>CC-70109 | CK-3108<br><br>CK-3108<br>CK-3113 |
| | | SL | 76.5-77.1<br>77.1-78.8 | 15/16<br>15/16 | | TK-9308<br>TK-9371 | 76.5-78.8 | 2 1/8 | DISC | SP-212 | | 76.5-78.8 | 7/8 | (R)WC-50035<br>(L)WC-50035 | WK-545 | CUP | 76.5-78.8 | BH-02235 | BH-02214 | 76.5-78.8 | 5/8 | MC-10046 | MK-4300 | 76.5-77.8<br>77.8-78.8 | 3/4<br>13/16 | CC-70102<br>CC-70110 | CK-3108<br>CK-3113 |
| (1800) | TT121 | DX・GL | 77.3-78.8 | 7/8 | | TK-9359 | 77.3-78.8 | 2 | DISC | A-16P | | 77.3-78.8 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 77.3-78.8 | BH-02235 | BH-02214 | 77.3-77.11 | 5/8 | MC-10046 | MK-4300 | 77.3-77.8<br>77.8-77.11 | 3/4<br>13/16 | CC-70102<br>CC-70110 | CK-3108<br>CK-3113 |
| | | SL | 77.3-78.8 | 15/16 | | TK-9371 | 77.3-78.8 | 2 1/8 | DISC | SP-212 | | 77.3-78.8 | 7/8 | (R)WC-50035<br>(L)WC-50035 | WK-545 | CUP | 77.3-78.8 | BH-02235 | BH-02214 | 77.3-77.11 | 5/8 | MC-10046 | MK-4300 | 77.3-77.8<br>77.8-77.11 | 3/4<br>13/16 | CC-70102<br>CC-70110 | CK-3108<br>CK-3113 |
| (1600) | TT125 | DX・GL | 77.8-78.8 | 7/8 | | TK-9359 | 77.8-78.8 | 2 | DISC | A-16P | | 77.8-78.8 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 77.8-78.8 | BH-02235 | BH-02214 | 77.8-78.8 | 5/8 | MC-10046 | MK-4300 | 77.8-78.8 | 13/16 | CC-70110 | CK-3113 |
| (1800) | TT126 | DX・GL | 77.11-78.8 | 7/8 | | TK-9359 | 77.11-78.8 | 2 | DISC | A-16P | | 77.11-78.8 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 77.11-78.8 | BH-02235 | BH-02214 | 77.11-78.8 | 5/8 | MC-10046 | MK-4300 | 77.11-78.8 | 13/16 | CC-70110 | CK-3113 |
| | | SL | 77.11-78.8 | 15/16 | | TK-9371 | 77.11-78.8 | 2 1/8 | DISC | SP-212 | | 77.11-78.8 | 7/8 | (R)WC-50035<br>(L)WC-50035 | WK-545 | CUP | 77.11-78.8 | BH-02235 | BH-02214 | 77.11-78.8 | 5/8 | MC-10046 | MK-4300 | 77.11-78.8 | 13/16 | CC-70110 | CK-3113 |
| (1600) | RT100 | タクシー | 73.8-77.1 | 13/16 | | TK-9345 | 73.8-77.1 | 7/8 | (R-1)WC-51001<br>(R-2)WC-52001<br>(L-1)WC-53001<br>(L-2)WC-54001 | WK-113 | CUP | 73.8-74.12<br><br>74.12-77.1 | 3/4<br><br>13/16 | (R)WC-50060<br>(L)WC-50060<br>(R)WC-50059<br>(L)WC-50059 | WK-491<br><br>WK-492 | CUP<br><br>CUP | 73.8-77.1 | BH-02209 | BH-02214 | 73.8-74.2<br>74.2-77.1 | 5/8<br>5/8 | MC-10042<br>MC-10046 | MK-4300<br>MK-4300 | 73.8-77.1 | 3/4 | CC-70096 | CK-3108 |
| (1800) | RT102 | DX(ドラム車) | 73.8-77.1 | 13/16 | | TK-9345 | 73.8-77.1 | 7/8 | (R-1)WC-51001<br>(R-2)WC-52001<br>(L-1)WC-53001<br>(L-2)WC-54001 | WK-113 | CUP | 73.8-75.11<br><br>75.11-77.1 | 3/4<br><br>13/16 | (R)WC-50060<br>(L)WC-50060<br>(R)WC-50059<br>(L)WC-50059 | WK-491<br><br>WK-492 | CUP<br><br>CUP | 73.8-77.1 | BH-02209 | BH-02214 | 73.8-74.2<br>74.2-77.1 | 5/8<br>5/8 | MC-10042<br>MC-10046 | MK-4300<br>MK-4300 | 73.8-77.1 | 3/4 | CC-70090 | CK-3108 |

| Models | TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | DX(ディスク車)<br>GL・SR | 73.8-77.1 | 7/8 | | TK-9307 | 73.8-77.1 | 2 | DISC | A-16P | | 73.8-77.1 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 73.8-73.12<br>73.12-77.1 | BH-02210<br>BH-02235 | BH-02214<br>BH-02214 | 73.8-74.2<br>74.2-77.1 | 5/8<br>5/8 | MC-10042<br>MC-10046 | MK-4300<br>MK-4300 | 73.8-77.1 | 3/4 | CC-70090 | CK-3108 |
| | | SL | 73.8-75.11<br>75.11-77.1 | 7/8<br>15/16 | | TK-9307<br>TK-9308 | 73.8-75.11<br>75.11-77.1 | 2<br>2 1/8 | DISC<br>DISC | A-16P<br>SP-212 | | 73.8-75.11<br>75.11-77.1 | 13/16<br>7/8 | (R)WC-50059<br>(L)WC-50059<br>(R)WC-50035<br>(L)WC-50035 | WK-492<br>WK-545 | CUP<br>CUP | 73.8-73.12<br>73.12-77.1 | BH-02210<br>BH-02235 | BH-02214<br>BH-02214 | 73.8-74.2<br>74.2-77.1 | 5/8<br>5/8 | MC-10042<br>MC-10046 | MK-4300<br>MK-4300 | 73.8-77.1 | 3/4 | CC-70090 | CK-3108 |
| (2000) | RT103 | DX | 74.12-76.2 | 7/8 | | TK-9307 | 74.12-76.2 | 2 | DISC | A-16P | | 74.12-76.2 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 74.12-76.2 | BH-02235 | BH-02214 | 74.12-76.2 | 5/8 | MC-10046 | MK-4300 | 74.12-76.2 | 3/4 | CC-70090 | CK-3108 |
| (2000) | RT104 | SL・SR | 73.8-75.11 | 7/8 | | TK-9307 | 73.8-75.11 | 2 | DISC | A-16P | | 73.8-75.11 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 73.8-73.12<br>73.12-75.11 | BH-02210<br>BH-02235 | BH-02214<br>BH-02214 | 73.8-74.2<br>74.2-75.11 | 5/8<br>5/8 | MC-10042<br>MC-10046 | MK-4300<br>MK-4300 | 73.8-75.11 | 3/4 | CC-70090 | CK-3108 |
| | | GT | 73.8-77.1 | 15/16 | | TK-9308 | 73.8-77.1 | 2 1/8 | DISC | SP-212 | | 73.8-77.1 | 7/8 | (R)WC-50035<br>(L)WC-50035 | WK-545 | CUP | 73.8-73.12<br>73.12-77.1 | BH-02210<br>BH-02235 | BH-02214<br>BH-02214 | 73.8-74.2<br>74.2-77.1 | 5/8<br>5/8 | MC-10047 | MK-4300<br>MK-4300 | 73.8-77.1 | 3/4 | CC-70090 | CK-3108 |
| (1600) | RT106V(バン) | STD(ドラム車) | 73.8-75.11 | 13/16 | | TK-9345 | 73.8-75.11 | 7/8 | (R-1)WC-51000<br>(R-2)WC-52000<br>(L-1)WC-53000<br>(L-2)WC-54000 | WK-054 | CUP | 73.8-75.11 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 73.8-74.4<br>74.4-75.11 | BH-02209<br>BH-02209 | BH-31380<br>BH-02214 | 73.8-74.2<br>74.2-75.11 | 5/8<br>5/8 | MC-10042<br>MC-10046 | MK-4300<br>MK-4300 | 73.8-75.11 | 3/4 | CC-70096 | CK-3108 |
| | | STD(ディスク車) | 73.8-75.11 | 7/8 | | TK-9307 | 73.8-75.11 | 2 | DISC | A-16P | | 73.8-75.11 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 73.8-73.12<br>73.12-74.4<br>74.4-75.11 | BH-02210<br>BH-02235<br>BH-02235 | BH-31380<br>BH-31380<br>BH-02214 | 73.8-74.2<br>74.2-75.11 | 5/8<br>5/8 | MC-10042<br>MC-10046 | MK-4300<br>MK-4300 | 73.8-75.11 | 3/4 | CC-70096 | CK-3108 |
| (1800) | RT108V(バン) | DX | 73.8-77.1<br>77.1-78.8 | 7/8<br>7/8 | | TK-9307<br>TK-9359 | 73.8-78.8 | 2 | DISC | A-16P | | 73.8-78.8 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 73.8-73.12<br>73.12-74.4<br>74.4-78.8 | BH-02210<br>BH-02235<br>BH-02235 | BH-31380<br>BH-31380<br>BH-02214 | 73.8-74.2<br>74.2-78.8 | 5/8<br>5/8 | MC-10042<br>MC-10046 | MK-4300<br>MK-4300 | 73.8-77.1<br>77.1-78.8 | 3/4<br>13/16 | CC-70090<br>CC-70107 | CK-3108<br>CK-3113 |
| | | GL | 77.1-78.8 | 7/8 | | TK-9359 | 77.1-78.8 | 2 | DISC | A-16P | | 77.1-78.8 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 77.1-78.8 | BH-02235 | BH-02214 | 77.1-78.8 | 5/8 | MC-10046 | MK-4300 | 77.1-78.8 | 13/16 | CC-70107 | CK-3113 |
| | RT112 | DX・GL | 73.8-77.1 | 7/8 | | TK-9307 | 73.8-77.1 | 2 | DISC | A-16P | | 73.8-77.1 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 73.8-73.12<br>73.12-77.1 | BH-02210<br>BH-02235 | BH-02214<br>BH-02214 | 73.8-74.2<br>74.2-77.1 | 5/8<br>5/8 | MC-10042<br>MC-10046 | MK-4300<br>MK-4300 | 73.8-77.1 | 3/4 | CC-70090 | CK-3108 |
| | | SL | 73.8-75.11<br>75.11-77.1 | 7/8<br>15/16 | | TK-9307<br>TK-9308 | 73.8-75.11<br>75.11-77.1 | 2<br>2 1/8 | DISC<br>DISC | A-16P<br>SP-212 | | 73.8-75.11<br>75.11-77.1 | 13/16<br>7/8 | (R)WC-50059<br>(L)WC-50059<br>(R)WC-50035<br>(L)WC-50035 | WK-492<br>WK-545 | CUP<br>CUP | 73.8-73.12<br>73.12-77.1 | BH-02210<br>BH-02235 | BH-02214<br>BH-02214 | 73.8-74.2<br>75.11-77.1 | 5/8<br>5/8 | MC-10042<br>MC-10046 | MK-4300<br>MK-4300 | 73.8-77.1 | 3/4 | CC-70090 | CK-3108 |
| (2000) | RT114 | SL・SR | 73.8-75.11 | 7/8 | | TK-9307 | 73.8-75.11 | 2 | DISC | A-16P | | 73.8-75.11 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 73.8-73.12<br>73.12-75.11 | BH-02210<br>BH-02235 | BH-02214<br>BH-02214 | 73.8-74.2<br>74.2-75.11 | 5/8<br>5/8 | MC-10042<br>MC-10046 | MK-4300<br>MK-4300 | 73.8-75.11 | 3/4 | CC-70090 | CK-3108 |
| | | GT | 73.8-77.1 | 15/16 | | TK-9308 | 73.8-77.1 | 2 1/8 | DISC | SP-212 | | 73.8-77.1 | 7/8 | (R)WC-50035<br>(L)WC-50035 | WK-545 | CUP | 73.8-73.12<br>73.12-77.1 | BH-02210<br>BH-02235 | BH-02214<br>BH-02214 | 73.8-74.2<br>74.2-77.1 | 5/8<br>5/8 | MC-10047 | MK-4300<br>MK-4300 | 73.8-77.1 | 3/4 | CC-70090 | CK-3108 |
| (1600L. P. G) | RT120 | STD・DX(ドラム車) | 77.1-78.8 | 13/16 | | TK-9370 | 77.1-78.8 | 7/8 | (R-1)WC-51001<br>(R-2)WC-52001<br>(L-1)WC-53001<br>(L-2)WC-54001 | WK-113 | CUP | 77.1-78.8 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 77.1-78.8 | BH-02209 | BH-02214 | 77.1-78.8 | 5/8 | MC-10046 | MK-4300 | 77.1-78.8 | 13/16 | CC-70121 | CK-3113 |
| | | STD・DX(ディスク車) | 77.1-78.8 | 7/8 | | TK-9359 | 77.1-78.8 | 2 | DISC | C-16P | | 77.1-78.8 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 77.1-78.8 | BH-02235 | BH-02214 | 77.1-78.8 | 5/8 | MC-10046 | MK-4300 | 77.1-78.8 | 13/16 | CC-70121 | CK-3113 |
| (2000) | RT122 | DX・GL | 76.6-77.1<br>77.1-78.8 | 7/8<br>7/8 | | TK-9307<br>TK-9359 | 76.6-78.8 | 2 | DISC | A-16P | | 76.6-78.8 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 76.6-78.8 | BH-02235 | BH-02214 | 76.6-78.8 | 5/8 | MC-10046 | MK-4300 | 76.6-77.1<br>77.1-78.8 | 3/4<br>13/16 | CC-70090<br>CC-70107 | CK-3108<br>CK-3113 |
| | | SL | 76.6-77.1<br>77.1-78.8 | 15/16<br>15/16 | | TK-9308<br>TK-9371 | 76.6-78.8 | 2 1/8 | DISC | SP-212 | | 76.6-78.8 | 7/8 | (R)WC-50035<br>(L)WC-50035 | WK-545 | CUP | 76.6-78.8 | BH-02235 | BH-02214 | 76.6-78.8 | 5/8 | MC-10046 | MK-4300 | 76.6-77.1<br>77.1-78.8 | 3/4<br>13/16 | CC-70090<br>CC-70107 | CK-3108<br>CK-3113 |
| | | GT | 77.1-78.8 | 15/16 | | TK-9371 | 77.1-78.8 | 2 1/8 | DISC | SP-212 | | 77.1-78.8 | 7/8 | (R)WC-50035<br>(L)WC-50035 | WK-545 | CUP | 77.1-78.8 | BH-02235 | BH-02214 | 77.1-78.8 | 5/8 | MC-10047 | MK-4300 | 77.1-78.8 | 13/16 | CC-70107 | CK-3113 |
| (2000) | RT123 | DX・GL | 76.3-77.1<br>77.1-78.8 | 7/8<br>7/8 | | TK-9307<br>TK-9359 | 76.3-78.8 | 2 | DISC | A-16P | | 76.3-78.8 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 76.3-78.8 | BH-02235 | BH-02214 | 76.3-78.8 | 5/8 | MC-10046 | MK-4300 | 76.3-77.1<br>77.1-78.8 | 3/4<br>13/16 | CC-70090<br>CC-70107 | CK-3108<br>CK-3113 |

| Models | TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CORONA : 130 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1600) | TT130 | STD | 78.9-81.12 | 13/16 | | TK-9389 | 78.9-81.12 | 2 | DISC | A-16P | | 78.9-81.12 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 78.9-81.12 | (1)BH-02390<br>(2)BH-02391 | BH-02394 | 78.9-80.8<br>80.8-81.12 | 5/8<br>5/8 | MC-10095<br>MC-10075 | MK-4308 | 78.9-80.8<br>80.8-81.2<br>81.2-81.12 | 13/16<br>13/16<br>13/16 | CC-70109<br>CC-70111<br>CC-70111 | CK-3113<br>CK-3113<br>CK-3144 |
| | | DX・GL・SL | 78.9-81.12 | 13/16 | | TK-9389 | 78.9-81.12 | 2 | DISC | A-16P | | 78.9-81.12 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 78.9-81.12 | (1)BH-02390<br>(2)BH-02391 | BH-02394 | <フロアシフト車><br>78.9-81.12<br><コラムシフト車><br>78.9-80.8 | 5/8<br>5/8 | MC-10075<br>MC-10095 | MK-4308 | <フロアシフト車><br>78.9-80.8<br>80.8-81.2<br>81.2-81.12<br><コラムシフト車><br>78.9-80.8 | 13/16<br>13/16<br>13/16<br>13/16 | CC-70110<br>CC-70111<br>CC-70111<br>CC-70109 | CK-3113<br>CK-3113<br>CK-3144<br>CK-3113 |
| | TT137V(バン) | | 78.9-79.12 | 13/16 | | TK-9389 | 78.9-79.12 | 2 | DISC | A-16P | | 78.9-79.12 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 78.9-79.12 | (1)BH-02390<br>(2)BH-02391 | BH-02214 | <フロアシフト車><br>78.9-79.12<br><コラムシフト車><br>78.9-79.12 | 5/8<br>5/8 | MC-10075<br>MC-10095 | MK-4308<br>MK-4308 | <フロアシフト車><br>78.9-79.12<br><コラムシフト車><br>78.9-79.12 | 13/16<br>13/16 | CC-70110<br>CC-70109 | CK-3113<br>CK-3113 |
| | TT138V(バン) | | 7912-8112 | 13/16 | | TK-9389 | 7912-8112 | 2 | DISC | A-16P | | 79.12-81.12 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 79.12-80.8<br>80.8-81.12 | (1)BH-02390<br>(2)BH-02391<br>(1)BH-02390<br>(2)BH-02391 | BH-02214<br>BH-91003 | 7912-8112 | 5/8 | MC-10075 | MK-4308 | 79.12-80.8<br>80.8-81.2<br>81.2-81.12 | 13/16<br>13/16<br>13/16 | CC-70110<br>CC-70111<br>CC-70111 | CK-3113<br>CK-3113<br>CK-3144 |
| | RT130 | ドラム車 | 79.2-82.8 | 13/16 | | TK-9389 | 79.2-82.8 | 7/8 | (R-1)WC-51013<br>(R-2)WC-52013<br>(L-1)WC-53013<br>(L-2)WC-54013 | WK-113 | CUP | 79.2-82.8 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 79.2-82.8 | BH-02385 | BH-02394 | 79.2-82.8 | 5/8 | MC-10095 | MK-4308 | 79.2-79.9<br>79.9-81.2<br>81.2-82.8 | 13/16<br>13/16<br>13/16 | CC-70121<br>CC-70132<br>CC-70132 | CK-3113<br>CK-3113<br>CK-3144 |
| | | ディスク車 | 79.2-82.8 | 13/16 | | TK-9389 | 79.2-82.8 | 2 | DISC | C-16P | | 79.2-82.8 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 79.2-82.8 | (1)BH-02390<br>(2)BH-02391 | BH-02394 | 79.2-82.8 | 5/8 | MC-10095 | MK-4308 | 79.2-79.9<br>79.9-81.2<br>81.2-82.8 | 13/16<br>13/16<br>13/16 | CC-70121<br>CC-70132<br>CC-70132 | CK-3113<br>CK-3113<br>CK-3144 |
| (1800) | TT131 | DX・GL | 78.9-81.12 | 13/16 | | TK-9389 | 78.9-81.12 | 2 | DISC | A-16P | | 78.9-81.12 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 78.9-81.12 | (1)BH-02390<br>(2)BH-02391 | BH-02394 | 78.9-81.12 | 5/8 | MC-10075 | MK-4308 | 78.9-80.8<br>80.8-81.2<br>81.2-81.12 | 13/16<br>13/16<br>13/16 | CC-70110<br>CC-70111<br>CC-70111 | CK-3113<br>CK-3113<br>CK-3144 |
| | | SL | 78.9-81.12 | 7/8 | | TK-9390 | 78.9-81.12 | 2 1/8 | DISC | SP-212 | | 78.9-81.12 | 7/8 | (R)WC-50035<br>(L)WC-50035 | WK-545 | CUP | 78.9-81.12 | BH-02385 | BH-02394 | 78.9-81.12 | 5/8 | MC-10075 | MK-4308 | 78.9-80.8<br>80.8-81.2<br>81.2-81.12 | 13/16<br>13/16<br>13/16 | CC-70110<br>CC-70111<br>CC-70111 | CK-3113<br>CK-3113<br>CK-3144 |
| | | CXサルーン(リヤードラム) | 80.8-81.12 | 7/8 | | TK-9390 | 80.8-81.12 | 2 1/8 | DISC | SP-212 | | 80.8-81.12 | 7/8 | (R)WC-50035<br>(L)WC-50035 | WK-545 | CUP | 80.8-81.12 | BH-02385 | BH-02394 | 80.8-81.12 | 5/8 | MC-10075 | MK-4308 | 80.8-81.2<br>81.2-81.12 | 13/16<br>13/16 | CC-70111<br>CC-70111 | CK-3113<br>CK-3144 |
| | | CXサルーン(四輪ディスク) | 80.8-81.6 | 7/8 | | TK-9390 | 80.8-81.6 | 2 1/8 | DISC | SP-212 | | 80.8-81.6 | 1 1/2 | DISC | A-73P<br>A-46LP | | 80.8-81.6 | BH-02385 | (C)BH-02394<br>(R)BH-31264<br>(L)BH-31264 | 80.8-81.6 | 5/8 | MC-10075 | MK-4308 | 80.8-81.2<br>81.2-81.6 | 13/16<br>13/16 | CC-70111<br>CC-70111 | CK-3113<br>CK-3144 |
| | TT132 | SLツーリング | 79.8-80.8 | 7/8 | | TK-9390 | 78.9-80.8 | 2 1/8 | DISC | SP-212 | | 78.9-80.8 | 1 1/2 | DISC | A-73P<br>A-46LP | | 78.9-80.8 | BH-02385 | (C)BH-02394<br>(R)BH-31264<br>(L)BH-31264 | 78.9-80.8 | 5/8 | MC-10075 | MK-4308 | 78.9-80.8 | 13/16 | CC-70109 | CK-3113 |
| | | SL(リヤードラム) | 80.8-81.12 | 7/8 | | TK-9390 | 80.8-81.12 | 2 1/8 | DISC | SP-212 | | 80.8-81.12 | 7/8 | (R)WC-50035<br>(L)WC-50035 | WK-545 | CUP | 80.8-81.12 | (1)BH-02390<br>(2)BH-02391 | BH-02394 | 80.8-81.12 | 5/8 | MC-10075 | MK-4308 | 80.8-81.2<br>81.2-81.12 | 13/16<br>13/16 | CC-70109<br>CC-70109 | CK-3113<br>CK-3144 |
| | | SL(四輪ディスク) | 80.8-81.12 | 7/8 | | TK-9390 | 80.8-81.12 | 2 1/8 | DISC | SP-212 | | 80.8-81.12 | 1 1/2 | DISC | A-73P<br>A-46LP | | 80.8-81.12 | (1)BH-02390<br>(2)BH-02391 | (C)BH-02394<br>(R)BH-31264<br>(L)BH-31264 | 80.8-81.12 | 5/8 | MC-10075 | MK-4308 | 80.8-81.2<br>81.2-81.12 | 13/16<br>13/16 | CC-70109<br>CC-70109 | CK-3113<br>CK-3144 |
| | | SX | 80.8-81.12 | 7/8 | | TK-9390 | 80.8-81.12 | 2 1/8 | DISC | SP-212 | | 80.8-81.12 | 1 1/2 | DISC | A-73P<br>A-46LP | | 80.8-81.12 | BH-02385 | (C)BH-02394<br>(R)BH-31264<br>(L)BH-31264 | 80.8-81.12 | 5/8 | MC-10075 | MK-4308 | 80.8-81.2<br>81.2-81.12 | 13/16<br>13/16 | CC-70109<br>CC-70109 | CK-3113<br>CK-3144 |
| | RT137V(バン) | DX・GL | 78.9-79.12 | 13/16 | | TK-9389 | 78.9-79.12 | 2 | DISC | A-16P | | 78.9-79.12 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 78.9-79.12 | (1)BH-02390<br>(2)BH-02391 | BH-02214 | 78.9-79.12 | 5/8 | MC-10075 | MK-4308 | 78.9-79.12 | 13/16 | CC-70111 | CK-3113 |
| (2000) | RT131 | ドラム車 | 78.9-82.8 | 13/16 | | TK-9389 | 78.9-82.8 | 7/8 | (R-1)WC-51013<br>(R-2)WC-52013<br>(L-1)WC-53013<br>(L-2)WC-54013 | WK-113 | CUP | 78.9-82.8 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 78.9-82.8 | BH-02385 | BH-02394 | 78.9-82.8 | 5/8 | MC-10076 | MK-4300 | 78.9-79.9<br>79.9-81.2<br>81.2-82.8 | 7/8<br>7/8<br>7/8 | CC-70103<br>CC-70123<br>CC-70123 | CK-3110<br>CK-3110<br>CK-3121 |
| | | ディスク車 | 78.9-82.8 | 13/16 | | TK-9389 | 78.9-82.8 | 2 | DISC | C-16P | | 78.9-82.8 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 78.9-82.8 | (1)BH-02390<br>(2)BH-02391 | BH-02394 | 78.9-82.8 | 5/8 | MC-10076 | MK-4300 | 78.9-79.9<br>79.9-81.2<br>81.2-82.8 | 7/8<br>7/8<br>7/8 | CC-70103<br>CC-70123<br>CC-70123 | CK-3110<br>CK-3110<br>CK-3121 |
| | RT132 | | 78.9-81.12 | 7/8 | | TK-9390 | 78.9-81.12 | 2 1/8 | DISC | SP-212 | | 78.9-81.12 | 1 1/2 | DISC | A-73P<br>A-46LP | | 78.9-81.12 | BH-02385 | (C)BH-02394<br>(R)BH-31264<br>(L)BH-31264 | 78.9-81.12 | 5/8 | MC-10075 | MK-4308 | 78.9-80.9<br>80.9-81.2<br>81.2-81.12 | 13/16<br>13/16<br>13/16 | CC-70111<br>CC-70110<br>CC-70110 | CK-3113<br>CK-3113<br>CK-3144 |
| | RT133 | GL・CX | 78.9-80.8 | 13/16 | | TK-9389 | 78.9-80.8 | 2 | DISC | A-16P | | 78.9-80.8 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 78.9-80.8 | (1)BH-02390<br>(2)BH-02391 | BH-02394 | 78.9-80.8 | 5/8 | MC-10075 | MK-4308 | 78.9-80.8 | 13/16 | CC-70111 | CK-3113 |
| | | SL(リヤードラム) | 78.9-80.8 | 7/8 | | TK-9390 | 78.9-80.8 | 2 1/8 | DISC | SP-212 | | 78.9-80.8 | 7/8 | (R)WC-50035<br>(L)WC-50035 | WK-545 | CUP | 78.9-80.8 | BH-02385 | BH-02394 | 78.9-80.8 | 5/8 | MC-10075 | MK-4308 | 78.9-80.8 | 13/16 | CC-70111 | CK-3113 |
| | | SL(四輪ディスク) | 78.9-80.8 | 7/8 | | TK-9390 | 78.9-80.8 | 2 1/8 | DISC | SP-212 | | 78.9-80.8 | 1 1/2 | DISC | A-73P<br>A-46LP | | 78.9-80.8 | BH-02385 | (C)BH-02394<br>(R)BH-31264<br>(L)BH-31264 | 78.9-80.8 | 5/8 | MC-10075 | MK-4308 | 78.9-80.8 | 13/16 | CC-70111 | CK-3113 |
| | | CXサルーン(リヤードラム) | 80.8-81.12 | 7/8 | | TK-9390 | 80.8-81.12 | 2 1/8 | DISC | SP-212 | | 80.8-81.12 | 7/8 | (R)WC-50035<br>(L)WC-50035 | WK-545 | CUP | 80.8-81.12 | BH-02385 | BH-02394 | 80.8-81.12 | 5/8 | MC-10075 | MK-4308 | 80.8-81.2<br>81.2-81.12 | 13/16<br>13/16 | CC-70110<br>CC-70110 | CK-3113<br>CK-3144 |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CXサルーン（四輪ディスク） | 80.8-81.6 | 7/8 | | TK-9390 | 80.8-81.6 | 2 1/8 | DISC | SP-212 | | 80.8-81.6 | 1 1/2 | DISC | A-73P<br>A-46LP | | 80.8-81.6 | BH-02385 | (C)BH-02394<br>(R)BH-31264<br>(L)BH-31264 | 80.8-81.6 | 5/8 | MC-10075 | MK-4308 | 80.8-81.2<br>81.2-81.6 | 13/16<br>13/16 | CC-70110<br>CC-70110 | CK-3113<br>CK-3144 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CORONA : 140 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1500) | E−AT140 | | 82.1−87.12 | 13/16 | TD−T234 | TK−9389 | 82.1−87.12 | 2 | DISC | A−102P | | 82.1−87.12 | 13/16 | (R)WC−50059<br>(L)WC−50059 | WK−492 | CUP | 82.1−85.4<br><br>85.4−87.12 | (1)BH−02426<br>(2)BH−96001<br>BH−02474 | BH−02394<br><br>BH−02394 | 82.1−83.5<br>83.5−87.12 | 5/8<br>5/8 | MC−10118<br>MC−10138 | MK−4308<br>MK−4308 | 82.1−87.12 | 13/16 | CC−70151 | CK−3144 |
| | L−KT147V(バン) | | 83.10−87.12 | 13/16 | TD−T234 | TK−9389 | 83.10−87.12 | 2 | DISC | A−102P | | 83.10−87.12 | 13/16 | (R)WC−50059<br>(L)WC−50059 | WK−492 | CUP | 83.10−84.12<br><br>84.12−87.12 | (1)BH−02426<br>(2)BH−96001<br>BH−02474 | BH−94005<br><br>BH−94005 | 83.10−87.12 | 5/8 | MC−10138 | MK−4308 | 83.10−87.12 | 13/16 | CC−70111 | CK−3144 |
| (1600) | E−AT141 | | 83.10−85.8 | 15/16 | TD−T333 | TK−9417 | 83.10−85.8 | 2 1/4 | DISC | SP−229 | CPS−219 | 83.10−85.8 | 1 11/16 | DISC | SP−218 | | 83.10−85.4<br><br>85.4−85.8 | (1)BH−02426<br>(2)BH−96001<br><br>BH−02474 | (R−1)BH−95001<br>(L−1)BH−95001<br>(R−2)BH−02343<br>(L−2)BH−02343<br>(R−1)BH−95001<br>(L−1)BH−95001<br>(R−2)BH−02343<br>(L−2)BH−02343 | 83.10−85.8 | 5/8 | MC−10102 | MK−4300 | 83.10−85.8 | 13/16 | CC−70153 | CK−3144 |
| | L−TT147V(バン) | | 82.1−83.10 | 13/16 | TD−T234 | TK−9389 | 82.1−83.10 | 2 | DISC | A−102P | | 82.1−83.10 | 13/16 | (R)WC−50059<br>(L)WC−50059 | WK−492 | CUP | 82.1−83.10 | (1)BH−02426<br>(2)BH−96001 | BH−94005 | 82.1−83.5<br>83.5−83.10 | 5/8<br>5/8 | MC−10118<br>MC−10138 | MK−4308<br>MK−4308 | 82.1−83.10 | 13/16 | CC−70111 | CK−3144 |
| (1800) | E−TT142 | SX | 82.1−83.10 | 15/16 | TD−T333 | TK−9417 | 82.1−83.10 | 2 1/4 | DISC | SP−229 | CPS−219 | 82.1−83.10 | 13/16 | (R)WC−50059<br>(L)WC−50059 | WK−492 | CUP | 82.1−83.10 | (1)BH−02426<br>(2)BH−96001 | (R)BH−95001<br>(L)BH−95001 | 82.1−83.5<br>83.5−83.10 | 5/8<br>5/8 | MC−10118<br>MC−10138 | MK−4308<br>MK−4308 | 82.1−83.10 | 13/16 | CC−70111 | CK−3144 |
| | | GT−T・GT−TR | 82.10−85.8 | 15/16 | TD−T234 | TK−9417 | 82.10−85.8 | 2 1/4 | DISC | SP−229 | CPS−219 | 82.10−85.8 | 1 11/16 | DISC | SP−218 | | 82.10−85.4<br><br>85.4−85.8 | (1)BH−02426<br>(2)BH−96001<br><br>BH−02474 | (R−1)BH−95001<br>(L−1)BH−95001<br>(R−2)BH−02343<br>(L−2)BH−02343<br>(R−1)BH−95001<br>(L−1)BH−95001<br>(R−2)BH−02343<br>(L−2)BH−02343 | 82.10−83.5<br>83.5−85.8 | 5/8<br>5/8 | MC−10074<br>MC−10102 | MK−4300<br>MK−4300 | 82.10−85.8 | 13/16 | CC−70110 | CK−3144 |
| | E−ST140 | | 82.1−87.12 | 13/16 | TD−T234 | TK−9389 | 82.1−87.12 | 2 | DISC | A−102P | | 82.1−87.12 | 13/16 | (R)WC−50059<br>(L)WC−50059 | WK−492 | CUP | 82.1−85.4<br><br>85.4−87.12 | (1)BH−02426<br>(2)BH−96001<br>BH−02474 | BH−02394<br><br>BH−02394 | 82.1−83.5<br>83.5−87.12 | 5/8<br>5/8 | MC−10118<br>MC−10138 | MK−4308<br>MK−4308 | 82.1−87.12 | 13/16 | CC−70151 | CK−3144 |
| (1800ディーゼル) | N−CT140<br>Q−CT141 | STD | 82.1−86.12<br>86.12−91.11 | 13/16<br>13/16 | TD−T234 | TK−9389<br>TK−T024 | 82.1−86.12<br><br><br><br>86.12−91.11<br><br><br><br><ディスク車><br>82.1−87.12<br>87.12−91.11 | 7/8<br><br><br><br>7/8<br><br><br><br><br>2<br>2 | (R−1)WC−51013<br>(R−2)WC−52013<br>(L−1)WC−53013<br>(L−2)WC−54013<br>(R−1)WC−51013<br>(R−2)WC−52026<br>(L−1)WC−53013<br>(L−2)WC−54026<br><br>DISC<br>DISC | WK−113<br><br><br><br>WK−113<br><br><br><br><br>C−16P<br>A−246P | CUP<br><br><br><br>CUP | 82.1−91.11 | 13/16 | (R)WC−50059<br>(L)WC−50059 | WK−492 | CUP | 82.1−86.12<br>86.12−88.1<br><br>88.1−91.11<br><br><ディスク車><br>82.1−85.4<br><br>85.4−91.11 | BH−02209<br>(R)BH−02528<br>(L)BH−02529<br>(R)BH−T515<br>(L)BH−T516<br><br>(1)BH−02426<br>(2)BH−96001<br>BH−02474 | BH−02394<br>BH−02394<br><br>BH−02394<br><br><br>BH−02394<br><br>BH−02394 | 82.1−83.5<br>83.5−86.9<br>86.9−91.11 | 5/8<br>5/8<br>5/8 | MC−10110<br>MC−10141<br>MC−10141 | <br><br>MK−4329 | 82.1−85.8<br>85.8−91.11 | 13/16<br>13/16 | CC−70151<br>CC−70149 | CK−3144<br>CK−3144 |
| | | GX・EXサルーン | 82.1−83.10 | 13/16 | TD−T234 | TK−9389 | 82.1−83.10 | 2 | DISC | A−102P | | 82.1−83.10 | 13/16 | (R)WC−50059<br>(L)WC−50059 | WK−492 | CUP | 82.1−83.10 | (1)BH−02426<br>(2)BH−96001 | BH−02394 | 82.1−83.5<br>83.5−83.10 | 5/8<br>5/8 | MC−10110<br>MC−10141 | | 82.1−83.10 | 13/16 | CC−70151 | CK−3144 |
| (1800ディーゼル) | N−CT147V(バン) | | 82.1−87.12 | 13/16 | TD−T234 | TK−9389 | 82.1−87.12 | 2 | DISC | A−102P | | 82.1−87.12 | 13/16 | (R)WC−50059<br>(L)WC−50059 | WK−492 | CUP | 82.1−84.12<br><br>84.12−87.12 | (1)BH−02426<br>(2)BH−96001<br>BH−02474 | BH−94005<br><br>BH−94005 | 82.1−83.5<br>83.5−86.9<br>86.9−86.12<br>86.12−87.12 | 5/8<br>5/8<br>5/8<br>5/8 | MC−10110<br>MC−10141<br>MC−10141<br>MC−10141 | <br><br>MK−4329<br>MK−4337 | 82.1−85.8<br>85.8−87.12 | 13/16<br>13/16 | CC−70151<br>CC−70149 | CK−3144<br>CK−3144 |
| (2000) | E−RT141 | | 82.1−82.10 | 15/16 | TD−T333 | TK−9417 | 82.1−82.10 | 2 1/4 | DISC | SP−229 | CPS−219 | 82.1−82.10 | 1 11/16 | DISC | SP−218 | | 82.1−82.10 | (1)BH−02426<br>(2)BH−96001 | (R−1)BH−95001<br>(L−1)BH−95001<br>(R−2)BH−02343<br>(L−2)BH−02343 | 82.1−82.10 | 5/8 | MC−10118 | MK−4308 | 82.1−82.10 | 13/16 | CC−70110 | CK−3144 |

| Models | TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CORONA : 140 ser.(LPG, DIESEL) | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | <YT140> | | | | <YT140> | | | |
| (1800L. P. G) | E−YT140 | 82.9-86.12 | 13/16 | TD-T234 | TK-9389 | 82.9-86.12 | 7/8 | (R-1)WC-51013 | WK-113 | CUP | 82.9-98.4 | 13/16 | (R)WC-50059 | WK-492 | CUP | 82.9-86.12 | BH-02209 | BH-02394 | 82.9-83.1 | 5/8 | MC-10118 | MK-4308 | 82.9-88.5 | 13/16 | CC-70110 | CK-3144 |
| (1800ディーゼル) | N−CT140 | 86.12-98.4 | 13/16 | | TK-T024 | | | (R-2)WC-52013 | | | | | (L)WC-50059 | | | 86.12-88.1 | (R)BH-02528 | BH-02394 | 83.1-86.12 | 5/8 | MC-10139 | MK-4308 | 88.5-91.3 | 13/16 | CC-70110 | CK-3144 |
| | Q−CT141 | | | | | | | (L-1)WC-53013 | | | | | | | | | (L)BH-02529 | | 86.12-89.8 | 5/8 | MC-10143 | MK-4353 | 91.3-98.4 | 13/16 | CC-70110 | CK-T201 |
| | | | | | | | | (L-2)WC-54013 | | | | | | | | 88.1-95.12 | (R)BH-T515 | BH-02394 | 89.8-91.8 | 5/8 | MC-T390 | MK-T236 | | | | |
| | | | | | | 86.12-95.12 | 7/8 | (R-1)WC-51013 | WK-113 | CUP | | | | | | | (L)BH-T516 | | 91.8-95.5 | | | | | | | |
| | | | | | | | | (R-2)WC-52026 | | | | | | | | <ﾃﾞｨｽｸ車> | | | 95.5-98.4 | | | | | | | |
| | | | | | | | | (L-1)WC-53013 | | | | | | | | 82.9-85.4 | (1)BH-02426 | BH-02394 | <CT140,141> | | | | <CT140,141> | | | |
| | | | | | | | | (L-2)WC-54026 | | | | | | | | | (2)BH-96001 | | 82.9-83.5 | 5/8 | MC-10110 | | 82.9-85.8 | 13/16 | CC-70151 | CK-3144 |
| | | | | | | <ﾃﾞｨｽｸ車> | | | | | | | | | | 85.4-98.4 | BH-02474 | BH-02394 | 83.5-86.9 | 5/8 | MC-10141 | | 85.8-91.11 | 13/16 | CC-70149 | CK-3144 |
| | | | | | | 82.9-87.12 | 2 | DISC | C-16P | | | | | | | | | | 86.9-91.11 | 5/8 | MC-10141 | MK-4329 | | | | |
| | | | | | | 87.12-98.4 | 2 | DISC | A-246P | | | | | | | | | | | | | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CORONA(FF) : 150, 160 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1500) | E−AT150 | | 83.10−87.11 | 7/8 | | TK-9421 | 83.10−87.11 | 51.1 | DISC | MP-6 | | 83.10−87.11 | 3/4 | (R)WC-55021<br>(L)WC-57021 | WK-542 | CUP | 83.10−87.8<br>87.8−87.11 | BH-02455<br>BH-02455 | (R)BH-95003<br>(L)BH-95003<br>(R)<br>(L) | 83.10−84.2<br>84.2−84.9<br>84.9−87.11 | 5/8<br>5/8<br>5/8 | | MK-4315<br>MK-4310<br>MK-4344 | 83.10−87.1 | 13/16 | CC-70152 | CK-3131 |
| (1600) | E−AT160 | | 85.8−87.8 | 15/16 | | TK-T006 | 85.8−87.8 | 54.0 | DISC | MP-18 | | 85.8−87.8 | 31.7 | MD-121M | A-222P | | 85.8−87.8 | BH-02455 | (R)BH-02581<br>(L)BH-02581 | 85.8−86.5<br>86.5−87.8 | 5/8<br>5/8 | MC-T232 | MK-4344<br>MK-4344 | 85.8−87.8 | 13/16 | CC-70152 | CK-3131 |
| (1800) | E−ST150 | | 83.1−83.10<br>83.10−87.11 | 7/8<br>7/8 | | TK-9421<br>TK-9421 | 83.1−87.11 | 51.1 | DISC | MP-6 | | 83.1−87.11 | 3/4 | (R)WC-55021<br>(L)WC-57021 | WK-542 | CUP | 83.1−83.4<br>83.4−87.8<br>87.8−87.11 | BH-02448<br>BH-02455<br>BH-02455 | (R)BH-95003<br>(L)BH-95003<br>(R)BH-95003<br>(L)BH-95003<br>(R)<br>(L) | 83.1−84.9<br>84.9−87.11 | 5/8<br>5/8 | | MK-4310<br>MK-4344 | 83.1−84.5<br>84.5−87.11 | 13/16<br>13/16 | CC-70150<br>CC-70150 | CK-3129<br>CK-3144 |
| | E−ST160 | | 85.8−88.5 | 15/16 | | TK-T006 | 85.8−88.5 | 54.0 | DISC | MP-19 | | 85.8−88.5 | 3/4 | (R)WC-55021<br>(L)WC-57021 | WK-542 | CUP | 85.8−87.8<br>87.8−88.5 | BH-02455<br>BH-02550 | (R)BH-02472<br>(L)BH-02472<br>(R)BH-02472<br>(L)BH-02472 | 85.8−85.8<br>85.8−88.5 | 5/8<br>5/8 | MC-T232 | MK-4344<br>MK-4344 | 85.8−88.5 | 13/16 | CC-70150 | CK-3144 |
| | E−ST163 | | 88.5−89.8 | 15/16 | | TK-T006 | 88.5−89.8 | 54.0 | DISC | MP-19 | | 88.5−89.8 | 3/4 | (R)WC-55021<br>(L)WC-57021 | WK-542 | CUP | 88.5−89.8 | BH-02550 | (R)BH-02472<br>(L)BH-02472 | 88.5−89.8 | 5/8 | MC-T232 | MK-4344 | 88.5−89.2<br>89.2−89.8 | 13/16<br>13/16 | CC-70180<br>CC-70180 | CK-3144<br>CK-3144 |
| (2000) | E−ST162 | GT・GT−R | 85.8−89.8<br><アンチスキッド付><br>87.8−89.8 | 15/16<br><br>1 | | TK-T006<br><br>TK-T048 | 85.8−89.8<br><アンチスキッド付><br>87.8−89.8 | 54.0<br><br>57.2 | DISC<br><br>DISC | MP-18<br><br>MP-21 | | 85.8−89.8 | 31.7 | MD-121M | A-222P | | 85.8−87.8<br>87.8−89.8 | BH-02455<br>BH-02550 | (R)BH-02581<br>(L)BH-02581<br>(R)BH-02551<br>(L)BH-02551 | 85.8−86.5<br>86.5−89.8 | 5/8<br>5/8 | MC-T232 | MK-4344<br>MK-4344 | 85.8−89.2<br>89.2−89.8 | 13/16<br>13/16 | CC-70150<br>CC-70150 | CK-3144<br>CK-3144 |
| | | VX | 87.8−89.8<br><アンチスキッド付><br>88.5−89.8 | 15/16<br><br>1 | | TK-T006<br><br>TK-T048 | 87.8−89.8<br><アンチスキッド付><br>88.5−89.8 | 54.0<br><br>57.2 | DISC<br><br>DISC | MP-18<br><br>MP-21 | | 87.8−88.5<br><br>88.5−89.8 | 3/4<br><br>31.7 | (R)WC-55021<br>(L)WC-57021<br>MD-121M | WK-542<br><br>A-222P | CUP | 87.8−88.5<br><br>88.5−89.8 | BH-02550<br><br>BH-02550 | (R)BH-02472<br>(L)BH-02472<br>(R)BH-02551<br>(L)BH-02551 | 87.8−89.8 | 5/8 | | MK-4344 | 87.8−89.2<br>89.2−89.8 | 13/16<br>13/16 | CC-70180<br>CC-70180 | CK-3144<br>CK-3144 |
| (2000ディーゼル) | N−CT150<br>Q−CT150 | | 83.10−87.11 | 7/8 | | TK-9421 | 83.10−87.11 | 51.1 | DISC | MP-6 | | 83.10−87.11 | 3/4 | (R)WC-55021<br>(L)WC-57021 | WK-542 | CUP | 83.10−87.8<br>87.8−87.11 | BH-02455<br>BH-02455 | (R)BH-95003<br>(L)BH-95003<br>(R)<br>(L) | 83.10−86.9<br>86.9−87.11 | 5/8<br>5/8 | MC-10140 | MK-4337 | 83.10−84.5<br>84.5−87.11 | 13/16<br>13/16 | CC-70150<br>CC-70150 | CK-3129<br>CK-3144 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CORONA(FF) : 170 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1500) | E－AT170 | STD・DX・GX・MX | 87.12-92.2 | 7/8 | | TK-T032 | 87.12-90.7 | 54.0 | DISC | MP-20 | CPM-20 | 87.12-92.2 | 11/16 | (R)WC-55020 | WK-569 | CUP | 87.12-92.2 | BH-02565 | (R)BH-02497 | 87.12-88.6 | 5/8 | MC-T235 | MK-4353 | 87.12-88.5 | 13/16 | CC-70183 | CK-3144 |
| | | EXサルーン・セレクトサルーン | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | 90.7-92.2 | | DISC | MP-20 | CPM-19 | | | (L)WC-57020 | | | | | (L)BH-02497 | 88.6-89.11 | 5/8 | MC-T235 | MK-4344 | 88.5-92.2 | 13/16 | CC-70183 | CK-3144 |
| | | | 88.8-92.2 | 15/16 | | TK-T049 | | | | | | | | | | | | | | 89.11-92.2 | 5/8 | | MK-T236 | | | | |
| | L－ET176V(バン) | STD・DX・GX | 87.12-92.11 | 7/8 | | TK-T032 | 87.12-90.7 | 54.0 | DISC | MP-20 | CPM-20 | 87.12-92.11 | 3/4 | (R)WC-55021 | WK-542 | CUP | 87.12-92.11 | BH-02565 | (R)BH-02539 | 87.12-88.6 | 5/8 | MC-T235 | MK-4353 | 87.12-88.5 | 13/16 | CC-70179 | CK-3144 |
| | ＜Rｰは89．11～＞ | | | | | | 90.7-92.11 | | DISC | MP-20 | CPM-19 | | | (L)WC-57021 | | | | | (L)BH-02539 | 88.6-89.11 | 5/8 | MC-T235 | MK-4344 | 88.5-92.11 | 13/16 | CC-70179 | CK-3144 |
| | | | | | | | | | | | | | | | | | | | | 89.11-92.4 | 5/8 | | MK-T236 | | | | |
| | | | | | | | | | | | | | | | | | | | | 92.4-92.11 | 5/8 | | | | | | |
| (1600) | E－AT175(4WD) | GX・MX・EXサルーン | 88.8-92.2 | 15/16 | | TK-T349 | 88.8-92.2 | 57.2 | DISC | MP-21 | | 88.8-91.6 | 34.9 | DISC | MP-82 | | 88.8-92.2 | BH-02550 | (R)BH-02549 | 88.8-89.11 | 5/8 | MC-T235 | MK-4344 | 88.8-92.2 | 13/16 | CC-70183 | CK-3144 |
| | | セレクトサルーン | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | 91.6-92.2 | 34.9 | DISC | MP-82 | | | | (L)BH-02549 | 89.11-92.2 | 5/8 | | MK-T236 | | | | |
| | | | 89.11-92.2 | 15/16 | | TK-T300 | | | | | | | | | | | | | | | | | | | | | |
| (1800) | E－ST170 | GX・MX・EXサルーン | 87.12-92.2 | 7/8 | | TK-T032 | 87.12-90.7 | 54.0 | DISC | MP-20 | CPM-20 | 87.12-92.2 | 11/16 | (R)WC-55020 | WK-569 | CUP | 87.12-92.2 | BH-02565 | (R)BH-02497 | 87.12-88.6 | 5/8 | MC-T235 | MK-4353 | 87.12-89.2 | 13/16 | CC-70180 | CK-3144 |
| | | セレクトサルーン | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | 90.7-92.2 | 54.0 | DISC | MP-20 | CPM-19 | | | (L)WC-57020 | | | | | (L)BH-02497 | 88.6-89.11 | 5/8 | MC-T235 | MK-4344 | 89.2-92.2 | 13/16 | CC-70180 | CK-3144 |
| | | SFｰX・SFｰZ | 88.8-92.2 | 15/16 | | TK-T049 | | | | | | | | | | | | | | 89.11-92.2 | 5/8 | | MK-T236 | | | | |
| (2000) | E－ST171 | SXｰR・EXサルーンG | 87.12-92.2 | 15/16 | | TK-T349 | 87.12-92.2 | 57.2 | DISC | MP-21 | | 87.12-92.2 | 3/4 | (R)WC-55021 | WK-542 | CUP | 87.12-92.2 | BH-02565 | (R)BH-02497 | 87.12-88.6 | 5/8 | MC-T235 | MK-4353 | 87.12-89.2 | 13/16 | CC-70180 | CK-3144 |
| | | SFｰG | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | (L)WC-57021 | | | | | (L)BH-02497 | 88.6-89.11 | 5/8 | MC-T235 | MK-4344 | 89.2-92.2 | 13/16 | CC-70180 | CK-3144 |
| | | リヤードラム車 | 87.12-92.2 | 1 | | TK-T048 | | | | | | | | | | | | | | 89.11-92.2 | 5/8 | | MK-T236 | | | | |
| | | 四輪ディスク車 | 87.12-92.2 | 15/16 | | TK-T349 | 87.12-92.2 | 57.2 | DISC | MP-21 | | 87.12-92.2 | 31.7 | DISC | A-222P | | 87.12-92.2 | BH-02565 | (R)BH-02498 | 87.12-88.6 | 5/8 | MC-T235 | MK-4353 | 87.12-89.2 | 13/16 | CC-70180 | CK-3144 |
| | | | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | | | | | | (L)BH-02498 | 88.6-89.11 | 5/8 | MC-T235 | MK-4344 | 89.2-92.2 | 13/16 | CC-70180 | CK-3144 |
| | | | 87.12-92.2 | 1 | | TK-T048 | | | | | | | | | | | | | | 89.11-92.2 | 5/8 | | MK-T236 | | | | |
| | | GTｰR | 87.12-92.2 | 15/16 | | TK-T349 | 87.12-92.2 | 57.2 | DISC | MP-21 | | 87.12-91.6 | 31.7 | DISC | A-222P | | 87.12-92.2 | BH-02565 | (R)BH-02498 | 87.12-88.6 | 5/8 | MC-T235 | MK-4353 | 87.12-89.2 | 13/16 | CC-70150 | CK-3144 |
| | | SFｰGT | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | 91.6-92.2 | 31.7 | DISC | A-222P | | | | (L)BH-02498 | 88.6-89.11 | 5/8 | MC-T235 | MK-4344 | 89.2-92.2 | 13/16 | CC-70150 | CK-3144 |
| | | | 87.12-92.2 | 1 | | TK-T048 | | | | | | | | | | | | | | 89.11-92.2 | 5/8 | | MK-T236 | | | | |
| (2000ディーゼル) | | GX・MX・EXサルーン | 87.12-92.2 | 7/8 | | TK-T032 | 87.12-92.2 | 54.0 | DISC | MP-20 | CPM-20 | 87.12-92.2 | 11/16 | (R)WC-55020 | WK-569 | CUP | 87.12-92.2 | BH-02565 | (R)BH-02497 | 87.12-88.6 | 5/8 | MC-T236 | MK-4337 | 87.12-89.2 | 13/16 | CC-70150 | CK-3144 |
| | Qｰ CT170 | セレクトサルーン | | | | | | | | | | | | (L)WC-57020 | | | | | (L)BH-02497 | 88.6-89.11 | 5/8 | MC-T236 | MK-4342 | 89.2-92.2 | 13/16 | CC-70150 | CK-3144 |
| | ＜Xｰは91．6～＞ | | | | | | | | | | | | | | | | | | | 89.11-92.2 | 5/8 | | MK-T236 | | | | |
| | Sｰ CT176V(バン) | DX | 87.12-92.11 | 7/8 | | TK-T032 | 87.12-90.7 | 54.0 | DISC | MP-20 | CPM-20 | 87.12-92.11 | 3/4 | (R)WC-55021 | WK-542 | CUP | 87.12-92.11 | BH-02565 | (R)BH-02539 | 87.12-88.6 | 5/8 | MC-T236 | MK-4337 | 87.12-89.2 | 13/16 | CC-70150 | CK-3144 |
| | | | | | | | 90.7-92.11 | | DISC | MP-20 | CPM-19 | | | (L)WC-57021 | | | | | (L)BH-02539 | 88.6-89.11 | 5/8 | MC-T236 | MK-4342 | 89.2-92.11 | 13/16 | CC-70150 | CK-3144 |
| | | | | | | | | | | | | | | | | | | | | 89.11-92.4 | 5/8 | | MK-T236 | | | | |
| | | | | | | | | | | | | | | | | | | | | 92.4-92.11 | 5/8 | | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CORONA(FF) : 190 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1600) | E−AT190 | | 92.2−96.1<br><ｱﾝﾁｽｷｯﾄﾞ付><br>92.2−96.1 | 7/8<br><br>15/16 | | TK−T402<br><br>TK−T344 | 92.2−96.1 | 57.2 | DISC | MP−50 | CPM−68 | 92.2−96.1 | 3/4 | (R)WC−T600<br>(L)WC−T605 | WK−542 | CUP | 92.2−96.1 | (R)BH−T596<br>(L)BH−T610 | (R)BH−T629<br>(L)BH−T607 | 92.2−94.3<br>94.3−96.1 | 5/8<br>5/8 | MC−T394 | MK−T244 | 92.2−93.1<br>93.1−96.1 | 13/16<br>13/16 | CC−70183<br>CC−70183 | CK−3144<br>CK−T201 |
| (1800) | E−ST190 | | 92.2−96.1<br><ｱﾝﾁｽｷｯﾄﾞ付><br>92.2−96.1 | 7/8<br><br>15/16 | | TK−T402<br><br>TK−T344 | 92.2−96.1 | 57.2 | DISC | MP−50 | CPM−68 | 92.2−96.1 | 3/4 | (R)WC−T600<br>(L)WC−T605 | WK−542 | CUP | 92.2−96.1 | (R)BH−T596<br>(L)BH−T610 | (R)BH−T629<br>(L)BH−T607 | 92.2−94.3<br>94.3−96.1 | 5/8<br>5/8 | MC−T394 | MK−T244 | 92.2−94.2<br>94.2−96.1 | 13/16<br>13/16 | CC−70180<br>CC−70180 | CK−3144<br>CK−T201 |
| | E−ST190Y | 教習車 | <生徒側><br>92.11−94.6<br>94.6−96.1<br><教官側><br>92.11−96.1 | <br>7/8<br>7/8 | | TK−T402<br>TK−T402 | 92.11−96.1 | 57.2 | DISC | MP−50 | CPM−68 | 92.11−96.1 | 3/4 | (R)WC−T600<br>(L)WC−T605 | WK−542 | CUP | 92.11−96.1 | (R)BH−T596<br>(L)BH−T610 | (R)BH−T629<br>(L)BH−T607 | 92.11−94.3<br>94.3−96.1 | 5/8<br>5/8 | MC−T394 | MK−T244 | 92.11−94.2<br>94.2−96.1 | 13/16<br>13/16 | CC−70180<br>CC−70180 | CK−3144<br>CK−T201 |
| (2000) | E−ST191 | | 92.2−96.1<br><ｱﾝﾁｽｷｯﾄﾞ付><br>92.2−96.1 | 7/8<br><br>15/16 | | TK−T402<br><br>TK−T344 | 92.2−96.1 | 57.2 | DISC | MP−50 | CPM−68 | 92.2−96.1 | 31.7 | DISC | A−222P | | 92.2−96.1 | (R)BH−T596<br>(L)BH−T610 | (R)BH−T571<br>(L)BH−T572 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | E−ST195(4WD) | | 92.2−96.1<br><ｱﾝﾁｽｷｯﾄﾞ付><br>92.2−96.1 | 7/8<br><br>15/16 | | TK−T402<br><br>TK−T344 | 92.2−96.1 | 57.2 | DISC | MP−50 | CPM−68 | 92.2−94.2<br>94.2−96.1 | 34.9 | DISC<br>DISC | MP−82<br>C−222P | | 92.2−96.1 | (R)BH−T596<br>(L)BH−T610 | (R)BH−T631<br>(L)BH−T632 | 92.2−94.3<br>94.3−96.1 | 5/8<br>5/8 | MC−T394 | MK−T244 | 92.2−94.2<br>94.2−96.1 | 13/16<br>13/16 | CC−70180<br>CC−70180 | CK−3144<br>CK−T201 |
| (2000ディーゼル) | X−CT190<br><KDーは94．12～> | | 92.2−96.1<br><ｱﾝﾁｽｷｯﾄﾞ付><br>92.2−96.1 | 7/8<br><br>15/16 | | TK−T402<br><br>TK−T344 | 92.2−96.1 | 57.2 | DISC | MP−50 | CPM−68 | 92.2−96.1 | 3/4 | (R)WC−T600<br>(L)WC−T605 | WK−542 | CUP | 92.2−96.1 | (R)BH−T596<br>(L)BH−T610 | (R)BH−T629<br>(L)BH−T607 | 92.2−94.3<br>94.3−96.1 | 5/8<br>5/8 | MC−T394 | MK−T244 | 92.2−94.2<br>94.2−96.1 | 13/16<br>13/16 | CC−70150<br>CC−70150 | CK−3144<br>CK−T201 |
| | X−CT190Y<br><KDーは94．12～> | 教習車 | <生徒側><br>92.11−94.6<br>94.6−96.1<br><教官側><br>92.11−96.1 | <br>7/8<br>7/8 | | TK−T402<br>TK−T402 | 92.11−96.1 | 57.2 | DISC | MP−50 | CPM−68 | 92.11−96.1 | 3/4 | (R)WC−T600<br>(L)WC−T605 | WK−542 | CUP | 92.11−96.1 | (R)BH−T596<br>(L)BH−T610 | (R)BH−T629<br>(L)BH−T607 | 92.11−94.3<br>94.3−96.1 | 5/8<br>5/8 | MC−T396 | MK−T244 | 92.11−94.2<br>94.2−96.1 | 13/16<br>13/16 | CC−70150<br>CC−70150 | CK−3144<br>CK−T201 |
| | Y−CT195(4WD)<br><KDーは94．12～> | | 92.8−96.1<br><ｱﾝﾁｽｷｯﾄﾞ付><br>92.8−96.1 | 7/8<br><br>15/16 | | TK−T402<br><br>TK−T344 | 92.8−96.1 | 57.2 | DISC | MP−50 | CPM−68 | 92.8−94.2<br>94.2−96.1 | 34.9 | DISC<br>DISC | MP−82<br>C−222P | | 92.8−96.1 | (R)BH−T596<br>(L)BH−T610 | (R)BH−T631<br>(L)BH−T632 | 92.8−94.3<br>94.3−96.1 | 5/8<br>5/8 | MC−T396 | MK−T244 | 92.8−94.2<br>94.2−96.1 | 13/16<br>13/16 | CC−70150<br>CC−70150 | CK−3144<br>CK−T201 |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CORONA(FF) : 210 ser. | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1600) E−AT210 <GF−は98. 8〜> | 96.1-01.12 | 15/16 | | TK-T401 | 96.1-97.11<br>97.11-01.12 | 57.2 | DISC<br>DISC | MP-50<br>MP-103 | CPM-68<br>CPM-68 | 96.1-01.12 | 3/4 | (R)WC-T600<br>(L)WC-T605 | WK-542 | CUP | 96.1-01.12 | (R)BH-T596<br>(L)BH-T610 | (R)BH-T692<br>(L)BH-T729 | 96.1-01.12 | 5/8 | MC-T394 | MK-T244 | 96.1-01.12 | 13/16 | CC-70183 | CK-T201 |
| (1800) E−AT211 <GF−は98. 8〜> | 96.1-01.12 | 15/16 | | TK-T401 | 96.1-97.11<br>97.11-01.12 | 57.2 | DISC<br>DISC | MP-50<br>MP-103 | CPM-68<br>CPM-68 | 96.1-01.12 | 3/4 | (R)WC-T600<br>(L)WC-T605 | WK-542 | CUP | 96.1-01.12 | (R)BH-T596<br>(L)BH-T610 | (R)BH-T692<br>(L)BH-T729 | 96.1-01.12 | 5/8 | MC-T394 | MK-T244 | 96.1-01.12 | 13/16 | CC-70183 | CK-T201 |
| (2000) E−ST210 <GF−は98. 8〜> | 96.1-01.12 | 15/16 | | TK-T401 | 96.1-97.11<br>97.11-01.12 | 57.2 | DISC<br>DISC | MP-50<br>MP-103 | CPM-68<br>CPM-68 | 96.1-01.12 | 3/4 | (R)WC-T600<br>(L)WC-T605 | WK-542 | CUP | 96.1-01.12 | (R)BH-T596<br>(L)BH-T610 | (R)BH-T692<br>(L)BH-T729 | | | (オートマチック) | | | | |
| E−ST215(4WD) <GF−は98. 8〜> | 96.1-01.12 | 15/16 | | TK-T401 | 96.1-97.11<br>97.11-01.12 | 57.2 | DISC<br>DISC | MP-50<br>MP-103 | CPM-68<br>CPM-68 | 96.1-01.12 | 3/4 | (R)WC-T743<br>(L)WC-T749 | WK-899 | CUP | 96.1-01.12 | (R)BH-T596<br>(L)BH-T610 | (R)BH-T732<br>(L)BH-T731 | 96.1-01.12 | 5/8 | MC-T395 | MK-T244 | 96.1-01.12 | 7/8 | | CK-T200 |
| (2000ディーゼル) KD−CT210 | 96.1-97.12 | 15/16 | | TK-T401 | 96.1-97.12 | 57.2 | DISC | MP-50 | CPM-68 | 96.1-97.12 | 3/4 | (R)WC-T600<br>(L)WC-T605 | WK-542 | CUP | 96.1-97.12 | (R)BH-T596<br>(L)BH-T610 | (R)BH-T692<br>(L)BH-T729 | 96.1-97.12 | 5/8 | MC-T396 | MK-T244 | 96.1-97.12 | 13/16 | CC-70150 | CK-T201 |
| KD−CT215(4WD) | 96.1-97.12 | 15/16 | | TK-T401 | 96.1-97.12 | 57.2 | DISC | MP-50 | CPM-68 | 96.1-97.12 | 3/4 | (R)WC-T743<br>(L)WC-T749 | WK-899 | CUP | 96.1-97.12 | (R)BH-T596<br>(L)BH-T610 | (R)BH-T732<br>(L)BH-T731 | 96.1-97.12 | 5/8 | MC-T396 | MK-T244 | 96.1-97.12 | 13/16 | CC-70150 | CK-T201 |
| (2200ディーゼル) KE−CT211 | 97.12-01.12 | 15/16 | | TK-T401 | 97.12-01.12 | 57.2 | DISC | MP-103 | CPM-68 | 97.12-01.12 | 3/4 | (R)WC-T600<br>(L)WC-T605 | WK-542 | CUP | 97.12-01.12 | (R)BH-T596<br>(L)BH-T610 | (R)BH-T692<br>(L)BH-T729 | 97.12-01.12 | 5/8 | MC-T396 | MK-T244 | 97.12-01.12 | 13/16 | CC-70150 | CK-T201 |
| KH−CT216(4WD) | 97.12-01.12 | 15/16 | | TK-T401 | 97.12-01.12 | 57.2 | DISC | MP-103 | CPM-68 | 97.12-01.12 | 3/4 | (R)WC-T743<br>(L)WC-T749 | WK-899 | CUP | 97.12-01.12 | (R)BH-T596<br>(L)BH-T610 | (R)BH-T732<br>(L)BH-T731 | | | (オートマチック) | | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| PREMIO, ALLION : 240 ser.(01.12-) | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1500) UA－NZT240<br>＜CBA－は04．12～＞ | 01.12-07.5 | | | | 01.12-07.5 | | DISC | MP-102 | CPM-102 | 01.12-07.5 | 3/4 | (R)WC-T780<br>(L)WC-T781 | WK-542 | CUP | 01.12-06.11<br><br><br>06.11-07.5 | (R)BH-T946<br>(L)BH-T947<br>(R)BH-T946<br>(L)BH-T947 | (R)BH-T948<br>(L)BH-T948<br>(R)<br>(L) | | | (オートマチック) | | | | | |
| (1800) UA－ZZT240<br>＜CBA－は04．12～＞<br>＜DBA－は04．12～＞ | 01.12-07.5 | | | | 01.12-07.5 | | DISC | MP-102 | CPM-102 | 01.12-07.5 | 3/4 | (R)WC-T780<br>(L)WC-T781 | WK-542 | CUP | 01.12-06.11<br><br><br>06.11-07.5 | (R)BH-T946<br>(L)BH-T947<br>(R)BH-T946<br>(L)BH-T947 | (R)BH-T948<br>(L)BH-T948<br>(R)<br>(L) | | | (オートマチック) | | | | | |
| UA－ZZT245(4WD)<br>＜CBA－は04．12～＞ | 01.12-07.5 | | | | 01.12-07.5 | | MD-261 | MP-103 | CPM-68 | 01.12-07.5 | 3/4 | (R)WC-T785<br>(L)WC-T785 | WK-899 | CUP | 01.12-07.5 | (R)BH-T946<br>(L)BH-T947 | (R)BH-T846<br>(L)BH-T846 | | | (オートマチック) | | | | | |
| (2000) TA－AZT240<br>＜CBA－は04．12～＞ | 01.12-07.5 | | | | 01.12-07.5 | | MD-261 | MP-103 | CPM-68 | 01.12-07.5 | 11/16 | (R)WC-T786<br>(L)WC-T786 | WK-834 | CUP | 01.12-06.11<br><br><br>06.11-07.5 | (R)BH-T946<br>(L)BH-T947<br>(R)BH-T946<br>(L)BH-T947 | (R)BH-T948<br>(L)BH-T948<br>(R)<br>(L) | | | (オートマチック) | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| PREMIO, ALLION : 260 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1500) | DBA－NZT260 | 07.6- | | | | <刻印確認 ADVICS><br>07.6-<br><刻印確認 AK><br>07.6- | <br><br>54 | DISC<br><br>DISC | MP-116<br><br>MP-110 | CPM-116 | 07.6- | 13/16 | (R)WC-T797<br>(L)WC-T798 | WK-999 | CUP | 07.6- | | | | | (オートマチック) | | | | | |
| (1800) | DBA－ZRT260 | 07.6- | | | | 07.6- | | DISC | MP-116 | CPM-116 | 07.6- | 13/16 | (R)WC-T797<br>(L)WC-T798 | WK-999 | CUP | 07.6- | | | | | (オートマチック) | | | | | |
| | DBA－ZRT265 4WD | 07.6- | | | | 07.6- | | DISC | MP-116 | CPM-116 | 07.6- | 7/8 | (R)WC-T796<br>(L)WC-T796 | WK-1051 | CUP | 07.6- | | | | | (オートマチック) | | | | | |
| (2000) | DBA－ZRT261 | 08.1- | | | | 08.1- | | DISC | MP-116 | CPM-116 | 08.1- | 7/8 | (R)WC-T796<br>(L)WC-T796 | WK-1051 | CUP | 08.1- | | | | | (オートマチック) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CORONA EXIV : 180 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) | E−ST180 | FG・TR・FE | 89.9−91.8 | 7/8 | | TK−T402 | 89.9−91.8 | 54.0 | DISC | MP−20 | | 89.9−93.9 | 3/4 | (R)WC−T558 | WK−542 | CUP | 89.9−93.9 | BH−T517 | (R)BH−T518 | 89.9−93.3 | 5/8 | MC−T294 | MK−T236 | 89.9−93.9 | 13/16 | CC−70180 | CK−3144 |
| | E−ST181(4WS) | | 91.8−93.9 | 15/16 | | TK−T307 | 91.8−93.9 | 57.2 | DISC | A−306P | | | | (L)WC−T575 | | | | | (L)BH−T518 | 93.3−93.9 | 5/8 | MC−T294 | | | | | |
| | | | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | 90.8−91.8 | 15/16 | | TK−T300 | | | | | | | | | | | | | | | | | | | | | | |
| | | | 91.8−93.9 | 1 | | TK−T306 | | | | | | | | | | | | | | | | | | | | | | |
| (2000) | E−ST182 | TR・FE・TR−G | 89.9−93.9 | 15/16 | | TK−T307 | 89.9−93.9 | 57.2 | DISC | A−306P | | 89.9−91.1 | 31.7 | DISC | A−222P | | 89.9−93.9 | BH−T517 | (R)BH−T519 | 89.9−93.3 | 5/8 | MC−T294 | MK−T236 | <TR,FE> 89.9−93.9 | 13/16 | CC−70180 | CK−3144 |
| | E−ST183(4WS) | | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | 91.1−93.9 | 31.7 | DISC | A−222P | | | | (L)BH−T519 | 93.3−93.9 | 5/8 | MC−T294 | | <TRG> | | | |
| | | | 89.9−93.9 | 1 | | TK−T306 | | | | | | | | | | | | | | | | | | 89.9−93.9 | 13/16 | | CK−3144 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CORONA EXIV : 200 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) | E−ST200・201 | | 93.9-95.8 | 7/8 | | TK-T341 | 93.9-98.4 | 57.2 | DISC | MP-50 | CPM-68 | 93.9-98.4 | 3/4 | (R)WC-T600 | WK-542 | CUP | 93.9-98.4 | (R)BH-T597 | (R)BH-T590 | 93.9-94.4 | 5/8 | MC-T413 | | 93.9-94.1 | 13/16 | CC-70180 | CK-3144 |
| | | | 95.8-96.6 | 7/8 | | TK-T402 | | | | | | | | (L)WC-T605 | | | | (L)BH-T598 | (L)BH-T590 | 94.4-98.4 | 5/8 | MC-T413 | MK-T244 | 94.1-98.4 | 13/16 | CC-70180 | CK-T201 |
| | | | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | 93.9-97.6 | 15/16 | | TK-T342 | | | | | | | | | | | | | | | | | | | | | |
| | | | 97.6-98.4 | 15/16 | | TK-T401 | | | | | | | | | | | | | | | | | | | | | |
| (2000) | E−ST202・203 | TR−R・TR−X | 93.9-95.8 | 15/16 | | TK-T349 | 93.9-98.4 | 57.2 | DISC | MP-50 | CPM-68 | 93.9-98.4 | 31.7 | DISC | A-222P | | 93.9-98.4 | (R)BH-T597 | (R)BH-T591 | 93.9-94.4 | 5/8 | MC-T413 | | 93.9-94.1 | 13/16 | CC-70180 | CK-3144 |
| | | 200E・200G | 95.8-96.6 | 15/16 | | TK-T409 | | | | | | | | | | | | (L)BH-T598 | (L)BH-T591 | 94.4-98.4 | 5/8 | MC-T413 | MK-T244 | 94.1-98.4 | 13/16 | CC-70180 | CK-T201 |
| | | | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | 93.9-97.6 | 15/16 | | TK-T342 | | | | | | | | | | | | | | | | | | | | | |
| | | | 97.6-98.4 | 15/16 | | TK-T401 | | | | | | | | | | | | | | | | | | | | | |
| | | TR−G | 93.9-95.8 | 15/16 | | TK-T349 | 93.9-98.4 | 57.2 | DISC | MP-50 | CPM-68 | 93.9-98.4 | | DISC | C-222P | | 93.9-98.4 | (R)BH-T597 | (R)BH-T591 | 93.9-94.4 | 5/8 | MC-T413 | | 93.9-94.1 | 13/16 | | CK-3144 |
| | | 200GT | 95.8-96.6 | 15/16 | | TK-T409 | | | | | | | | | | | | (L)BH-T598 | (L)BH-T591 | 94.4-98.4 | 5/8 | MC-T413 | MK-T244 | 94.1-98.4 | 13/16 | | CK-T201 |
| | | （ノーマルサス車） | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | 93.9-97.6 | 15/16 | | TK-T342 | | | | | | | | | | | | | | | | | | | | | |
| | | | 97.6-98.4 | 15/16 | | TK-T401 | | | | | | | | | | | | | | | | | | | | | |
| | | TR−G | 93.9-95.8 | 15/16 | | TK-T349 | 93.9-98.4 | | DISC | MP-61 | | 93.9-98.4 | | DISC | C-222P | | 93.9-98.4 | (R)BH-T641 | (R)BH-T591 | 93.9-94.4 | 5/8 | MC-T413 | | 93.9-94.1 | 13/16 | | CK-3144 |
| | | 200GT | 95.8-96.6 | 15/16 | | TK-T409 | | | | | | | | | | | | (L)BH-T642 | (L)BH-T591 | 94.4-98.4 | 5/8 | MC-T413 | MK-T244 | 94.1-98.4 | 13/16 | | CK-T201 |
| | | （スーパーストラットサス車） | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | 93.9-97.6 | 15/16 | | TK-T342 | | | | | | | | | | | | | | | | | | | | | |
| | | | 97.6-98.4 | 15/16 | | TK-T401 | | | | | | | | | | | | | | | | | | | | | |
| | E−ST205（4WD） | | 94.5-95.8 | 15/16 | | TK-T349 | 94.5-98.4 | | DISC | MP-61 | | 94.5-98.4 | | DISC | C-438P | | 94.5-98.4 | (R)BH-T641 | (R)BH-T643 | 94.5-98.4 | 5/8 | MC-T413 | MK-T244 | 94.5-98.4 | 13/16 | | CK-T201 |
| | | | 95.8-96.6 | 15/16 | | TK-T409 | | | | | | | | | | | | (L)BH-T642 | (L)BH-T644 | | | | | | | | |
| | | | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | 94.5-97.6 | 15/16 | | TK-T342 | | | | | | | | | | | | | | | | | | | | | |
| | | | 97.6-98.4 | 15/16 | | TK-T401 | | | | | | | | | | | | | | | | | | | | | |

| Models | TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| MARK 2 : 10, 20 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1700) | RX10・20 | DX | 72.1-73.4<br>73.4-73.7 | 15/16<br>7/8 | | TK-9311<br>TK-9313 | 72.1-73.7 | 48.1 | DISC | SP-208 | | 72.1-73.7 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 72.1-73.7 | BH-02181 | BH-02192 | 72.1-73.7 | 5/8 | MC-10044 | MK-3001 | 72.1-73.7 | 3/4 | CC-70071 | CK-41480 |
| | RX16V(バン) | STD・DX | 72.1-73.7 | 3/4 | | MK-4402 | 72.1-73.7 | 7/8 | (R)WC-32011<br>(L)WC-32012 | WK-048 | CUP | 72.1-73.7 | 3/4 | (R)WC-50022<br>(L)WC-50022 | | CUP | 72.1-73.7 | BH-02191 | BH-31380 | 72.1-73.7 | 5/8 | MC-10044 | MK-3001 | 72.1-73.7 | 3/4 | CC-70071 | CK-41480 |
| (1800) | RX11・21 | DX | 73.8-75.8<br>75.8-75.11 | 7/8<br>7/8 | | TK-9313<br>TK-9313 | 73.8-75.11 | 48.1 | DISC | SP-208 | | 73.8-75.11 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 73.8-75.11 | BH-02181 | BH-02192 | 73.8-74.8<br>74.8-75.11 | 5/8<br>5/8 | MC-10044<br>MC-10064 | <br>MK-4300 | 73.8-75.11 | 3/4 | CC-70090 | CK-3108 |
| | | GL | 7412-7511 | 7/8 | | TK-9313 | 7412-7511 | 48.1 | DISC | SP-208 | | 7412-7511 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 74.12-75.11 | BH-02181 | BH-02192 | 7412-7511 | 5/8 | MC-10064 | MK-4300 | 7412-7511 | 3/4 | CC-70090 | CK-3108 |
| | RX17V(バン) | STD・DX | 73.8-75.8<br>75.8-76.11 | 7/8<br>7/8 | | TK-9313<br>TK-9313 | 73.8-76.11 | 48.1 | DISC | SP-208 | | 73.8-76.11 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 73.8-76.11 | BH-02181 | BH-31380 | 73.8-74.8<br>74.8-76.11 | 5/8<br>5/8 | MC-10044<br>MC-10064 | <br>MK-4300 | 73.8-76.11 | 3/4 | CC-70090 | CK-3108 |
| (2000) | RX12 | STD・DX | 72.1-73.4<br>73.4-75.8<br>75.8-76.5 | 15/16<br>7/8<br>7/8 | | TK-9311<br>TK-9313<br>TK-9313 | 72.1-76.5 | 48.1 | DISC | SP-208 | | 72.1-76.5 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 72.1-76.5 | BH-02181 | BH-02192 | 72.1-73.7<br>73.8-74.8<br>74.8-76.5 | 5/8<br>5/8<br>5/8 | MC-10044<br>MC-10044<br>MC-10064 | MK-3001<br><br>MK-4300 | 72.1-73.7<br>73.8-76.5 | 3/4<br>3/4 | CC-70071<br>CC-70090 | CK-41480<br>CK-3108 |
| | | GL・GSL | 72.1-73.4<br>73.4-74.8<br>74.8-76.5 | 15/16<br>7/8<br>15/16 | | TK-9311<br>TK-9313<br>TK-9311 | 72.1-74.8<br>74.8-76.5 | 48.1<br>2 1/8 | DISC<br>DISC | SP-208<br>SP-212 | | 72.1-74.8<br>74.8-76.5 | 3/4<br>7/8 | (R)WC-50060<br>(L)WC-50060<br>(R)WC-50035<br>(L)WC-50035 | WK-491<br>WK-545 | CUP<br>CUP | 72.1-76.5 | BH-02181 | BH-02192 | 72.1-73.7<br>73.8-74.8<br>74.8-76.5 | 5/8<br>5/8<br>5/8 | MC-10044<br>MC-10044<br>MC-10064 | MK-3001<br><br>MK-4300 | 72.1-73.7<br>73.8-76.5 | 3/4<br>3/4 | CC-70071<br>CC-70090 | CK-41480<br>CK-3108 |
| | RX15 | DX | 76.6-76.11 | 7/8 | | TK-9313 | 76.6-76.11 | 48.1 | DISC | SP-208 | | 76.6-76.11 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 76.6-76.11 | BH-02181 | BH-02192 | 76.6-76.11 | 5/8 | MC-10064 | MK-4300 | 76.6-76.11 | 3/4 | CC-70090 | CK-3108 |
| | | GL・GSL | 76.6-76.11 | 15/16 | | TK-9311 | 76.6-76.11 | 2 1/8 | DISC | SP-212 | | 76.6-76.11 | 7/8 | (R)WC-50035<br>(L)WC-50035 | WK-545 | CUP | 76.6-76.11 | BH-02181 | BH-02192 | 76.6-76.11 | 5/8 | MC-10064 | MK-4300 | 76.6-76.11 | 3/4 | CC-70090 | CK-3108 |
| (2000) | RX22 | DX | 72.1-73.4<br>73.4-75.8<br>75.8-76.5 | 15/16<br>7/8<br>7/8 | | TK-9311<br>TK-9313<br>TK-9313 | 72.1-76.5 | 48.1 | DISC | SP-208 | | 72.1-76.5 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 72.1-76.5 | BH-02181 | BH-02192 | 72.1-73.7<br>73.8-74.8<br>74.8-76.5 | 5/8<br>5/8<br>5/8 | MC-10044<br>MC-10044<br>MC-10064 | MK-3001<br><br>MK-4300 | 72.1-73.7<br>73.8-76.5 | 3/4<br>3/4 | CC-70071<br>CC-70090 | CK-41480<br>CK-3108 |
| | | GL・SL・GSL | 72.1-73.4<br>73.4-74.8<br>74.8-76.5 | 15/16<br>7/8<br>15/16 | | TK-9311<br>TK-9313<br>TK-9311 | 72.1-74.8<br>74.8-76.5 | 48.1<br>2 1/8 | DISC<br>DISC | SP-208<br>SP-212 | | 72.1-74.8<br>74.8-76.5 | 3/4<br>7/8 | (R)WC-50060<br>(L)WC-50060<br>(R)WC-50035<br>(L)WC-50035 | WK-491<br>WK-545 | CUP<br>CUP | 72.1-76.5 | BH-02181 | BH-02192 | 72.1-73.7<br>73.8-74.8<br>74.8-76.5 | 5/8<br>5/8<br>5/8 | MC-10044<br>MC-10044<br>MC-10064 | MK-3001<br><br>MK-4300 | 72.1-73.7<br>73.8-76.5 | 3/4<br>3/4 | CC-70071<br>CC-70090 | CK-41480<br>CK-3108 |
| (2000) | RX22 | GSS | 72.1-75.11 | 15/16 | | TK-9311 | 72.1-75.11 | 2 1/8 | DISC | SP-212 | | 72.1-75.11 | 7/8 | (R)WC-50035<br>(L)WC-50035 | WK-545 | CUP | 72.1-75.11 | BH-02181 | BH-02192 | 72.1-74.11<br>74.11-75.11 | 5/8<br>5/8 | MC-10045 | MK-4300<br>MK-4300 | 72.1-73.7<br>73.8-75.11 | 3/4<br>3/4 | CC-70071<br>CC-70090 | CK-41480<br>CK-3108 |
| (1700) | RX26(ワゴン) | DX | 72.1-73.4 | 15/16 | | TK-9311 | 72.1-76.11 | 48.1 | DISC | SP-208 | | 72.1-76.11 | 3/4 | (R)WC-50060 | WK-491 | CUP | 72.1-76.11 | BH-02181 | BH-31380 | 72.1-73.7 | 5/8 | MC-10044 | MK-3001 | 72.1-73.7 | 3/4 | CC-70071 | CK-41480 |
| (1800) | RX27(ワゴン) | | 73.4-75.8 | 7/8 | | TK-9313 | | | | | | | | (L)WC-50060 | | | | | | 73.8-74.8 | 5/8 | MC-10044 | | 73.8-76.11 | 3/4 | CC-70090 | CK-3108 |
| (2000) | RX28(ワゴン) | | 75.8-76.11 | 7/8 | | TK-9313 | | | | | | | | | | | | | | 74.8-76.11 | 5/8 | MC-10064 | MK-4300 | | | | |
| (2000) | MX10・20 | L・LX・LG | 72.1-76.11 | 15/16 | | TK-9311 | 72.1-76.11 | 2 1/8 | DISC | SP-212 | | 72.1-76.11 | 7/8 | (R)WC-50035<br>(L)WC-50035 | WK-545 | CUP | 72.1-76.11 | BH-02181 | BH-02192 | 72.1-73.7<br>73.8-74.8<br>74.8-76.11 | 5/8<br>5/8<br>5/8 | MC-10044<br>MC-10044<br>MC-10064 | MK-3001<br><br>MK-4300 | 72.1-73.7<br>73.8-76.11 | 3/4<br>3/4 | CC-22020<br>CC-70091 | CK-41480<br>CK-3108 |
| | MX27(ワゴン) | L | 73.8-74.8<br>74.8-76.11 | 15/16<br>15/16 | | TK-9311<br>TK-9311 | 73.8-76.11 | 2 1/8 | DISC | SP-212 | | 73.8-76.11 | 7/8 | (R)WC-50035<br>(L)WC-50035 | WK-545 | CUP | 73.8-76.11 | BH-02181 | BH-31380 | 73.8-74.8<br>74.8-76.11 | 5/8<br>5/8 | MC-10044<br>MC-10064 | <br>MK-4300 | 73.8-76.11 | 3/4 | CC-70091 | CK-3108 |

| Models | TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| MARK 2 : 30, 40 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) | TX30 | DX・GL | 77.4-79.3 | 7/8 | | TK-9337 | 77.4-79.3 | 2 1/8 | DISC | SP-212 | | 77.4-79.3 | 7/8 | (R)WC-50035<br>(L)WC-50035 | WK-545 | CUP | 77.4-79.3 | BH-02220 | BH-T822 | 77.4-79.3 | 5/8 | MC-10074 | MK-4300 | 77.4-79.3 | 13/16 | CC-70109 | CK-3113 |
| | TX40 | STD・DX・GL | 77.11-80.8 | 7/8 | | TK-9337 | 77.11-80.8 | 2 1/8 | DISC | SP-212 | | 77.11-80.8 | 7/8 | (R)WC-50035<br>(L)WC-50035 | WK-545 | CUP | 77.11-80.8 | BH-02220 | BH-T822 | 77.11-80.8 | 5/8 | MC-10074 | MK-4300 | 77.11-80.8 | 13/16 | CC-70109 | CK-3113 |
| | TX47V(バン) | STD・DX・GL | 79.12-80.8 | 7/8 | | TK-9337 | 79.12-80.8 | 2 1/8 | DISC | SP-212 | | 79.12-80.8 | 7/8 | (R)WC-50035<br>(L)WC-50035 | WK-545 | CUP | 79.12-80.8 | BH-02220 | BH-02342 | 79.12-80.8 | 5/8 | MC-10074 | MK-4300 | 79.12-80.8 | 13/16 | CC-70109 | CK-3113 |
| (2000) | RX30 | STD・DX・GL | 76.12-78.8 | 7/8 | | TK-9337 | 76.12-78.8 | 2 1/8 | DISC | SP-212 | | 76.12-78.8 | 7/8 | (R)WC-50035<br>(L)WC-50035 | WK-545 | CUP | 76.12-78.8 | BH-02220 | BH-T822 | 76.12-78.8 | 5/8 | MC-10074 | MK-4300 | 76.12-78.8 | 13/16 | CC-70113 | CK-3113 |
| | RX31 | GSL | 76.12-78.8 | 7/8 | | TK-9355 | 76.12-78.8 | 2 1/8 | DISC | SP-212 | | 76.12-78.8 | 1 11/16 | DISC | SP-218 | | 76.12-78.8 | BH-02220 | (R-1)BH-02340<br>(L-1)BH-02340<br>(R-2)BH-02343<br>(L-2)BH-02343 | 76.12-78.8 | 5/8 | MC-10074 | MK-4300 | 76.12-78.8 | 13/16 | CC-70113 | CK-3113 |
| (1800) | RX37V(バン) | STD・DX・GL | 7612-7912 | 7/8 | | TK-9337 | 7612-7912 | 2 1/8 | DISC | SP-212 | | 7612-7912 | 7/8 | (R)WC-50035<br>(L)WC-50035 | WK-545 | CUP | 76.12-79.12 | BH-02220 | BH-02342 | 7612-7912 | 5/8 | MC-10074 | MK-4300 | 76.12-78.8<br>78.8-79.12 | 13/16<br>13/16 | CC-70113<br>CC-70111 | CK-3113<br>CK-3113 |
| (2000) | RX40 | DX・GL | 78.8-80.8 | 7/8 | | TK-9337 | 78.8-80.8 | 2 1/8 | DISC | SP-212 | | 78.8-80.8 | 7/8 | (R)WC-50035<br>(L)WC-50035 | WK-545 | CUP | 78.8-80.8 | BH-02220 | BH-T822 | 78.8-80.8 | 5/8 | MC-10074 | MK-4300 | 78.8-80.8 | 13/16 | CC-70120 | CK-3113 |
| | RX41 | GSL | 78.8-80.8 | 7/8 | | TK-9355 | 78.8-80.8 | 2 1/8 | DISC | SP-212 | | 78.8-80.8 | 1 11/16 | DISC | SP-218 | | 78.8-80.8 | BH-02220 | (R-1)BH-02340<br>(L-1)BH-02340<br>(R-2)BH-02343<br>(L-2)BH-02343 | 78.8-80.8 | 5/8 | MC-10074 | MK-4300 | 78.8-80.8 | 13/16 | CC-70120 | CK-3113 |
| | MX30 | DX・L・LG | 76.12-79.3 | 7/8 | | TK-9337 | 76.12-79.3 | 2 1/8 | DISC | SP-212 | | 76.12-79.3 | 7/8 | (R)WC-50035<br>(L)WC-50035 | WK-545 | CUP | 76.12-79.3 | BH-02220 | BH-T822 | 76.12-79.3 | 5/8 | MC-10074 | MK-4300 | 76.12-77.8<br>77.8-79.3 | 13/16<br>13/16 | CC-70106<br>CC-70112 | CK-3113<br>CK-3113 |
| | MX31 | LGツーリング・グランデ | 76.12-77.7 | 7/8 | | TK-9355 | 76.12-77.7 | 2 1/8 | DISC | SP-212 | | 76.12-77.7 | 1 11/16 | DISC | SP-218 | | 76.12-77.7 | BH-02220 | (R-1)BH-02340<br>(L-1)BH-02340<br>(R-2)BH-02343<br>(L-2)BH-02343 | 76.12-77.7 | 5/8 | MC-10074 | MK-4300 | 76.12-77.7 | 13/16 | CC-70106 | CK-3113 |
| (2600) | MX33 | グランデ | 76.12-78.3 | 7/8 | | TK-9355 | 76.12-78.3 | 2 1/8 | DISC | SP-212 | | 76.12-78.3 | 1 11/16 | DISC | SP-218 | | 76.12-78.3 | BH-02220 | (R-1)BH-02340<br>(L-1)BH-02340<br>(R-2)BH-02343<br>(L-2)BH-02343 | | | (オートマチック) | | | | | |
| (2000) | MX35・45(ワゴン) | L | 76.12-80.8 | 7/8 | | TK-9337 | 76.12-80.8 | 2 1/8 | DISC | SP-212 | | 76.12-80.8 | 7/8 | (R)WC-50035<br>(L)WC-50035 | WK-545 | CUP | 76.12-80.8 | BH-02220 | BH-02342 | 76.12-80.8 | 5/8 | MC-10074 | MK-4300 | 76.12-77.8<br>77.8-80.8 | 13/16<br>13/16 | CC-70106<br>CC-70112 | CK-3113<br>CK-3113 |
| | MX40 | L・LG | 77.7-80.8 | 7/8 | | TK-9337 | 77.7-80.8 | 2 1/8 | DISC | SP-212 | | 77.7-80.8 | 7/8 | (R)WC-50035<br>(L)WC-50035 | WK-545 | CUP | 77.7-80.8 | BH-02220 | BH-T822 | 77.7-80.8 | 5/8 | MC-10074 | MK-4300 | 77.7-77.8<br>77.8-80.8 | 13/16<br>13/16 | CC-70106<br>CC-70112 | CK-3113<br>CK-3113 |
| | MX41 | LGツーリング・グランデ | 77.7-80.8 | 7/8 | | TK-9355 | 77.7-80.8 | 2 1/8 | DISC | SP-212 | | 77.7-80.8 | 1 11/16 | DISC | SP-218 | | 77.7-80.8 | BH-02220 | (R-1)BH-02340<br>(L-1)BH-02340<br>(R-2)BH-02343<br>(L-2)BH-02343 | 77.7-80.8 | 5/8 | MC-10074 | MK-4300 | 77.7-77.8<br>77.8-80.8 | 13/16<br>13/16 | CC-70106<br>CC-70112 | CK-3113<br>CK-3113 |
| (2600) | MX43 | グランデ | 78.3-80.8 | 7/8 | | TK-9355 | 78.3-80.8 | 2 1/8 | DISC | SP-212 | | 78.3-80.8 | 1 11/16 | DISC | SP-218 | | 78.3-80.8 | BH-02220 | (R-1)BH-02340<br>(L-1)BH-02340<br>(R-2)BH-02343<br>(L-2)BH-02343 | | | (オートマチック) | | | | | |
| (2200ディーゼル) | LX40 | DX・GL | 79.9-80.8 | 7/8 | | TK-9337 | 79.9-80.8 | 2 1/8 | DISC | SP-212 | | 79.9-80.8 | 7/8 | (R)WC-50035<br>(L)WC-50035 | WK-545 | CUP | 79.9-80.8 | BH-02220 | BH-T822 | 79.9-80.8 | 5/8 | MC-10072 | MK-4300 | 79.9-80.8 | 7/8 | CC-70124 | CK-3110 |

| Models | TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| MARK 2 : 60 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) | E−TX60 | STD・DX・GL | 80.9−82.8 | 7/8 | | TK−9390 | 80.9−82.8 | 2 1/4 | DISC | SP−229 | CPS−219 | 80.9−82.8 | 7/8 | (R)WC−50035<br>(L)WC−50035 | WK−545 | CUP | 80.9−82.8 | BH−02407 | BH−02394 | 80.9−82.8 | 5/8 | MC−10074 | MK−4300 | 80.9−80.12<br>80.12−82.8 | 13/16<br>13/16 | CC−70110<br>CC−70110 | CK−3113<br>CK−3144 |
| | L−TX67V(バン) | STD・DX・GL | 80.11−84.7 | 7/8 | | TK−9390 | 80.11−84.7 | 2 1/4 | DISC | SP−229 | CPS−219 | 80.11−84.7 | 7/8 | (R)WC−50035<br>(L)WC−50035 | WK−545 | CUP | 80.11−84.7 | BH−02407 | BH−94201 | 80.11−84.7 | 5/8 | MC−10074 | MK−4300 | 8011−8012<br>80.12−84.7 | 13/16<br>13/16 | CC−70110<br>CC−70110 | CK−3113<br>CK−3144 |
| | E−SX60 | STD・DX・GL・GR | 82.8−84.7 | 7/8 | | TK−9390 | 82.8−84.7 | 2 1/4 | DISC | SP−229 | CPS−219 | 82.8−84.7 | 7/8 | (R)WC−50035<br>(L)WC−50035 | WK−545 | CUP | 82.8−84.7 | BH−02407 | BH−02394 | 82.8−84.7 | 5/8 | MC−10118 | MK−4308 | 82.8−84.7<br><LPG車><br>83.2−84.7 | 13/16<br><br>13/16 | CC−70133<br><br>CC−70145 | CK−3144<br><br>CK−3144 |
| (2000) | E−RX60 | GL・GR | 80.9−82.8 | 7/8 | | TK−9390 | 80.9−82.8 | 2 1/4 | DISC | SP−229 | CPS−219 | 80.9−82.8 | 7/8 | (R)WC−50035<br>(L)WC−50035 | WK−545 | CUP | 80.9−82.8 | BH−02407 | BH−02394 | 80.9−82.8 | 5/8 | MC−10072 | MK−4300 | 80.9−80.12<br>80.12−82.8 | 13/16<br>13/16 | CC−70110<br>CC−70110 | CK−3113<br>CK−3144 |
| | E−RX63 | GT | 80.9−82.8 | 7/8 | TD−T746 | TK−9409 | 80.9−82.8 | 2 1/4 | DISC | SP−229 | CPS−219 | 80.9−82.8 | 1 11/16 | DISC | SP−218 | | 80.9−82.8 | BH−02407 | (R−1)BH−02340<br>(L−1)BH−02340<br>(R−2)BH−02343<br>(L−2)BH−02343 | 80.9−82.8 | 5/8 | MC−10072 | MK−4300 | 80.9−80.12<br>80.12−82.8 | 13/16<br>13/16 | CC−70110<br>CC−70110 | CK−3113<br>CK−3144 |
| | E−GX60 | LE・LG | 80.9−82.8 | 7/8 | | TK−9390 | 80.9−82.8 | 2 1/4 | DISC | SP−229 | CPS−219 | 80.9−82.8 | 7/8 | (R)WC−50035<br>(L)WC−50035 | WK−545 | CUP | 80.9−82.8 | BH−02407 | BH−02394 | 80.9−82.8 | 5/8 | MC−10072 | MK−4300 | 80.9−82.8 | 13/16 | CC−70133 | CK−3144 |
| | E−GX61 | LGツーリング<br>グランデ | 80.9−84.7 | 7/8 | TD−T746 | TK−9409 | 80.9−84.7 | 2 1/4 | DISC | SP−229 | CPS−219 | 80.9−84.7 | 1 11/16 | DISC | SP−218 | | 80.9−84.7 | BH−02407 | (R−1)BH−02340<br>(L−1)BH−02340<br>(R−2)BH−02343<br>(L−2)BH−02343 | 80.9−82.8<br>82.8−84.7 | 5/8<br>5/8 | MC−10072<br>MC−10110 | MK−4300<br>MK−4312 | 80.9−84.7 | 13/16 | CC−70133 | CK−3144 |
| | | LE・LG | 82.8−84.7 | 7/8 | TD−T746 | TK−9390 | 82.8−84.7 | 2 1/4 | DISC | SP−229 | CPS−219 | 82.8−84.7 | 7/8 | (R)WC−50035<br>(L)WC−50035 | WK−545 | CUP | 82.8−84.7 | BH−02407 | (R)BH−02340<br>(L)BH−02340 | 82.8−84.7 | 5/8 | MC−10110 | MK−4312 | 82.8−84.7 | 13/16 | CC−70133 | CK−3144 |
| (2000) | E−GX60G(ワゴン) | LE | 80.11−84.7 | 7/8 | | TK−9390 | 80.11−84.7 | 2 1/4 | DISC | SP−229 | CPS−219 | 80.11−84.7 | 7/8 | (R)WC−50035<br>(L)WC−50035 | WK−545 | CUP | 80.11−84.7 | BH−02407 | BH−02221 | 80.11−82.8<br>82.8−84.7 | 5/8<br>5/8 | MC−10072<br>MC−10110 | MK−4300<br>MK−4312 | 80.11−84.7 | 13/16 | CC−70133 | CK−3144 |
| | E−MX60 | DX | 80.11−84.7 | 7/8 | | TK−9390 | 80.11−84.7 | 2 1/4 | DISC | SP−229 | CPS−219 | 80.11−84.7 | 7/8 | (R)WC−50035<br>(L)WC−50035 | WK−545 | CUP | 80.11−84.7 | BH−02407 | BH−02394 | 80.11−84.7 | 5/8 | MC−10074 | MK−4300 | 80.11−84.7 | 13/16 | CC−70133 | CK−3144 |
| | E−MX61 | LGツーリング(ターボ)<br>グランデ(ターボ) | 81.10−84.7 | 7/8 | | TK−9418 | 81.10−84.7 | 2 1/4 | DISC | SP−229 | CPS−219 | 81.10−83.2<br>83.2−84.7 | 1 11/16<br>1 11/16 | DISC<br>DISC | SP−218<br>SP−219 | | 81.10−84.7 | BH−02407 | (R−1)BH−02340<br>(L−1)BH−02340<br>(R−2)BH−02343<br>(L−2)BH−02343 | | | (オートマチック) | | | | | |
| (2800) | E−MX63 | グランデ | 80.9−82.8 | 7/8 | TD−T746 | TK−9409 | 80.9−82.8 | 2 1/4 | DISC | SP−229 | CPS−219 | 80.9−82.8 | 1 11/16 | DISC | SP−218 | | 80.9−82.8 | BH−02407 | (R−1)BH−02340<br>(L−1)BH−02340<br>(R−2)BH−02343<br>(L−2)BH−02343 | | | (オートマチック) | | | | | |
| (2200ディーゼル) | K−LX60<br>N−LX60<br><N−は82. 8〜> | DX・GL | 80.9−84.7 | 7/8 | | TK−9390 | 80.9−84.7 | 2 1/4 | DISC | SP−229 | CPS−219 | 80.9−84.7 | 7/8 | (R)WC−50035<br>(L)WC−50035 | WK−545 | CUP | 80.9−84.7 | BH−02407 | BH−02394 | 80.9−82.8<br>82.8−84.7 | 5/8<br>5/8 | MC−10072<br>MC−10110 | MK−4300<br>MK−4312 | 80.9−84.7 | 7/8 | CC−70134 | CK−3122 |
| | K−LX67V(バン)<br>N−LX67V(バン)<br><N−は82. 8〜> | DX | 80.11−84.7 | 7/8 | | TK−9390 | 80.11−84.7 | 2 1/4 | DISC | SP−229 | CPS−219 | 80.11−84.7 | 7/8 | (R)WC−50035<br>(L)WC−50035 | WK−545 | CUP | 80.11−84.7 | BH−02407 | BH−94201 | 80.11−82.8<br>82.8−84.7 | 5/8<br>5/8 | MC−10072<br>MC−10110 | MK−4300<br>MK−4312 | 80.11−84.7 | 7/8 | CC−70134 | CK−3122 |
| (2400ディーゼル) | N−LX65 | LE(ターボ) | 82.8−84.7 | 7/8 | TD−T749 | TK−9390 | 82.8−84.7 | 2 1/4 | DISC | SP−229 | CPS−219 | 82.8−84.7 | 7/8 | (R)WC−50035<br>(L)WC−50035 | WK−545 | CUP | 82.8−84.7 | BH−02407 | (R)BH−02340<br>(L)BH−02340 | | | (オートマチック) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| MARK 2 : 70 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) | E−SX70 | STD・GL・GR | 84.8−88.8 | 7/8 | | TK−T004 | 84.8−88.8 | 2 1/4 | DISC | SP−229 | CPS−229 | 84.8−84.9 | 7/8 | (R)WC−50035<br>(L)WC−50035 | WK−545 | CUP | 84.8−88.8 | BH−02462 | BH−94015 | 84.8−85.2<br>85.2−88.8 | 5/8<br>5/8 | MC−10110<br>MC−10110 | MK−4312<br>MK−4312 | 84.8−88.8 | 13/16 | CC−70133 | CK−3144 |
| | | | | | | | | | | | | 84.9−88.8 | 7/8 | (R)WC−50070<br>(L)WC−50070 | WK−545 | CUP | | | | | | | | | | | |
| (1800L. P. G) | E−YX70<br>E−YX72 | GL | 84.8−88.8 | 7/8 | | TK−T004 | 84.8−88.8 | 2 1/4 | DISC | SP−229 | CPS−229 | 84.8−84.9 | 7/8 | (R)WC−50035<br>(L)WC−50035 | WK−545 | CUP | 84.8−88.8 | BH−02462 | BH−94015 | 84.8−88.8 | 5/8 | | MK−4312 | 84.8−86.8<br><YX72> | 13/16 | CC−70110 | CK−3144 |
| | | | | | | | | | | | | 84.9−88.8 | 7/8 | (R)WC−50070<br>(L)WC−50070 | WK−545 | CUP | | | | | | | 86.8−88.5<br>88.5−88.8 | 13/16<br>13/16 | CC−70145<br>CC−70145 | CK−3144<br>CK−3144 |
| (2000) | E−GX71 | LS・LG(E. F. I) | 84.8−88.8 | 7/8 | | TK−T004 | 84.8−88.8 | 2 1/4 | DISC | SP−229 | CPS−229 | 84.8−84.9 | 7/8 | (R)WC−50035<br>(L)WC−50035 | WK−545 | CUP | 84.8−88.8 | BH−02462 | (R)BH−95001<br>(L)BH−95001 | 84.8−85.2<br>85.2−88.8 | 5/8<br>5/8 | MC−10110<br>MC−10110 | MK−4312<br>MK−4312 | 84.8−88.8 | 13/16 | CC−70133 | CK−3144 |
| | | | | | | | | | | | | 84.9−88.8 | 7/8 | (R)WC−50070<br>(L)WC−50070 | WK−545 | CUP | | | | | | | | | | | |
| | | グランデ(E. F. I) | 84.8−85.10<br>85.10−88.8 | 7/8<br>15/16 | | TK−T004<br>TK−T003 | 84.8−88.8 | 2 1/4 | DISC | SP−229 | CPS−229 | 84.8−88.8 | 42.8 | DISC | SP−238 | | 84.8−88.8 | BH−02462 | (R−1)BH−95001<br>(L−1)BH−95001<br>(R−2)BH−02343<br>(L−2)BH−02343 | 84.8−85.2<br>85.2−88.8 | 5/8<br>5/8 | MC−10110<br>MC−10110 | MK−4312<br>MK−4312 | 84.8−88.8 | 13/16 | CC−70133 | CK−3144 |
| | | グランデ(ツインカム)<br>GT | 84.8−88.8 | 15/16 | | TK−T003 | 84.8−88.8 | 2 1/4 | DISC | SP−229 | CPS−229 | 84.8−88.8 | 42.8 | DISC | SP−238 | | 84.8−88.8 | BH−02462 | (R−1)BH−95001<br>(L−1)BH−95001<br>(R−2)BH−02343<br>(L−2)BH−02343 | 84.8−88.8<br><GT><br>85.10−88.8 | 5/8<br><br>5/8 | | MK−4337<br><br>MK−4337 | 84.8−88.8 | 13/16 | CC−70133 | CK−3144 |
| | E−MX71 | グランデ(ターボ) | 84.8−85.10 | 15/16 | | TK−T003 | 84.8−85.10 | 2 1/4 | DISC | SP−229 | CPS−229 | 84.8−85.10 | 42.8 | DISC | SP−238 | | 84.8−85.10 | BH−02462 | (R−1)BH−95001<br>(L−1)BH−95001<br>(R−2)BH−02343<br>(L−2)BH−02343 | | | (オートマチック) | | | | | |
| (2400ディーゼル) | N−LX70<br>Q−LX70 | GL | 84.8−88.8 | 7/8 | | TK−T004 | 84.8−88.8 | 2 1/4 | DISC | SP−229 | CPS−229 | 84.8−84.9 | 7/8 | (R)WC−50035<br>(L)WC−50035 | WK−545 | CUP | 84.8−88.8 | BH−02462 | BH−94015 | 84.8−85.2<br>85.2−88.8<br><TAXI> | 5/8<br>5/8 | MC−10110<br>MC−10110 | MK−4312<br>MK−4312 | 84.8−88.8 | 13/16 | CC−70171 | CK−3144 |
| | | | | | | | | | | | | 84.9−88.8 | 7/8 | (R)WC−50070<br>(L)WC−50070 | WK−545 | CUP | | | | 84.8−87.4<br>87.4−88.8 | 5/8<br>5/8 | | MK−4337<br>MK−4312 | | | | |
| | | GL・GR(ターボ) | 84.8−86.8<br>86.8−88.8 | 7/8<br>15/16 | | TK−T004<br>TK−T003 | 84.8−88.8 | 2 1/4 | DISC | SP−229 | CPS−229 | 84.8−84.9 | 7/8 | (R)WC−50035<br>(L)WC−50035 | WK−545 | CUP | 84.8−88.8 | BH−02462 | BH−94015 | 84.8−88.8 | 5/8 | | MK−4337 | 84.8−88.8 | 13/16 | CC−70171 | CK−3144 |
| | | | | | | | | | | | | 84.9−88.8 | 7/8 | (R)WC−50070<br>(L)WC−50070 | WK−545 | CUP | | | | | | | | | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| MARK 2 : 70 ser.(FOR TRAINING CAR) | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) E－SX70Y | <生徒側><br>84.8-88.8<br><教官側><br>84.8-88.8 | 7/8 | TD-T752 | TK-T004 | 84.8-88.8 | 2 1/4 | DISC | SP-229 | CPS-229 | 84.8-84.9<br><br>84.9-88.8 | 7/8<br><br>7/8 | (R)WC-50035<br>(L)WC-50035<br>(R)WC-50070<br>(L)WC-50070 | WK-545<br><br>WK-545 | CUP<br><br>CUP | 84.8-88.8 | BH-02462 | BH-94015 | 84.8-85.2<br>85.2-88.8 | 5/8<br>5/8 | MC-10110<br>MC-10110 | MK-4312<br>MK-4312 | 84.8-88.8 | 13/16 | CC-70133 | CK-3144 |
| (1800L. P. G) E－YX70Y<br>E－YX72Y | <生徒側><br>84.8-88.8<br><教官側><br>84.8-88.8 | 7/8 | TD-T752 | TK-T004 | 84.8-88.8 | 2 1/4 | DISC | SP-229 | CPS-229 | 84.8-84.9<br><br>84.9-88.8 | 7/8<br><br>7/8 | (R)WC-50035<br>(L)WC-50035<br>(R)WC-50070<br>(L)WC-50070 | WK-545<br><br>WK-545 | CUP<br><br>CUP | 84.8-88.8 | BH-02462 | BH-94015 | 84.8-88.8 | 5/8 | | MK-4312 | 84.8-86.8<br><YX72Y><br>86.8-88.5<br>88.5-88.8 | 13/16<br><br>13/16<br>13/16 | CC-70110<br><br>CC-70145<br>CC-70145 | CK-3144<br><br>CK-3144<br>CK-3144 |
| (2400ディーゼル)<br>N－LX70Y<br>Q－LX70Y<br>＜Q－は87. 9～＞ | <生徒側><br>84.8-88.8<br><教官側><br>84.8-88.8 | 7/8 | TD-T752 | TK-T004 | 84.8-88.8 | 2 1/4 | DISC | SP-229 | CPS-229 | 84.8-84.9<br><br>84.9-88.8 | 7/8<br><br>7/8 | (R)WC-50035<br>(L)WC-50035<br>(R)WC-50070<br>(L)WC-50070 | WK-545<br><br>WK-545 | CUP<br><br>CUP | 84.8-88.8 | BH-02462 | BH-94015 | 84.8-85.2<br>85.2-88.8 | 5/8<br>5/8 | MC-10110<br>MC-10110 | MK-4312<br>MK-4312 | 84.8-88.8 | 13/16 | CC-70171 | CK-3144 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| MARK 2 : 70 ser.(VAN, WAGON) | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) | L－YX76V(バン)<br>T－YX76V(バン) | DX・GL | 84.11-93.2 | 7/8 | TD-T270 | TK-T004 | 84.11-93.2 | 2 1/4 | DISC | SP-229 | CPS-229 | 84.11-88.10 | 7/8 | (R)WC-50070<br>(L)WC-50070 | WK-545 | CUP | 84.11-93.2 | BH-02462 | BH-02221 | 84.11-88.10<br>88.10-90.8 | 5/8<br>5/8 | MC-T301 | MK-4312<br>MK-4337 | 84.11-88.10 | 13/16<br>13/16 | CC-70110<br>CC-70110 | CK-3144<br>CK-3144 |
| | | | | | | | | | | | | 88.10-90.1 | 7/8 | (R)WC-50074<br>(L)WC-50074 | WK-545 | CUP | | | | 90.8-93.2 | 5/8 | MC-T400 | MK-T236 | 91.3-93.2 | 13/16 | CC-70110 | CK-T201 |
| | | | | | | | | | | | | ｶｯﾌﾟ2種類有り<br>形状確認要す | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | 90.1-91.5 | 7/8 | (R)WC-50074<br>(L)WC-50074 | WK-545<br>WK-770 | 皿型ｶｯﾌﾟ<br>CUP<br>ﾘﾝｸﾞ型ｶｯﾌﾟ<br>CUP | | | | | | | | | | | |
| | | | | | | | | | | | | 91.5-93.2 | 7/8 | | WK-770 | CUP | | | | | | | | | | | |
| (2000) | E－GX70G(ワゴン) | LG(E. F. I) | 84.11-97.4 | 7/8 | TD-T270 | TK-T004 | 84.11-97.4 | 2 1/4 | DISC | SP-229 | CPS-229 | 84.11-88.10 | 7/8 | (R)WC-50070<br>(L)WC-50070 | WK-545 | CUP | 84.11-97.4 | BH-02462 | BH-02221 | 84.11-85.2<br>85.2-88.10 | 5/8<br>5/8 | MC-10110<br>MC-10110 | MK-4312<br>MK-4312 | 84.11-88.10<br>88.10-91.3 | 13/16<br>13/16 | CC-70133<br>CC-70133 | CK-3144<br>CK-3144 |
| | | | | | | | | | | | | 88.10-90.1 | 7/8 | (R)WC-50074<br>(L)WC-50074 | WK-545 | CUP | | | | 88.10-90.8<br>90.8-93.4 | 5/8<br>5/8 | MC-T302<br>MC-T400 | MK-4337<br>MK-T236 | 91.3-97.4 | 13/16 | | CK-T201 |
| | | | | | | | | | | | | ｶｯﾌﾟ2種類有り<br>形状確認要す | | | | | | | | 93.4-94.3<br>94.3-97.4 | 5/8<br>5/8 | | MK-T244 | | | | |
| | | | | | | | | | | | | 90.1-91.5 | 7/8 | (R)WC-50074<br>(L)WC-50074 | WK-545<br>WK-770 | 皿型ｶｯﾌﾟ<br>CUP<br>ﾘﾝｸﾞ型ｶｯﾌﾟ<br>CUP | | | | | | | | | | | |
| | | | | | | | | | | | | 91.5-97.4 | 7/8 | | WK-770 | CUP | | | | | | | | | | | |
| (2000) | T－YX78V(バン)<br>＜GA－は95. 9～＞ | | 93.2-97.4 | 7/8 | | TK-T004 | 93.2-97.4 | 2 1/4 | DISC | SP-229 | CPS-229 | 93.2-97.4 | 7/8 | | WK-770 | CUP | 93.2-97.4 | BH-02462 | BH-02221 | 93.2-93.4<br>93.4-94.3<br>94.3-97.4 | 5/8<br>5/8<br>5/8 | MC-T400 | MK-T236<br>MK-T244 | 93.2-97.4 | 13/16 | CC-T317 | CK-T201 |
| (2400ディーゼル) | N－LX76V(バン)<br>＜S－は88. 12～＞ | DX | 84.11-88.11<br>88.12-94.9 | 7/8<br>15/16 | TD-T270 | TK-T004<br>TK-T003 | 84.11-94.9 | 2 1/4 | DISC | SP-229 | CPS-229 | 84.11-88.10 | 7/8 | (R)WC-50070<br>(L)WC-50070 | WK-545 | CUP | 84.11-94.9 | BH-02462 | BH-02221 | 84.11-85.2<br>85.2-88.10 | 5/8<br>5/8 | MC-10110<br>MC-10110 | MK-4312<br>MK-4312 | 84.11-88.10<br>88.10-91.3 | 13/16<br>13/16 | CC-70171<br>CC-70171 | CK-3144<br>CK-3144 |
| | | | | | | | | | | | | 88.10-90.1 | 7/8 | (R)WC-50074<br>(L)WC-50074 | WK-545 | CUP | | | | 88.10-90.8<br>90.8-93.4 | 5/8<br>5/8 | MC-T302<br>MC-T400 | MK-4337<br>MK-T236 | 91.3-94.9 | 13/16 | CC-70171 | CK-T201 |
| | | | | | | | | | | | | ｶｯﾌﾟ2種類有り<br>形状確認要す | | | | | | | | 93.4-94.3<br>94.3-94.9 | 5/8<br>5/8 | | MK-T244 | | | | |
| | | | | | | | | | | | | 90.1-91.5 | 7/8 | (R)WC-50074<br>(L)WC-50074 | WK-545<br>WK-770 | 皿型ｶｯﾌﾟ<br>CUP<br>ﾘﾝｸﾞ型ｶｯﾌﾟ<br>CUP | | | | | | | | | | | |
| | | | | | | | | | | | | 91.5-94.9 | 7/8 | | WK-770 | CUP | | | | | | | | | | | |

| Models | TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| MARK 2 : 80 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) | E−SX80 | STD<br>GL・GR | 88.8-95.12 | 15/16 | | TK-T325 | 88.8-95.12 | 60.6 | DISC | SP-251 | CPS-249 | 88.8-90.1<br>カップ2種類有り<br>形状確認要す<br>90.1-91.5<br><br><br>91.5-95.12 | 7/8<br><br><br>7/8<br><br>7/8<br><br>7/8 | (R)WC-50074<br>(L)WC-50074<br><br>(R)WC-50074<br>(L)WC-50074<br>(R)WC-50074<br>(L)WC-50074<br>(R)WC-T650<br>(L)WC-T650 | WK-545<br><br><br>WK-545<br><br>WK-770<br><br>WK-770 | CUP<br><br>皿型ｶｯﾌﾟ<br>CUP<br>ﾘﾝｸﾞ型ｶｯﾌﾟ<br>CUP<br><br>CUP | 88.8-95.12 | BH-T821 | BH-T822 | 88.8-93.4<br>93.4-94.3<br>94.3-95.12 | 5/8<br>5/8<br>5/8 | MC-T400<br>MC-T400 | MK-T236 | 88.8-91.3<br>91.3-95.12 | 13/16<br>13/16 | CC-70133 | CK-3144<br>CK-T201 |
| (2000) | E−GX81 | LG<br>1G−FEエンジン車 | 88.8-93.2 | 15/16 | | TK-T325 | 88.8-93.2 | 60.6 | DISC | SP-251 | CPS-249 | 88.8-93.2 | 40.4 | DISC | SP-247 | | 88.8-93.2 | BH-T821 | (R)BH-02568<br>(L)BH-02568 | 88.8-93.2 | 5/8 | MC-T400 | MK-T236 | 88.8-91.3<br>91.3-93.2 | 13/16<br>13/16 | CC-70133 | CK-3144<br>CK-T201 |
| | | グランデ<br>1G−FEエンジン車<br>1G−GEエンジン車 | 88.8-95.12<br><ｱﾝﾁｽｷｯﾄﾞ付><br>88.8-89.8<br>89.8-95.12 | 1<br><br>1<br>1 | | TK-T042<br><br>TK-T046<br>TK-T301 | 88.8-95.12 | 60.6 | DISC | SP-251 | CPS-249 | <1GFEｴﾝｼﾞﾝ車><br>88.8-95.12<br><1GGEｴﾝｼﾞﾝ車><br>88.8-93.2 | 40.4<br><br>42.8 | DISC<br><br>DISC | SP-247<br><br>SP-262 | | 88.8-95.12 | BH-T821 | (R)BH-02568<br>(L)BH-02568 | 88.8-93.2<br><br>93.2-95.12 | 5/8 | MC-T400<br><br>(ｵｰﾄﾏﾁｯｸ) | MK-T236 | 88.8-91.3<br>91.3-93.2 | 13/16<br>13/16 | CC-70133 | CK-3144<br>CK-T201 |
| | | グランデG<br>1G−GZEエンジン車 | 88.8-89.8<br><ﾄﾗｸｼｮﾝｺﾝﾄﾛｰﾙ付><br>89.8-90.8<br><ﾄﾗｸｼｮﾝｺﾝﾄﾛｰﾙ無><br>89.8-90.8 | 1<br><br>1<br><br>1 | | TK-T046<br><br>TK-T301<br><br>TK-T042 | 88.8-90.8 | 60.6 | DISC | SP-251 | CPS-249 | 88.8-90.8 | 42.8 | DISC | SP-262 | | 89.8-90.8 | BH-T821 | (R)BH-02568<br>(L)BH-02568 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | | GT<br>1G−GTEエンジン車 | 88.8-90.8<br><ｱﾝﾁｽｷｯﾄﾞ付><br>88.8-89.8<br>89.8-90.8 | 1<br><br>1<br>1 | | TK-T042<br><br>TK-T046<br>TK-T301 | 88.8-90.8 | 60.6 | DISC | SP-251 | CPS-249 | 88.8-90.8 | 42.8 | DISC | SP-262 | | 88.8-90.8 | BH-T821 | (R)BH-02568<br>(L)BH-02568 | 88.8-90.8 | 5/8 | | MK-4337 | 88.8-90.8 | 13/16 | | CK-3144 |
| (2500) | E−JZX81 | グランデ | 90.8-93.2<br><ｱﾝﾁｽｷｯﾄﾞ付><br>90.8-93.2 | 1<br><br>1 1/16 | | TK-T042<br><br>TK-T326 | 90.8-93.2 | 60.6 | DISC | SP-251 | CPS-249 | 90.8-93.2 | 42.8 | DISC | SP-262 | | 90.8-93.2 | BH-T821 | (R)BH-02568<br>(L)BH-02568 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | | グランデG | 90.8-93.2 | 1 1/16 | | TK-T326 | 90.8-93.2 | 60.6 | DISC | SP-251 | CPS-249 | 90.8-93.2 | 42.8 | DISC | SP-262 | | 90.8-93.2 | BH-T821 | (R)BH-02568<br>(L)BH-02568 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | | GT(ターボ) | 90.8-92.10 | 1 1/16 | | TK-T326 | 90.8-92.10 | 60.6 | DISC | SP-264 | CPS-249 | 90.8-92.10 | 42.8 | DISC | SP-262 | | 90.8-92.10 | BH-T821 | (R)BH-02568<br>(L)BH-02568 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (3000) | E−MX83 | グランデG | 89.8-90.8<br>90.8-93.2 | 1<br>1 1/16 | | TK-T301<br>TK-T326 | 89.8-93.2 | 60.6 | DISC | SP-251 | CPS-249 | 89.8-93.2 | 42.8 | DISC | SP-262 | | 89.8-93.2 | BH-T821 | (R)BH-02568<br>(L)BH-02568 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (2000L. P. G) | E−YX80 | GL | 88.8-95.12 | 15/16 | | TK-T325 | 88.8-95.12 | 60.6 | DISC | SP-251 | CPS-249 | 88.8-90.1<br>カップ2種類有り<br>形状確認要す<br>90.1-91.5<br><br><br>91.5-95.12 | 7/8<br><br><br>7/8<br><br>7/8<br><br>7/8 | (R)WC-50074<br>(L)WC-50074<br><br>(R)WC-50074<br>(L)WC-50074<br>(R)WC-50074<br>(L)WC-50074<br>(R)WC-T650<br>(L)WC-T650 | WK-545<br><br><br>WK-545<br><br>WK-770<br><br>WK-770 | CUP<br><br>皿型ｶｯﾌﾟ<br>CUP<br>ﾘﾝｸﾞ型ｶｯﾌﾟ<br>CUP<br><br>CUP | 88.8-95.12 | BH-T821 | BH-T822 | 88.8-93.4<br>93.4-94.3<br>94.3-95.12 | 5/8<br>5/8<br>5/8 | MC-T400<br>MC-T400 | MK-T236 | 88.8-91.3<br>91.3-95.12 | 13/16<br>13/16 | CC-70145<br>CC-T317 | CK-3144<br>CK-T201 |
| (2400ディーゼル) | Q−LX80 | GL・GR | 88.8-93.8 | 15/16 | | TK-T325 | 88.8-93.8 | 60.6 | DISC | SP-251 | CPS-249 | 88.8-90.1<br>ｶｯﾌﾟ2種類有り<br>形状確認要す<br>90.1-91.5<br><br><br>91.5-93.8 | 7/8<br><br><br>7/8<br><br>7/8<br><br>7/8 | (R)WC-50074<br>(L)WC-50074<br><br>(R)WC-50074<br>(L)WC-50074<br>(R)WC-50074<br>(L)WC-50074<br>(R)WC-T650<br>(L)WC-T650 | WK-545<br><br><br>WK-545<br><br>WK-770<br><br>WK-770 | CUP<br><br>皿型ｶｯﾌﾟ<br>CUP<br>ﾘﾝｸﾞ型ｶｯﾌﾟ<br>CUP<br><br>CUP | 88.8-93.8 | BH-T821 | BH-T822 | 88.8-93.4<br>93.4-93.8 | 5/8<br>5/8 | MC-T400<br>MC-T400 | MK-T236 | 88.8-91.3<br>91.3-93.8 | 13/16<br>13/16 | CC-70171<br>CC-70171 | CK-3144<br>CK-T201 |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| MARK 2 : 80 ser.(FOR TRAINING CAR) | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) E－SX80Y | <生徒側><br>88.8-95.12<br><教官側><br>88.8-95.12 | 15/16 | | TK-T325 | 88.8-95.12 | 60.6 | DISC | SP-251 | CPS-249 | 88.8-90.1<br>カップ2種類有り<br>形状確認要す<br>90.1-91.5<br>91.5-95.12 | 7/8<br><br><br>7/8<br>7/8 | (R)WC-50074<br>(L)WC-50074<br><br>(R)WC-50074<br>(L)WC-50074 | WK-545<br><br><br>WK-545<br><br>WK-770<br>WK-770 | CUP<br><br><br>皿型カップ<br>CUP<br>リング型カップ<br>CUP<br>CUP | 88.8-95.12 | BH-T821 | BH-T822 | 88.8-93.4<br>93.4-94.3<br>94.3-95.12 | 5/8<br>5/8<br>5/8 | MC-T400<br>MC-T400 | MK-T236 | 88.8-91.3<br>91.3-95.12 | 13/16<br>13/16 | CC-70133<br>CC-T317 | CK-3144<br>CK-T201 |
| (2000L. P. G) E－YX80Y | <生徒側><br>88.8-95.12<br><教官側><br>88.8-95.12 | 15/16<br><br>7/8 | | TK-T325 | 88.8-95.12 | 60.6 | DISC | SP-251 | CPS-249 | 88.8-90.1<br>カップ2種類有り<br>形状確認要す<br>90.1-91.5<br>91.5-95.12 | 7/8<br><br><br>7/8<br>7/8 | (R)WC-50074<br>(L)WC-50074<br><br>(R)WC-50074<br>(L)WC-50074 | WK-545<br><br><br>WK-545<br><br>WK-770<br>WK-770 | CUP<br><br><br>皿型カップ<br>CUP<br>リング型カップ<br>CUP<br>CUP | 88.8-95.12 | BH-T821 | BH-T822 | 88.8-93.4<br>93.4-94.3<br>94.3-95.12 | 5/8<br>5/8<br>5/8 | MC-T400<br>MC-T400 | MK-T236 | 88.8-91.3<br>91.3-95.12 | 13/16<br>13/16 | CC-70133<br>CC-T317 | CK-3144<br>CK-T201 |
| (2400ディーゼル)<br>Q－LX80Y | <生徒側><br>88.8-93.2<br><教官側><br>88.8-93.2 | 15/16 | | TK-T325 | 88.8-93.2 | 60.6 | DISC | SP-251 | CPS-249 | 88.8-90.1<br>カップ2種類有り<br>形状確認要す<br>90.1-91.5<br>91.5-93.2 | 7/8<br><br><br>7/8<br>7/8 | (R)WC-50074<br>(L)WC-50074<br><br>(R)WC-50074<br>(L)WC-50074 | WK-545<br><br><br>WK-545<br><br>WK-770<br>WK-770 | CUP<br><br><br>皿型カップ<br>CUP<br>リング型カップ<br>CUP<br>CUP | 88.8-93.2 | BH-T821 | BH-T822 | 88.8-93.2 | 5/8 | MC-T400 | MK-T236 | 88.8-91.3<br>91.3-93.2 | 13/16<br>13/16 | CC-70171<br>CC-70171 | CK-3144<br>CK-T201 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| MARK 2 : 90 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) | E−SX90 | | 92.10-96.9<br><ｱﾝﾁｽｷｯﾄﾞ付><br>92.10-94.7<br>94.7-96.9 | 15/16<br><br>1<br>1 | | TK-T348<br><br>TK-T366<br>TK-T366 | 92.10-96.9 | | DISC | SP-255 | CPS-255 | 92.10-96.9 | | DISC | SP-263 | CPS-263 | 92.10-96.9 | BH-T595 | (R)BH-T594<br>(L)BH-T594 | 92.10-94.3<br>94.3-96.9 | 5/8<br>5/8 | MC-T402<br>MC-T402 | MK-T244 | 92.10-96.9 | 13/16 | | CK-T201 |
| (2000) | E−GX90 | | 92.10-96.9<br><ｱﾝﾁｽｷｯﾄﾞ付><br>92.10-94.7<br>94.7-96.9 | 15/16<br><br>1<br>1 | | TK-T348<br><br>TK-T366<br>TK-T366 | 92.10-96.9 | | DISC | SP-255 | CPS-255 | 92.10-96.9 | | DISC | SP-263 | CPS-263 | 92.10-96.9 | BH-T595 | (R)BH-T594<br>(L)BH-T594 | 92.10-94.3<br>94.3-96.9 | 5/8<br>5/8 | MC-T402<br>MC-T402 | MK-T244 | 92.10-96.9 | 13/16 | | CK-T201 |
| (2400ディーゼル) | Y−LX90<br><KD−は95．9～> | | 92.10-96.9<br><ｱﾝﾁｽｷｯﾄﾞ付><br>92.10-94.9<br>94.9-96.9 | 15/16<br><br>1<br>1 | | TK-T348<br><br>TK-T301<br>TK-T366 | 92.10-96.9 | | DISC | SP-255 | CPS-255 | 92.10-96.9 | | DISC | SP-263 | CPS-263 | 92.10-96.9 | BH-T595 | (R)BH-T594<br>(L)BH-T594 | 92.10-94.3<br>94.3-96.9 | 5/8<br>5/8 | MC-T403<br>MC-T403 | MK-T244 | 92.10-96.9 | 13/16 | CC-70171 | CK-T201 |
| (2500) | E−JZX90･93 | ターボ車 | 92.10-96.9 | 1 1/16 | | TK-T332 | 92.10-96.9 | 44.4 | DISC | MP-47 | | 92.10-96.9 | | DISC | SP-256 | | 92.10-96.9 | BH-T595 | (R)BH-T594<br>(L)BH-T594 | 92.10-94.3<br>94.3-96.9 | 5/8<br>5/8 | MC-T401<br>MC-T401 | MK-T244 | 92.10-95.12<br>95.12-96.9 | 7/8<br>7/8 | | CK-3143<br>CK-T223 |
| | | ターボ無 | 92.10-96.9<br><ｱﾝﾁｽｷｯﾄﾞ付><br>92.10-94.7<br>94.7-96.9 | 15/16<br><br>1<br>1 | | TK-T348<br><br>TK-T366<br>TK-T366 | 92.10-96.9 | 57.2 | DISC | MP-50 | CPM-68 | 92.10-95.9<br>95.9-96.9 | | DISC<br>DISC | SP-263<br>MP-67 | CPS-263 | 92.10-96.9<br><br><JZX93><br>93.10-96.9 | BH-T595 | (R)BH-T594<br>(L)BH-T594<br><br>(R)BH-T594<br>(L)BH-T594 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (3000) | E−JZX91 | | 92.10-94.7<br>94.7-96.9 | 1<br>1 | | TK-T366<br>TK-T366 | 92.10-96.9 | 57.2 | DISC | MP-50 | CPM-68 | 92.10-95.9<br>95.9-96.9 | | DISC<br>DISC | SP-263<br>MP-67 | CPS-263 | 92.10-96.9 | BH-T595 | (R)BH-T594<br>(L)BH-T594 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| MARK 2 : 100 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000) | E－GX100<br>＜GF－は98．8～＞ | | 96.9-00.10 | 1 | | TK-T412 | 96.9-98.8<br>98.8-00.10 | | DISC<br>DISC | SP-204<br>SP-102 | CPS-204<br>CPS-102 | 96.9-00.10 | | DISC | SP-295 | CPS-295 | 96.9-00.10 | BH-T595 | (R)BH-T594<br>(L)BH-T594 | 96.9-00.10 | 5/8 | | MK-T244 | 96.9-00.10 | 13/16 | | CK-T201 |
| | GF－GX105（4WD） | | 98.8-00.10 | 1 | | TK-T412 | 98.8-00.10 | | DISC | MP-72 | CPM-121 | 98.8-00.10 | | DISC | MP-73 | | 98.8-00.10 | BH-T691 | (R)BH-T594<br>(L)BH-T594 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (2400ディーゼル) | KD－LX100 | | 96.9-00.10 | 1 | | TK-T377 | 96.9-98.8<br>98.8-00.10 | | DISC<br>DISC | SP-204<br>SP-102 | CPS-204<br>CPS-102 | 96.9-00.10 | | DISC | SP-295 | CPS-295 | 96.9-00.10 | BH-T595 | (R)BH-T594<br>(L)BH-T594 | | | (ｵｰﾄﾏﾁｯｸ) | | | | |
| (2500) | E－JZX100<br>＜GF－は98．8～＞ | ターボ無 | 96.9-00.10<br><VSC付><br>98.8-00.10 | 1<br><br>1 | | TK-T412<br><br>TK-T431 | 96.9-00.10 | | DISC | MP-72 | CPM-121 | 96.9-00.10 | | DISC | MP-73 | | 96.9-00.10 | BH-T595 | (R)BH-T594<br>(L)BH-T594 | | | (ｵｰﾄﾏﾁｯｸ) | | | | |
| | | ターボ車 | 96.9-00.10 | 1 | | TK-T412 | 96.9-00.10 | 44.4 | DISC | MP-47 | CPM-77 | 96.9-00.10 | | DISC | SP-293 | CPS-293 | 96.9-00.10 | BH-T595 | (R)BH-T594<br>(L)BH-T594 | 96.9-00.10 | 5/8 | | MK-T244 | 96.9-00.10 | 7/8 | | CK-T223 |
| | E－JZX105（4WD）<br>＜GF－は98．8～＞ | | 96.9-00.10 | 1 | | TK-T412 | 96.9-00.10 | | DISC | MP-72 | CPM-121 | 96.9-00.10 | | DISC | MP-73 | | 96.9-00.10 | BH-T691 | (R)BH-T594<br>(L)BH-T594 | | | (ｵｰﾄﾏﾁｯｸ) | | | | |
| (3000) | E－JZX101<br>＜GF－は98．8～＞ | | 96.9-98.8<br>98.8-00.10 | <br>1 | | <br>TK-T431 | 96.9-00.10 | | DISC | MP-72 | CPM-121 | 96.9-00.10 | | DISC | MP-73 | | 96.9-98.8<br><br>98.8-00.10 | BH-T595<br><br>BH-T595 | (R)<br>(L)<br>(R)BH-T594<br>(L)BH-T594 | | | (ｵｰﾄﾏﾁｯｸ) | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| MARK 2 : 110 ser.(00.10-) | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000) | TA－GX110 | | 00.10- | | | | 00.10- | | DISC | MP-121 | CPM-112 | 00.10- | | DISC | MP-79 | CPM-79 | 00.10- | BH-T830 | (R)BH-T864<br>(L)BH-T864 | | | (オートマチック) | | | | | |
| | TA－GX115(4WD) | | 00.10- | | | | 00.10- | | DISC | MP-121 | CPM-121 | 00.10- | | DISC | MP-79 | CPM-79 | 00.10- | BH-T691 | (R)BH-T864<br>(L)BH-T864 | | | (オートマチック) | | | | | |
| (2500) | TA－JZX110 | ターボ無 | 00.10-<br><VSC付><br>00.10- | | | | 00.10- | | DISC | MP-121 | CPM-112 | 00.10- | | DISC | MP-79 | CPM-79 | 00.10- | BH-T830 | (R)BH-T864<br>(L)BH-T864 | | | (オートマチック) | | | | | |
| | GH－JZX110 | ターボ車 | 00.10-<br><VSC付><br>00.10- | | | | 00.10- | | DISC | MP-77 | CPM-77 | 00.10- | | DISC | MP-79 | CPM-79 | 00.10- | BH-T830 | (R)BH-T864<br>(L)BH-T864 | 00.10- | 5/8 | | MK-T244 | 00.10- | 7/8 | | CK-T223 |
| | TA－JZX115(4WD) | | 00.10- | | | | 00.10- | | DISC | MP-121 | CPM-121 | 00.10- | | DISC | MP-79 | CPM-79 | 00.10- | BH-T691 | (R)BH-T864<br>(L)BH-T864 | | | (オートマチック) | | | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| MARK 2 WAGON QUALIS : 20 ser. | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2200) E－SXV20W<br>＜GF－は98．8～＞ | 97.4-01.12 | 1 | | TK-T370 | 97.4-01.12 | 57.2 | DISC | MP-50 | CPM-68 | 97.4-99.8<br>99.8-01.12 | 34.9 | DISC<br>DISC | MP-82<br>MP-98 | CPM-98 | 97.4-01.12 | (R)BH-T702<br>(L)BH-T703 | (R)BH-T739<br>(L)BH-T704 | | | (オートマチック) | | | | | |
| E－SXV25W(4WD)<br>＜GF－は98．8～＞ | 97.6-01.12 | 1 | | TK-T370 | 97.6-01.12 | | DISC | A-678P | CPA-678 | 97.6-01.12 | 34.9 | DISC | MP-82 | | 97.6-01.12 | (R)BH-T702<br>(L)BH-T703 | (R)BH-T707<br>(L)BH-T706 | | | (オートマチック) | | | | | |
| (2500) E－MCV21W<br>＜GF－は98．8～＞ | 97.4-01.12<br><トラクションコントロール付><br>97.4-99.8<br>99.8-01.12 | 1<br><br>1 | | TK-T370<br><br>TK-T414 | 97.4-01.12 | | DISC | A-678P | CPA-678 | 97.4-99.8<br>99.8-01.12 | 34.9 | DISC<br>DISC | MP-82<br>MP-98 | CPM-98 | 97.4-01.12 | (R)BH-T702<br>(L)BH-T703 | (R)BH-T739<br>(L)BH-T704 | | | (オートマチック) | | | | | |
| E－MCV25W(4WD)<br>＜GF－は98．8～＞ | 97.6-01.12 | 1 | | TK-T370 | 97.6-01.12 | | DISC | A-678P | CPA-678 | 97.6-01.12 | 34.9 | DISC | MP-82 | | 97.6-01.12 | (R)BH-T702<br>(L)BH-T703 | (R)BH-T707<br>(L)BH-T706 | | | (オートマチック) | | | | | |
| (3000) E－MCV20W<br>＜GF－は98．8～＞<br>＜GH－は99．8～＞<br>＜TA－は00．8～＞ | 97.4-99.8<br>99.8-01.12 | 1 | | TK-T414 | 97.4-01.12 | | DISC | A-678P | CPA-678 | 97.4-99.8<br>99.8-01.12 | 34.9 | DISC<br>DISC | MP-82<br>MP-98 | CPM-98 | 97.4-01.12 | (R)BH-T702<br>(L)BH-T703 | (R)BH-T739<br>(L)BH-T704 | | | (オートマチック) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| MARK 2 WAGON BLIT : 110 ser.(02.1-) | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000) | TA-GX110W | | 02.1- | | | | 02.1- | | DISC | MP-121 | CPM-112 | 02.1- | | DISC | MP-79 | CPM-79 | 02.1- | BH-T830 | (R)BH-T864<br>(L)BH-T864 | | | (オートマチック) | | | | | |
| | TA-GX115W(4WD) | | 02.1- | | | | 02.1- | | DISC | MP-121 | CPM-121 | 02.1- | | DISC | MP-79 | CPM-79 | 02.1- | BH-T691 | (R)BH-T864<br>(L)BH-T864 | | | (オートマチック) | | | | | |
| (2500) | TA-JZX110W | ターボ無 | 02.1-<br><VSC付><br>02.1- | | | | 02.1- | | DISC | MP-121 | CPM-112 | 02.1- | | DISC | MP-79 | CPM-79 | 02.1- | BH-T830 | (R)BH-T864<br>(L)BH-T864 | | | (オートマチック) | | | | | |
| | GH-JZX110W | ターボ車 | 02.1-<br><VSC付><br>02.1- | | | | 02.1- | | DISC | MP-77 | CPM-77 | 02.1- | | DISC | MP-79 | CPM-79 | 02.1- | BH-T830 | (R)BH-T864<br>(L)BH-T864 | | | (オートマチック) | | | | | |
| | TA-JZX115W(4WD) | | 02.1- | | | | 02.1- | | DISC | MP-121 | CPM-121 | 02.1- | | DISC | MP-79 | CPM-79 | 02.1- | BH-T691 | (R)BH-T864<br>(L)BH-T864 | | | (オートマチック) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| MARK X : 120, 130 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2500) | DBA－GRX120 | | 04.11-09.9 | | | | 04.11-09.9<br><SﾊﾟｯｹｰｼﾞVSC付225/45R18ﾀｲﾔ><br>04.11-09.9 | | DISC<br><br>DISC | MP-112<br><br>MP-112 | | 04.11-05.11<br>05.11-09.9<br><SﾊﾟｯｹｰｼﾞVSC付225/45R18ﾀｲﾔ><br>04.11-05.11<br>05.11-09.9 | | DISC<br>DISC<br><br>DISC<br>DISC | SP-417<br>MP-113<br><br>SP-418<br>MP-117 | CPM-113<br>CPM-113<br><br>CPM-117<br>CPM-117 | 04.11-07.1<br><br>07.1-09.9 | (R)<br>(L)<br>(R)<br>(L) | (R)<br>(L)<br>(R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | |
| | DBA－GRX130 | | 09.10- | 7/8 | TD-T931 | | 09.10-<br><br><G's仕様><br>12.10- | | DISC<br><br><br>DISC | MP-112<br><br><br>SP-112 | | 09.10-14.6<br>14.6-<br><G's仕様><br>12.10-14.8<br>14.8- | | DISC<br>DISC<br><br>DISC<br>DISC | MP-113<br>SP-462<br><br>SP-412 | CPM-113<br>CPM-113<br><br>CPS-412<br>CPS-412 | 09.10-12.12<br><br>12.12- | (R)<br>(L)<br>(R)<br>(L) | (R)<br>(L)<br>(R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | |
| | DBA－GRX125 | 4WD | 04.11-09.9 | | | | 04.11-09.9 | | DISC | MP-112 | | 04.11-05.11<br>05.11-09.9 | | DISC<br>DISC | SP-417<br>MP-113 | CPM-113<br>CPM-113 | 04.11-07.1<br><br>07.1-09.9 | (R)<br>(L)<br>(R)<br>(L) | (R)<br>(L)<br>(R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | |
| | DBA－GRX135 | 4WD | 09.10- | 7/8 | TD-T931 | | 09.10-11.12<br>11.12- | | DISC<br>DISC | MP-112<br>MP-112 | | 09.10-11.4<br>11.4- | | DISC<br>DISC | MP-113 | CPM-113 | 09.10-12.12<br><br>12.12- | (R)<br>(L)<br>(R)<br>(L) | (R)<br>(L)<br>(R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | |
| (3000) | DBA－GRX121 | | 04.11-09.9 | | | | 04.11-09.9<br><300Gﾊﾟｯｹｰｼﾞ225/45R18ﾀｲﾔ><br>04.11-09.9 | | DISC<br><br>DISC | MP-112<br><br>MP-112 | | 04.11-05.11<br>05.11-09.9<br><300Gﾊﾟｯｹｰｼﾞ225/45R18ﾀｲﾔ><br>04.11-05.11<br>05.11-09.9 | | DISC<br>DISC<br><br>DISC<br>DISC | SP-417<br>MP-113<br><br>SP-418<br>MP-117 | CPM-113<br>CPM-113<br><br>CPM-117<br>CPM-117 | 04.11-07.1<br><br>07.1-09.9 | (R)<br>(L)<br>(R)<br>(L) | (R)<br>(L)<br>(R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | |
| (3500) | DBA－GRX133 | | 09.10- | 7/8 | TD-T931 | | 09.10-<br><br><G's仕様><br>12.10-<br><特設ﾊﾟｯｹｰｼﾞGRMN><br>15.5-15.10 | | DISC<br><br><br>DISC<br><br>DISC | SP-112<br><br><br>SP-112<br><br>SP-112 | CPS-112<br><br><br><br><br>CPS-112 | 09.10-13.9<br>13.9-<br><br><G's仕様><br>12.10-14.8<br>14.8-<br><特設ﾊﾟｯｹｰｼﾞGRMN><br>15.5-15.10 | | DISC<br>DISC<br><br><br>DISC<br>DISC<br><br>DISC | SP-412<br><br><br><br>SP-412 | CPS-412<br>CPS-412<br><br><br>CPS-412<br>CPS-412<br><br>CPS-412 | 09.10-12.12<br><br>12.12- | (R)<br>(L)<br>(R)<br>(L) | (R)<br>(L)<br>(R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| MARK X ZIO : 10 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2400) | DBA－ANA10 | | 07.9-12.5<br>12.5- | | | | 07.9-11.7<br>11.8- | | DISC<br>DISC | MP-114 | CPM-106 | 07.9-11.7<br>11.7- | | DISC<br>DISC | SP-134<br>SP-422 | CPS-134<br>CPS-134 | 07.9- | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| | DBA－ANA15 | 4WD | 07.9-12.5<br>12.5- | | | | 07.9-11.7<br>11.8- | | DISC<br>DISC | MP-114 | CPM-106 | 07.9-11.7<br>11.7- | | DISC<br>DISC | SP-134<br>SP-422 | CPS-134<br>CPS-134 | 07.9- | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| (3500) | DBA－GGA10 | | 07.9-12.5<br>12.5- | | | | 07.9-11.7<br>11.8- | | DISC<br>DISC | MP-114 | CPM-106 | 07.9-11.7<br>11.7- | | DISC<br>DISC | SP-134<br>SP-422 | CPS-134<br>CPS-134 | 07.9- | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |

| Models | TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CHASER : 30, 40 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) | TX30・40 | DX・XL | 77.7-80.8 | 7/8 | | TK-9337 | 77.7-77.11<br>77.11-80.8 | 2 1/8<br>2 1/8 | DISC<br>DISC | SP-212<br>SP-212 | | 77.7-80.8 | 7/8 | (R)WC-50035<br>(L)WC-50035 | WK-545 | CUP | 77.7-80.8 | BH-02220 | BH-T822 | 77.7-80.8 | 5/8 | MC-10074 | MK-4300 | 77.7-80.8 | 13/16 | CC-70109 | CK-3113 |
| (2000) | RX30・40 | DX・XL | 77.7-80.8 | 7/8 | | TK-9337 | 77.7-77.11<br>77.11-80.8 | 2 1/8<br>2 1/8 | DISC<br>DISC | SP-212<br>SP-212 | | 77.7-80.8 | 7/8 | (R)WC-50035<br>(L)WC-50035 | WK-545 | CUP | 77.7-80.8 | BH-02220 | BH-T822 | 77.7-80.8 | 5/8 | MC-10074 | MK-4300 | 77.7-78.8<br>78.8-80.8 | 13/16<br>13/16 | CC-70113<br>CC-70120 | CK-3113<br>CK-3113 |
| | RX31・41 | GS | 77.7-80.8 | 7/8 | | TK-9355 | 77.7-77.11<br>77.11-80.8 | 2 1/8<br>2 1/8 | DISC<br>DISC | SP-212<br>SP-212 | | 77.7-80.8 | 1 11/16 | DISC | SP-218 | | 77.7-80.8 | BH-02220 | (R-1)BH-02340<br>(L-1)BH-02340<br>(R-2)BH-02343<br>(L-2)BH-02343 | 77.7-80.8 | 5/8 | MC-10074 | MK-4300 | 77.7-78.8<br>78.8-80.8 | 13/16<br>13/16 | CC-70113<br>CC-70120 | CK-3113<br>CK-3113 |
| | MX30・40 | SXL | 77.7-80.8 | 7/8 | | TK-9337 | 77.7-77.11<br>77.11-80.8 | 2 1/8<br>2 1/8 | DISC<br>DISC | SP-212<br>SP-212 | | 77.7-80.8 | 7/8 | (R)WC-50035<br>(L)WC-50035 | WK-545 | CUP | 77.7-80.8 | BH-02220 | BH-T822 | 77.7-80.8 | 5/8 | MC-10074 | MK-4300 | 77.7-77.8<br>77.8-80.8 | 13/16<br>13/16 | CC-70106<br>CC-70112 | CK-3113<br>CK-3113 |
| | MX41 | SGS・SGツーリング | 77.7-80.8 | 7/8 | | TK-9355 | 77.7-77.11<br>77.11-79.12<br>79.12-80.8 | 2 1/8<br>2 1/8<br>2 1/8 | DISC<br>DISC<br>DISC | SP-212<br>SP-212<br>SP-212 | | 77.7-80.8 | 1 11/16 | DISC | SP-218 | | 77.7-80.8 | BH-02220 | (R-1)BH-02340<br>(L-1)BH-02340<br>(R-2)BH-02343<br>(L-2)BH-02343 | 77.7-80.8 | 5/8 | MC-10074 | MK-4300 | 77.7-77.8<br>77.8-80.8 | 13/16<br>13/16 | CC-70106<br>CC-70112 | CK-3113<br>CK-3113 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CHASER : 60 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) | E−TX60 | DX・XL | 80.9−82.8 | 7/8 | | TK−9390 | 80.9−82.8 | 2 1/4 | DISC | SP−229 | CPS−219 | 80.9−82.8 | 7/8 | (R)WC−50035<br>(L)WC−50035 | WK−545 | CUP | 80.9−82.8 | BH−02407 | BH−02394 | 80.9−82.8 | 5/8 | MC−10074 | MK−4300 | 80.9−80.12<br>80.12−82.8 | 13/16<br>13/16 | CC−70110<br>CC−70110 | CK−3113<br>CK−3144 |
| | E−SX60 | STD・DX・XL・XG | 82.8−84.7 | 7/8 | | TK−9390 | 82.8−84.7 | 2 1/4 | DISC | SP−229 | CPS−219 | 82.8−84.7 | 7/8 | (R)WC−50035<br>(L)WC−50035 | WK−545 | CUP | 82.8−84.7 | BH−02407 | BH−02394 | 82.8−84.7 | 5/8 | MC−10118 | MK−4308 | 82.8−84.7<br><LPG車><br>83.2−84.7 | 13/16<br><br>13/16 | CC−70133<br><br>CC−70145 | CK−3144<br><br>CK−3144 |
| (2000) | E−RX60 | XL・XG | 80.9−82.8 | 7/8 | | TK−9390 | 80.9−82.8 | 2 1/4 | DISC | SP−229 | CPS−219 | 80.9−82.8 | 7/8 | (R)WC−50035<br>(L)WC−50035 | WK−545 | CUP | 80.9−82.8 | BH−02407 | BH−02394 | 80.9−82.8 | 5/8 | MC−10072 | MK−4300 | 80.9−80.12<br>80.12−82.8 | 13/16<br>13/16 | CC−70110<br>CC−70110 | CK−3113<br>CK−3144 |
| | E−RX63 | GT | 80.9−82.8 | 7/8 | | TK−9409 | 80.9−82.8 | 2 1/4 | DISC | SP−229 | CPS−219 | 80.9−82.8 | 1 11/16 | DISC | SP−218 | | 80.9−82.8 | BH−02407 | (R−1)BH−02340<br>(L−1)BH−02340<br>(L−2)BH−02343 | 80.9−82.8 | 5/8 | MC−10072 | MK−4300 | 80.9−80.12<br>80.12−82.8 | 13/16<br>13/16 | CC−70110<br>CC−70110 | CK−3113<br>CK−3144 |
| | E−GX60 | SXL | 80.9−82.8 | 7/8 | | TK−9390 | 80.9−82.8 | 2 1/4 | DISC | SP−229 | CPS−219 | 80.9−82.8 | 7/8 | (R)WC−50035<br>(L)WC−50035 | WK−545 | CUP | 80.9−82.8 | BH−02407 | BH−02394 | 80.9−82.8 | 5/8 | MC−10072 | MK−4300 | 80.9−82.8 | 13/16 | CC−70133 | CK−3144 |
| | E−GX61 | SGツーリング<br>アバンテ | 80.9−84.7 | 7/8 | | TK−9409 | 80.9−84.7 | 2 1/4 | DISC | SP−229 | CPS−219 | 80.9−84.7 | 1 11/16 | DISC | SP−218 | | 80.9−84.7 | BH−02407 | (R−1)BH−02340<br>(L−1)BH−02340<br>(R−2)BH−02343<br>(L−2)BH−02343 | 80.9−82.8<br>82.8−84.7 | 5/8<br>5/8 | MC−10072<br>MC−10110 | MK−4300<br>MK−4312 | 80.9−84.7 | 13/16 | CC−70133 | CK−3144 |
| | | SXL | 82.8−84.7 | 7/8 | | TK−9390 | 82.8−84.7 | 2 1/4 | DISC | SP−229 | CPS−219 | 82.8−84.7 | 7/8 | (R)WC−50035<br>(L)WC−50035 | WK−545 | CUP | 82.8−84.7 | BH−02407 | (R)BH−02340<br>(L)BH−02340 | 82.8−84.7 | 5/8 | MC−10110 | MK−4312 | 82.8−84.7 | 13/16 | CC−70133 | CK−3144 |
| | E−MX61 | SGツーリング(ターボ)<br>アバンテ(ターボ) | 81.10−84.7 | 7/8 | | TK−9418 | 81.10−84.7 | 2 1/4 | DISC | SP−229 | CPS−219 | 81.10−84.7 | 1 11/16 | DISC | SP−218 | | 81.10−84.7 | BH−02407 | (R−1)BH−02340<br>(L−1)BH−02340<br>(R−2)BH−02343<br>(L−2)BH−02343 | | | (オートマチック) | | | | | |
| (2200ディーゼル) | K−LX60<br>N−LX60<br><N−は82. 8〜> | DX・XL | 80.9−84.7 | 7/8 | | TK−9390 | 80.9−84.7 | 2 1/4 | DISC | SP−229 | CPS−219 | 80.9−84.7 | 7/8 | (R)WC−50035<br>(L)WC−50035 | WK−545 | CUP | 80.9−84.7 | BH−02407 | BH−02394 | 80.9−82.8<br>82.8−84.7 | 5/8<br>5/8 | MC−10072<br>MC−10110 | MK−4300<br>MK−4312 | 80.9−84.7 | 7/8 | CC−70134 | CK−3122 |
| (2400ディーゼル) | N−LX65 | SXL(ターボ) | 82.8−84.7 | 7/8 | | TK−9390 | 82.8−84.7 | 2 1/4 | DISC | SP−229 | CPS−219 | 82.8−84.7 | 7/8 | (R)WC−50035<br>(L)WC−50035 | WK−545 | CUP | 82.8−84.7 | BH−02407 | (R)BH−02340<br>(L)BH−02340 | | | (オートマチック) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CHASER : 70 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) | E−SX70 | XL・XG<br>XGエクストラ<br>XLエクストラ | 84.8-88.8 | 7/8 | TD-T270 | TK-T004 | 84.8-88.8 | 2 1/4 | DISC | SP-229 | CPS-229 | 84.8-84.9<br><br>84.9-88.8 | 7/8<br><br>7/8 | (R)WC-50035<br>(L)WC-50035<br>(R)WC-50070<br>(L)WC-50070 | WK-545<br><br>WK-545 | CUP<br><br>CUP | 84.8-88.8 | BH-02462 | BH-94015 | 84.8-85.2<br>85.2-88.8 | 5/8<br>5/8 | MC-10110<br>MC-10110 | MK-4312<br>MK-4312 | 84.8-88.8 | 13/16 | CC-70133 | CK-3144 |
| (2000) | E−GX71 | SXL(E. F. I) | 84.8-88.8 | 7/8 | TD-T270 | TK-T004 | 84.8-88.8 | 2 1/4 | DISC | SP-229 | CPS-229 | 84.8-84.9<br><br>84.9-88.8 | 7/8<br><br>7/8 | (R)WC-50035<br>(L)WC-50035<br>(R)WC-50070<br>(L)WC-50070 | WK-545<br><br>WK-545 | CUP<br><br>CUP | 84.8-88.8 | BH-02462 | (R)BH-95001<br>(L)BH-95001 | 84.8-85.2<br>85.2-88.8 | 5/8<br>5/8 | MC-10110<br>MC-10110 | MK-4312<br>MK-4312 | 84.8-88.8 | 13/16 | CC-70133 | CK-3144 |
| | | アバンテ(E. F. I) | 84.8-85.10<br>85.10-88.8 | 7/8<br>15/16 | TD-T351 | TK-T004<br>TK-T003 | 84.8-88.8 | 2 1/4 | DISC | SP-229 | CPS-229 | 84.8-88.8 | 42.8 | DISC | SP-238 | | 84.8-88.8 | BH-02462 | (R-1)BH-95001<br>(L-1)BH-95001<br>(R-2)BH-02343<br>(L-2)BH-02343 | 84.8-85.2<br>85.2-88.8 | 5/8<br>5/8 | MC-10110<br>MC-10110 | MK-4312<br>MK-4312 | 84.8-88.8 | 13/16 | CC-70133 | CK-3144 |
| | | アバンテ(ツインカム)<br>GT | 84.8-88.8 | 15/16 | TD-T407 | TK-T003 | 84.8-88.8 | 2 1/4 | DISC | SP-229 | CPS-229 | 84.8-88.8 | 42.8 | DISC | SP-238 | | 84.8-88.8 | BH-02462 | (R-1)BH-95001<br>(L-1)BH-95001<br>(R-2)BH-02343<br>(L-2)BH-02343 | 84.8-88.8<br><GT><br>85.10-88.8 | 5/8<br><br>5/8 | | MK-4337<br><br>MK-4337 | 84.8-88.8 | 13/16 | CC-70133 | CK-3144 |
| | E−MX71 | アバンテ(ターボ) | 84.8-85.10 | 15/16 | TD-T406 | TK-T003 | 84.8-85.10 | 2 1/4 | DISC | SP-229 | CPS-229 | 84.8-85.10 | 42.8 | DISC | SP-238 | | 84.8-85.10 | BH-02462 | (R-1)BH-95001<br>(L-1)BH-95001<br>(R-2)BH-02343<br>(L-2)BH-02343 | | | (オートマチック) | | | | | |
| (2400ディーゼル) | N−LX70<br>Q−LX70 | XL | 84.8-88.8 | 7/8 | TD-T270 | TK-T004 | 84.8-88.8 | 2 1/4 | DISC | SP-229 | CPS-229 | 84.8-84.9<br><br>84.9-88.8 | 7/8<br><br>7/8 | (R)WC-50035<br>(L)WC-50035<br>(R)WC-50070<br>(L)WC-50070 | WK-545<br><br>WK-545 | CUP<br><br>CUP | 84.8-88.8 | BH-02462 | BH-94015 | 84.8-85.2<br>85.2-88.8 | 5/8<br>5/8 | MC-10110<br>MC-10110 | MK-4312<br>MK-4312 | 84.8-88.8 | 13/16 | CC-70171 | CK-3144 |
| | N−LX70<br>Q−LX70 | XL・XG(ターボ) | 84.8-86.8<br>86.8-88.8 | 7/8<br>15/16 | TD-T270 | TK-T004<br>TK-T003 | 84.8-88.8 | 2 1/4 | DISC | SP-229 | CPS-229 | 84.8-84.9<br><br>84.9-88.8 | 7/8<br><br>7/8 | (R)WC-50035<br>(L)WC-50035<br>(R)WC-50070<br>(L)WC-50070 | WK-545<br><br>WK-545 | CUP<br><br>CUP | 84.8-88.8 | BH-02462 | BH-94015 | 84.8-88.8 | 5/8 | | MK-4337 | 84.8-88.8 | 13/16 | CC-70171 | CK-3144 |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CHASER : 70 ser.(FOR TRAINING CAR) | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) E－SX70Y | <生徒側><br>84.8-88.8<br><教官側><br>84.8-88.8 | 7/8 | | TK-T004 | 84.8-88.8 | 2 1/4 | DISC | SP-229 | | 84.8-84.9<br><br>84.9-88.8 | 7/8<br><br>7/8 | (R)WC-50035<br>(L)WC-50035<br>(R)WC-50070<br>(L)WC-50070 | WK-545<br><br>WK-545 | CUP<br><br>CUP | 84.8-88.8 | BH-02462 | BH-94015 | 84.8-85.2<br>85.2-88.8 | 5/8<br>5/8 | MC-10110<br>MC-10110 | MK-4312<br>MK-4312 | 84.8-88.8 | 13/16 | CC-70133 | CK-3144 |
| (1800L. P. G) E－YX70Y<br>E－YX72Y | <生徒側><br>84.8-88.8<br><教官側><br>84.8-88.8 | 7/8 | | TK-T004 | 84.8-88.8 | 2 1/4 | DISC | SP-229 | | 84.8-84.9<br><br>84.9-88.8 | 7/8<br><br>7/8 | (R)WC-50035<br>(L)WC-50035<br>(R)WC-50070<br>(L)WC-50070 | WK-545<br><br>WK-545 | CUP<br><br>CUP | 84.8-88.8 | BH-02462 | BH-94015 | 84.8-88.8 | 5/8 | | MK-4312 | 84.8-86.8<br><YX72Y><br>86.8-88.5<br>88.5-88.8 | 13/16<br><br>13/16<br>13/16 | CC-70110<br><br>CC-70145<br>CC-70145 | CK-3144<br><br>CK-3144<br>CK-3144 |
| (2400ディーゼル)<br>N－LX70Y<br>Q－LX70Y<br>＜Q－は87. 9～＞ | <生徒側><br>84.8-88.8<br><教官側><br>84.8-88.8 | 7/8 | | TK-T004 | 84.8-88.8 | 2 1/4 | DISC | SP-229 | | 84.8-84.9<br><br>84.9-88.8 | 7/8<br><br>7/8 | (R)WC-50035<br>(L)WC-50035<br>(R)WC-50070<br>(L)WC-50070 | WK-545<br><br>WK-545 | CUP<br><br>CUP | 84.8-88.8 | BH-02462 | BH-94015 | 84.8-85.2<br>85.2-88.8 | 5/8<br>5/8 | MC-10110<br>MC-10110 | MK-4312<br>MK-4312 | 84.8-88.8 | 13/16 | CC-70171 | CK-3144 |

| Models | TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CHASER : 80 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) | E－SX80 | XL・XG | 88.8-92.10 | 15/16 | | TK-T325 | 88.8-92.10 | 60.6 | DISC | SP-251 | CPS-249 | 88.8-90.1 | 7/8 | (R)WC-50074<br>(L)WC-50074 | WK-545 | CUP | 88.8-92.10 | BH-T821 | BH-T822 | 88.8-92.10 | 5/8 | MC-T400 | MK-T236 | 88.8-91.3<br>91.3-92.10 | 13/16<br>13/16 | CC-70133 | CK-3144<br>CK-T201 |
| | | | | | | | | | | | | カップ2種類有り<br>形状確認要す<br>90.1-92.10 | 7/8<br>7/8 | (R)WC-50074<br>(L)WC-50074<br>(R)WC-T650<br>(L)WC-T650 | WK-545<br>WK-770 | 皿型カップ<br>CUP<br>リング型カップ<br>CUP | | | | | | | | | | | |
| (2000) | E－GX81 | SXL<br>1G－FEエンジン車 | 88.8-92.10 | 15/16 | | TK-T325 | 88.8-92.10 | 60.6 | DISC | SP-251 | CPS-249 | 88.8-92.10 | 40.4 | DISC | SP-247 | | 88.8-92.10 | BH-T821 | (R)BH-02568<br>(L)BH-02568 | 88.8-92.10 | 5/8 | MC-T400 | MK-T236 | 88.8-91.3<br>91.3-92.10 | 13/16<br>13/16 | CC-70133 | CK-3144<br>CK-T201 |
| | | アバンテ<br>1G－FEエンジン車<br>1G－GEエンジン車 | 88.8-92.10<br><アンチスキッド付><br>88.8-89.8<br>89.8-92.10 | 1<br><br>1<br>1 | | TK-T042<br><br>TK-T046<br>TK-T301 | 88.8-92.10 | 60.6 | DISC | SP-251 | CPS-249 | <1GFEエンジン車><br>88.8-92.10<br><1GGEエンジン車><br>88.8-92.10 | 40.4<br><br>42.8 | DISC<br><br>DISC | SP-247<br><br>SP-262 | | 88.8-92.10 | BH-T821 | (R)BH-02568<br>(L)BH-02568 | 88.8-92.10 | 5/8 | MC-T400 | MK-T236 | 88.8-91.3<br>91.3-92.10 | 13/16<br>13/16 | CC-70133 | CK-3144<br>CK-T201 |
| | | アバンテG<br>1G－GZEエンジン車 | 88.8-89.8<br><トラクションコントロール付><br>89.8-90.8<br><トラクションコントロール無><br>89.8-90.8 | 1<br><br>1<br><br>1 | | TK-T046<br><br>TK-T301<br><br>TK-T042 | 88.8-90.8 | 60.6 | DISC | SP-251 | CPS-249 | 88.8-90.8 | 42.8 | DISC | SP-262 | | 88.9-90.8 | BH-T821 | (R)BH-02568<br>(L)BH-02568 | | | (オートマチック) | | | | | |
| | | GT<br>1G－GTEエンジン車 | 88.8-90.8<br><アンチスキッド付><br>88.8-89.8<br>89.8-90.8 | 1<br><br>1<br>1 | | TK-T042<br><br>TK-T046<br>TK-T301 | 88.8-90.8 | 60.6 | DISC | SP-251 | CPS-249 | 88.8-90.8 | 42.8 | DISC | SP-262 | | 88.8-90.8 | BH-T821 | (R)BH-02568<br>(L)BH-02568 | 88.8-90.8 | 5/8 | | MK-4337 | 88.8-90.8 | 13/16 | | CK-3144 |
| (2500) | E－JZX81 | アバンテ<br>1JZ－GEエンジン車 | 90.8-92.10<br><アンチスキッド付><br>90.8-92.10 | 1<br><br>1 1/16 | | TK-T042<br><br>TK-T326 | 90.8-92.10 | 60.6 | DISC | SP-251 | CPS-249 | 90.8-92.10 | 42.8 | DISC | SP-262 | | 90.8-92.10 | BH-T821 | (R)BH-02568<br>(L)BH-02568 | | | (オートマチック) | | | | | |
| | | アバンテG<br>1JZ－GEエンジン車 | 90.8-92.10 | 1 1/16 | | TK-T326 | 90.8-92.10 | 60.6 | DISC | SP-251 | CPS-249 | 90.8-92.10 | 42.8 | DISC | SP-262 | | 90.8-92.10 | BH-T821 | (R)BH-02568<br>(L)BH-02568 | | | (オートマチック) | | | | | |
| | | GT（ターボ）<br>1JZ－GTEエンジン車 | 90.8-92.10 | 1 1/16 | | TK-T326 | 90.8-92.10 | 60.6 | DISC | SP-264 | | 90.8-92.10 | 42.8 | DISC | SP-262 | | 90.8-92.10 | BH-T821 | (R)BH-02568<br>(L)BH-02568 | | | (オートマチック) | | | | | |
| (3000) | E－MX83 | アバンテG | 89.8-90.8<br>90.8-92.10 | 1<br>1 1/16 | | TK-T301<br>TK-T326 | 89.8-92.10 | 60.6 | DISC | SP-251 | CPS-249 | 89.8-92.10 | 42.8 | DISC | SP-262 | | 89.8-92.10 | BH-T821 | (R)BH-02568<br>(L)BH-02568 | | | (オートマチック) | | | | | |
| (2400ディーゼル) | Q－LX80 | XL・XG | 88.8-92.10 | 15/16 | | TK-T325 | 88.8-92.10 | 60.6 | DISC | SP-251 | CPS-249 | 88.8-90.1 | 7/8 | (R)WC-50074<br>(L)WC-50074 | WK-545 | CUP | 88.8-92.10 | BH-T821 | BH-T822 | 88.8-92.10 | 5/8 | MC-T400 | MK-T236 | 88.8-91.3<br>91.3-92.10 | 13/16<br>13/16 | CC-70171<br>CC-70171 | CK-3144<br>CK-T201 |
| | | | | | | | | | | | | カップ2種類有り<br>形状確認要す<br>90.1-92.10 | 7/8<br>7/8 | (R)WC-50074<br>(L)WC-50074<br>(R)WC-T650<br>(L)WC-T650 | WK-545<br>WK-770 | 皿型カップ<br>CUP<br>リング型カップ<br>CUP | | | | | | | | | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CHASER : 80 ser.(FOR TRAINING CAR) | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) E－SX80Y | <生徒側><br>88.8-92.10<br><教官側><br>88.8-92.10 | 15/16<br>7/8 | | TK-T325 | 88.8-92.10 | 60.6 | DISC | SP-251 | CPS-249 | 88.8-90.1<br>ｶｯﾌﾟ2種類有り<br>形状確認要す<br>90.1-92.10 | 7/8<br>7/8 | (R)WC-50074<br>(L)WC-50074<br>(R)WC-50074<br>(L)WC-50074 | WK-545<br>WK-545<br>WK-770 | CUP<br>皿型ｶｯﾌﾟ<br>CUP<br>ﾘﾝｸﾞ型ｶｯﾌﾟ<br>CUP | 88.8-92.10 | BH-T821 | BH-T822 | 88.8-92.10 | 5/8 | MC-T400 | MK-T236 | 88.8-91.3<br>91.3-92.10 | 13/16<br>13/16 | CC-70133 | CK-3144<br>CK-T201 |
| (2000L. P. G) E－YX80Y | <生徒側><br>88.8-92.10<br><教官側><br>88.8-92.10 | 15/16<br>7/8 | | TK-T325 | 88.8-92.10 | 60.6 | DISC | SP-251 | CPS-249 | 88.8-90.1<br>ｶｯﾌﾟ2種類有り<br>形状確認要す<br>90.1-92.10 | 7/8<br>7/8 | (R)WC-50074<br>(L)WC-50074<br>(R)WC-50074<br>(L)WC-50074 | WK-545<br>WK-545<br>WK-770 | CUP<br>皿型ｶｯﾌﾟ<br>CUP<br>ﾘﾝｸﾞ型ｶｯﾌﾟ<br>CUP | 88.8-92.10 | BH-T821 | BH-T822 | 88.8-92.10 | 5/8 | MC-T400 | MK-T236 | 88.8-91.3<br>91.3-92.10 | 13/16<br>13/16 | CC-70145<br>CC-T317 | CK-3144<br>CK-T201 |
| (2400ディーゼル)<br>Q－LX80Y | <生徒側><br>88.8-92.10<br><教官側><br>88.8-92.10 | 15/16<br>7/8 | | TK-T325 | 88.8-92.10 | 60.6 | DISC | SP-251 | CPS-249 | 88.8-90.1<br>ｶｯﾌﾟ2種類有り<br>形状確認要す<br>90.1-92.10 | 7/8<br>7/8 | (R)WC-50074<br>(L)WC-50074<br>(R)WC-50074<br>(L)WC-50074 | WK-545<br>WK-545<br>WK-770 | CUP<br>皿型ｶｯﾌﾟ<br>CUP<br>ﾘﾝｸﾞ型ｶｯﾌﾟ<br>CUP | 88.8-92.10 | BH-T821 | BH-T822 | 88.8-92.10 | 5/8 | MC-T400 | MK-T236 | 88.8-91.3<br>91.3-92.10 | 13/16<br>13/16 | CC-70171<br>CC-70171 | CK-3144<br>CK-T201 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CHASER : 90 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) | E−SX90 | | 92.10-96.9 | 15/16 | | TK-T348 | 92.10-96.9 | | DISC | SP-255 | CPS-255 | 92.10-96.9 | | DISC | SP-263 | CPS-263 | 92.10-96.9 | BH-T595 | (R)BH-T594 | 92.10-94.3 | 5/8 | MC-T402 | | 92.10-96.9 | 13/16 | | CK-T201 |
| | | | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | | | | | | (L)BH-T594 | 94.3-96.9 | 5/8 | MC-T402 | MK-T244 | | | | |
| | | | 92.10-94.7 | 1 | | TK-T366 | | | | | | | | | | | | | | | | | | | | | |
| | | | 94.7-96.9 | 1 | | TK-T366 | | | | | | | | | | | | | | | | | | | | | |
| (2000) | E−GX90 | | 92.10-96.9 | 15/16 | | TK-T348 | 92.10-96.9 | | DISC | SP-255 | CPS-255 | 92.10-96.9 | | DISC | SP-263 | CPS-263 | 92.10-96.9 | BH-T595 | (R)BH-T594 | 92.10-94.3 | 5/8 | MC-T402 | | 92.10-96.9 | 13/16 | | CK-T201 |
| | | | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | | | | | | (L)BH-T594 | 94.3-96.9 | 5/8 | MC-T402 | MK-T244 | | | | |
| | | | 92.10-94.7 | 1 | | TK-T366 | | | | | | | | | | | | | | | | | | | | | |
| | | | 94.7-96.9 | 1 | | TK-T366 | | | | | | | | | | | | | | | | | | | | | |
| (2400ディーゼル) | | | 92.10-96.9 | 15/16 | | TK-T348 | 92.10-96.9 | | DISC | SP-255 | CPS-255 | 92.10-96.9 | | DISC | SP-263 | CPS-263 | 92.10-96.9 | BH-T595 | (R)BH-T594 | 92.10-94.3 | 5/8 | MC-T403 | | 92.10-96.9 | 13/16 | CC-70171 | CK-T201 |
| | Y−LX90 | | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | | | | | | (L)BH-T594 | 94.3-96.9 | 5/8 | MC-T403 | MK-T244 | | | | |
| | <KD−は95．9～> | | 92.10-94.9 | 1 | | TK-T301 | | | | | | | | | | | | | | | | | | | | | |
| | | | 94.9-96.9 | 1 | | TK-T366 | | | | | | | | | | | | | | | | | | | | | |
| (2500) | E−JZX90・93 | ターボ車 | 92.10-96.9 | 1 1/16 | | TK-T332 | 92.10-96.9 | 44.4 | DISC | MP-47 | | 92.10-96.9 | | DISC | SP-256 | | 92.10-96.9 | BH-T595 | (R)BH-T594 | 92.10-94.3 | 5/8 | MC-T401 | | 92.10-95.12 | 7/8 | | CK-3143 |
| | | | | | | | | | | | | | | | | | | | (L)BH-T594 | 94.3-96.9 | 5/8 | MC-T401 | MK-T244 | 95.12-96.9 | 7/8 | | CK-T223 |
| | | ターボ無 | 92.10-96.9 | 15/16 | | TK-T348 | 92.10-96.9 | 57.2 | DISC | MP-50 | CPM-68 | 92.10-95.9 | | DISC | SP-263 | CPS-263 | 92.10-96.9 | BH-T595 | (R)BH-T594 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | | | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | 95.9-96.9 | | DISC | MP-67 | | | | (L)BH-T594 | | | | | | | | |
| | | | 92.10-94.7 | 1 | | TK-T366 | | | | | | | | | | | <JZX93> | | | | | | | | | | |
| | | | 94.7-96.9 | 1 | | TK-T366 | | | | | | | | | | | 93.10-96.9 | BH-T691 | (R)BH-T594 | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | (L)BH-T594 | | | | | | | | |
| (3000) | E−JZX91 | | 92.10-94.7 | 1 | | TK-T366 | 92.10-96.9 | 57.2 | DISC | MP-50 | CPM-68 | 92.10-95.9 | | DISC | SP-263 | CPS-263 | 92.10-96.9 | BH-T595 | (R)BH-T594 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | | | 94.7-96.9 | 1 | | TK-T366 | | | | | | 95.9-96.9 | | DISC | MP-67 | | | | (L)BH-T594 | | | | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CHASER : 100 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) | E－SX100<br>＜GF－は98．8～＞ | | 97.4-01.6 | 1 | | TK-T412 | 97.4-98.8<br>98.8-01.6 | | DISC<br>DISC | SP-204<br>SP-102 | CPS-204<br>CPS-102 | 97.4-01.6 | | DISC | SP-295 | CPS-295 | 97.4-01.6 | BH-T595 | (R)BH-T594<br>(L)BH-T594 | | | (オートマチック) | | | | | |
| (2000) | E－GX100<br>＜GF－は98．8～＞ | | 96.9-01.6 | 1 | | TK-T412 | 96.9-98.8<br>98.8-01.6 | | DISC<br>DISC | SP-204<br>SP-102 | CPS-204<br>CPS-102 | 96.9-01.6 | | DISC | SP-295 | CPS-295 | 96.9-01.6 | BH-T595 | (R)BH-T594<br>(L)BH-T594 | 96.9-01.6 | 5/8 | | MK-T244 | 96.9-01.6 | 13/16 | | CK-T201 |
| | GF－GX105(4WD) | | 98.8-01.6 | 1 | | TK-T412 | 98.8-01.6 | | DISC | MP-72 | CPM-121 | 98.8-01.6 | | DISC | MP-73 | | 98.8-01.6 | BH-T691 | (R)BH-T594<br>(L)BH-T594 | | | (オートマチック) | | | | | |
| (2400ディーゼル) | KD－LX100 | | 96.9-99.8 | 1 | | TK-T377 | 96.9-98.8<br>98.8-99.8 | | DISC<br>DISC | SP-204<br>SP-102 | CPS-204<br>CPS-102 | 96.9-99.8 | | DISC | SP-295 | CPS-295 | 96.9-99.8 | BH-T595 | (R)BH-T594<br>(L)BH-T594 | | | (オートマチック) | | | | | |
| (2500) | E－JZX100<br>＜GF－は98．8～＞ | ターボ無 | 96.9-01.6<br><VSC付><br>98.6-01.6 | 1<br><br>1 | | TK-T412<br><br>TK-T431 | 96.9-01.6 | | DISC | MP-72 | CPM-121 | 96.9-01.6 | | DISC | MP-73 | | 96.9-01.6 | BH-T595 | (R)BH-T594<br>(L)BH-T594 | | | (オートマチック) | | | | | |
| | | ターボ車 | 96.9-01.6 | 1 | | TK-T412 | 96.9-01.6 | 44.4 | DISC | MP-47 | CPM-77 | 96.9-01.6 | | DISC | SP-293 | CPS-293 | 96.9-01.6 | BH-T595 | (R)BH-T594<br>(L)BH-T594 | 96.9-01.6 | 5/8 | | MK-T244 | 96.9-01.6 | 7/8 | | CK-T223 |
| | E－JZX105(4WD)<br>＜GF－は98．8～＞ | | 96.9-01.6 | 1 | | TK-T412 | 96.9-01.6 | | DISC | MP-72 | CPM-121 | 96.9-01.6 | | DISC | MP-73 | | 96.9-01.6 | BH-T691 | (R)BH-T594<br>(L)BH-T594 | | | (オートマチック) | | | | | |
| (3000) | E－JZX101<br>＜GF－は98．8～＞ | | 96.9-98.6<br>98.6-01.6 | <br>1 | | <br>TK-T431 | 96.9-01.6 | | DISC | MP-72 | CPM-121 | 96.9-01.6 | | DISC | MP-73 | | 96.9-98.8<br><br>98.8-01.6 | BH-T595<br><br>BH-T595 | (R)<br>(L)<br>(R)BH-T594<br>(L)BH-T594 | | | (オートマチック) | | | | | |

| Models | TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CRESTA : 50 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) | TX50 | カスタム<br>スーパーカスタム | 80.3-82.8 | 7/8 | | TK-9390 | 80.3-81.9<br>81.9-82.8 | 2 1/4<br>2 1/4 | DISC<br>DISC | SP-219<br>SP-229 | CPS-219<br>CPS-219 | 80.3-82.8 | 7/8 | (R)WC-50035<br>(L)WC-50035 | WK-545 | CUP | 80.3-80.8<br>80.8-82.8 | BH-02407<br>BH-02407 | BH-T822<br>BH-02394 | 80.3-82.8 | 5/8 | MC-10074 | MK-4300 | 80.3-80.10<br>80.10-82.8 | 13/16<br>13/16 | CC-70109<br>CC-70110 | CK-3113<br>CK-3144 |
| (2000) | GX50 | スーパーDX | 80.3-82.8 | 7/8 | | TK-9390 | 80.3-81.9<br>81.9-82.8 | 2 1/4<br>2 1/4 | DISC<br>DISC | SP-219<br>SP-229 | CPS-219<br>CPS-219 | 80.3-82.8 | 7/8 | (R)WC-50035<br>(L)WC-50035 | WK-545 | CUP | 80.3-80.8<br>80.8-82.8 | BH-02407<br>BH-02407 | BH-T822<br>BH-02394 | 80.3-82.8 | 5/8 | MC-10072 | MK-4300 | 80.3-80.10<br>80.10-82.8 | 13/16<br>13/16 | CC-70112<br>CC-70133 | CK-3113<br>CK-3144 |
| | GX51 | スーパーツーリング<br>スーパールーセント | 80.3-82.8 | 7/8 | | TK-9409 | 80.3-81.9<br>81.9-82.8 | 2 1/4<br>2 1/4 | DISC<br>DISC | SP-219<br>SP-229 | CPS-219<br>CPS-219 | 80.3-82.8 | 1 11/16 | DISC | SP-218 | | 80.3-82.8 | BH-02407 | (R-1)BH-02340<br>(L-1)BH-02340<br>(R-2)BH-02343<br>(L-2)BH-02343 | 80.3-82.8 | 5/8 | MC-10072 | MK-4300 | 80.3-80.10<br>80.10-82.8 | 13/16<br>13/16 | CC-70112<br>CC-70133 | CK-3113<br>CK-3144 |
| | MX51 | スーパーツーリング(ターボ)<br>スーパールーセント(ターボ) | 81.10-82.8 | 7/8 | | TK-9418 | 81.10-82.8 | 2 1/4 | DISC | SP-229 | CPS-219 | 81.10-82.8 | 1 11/16 | DISC | SP-218 | | 81.10-82.8 | BH-02407 | (R-1)BH-02340<br>(L-1)BH-02340<br>(R-2)BH-02343<br>(L-2)BH-02343 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |

| Models | TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CRESTA : 60 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) E−SX60 | カスタム・スーパーカスタム | 82.8−84.7 | 7/8 | | TK−9390 | 82.8−84.7 | 2 1/4 | DISC | SP−229 | | 82.8−84.7 | 7/8 | (R)WC−50035<br>(L)WC−50035 | WK−545 | CUP | 82.8−84.7 | BH−02407 | BH−02394 | 82.8−84.7 | 5/8 | MC−10118 | MK−4308 | 82.8−84.7 | 13/16 | CC−70133 | CK−3144 |
| (2000) E−GX61 | スーパーDX | 82.8−84.7 | 7/8 | | TK−9390 | 82.8−84.7 | 2 1/4 | DISC | SP−229 | | 82.8−84.7 | 7/8 | (R)WC−50035<br>(L)WC−50035 | WK−545 | CUP | 82.8−84.7 | BH−02407 | (R)BH−02340<br>(L)BH−02340 | 82.8−84.7 | 5/8 | MC−10110 | MK−4312 | 82.8−84.7 | 13/16 | CC−70133 | CK−3144 |
| | スーパールーセント | 82.8−84.7 | 7/8 | | TK−9409 | 82.8−84.7 | 2 1/4 | DISC | SP−229 | | 82.8−84.7 | 1 11/16 | DISC | SP−218 | | 82.8−84.7 | BH−02407 | (R−1)BH−02340<br>(L−1)BH−02340<br>(R−2)BH−02343<br>(L−2)BH−02343 | 82.8−84.7 | 5/8 | MC−10110 | MK−4312 | 82.8−84.7 | 13/16 | CC−70133 | CK−3144 |
| E−MX61 | スーパーツリング(ターボ)<br>スーパールーセント(ターボ) | 82.8−84.7 | 7/8 | | TK−9418 | 82.8−84.7 | 2 1/4 | DISC | SP−229 | | 82.8−83.2<br>83.2−84.7 | 1 11/16<br>1 11/16 | DISC<br>DISC | SP−218<br>SP−218 | | 82.8−84.7 | BH−02407 | (R−1)BH−02340<br>(L−1)BH−02340<br>(R−2)BH−02343<br>(L−2)BH−02343 | | | (オートマチック) | | | | |
| (2200ディーゼル) N−LX60 | カスタム・スーパーカスタム | 83.8−84.7 | 7/8 | | TK−9390 | 83.8−84.7 | 2 1/4 | DISC | SP−229 | | 83.8−84.7 | 7/8 | (R)WC−50035<br>(L)WC−50035 | WK−545 | CUP | 83.8−84.7 | BH−02407 | BH−02394 | 83.8−84.7 | 5/8 | MC−10110 | MK−4312 | 83.8−84.7 | 7/8 | CC−70134 | CK−3122 |

| Models | TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CRESTA : 70 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) E−SX70 | スーパーカスタム | 84.8-88.8 | 7/8 | TD-T270 | TK-T004 | 84.8-88.8 | 2 1/4 | DISC | SP-229 | CPS-229 | 84.8-84.9<br>84.9-88.8 | 7/8<br>7/8 | (R)WC-50035<br>(L)WC-50035<br>(R)WC-50070<br>(L)WC-50070 | WK-545<br>WK-545 | CUP<br>CUP | 84.8-88.8 | BH-02462 | BH-94015 | 84.8-85.2<br>85.2-88.8 | 5/8<br>5/8 | MC-10110<br>MC-10110 | MK-4312<br>MK-4312 | 84.8-88.8 | 13/16 | CC-70133 | CK-3144 |
| (2000) E−GX71 | スーパーDX(E. F. I) | 84.8-88.8 | 7/8 | TD-T270 | TK-T004 | 84.8-88.8 | 2 1/4 | DISC | SP-229 | CPS-229 | 84.8-84.9<br>84.9-88.8 | 7/8<br>7/8 | (R)WC-50035<br>(L)WC-50035<br>(R)WC-50070<br>(L)WC-50070 | WK-545<br>WK-545 | CUP<br>CUP | 84.8-88.8 | BH-02462 | (R)BH-95001<br>(L)BH-95001 | 84.8-85.2<br>85.2-88.8 | 5/8<br>5/8 | MC-10110<br>MC-10110 | MK-4312<br>MK-4312 | 84.8-88.8 | 13/16 | CC-70133 | CK-3144 |
| | スーパールーセント(E. F. I) | 84.8-85.10<br>85.10-88.8 | 7/8<br>15/16 | TD-T351 | TK-T004<br>TK-T003 | 84.8-88.8 | 2 1/4 | DISC | SP-229 | CPS-229 | 84.8-88.8 | 42.8 | DISC | SP-238 | | 84.8-88.8 | BH-02462 | (R-1)BH-95001<br>(L-1)BH-95001<br>(R-2)BH-02343<br>(L-2)BH-02343 | 84.8-85.2<br>85.2-88.8 | 5/8<br>5/8 | MC-10110<br>MC-10110 | MK-4312<br>MK-4312 | 84.8-88.8 | 13/16 | CC-70133 | CK-3144 |
| | スーパールーセント(ツインカム)<br>GT | 84.8-88.8 | 15/16 | TD-T407 | TK-T003 | 84.8-88.8 | 2 1/4 | DISC | SP-229 | CPS-229 | 84.8-88.8 | 42.8 | DISC | SP-238 | | 84.8-88.8 | BH-02462 | (R-1)BH-95001<br>(L-1)BH-95001<br>(R-2)BH-02343<br>(L-2)BH-02343 | 84.8-88.8<br><GT><br>85.10-88.8 | 5/8<br><br>5/8 | | MK-4337<br><br>MK-4337 | 84.8-88.8 | 13/16 | CC-70133 | CK-3144 |
| | E−MX71 スーパールーセント(ターボ) | 84.8-85.10 | 15/16 | TD-T406 | TK-T003 | 84.8-85.10 | 2 1/4 | DISC | SP-229 | CPS-229 | 84.8-85.10 | 42.8 | DISC | SP-238 | | 84.8-85.10 | BH-02462 | (R-1)BH-95001<br>(L-1)BH-95001<br>(R-2)BH-02343<br>(L-2)BH-02343 | | | (オートマチック) | | | | | |
| (2400ディーゼル)<br>N−LX70<br>Q−LX70 | スーパーカスタム | 84.8-88.8 | 7/8 | TD-T270 | TK-T004 | 84.8-88.8 | 2 1/4 | DISC | SP-229 | CPS-229 | 84.8-84.9<br>84.9-88.8 | 7/8<br>7/8 | (R)WC-50035<br>(L)WC-50035<br>(R)WC-50070<br>(L)WC-50070 | WK-545<br>WK-545 | CUP<br>CUP | 84.8-88.8 | BH-02462 | BH-94015 | 84.8-85.2<br>85.2-88.8 | 5/8<br>5/8 | MC-10110<br>MC-10110 | MK-4312<br>MK-4312 | 84.8-88.8 | 13/16 | CC-70171 | CK-3144 |
| | スーパーカスタム(ターボ) | 84.8-86.8<br>86.8-88.8 | 7/8<br>15/16 | TD-T270 | TK-T004<br>TK-T003 | 84.8-88.8 | 2 1/4 | DISC | SP-229 | CPS-229 | 84.8-84.9<br>84.9-88.8 | 7/8<br>7/8 | (R)WC-50035<br>(L)WC-50035<br>(R)WC-50070<br>(L)WC-50070 | WK-545<br>WK-545 | CUP<br>CUP | 84.8-88.8 | BH-02462 | BH-94015 | 84.8-88.8 | 5/8 | | MK-4337 | 84.8-88.8 | 13/16 | CC-70171 | CK-3144 |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CRESTA : 70 ser.(FOR TRAINING CAR) | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) E－SX70Y | <生徒側><br>84.8-88.8<br><教官側><br>84.8-88.8 | 7/8 | TD-T752 | TK-T004 | 84.8-88.8 | 2 1/4 | DISC | SP-229 | | 84.8-84.9<br><br>84.9-88.8 | 7/8<br><br>7/8 | (R)WC-50035<br>(L)WC-50035<br>(R)WC-50070<br>(L)WC-50070 | WK-545 | CUP<br><br>CUP | 84.8-88.8 | BH-02462 | BH-94015 | 84.8-85.2<br>85.2-88.8 | 5/8<br>5/8 | MC-10110<br>MC-10110 | MK-4312<br>MK-4312 | 84.8-88.8 | 13/16 | CC-70133 | CK-3144 |
| (2400ディーゼル)<br>N－LX70Y<br>Q－LX70Y<br>＜Q－は87．9～＞ | <生徒側><br>84.8-88.8<br><教官側><br>84.8-88.8 | 7/8 | TD-T752 | TK-T004 | 84.8-88.8 | 2 1/4 | DISC | SP-229 | | 84.8-84.9<br><br>84.9-88.8 | 7/8<br><br>7/8 | (R)WC-50035<br>(L)WC-50035<br>(R)WC-50070<br>(L)WC-50070 | WK-545 | CUP<br><br>CUP | 84.8-88.8 | BH-02462 | BH-94015 | 84.8-85.2<br>85.2-88.8 | 5/8<br>5/8 | MC-10110<br>MC-10110 | MK-4312<br>MK-4312 | 84.8-88.8 | 13/16 | CC-70171 | CK-3144 |

| Models | TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CRESTA : 80 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) | E−SX80 | スーパーカスタム | 88.8-92.10 | 15/16 | | TK-T325 | 88.8-92.10 | 60.6 | DISC | SP-251 | CPS-249 | 88.8-90.1 | 7/8 | (R)WC-50074<br>(L)WC-50074 | WK-545 | CUP | 88.8-92.10 | BH-T821 | BH-T822 | 88.8-92.10 | 5/8 | MC-T400 | MK-T236 | 88.8-91.3<br>91.3-92.10 | 13/16<br>13/16 | CC-70133 | CK-3144<br>CK-T201 |
| | | | | | | | | | | | | カップ2種類有り<br>形状確認要す<br>90.1-92.10 | | | | 皿型カップ<br>CUP<br>リング型カップ | | | | | | | | | | | |
| | | | | | | | | | | | | | 7/8 | (R)WC-50074<br>(L)WC-50074 | WK-545 | | | | | | | | | | | | |
| | | | | | | | | | | | | | 7/8 | (R)WC-T650<br>(L)WC-T650 | WK-770 | | | | | | | | | | | | |
| (2000) | E−GX81 | スーパーデラックス<br>1G−FEエンジン車 | 88.8-92.10 | 15/16 | | TK-T325 | 88.8-92.10 | 60.6 | DISC | SP-251 | CPS-249 | 88.8-92.10 | 40.4 | DISC | SP-247 | | 88.8-92.10 | BH-T821 | (R)BH-02568<br>(L)BH-02568 | 88.8-92.10 | 5/8 | MC-T400 | MK-T236 | 88.8-91.3<br>91.3-92.10 | 13/16<br>13/16 | CC-70133 | CK-3144<br>CK-T201 |
| | | スーパールーセント<br>1G−FEエンジン車<br>1G−GEエンジン車 | 88.8-92.10<br><アンチスキッド付><br>88.8-89.8<br>89.8-92.10 | 1<br><br>1<br>1 | | TK-T042<br><br>TK-T046<br>TK-T301 | 88.8-92.10 | 60.6 | DISC | SP-251 | CPS-249 | <1GFEエンジン車><br>88.8-92.10<br><1GGEエンジン車><br>88.8-92.10 | 40.4<br><br>42.8 | DISC<br><br>DISC | SP-247<br><br>SP-262 | | 88.8-92.10 | BH-T821 | (R)BH-02568<br>(L)BH-02568 | 88.8-92.10 | 5/8 | MC-T400 | MK-T236 | 88.8-91.3<br>91.3-92.10 | 13/16<br>13/16 | CC-70133 | CK-3144<br>CK-T201 |
| | | スーパールーセントG<br>1G−GZEエンジン車 | 88.8-89.8<br><トラクションコントロール付><br>89.8-90.8<br><トラクションコントロール無><br>89.8-90.8 | 1<br><br>1<br><br>1 | | TK-T046<br><br>TK-T301<br><br>TK-T042 | 88.8-90.8 | 60.6 | DISC | SP-251 | CPS-249 | 88.8-90.8 | 42.8 | DISC | SP-262 | | 89.8-90.8 | BH-T821 | (R)BH-02568<br>(L)BH-02568 | | | (オートマチック) | | | | | |
| | | GT<br>1G−GTEエンジン車 | 88.8-90.8<br><アンチスキッド付><br>88.8-89.8<br>89.8-90.8 | 1<br><br>1<br>1 | | TK-T042<br><br>TK-T046<br>TK-T301 | 88.8-90.8 | 60.6 | DISC | SP-251 | CPS-249 | 88.8-90.8 | 42.8 | DISC | SP-262 | | 88.8-90.8 | BH-T821 | (R)BH-02568<br>(L)BH-02568 | 88.8-90.8 | 5/8 | | MK-4337 | 88.8-90.8 | 13/16 | | CK-3144 |
| (2500) | E−JZX81 | スーパールーセント<br>1JZ−GEエンジン車 | 90.8-92.10<br><アンチスキッド付><br>90.8-92.10 | 1<br><br>1 1/16 | | TK-T042<br><br>TK-T326 | 90.8-92.10 | 60.6 | DISC | SP-251 | CPS-249 | 90.8-92.10 | 42.8 | DISC | SP-262 | | 90.8-92.10 | BH-T821 | (R)BH-02568<br>(L)BH-02568 | | | (オートマチック) | | | | | |
| | | スーパールーセントG<br>1JZ−GEエンジン車 | 90.8-92.10 | 1 1/16 | | TK-T326 | 90.8-92.10 | 60.6 | DISC | SP-251 | CPS-249 | 90.8-92.10 | 42.8 | DISC | SP-262 | | 90.8-92.10 | BH-T821 | (R)BH-02568<br>(L)BH-02568 | | | (オートマチック) | | | | | |
| | | GT(ターボ)<br>1JZ−GTEエンジン車 | 90.8-92.10 | 1 1/16 | | TK-T326 | 90.8-92.10 | 60.6 | DISC | SP-264 | | 90.8-92.10 | 42.8 | DISC | SP-262 | | 90.8-92.10 | BH-T821 | (R)BH-02568<br>(L)BH-02568 | | | (オートマチック) | | | | | |
| (3000) | E−MX83 | スーパールーセントG | 89.8-90.8<br>90.8-92.10 | 1<br>1 1/16 | | TK-T301<br>TK-T326 | 89.8-92.10 | 60.6 | DISC | SP-251 | CPS-249 | 89.8-92.10 | 42.8 | DISC | SP-262 | | 89.8-92.10 | BH-T821 | (R)BH-02568<br>(L)BH-02568 | | | (オートマチック) | | | | | |
| (2400ディーゼル)<br>Q−LX80 | | スーパーカスタム | 88.8-92.10 | 15/16 | | TK-T325 | 88.8-92.10 | 60.6 | DISC | SP-251 | CPS-249 | 88.8-90.1 | 7/8 | (R)WC-50074<br>(L)WC-50074 | WK-545 | CUP | 88.8-92.10 | BH-T821 | BH-T822 | 88.8-92.10 | 5/8 | MC-T400 | MK-T236 | 88.8-91.3<br>91.3-92.10 | 13/16<br>13/16 | CC-70171<br>CC-70171 | CK-3144<br>CK-T201 |
| | | | | | | | | | | | | カップ2種類有り<br>形状確認要す<br>90.1-92.10 | | | | 皿型カップ<br>CUP<br>リング型カップ | | | | | | | | | | | |
| | | | | | | | | | | | | | 7/8 | (R)WC-50074<br>(L)WC-50074 | WK-545 | | | | | | | | | | | | |
| | | | | | | | | | | | | | 7/8 | (R)WC-T650<br>(L)WC-T650 | WK-770 | | | | | | | | | | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CRESTA : 80 ser.(FOR TRAINING CAR) | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) E－SX80Y | <生徒側><br>88.8-92.10<br><教官側><br>88.8-92.10 | 15/16<br>7/8 | | TK-T325 | 88.8-92.10 | 60.6 | DISC | SP-251 | CPS-249 | 88.8-90.1<br>カップ2種類有り<br>形状確認要す<br>90.1-92.10 | 7/8<br>7/8 | (R)WC-50074<br>(L)WC-50074<br>(R)WC-50074<br>(L)WC-50074 | WK-545<br>WK-545<br>WK-770 | CUP<br>皿型カップ<br>CUP<br>リング型カップ<br>CUP | 88.8-92.10 | BH-T821 | BH-T822 | 88.8-92.10 | 5/8 | MC-T400 | MK-T236 | 88.8-91.3<br>91.3-92.10 | 13/16<br>13/16 | CC-70133 | CK-3144<br>CK-T201 |
| (2000L. P. G) E－YX80Y | <生徒側><br>88.8-92.10<br><教官側><br>88.8-92.10 | 15/16<br>7/8 | | TK-T325 | 88.8-92.10 | 60.6 | DISC | SP-251 | CPS-249 | 88.8-90.1<br>カップ2種類有り<br>形状確認要す<br>90.1-92.10 | 7/8<br>7/8 | (R)WC-50074<br>(L)WC-50074<br>(R)WC-50074<br>(L)WC-50074 | WK-545<br>WK-545<br>WK-770 | CUP<br>皿型カップ<br>CUP<br>リング型カップ<br>CUP | 88.8-92.10 | BH-T821 | BH-T822 | 88.8-92.10 | 5/8 | MC-T400 | MK-T236 | 88.8-91.3<br>91.3-92.10 | 13/16<br>13/16 | CC-70145<br>CC-T317 | CK-3144<br>CK-T201 |
| (2400ディーゼル)<br>Q－LX80Y | <生徒側><br>88.8-92.10<br><教官側><br>88.8-92.10 | 15/16<br>7/8 | | TK-T325 | 88.8-92.10 | 60.6 | DISC | SP-251 | CPS-249 | 88.8-90.1<br>カップ2種類有り<br>形状確認要す<br>90.1-92.10 | 7/8<br>7/8 | (R)WC-50074<br>(L)WC-50074<br>(R)WC-50074<br>(L)WC-50074 | WK-545<br>WK-545<br>WK-770 | CUP<br>皿型カップ<br>CUP<br>リング型カップ<br>CUP | 88.8-92.10 | BH-T821 | BH-T822 | 88.8-92.10 | 5/8 | MC-T400 | MK-T236 | 88.8-91.3<br>91.3-92.10 | 13/16<br>13/16 | CC-70171<br>CC-70171 | CK-3144<br>CK-T201 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CRESTA : 90 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) | E−SX90 | | 92.10-96.9<br><ｱﾝﾁｽｷｯﾄﾞ付><br>92.10-94.7<br>94.7-96.9 | 15/16<br><br>1<br>1 | | TK-T348<br><br>TK-T366<br>TK-T366 | 92.10-96.9 | | DISC | SP-255 | CPS-255 | 92.10-96.9 | | DISC | SP-263 | CPS-263 | 92.10-96.9 | BH-T595 | (R)BH-T594<br>(L)BH-T594 | 92.10-94.3<br>94.3-96.9 | 5/8<br>5/8 | MC-T402<br>MC-T402 | MK-T244 | 92.10-96.9 | 13/16 | | CK-T201 |
| (2000) | E−GX90 | | 92.10-96.9<br><ｱﾝﾁｽｷｯﾄﾞ付><br>92.10-94.7<br>94.7-96.9 | 15/16<br><br>1<br>1 | | TK-T348<br><br>TK-T366<br>TK-T366 | 92.10-96.9 | | DISC | SP-255 | CPS-255 | 92.10-96.9 | | DISC | SP-263 | CPS-263 | 92.10-96.9 | BH-T595 | (R)BH-T594<br>(L)BH-T594 | 92.10-94.3<br>94.3-96.9 | 5/8<br>5/8 | MC-T402<br>MC-T402 | MK-T244 | 92.10-96.9 | 13/16 | | CK-T201 |
| (2400ディーゼル) | Y−LX90<br><KD−は95．9〜> | | 92.10-96.9<br><ｱﾝﾁｽｷｯﾄﾞ付><br>92.10-94.9<br>94.9-96.9 | 15/16<br><br>1<br>1 | | TK-T348<br><br>TK-T301<br>TK-T366 | 92.10-96.9 | | DISC | SP-255 | CPS-255 | 92.10-96.9 | | DISC | SP-263 | CPS-263 | 92.10-96.9 | BH-T595 | (R)BH-T594<br>(L)BH-T594 | 92.10-94.3<br>94.3-96.9 | 5/8<br>5/8 | MC-T403<br>MC-T403 | MK-T244 | 92.10-96.9 | 13/16 | CC-70171 | CK-T201 |
| (2500) | E−JZX90・93 | ターボ車 | 92.10-96.9 | 1 1/16 | | TK-T332 | 92.10-96.9 | 44.4 | DISC | MP-47 | | 92.10-96.9 | | DISC | SP-256 | | 92.10-96.9 | BH-T595 | (R)BH-T594<br>(L)BH-T594 | 92.10-94.3<br>94.3-96.9 | 5/8<br>5/8 | MC-T401<br>MC-T401 | MK-T221<br>MK-T244 | 92.10-95.12<br>95.12-96.9 | 7/8<br>7/8 | | CK-3143<br>CK-T223 |
| | | ターボ無 | 92.10-96.9<br><ｱﾝﾁｽｷｯﾄﾞ付><br>92.10-94.7<br>94.7-96.9 | 15/16<br><br>1<br>1 | | TK-T348<br><br>TK-T366<br>TK-T366 | 92.10-96.9 | 57.2 | DISC | MP-50 | CPM-68 | 92.10-95.9<br>95.9-96.9 | | DISC<br>DISC | SP-263<br>MP-67 | CPS-263 | 92.10-96.9<br><br><JZX93><br>93.10-96.9 | BH-T595<br><br><br>BH-T691 | (R)BH-T594<br>(L)BH-T594<br><br>(R)BH-T594<br>(L)BH-T594 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (3000) | E−JZX91 | | 92.10-94.7<br>94.7-96.9 | 1<br>1 | | TK-T366<br>TK-T366 | 92.10-96.9 | 57.2 | DISC | MP-50 | CPM-68 | 92.10-95.9<br>95.9-96.9 | | DISC<br>DISC | SP-263<br>MP-67 | CPS-263 | 92.10-96.9 | BH-T595 | (R)BH-T594<br>(L)BH-T594 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CRESTA : 100 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000) | E－GX100<br>＜GF－は98．8～＞ | | 96.9-01.6 | 1 | | TK-T412 | 96.9-98.8<br>98.8-01.6 | | DISC<br>DISC | SP-204<br>SP-102 | CPS-204<br>CPS-102 | 96.9-01.6 | | DISC | SP-295 | CPS-295 | 96.9-01.6 | BH-T595 | (R)BH-T594<br>(L)BH-T594 | 96.9-01.6 | 5/8 | | MK-T244 | 96.9-01.6 | 13/16 | | CK-T201 |
| | GF－GX105（4WD） | | 98.8-01.6 | 1 | | TK-T412 | 98.8-01.6 | | DISC | MP-72 | CPM-121 | 98.8-01.6 | | DISC | MP-73 | | 98.8-01.6 | BH-T691 | (R)BH-T594<br>(L)BH-T594 | | | (オートマチック) | | | | | |
| (2400ディーゼル) | KD－LX100 | | 96.9-99.8 | 1 | | TK-T377 | 96.9-98.8<br>98.8-99.8 | | DISC<br>DISC | SP-204<br>SP-102 | CPS-204<br>CPS-102 | 96.9-99.8 | | DISC | SP-295 | CPS-295 | 96.9-99.8 | BH-T595 | (R)BH-T594<br>(L)BH-T594 | | | (オートマチック) | | | | |
| (2500) | E－JZX100<br>＜GF－は98．8～＞ | ターボ無 | 96.9-01.6<br><VSC付><br>98.6-01.6 | 1<br><br>1 | | TK-T412<br><br>TK-T431 | 96.9-01.6 | | DISC | MP-72 | CPM-121 | 96.9-01.6 | | DISC | MP-73 | | 96.9-01.6 | BH-T595 | (R)BH-T594<br>(L)BH-T594 | | | (オートマチック) | | | | |
| | | ターボ車 | 96.9-01.6 | 1 | | TK-T412 | 96.9-01.6 | 44.4 | DISC | MP-47 | CPM-77 | 96.9-01.6 | | DISC | SP-293 | CPS-293 | 96.9-01.6 | BH-T595 | (R)BH-T594<br>(L)BH-T594 | | | (オートマチック) | | | | |
| | E－JZX105（4WD）<br>＜GF－は98．8～＞ | | 96.9-01.6 | 1 | | TK-T412 | 96.9-01.6 | | DISC | MP-72 | CPM-121 | 96.9-01.6 | | DISC | MP-73 | | 96.9-01.6 | BH-T691 | (R)BH-T594<br>(L)BH-T594 | | | (オートマチック) | | | | |
| (3000) | E－JZX101<br>＜GF－は98．8～＞ | | 96.9-98.6<br>98.6-01.6 | <br>1 | | <br>TK-T431 | 96.9-01.6 | | DISC | MP-72 | CPM-121 | 96.9-01.6 | | DISC | MP-73 | | 96.9-98.8<br><br>98.8-01.6 | BH-T595<br><br>BH-T595 | (R)<br>(L)<br>(R)BH-T594<br>(L)BH-T594 | | | (オートマチック) | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| VEROSSA : 110 ser.(01.6-) | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000) | TA－GX110 | | 01.6- | | | | 01.6- | | DISC | MP-121 | CPM-112 | 01.6- | | DISC | MP-79 | CPM-79 | 01.6- | BH-T830 | (R)BH-T864<br>(L)BH-T864 | | | (オートマチック) | | | | | |
| | TA－GX115(4WD) | | 01.6- | | | | 01.6- | | DISC | MP-121 | CPM-121 | 01.6- | | DISC | MP-79 | CPM-79 | 01.6- | BH-T691 | (R)BH-T864<br>(L)BH-T864 | | | (オートマチック) | | | | | |
| (2500) | TA－JZX110 | ターボ無 | 01.6-<br><VSC付><br>01.6- | | | | 01.6- | | DISC | MP-121 | CPM-112 | 01.6- | | DISC | MP-79 | CPM-79 | 01.6- | BH-T830 | (R)BH-T864<br>(L)BH-T864 | | | (オートマチック) | | | | | |
| | GH－JZX110 | ターボ車 | 01.6-<br><VSC付><br>01.6- | | | | 01.6- | | DISC | MP-77 | CPM-77 | 01.6- | | DISC | MP-79 | CPM-79 | 01.6- | BH-T830 | (R)BH-T864<br>(L)BH-T864 | 01.6- | 5/8 | | MK-T244 | 01.6- | 7/8 | | CK-T223 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CELICA XX : 40, 50 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000) | MA45 | L(リヤードラム) | 78.4-81.6 | 7/8 | | TK-9337 | 78.4-80.8<br>80.8-81.6 | 2 1/8<br>2 1/8 | DISC<br>DISC | A-42P<br>A-57P | | 78.4-81.6 | 7/8 | (R)WC-50035<br>(L)WC-50035 | WK-545 | CUP | 78.4-78.8<br><br>78.8-81.6 | (1)<br>(2)BH-02224<br>(1)<br>(2)BH-02224 | BH-T822<br><br>BH-02394 | 78.4-81.6 | 5/8 | MC-10077 | MK-4300 | 78.4-81.1<br>81.1-81.6 | 13/16<br>13/16 | CC-70112<br>CC-70112 | CK-3113<br>CK-3144 |
| | | L(四輪ディスク)<br>S・G | 78.4-81.6 | 7/8 | | TK-9337 | 78.4-80.8<br>80.8-81.6 | 2 1/8<br>2 1/8 | DISC<br>DISC | A-42P<br>A-57P | | 78.4-81.6 | 1 1/2 | DISC | A-73P<br>A-46LP | | 78.4-78.8<br><br>78.8-81.6 | (1)<br>(2)BH-02224<br>(1)<br>(2)BH-02224 | (C)BH-T822<br>(R)BH-31264<br>(L)BH-31264<br>(C)BH-02394<br>(R)BH-31264<br>(L)BH-31264 | 78.4-81.6 | 5/8 | MC-10077 | MK-4300 | 78.4-81.1<br>81.1-81.6 | 13/16<br>13/16 | CC-70112<br>CC-70112 | CK-3113<br>CK-3144 |
| | MA55 | | 80.8-81.6 | 7/8 | | TK-9355 | 80.8-81.6 | 2 1/8 | DISC | A-57P | | 80.8-81.6 | 1 11/16 | DISC | SP-218 | | 80.8-81.6 | (1)<br>(2)BH-02224 | (R-1)BH-95001<br>(L-1)BH-95001<br>(R-2)BH-02343<br>(L-2)BH-02343 | 80.8-81.6 | 5/8 | MC-10077 | MK-4300 | 80.8-81.1<br>81.1-81.6 | 13/16<br>13/16 | CC-70112<br>CC-70112 | CK-3113<br>CK-3144 |
| (2600) | MA46 | | 78.4-80.8 | 7/8 | | TK-9337 | 78.4-80.8 | 2 1/8 | DISC | A-42P | | 78.4-80.8 | 1 1/2 | DISC | A-73P<br>A-46LP | | 78.4-78.8<br><br>78.8-80.8 | (1)<br>(2)BH-02224<br>(1)<br>(2)BH-02224 | (C)BH-T822<br>(R)BH-31264<br>(L)BH-31264<br>(C)BH-02394<br>(R)BH-31264<br>(L)BH-31264 | 78.4-80.8 | 5/8 | MC-10077 | MK-4300 | 78.4-80.8 | 13/16 | CC-70112 | CK-3113 |
| (2800) | MA56 | | 80.8-81.6 | 7/8 | | TK-9355 | 80.8-81.6 | 2 1/8 | DISC | A-57P | | 80.8-81.6 | 1 11/16 | DISC | SP-218 | | 80.8-81.6 | (1)<br>(2)BH-02224 | (R-1)BH-95001<br>(L-1)BH-95001<br>(R-2)BH-02343<br>(L-2)BH-02343 | 80.8-81.6 | 5/8 | MC-10077 | MK-4300 | 80.8-81.1<br>81.1-81.6 | 7/8<br>7/8 | CC-70130<br>CC-70130 | CK-3114<br>CK-3122 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CELICA XX : 60 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000) | E−GA61 | L・S・G | 81.7-85.12 | 15/16 | | TK-9417 | 81.7-85.12 | 2 1/4 | DISC | SP-229 | | 81.7-82.5 | 1 11/16 | DISC | SP-218 | | 81.7-85.4 | (1)BH-02424<br>(2)BH-96002 | (R-1)BH-95001<br>(L-1)BH-95001<br>(R-2)BH-02343<br>(L-2)BH-02343 | 81.7-83.5<br>83.5-85.12 | 5/8<br>5/8 | MC-10118<br>MC-10138 | MK-4308<br>MK-4308 | 81.7-85.12 | 13/16 | CC-70133 | CK-3144 |
| | | | | | | | | | | | | | | | | | 85.4-85.12 | BH-02475 | (R-1)BH-95001<br>(L-1)BH-95001<br>(R-2)BH-02343<br>(L-2)BH-02343 | | | | | | | | |
| | | GT | 82.8-85.12 | 15/16 | | TK-9417 | 82.8-85.12 | 2 1/4 | DISC | SP-229 | | 82.8-85.12 | 1 11/16 | DISC | SP-218 | | 82.8-85.4 | (1)BH-02424<br>(2)BH-96002 | (R-1)BH-95001<br>(L-1)BH-95001<br>(R-2)BH-02343<br>(L-2)BH-02343 | 82.8-83.5<br>83.5-85.12 | 5/8<br>5/8 | MC-10110<br>MC-10141 | MK-4312<br>MK-4312 | 82.8-85.12 | 13/16 | CC-70133 | CK-3144 |
| | | | | | | | | | | | | | | | | | 85.4-85.12 | BH-02475 | (R-1)BH-95001<br>(L-1)BH-95001<br>(R-2)BH-02343<br>(L-2)BH-02343 | | | | | | | | |
| | E−MA63 | S・G(ターボ) | 82.2-85.12 | 15/16 | | TK-9419 | 82.2-85.12 | 2 1/4 | DISC | SP-229 | | 82.2-85.12 | 1 11/16 | DISC | SP-218 | | 82.2-85.4 | (1)BH-02424<br>(2)BH-96002 | (R-1)BH-95001<br>(L-1)BH-95001<br>(R-2)BH-02343<br>(L-2)BH-02343 | | | (オートマチック) | | | | |
| | | | | | | | | | | | | | | | | | 85.4-85.12 | BH-02475 | (R-1)BH-95001<br>(L-1)BH-95001<br>(R-2)BH-02343<br>(L-2)BH-02343 | | | | | | | |
| (2800) | E−MA61 | GT | 81.7-85.12 | 15/16 | | TK-9417 | 81.7-85.12 | 2 1/4 | DISC | SP-229 | | 81.7-82.5<br>82.5-85.12 | 1 11/16<br>1 11/16 | DISC<br>DISC | SP-218<br>SP-218 | | 81.7-85.4 | (1)BH-02424<br>(2)BH-96002 | (R-1)BH-95001<br>(L-1)BH-95001<br>(R-2)BH-02343<br>(L-2)BH-02343 | 81.7-83.5<br>83.5-85.12 | 5/8<br>5/8 | MC-10074<br>MC-10102 | MK-4300<br>MK-4300 | 81.7-85.12 | 13/16 | CC-70133 | CK-3144 |
| | | | | | | | | | | | | | | | | | 85.4-85.12 | BH-02475 | (R-1)BH-95001<br>(L-1)BH-95001<br>(R-2)BH-02343<br>(L-2)BH-02343 | | | | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| SUPRA : 70 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | <S・G> | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000) | E－GA70 | S・G・GT | 86.2-90.8 | 15/16 | | TK-T017 | 86.2-93.5 | 2 3/8 | DISC | A-226P | CPC-226 | 86.2-93.5 | 1 1/2 | DISC | A-227P | | 86.2-93.5 | BH-02489 | (R)BH-02568 | 86.2-86.12 | 5/8 | | MK-4334 | 86.2-88.8 | 13/16 | CC-70133 | CK-3144 |
| | E－GA70H | GTツインターボ | <GT・GTT> | | | | | | | | | | | | | | | | (L)BH-02568 | 86.12-90.8 | 5/8 | MC-T218 | MK-4357 | 88.8-91.3 | 13/16 | CC-70133 | CK-3144 |
| | | | 86.2-87.1 | 1 | | TK-T018 | | | | | | | | | | | | | | 90.8-93.5 | 5/8 | MC-T302 | | 91.3-93.5 | 13/16 | | CK-T201 |
| | | | 87.1-93.5 | 1 | | TK-T034 | | | | | | | | | | | | | | | | | | <GTT> | | | |
| | | | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | | | | | | | | | | | 86.2-88.8 | 13/16 | CC-70133 | CK-3144 |
| | | | 87.1-90.8 | 1 | | TK-T019 | | | | | | | | | | | | | | | | | | 88.8-91.3 | 13/16 | | CK-3144 |
| | | | 90.8-93.5 | 1 | | TK-T343 | | | | | | | | | | | | | | | | | | 91.3-93.5 | 13/16 | | CK-T201 |
| (2500) | E－JZA70 | GTツインターボ | 90.8-93.5 | 1 | | TK-T034 | 90.8-93.5 | 2 3/8 | DISC | A-226P | CPC-226 | 90.8-93.5 | 1 1/2 | DISC | A-227P | | 90.8-93.5 | BH-02489 | (R)BH-02568 | 90.8-93.5 | 5/8 | MC-T382 | | 90.8-93.5 | 7/8 | CC-70181 | CK-3143 |
| | | GTツインターボR | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | | | | | | (L)BH-02568 | | | | | | | | |
| | | GTツインターボリミテッド | 90.8-93.5 | 1 | | TK-T343 | | | | | | | | | | | | | | | | | | | | | |
| (3000) | E－MA70 | GTターボ | 86.2-87.1 | 1 | | TK-T018 | 86.2-90.8 | 2 3/8 | DISC | A-226P | CPC-226 | 86.2-90.8 | 1 1/2 | DISC | A-227P | | 86.2-90.8 | BH-02489 | (R)BH-02568 | 86.2-90.8 | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | | GTリミテッド | 87.1-90.8 | 1 | | TK-T034 | | | | | | | | | | | | | (L)BH-02568 | 87.1-90.8 | 5/8 | MC-T382 | MK-4357 | 87.1-90.8 | 7/8 | CC-70181 | CK-3143 |
| | | GTターボリミテッド | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | 86.2-90.8 | 1 | | TK-T019 | | | | | | | | | | | | | | | | | | | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| SUPRA : 80 ser.(93.5-) | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | <GZ,RZS,SZ> | | | | | | | <5速車> | | | |
| (3000) E－JZA80 | 93.5-02.8 | 1 | | TK-T412 | 93.5-02.8 | 1 3/4 | DISC | A-413P | | 93.5-94.11 | 42.8 | DISC | MP-43 | | 93.5-02.8 | (R)BH-T555 | (R)BH-T619 | 93.5-94.3 | 5/8 | | | 93.5-02.8 | 13/16 | | CK-T201 |
| ＜GFーは99．8～＞ | <17インチホイール> | | | | <17インチホイール> | | | | | 94.1-02.8 | 42.8 | DISC | MP-43 | | | (L)BH-T556 | (L)BH-T619 | 94.3-02.8 | 5/8 | | | <6速車> | | | |
| | 94.8-96.5 | 1 | | TK-T412 | 94.8-02.8 | | DISC | SP-272 | | <17インチホイール> | | | | | <RZ,SZR> | | | | | | | 93.5-02.8 | 7/8 | | CK-T207 |
| | 96.5-98.3 | 1 1/16 | | TK-T332 | | | | | | 94.8-02.8 | | DISC | SP-289 | | 93.5-97.9 | (R)BH-T555 | (R)BH-T619 | | | | | <SZR6速車> | | | |
| | 98.3-02.8 | 1 1/16 | | TK-T437 | | | | | | | | | | | | (L)BH-T556 | (L)BH-T619 | | | | | 96.5-02.8 | 13/16 | | CK-T227 |
| | | | | | | | | | | | | | | | 97.9-02.8 | (R) | (R)BH-T619 | | | | | | | | |
| | | | | | | | | | | | | | | | | (L) | (L)BH-T619 | | | | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| SUPRA : DB ser.(2019.3-) | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000) | 3BA－DB22 | 19.3- | | | ｷｯﾄｾｯﾃｲﾅｼ | <ｷｬﾘﾊﾟｰﾚｯﾄﾞ塗装有><br>19.3- | | DISC | ｾｯﾃｲﾅｼ | (R)<br>(L) | <ｷｬﾘﾊﾟｰﾚｯﾄﾞ塗装有><br>19.3- | | DISC | | ｾｯﾃｲﾅｼ | 19.3- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | | | | | | <ｷｬﾘﾊﾟｰﾚｯﾄﾞ塗装無><br>19.3- | | DISC | ｾｯﾃｲﾅｼ | (R)<br>(L) | <ｷｬﾘﾊﾟｰﾚｯﾄﾞ塗装無><br>19.3- | | DISC | | ｾｯﾃｲﾅｼ | | | | | | | | | | | |
| | 3BA－DB82 | 19.3- | | | ｷｯﾄｾｯﾃｲﾅｼ | 19.3- | | DISC | | (R)<br>(L) | 19.3- | | DISC | | ｾｯﾃｲﾅｼ | 19.3- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (3000) | 3BA－DB42 | 19.3- | | | ｷｯﾄｾｯﾃｲﾅｼ | <ｷｬﾘﾊﾟｰﾚｯﾄﾞ塗装有><br>19.3- | | DISC | ｾｯﾃｲﾅｼ | (R)<br>(L) | <ｷｬﾘﾊﾟｰﾚｯﾄﾞ塗装有><br>19.3- | | DISC | | ｾｯﾃｲﾅｼ | 19.3- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | | | | | | <ｷｬﾘﾊﾟｰﾚｯﾄﾞ塗装無><br>19.3- | | DISC | ｾｯﾃｲﾅｼ | (R)<br>(L) | <ｷｬﾘﾊﾟｰﾚｯﾄﾞ塗装無><br>19.3- | | DISC | | ｾｯﾃｲﾅｼ | | | | | | | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| BLADE : 150 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2400) | DBA－AZE156H | | 06.12- | | | | 06.12- | | DISC | MP-114 | CPM-106 | 06.12- | | DISC | TP-111 | | 06.12- | | | | | (オートマチック) | | | | | |
| | DBA－AZE154H | 4WD | 06.12- | | | | 06.12- | | DISC | MP-114 | CPM-106 | 06.12- | | DISC | TP-111 | | 06.12- | | | | | (オートマチック) | | | | | |
| (3500) | DBA－GRE156H | | 07.8- | | | | 07.8- | | DISC | SP-135 | CPM-106 | 07.8- | | DISC | TP-111 | | 07.8- | | | | | (オートマチック) | | | | | |

| Models | TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CELICA : 20, 35 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1400) | TA20 | ドラム車 | 70.12-73.9<br>73.9-75.9 | 11/16<br>13/16 | | MK-3048<br>TK-9331 | 70.12-73.9<br><br><br><br><br>73.9-75.9 | 15/16<br><br><br><br><br>7/8 | (R-1)WC-1066<br>(R-2)WC-2056<br>(L-1)WC-3066<br>(L-2)WC-4056<br>(R-1)WC-51000<br>(R-2)WC-52000<br>(L-1)WC-53000<br>(L-2)WC-54000 | WK-082<br><br><br><br><br>WK-054 | CUP<br><br><br><br><br>CUP | 70.12-75.9 | 11/16 | (R)WC-50041<br>(L)WC-50041 | WK-083 | CUP | 70.12-75.9 | | BH-T822 | 70.12-75.9 | 5/8 | MC-10046 | MK-4300 | 7012-7312<br>73.12-75.9 | 3/4<br>3/4 | CC-14011<br>CC-14012 | CK-41480<br>CK-3108 |
| | | ディスク車 | 70.12-75.9 | 13/16 | | TK-9314 | 70.12-74.1<br>74.1-75.9 | 1 7/8<br>2 | DISC<br>DISC | C-16<br>A-16P | | 70.12-75.9 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 70.12-75.9 | (1)<br>(2)BH-02163 | BH-T822 | 70.12-75.9 | 5/8 | MC-10046 | MK-4300 | 7012-7312<br>73.12-75.9 | 3/4<br>3/4 | CC-14011<br>CC-14012 | CK-41480<br>CK-3108 |
| (1600) | TA22・27 | | 70.12-75.9 | 13/16 | | TK-9314 | 70.12-74.1<br>74.1-75.9 | 1 7/8<br>2 | DISC<br>DISC | C-16<br>A-16P | | 70.12-75.9 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 70.12-75.9 | (1)<br>(2)BH-02163 | BH-T822 | 70.12-75.9 | 5/8 | MC-10046 | MK-4300 | 7012-7312<br>73.12-75.9 | 3/4<br>3/4 | CC-14011<br>CC-14012 | CK-41480<br>CK-3108 |
| | TA23・28 | | 75.10-76.4 | 13/16 | | TK-9346 | 75.10-76.4 | 2 | DISC | A-16P | | 75.10-76.4 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 75.10-76.4 | (1)<br>(2)BH-02224 | BH-T822 | 75.10-76.4 | 5/8 | MC-10046 | MK-4300 | 75.10-76.4 | 3/4 | CC-70102 | CK-3108 |
| | TA35 | | 76.5-77.7 | 13/16 | | TK-9346 | 76.5-77.7 | 2 | DISC | A-16P | | 76.5-77.7 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 76.5-77.7 | (1)<br>(2)BH-02224 | BH-T822 | 76.5-77.7 | 5/8 | MC-10046 | MK-4300 | 76.5-77.7 | 3/4 | CC-70102 | CK-3108 |
| (2000) | RA21・25 | ET・LT・ST | 73.4-75.9 | 13/16 | | TK-9314 | 73.4-75.9 | 2 | DISC | A-16P | | 73.4-75.9 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 73.4-75.9 | (1)<br>(2)BH-02163 | BH-T822 | 73.4-75.9 | 5/8 | MC-10046 | MK-4300 | 73.4-73.8<br>73.8-75.9 | 3/4<br>3/4 | CC-70071<br>CC-70090 | CK-41480<br>CK-3108 |
| | | GT | 73.4-75.9 | 13/16 | | TK-9314 | 73.4-75.9 | 2 | DISC | A-16P | | 73.4-75.9 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 73.4-75.9 | (1)<br>(2)BH-02163 | BH-T822 | 73.4-75.9 | 5/8 | MC-10047 | MK-4300 | 73.4-73.8<br>73.8-75.9 | 3/4<br>3/4 | CC-70071<br>CC-70090 | CK-41480<br>CK-3108 |
| | RA23・28 | | 75.10-77.1 | 13/16 | | TK-9346 | 75.10-77.1 | 2 | DISC | A-16P | | 75.10-77.1 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 75.10-77.1 | (1)<br>(2)BH-02224 | BH-T822 | 75.10-77.1 | 5/8 | MC-10046 | MK-4300 | 75.10-77.1 | 3/4 | CC-70102 | CK-3108 |
| | RA35 | LT・ST | 76.6-77.7 | 13/16 | | TK-9346 | 76.6-77.7 | 2 | DISC | A-16P | | 76.6-77.7 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 76.6-77.7 | (1)<br>(2)BH-02224 | BH-T822 | 76.6-77.7 | 5/8 | MC-10046 | MK-4300 | 76.6-77.7 | 3/4 | CC-70102 | CK-3108 |
| | | GT・GTV | 77.1-77.7 | 13/16 | | TK-9346 | 77.1-77.7 | 2 | DISC | A-16P | | 77.1-77.7 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 76.6-77.1 | (1)<br>(2)BH-02224 | BH-T822 | 76.6-77.7 | 5/8 | MC-10046 | MK-4300 | 76.6-77.7 | 3/4 | CC-70102 | CK-3108 |
| | | GT・GTV(リフトバック) | 77.1-77.7 | 13/16 | | TK-9346 | 77.1-77.7 | 2 | DISC | C-16P | | 77.1-77.7 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 76.6-77.7 | (1)<br>(2)BH-02224 | BH-T822 | 76.6-77.7 | 5/8 | MC-10046 | MK-4300 | 76.6-77.7 | 3/4 | CC-70102 | CK-3108 |

| Models | TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CELICA : 40, 50 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1600) | TA40 | リヤードラム | 77.8-78.5 | 13/16 | | TK-9346 | 77.8-78.5 | 2 | DISC | A-16P | | 77.8-78.5 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 77.8-78.5 | (1)<br>(2)BH-02224 | BH-T822 | 77.8-78.4<br>78.4-78.5 | 5/8<br>5/8 | MC-10046<br>MC-10077 | MK-4300<br>MK-4300 | 77.8-78.5 | 13/16 | CC-70110 | CK-3113 |
| | | 四輪ディスク | 77.8-78.5 | 13/16 | | TK-9346 | 77.8-78.5 | 2 | DISC | A-16P | | 77.8-78.5 | 1 3/8 | DISC | A-43P<br>A-46LP | | 77.8-78.5 | (1)<br>(2)BH-02224 | (C)BH-T822<br>(R)BH-02377<br>(L)BH-02377 | 77.8-78.4<br>78.4-78.5 | 5/8<br>5/8 | MC-10046<br>MC-10077 | MK-4300<br>MK-4300 | 77.8-78.5 | 13/16 | CC-70110 | CK-3113 |
| | | フロント14"ディスク | 77.8-78.5 | 13/16 | | TK-9346 | 77.8-78.5 | 2 | DISC | C-16P | | 77.8-78.5 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 77.8-78.5 | (1)<br>(2)BH-02224 | BH-T822 | 77.8-78.4<br>78.4-78.5 | 5/8<br>5/8 | MC-10046<br>MC-10077 | MK-4300<br>MK-4300 | 77.8-78.5 | 13/16 | CC-70110 | CK-3113 |
| | TA41 | リヤードラム | 77.8-81.6 | 13/16 | | TK-9346 | 77.8-81.6 | 2 | DISC | A-16P | | 77.8-81.6 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 77.8-78.8<br><br>78.8-81.6 | (1)<br>(2)BH-02224<br>(1)<br>(2)BH-02224 | BH-T822<br><br>BH-02394 | 77.8-78.4<br>78.4-79.2<br>79.2-81.6 | 5/8<br>5/8<br>5/8 | MC-10046<br>MC-10077<br>MC-10094 | MK-4300<br>MK-4300<br>MK-4308 | 77.8-80.8<br>80.8-81.1<br>81.1-81.6 | 13/16<br>13/16<br>13/16 | CC-70110<br>CC-70111<br>CC-70111 | CK-3113<br>CK-3113<br>CK-3144 |
| | | 四輪ディスク | 77.8-81.6 | 13/16 | | TK-9346 | 77.8-81.6 | 2 | DISC | A-16P | | 77.8-81.6 | 1 3/8 | DISC | A-43P<br>A-46LP | | 77.8-78.8<br><br>78.8-81.6 | (1)<br>(2)BH-02224<br><br>(1)<br>(2)BH-02224 | (C)BH-T822<br>(R)BH-02377<br>(L)BH-02377<br>(C)BH-02394<br>(R)BH-02377<br>(L)BH-02377 | 77.8-78.4<br>78.4-79.2<br>79.2-81.6 | 5/8<br>5/8<br>5/8 | MC-10046<br>MC-10077<br>MC-10094 | MK-4300<br>MK-4300<br>MK-4308 | 77.8-80.8<br>80.8-81.1<br>81.1-81.6 | 13/16<br>13/16<br>13/16 | CC-70110<br>CC-70111<br>CC-70111 | CK-3113<br>CK-3113<br>CK-3144 |
| | TA45 | GTR(リヤードラム) | 78.11-81.6 | 13/16 | | TK-9346 | 78.11-81.6 | 2 | DISC | A-16P | | 78.11-81.6 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 78.11-81.6 | (1)<br>(2)BH-02224 | BH-02394 | 78.11-79.2<br>79.2-81.6 | 5/8<br>5/8 | MC-10077<br>MC-10094 | MK-4300<br>MK-4308 | 78.11-80.8<br>80.8-81.1<br>81.1-81.6 | 13/16<br>13/16<br>13/16 | CC-70110<br>CC-70111<br>CC-70111 | CK-3113<br>CK-3113<br>CK-3144 |
| | | GTR(フロント14"ディスク) | 78.11-81.6 | 13/16 | | TK-9346 | 78.11-80.8<br>80.8-81.6 | 2 1/8<br>2 1/8 | DISC<br>DISC | A-42P<br>A-57P | | 78.11-81.6 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 78.11-81.6 | (1)<br>(2)BH-02224 | BH-02394 | 78.11-79.2<br>79.2-81.6 | 5/8<br>5/8 | MC-10077<br>MC-10094 | MK-4300<br>MK-4308 | 78.11-80.8<br>80.8-81.1<br>81.1-81.6 | 13/16<br>13/16<br>13/16 | CC-70110<br>CC-70111<br>CC-70111 | CK-3113<br>CK-3113<br>CK-3144 |
| | | GT・GTV・GTR<br>四輪ディスク | 78.5-81.6 | 13/16 | | TK-9346 | 78.5-81.6 | 2 | DISC | A-16P | | 78.5-81.6 | 1 3/8 | DISC | A-43P<br>A-46LP | | 78.5-78.8<br><br>78.8-81.6 | (1)<br>(2)BH-02224<br><br>(1)<br>(2)BH-02224 | (C)BH-T822<br>(R)BH-02377<br>(L)BH-02377<br>(C)BH-02394<br>(R)BH-02377<br>(L)BH-02377 | 78.5-79.2<br>79.2-81.6 | 5/8<br>5/8 | MC-10077<br>MC-10094 | MK-4300<br>MK-4308 | 78.5-80.8<br>80.8-81.1<br>81.1-81.6 | 13/16<br>13/16<br>13/16 | CC-70110<br>CC-70111<br>CC-70111 | CK-3113<br>CK-3113<br>CK-3144 |
| (1600) | TA45 | GT・GTV・GTR<br>四輪14"ディスク | 78.5-81.6 | 7/8 | | TK-9337 | 78.5-80.8<br>80.8-81.6 | 2 1/8<br>2 1/8 | DISC<br>DISC | A-42P<br>A-57P | | 78.5-81.6 | 1 1/2 | DISC | A-73P<br>A-46LP | | 78.5-78.8<br><br>78.8-81.6 | (1)<br>(2)BH-02224<br><br>(1)<br>(2)BH-02224 | (C)BH-T822<br>(R)BH-31264<br>(L)BH-31264<br>(C)BH-02394<br>(R)BH-31264<br>(L)BH-31264 | 78.5-79.2<br>79.2-81.6 | 5/8<br>5/8 | MC-10077<br>MC-10094 | MK-4300<br>MK-4308 | 78.5-80.8<br>80.8-81.1<br>81.1-81.6 | 13/16<br>13/16<br>13/16 | CC-70110<br>CC-70111<br>CC-70111 | CK-3113<br>CK-3113<br>CK-3144 |
| | TA55 | GT | 80.8-81.6 | 7/8 | | TK-9355 | 80.8-81.6 | 2 1/8 | DISC | A-57P | | 80.8-81.6 | 1 11/16 | DISC | SP-218 | | 80.8-81.6 | (1)<br>(2)BH-02224 | (R-1)BH-95001<br>(L-1)BH-95001<br>(R-2)BH-02343<br>(L-2)BH-02343 | 80.8-81.6 | 5/8 | MC-10094 | MK-4308 | 80.8-81.1<br>81.1-81.6 | 13/16<br>13/16 | CC-70111<br>CC-70111 | CK-3113<br>CK-3144 |
| (1800) | TA42 | リヤードラム | 77.8-78.5 | 13/16 | | TK-9346 | 77.8-78.5 | 2 | DISC | A-16P | | 77.8-78.5 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 77.8-78.5 | (1)<br>(2)BH-02224 | BH-T822 | 77.8-77.11<br>77.11-78.5 | 5/8 | MC-10046<br>(オートマチック) | MK-4300 | 77.8-77.11 | 13/16 | CC-70110 | CK-3113 |
| | | 四輪ディスク | 77.8-78.5 | 13/16 | | TK-9346 | 77.8-78.5 | 2 | DISC | A-16P | | 77.8-78.5 | 1 3/8 | DISC | A-43P<br>A-46LP | | 77.8-78.5 | (1)<br>(2)BH-02224 | (C)BH-T822<br>(R)BH-02377<br>(L)BH-02377 | 77.8-77.11<br>77.11-78.5 | 5/8 | MC-10046<br>(オートマチック) | MK-4300 | 77.8-77.11 | 13/16 | CC-70110 | CK-3113 |
| | TA46 | リヤードラム | 77.11-81.6 | 13/16 | | TK-9346 | 77.11-81.6 | 2 | DISC | A-16P | | 77.11-81.6 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 77.11-78.8<br><br>78.8-81.6 | (1)<br>(2)BH-02224<br>(1)<br>(2)BH-02224 | BH-T822<br><br>BH-02394 | 77.11-78.4<br>78.4-79.2<br>79.2-81.6 | 5/8<br>5/8<br>5/8 | MC-10046<br>MC-10077<br>MC-10094 | MK-4300<br>MK-4300<br>MK-4308 | 77.11-80.8<br>80.8-81.1<br>81.1-81.6 | 13/16<br>13/16<br>13/16 | CC-70110<br>CC-70111<br>CC-70111 | CK-3113<br>CK-3113<br>CK-3144 |
| | | 四輪ディスク | 77.11-81.6 | 13/16 | | TK-9346 | 77.11-81.6 | 2 | DISC | A-16P | | 77.11-81.6 | 1 3/8 | DISC | A-43P<br>A-46LP | | 77.11-78.8<br><br>78.8-81.6 | (1)<br>(2)BH-02224<br><br>(1)<br>(2)BH-02224 | (C)BH-T822<br>(R)BH-02377<br>(L)BH-02377<br>(C)BH-02394<br>(R)BH-02377<br>(L)BH-02377 | 77.11-78.4<br>78.4-79.2<br>79.2-81.6 | 5/8<br>5/8<br>5/8 | MC-10046<br>MC-10077<br>MC-10094 | MK-4300<br>MK-4300<br>MK-4308 | 77.11-80.8<br>80.8-81.1<br>81.1-81.6 | 13/16<br>13/16<br>13/16 | CC-70110<br>CC-70111<br>CC-70111 | CK-3113<br>CK-3113<br>CK-3144 |
| | TA47 | リヤードラム | 78.8-81.6 | 13/16 | | TK-9346 | 78.8-81.6 | 2 | DISC | A-16P | | 78.8-81.6 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 78.8-81.6 | (1)<br>(2)BH-02224 | BH-02394 | 78.8-79.2<br>79.2-81.6 | 5/8<br>5/8 | MC-10077<br>MC-10094 | MK-4300<br>MK-4308 | 78.8-81.1<br>81.1-81.6 | 13/16<br>13/16 | CC-70109<br>CC-70109 | CK-3113<br>CK-3144 |
| | | 四輪ディスク | 78.8-81.6 | 13/16 | | TK-9346 | 78.8-81.6 | 2 | DISC | A-16P | | 78.8-81.6 | 1 3/8 | DISC | A-43P<br>A-46LP | | 78.8-81.6 | (1)<br>(2)BH-02224 | (C)BH-02394<br>(R)BH-02377<br>(L)BH-02377 | 78.8-79.2<br>79.2-81.6 | 5/8<br>5/8 | MC-10077<br>MC-10094 | MK-4300<br>MK-4308 | 78.8-81.1<br>81.1-81.6 | 13/16<br>13/16 | CC-70109<br>CC-70109 | CK-3113<br>CK-3144 |
| (2000) | RA40 | ST・XT・SE<br>リヤードラム | 77.8-78.8 | 13/16 | | TK-9346 | 77.8-78.8 | 2 | DISC | A-16P | | 77.8-78.8 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 77.8-78.8 | (1)<br>(2)BH-02224 | BH-T822 | 77.8-78.4<br>78.4-78.8 | 5/8<br>5/8 | MC-10046<br>MC-10077 | MK-4300<br>MK-4300 | 77.8-78.8 | 13/16 | CC-70113 | CK-3113 |
| | | 四輪ディスク | 77.8-78.8 | 13/16 | | TK-9346 | 77.8-78.8 | 2 | DISC | A-16P | | 77.8-78.8 | 1 3/8 | DISC | A-43P<br>A-46LP | | 77.8-78.8 | (1)<br>(2)BH-02224 | (C)BH-T822<br>(R)BH-02377<br>(L)BH-02377 | 77.8-78.4<br>78.4-78.8 | 5/8<br>5/8 | MC-10046<br>MC-10077 | MK-4300<br>MK-4300 | 77.8-78.8 | 13/16 | CC-70113 | CK-3113 |
| | | GT・GTV<br>リヤードラム | 77.8-78.5 | 13/16 | | TK-9346 | 77.8-78.5 | 2 | DISC | A-16P | | 77.8-78.5 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 77.8-78.5 | (1)<br>(2)BH-02224 | BH-T822 | 77.8-78.4<br>78.4-78.5 | 5/8<br>5/8 | MC-10046<br>MC-10077 | MK-4300<br>MK-4300 | 77.8-78.5 | 13/16 | CC-70113 | CK-3113 |

| Models | TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | 四輪ディスク | 77.8-78.8 | 13/16 | | TK-9346 | 77.8-78.8 | 2 | DISC | A-16P | | 77.8-78.8 | 1 3/8 | DISC | A-43P<br>A-46LP | | 77.8-78.8 | (1)<br>(2)BH-02224 | (C)BH-T822<br>(R)BH-02377<br>(L)BH-02377 | 77.8-78.4<br>78.4-78.8 | 5/8<br>5/8 | MC-10046<br>MC-10077 | MK-4300<br>MK-4300 | 77.8-78.8 | 13/16 | CC-70113 | CK-3113 |
| | | フロント14"ディスク | 77.8-78.5 | 13/16 | | TK-9346 | 77.8-78.5 | 2 | DISC | C-16P | | 77.8-78.5 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 77.8-78.5 | (1)<br>(2)BH-02224 | BH-T822 | 77.8-78.4<br>78.4-78.5 | 5/8<br>5/8 | MC-10046<br>MC-10077 | MK-4300<br>MK-4300 | 77.8-78.5 | 13/16 | CC-70113 | CK-3113 |
| | | 四輪14"ディスク | 78.5-78.8 | 7/8 | | TK-9337 | 78.5-78.8 | 2 1/8 | DISC | A-42P | | 78.5-78.8 | 1 1/2 | DISC | A-73P<br>A-46LP | | 78.5-78.8 | (1)<br>(2)BH-02224 | (C)BH-T822<br>(R)BH-31264<br>(L)BH-31264 | 78.5-78.8 | 5/8 | MC-10077 | MK-4300 | 78.5-78.8 | 13/16 | CC-70113 | CK-3113 |
| | RA45 | GTR<br>リヤードラム | 78.8-81.6 | 13/16 | | TK-9346 | 78.8-81.6 | 2 | DISC | A-16P | | 78.8-81.6 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 78.8-81.6 | (1)<br>(2)BH-02224 | BH-02394 | 78.8-79.2<br>79.2-81.6 | 5/8<br>5/8 | MC-10077<br>MC-10094 | MK-4300<br>MK-4308 | 78.8-80.8<br>80.8-81.1<br>81.1-81.6 | 13/16<br>13/16<br>13/16 | CC-70111<br>CC-70110<br>CC-70110 | CK-3113<br>CK-3113<br>CK-3144 |
| | | フロント14"ディスク | 78.8-81.6 | 13/16 | | TK-9346 | 78.8-80.8<br>80.8-81.6 | 2 1/8<br>2 1/8 | DISC<br>DISC | A-42P<br>A-57P | | 78.8-81.6 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 78.8-81.6 | (1)<br>(2)BH-02224 | BH-02394 | 78.8-79.2<br>79.2-81.6 | 5/8<br>5/8 | MC-10077<br>MC-10094 | MK-4300<br>MK-4308 | 78.8-80.8<br>80.8-81.1<br>81.1-81.6 | 13/16<br>13/16<br>13/16 | CC-70111<br>CC-70110<br>CC-70110 | CK-3113<br>CK-3113<br>CK-3144 |
| | | GT・GTR<br>四輪ディスク | 78.8-81.6 | 13/16 | | TK-9346 | 78.8-81.6 | 2 | DISC | A-16P | | 78.8-81.6 | 1 3/8 | DISC | A-43P<br>A-46LP | | 78.8-81.6 | (1)<br>(2)BH-02224 | (C)BH-02394<br>(R)BH-02377<br>(L)BH-02377 | 78.8-79.2<br>79.2-81.6 | 5/8<br>5/8 | MC-10077<br>MC-10094 | MK-4300<br>MK-4308 | 78.8-80.8<br>80.8-81.1<br>81.1-81.6 | 13/16<br>13/16<br>13/16 | CC-70111<br>CC-70110<br>CC-70110 | CK-3113<br>CK-3113<br>CK-3144 |
| | | 四輪14"ディスク | 78.8-81.6 | 7/8 | | TK-9337 | 78.8-80.8<br>80.8-81.6 | 2 1/8<br>2 1/8 | DISC<br>DISC | A-42P<br>A-57P | | 78.8-81.6 | 1 1/2 | DISC | A-73P<br>A-46LP | | 78.8-81.6 | (1)<br>(2)BH-02224 | (C)BH-02394<br>(R)BH-31264<br>(L)BH-31264 | 78.8-79.2<br>79.2-81.6 | 5/8<br>5/8 | MC-10077<br>MC-10094 | MK-4300<br>MK-4308 | 78.8-80.8<br>80.8-81.1<br>81.1-81.6 | 13/16<br>13/16<br>13/16 | CC-70111<br>CC-70110<br>CC-70110 | CK-3113<br>CK-3113<br>CK-3144 |
| (2000) | RA46 | リヤードラム | 78.8-81.6 | 13/16 | | TK-9346 | 78.8-81.6 | 2 | DISC | A-16P | | 78.8-81.6 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 78.8-81.6 | (1)<br>(2)BH-02224 | BH-02394 | 78.8-79.2<br>79.2-81.6 | 5/8<br>5/8 | MC-10077<br>MC-10094 | MK-4300<br>MK-4308 | 78.8-80.8<br>80.8-81.1<br>81.1-81.6 | 13/16<br>13/16<br>13/16 | CC-70111<br>CC-70110<br>CC-70110 | CK-3113<br>CK-3113<br>CK-3144 |
| | | 四輪ディスク | 78.8-81.6 | 13/16 | | TK-9346 | 78.8-81.6 | 2 | DISC | A-16P | | 78.8-81.6 | 1 3/8 | DISC | A-43P<br>A-46LP | | 78.8-81.6 | (1)<br>(2)BH-02224 | (C)BH-02394<br>(R)BH-02377<br>(L)BH-02377 | 78.8-79.2<br>79.2-81.6 | 5/8<br>5/8 | MC-10077<br>MC-10094 | MK-4300<br>MK-4308 | 78.8-80.8<br>80.8-81.1<br>81.1-81.6 | 13/16<br>13/16<br>13/16 | CC-70111<br>CC-70110<br>CC-70110 | CK-3113<br>CK-3113<br>CK-3144 |
| | RA55 | GT | 80.8-81.6 | 13/16 | | TK-9355 | 80.8-81.6 | 2 1/8 | DISC | A-57P | | 80.8-81.6 | 1 11/16 | DISC | SP-218 | | 80.8-81.6 | (1)<br>(2)BH-02224 | (R-1)BH-95001<br>(L-1)BH-95001<br>(R-2)BH-02343<br>(L-2)BH-02343 | 80.8-81.6 | 5/8 | MC-10094 | MK-4308 | 80.8-81.1<br>81.1-81.6 | 13/16<br>13/16 | CC-70110<br>CC-70110 | CK-3113<br>CK-3144 |

| Models | TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CELICA : 60 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1600) | E−TA61 | GT | 81.7-83.8 | 15/16 | | TK-9417 | 81.7-83.8 | 2 1/4 | DISC | SP-229 | CPS-219 | 81.7-82.5<br>82.5-83.8 | 1 11/16<br>1 11/16 | DISC<br>DISC | SP-218<br>SP-218 | | 81.7-83.8 | (1)BH-02426<br>(2)BH-96001 | (R-1)BH-95001<br>(L-1)BH-95001<br>(R-2)BH-02343<br>(L-2)BH-02343 | 81.7-83.5<br>83.5-83.8 | 5/8<br>5/8 | MC-10118<br>MC-10138 | MK-4308<br>MK-4308 | 81.7-83.8 | 13/16 | CC-70111 | CK-3144 |
| | | GTR | 81.7-83.8 | 15/16 | | TK-9417 | 81.7-83.8 | 2 1/4 | DISC | SP-229 | CPS-219 | 81.7-83.8 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 81.7-83.8 | (1)BH-02426<br>(2)BH-96001 | (R)BH-95001<br>(L)BH-95001 | 81.7-83.5<br>83.5-83.8 | 5/8<br>5/8 | MC-10118<br>MC-10138 | MK-4308<br>MK-4308 | 81.7-83.8 | 13/16 | CC-70111 | CK-3144 |
| | E−AA63 | GT | 83.8-85.7 | 15/16 | | TK-9417 | 83.8-85.7 | 2 1/4 | DISC | SP-229 | CPS-219 | 83.8-85.7 | 1 11/16 | DISC | SP-218 | | 83.8-85.4<br><br><br><br><br>85.4-85.7 | (1)BH-02426<br>(2)BH-96001<br><br><br><br>BH-02474 | (R-1)BH-95001<br>(L-1)BH-95001<br>(R-2)BH-02343<br>(L-2)BH-02343<br>(R-1)BH-95001<br>(L-1)BH-95001<br>(R-2)BH-02343<br>(L-2)BH-02343 | 83.8-85.7 | 5/8 | MC-10102 | MK-4300 | 83.8-85.7 | 13/16 | CC-70153 | CK-3144 |
| (1800) | E−TA63 | SX | 81.7-83.8 | 15/16 | | TK-9417 | 81.7-83.8 | 2 1/4 | DISC | SP-229 | CPS-219 | 81.7-82.5<br>82.5-83.8 | 1 11/16<br>1 11/16 | DISC<br>DISC | SP-218<br>SP-218 | | 81.7-83.8 | (1)BH-02426<br>(2)BH-96001 | (R-1)BH-95001<br>(L-1)BH-95001<br>(R-2)BH-02343<br>(L-2)BH-02343 | 81.7-83.5<br>83.5-83.8 | 5/8<br>5/8 | MC-10118<br>MC-10138 | MK-4308<br>MK-4308 | 81.7-83.8 | 13/16 | CC-70111 | CK-3144 |
| | | ST | 81.7-82.10 | 15/16 | | TK-9417 | 81.7-82.10 | 2 1/4 | DISC | SP-229 | CPS-219 | 81.7-82.10 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 81.7-82.10 | (1)BH-02426<br>(2)BH-96001 | (R)BH-95001<br>(L)BH-95001 | 81.7-82.10 | 5/8 | MC-10118 | MK-4308 | 81.7-82.10 | 13/16 | CC-70111 | CK-3144 |
| | | GT−T | 82.10-85.7 | 15/16 | | TK-9417 | 82.10-85.7 | 2 1/4 | DISC | SP-229 | CPS-219 | 82.10-85.7 | 1 11/16 | DISC | SP-218 | | 82.10-85.4<br><br><br><br><br>85.4-85.7 | (1)BH-02426<br>(2)BH-96001<br><br><br><br>BH-02474 | (R-1)BH-95001<br>(L-1)BH-95001<br>(R-2)BH-02343<br>(L-2)BH-02343<br>(R-1)BH-95001<br>(L-1)BH-95001<br>(R-2)BH-02343<br>(L-2)BH-02343 | 82.10-83.5<br>83.5-85.7 | 5/8<br>5/8 | MC-10074<br>MC-10102 | MK-4300<br>MK-4300 | 82.10-85.7 | 13/16 | CC-70110 | CK-3144 |
| (1800) | E−TA64 | GT−TS | 82.10-83.8 | 15/16 | | TK-9417 | 82.10-83.8 | 2 1/4 | DISC | SP-229 | CPS-219 | 82.10-83.8 | 1 1/2 | DISC | A-73P<br>A-46LP | | 82.10-83.8 | (1)BH-02426<br>(2)BH-96001 | (C)BH-02394<br>(R)BH-31264<br>(L)BH-31264 | 82.10-83.5<br>83.5-83.8 | 5/8<br>5/8 | MC-10074<br>MC-10102 | MK-4300<br>MK-4300 | 82.10-83.8 | 13/16 | CC-70110 | CK-3144 |
| | E−SA60 | SV･ST･SX | 81.7-85.7 | 13/16 | | TK-9389 | 81.7-85.7 | 2 | DISC | A-102P | | 81.7-85.7 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 81.7-85.4<br><br>85.4-85.7 | (1)BH-02426<br>(2)BH-96001<br>BH-02474 | BH-02394<br><br>BH-02394 | 81.7-83.5<br>83.5-85.7 | 5/8<br>5/8 | MC-10118<br>MC-10138 | MK-4308<br>MK-4308 | 81.7-85.7 | 13/16 | CC-70151 | CK-3144 |
| (2000) | E−RA63 | GT | 81.7-82.8 | 15/16 | | TK-9417 | 81.7-82.8 | 2 1/4 | DISC | SP-229 | CPS-219 | 81.7-82.8 | 1 11/16 | DISC | SP-218 | | 81.7-82.8 | (1)BH-02426<br>(2)BH-96001 | (R-1)BH-95001<br>(L-1)BH-95001<br>(R-2)BH-02343<br>(L-2)BH-02343 | 81.7-82.8 | 5/8 | MC-10118 | MK-4308 | 81.7-82.8 | 13/16 | CC-70110 | CK-3144 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CELICA(FF) : 160 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1600) | E−AT160 | | 85.8-87.8 | 15/16 | | TK-T006 | 85.8-87.8 | 54.0 | DISC | MP-18 | | 85.8-87.8 | 31.7 | MD-121M | A-222P | | 85.8-87.8 | BH-02455 | (R)BH-02581<br>(L)BH-02581 | 85.8-87.8 | 5/8 | | MK-4344 | 85.8-87.8 | 13/16 | CC-70152 | CK-3131 |
| (1800) | E−ST160 | | 85.8-88.5 | 15/16 | | TK-T006 | 85.8-88.5 | 54.0 | DISC | MP-19 | | 85.8-88.5 | 3/4 | (R)WC-55021<br>(L)WC-57021 | WK-542 | CUP | 85.8-87.8<br>87.8-88.5 | BH-02455<br>BH-02550 | (R)BH-02472<br>(L)BH-02472<br>(R)BH-02472<br>(L)BH-02472 | 85.8-88.5 | 5/8 | MC-T232 | MK-4344 | 85.8-88.5 | 13/16 | CC-70150 | CK-3144 |
| (2000) | E−ST162 | GT・GT−R | 85.8-89.8<br><アンチスキッド付><br>87.8-89.8 | 15/16<br><br>1 | | TK-T006<br><br>TK-T048 | 85.8-89.8<br><アンチスキッド付><br>87.8-89.8 | 54.0<br><br>57.2 | DISC<br><br>DISC | MP-18<br><br>MP-21 | | 85.8-89.8 | 31.7 | MD-121M | A-222P | | 85.8-87.8<br>87.8-89.8 | BH-02455<br>BH-02550 | (R)BH-02581<br>(L)BH-02581<br>(R)BH-02551<br>(L)BH-02551 | 85.8-89.8 | 5/8 | MC-T232 | MK-4344 | 85.8-89.2<br>89.2-89.8 | 13/16<br>13/16 | CC-70150<br>CC-70150 | CK-3144<br>CK-3144 |
| | | ZR | 87.8-89.8<br><アンチスキッド付><br>88.5-89.8 | 15/16<br><br>1 | | TK-T006<br><br>TK-T048 | 87.8-89.8<br><アンチスキッド付><br>88.5-89.8 | 54.0<br><br>57.2 | DISC<br><br>DISC | MP-18<br><br>MP-21 | | 87.8-88.5<br><br>88.5-89.8 | 3/4<br><br>31.7 | (R)WC-55021<br>(L)WC-57021<br>MD-121M | WK-542<br><br>A-222P | CUP | 87.8-88.5<br><br>88.5-89.8 | BH-02550<br><br>BH-02550 | (R)BH-02472<br>(L)BH-02472<br>(R)BH-02551<br>(L)BH-02551 | 87.8-89.8 | 5/8 | MC-T232 | MK-4344 | 87.8-89.2<br>89.2-89.8 | 13/16<br>13/16 | CC-70180<br>CC-70180 | CK-3144<br>CK-3144 |
| | E−ST162C | CV(コンバーチブル車) | 87.10-89.8 | 15/16 | | TK-T006 | 87.10-89.8 | 54.0 | DISC | MP-18 | | 87.10-89.8 | 3/4 | (R)WC-55021<br>(L)WC-57021 | WK-542 | CUP | 87.10-89.8 | BH-02550 | (R)BH-02472<br>(L)BH-02472 | 87.10-89.8 | 5/8 | MC-T232 | MK-4344 | 87.10-89.2<br>89.2-89.8 | 13/16<br>13/16 | CC-70180<br>CC-70180 | CK-3144<br>CK-3144 |
| | E−ST163 | | 88.5-89.8 | 15/16 | | TK-T006 | 88.5-89.8 | 54.0 | DISC | MP-19 | | 88.5-89.8 | 3/4 | (R)WC-55021<br>(L)WC-57021 | WK-542 | CUP | 88.5-89.8 | BH-02550 | (R)BH-02472<br>(L)BH-02472 | 88.5-89.8 | 5/8 | MC-T232 | MK-4344 | 88.5-89.2<br>89.2-89.8 | 13/16<br>13/16 | CC-70180<br>CC-70180 | CK-3144<br>CK-3144 |
| | E−ST165(4WD) | | 86.10-87.10<br>87.10-89.8<br><アンチスキッド付><br>87.10-89.8 | 15/16<br>1<br><br>1 | | TK-T349<br>TK-T047<br><br>TK-T048 | 86.10-87.10<br>87.10-89.8 | 57.2<br>1 11/16 | DISC<br>DISC | MP-21<br>A-268P | CPC-227B | 86.10-87.10<br>87.10- | 31.7<br>34.9 | MD-121M<br>MD-121M | MP-22<br>MP-82 | | 86.10-87.10<br><br>87.10-89.8 | BH-02455<br><br>BH-02550 | (R)BH-02503<br>(L)BH-02503<br>(R)BH-02549<br>(L)BH-02549 | 86.10-89.8 | 5/8 | MC-T232 | MK-4344 | 86.10-89.2<br>89.2-89.8 | 13/16<br>13/16 | CC-70180<br>CC-70180 | CK-3144<br>CK-3144 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CELICA(FF) : 180 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000) | E－ST182 | SR･ZR･GTR | 89.9-93.9<br><ｱﾝﾁｽｷｯﾄﾞ付>
89.9-93.9 | 15/16<br>1 | | TK-T307<br>TK-T306 | 89.9-93.9 | 2 1/4 | DISC | A-306P | | 89.9-91.1<br>91.1-93.9<br><GTR><br>91.8-93.9 | 31.7<br>31.7<br><br>34.9 | DISC<br>DISC<br><br>DISC | A-222P<br>A-222P<br><br>MP-82 | | 89.9-93.9 | BH-T517 | (R)BH-T519<br>(L)BH-T519 | 89.9-93.3<br>93.3-93.9 | 5/8<br>5/8 | MC-T294 | MK-T236 | 89.9-93.9<br><GTR><br>89.9-93.9 | 13/16<br><br>13/16 | CC-70180 | CK-3144<br><br>CK-3144 |
| | E－ST183（4WS）<br>E－ST183C<br>（コンバーチブル車） | SR･ZR･GTR<br>アクティブスポーツ<br>CV | 89.9-93.9<br><ｱﾝﾁｽｷｯﾄﾞ付>
89.9-93.9 | 15/16<br>1 | | TK-T307<br>TK-T306 | 89.9-93.9 | 2 1/4 | DISC | A-306P | | 89.9-91.1<br>91.1-93.9<br><GTR><br>91.8-93.9 | 31.7<br>31.7<br><br>34.9 | DISC<br>DISC<br><br>DISC | A-222P<br>A-222P<br><br>MP-82 | | 89.9-93.9<br><ｱｸﾃｨﾌﾞｽﾎﾟｰﾂ><br>90.4-91.8 | BH-T517<br>(R)BH-T561<br>(L)BH-T562 | (R)BH-T519<br>(L)BH-T519<br>(R)BH-T519<br>(L)BH-T519 | 89.9-93.3<br>93.3-93.9 | 5/8<br>5/8 | MC-T294 | MK-T236 | 89.9-93.9<br><SR,ZR><br>89.9-93.9 | 13/16<br><br>13/16 | <br><br>CC-70180 | CK-3144<br><br>CK-3144 |
| | E－ST185･185H | | 89.10-91.8<br>91.8-93.9<br><ｱﾝﾁｽｷｯﾄﾞ付>
89.10-93.9 | 1<br>15/16<br><br>1 | | TK-T310<br>TK-T307<br><br>TK-T306 | 89.10-91.8<br><br><GT-FOUR仕様><br>89.10-91.8<br>91.8-93.9 | | DISC<br><br><br>DISC<br>DISC | A-268P<br><br><br>A-306P<br>A-306P | CPC-227B | 89.10-91.6<br>91.6-93.9 | 34.9<br>34.9 | DISC<br>DISC | MP-82<br>MP-82 | | 89.10-93.9 | BH-T517 | (R)BH-T522<br>(L)BH-T522 | 89.10-93.3<br>93.3-93.9 | 5/8<br>5/8 | MC-T393 | MK-T236 | 89.10-93.9 | 7/8 | | CK-T200 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CELICA(FF) : 200 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000) | E－ST202・203<br>E－ST202C | SS－1 | 93.9-95.8<br>95.8-96.6<br><アンチスキッド付><br>93.9-97.6<br>97.6-99.8 | 15/16<br>15/16<br><br>15/16<br>15/16 | | TK-T349<br>TK-T409<br><br>TK-T342<br>TK-T401 | 93.9-99.8 | 57.2 | DISC | MP-50 | CPM-68 | 93.9-99.8 | 31.7 | DISC | A-222P | | 93.9-99.8 | (R)BH-T597<br>(L)BH-T598 | (R)BH-T591<br>(L)BH-T591 | 93.9-94.4<br>94.4-99.8 | 5/8<br>5/8 | MC-T413<br>MC-T413 | MK-T244 | 93.9-94.1<br>94.1-99.8 | 13/16<br>13/16 | CC-70180<br>CC-70180 | CK-3144<br>CK-T201 |
| | | SS－2・コンバーチブル<br>（ノーマルサス車） | 93.9-95.8<br>95.8-96.6<br><ST202C><br>94.8-95.12<br>95.12-97.12<br><アンチスキッド付><br>93.9-97.6<br>97.6-97.12<br>97.12-99.8 | 15/16<br>15/16<br><br>15/16<br>15/16<br><br>15/16<br>15/16<br>15/16 | | TK-T349<br>TK-T409<br><br>TK-T349<br>TK-T409<br><br>TK-T342<br>TK-T401<br>TK-T436 | 93.9-97.12<br>97.12-99.8 | 57.2 | DISC<br>DISC | MP-50<br>MP-62 | CPM-68 | 93.9-99.8 | | DISC | C-222P | | 93.9-97.12<br><br>97.12-99.8 | (R)BH-T597<br>(L)BH-T598<br>(R)<br>(L) | (R)BH-T591<br>(L)BH-T591<br>(R)BH-T591<br>(L)BH-T591 | 93.9-94.4<br>94.4-99.8 | 5/8<br>5/8 | MC-T413<br>MC-T413 | MK-T244 | 93.9-94.1<br>94.1-99.8 | 13/16<br>13/16 | | CK-3144<br>CK-T201 |
| | | SS－2・SS－3<br>（スーパーストラットサス車） | 93.9-95.8<br>95.8-96.6<br><アンチスキッド付><br>93.9-97.6<br>97.6-97.12<br>97.12-99.8 | 15/16<br>15/16<br><br>15/16<br>15/16<br>15/16 | | TK-T349<br>TK-T409<br><br>TK-T342<br>TK-T401<br>TK-T436 | 93.9-99.8 | 40.4 | DISC | MP-61 | | 93.9-99.8 | | DISC | C-222P | | 93.9-99.8 | (R)BH-T641<br>(L)BH-T642 | (R)BH-T591<br>(L)BH-T591 | 93.9-94.4<br>94.4-99.8 | 5/8<br>5/8 | MC-T413<br>MC-T413 | MK-T244 | 93.9-94.1<br>94.1-99.8 | 13/16<br>13/16 | | CK-3144<br>CK-T201 |
| | E－ST205（4WD） | | 94.2-95.8<br>95.8-96.6<br><アンチスキッド付><br>94.2-95.8<br>95.8-99.8 | 15/16<br>15/16<br><br>15/16<br>1 | | TK-T349<br>TK-T409<br><br>TK-T342<br>TK-T370 | 94.2-99.8 | 40.5 | DISC | SP-287 | | 94.2-99.8 | 38.1 | DISC | SP-288 | | 94.2-99.8 | (R-1)BH-T637<br>(L-1)BH-T639<br>(R-2)BH-T638<br>(L-2)BH-T640 | (R)BH-T643<br>(L)BH-T644 | 94.2-94.4<br>94.4-99.8 | 5/8<br>5/8 | MC-T413<br>MC-T413 | MK-T244 | 94.2-99.8 | 7/8 | | CK-T200 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CELICA : 230 ser.(99.8-) | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) | GH－ZZT230<br>＜TA－は00．8～＞ | | 99.8- | | | | 99.8- | | DISC | MP-102 | CPM-102 | 99.8-02.8<br><br>02.8- | 3/4<br><br>3/4 | (R)WC-T600<br>(L)WC-T605<br>(R)WC-T780<br>(L)WC-T781 | WK-542<br><br>WK-542 | CUP<br><br>CUP | 99.8- | (R)<br>(L) | (R)BH-T846<br>(L)BH-T846 | 99.8- | 5/8 | | | 99.8-00.3<br>00.3-02.8<br>02.8- | 13/16<br><br>3/4 | | CK-T201<br>CK-T230<br>CK-T202 |
| | GH－ZZT231<br>＜TA－は00．8～＞ | ノーマルサス車 | 99.8-06.4 | | | | 99.8-06.4 | | DISC | MP-103 | CPM-68 | 99.8-06.4 | | DISC | SP-106 | CPS-106 | 99.8-06.4 | (R)<br>(L) | (R)BH-T836<br>(L)BH-T836 | 99.8-06.4 | 5/8 | | | 99.8-00.3<br>00.3-02.8<br>02.8-06.4 | 13/16 | | CK-T201<br>CK-T230<br>CK-T201 |
| | | スーパーストラットサス車 | 99.8-06.4 | | | | 99.8-06.4 | | DISC | MP-103 | CPM-68 | 99.8-06.4 | | DISC | SP-106 | CPS-106 | 99.8-06.4 | (R)<br>(L) | (R)BH-T836<br>(L)BH-T836 | 99.8-06.4 | 5/8 | | | 99.8-00.3<br>00.3-02.8<br>02.8-06.4 | 13/16 | | CK-T201<br>CK-T230<br>CK-T201 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CURREN : 200 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) | E−ST208 | | 95.9−96.6 | 7/8 | | TK−T402 | 95.9−98.7 | 57.2 | DISC | MP−50 | CPM−68 | 95.9−98.7 | 3/4 | | WK−542 | CUP | 95.9−98.7 | (R)BH−T597<br>(L)BH−T598 | (R)BH−T590<br>(L)BH−T590 | 95.9−98.7 | 5/8 | MC−T413 | MK−T244 | 95.9−98.7 | 13/16 | CC−70180 | CK−T201 |
| | | | <アンチスキッド付> | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | 95.9−97.6 | 15/16 | | TK−T342 | | | | | | | | | | | | | | | | | | | | | |
| | | | 97.6−98.7 | 15/16 | | TK−T401 | | | | | | | | | | | | | | | | | | | | | |
| (2000) | E−ST206・207 | FS・XS | 94.2−95.9 | 15/16 | | TK−T349 | 94.2−98.7 | 57.2 | DISC | MP−50 | CPM−68 | 94.2−98.7 | 31.7 | DISC | A−222P | | 94.2−98.7 | (R)BH−T597<br>(L)BH−T598 | (R)BH−T591<br>(L)BH−T591 | 94.2−94.4<br>94.4−98.7 | 5/8<br>5/8 | MC−T413<br>MC−T413 | MK−T244 | 94.2−98.7 | 13/16 | CC−70180 | CK−T201 |
| | | | 95.9−96.6 | 15/16 | | TK−T409 | | | | | | | | | | | | | | | | | | | | | |
| | | | <アンチスキッド付> | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | 94.2−97.6 | 15/16 | | TK−T342 | | | | | | | | | | | | | | | | | | | | | |
| | | | 97.6−98.7 | 15/16 | | TK−T401 | | | | | | | | | | | | | | | | | | | | | |
| | | ZS<br>(ノーマルサス車) | 94.2−95.9 | 15/16 | | TK−T349 | 94.2−98.7 | 57.2 | DISC | MP−50 | CPM−68 | 94.2−98.7 | | DISC | C−222P | | 94.2−98.7 | (R)BH−T597<br>(L)BH−T598 | (R)BH−T591<br>(L)BH−T591 | 94.2−94.4<br>94.4−98.7 | 5/8<br>5/8 | MC−T413<br>MC−T413 | MK−T244 | 94.2−98.7 | 13/16 | | CK−T201 |
| | | | 95.9−96.6 | 15/16 | | TK−T409 | | | | | | | | | | | | | | | | | | | | | |
| | | | <アンチスキッド付> | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | 94.2−97.6 | 15/16 | | TK−T342 | | | | | | | | | | | | | | | | | | | | | |
| | | | 97.6−98.7 | 15/16 | | TK−T401 | | | | | | | | | | | | | | | | | | | | | |
| | | ZS<br>(スーパーストラットサス車) | 94.2−95.9 | 15/16 | | TK−T349 | 94.2−98.7 | 40.4 | DISC | MP−61 | | 94.2−98.7 | | DISC | C−222P | | 94.2−98.7 | (R)BH−T641<br>(L)BH−T642 | (R)BH−T591<br>(L)BH−T591 | 94.2−94.4<br>94.4−98.7 | 5/8<br>5/8 | MC−T413<br>MC−T413 | MK−T244 | 94.2−98.7 | 13/16 | | CK−T201 |
| | | | 95.9−96.6 | 15/16 | | TK−T409 | | | | | | | | | | | | | | | | | | | | | |
| | | | <アンチスキッド付> | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | 94.2−97.6 | 15/16 | | TK−T342 | | | | | | | | | | | | | | | | | | | | | |
| | | | 97.6−98.7 | 15/16 | | TK−T401 | | | | | | | | | | | | | | | | | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| OPA : 10 ser.(00.4-) | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) | TA－ZCT10<br>＜UA－は02．5～＞ | リヤードラム車 | 00.4- | 13/16 | | TK-T440 | 00.4- | | DISC | MP-104 | CPM-102 | 00.4- | 3/4 | | WK-542 | CUP | 00.4- | (R)BH-T833<br>(L)BH-T834 | (R)BH-T948<br>(L)BH-T948 | | | (オートマチック) | | | | | |
| | | 四輪ディスク車 | 02.5- | 13/16 | | TK-T440 | 02.5- | | DISC | MP-103 | CPM-68 | 02.5- | | DISC | MP-96 | | 02.5- | (R)BH-T833<br>(L)BH-T834 | (R)BH-T949<br>(L)BH-T949 | | | (オートマチック) | | | | | |
| | TA－ZCT15(4WD)<br>＜UA－は02．5～＞ | リヤードラム車 | 00.4- | 13/16 | | TK-T440 | 00.4-02.5<br>02.5- | | DISC<br>DISC | MP-68<br>MP-103 | CPM-68<br>CPM-68 | 00.4- | 3/4 | (R)WC-T785<br>(L)WC-T785 | WK-899 | CUP | 00.4- | (R)BH-T833<br>(L)BH-T834 | (R)BH-T846<br>(L)BH-T846 | | | (オートマチック) | | | | | |
| | | 四輪ディスク車 | 02.5- | 13/16 | | TK-T440 | 02.5- | | DISC | MP-103 | CPM-68 | 02.5- | | DISC | MP-96 | | 02.5- | (R)BH-T833<br>(L)BH-T834 | (R)BH-T836<br>(L)BH-T836 | | | (オートマチック) | | | | | |
| (2000) | TA－ACT10 | リヤードラム車<br>a仕様 | 00.8- | 13/16 | | TK-T440 | 00.8-02.5<br>02.5- | | DISC<br>DISC | MP-104<br>MP-103 | CPM-102 | 00.8- | 11/16 | (R)WC-T786<br>(L)WC-T786 | WK-834 | CUP | 00.8- | (R)BH-T833<br>(L)BH-T834 | (R)BH-T948<br>(L)BH-T948 | | | (オートマチック) | | | | | |
| | | リヤードラム車<br>i仕様 | 00.8- | 13/16 | | TK-T440 | 00.8-02.5<br>02.5- | | DISC<br>DISC | MP-68<br>MP-103 | CPM-68<br>CPM-68 | 00.8- | 11/16 | (R)WC-T786<br>(L)WC-T786 | WK-834 | CUP | 00.8- | (R)BH-T833<br>(L)BH-T834 | (R)BH-T948<br>(L)BH-T948 | | | (オートマチック) | | | | | |
| | | 四輪ディスク車 | 02.5- | 13/16 | | TK-T440 | 02.5- | | DISC | MP-103 | CPM-68 | 02.5- | | DISC | MP-96 | | 02.5- | (R)BH-T833<br>(L)BH-T834 | (R)BH-T949<br>(L)BH-T949 | | | (オートマチック) | | | | | |

| Models | TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CELICA, CAMRY : TA, RA | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1600) | TA41 | LT・XT | 80.1-82.2 | 13/16 | | TK-9346 | 80.1-82.2 | 2 | DISC | A-16P | | 80.1-81.9 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 80.1-82.2 | (1)<br>(2)BH-02224 | BH-02394 | 80.1-82.2 | 5/8 | MC-10094 | MK-4308 | 80.1-80.8<br>80.8-81.1 | 13/16<br>13/16 | CC-70110<br>CC-70111 | CK-3113<br>CK-3113 |
| | | | | | | | | | | | | 81.9-82.2 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | | | | | | | | 81.1-82.2 | 13/16 | CC-70111 | CK-3144 |
| (1800) | TA46 | LT・XT | 80.1-82.2 | 13/16 | | TK-9346 | 80.1-82.2 | 2 | DISC | A-16P | | 80.1-81.9 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 80.1-82.2 | (1)<br>(2)BH-02224 | BH-02394 | 80.1-82.2 | 5/8 | MC-10094 | MK-4308 | 80.1-80.8<br>80.8-81.1 | 13/16<br>13/16 | CC-70110<br>CC-70111 | CK-3113<br>CK-3113 |
| | | | | | | | | | | | | 81.9-82.2 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | | | | | | | | 81.1-82.2 | 13/16 | CC-70111 | CK-3144 |
| | TA57 | SX | 80.8-82.2 | 7/8 | | TK-9355 | 80.8-82.2 | 2 1/8 | DISC | A-57P | | 80.8-82.2 | 1 11/16 | DISC | SP-218 | | 80.8-82.2 | (1)<br>(2)BH-02224 | (R-1)BH-95001<br>(L-1)BH-95001<br>(R-2)BH-02343<br>(L-2)BH-02343 | 80.8-82.2 | 5/8 | MC-10094 | MK-4308 | 80.8-81.1<br>81.1-82.2 | 13/16<br>13/16 | CC-70110<br>CC-70110 | CK-3113<br>CK-3144 |
| (2000) | RA55<br>RA56 | GT<br>SE | 80.8-82.2 | 7/8 | | TK-9355 | 80.8-82.2 | 2 1/8 | DISC | A-57P | | 80.8-82.2 | 1 11/16 | DISC | SP-218 | | 80.8-82.2 | (1)<br>(2)BH-02224 | (R-1)BH-95001<br>(L-1)BH-95001<br>(R-2)BH-02343<br>(L-2)BH-02343 | 80.8-82.2 | 5/8 | MC-10094 | MK-4308 | 80.8-81.1<br>81.1-82.2 | 13/16<br>13/16 | CC-70110<br>CC-70110 | CK-3113<br>CK-3144 |

| Models | TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CAMRY, VISTA : SV, CV10 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) | E－SV10 | 全車 | 82.3-84.6 | 7/8 | | TK-9421 | 82.3-86.7 | 51.1 | DISC | MP-6 | | 82.3-86.7 | 3/4 | (R)WC-55021 | WK-542 | CUP | 82.3-86.7 | BH-02429 | (R)BH-95003 | 82.3-84.3 | 5/8 | | MK-4310 | 82.3-84.4 | 13/16 | CC-70150 | CK-3129 |
| (2000) | E－SV11・12 | | 84.6-86.7 | 7/8 | | TK-9421 | | | | | | | | (L)WC-57021 | | | | | (L)BH-95003 | 84.3-86.7 | 5/8 | | MK-4344 | 84.4-86.7 | 13/16 | CC-70150 | CK-3144 |
| (1800ディーゼル) | N－CV10 | 全車 | 83.8-84.6 | 7/8 | | TK-9421 | 83.8-86.7 | 51.1 | DISC | MP-6 | | 83.8-86.7 | 3/4 | (R)WC-55021 | WK-542 | CUP | 83.8-86.7 | BH-02429 | (R)BH-95003 | 83.8-86.7 | 5/8 | MC-10122 | MK-4312 | 83.8-84.4 | 13/16 | CC-70150 | CK-3129 |
| (2000ディーゼル) | N－CV11 | | 84.6-86.7 | 7/8 | | TK-9421 | | | | | | | | (L)WC-57021 | | | | | (L)BH-95003 | | | | | 84.4-86.7 | 13/16 | CC-70150 | CK-3144 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CAMRY, VISTA : 20 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) | E−SV20<br>E−SV22 | | 86.8- | 1 1/8<br>7/8 | | TK-T022 | 86.8- | 54.0 | DISC | MP-20 | CPM-20 | 86.8- | 3/4 | (R)WC-55021<br>(L)WC-57021 | WK-542 | CUP | 86.8-89.8<br><br>89.8- | BH-02496<br><br>BH-02496 | (R)BH-02497<br>(L)BH-02497<br>(R)BH-02497<br>(L)BH-02497 | 86.8-86.11<br>86.11-87.11<br>87.11- | 5/8<br>5/8<br>5/8 | | MK-4335<br>MK-4337<br>MK-4342 | 86.8-88.8<br>88.8-89.2<br>89.2- | 13/16<br>13/16<br>13/16 | CC-70150<br>CC-70180<br>CC-70180 | CK-3144<br>CK-3144<br>CK-3144 |
| (2000) | E−SV21 | 除く四輪ディスク車 | 86.8-88.8 | 15/16 | | TK-T349 | 86.8-88.8 | 57.2 | DISC | MP-21 | | 86.8-88.8 | 3/4 | (R)WC-55021<br>(L)WC-57021 | WK-542 | CUP | 86.8-88.8 | BH-02496 | (R)BH-02497<br>(L)BH-02497 | 86.8-86.11<br>86.11-87.11<br>87.11-88.8 | 5/8<br>5/8<br>5/8 | | MK-4335<br>MK-4337<br>MK-4342 | 86.8-88.8 | 13/16 | CC-70180 | CK-3144 |
| | | 四輪ディスク車 | 86.8-<br><アンチスキッド付><br>87.4- | 15/16<br><br>1 | | TK-T349<br><br>TK-T037 | 86.8- | 57.2 | DISC | MP-21 | | 86.8- | 31.7 | DISC | MP-22 | | 86.8-89.8<br><br>89.8-<br><br><アンチスキッド付><br>87.4- | BH-02496<br><br>BH-02496<br><br>BH-02496 | (R)BH-02498<br>(L)BH-02498<br>(R)BH-02498<br>(L)BH-02498<br><br>(R)BH-02498<br>(L)BH-02498 | 86.8-86.11<br>86.11-87.11<br>87.11- | 5/8<br>5/8<br>5/8 | | MK-4335<br>MK-4337<br>MK-4342 | 86.8-89.2<br>89.2-<br><GT><br>86.8-89.2<br>89.2- | 13/16<br>13/16<br><br>13/16<br>13/16 | CC-70180<br>CC-70180<br><br>CC-70150<br>CC-70150 | CK-3144<br>CK-3144<br><br>CK-3144<br>CK-3144 |
| | E−VZV20 | | 87.4-<br><アンチスキッド付><br>87.4- | 15/16<br><br>1 | | TK-T349<br><br>TK-T037 | 87.4- | 57.2 | DISC | MP-21 | | 87.4- | 31.7 | DISC | MP-22 | | 87.4-89.8<br><br>89.8-<br><br><アンチスキッド付><br>87.4- | BH-02496<br><br>BH-02496<br><br>BH-02496 | (R)BH-02498<br>(L)BH-02498<br>(R)BH-02498<br>(L)BH-02498<br><br>(R)BH-02498<br>(L)BH-02498 | 87.4-87.11<br>87.11- | 5/8<br>5/8 | MC-T416 | MK-4337<br>MK-4342 | 87.4-89.2<br>89.2- | 13/16<br>13/16 | CC-70180<br>CC-70180 | CK-3144<br>CK-3144 |
| | E−SV25(4WD) | | 87.10-<br><アンチスキッド付><br>87.10- | 15/16<br><br>1 | | TK-T349<br><br>TK-T037 | 87.10- | 57.2 | DISC | MP-21 | | 87.10- | 31.7 | DISC | MP-22 | | 87.10-89.8<br><br>89.8-<br><br><アンチスキッド付><br>87.10- | BH-02496<br><br>BH-02496<br><br>BH-02496 | (R)BH-02549<br>(L)BH-02549<br>(R)BH-02549<br>(L)BH-02549<br><br>(R)BH-02549<br>(L)BH-02549 | 87.10-87.11<br>87.11- | 5/8<br>5/8 | MC-T416 | MK-4337<br>MK-4342 | 87.10-89.2<br>89.2- | 13/16<br>13/16 | CC-70180<br>CC-70180 | CK-3144<br>CK-3144 |
| (2000ディーゼル) | N−CV20<br>Q−CV20 | 全車 | 86.8- | 1 1/8 | | TK-T022 | 86.8- | 54.0 | DISC | MP-20 | CPM-20 | 86.8- | 3/4 | (R)WC-55021<br>(L)WC-57021 | WK-542 | CUP | 86.8-89.8<br><br>89.8- | BH-02496<br><br>BH-02496 | (R)BH-02497<br>(L)BH-02497<br>(R)BH-02497<br>(L)BH-02497 | 86.8-86.11<br>86.11-87.11<br>87.11- | 5/8<br>5/8<br>5/8 | MC-T416 | MK-4312<br>MK-4337<br>MK-4342 | 86.8-89.2<br>89.2- | 13/16<br>13/16 | CC-70150<br>CC-70150 | CK-3144<br>CK-3144 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CAMRY, VISTA : 30 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) | E－SV30 | | <MT車><br>90.7-94.6<br><AT車><br>90.7-94.6<br><アンチスキッド付><br>90.7-94.6 | 7/8<br><br>15/16<br><br>1 | | TK-T402<br><br>TK-T307<br><br>TK-T306 | 90.7-94.6 | 57.2 | DISC | MP-50 | | 90.7-94.6 | 3/4 | (R)WC-55021<br>(L)WC-57021 | WK-542 | CUP | 90.7-92.6<br><br>92.6-94.6 | (R)BH-T534<br>(L)BH-T535<br>(R)BH-T534<br>(L)BH-T535 | (R)BH-T539<br>(L)BH-T539<br>(R)BH-T625<br>(L)BH-T693 | 90.7-93.3<br>93.3-94.6 | 5/8<br>5/8 | MC-T417 | MK-T236 | 90.7-94.1<br>94.1-94.6 | 13/16<br>13/16 | CC-70180<br>CC-70180 | CK-3144<br>CK-T201 |
| (2000) | E－SV32 | 3S－FEエンジン車 | 90.7-94.6<br><アンチスキッド付><br>90.7-94.6 | 15/16<br><br>1 | | TK-T307<br><br>TK-T306 | 90.7-94.6 | 57.2 | DISC | MP-50 | | 90.7-94.6<br><TOURING仕様><br>92.6-94.6 | 31.7<br><br>34.9 | DISC<br><br>DISC | MP-22<br><br>MP-82 | | 90.7-92.6<br><br>92.6-94.6 | (R)BH-T534<br>(L)BH-T535<br>(R)BH-T534<br>(R)BH-T535 | (R)BH-T541<br>(L)BH-T542<br>(R)BH-T615<br>(L)BH-T616 | 90.7-93.3<br>93.3-94.6 | 5/8<br>5/8 | MC-T417 | MK-T236 | 90.7-94.1<br>94.1-94.6 | 13/16<br>13/16 | CC-70180<br>CC-70180 | CK-3144<br>CK-T201 |
| | | 3S－GEエンジン車 | 90.7-92.6<br><アンチスキッド付><br>90.7-92.6 | 15/16<br><br>1 | | TK-T307<br><br>TK-T306 | 90.7-92.6 | 57.2 | DISC | MP-50 | | 90.7-92.6 | 34.9 | DISC | MP-82 | | 90.7-92.6 | (R)BH-T534<br>(L)BH-T535 | (R)BH-T541<br>(L)BH-T542 | 90.7-92.6 | 5/8 | MC-T417 | MK-T236 | 90.7-92.6 | 13/16 | | CK-3144 |
| | E－SV33(4WS) | 3S－FEエンジン車 | 90.7-94.6<br><アンチスキッド付><br>90.7-94.6 | 15/16<br><br>1 | | TK-T307<br><br>TK-T306 | 90.7-94.6 | 57.2 | DISC | MP-50 | | 90.7-94.6<br><TOURING仕様><br>92.6-94.6 | 31.7<br><br>34.9 | DISC<br><br>DISC | MP-22<br><br>MP-82 | | 90.7-92.6<br><br>92.6-94.6 | (R)BH-T534<br>(L)BH-T535<br>(R)BH-T534<br>(L)BH-T535 | (R)BH-T536<br>(L)BH-T540<br>(R)<br>(L) | 90.7-93.3<br>93.3-94.6 | 5/8<br>5/8 | MC-T417 | MK-T236 | 90.7-94.1<br>94.1-94.6 | 13/16<br>13/16 | CC-70180<br>CC-70180 | CK-3144<br>CK-T201 |
| | | 3S－GEエンジン車 | 90.7-92.6<br><アンチスキッド付><br>90.7-92.6 | 15/16<br><br>1 | | TK-T307<br><br>TK-T306 | 90.7-92.6 | 57.2 | DISC | MP-50 | | 90.7-92.6 | 34.9 | DISC | MP-82 | | 90.7-92.6 | (R)BH-T534<br>(L)BH-T535 | (R)BH-T536<br>(L)BH-T540 | 90.7-92.6 | 5/8 | MC-T417 | MK-T236 | 90.7-92.6 | 13/16 | | CK-3144 |
| | E－SV35(4WD) | | 90.7-94.6<br><アンチスキッド付><br>90.7-94.6 | 15/16<br><br>1 | | TK-T307<br><br>TK-T306 | 90.7-94.6 | 57.2 | DISC | MP-50 | | 90.7-94.6 | 34.9 | DISC | MP-82 | | 90.7-92.6<br><br>92.6-94.6 | (R)BH-T534<br>(L)BH-T535<br>(R)BH-T534<br>(L)BH-T535 | (R)BH-T537<br>(L)BH-T538<br>(R)BH-T613<br>(L)BH-T614 | 90.7-93.3<br>93.3-94.6 | 5/8<br>5/8 | MC-T417 | MK-T236 | 90.7-94.1<br>94.1-94.6 | 13/16<br>13/16 | CC-70180<br>CC-70180 | CK-3144<br>CK-T201 |
| | E－VZV30 | | 90.7-92.6<br><アンチスキッド付><br>90.7-92.6 | 15/16<br><br>1 | | TK-T307<br><br>TK-T306 | 90.7-92.6 | 57.2 | DISC | MP-50 | | 90.7-92.6 | 34.9 | DISC | MP-82 | | 90.7-92.6 | (R)BH-T534<br>(L)BH-T535 | (R)BH-T541<br>(L)BH-T542 | 90.7-92.6 | 5/8 | MC-T418 | MK-T236 | 90.7-92.6 | 13/16 | CC-70180 | CK-3144 |
| | E－VZV31(4WS) | | 90.7-92.6<br><アンチスキッド付><br>90.7-92.6 | 15/16<br><br>1 | | TK-T307<br><br>TK-T306 | 90.7-92.6 | 57.2 | DISC | MP-50 | | 90.7-92.6 | 34.9 | DISC | MP-82 | | 90.7-92.6 | (R)BH-T534<br>(L)BH-T535 | (R)BH-T536<br>(L)BH-T540 | 90.7-92.6 | 5/8 | MC-T418 | MK-T236 | 90.7-92.6 | 13/16 | CC-70180 | CK-3144 |
| (2000ディーゼル)<br>Q－CV30<br>X－CV30<br><Y－は92．6～> | | アンチスキッド無 | 90.7-94.6 | 7/8 | | TK-T402 | 90.7-94.6 | 57.2 | DISC | MP-50 | | 90.7-94.6 | 3/4 | (R)WC-55021<br>(L)WC-57021 | WK-542 | CUP | 90.7-92.6<br><br>92.6-94.6 | (R)BH-T534<br>(L)BH-T535<br>(R)BH-T534<br>(L)BH-T535 | (R)BH-T539<br>(L)BH-T539<br>(R)BH-T625<br>(L)BH-T693 | 90.7-93.3<br>93.3-94.6 | 5/8<br>5/8 | MC-T418 | MK-T236 | 90.7-94.1<br>94.1-94.6 | 13/16<br>13/16 | CC-70150<br>CC-70150 | CK-3144<br>CK-T201 |
| | | アンチスキッド車 | 92.6-94.6 | 15/16 | | TK-T300 | 92.6-94.6 | 57.2 | DISC | MP-50 | | 92.6-94.6 | 31.7 | DISC | MP-22 | | 92.6-94.6 | (R)BH-T534<br>(L)BH-T535 | (R)BH-T615<br>(L)BH-T616 | 92.6-93.3<br>93.3-94.6 | 5/8<br>5/8 | MC-T418 | MK-T236 | 92.6-94.1<br>94.1-94.6 | 13/16<br>13/16 | CC-70150<br>CC-70150 | CK-3144<br>CK-T201 |
| (2500) | E－VZV32 | | 91.5-94.6<br><アンチスキッド付><br>91.5-94.6 | 15/16<br><br>1 | | TK-T307<br><br>TK-T306 | 91.5-94.6 | 57.2 | DISC | MP-50 | | 91.5-94.6 | 34.9 | DISC | MP-82 | | 91.5-92.6<br><br>92.6-94.6 | (R)BH-T534<br>(L)BH-T535<br>(R)BH-T534<br>(L)BH-T535 | (R)BH-T541<br>(L)BH-T542<br>(R)BH-T615<br>(L)BH-T616 | | | (オートマチック) | | | | | |
| | E－VZV33 | | 91.5-94.6<br><アンチスキッド付><br>91.5-94.6 | 15/16<br><br>1 | | TK-T307<br><br>TK-T306 | 91.5-94.6 | 57.2 | DISC | MP-50 | | 91.5-94.6 | 34.9 | DISC | MP-82 | | 91.5-92.6<br><br>92.6-94.6 | (R)BH-T534<br>(L)BH-T535<br>(R)BH-T534<br>(L)BH-T535 | (R)BH-T536<br>(L)BH-T540<br>(R)<br>(L) | | | (オートマチック) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CAMRY, VISTA : 40 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) | E－SV40 | | 94.6-96.5<br><ｱﾝﾁｽｷｯﾄﾞ付><br>94.6-98.6 | 7/8<br><br>15/16 | | TK-T360<br><br>TK-T401 | 94.6-97.11<br>97.11-98.6 | 57.2<br>57.2 | DISC<br>DISC | MP-50<br>MP-103 | CPM-68<br>CPM-68 | 94.6-98.6 | 3/4 | | WK-542 | CUP | 94.6-98.6 | (R)BH-T652<br>(L)BH-T653 | (R)BH-T654<br>(L)BH-T655 | 94.6-98.6 | 5/8 | | MK-T244 | 94.6-96.5<br>96.5-98.6 | 13/16<br>7/8 | CC-70180 | CK-T201<br>CK-T200 |
| (2000) | E－SV41 | | 94.6-96.5<br><ｱﾝﾁｽｷｯﾄﾞ付><br>94.6-98.6 | 15/16<br><br>1 | | TK-T367<br><br>TK-T370 | 94.6-97.11<br>97.11-98.6 | 57.2<br>57.2 | DISC<br>DISC | MP-50<br>MP-103 | CPM-68<br>CPM-68 | 94.6-97.11<br>97.11-98.6 | 31.7 | DISC<br>DISC | A-222P<br>A-222P | | 94.6-98.6 | (R)BH-T652<br>(L)BH-T653 | (R)BH-T615<br>(L)BH-T616 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | E－SV42(4WS) | | 94.6-96.5<br><ｱﾝﾁｽｷｯﾄﾞ付><br>94.6-98.6 | 15/16<br><br>1 | | TK-T367<br><br>TK-T370 | 94.6-97.11<br>97.11-98.6 | 57.2<br>57.2 | DISC<br>DISC | MP-50<br>MP-103 | CPM-68<br>CPM-68 | 94.6-97.11<br>97.11-98.6 | 31.7 | DISC<br>DISC | A-222P<br>A-222P | | 94.6-98.6 | (R)BH-T652<br>(L)BH-T653 | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | E－SV43(4WD) | | 94.6-96.5<br><ｱﾝﾁｽｷｯﾄﾞ付><br>94.6-98.6 | 15/16<br><br>1 | | TK-T367<br><br>TK-T370 | 94.6-97.11<br>97.11-98.6 | 57.2<br>57.2 | DISC<br>DISC | MP-50<br>MP-103 | CPM-68<br>CPM-68 | 94.6-98.6 | | DISC | C-222P | | 94.6-98.6 | (R)BH-T652<br>(L)BH-T653 | (R)BH-T613<br>(L)BH-T614 | 94.6-98.6 | 5/8 | | MK-T244 | 94.6-96.5<br>96.5-98.6 | 13/16<br>7/8 | CC-70180 | CK-T201<br>CK-T200 |
| (2200ディーゼル) | KD－CV40 | リヤードラム車 | 94.6-96.5<br>96.5-98.6 | 7/8<br>15/16 | | TK-T360<br>TK-T401 | 94.6-97.11<br>97.11-98.6 | 57.2<br>57.2 | DISC<br>DISC | MP-50<br>MP-103 | CPM-68<br>CPM-68 | 94.6-98.6 | 3/4 | | WK-542 | CUP | 94.6-98.6 | (R)BH-T652<br>(L)BH-T653 | (R)BH-T654<br>(L)BH-T655 | 94.6-98.6 | 5/8 | | MK-T244 | 94.6-98.6 | 13/16 | CC-70150 | CK-T201 |
| | | 四輪ディスク車 | 94.6-96.5 | 15/16 | | TK-T401 | 94.6-96.5 | 57.2 | DISC | MP-50 | CPM-68 | 94.6-96.5 | 31.7 | DISC | A-222P | | 94.6-96.5 | (R)BH-T652<br>(L)BH-T653 | (R)BH-T615<br>(L)BH-T616 | 94.6-96.5 | 5/8 | | MK-T244 | 94.6-96.5 | 13/16 | CC-70150 | CK-T201 |
| | KD－CV43(4WD) | | 95.1-96.5<br><ｱﾝﾁｽｷｯﾄﾞ付><br>95.1-98.6 | 15/16<br><br>1 | | TK-T367<br><br>TK-T370 | 95.1-97.11<br>97.11-98.6 | 57.2<br>57.2 | DISC<br>DISC | MP-50<br>MP-103 | CPM-68<br>CPM-68 | 95.1-98.6 | | DISC | C-222P | | 95.1-98.6 | (R)BH-T652<br>(L)BH-T653 | (R)BH-T613<br>(L)BH-T614 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| VISTA, VISTA ARDEO : 50 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) | GF－ZZV50・50G<br>＜TA－は00．4～＞ | 98.6-03.7 | 13/16 | | TK-T440 | 98.6-00.4<br>00.4-03.7 | | DISC<br>DISC | MP-103<br>MP-104 | CPM-68<br>CPM-102 | ＜現車確認 W/C ASSY 鋳物製＞<br>00.4-03.7<br>＜現車確認 W/C ASSY アルミ製＞<br>00.4-01.5 | 3/4<br>3/4 | (R)WC-T600<br>(L)WC-T605<br>(R)WC-T780<br>(L)WC-T781 | WK-542<br>WK-542 | CUP<br>CUP | 98.6-00.4<br>00.4-03.7 | (R)BH-T831<br>(L)BH-T832<br>(R)BH-T833<br>(L)BH-T834 | (R)BH-T865<br>(L)BH-T865<br>(R)BH-T948<br>(L)BH-T948 | | | (オートマチック) | | | | | |
| (2000) | GF－SV50・50G<br>TA－AZV50・50G<br>＜TA－は01．8～＞ | 98.6-03.7 | 13/16 | | TK-T440 | 98.6-03.7 | | DISC | MP-68 | CPM-68 | 98.6-03.7 | | DISC | MP-96 | | 98.6-00.4<br>00.4-03.7 | (R)BH-T833<br>(L)BH-T834<br>(R)BH-T833<br>(L)BH-T834 | (R)BH-T835<br>(L)BH-T835<br>(R)BH-T949<br>(L)BH-T949 | | | (オートマチック) | | | | | |
| | GF－SV55・55G(4WD)<br>TA－AZV55・55G(4WD)<br>＜TA－は02．4～＞ | 98.6-03.7 | 13/16 | | TK-T440 | 98.6-03.7 | | DISC | MP-68 | CPM-68 | 98.6-03.7 | | DISC | MP-96 | | 98.6-02.9<br>02.9-03.7 | (R)BH-T833<br>(L)BH-T834<br>(R)BH-T833<br>(L)BH-T834 | (R)BH-T836<br>(L)BH-T836<br>(R)<br>(L) | | | (オートマチック) | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CAMRY, CAMRY GRACIA : 20 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2200) | E－SXV20・20W<br>＜GF－は98．8～＞ | 96.12-01.9 | 1 | | TK-T370 | 96.12-01.9 | 57.2 | DISC | MP-50 | CPM-68 | 96.12-99.8<br>99.8-01.9<br><ﾜｺﾞﾝ><br>96.12-99.8<br>99.8-01.9 | 31.7<br><br><br><br>34.9 | DISC<br>DISC<br><br><br>DISC<br>DISC | MP-78<br>MP-98<br><br><br>MP-82<br>MP-98 | <br>CPM-98<br><br><br><br>CPM-98 | 96.12-01.9 | (R)BH-T702<br>(L)BH-T703 | (R)BH-T739<br>(L)BH-T704 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | E－SXV25W(4WD)<br>GF－SXV25・25W(4WD)<br>＜GF－は98．8～＞ | 97.6-01.9 | 1 | | TK-T370 | 97.6-01.9 | | DISC | A-678P | CPA-678 | 97.6-01.9 | 34.9 | DISC | MP-82 | | 97.6-01.9 | (R)BH-T702<br>(L)BH-T703 | (R)BH-T707<br>(L)BH-T706 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (2500) | E－MCV21・21W<br>＜GF－は98．8～＞ | 96.12-01.9<br><ﾄﾗｸｼｮﾝｺﾝﾄﾛｰﾙ付><br>96.12-99.8<br>99.8-01.9 | 1<br><br>1 | | TK-T370<br><br>TK-T414 | 96.12-01.9 | | DISC | A-678P | CPA-678 | 96.12-99.8<br>99.8-01.9<br><ﾜｺﾞﾝ><br>96.12-99.8<br>99.8-01.9 | 31.7<br><br><br><br>34.9 | DISC<br>DISC<br><br><br>DISC<br>DISC | MP-78<br>MP-98<br><br><br>MP-82<br>MP-98 | <br>CPM-98<br><br><br><br>CPM-98 | 96.12-01.9 | (R)BH-T702<br>(L)BH-T703 | (R)BH-T739<br>(L)BH-T704 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | E－MCV25W(4WD)<br>＜GF－は98．8～＞ | 97.6-01.9 | 1 | | TK-T370 | 97.6-01.9 | | DISC | A-678P | CPA-678 | 97.6-01.9 | 34.9 | DISC | MP-82 | | 97.6-01.9 | (R)BH-T702<br>(L)BH-T703 | (R)BH-T707<br>(L)BH-T706 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CAMRY : ACV30 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2400) | UA－ACV30 | 01.9- | | | | 01.9- | | DISC | MP-106 | CPM-106 | 01.9- | | DISC | MP-100 | | 01.9- | (R)BH-T804<br>(L)BH-T805 | (R)BH-T806<br>(L)BH-T807 | | | (オートマチック) | | | | | |
| | UA－ACV35(4WD) | 01.9- | | | | 01.9- | | DISC | MP-106 | CPM-106 | 01.9- | | DISC | MP-105 | | 01.9- | (R)BH-T804<br>(L)BH-T805 | (R)<br>(L) | | | (オートマチック) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CAMRY : ACV40 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2400) | DBA－ACV40 | | 06.2-11.8 | | | | 06.2-07.5<br>07.5-11.8 | | DISC<br>DISC | MP-114 | CPM-106<br>CPM-106 | 06.2-07.10<br>07.10-11.8 | | DISC<br>DISC | SP-134<br>SP-416 | CPS-134<br>CPS-134 | 06.2-07.1<br><br>07.1-11.8 | (R)<br>(L)<br>(R)BH-T950<br>(L)BH-T951 | (R)BH-T806<br>(L)BH-T807<br>(R)BH-T806<br>(L)BH-T807 | | | (オートマチック) | | | | | |
| | DBA－ACV45 4WD | | 06.2-11.8 | | | | 06.2-07.5<br>07.5-11.8 | | DISC<br>DISC | MP-114 | CPM-106<br>CPM-106 | 06.2-09.7<br>09.7-10.12<br>10.12-11.6 | 38.1 | DISC<br>DISC<br>DISC | MP-100<br>SP-420 | | 06.2-07.1<br><br>07.1-11.8 | (R)<br>(L)<br>(R)BH-T950<br>(L)BH-T951 | (R)<br>(L)<br>(R)<br>(L) | | | (オートマチック) | | | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CAMRY : AVV50 ser. | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2500) DAA－AVV50 ハイブリット | 11.8-17.4 | | | ｷｯﾄｾｯﾃｲﾅｼ | 11.8-17.4 | | DISC | MP-106 | CPM-106 | 11.8-17.4 | | DISC | SP-416 | CPS-134 | 11.8-17.4 | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CAMRY : AXVH70 ser.(2017.6-) | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2500) DAA－AXVH70 | 17.6- | | ﾌﾞｰｽﾀｰ | ｷｯﾄｾｯﾃｲﾅｼ | 17.6- | | DISC | | CPM-116 | 17.6- | | DISC | | | 17.6- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| SAI : AZK10 ser. | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2400) DAA－AZK10 | 09.12- | | | | 09.12- | | DISC | MP-114 | CPM-106 | 09.12-10.1<br>10.1-11.7<br>11.7- | | DISC<br>DISC<br>DISC | SP-134<br>SP-134<br>SP-422 | CPS-134<br>CPS-134<br>CPS-134 | 09.12- | (R)<br>(L) | (R)<br>(L) | 09.12- | | (オートマチック) | | 09.12- | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| WINDOM : 10 ser. | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2500) E－VCV11 | 91.10-96.8 | 1 | | TK-T330 | 91.10-96.8 | 57.2 | DISC | MP-50 | CPM-68 | 91.10-96.8 | 34.9 | DISC | MP-82 | | 91.10-96.8 | (R)BH-T634 | (R)BH-T571 | | | (オートマチック) | | | | | |
| (3000) E－VCV10 | <アンチスキッド付> | | | | <アンチスキッド付> | | | | | | | | | | | (L)BH-T635 | (L)BH-T572 | | | | | | | | |
| | 91.10-96.8 | 1 | | TK-T370 | 91.10-93.8 | 57.2 | DISC | MP-50 | CPM-68 | | | | | | | | | | | | | | | | |
| | | | | | 93.8-96.8 | | DISC | C-322P | | | | | | | | | | | | | | | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| WINDOM : 20 ser. | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2500) E－MCV21<br>＜GF－は98．8～＞ | 96.8-01.7<br>＜ﾄﾗｸｼｮﾝｺﾝﾄﾛｰﾙ付＞<br>96.8-99.8<br>99.8-01.7 | 1<br><br>1 | | TK-T370<br><br>TK-T414 | 96.8-01.7 | | DISC | A-678P | CPA-678 | 96.8-99.8<br>99.8-01.7 | | DISC<br>DISC | MP-78<br>MP-98 | CPM-98 | 96.8-01.7 | (R)BH-T702<br>(L)BH-T703 | (R)BH-T739<br>(L)BH-T704 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (3000) E－MCV20<br>＜GF－は98．8～＞<br>＜GH－は99．8～＞<br>＜TA－は00．8～＞ | 96.8-98.8<br>＜ﾄﾗｸｼｮﾝｺﾝﾄﾛｰﾙ付＞<br>96.8-98.8<br>98.8-99.8<br>99.8-01.7 | 1<br><br>1 | | TK-T370<br><br>TK-T414 | 96.8-01.7 | | DISC | A-678P | CPA-678 | 96.8-99.8<br>99.8-01.7 | | DISC<br>DISC | MP-78<br>MP-98 | CPM-98 | 96.8-01.7 | (R)BH-T702<br>(L)BH-T703 | (R)BH-T739<br>(L)BH-T704 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| WINDOM : 30 ser. | | | | | | | | | | | | | | | | | | | | | | | | | |
| (3000) TA－MCV30 | 01.7-<br><VSC付><br>01.7- | | | | 01.7- | | DISC | MP-107 | | 01.7- | | DISC | MP-100 | | 01.7- | (R)BH-T804<br>(L)BH-T805 | (R)BH-T806<br>(L)BH-T807 | | | (オートマチック) | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CEPTER : | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2200) | E－SXV10（セダン） | 92.11-96.8 | 1 | | TK-T330 | 92.11-96.8 | 57.2 | DISC | MP-50 | | 92.11-96.8 | 34.9 | DISC | MP-82 | | 92.11-96.8 | (R)BH-T634<br>(L)BH-T635 | (R)BH-T571<br>(L)BH-T572 | | | (オートマチック) | | | | | |
| | | <アンチスキッド付><br>92.11-96.8 | 1 | | TK-T370 | | | | | | | | | | | | | | | | | | | | | |
| | E－SXV15W（ワゴン）<br>E－SXV15（クーペ） | 92.12-95.10<br>95.10-96.7 | 1 | | TK-T330 | 92.12-93.9<br>93.9-93.12 | 57.2<br>57.2 | DISC<br>DISC | MP-50<br>MP-50 | <br>CPM-68 | 92.12-96.7 | 34.9 | DISC | MP-82 | | 92.12-96.7 | (R)BH-T634<br>(L)BH-T635 | (R)BH-T571<br>(L)BH-T572 | | | (オートマチック) | | | | | |
| | | <アンチスキッド付><br>92.12-96.7 | 1 | | TK-T370 | 93.12-96.7 | 57.2 | DISC | MP-50 | | | | | | | | | | | | | | | | | |
| (3000) | E－VCV10（セダン） | 92.11-96.8 | 1 | | TK-T330 | 92.11-96.8 | 57.2 | DISC | MP-50 | | 92.11-96.8 | 34.9 | DISC | MP-82 | | 92.11-96.8 | (R)BH-T634<br>(L)BH-T635 | (R)BH-T571<br>(L)BH-T572 | | | (オートマチック) | | | | | |
| | | <アンチスキッド付><br>92.11-96.8 | 1 | | TK-T370 | <アンチスキッド付><br>92.7-93.8 | 57.2 | DISC | MP-50 | | | | | | | | | | | | | | | | | |
| | | | | | | 93.8-96.8 | | DISC | C-322P | | | | | | | | | | | | | | | | | |
| | E－VCV15W（ワゴン） | 92.7-96.7 | 1 | | TK-T330 | 除く(3.0G)<br>92.7-93.9 | 57.2 | DISC | MP-50 | | 92.7-93.9 | 34.9 | DISC | MP-82 | | 92.7-96.7 | (R)BH-T634 | (R)BH-T571 | | | (オートマチック) | | | | | |
| | | <アンチスキッド付><br>92.7-96.7 | 1 | | TK-T370 | 93.9-94.8<br>94.8-96.7 | | DISC<br>DISC | MP-50<br>C-322P | CPM-68 | 93.9-96.7 | 1 1/2 | DISC | MP-76 | | | (L)BH-T635 | (L)BH-T572 | | | | | | | | |
| | | | | | | <3.0G><br>92.7-93.9 | 57.2 | DISC | MP-50 | | | | | | | | | | | | | | | | | |
| | | | | | | 93.9-96.7 | | DISC | C-322P | | | | | | | | | | | | | | | | | |
| | E－VCV15（クーペ） | 92.7-96.7 | 1 | | TK-T330 | 92.7-94.8 | 57.2 | DISC | MP-50 | | 92.7-96.7 | 34.9 | DISC | MP-82 | | 92.7-96.7 | (R)BH-T634 | (R)BH-T571 | | | (オートマチック) | | | | | |
| | | <アンチスキッド付><br>92.7-96.7 | 1 | | TK-T370 | 94.8-94.9<br><3.0G> | | DISC | C-322P | | | | | | | | (L)BH-T635 | (L)BH-T572 | | | | | | | | |
| | | | | | | 92.7-93.9 | 57.2 | DISC | MP-50 | | | | | | | | | | | | | | | | | |
| | | | | | | 93.9-96.7 | | DISC | C-322P | | | | | | | | | | | | | | | | | |

| Models | TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CARINA : 10, 30 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1400) | TA10・15 | STD・DX(ドラム車) | 70.12-73.9<br>73.9-75.9 | 11/16<br>13/16 | | MK-3048<br>TK-9331 | 70.12-73.9<br><br><br><br><br>73.9-75.9 | 15/16<br><br><br><br><br>7/8 | (R-1)WC-1066<br>(R-2)WC-2056<br>(L-1)WC-3066<br>(L-2)WC-4056<br>(R-1)WC-51000<br>(R-2)WC-52000<br>(L-1)WC-53000<br>(L-2)WC-54000 | WK-082<br><br><br><br><br>WK-054 | CUP<br><br><br><br><br>CUP | 70.12-75.9 | 11/16 | (R)WC-50041<br>(L)WC-50041 | WK-083 | CUP | 70.12-75.9 | | BH-T822 | 70.12-75.9 | 5/8 | MC-10046 | MK-4300 | 7012-7312<br>73.12-75.9 | 3/4<br>3/4 | CC-14011<br>CC-14012 | CK-41480<br>CK-3108 |
| | | DX・SDX(ディスク車) | 70.12-72.7<br>72.8-75.9 | 13/16<br>13/16 | | TK-9314<br>TK-9314 | 70.12-74.1<br>74.1-75.9 | 1 7/8<br>2 | DISC<br>DISC | C-16<br>A-16P | | 70.12-75.9 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 70.12-75.9 | (1)<br>(2)BH-02163 | BH-T822 | 70.12-75.9 | 5/8 | MC-10046 | MK-4300 | 7012-7312<br>73.12-75.9 | 3/4<br>3/4 | CC-14011<br>CC-14012 | CK-41480<br>CK-3108 |
| (1600) | TA12 | DX(ドラム車) | 70.12-73.9<br>73.9-75.9 | 11/16<br>13/16 | | MK-3048<br>TK-9331 | 70.12-73.9<br><br><br><br><br>73.9-75.9 | 15/16<br><br><br><br><br>7/8 | (R-1)WC-1066<br>(R-2)WC-2056<br>(L-1)WC-3066<br>(L-2)WC-4056<br>(R-1)WC-51000<br>(R-2)WC-52000<br>(L-1)WC-53000<br>(L-2)WC-54000 | WK-082<br><br><br><br><br>WK-054 | CUP<br><br><br><br><br>CUP | 70.12-75.9 | 11/16 | (R)WC-50041<br>(L)WC-50041 | WK-083 | CUP | 70.12-75.9 | | BH-T822 | 70.12-75.9 | 5/8 | MC-10046 | MK-4300 | 7012-7312<br>73.12-75.9 | 3/4<br>3/4 | CC-14011<br>CC-14012 | CK-41480<br>CK-3108 |
| | | DX(ディスク車)<br>ST・GT・SDX | 70.12-75.9 | 13/16 | | TK-9314 | 70.12-74.1<br>74.1-75.9 | 1 7/8<br>2 | DISC<br>DISC | C-16<br>A-16P | | 70.12-75.9 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 70.12-75.9 | (1)<br>(2)BH-02163 | BH-T822 | 70.12-75.9 | 5/8 | MC-10046 | MK-4300 | 7012-7312<br>73.12-75.9 | 3/4<br>3/4 | CC-14011<br>CC-14012 | CK-41480<br>CK-3108 |
| | TA14 | STD・DX(ドラム車) | 75.10-76.4 | 13/16 | | TK-9345 | 75.10-76.4 | 7/8 | (R-1)WC-51000<br>(R-2)WC-52000<br>(L-1)WC-53000<br>(L-2)WC-54000 | WK-054 | CUP | 75.10-76.4 | 11/16 | (R)WC-50041<br>(L)WC-50041 | WK-083 | CUP | 75.10-76.4 | | BH-T822 | 75.10-76.4 | 5/8 | MC-10046 | MK-4300 | 75.10-76.4 | 3/4 | CC-70102 | CK-3108 |
| | | STD・DX(ディスク車)<br>SDX・ST | 75.10-76.4 | 13/16 | | TK-9346 | 75.10-76.4 | 2 | DISC | A-16P | | 75.10-76.4 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 75.10-76.4 | (1)<br>(2)BH-02224 | BH-T822 | 75.10-76.4 | 5/8 | MC-10046 | MK-4300 | 75.10-76.4 | 3/4 | CC-70102 | CK-3108 |
| | TA17 | | 72.12-75.9<br><GT><br>72.8-75.9 | 13/16<br><br>13/16 | | TK-9314<br><br>TK-9314 | 72.12-74.1<br>74.1-75.9 | 1 7/8<br>2 | DISC<br>DISC | C-16<br>A-16P | | 72.12-75.9 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 72.12-75.9 | (1)<br>(2)BH-02163 | BH-T822 | 72.12-75.9 | 5/8 | MC-10046 | MK-4300 | 7212-7312<br>73.12-75.9 | 3/4<br>3/4 | CC-14011<br>CC-14012 | CK-41480<br>CK-3108 |
| (1600) | TA18 | | 75.10-76.4 | 13/16 | | TK-9346 | 75.10-76.4 | 2 | DISC | A-16P | | 75.10-76.4 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 75.10-76.4 | (1)<br>(2)BH-02224 | BH-T822 | 75.10-76.4 | 5/8 | MC-10046 | MK-4300 | 75.10-76.4 | 3/4 | CC-70102 | CK-3108 |
| | TA30・31 | STD・DX(ドラム車) | 76.3-77.7 | 13/16 | | TK-9345 | 76.3-77.7 | 7/8 | (R-1)WC-51000<br>(R-2)WC-52000<br>(L-1)WC-53000<br>(L-2)WC-54000 | WK-054 | CUP | 76.3-77.7 | 11/16 | (R)WC-50041<br>(L)WC-50041 | WK-083 | CUP | 76.3-77.7 | | BH-T822 | 76.3-77.7 | 5/8 | MC-10046 | MK-4300 | 76.3-77.7 | 3/4 | CC-70102 | CK-3108 |
| | | STD・DX(ディスク車)<br>SDX・SR・ST | 76.3-77.7 | 13/16 | | TK-9346 | 76.3-77.7 | 2 | DISC | A-16P | | 76.3-77.7 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 76.3-77.7 | (1)<br>(2)BH-02224 | BH-T822 | 76.3-77.7 | 5/8 | MC-10046 | MK-4300 | 76.3-77.7 | 3/4 | CC-70102 | CK-3108 |
| (1800) | TA32 | | 77.3-77.7 | 13/16 | | TK-9346 | 77.3-77.7 | 2 | DISC | A-16P | | 77.3-77.7 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 77.3-77.7 | (1)<br>(2)BH-02224 | BH-T822 | 77.3-77.7 | 5/8 | MC-10046 | MK-4300 | 77.3-77.7 | 3/4 | CC-70102 | CK-3108 |
| | RA10・16 | | 75.10-77.2 | 13/16 | | TK-9346 | 75.10-77.2 | 2 | DISC | A-16P | | 75.10-77.2 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 75.10-77.2 | (1)<br>(2)BH-02224 | BH-T822 | 75.10-77.2 | 5/8 | MC-10046 | MK-4300 | 75.10-77.2 | 3/4 | CC-70102 | CK-3108 |
| (2000) | RA11・13・15 | | 74.1-75.9<br><RA15 GT><br>74.1-75.9 | 13/16<br><br>13/16 | | TK-9314<br><br>TK-9314 | 74.1-75.9 | 2 | DISC | A-16P | | 74.1-75.9 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 74.1-75.9 | (1)<br>(2)BH-02163 | BH-T822 | 74.1-75.9<br><GT><br>74.1-75.9 | 5/8<br><br>5/8 | MC-10046<br><br>MC-10047 | MK-4300<br><br>MK-4300 | 74.1-75.9 | 3/4 | CC-70090 | CK-3108 |
| | RA14・17・30 | | 75.10-77.7 | 13/16 | | TK-9346 | 75.10-77.7 | 2 | DISC | A-16P | | 75.10-77.7 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 75.10-77.7 | (1)<br>(2)BH-02224 | BH-T822 | 75.10-77.7 | 5/8 | MC-10046 | MK-4300 | 75.10-77.7 | 3/4 | CC-70102 | CK-3108 |
| | RA31 | | 76.3-77.7 | 13/16 | | TK-9346 | 76.3-77.7 | 2 | DISC | A-16P | | 76.3-77.7 | 3/4 | (R)WC-50060<br>(R)WC-50060 | WK-491 | CUP | 76.3-77.7 | (1)<br>(2)BH-02224 | BH-T822 | 76.3-77.7 | 5/8 | MC-10046 | MK-4300 | 76.3-77.7 | 3/4 | CC-70102 | CK-3108 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CARINA : 16, 19, 40 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1400) | TA16V(バン) | ドラム車 | 75.12-77.7<br>77.8-79.8 | 13/16<br>13/16 | | TK-9345<br>TK-9346 | 75.12-79.8 | 7/8 | (R-1)WC-51000<br>(R-2)WC-52000<br>(L-1)WC-53000<br>(L-2)WC-54000 | WK-054 | CUP | 75.12-79.8 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 75.12-79.8 | | BH-31304 | 75.12-78.4<br>78.4-79.2<br>79.2-79.8 | 5/8<br>5/8<br>5/8 | MC-10046<br>MC-10077<br>MC-10094 | MK-4300<br>MK-4300<br>MK-4308 | 75.12-77.8<br>77.8-79.8 | 3/4<br>13/16 | CC-70102<br>CC-70110 | CK-3108<br>CK-3113 |
| | | ディスク車 | 75.12-79.8 | 13/16 | | TK-9346 | 75.12-79.8 | 2 | DISC | A-16P | | 75.12-79.8 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 75.12-79.8 | (1)<br>(2)BH-02224 | BH-31304 | 75.12-78.4<br>78.4-79.2<br>79.2-79.8 | 5/8<br>5/8<br>5/8 | MC-10046<br>MC-10077<br>MC-10094 | MK-4300<br>MK-4300<br>MK-4308 | 75.12-77.8<br>77.8-79.8 | 3/4<br>13/16 | CC-70102<br>CC-70110 | CK-3108<br>CK-3113 |
| (1600) | TA19V(バン)<br>TA49V(バン) | ドラム車 | 75.12-77.7<br>77.8-81.8 | 13/16<br>13/16 | | TK-9345<br>TK-9346 | 75.12-81.8 | 7/8 | (R-1)WC-51000<br>(R-2)WC-52000<br>(L-1)WC-53000<br>(L-2)WC-54000 | WK-054 | CUP | 75.12-81.8 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 75.12-81.8 | | BH-31304 | 75.12-78.4<br>78.4-79.2<br>79.2-81.8 | 5/8<br>5/8<br>5/8 | MC-10046<br>MC-10077<br>MC-10094 | MK-4300<br>MK-4300<br>MK-4308 | 75.12-80.8<br>80.8-81.1<br>81.1-81.8 | 13/16<br>13/16<br>13/16 | CC-70110<br>CC-70111<br>CC-70111 | CK-3113<br>CK-3113<br>CK-3144 |
| | | ディスク車 | 75.12-81.8 | 13/16 | | TK-9346 | 75.12-81.8 | 2 | DISC | A-16P | | 75.12-81.8 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 75.12-81.8 | (1)<br>(2)BH-02224 | BH-31304 | 75.12-78.4<br>78.4-79.2<br>79.2-81.8 | 5/8<br>5/8<br>5/8 | MC-10046<br>MC-10077<br>MC-10094 | MK-4300<br>MK-4300<br>MK-4308 | 75.12-80.8<br>80.8-81.1<br>81.1-81.8 | 13/16<br>13/16<br>13/16 | CC-70110<br>CC-70111<br>CC-70111 | CK-3113<br>CK-3113<br>CK-3144 |
| | TA40 | | 77.8-78.5 | 13/16 | | TK-9346 | 77.8-78.5 | 2 | DISC | A-16P | | 77.8-78.5 | 1 3/8 | DISC | A-43P<br>A-46LP | | 77.8-78.5 | (1)<br>(2)BH-02224 | (C)BH-T822<br>(R)BH-02377<br>(L)BH-02377 | 77.8-78.4<br>78.4-78.5 | 5/8<br>5/8 | MC-10046<br>MC-10077 | MK-4300<br>MK-4300 | 77.8-78.5 | 13/16 | CC-70110 | CK-3113 |
| | TA41 | STD(ドラム車) | 77.8-81.8 | 13/16 | | TK-9346 | 77.8-81.8 | 7/8 | (R-1)WC-51000<br>(R-2)WC-52000<br>(L-1)WC-53000<br>(L-2)WC-54000 | WK-054 | CUP | 77.8-81.8 | 11/16 | (R)WC-50041<br>(L)WC-50041 | WK-083 | CUP | 77.8-78.8<br>78.8-81.8 | | BH-T822<br>BH-02394 | 77.8-78.4<br>78.4-79.2<br>79.2-81.8 | 5/8<br>5/8<br>5/8 | MC-10046<br>MC-10077<br>MC-10094 | MK-4300<br>MK-4300<br>MK-4308 | 77.8-80.8<br>80.8-81.1<br>81.1-81.8 | 13/16<br>13/16<br>13/16 | CC-70110<br>CC-70111<br>CC-70111 | CK-3113<br>CK-3113<br>CK-3144 |
| | | STD(ディスク車) | 77.8-81.8 | 13/16 | | TK-9346 | 77.8-81.8 | 2 | DISC | A-16P | | 77.8-81.8 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 77.8-78.8<br>78.8-81.8 | (1)<br>(2)BH-02224<br>(1)<br>(2)BH-02224 | BH-T822<br>BH-02394 | 77.8-78.4<br>78.4-79.2<br>79.2-81.8 | 5/8<br>5/8<br>5/8 | MC-10046<br>MC-10077<br>MC-10094 | MK-4300<br>MK-4300<br>MK-4308 | 77.8-80.8<br>80.8-81.1<br>81.1-81.8 | 13/16<br>13/16<br>13/16 | CC-70110<br>CC-70111<br>CC-70111 | CK-3113<br>CK-3113<br>CK-3144 |
| | | DX・SDX・ST<br>SR(リヤードラム) | 77.8-81.8 | 13/16 | | TK-9346 | 77.8-81.8 | 2 | DISC | A-16P | | 77.8-81.8 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 77.8-78.8<br>78.8-81.8 | (1)<br>(2)BH-02224<br>(1)<br>(2)BH-02224 | BH-T822<br>BH-02394 | 77.8-78.4<br>78.4-79.2<br>79.2-81.8 | 5/8<br>5/8<br>5/8 | MC-10046<br>MC-10077<br>MC-10094 | MK-4300<br>MK-4300<br>MK-4308 | 77.8-80.8<br>80.8-81.1<br>81.1-81.8 | 13/16<br>13/16<br>13/16 | CC-70110<br>CC-70111<br>CC-70111 | CK-3113<br>CK-3113<br>CK-3144 |
| (1600) | TA41 | SR(四輪ディスク) | 77.8-81.8 | 13/16 | | TK-9346 | 77.8-81.8 | 2 | DISC | A-16P | | 77.8-79.8<br>79.8-80.3<br>80.3-81.8 | 1 3/8<br>1 3/8<br>1 3/8 | DISC<br>DISC<br>DISC | A-43P<br>A-46LP | | 77.8-78.8<br>78.8-81.8 | (1)<br>(2)BH-02224<br>(1)<br>(2)BH-02224 | (C)BH-T822<br>(R)BH-02377<br>(L)BH-02377<br>(C)BH-02394<br>(R)BH-02377<br>(L)BH-02377 | 77.8-78.4<br>78.4-79.2<br>79.2-81.8 | 5/8<br>5/8<br>5/8 | MC-10046<br>MC-10077<br>MC-10094 | MK-4300<br>MK-4300<br>MK-4308 | 77.8-80.8<br>80.8-81.1<br>81.1-81.8 | 13/16<br>13/16<br>13/16 | CC-70110<br>CC-70111<br>CC-70111 | CK-3113<br>CK-3113<br>CK-3144 |
| | TA45 | | 78.5-81.8 | 13/16 | | TK-9346 | 78.5-81.8 | 2 | DISC | A-16P | | 77.8-79.8<br>79.8-80.3<br>80.3-81.8 | 1 3/8<br>1 3/8<br>1 3/8 | DISC<br>DISC<br>DISC | A-43P<br>A-46LP | | 78.5-78.8<br>78.8-81.8 | (1)<br>(2)BH-02224<br>(1)<br>(2)BH-02224 | (C)BH-T822<br>(R)BH-02377<br>(L)BH-02377<br>(C)BH-02394<br>(R)BH-02377<br>(L)BH-02377 | 78.5-79.2<br>79.2-81.8 | 5/8<br>5/8 | MC-10077<br>MC-10094 | MK-4300<br>MK-4308 | 78.5-80.8<br>80.8-81.1<br>81.1-81.8 | 13/16<br>13/16<br>13/16 | CC-70110<br>CC-70111<br>CC-70111 | CK-3113<br>CK-3113<br>CK-3144 |
| (1800) | TA42 | DX・SDX・SE・ST<br>SR(リヤードラム) | 77.8-78.5 | 13/16 | | TK-9346 | 77.8-78.5 | 2 | DISC | A-16P | | 77.8-78.5 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 77.8-78.5 | (1)<br>(2)BH-02224 | BH-T822 | 77.8-77.11<br>77.11-78.5 | 5/8 | MC-10046<br>(オートマチック) | MK-4300 | 77.8-77.11 | 13/16 | CC-70110 | CK-3113 |
| | | SR(四輪ディスク) | 77.8-77.11 | 13/16 | | TK-9346 | 77.8-77.11 | 2 | DISC | A-16P | | 77.8-77.11 | 1 3/8 | DISC | A-43P<br>A-46LP | | 77.8-77.11 | (1)<br>(2)BH-02224 | (C)BH-T822<br>(R)BH-02377<br>(L)BH-02377 | 77.8-77.11 | 5/8 | MC-10046 | MK-4300 | 77.8-77.11 | 13/16 | CC-70110 | CK-3113 |
| | TA46 | DX・SDX・SE・ST<br>SR(リヤードラム) | 77.11-81.8 | 13/16 | | TK-9346 | 77.11-81.8 | 2 | DISC | A-16P | | 77.11-81.8 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 77.11-78.8<br>78.8-81.8 | (1)<br>(2)BH-02224<br>(1)<br>(2)BH-02224 | BH-T822<br>BH-02394 | 77.11-78.4<br>78.4-79.2<br>79.2-81.8 | 5/8<br>5/8<br>5/8 | MC-10046<br>MC-10077<br>MC-10094 | MK-4300<br>MK-4300<br>MK-4308 | 77.11-80.8<br>80.8-81.1<br>81.1-81.8 | 13/16<br>13/16<br>13/16 | CC-70110<br>CC-70111<br>CC-70111 | CK-3113<br>CK-3113<br>CK-3144 |
| | | SR(四輪ディスク) | 77.11-81.8 | 13/16 | | TK-9346 | 77.11-81.8 | 2 | DISC | A-16P | | 77.8-79.8<br>79.8-80.3<br>80.3-81.8 | 1 3/8<br>1 3/8<br>1 3/8 | DISC<br>DISC<br>DISC | A-43P<br>A-46LP | | 77.11-78.8<br>78.8-81.8 | (1)<br>(2)BH-02224<br>(1)<br>(2)BH-02224 | (C)BH-T822<br>(R)BH-02377<br>(L)BH-02377<br>(C)BH-02394<br>(R)BH-02377<br>(L)BH-02377 | 77.11-78.4<br>78.4-79.2<br>79.2-81.8 | 5/8<br>5/8<br>5/8 | MC-10046<br>MC-10077<br>MC-10094 | MK-4300<br>MK-4300<br>MK-4308 | 77.11-80.8<br>80.8-81.1<br>81.1-81.8 | 13/16<br>13/16<br>13/16 | CC-70110<br>CC-70111<br>CC-70111 | CK-3113<br>CK-3113<br>CK-3144 |
| (1800) | TA47 | リヤードラム車 | 78.8-81.8 | 13/16 | | TK-9346 | 78.8-81.8 | 2 | DISC | A-16P | | 78.8-81.8 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 78.8-81.8 | (1)<br>(2)BH-02224 | BH-02394 | 78.8-79.2<br>79.2-81.8 | 5/8<br>5/8 | MC-10077<br>MC-10094 | MK-4300<br>MK-4308 | 78.8-81.1<br>81.1-81.8 | 13/16<br>13/16 | CC-70109<br>CC-70109 | CK-3113<br>CK-3144 |
| | | 四輪ディスク車 | 78.8-81.8 | 13/16 | | TK-9346 | 78.8-81.8 | 2 | DISC | A-16P | | 78.8-79.8<br>79.8-80.3<br>80.3-81.8 | 1 3/8<br>1 3/8<br>1 3/8 | DISC<br>DISC<br>DISC | A-43P<br>A-46LP | | 78.8-81.8 | (1)<br>(2)BH-02224 | (C)BH-02394<br>(R)BH-02377<br>(L)BH-02377 | 78.8-79.2<br>79.2-81.8 | 5/8<br>5/8 | MC-10077<br>MC-10094 | MK-4300<br>MK-4308 | 78.8-81.1<br>81.1-81.8 | 13/16<br>13/16 | CC-70109<br>CC-70109 | CK-3113<br>CK-3144 |
| (2000) | RA40 | SDX・SE・ST | 77.8-78.8 | 13/16 | | TK-9346 | 77.8-78.8 | 2 | DISC | A-16P | | 77.8-78.8 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 77.8-78.8 | (1)<br>(2)BH-02224 | BH-T822 | 77.8-78.4<br>78.4-78.8 | 5/8<br>5/8 | MC-10046<br>MC-10077 | MK-4300<br>MK-4300 | 77.8-78.8 | 13/16 | CC-70113 | CK-3113 |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| GT | 77.8-78.8 | 13/16 | | TK-9346 | 77.8-78.8 | 2 | DISC | A-16P | | 77.8-78.8 | 1 3/8 | DISC | A-43P<br>A-46LP | | 77.8-78.8 | (1)<br>(2)BH-02224 | (C)BH-T822<br>(R)BH-02377<br>(L)BH-02377 | 77.8-78.4<br>78.4-78.8 | 5/8<br>5/8 | MC-10046<br>MC-10077 | MK-4300<br>MK-4300 | 77.8-78.8 | 13/16 | CC-70113 | CK-3113 |
| RA45 | 78.8-81.8 | 13/16 | | TK-9346 | 78.8-81.8 | 2 | DISC | A-16P | | 78.8-79.8<br>79.8-80.3<br>80.3-81.8 | 1 3/8<br>1 3/8<br>1 3/8 | DISC<br>DISC<br>DISC | A-43P<br>A-46LP | | 78.8-81.8 | (1)<br>(2)BH-02224 | (C)BH-02394<br>(R)BH-02377<br>(L)BH-02377 | 78.8-79.2<br>79.2-81.8 | 5/8<br>5/8 | MC-10077<br>MC-10094 | MK-4300<br>MK-4308 | 78.8-80.8<br>80.8-81.1<br>81.1-81.8 | 13/16<br>13/16<br>13/16 | CC-70111<br>CC-70110<br>CC-70110 | CK-3113<br>CK-3113<br>CK-3144 |
| RA46 | 78.8-81.8 | 13/16 | | TK-9346 | 78.8-81.8 | 2 | DISC | A-16P | | 78.8-81.8 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 78.8-81.8 | (1)<br>(2)BH-02224 | BH-02394 | 78.8-79.2<br>79.2-81.8 | 5/8<br>5/8 | MC-10077<br>MC-10094 | MK-4300<br>MK-4308 | 78.8-80.8<br>80.8-81.1<br>81.1-81.8 | 13/16<br>13/16<br>13/16 | CC-70111<br>CC-70110<br>CC-70110 | CK-3113<br>CK-3113<br>CK-3144 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CARINA : 60 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1500) | E−AA60 | STD・DX・ST SG・SE | 81.9-87.12 | 13/16 | | TK-9389 | 81.9-87.12 | 2 | DISC | A-102P | | 81.9-87.12 | 13/16 | (R)WC-50059 (L)WC-50059 | WK-492 | CUP | 81.9-85.4 85.4-87.12 | (1)BH-02426 (2)BH-96001 BH-02474 | BH-02394 BH-02394 | 81.9-83.5 83.5-87.12 | 5/8 5/8 | MC-10118 MC-10138 | MK-4308 MK-4308 | 81.9-87.12 | 13/16 | CC-70151 | CK-3144 |
| | L−KA67V(バン) | STD・DX・SG | 83.8-88.4 | 13/16 | | TK-9389 | 83.8-88.4 | 2 | DISC | A-102P | | 83.8-88.4 | 13/16 | (R)WC-50059 (L)WC-50059 | WK-492 | CUP | 83.8-84.12 84.12-88.4 | (1)BH-02426 (2)BH-96001 BH-02474 | BH-94005 BH-94005 | 83.8-88.4 | 5/8 | MC-10138 | MK-4308 | 83.8-88.4 | 13/16 | CC-70111 | CK-3144 |
| (1600) | E−TA61 | GT | 81.9-83.5 | 15/16 | | TK-9417 | 81.9-83.5 | 2 1/4 | DISC | SP-229 | CPS-219 | 81.9-82.5 82.5-83.5 | 1 11/16 1 11/16 | DISC DISC | SP-218 SP-218 | | 81.9-83.5 | (1)BH-02426 (2)BH-96001 | (R-1)BH-95001 (L-1)BH-95001 (R-2)BH-02343 (L-2)BH-02343 | 81.9-83.5 | 5/8 | MC-10118 | MK-4308 | 81.9-83.5 | 13/16 | CC-70111 | CK-3144 |
| | E−AA63 | GT・GT−R | 83.5-85.7 | 15/16 | | TK-9417 | 83.5-85.7 | 2 1/4 | DISC | SP-229 | CPS-219 | 83.5-85.7 | 1 11/16 | DISC | SP-218 | | 83.5-85.7 | (1)BH-02426 (2)BH-96001 | (R-1)BH-95001 (L-1)BH-95001 (R-2)BH-02343 (L-2)BH-02343 | 83.5-85.7 | 5/8 | MC-10102 | MK-4300 | 83.5-85.7 | 13/16 | CC-70153 | CK-3144 |
| | L−TA67V(バン) | STD・DX・SG | 81.9-83.8 | 13/16 | | TK-9389 | 81.9-83.8 | 2 | DISC | A-102P | | 81.9-83.8 | 13/16 | (R)WC-50059 (L)WC-50059 | WK-492 | CUP | 81.9-83.8 | (1)BH-02426 (2)BH-96001 | BH-94005 | 81.9-83.5 83.5-83.8 | 5/8 5/8 | MC-10118 MC-10138 | MK-4308 MK-4308 | 81.9-83.8 | 13/16 | CC-70111 | CK-3144 |
| (1800) | E−SA60 | SE・SG・ST | 81.9-87.12 | 13/16 | | TK-9389 | 81.9-87.12 | 2 | DISC | A-102P | | 81.9-87.12 | 13/16 | (R)WC-50059 (L)WC-50059 | WK-492 | CUP | 81.9-85.4 85.4-87.12 | (1)BH-02426 (2)BH-96001 BH-02474 | BH-02394 BH-02394 | 81.9-83.5 83.5-87.12 | 5/8 5/8 | MC-10118 MC-10138 | MK-4308 MK-4308 | 81.9-87.12 | 13/16 | CC-70151 | CK-3144 |
| | E−SA60G(ワゴン) | ST(サーフ) | 82.2-88.4 | 13/16 | | TK-9389 | 82.2-88.4 | 2 | DISC | A-102P | | 82.2-88.4 | 13/16 | (R)WC-50059 (L)WC-50059 | WK-492 | CUP | 82.2-84.12 84.12-88.4 | (1)BH-02426 (2)BH-96001 BH-02474 | BH-02394 BH-02394 | 82.2-83.5 83.5-88.4 | 5/8 5/8 | MC-10118 MC-10138 | MK-4308 MK-4308 | 82.2-88.4 | 13/16 | CC-70151 | CK-3144 |
| (1800) | E−TA63 | ST | 81.9-83.5 | 15/16 | | TK-9417 | 81.9-83.5 | 2 1/4 | DISC | SP-229 | CPS-219 | 81.9-83.5 | 13/16 | (R)WC-50059 (L)WC-50059 | WK-492 | CUP | 81.9-83.5 | (1)BH-02426 (2)BH-96001 | (R)BH-95001 (L)BH-95001 | 81.9-83.5 | 5/8 | MC-10118 | MK-4308 | 81.9-83.5 | 13/16 | CC-70111 | CK-3144 |
| | | SE | 81.9-83.5 | 15/16 | | TK-9417 | 81.9-83.5 | 2 1/4 | DISC | SP-229 | CPS-219 | 81.9-82.5 82.5-83.5 | 1 11/16 1 11/16 | DISC DISC | SP-218 SP-218 | | 81.9-83.5 | (1)BH-02426 (2)BH-96001 | (R-1)BH-95001 (L-1)BH-95001 (R-2)BH-02343 (L-2)BH-02343 | 81.9-83.5 | 5/8 | MC-10118 | MK-4308 | 81.9-83.5 | 13/16 | CC-70111 | CK-3144 |
| | | GT−T・GT−TR | 82.10-85.7 | 15/16 | | TK-9417 | 82.10-85.7 | 2 1/4 | DISC | SP-229 | CPS-219 | 82.10-85.7 | 1 11/16 | DISC | SP-218 | | 82.10-85.4 85.4-85.7 | (1)BH-02426 (2)BH-96001 BH-02474 | (R-1)BH-95001 (L-1)BH-95001 (R-2)BH-02343 (L-2)BH-02343 (R-1)BH-95001 (L-1)BH-95001 (R-2)BH-02343 (L-2)BH-02343 | 82.10-83.5 83.5-85.7 | 5/8 5/8 | MC-10074 MC-10102 | MK-4300 MK-4300 | 82.10-85.7 | 13/16 | CC-70110 | CK-3144 |
| (2000) | E−RA63 | GT | 81.9-82.10 | 15/16 | | TK-9417 | 81.9-82.10 | 2 1/4 | DISC | SP-229 | CPS-219 | 81.9-82.10 | 1 11/16 | DISC | SP-218 | | 81.9-82.10 | (1)BH-02426 (2)BH-96001 | (R-1)BH-95001 (L-1)BH-95001 (R-2)BH-02343 (L-2)BH-02343 | 81.9-82.10 | 5/8 | MC-10118 | MK-4308 | 81.9-82.10 | 13/16 | CC-70110 | CK-3144 |
| (1800ディーゼル) | N−CA60 | SE・SG | 82.2-84.5 | 13/16 | | TK-9389 | 82.2-84.5 | 2 | DISC | A-102P | | 82.2-84.5 | 13/16 | (R)WC-50059 (L)WC-50059 | WK-492 | CUP | 82.2-84.5 | (1)BH-02426 (2)BH-96001 | BH-02394 | 82.2-83.5 83.5-84.5 | 5/8 5/8 | MC-10110 MC-10141 | MK-4312 MK-4312 | 82.2-84.5 | 13/16 | CC-70151 | CK-3144 |
| | N−CA67V(バン) | DX・SG | 82.2-88.4 | 13/16 | | TK-9389 | 82.2-88.4 | 2 | DISC | A-102P | | 82.2-88.4 | 13/16 | (R)WC-50059 (L)WC-50059 | WK-492 | CUP | 82.2-84.12 84.12-88.4 | (1)BH-02426 (2)BH-96001 BH-02474 | BH-94005 BH-94005 | 82.2-83.5 83.5-88.4 | 5/8 5/8 | MC-10110 MC-10141 | MK-4312 MK-4312 | 82.2-85.8 85.8-88.4 | 13/16 13/16 | CC-70151 CC-70149 | CK-3144 CK-3144 |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CARINA(FF) : 150, 160 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1500) | E−AT150 | <SG除く><br>84.5-88.4<br><SG><br>84.5-86.4<br>86.4-88.4 | 7/8<br><br>7/8<br>7/8 | | TK-9421<br><br>TK-9421<br>TK-T033 | 84.5-88.4 | 51.1 | DISC | MP-6 | | 84.5-88.4 | 3/4 | (R)WC-55021<br>(L)WC-57021 | WK-542 | CUP | 84.5-87.8<br><br>87.8-88.4 | BH-02455<br><br>BH-02455 | (R)BH-95003<br>(L)BH-95003<br>(R)<br>(L) | 84.5-84.8<br>84.8-88.4 | 5/8<br>5/8 | | MK-4310<br>MK-4344 | 84.5-88.4 | 13/16 | CC-70152 | CK-3131 |
| (1600) | E−AT151 | 84.5-88.4 | 7/8 | | TK-9421 | 84.5-88.4 | 51.1 | DISC | MP-6 | | 84.5-88.4 | 3/4 | (R)WC-55021<br>(L)WC-57021 | WK-542 | CUP | 84.5-87.8<br><br>87.8-88.4 | BH-02455<br><br>BH-02455 | (R)BH-95003<br>(L)BH-95003<br>(R)<br>(L) | 84.5-84.8<br>84.8-88.4 | 5/8<br>5/8 | | MK-4310<br>MK-4344 | 84.5-88.4 | 13/16 | CC-70152 | CK-3131 |
| | E−AT160 | 85.8-88.4 | 15/16 | | TK-T006 | 85.8-88.4 | 54.0 | DISC | MP-18 | | 85.8-88.4 | 31.7 | DISC | A-222P | | 85.8-87.8<br><br>87.8-88.4 | BH-02455<br><br>BH-02455 | (R)BH-02581<br>(L)BH-02581<br>(R)BH-02551<br>(L)BH-02551 | 85.8-88.4 | 5/8 | | MK-4344 | 85.8-88.4 | 13/16 | CC-70152 | CK-3131 |
| (1800) | E−ST150 | 84.5-88.4 | 7/8 | | TK-9421 | 84.5-88.4 | 51.1 | DISC | MP-6 | | 84.5-88.4 | 3/4 | (R)WC-55021<br>(L)WC-57021 | WK-542 | CUP | 84.5-87.8<br><br>87.8-88.4 | BH-02455<br><br>BH-02455 | (R)BH-95003<br>(L)BH-95003<br>(R)<br>(L) | 84.5-84.8<br>84.8-88.4 | 5/8<br>5/8 | | MK-4310<br>MK-4344 | 84.5-88.4 | 13/16 | CC-70150 | CK-3144 |
| (2000) | E−ST162 | 85.8-88.4 | 15/16 | | TK-T006 | 85.8-88.4 | 54.0 | DISC | MP-18 | | 85.8-88.4 | 31.7 | DISC | A-222P | | 85.8-87.8<br><br>87.8-88.4 | BH-02455<br><br>BH-02455 | (R)BH-02581<br>(L)BH-02581<br>(R)BH-02551<br>(L)BH-02551 | 85.8-88.4 | 5/8 | | MK-4344 | 85.8-88.4 | 13/16 | CC-70150 | CK-3144 |
| (2000ディーゼル)<br>N−CT150<br>Q−CT150 | | 84.5-88.4 | 7/8 | | TK-9421 | 84.5-88.4 | 51.1 | DISC | MP-6 | | 84.5-88.4 | 3/4 | (R)WC-55021<br>(L)WC-57021 | WK-542 | CUP | 84.5-87.8<br><br>87.8-88.4 | BH-02455<br><br>BH-02455 | (R)BH-95003<br>(L)BH-95003<br>(R)<br>(L) | 84.5-86.9<br>86.9-88.4 | 5/8<br>5/8 | MC-10140 | MK-4312<br>MK-4337 | 84.5-88.4 | 13/16 | CC-70150 | CK-3144 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CARINA(FF) : 170 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1500) | E−AT170 | | 88.5−91.5 | 7/8 | | TK−T033 | 88.5−92.8 | 54.0 | DISC | MP−20 | CPM−19 | 88.5−92.8 | 11/16 | (R)WC−55020 | WK−569 | CUP | 88.5−92.8 | BH−02565 | (R)BH−02497 | 88.5−90.5 | 5/8 | MC−T235 | MK−4344 | 88.5−92.8 | 13/16 | CC−70183 | CK−3144 |
| | | | 91.5−92.8 | | | | | | | | | | | (L)WC−57020 | | | | | (L)BH−02497 | 90.5−92.8 | 5/8 | MC−T392 | MK−T236 | | | | |
| | | | <アンチスキッド付> | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | 88.8−92.8 | 15/16 | | TK−T049 | | | | | | | | | | | | | | | | | | | | | |
| | E−AT170G(ワゴン) | | 88.5−90.5 | 7/8 | | TK−T032 | 88.5−92.11 | 54.0 | DISC | MP−20 | CPM−19 | 88.5−92.11 | 11/16 | (R)WC−55020 | WK−569 | CUP | 88.5−92.11 | BH−02565 | (R)BH−02497 | 88.5−90.5 | 5/8 | MC−T235 | MK−4344 | 88.5−92.11 | 13/16 | CC−70183 | CK−3144 |
| | | | 90.5−91.5 | 7/8 | | TK−T033 | | | | | | | | (L)WC−57020 | | | | | (L)BH−02497 | 90.5−92.11 | 5/8 | MC−T392 | MK−T236 | | | | |
| | | | 91.5−92.11 | | | | | | | | | | | | | | | | | | | | | | | | |
| | L−ET176V(バン) | | 88.5−92.11 | 7/8 | | TK−T032 | 88.5−92.11 | 54.0 | DISC | MP−20 | CPM−19 | 88.5−92.11 | 3/4 | (R)WC−55021 | WK−542 | CUP | 88.5−92.11 | BH−02565 | (R)BH−02539 | 88.5−89.11 | 5/8 | MC−T235 | MK−4344 | 88.5−92.11 | 13/16 | CC−70179 | CK−3144 |
| | <R−は89．11〜> | | | | | | | | | | | | | (L)WC−57021 | | | | | (L)BH−02539 | 89.11−92.11 | 5/8 | MC−T392 | MK−T236 | | | | |
| (1600) | E−AT171 | S | 88.5−90.5 | 7/8 | | TK−T032 | 88.5−90.5 | 54.0 | DISC | MP−20 | | 88.5−90.5 | 11/16 | (R)WC−55020 | WK−569 | CUP | 88.5−92.8 | BH−02565 | (R)BH−02497 | 88.5−90.5 | 5/8 | MC−T235 | MK−4344 | 88.5−92.8 | 13/16 | CC−70183 | CK−3144 |
| | | | 90.5−92.8 | 15/16 | | TK−T349 | 90.5−92.8 | 57.2 | DISC | MP−20 | CPM−19 | | | (L)WC−57020 | | | | | (L)BH−02497 | 90.5−92.8 | 5/8 | MC−T392 | MK−T236 | | | | |
| | | | <アンチスキッド付> | | | | | | | | | 90.5−92.8 | 3/4 | (R)WC−55021 | WK−542 | CUP | | | | | | | | | | | |
| | | | 88.8−90.5 | 15/16 | | TK−T049 | | | | | | | | (L)WC−57021 | | | | | | | | | | | | | |
| | | | 90.5−92.8 | 1 | | TK−T048 | | | | | | | | | | | | | | | | | | | | | |
| | | Gリミテッド | 88.5−92.8 | 15/16 | | TK−T349 | 88.5−92.8 | 57.2 | DISC | MP−21 | | 88.5−91.6 | 31.7 | DISC | A−222P | | 88.5−92.8 | BH−02565 | (R)BH−02498 | 88.5−90.5 | 5/8 | MC−T235 | MK−4344 | 88.5−92.8 | 13/16 | CC−70183 | CK−3144 |
| | | | <アンチスキッド付> | | | | | | | | | 91.6−92.8 | 31.7 | DISC | A−222P | | | | (L)BH−02498 | 90.5−92.8 | 5/8 | MC−T392 | MK−T236 | | | | |
| | | | 88.5−92.8 | 1 | | TK−T048 | | | | | | | | | | | | | | | | | | | | | |
| | E−AT175(4WD) | | 88.8−92.8 | 15/16 | | TK−T349 | 88.8−92.8 | 57.2 | DISC | MP−21 | | 88.8−91.6 | 34.9 | DISC | MP−82 | | 88.8−92.8 | BH−02550 | (R)BH−02549 | 88.8−90.5 | 5/8 | MC−T235 | MK−4344 | 88.8−92.8 | 13/16 | CC−70183 | CK−3144 |
| | | | <アンチスキッド付> | | | | | | | | | 81.6−92.8 | 34.9 | DISC | MP−82 | | | | (L)BH−02549 | 90.5−92.8 | 5/8 | MC−T392 | MK−T236 | | | | |
| | | | 90.5−92.8 | 15/16 | | TK−T300 | | | | | | | | | | | | | | | | | | | | | |
| (1800) | E−ST170 | | 88.5−92.11 | 7/8 | | TK−T032 | 88.5−92.11 | 54.0 | DISC | MP−20 | CPM−19 | 88.5−92.11 | 11/16 | (R)WC−55020 | WK−569 | CUP | 88.5−92.11 | BH−02565 | (R)BH−02497 | 88.5−90.5 | 5/8 | MC−T235 | MK−4344 | 88.5−89.2 | 13/16 | CC−70180 | CK−3144 |
| | E−ST170G(ワゴン) | | <アンチスキッド付> | | | | | | | | | | | (L)WC−57020 | | | | | (L)BH−02497 | 90.5−92.11 | 5/8 | MC−T392 | MK−T236 | 89.2−92.11 | 13/16 | CC−70180 | CK−3144 |
| | | | 88.5−92.8 | 15/16 | | TK−T049 | | | | | | | | | | | | | | | | | | | | | |
| (2000ディーゼル) | | | 88.5−92.11 | 7/8 | | TK−T032 | 88.5−92.11 | 54.0 | DISC | MP−20 | CPM−19 | 88.5−92.11 | 11/16 | (R)WC−55020 | WK−569 | CUP | 88.5−92.11 | BH−02565 | (R)BH−02497 | 88.5−90.5 | 5/8 | MC−T236 | MK−4342 | 88.5−89.2 | 13/16 | CC−70150 | CK−3144 |
| | Q−CT170・170G(ワゴン) | | | | | | | | | | | | | (L)WC−57020 | | | | | (L)BH−02497 | 90.5−92.11 | 5/8 | MC−T392 | MK−T236 | 89.2−92.11 | 13/16 | CC−70150 | CK−3144 |
| | <X−は91．6〜> | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | S−CT176V(バン) | | 88.5−92.11 | 7/8 | | TK−T032 | 88.5−92.11 | 54.0 | DISC | MP−20 | CPM−19 | 88.5−92.11 | 3/4 | (R)WC−55021 | WK−542 | CUP | 88.5−92.11 | BH−02565 | (R)BH−02539 | 88.5−89.11 | 5/8 | MC−T236 | MK−4342 | 88.5−89.2 | 13/16 | CC−70150 | CK−3144 |
| | | | | | | | | | | | | | | (L)WC−57021 | | | | | (L)BH−02539 | 89.11−92.11 | 5/8 | MC−T392 | MK−T236 | 89.2−92.11 | 13/16 | CC−70150 | CK−3144 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CARINA(FF) : 190 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | <13インチホイール> | | | | | | | | | | | | | | | | | | | | |
| (1500) | E−AT192 | | 92.8−94.6 | 7/8 | | TK−T402 | 92.8−96.8 | 54.0 | DISC | MP−20 | CPM−19 | 92.8−96.8 | 3/4 | | WK−542 | CUP | 92.8−96.8 | (R)BH−T596 | (R)BH−T629 | 92.8−94.3 | 5/8 | | | 92.8−93.1 | 13/16 | CC−70183 | CK−3144 |
| | | | 94.6−96.8 | 7/8 | | TK−T402 | <14インチホイール> | | | | | | | | | | | (L)BH−T610 | (L)BH−T607 | 94.3−96.8 | 5/8 | | MK−T244 | 93.1−96.8 | 13/16 | CC−70183 | CK−T201 |
| | | | <アンチスキッド付> | | | | 92.8−96.8 | 57.2 | DISC | MP−50 | CPM−68 | | | | | | | | | | | | | | | | |
| | | | 92.8−96.8 | 15/16 | | TK−T344 | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | <13インチホイール> | | | | | | | | | | | | | | | | | | | | |
| (1600) | E−AT190 | | 92.8−94.6 | 7/8 | | TK−T402 | 92.8−96.8 | 54.0 | DISC | MP−20 | CPM−19 | 92.8−96.8 | 3/4 | | WK−542 | CUP | 92.8−96.8 | (R)BH−T596 | (R)BH−T629 | 92.8−94.3 | 5/8 | | | 92.8−93.1 | 13/16 | CC−70183 | CK−3144 |
| | | | 94.6−96.8 | 7/8 | | TK−T402 | <14インチホイール> | | | | | | | | | | | (L)BH−T610 | (L)BH−T607 | 94.3−96.8 | 5/8 | | MK−T244 | 93.1−96.8 | 13/16 | CC−70183 | CK−T201 |
| | | | <アンチスキッド付> | | | | 92.8−96.8 | 57.2 | DISC | MP−50 | CPM−68 | | | | | | | | | | | | | | | | |
| | | | 92.8−96.8 | 15/16 | | TK−T344 | | | | | | | | | | | | | | | | | | | | | |
| (1800) | E−ST190 | リヤードラム車 | 92.8−94.6 | 7/8 | | TK−T402 | 92.8−94.8 | 57.2 | DISC | MP−50 | CPM−68 | 92.8−94.8 | 3/4 | | WK−542 | CUP | 92.8−94.8 | (R)BH−T596 | (R)BH−T629 | 92.8−94.3 | 5/8 | | | 92.8−94.2 | 13/16 | CC−70180 | CK−3144 |
| | | (除くSリミテッド) | 94.6−94.8 | 7/8 | | TK−T402 | | | | | | | | | | | | (L)BH−T610 | (L)BH−T607 | 94.3−94.8 | 5/8 | | MK−T244 | 94.2−94.8 | 13/16 | CC−70180 | CK−T201 |
| | | | <アンチスキッド付> | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | 92.8−94.8 | 15/16 | | TK−T344 | | | | | | | | | | | | | | | | | | | | | |
| | | 四輪ディスク車 | 92.8−94.6 | 7/8 | | TK−T402 | 92.8−94.8 | 57.2 | DISC | MP−50 | CPM−68 | 92.8−94.8 | 31.7 | DISC | A−222P | | 92.8−94.8 | (R)BH−T596 | (R)BH−T571 | 92.8−94.3 | 5/8 | | | 92.8−94.2 | 13/16 | CC−70180 | CK−3144 |
| | | (Sリミテッド) | 94.6−94.8 | 7/8 | | TK−T402 | | | | | | | | | | | | (L)BH−T610 | (L)BH−T572 | 94.3−94.8 | 5/8 | | MK−T244 | 94.2−94.8 | 13/16 | CC−70180 | CK−T201 |
| | | | <アンチスキッド付> | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | 92.8−94.8 | 15/16 | | TK−T344 | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | <13インチホイール> | | | | | | | | | | | | | | | | | | | | |
| | E−AT191 | リヤードラム車 | 94.8−96.8 | 7/8 | | TK−T402 | 94.8−96.8 | 54.0 | DISC | MP−20 | CPM−19 | 94.8−96.8 | 3/4 | | WK−542 | CUP | 94.8−96.8 | (R)BH−T596 | (R)BH−T629 | 94.8−96.8 | 5/8 | | MK−T244 | 94.8−96.8 | 13/16 | CC−70183 | CK−T201 |
| | | (除くSリミテッド) | <アンチスキッド付> | | | | <14インチホイール> | | | | | | | | | | | (L)BH−T610 | (L)BH−T607 | | | | | | | | |
| | | | 94.8−96.8 | 15/16 | | TK−T344 | 94.8−96.8 | 57.2 | DISC | MP−50 | CPM−68 | | | | | | | | | | | | | | | | |
| | | 四輪ディスク車 | 94.8−96.8 | 7/8 | | TK−T402 | 94.8−96.8 | 57.2 | DISC | MP−50 | CPM−68 | 94.8−96.8 | | DISC | C−222P | | 94.8−96.8 | (R)BH−T596 | (R)BH−T571 | 94.8−96.8 | 5/8 | | MK−T244 | 94.8−96.8 | 13/16 | CC−70183 | CK−T201 |
| | | (Sリミテッド) | <アンチスキッド付> | | | | | | | | | | | | | | | (L)BH−T610 | (L)BH−T572 | | | | | | | | |
| | | | 94.8−96.8 | 15/16 | | TK−T344 | | | | | | | | | | | | | | | | | | | | | |
| (2000) | E−ST195(4WD) | | 92.8−94.6 | 7/8 | | TK−T402 | 92.8−96.8 | 57.2 | DISC | MP−50 | CPM−68 | 92.8−94.2 | 34.9 | DISC | MP−82 | | 92.8−96.8 | (R)BH−T596 | (R)BH−T631 | 92.8−94.3 | 5/8 | | | 92.8−94.2 | 13/16 | CC−70180 | CK−3144 |
| | | | 94.6−96.8 | 7/8 | | TK−T402 | | | | | | 94.2−96.8 | | DISC | C−222P | | | (L)BH−T610 | (L)BH−T632 | 94.3−96.8 | 5/8 | | MK−T244 | 94.2−96.8 | 13/16 | CC−70180 | CK−T201 |
| | | | <アンチスキッド付> | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | 92.8−96.8 | 15/16 | | TK−T344 | | | | | | | | | | | | | | | | | | | | | |
| (2000ディーゼル) | | | 92.8−94.6 | 7/8 | | TK−T402 | 92.8−96.8 | 57.2 | DISC | MP−50 | CPM−68 | 92.8−96.8 | 3/4 | | WK−542 | CUP | 92.8−96.8 | (R)BH−T596 | (R)BH−T629 | 92.8−94.3 | 5/8 | | | 92.8−94.2 | 13/16 | CC−70150 | CK−3144 |
| | X−CT190 | | 94.6−96.8 | 7/8 | | TK−T402 | | | | | | | | | | | | (L)BH−T610 | (L)BH−T607 | 94.3−96.8 | 5/8 | | MK−T244 | 94.2−96.8 | 13/16 | CC−70150 | CK−T201 |
| | <KD−は94．8〜> | | <アンチスキッド付> | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | 92.8−96.8 | 15/16 | | TK−T344 | | | | | | | | | | | | | | | | | | | | | |
| | X･Y−CT195(4WD) | | 92.8−94.6 | 7/8 | | TK−T402 | 92.8−96.8 | 57.2 | DISC | MP−50 | | 92.8−94.2 | 34.9 | DISC | MP−82 | | 92.8−96.8 | (R)BH−T596 | (R)BH−T631 | 92.8−94.3 | 5/8 | | | 92.8−94.2 | 13/16 | CC−70150 | CK−3144 |
| | <KD−は94．8〜> | | 94.6−96.8 | 7/8 | | TK−T402 | | | | | | 94.2−96.8 | | DISC | C−222P | | | (L)BH−T610 | (L)BH−T632 | 94.3−96.8 | 5/8 | | MK−T244 | 94.2−96.8 | 13/16 | CC−70150 | CK−T201 |
| | | | <アンチスキッド付> | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | 92.8−96.8 | 15/16 | | TK−T344 | | | | | | | | | | | | | | | | | | | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CARINA : 210 ser. | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1500) E−AT212 ＜GF−は98．8～＞ | 96.8-01.12 | 15/16 | | TK-T401 | ＜14インチホイール＞<br>96.8-01.12<br>＜13インチホイール＞<br>97.11-01.12 | 57.2<br><br>54.0 | DISC<br><br>DISC | MP-50<br><br>MP-65 | CPM-68<br><br>CPM-19 | 96.8-01.12 | 3/4 | (R)WC-T600<br>(L)WC-T605 | WK-542 | CUP | 96.8-01.12 | (R)BH-T596<br>(L)BH-T610 | (R)BH-T692<br>(L)BH-T729 | 96.8-01.12 | 5/8 | MC-T394 | MK-T244 | 96.8-01.12 | 13/16 | CC-70183 | CK-T201 |
| (1600) E−AT210 ＜GF−は98．8～＞ | 96.8-01.12 | 15/16 | | TK-T401 | 96.8-98.8<br>98.8-01.12 | 57.2 | DISC<br>DISC | MP-50<br>MP-62 | CPM-68 | 96.8-98.8<br>98.8-01.12 | 31.7 | DISC<br>DISC | A-222P<br>C-222P | | 96.8-98.8<br><br>98.8-01.12 | (R)BH-T596<br>(L)BH-T610<br>(R)BH-T827<br>(L)BH-T828 | (R)BH-T571<br>(L)<br>(R)BH-T571<br>(L) | 96.8-01.12 | 5/8 | MC-T395 | MK-T244 | 96.8-01.12 | 13/16 | CC-70183 | CK-T201 |
| (1800) E−AT211 ＜GF−は98．8～＞ | 96.8-01.12 | 15/16 | | TK-T401 | 96.8-01.12 | 57.2 | DISC | MP-50 | CPM-68 | 96.8-01.12 | 3/4 | (R)WC-T600<br>(L)WC-T605 | WK-542 | CUP | 96.8-01.12 | (R)BH-T596<br>(L)BH-T610 | (R)BH-T692<br>(L)BH-T729 | 96.8-01.12 | 5/8 | MC-T394 | MK-T244 | 96.8-01.12 | 13/16 | CC-70183 | CK-T201 |
| (2000) E−ST215(4WD) ＜GF−は98．8～＞ | 96.8-01.12 | 15/16 | | TK-T401 | 96.8-01.12 | 57.2 | DISC | MP-50 | CPM-68 | 96.8-01.12 | 3/4 | (R)WC-T743<br>(L)WC-T749 | WK-899 | CUP | 96.8-01.12 | (R)BH-T596<br>(L)BH-T610 | (R)BH-T732<br>(L)BH-T731 | 96.8-01.12 | 5/8 | MC-T395 | MK-T244 | 96.8-01.12 | 7/8 | | CK-T200 |
| (2000ディーゼル) KD−CT210 | 96.8-98.8 | 15/16 | | TK-T401 | 96.8-98.8 | 57.2 | DISC | MP-50 | CPM-68 | 96.8-98.8 | 3/4 | (R)WC-T600<br>(L)WC-T605 | WK-542 | CUP | 96.8-98.8 | (R)BH-T596<br>(L)BH-T610 | (R)BH-T692<br>(L)BH-T729 | 96.8-98.8 | 5/8 | MC-T396 | MK-T244 | 96.8-98.8 | 13/16 | CC-70150 | CK-T201 |
| KD−CT215(4WD) | 96.8-98.8 | 15/16 | | TK-T401 | 96.8-98.8 | 57.2 | DISC | MP-50 | CPM-68 | 96.8-98.8 | 3/4 | (R)WC-T743<br>(L)WC-T749 | WK-899 | CUP | 96.8-98.8 | (R)BH-T596<br>(L)BH-T610 | (R)BH-T732<br>(L)BH-T731 | 96.8-98.8 | 5/8 | MC-T396 | MK-T244 | 96.8-98.8 | 13/16 | CC-70150 | CK-T201 |
| (2200ディーゼル) KE−CT211 | 98.8-01.12 | 15/16 | | TK-T401 | 98.8-01.12 | 57.2 | DISC | MP-50 | CPM-68 | 98.8-01.12 | 3/4 | (R)WC-T600<br>(L)WC-T605 | WK-542 | CUP | 98.8-01.12 | (R)BH-T596<br>(L)BH-T610 | (R)BH-T692<br>(L)BH-T729 | 98.8-01.12 | 5/8 | MC-T396 | MK-T244 | 98.8-01.12 | 13/16 | CC-70150 | CK-T201 |
| KH−CT216(4WD) | 98.8-01.12 | 15/16 | | TK-T401 | 98.8-01.12 | 57.2 | DISC | MP-50 | CPM-68 | 98.8-01.12 | 3/4 | (R)WC-T743<br>(L)WC-T749 | WK-899 | CUP | 98.8-01.12 | (R)BH-T596<br>(L)BH-T610 | (R)BH-T732<br>(L)BH-T731 | | | (オートマチック) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CARINA ED : 160 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) | E−ST160 | | 85.8-88.5 | 15/16 | | TK-T006 | 85.8-88.5 | 54.0 | DISC | MP-19 | | 85.8-88.5 | 3/4 | (R)WC-55021<br>(L)WC-57021 | WK-542 | CUP | 85.8-87.8 | BH-02455 | (R)BH-02472<br>(L)BH-02472 | 85.8-87.8<br><現車確認 PLANT No.A41,A42> | 5/8 | | MK-4344 | 85.8-88.5 | 13/16 | CC-70150 | CK-3144 |
| | | | | | | | | | | | | | | | | | 87.8-88.5 | BH-02550 | (R)BH-02472<br>(L)BH-02472 | 87.8-89.8<br>87.10-89.8<br><現車確認 PLANT No.A51−A54> | 5/8<br>5/8 | | MK-4344<br>MK-4344 | | | | |
| | | | | | | | | | | | | | | | | | | | | 87.8-89.8<br><現車確認 PLANT No.A41,A42> | 5/8 | MC-T232 | MK-4344 | | | | |
| | E−ST163 | | 88.5-89.8 | 15/16 | | TK-T006 | 88.5-89.8 | 54.0 | DISC | MP-19 | | 88.5-89.8 | 3/4 | (R)WC-55021<br>(L)WC-57021 | WK-542 | CUP | 88.5-89.8 | BH-02550 | (R)BH-02472<br>(L)BH-02472 | 88.5-89.8<br><現車確認 PLANT No.A51−A54> | 5/8 | | MK-4344 | 88.5-89.2<br>89.2-89.8 | 13/16<br>13/16 | CC-70180<br>CC-70180 | CK-3144<br>CK-3144 |
| | | | | | | | | | | | | | | | | | | | | 88.5-89.8<br><現車確認 PLANT No.A41,A42> | 5/8 | MC-T232 | MK-4344 | | | | |
| (2000) | E−ST162 | G・Gリミテッド | 85.8-89.8<br><アンチスキッド付> | 15/16 | | TK-T006 | 85.8-89.8<br><アンチスキッド付> | 54.0 | DISC | MP-18 | | 85.8-89.8 | 31.7 | MD-121M | A-222P | | 85.8-87.8 | BH-02455 | (R)BH-02581<br>(L)BH-02581 | 85.8-89.8<br><現車確認 PLANT No.A51−A54> | 5/8 | | MK-4344 | 85.8-89.2<br>89.2-89.8 | 13/16<br>13/16 | CC-70150<br>CC-70150 | CK-3144<br>CK-3144 |
| | | | 87.8-89.8 | 1 | | TK-T048 | 87.8-89.8 | 57.2 | DISC | MP-21 | | | | | | | 87.8-89.8 | BH-02550 | (R)BH-02551<br>(L)BH-02551 | 85.8-89.8<br><現車確認 PLANT No.A41,A42> | 5/8 | MC-T232 | MK-4344 | | | | |
| | | S・X | 87.8-89.8 | 15/16 | | TK-T006 | 87.8-88.5<br>88.5-89.8 | 54.0<br>54.0 | DISC<br>DISC | MP-19<br>MP-18 | | 87.8-89.8 | 3/4 | (R)WC-55021<br>(L)WC-57021 | WK-542 | CUP | 87.8-89.8 | BH-02550 | (R)BH-02472<br>(L)BH-02472 | 87.8-89.8<br><現車確認 PLANT No.A51−A54> | 5/8 | | MK-4344 | 87.8-89.2<br>89.2-89.8 | 13/16<br>13/16 | CC-70180<br>CC-70180 | CK-3144<br>CK-3144 |
| | | | | | | | | | | | | | | | | | | | | 87.8-89.8<br><現車確認 PLANT No.A41,A42> | 5/8 | MC-T232 | MK-4344 | | | | |
| | | S・X(四輪ディスク | 88.5-89.8<br><アンチスキッド付> | 15/16 | | TK-T006 | 88.5-89.8<br><アンチスキッド付> | 54.0 | DISC | MP-18 | | 88.5-89.8 | 31.7 | MD-121M | A-222P | | 88.5-89.8 | BH-02550 | (R)BH-02551<br>(L)BH-02551 | 88.5-89.8<br><現車確認 PLANT No.A51−A54> | 5/8 | | MK-4344 | 88.5-89.2<br>89.2-89.8 | 13/16<br>13/16 | CC-70180<br>CC-70180 | CK-3144<br>CK-3144 |
| | | | 88.5-89.8 | 1 | | TK-T048 | 88.5-89.8 | 57.2 | DISC | MP-21 | | | | | | | | | | 88.5-89.8 | 5/8 | MC-T232 | MK-4344 | | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CARINA ED : 180 ser. | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) E－ST180 | 89.9-91.8 | 7/8 | | TK-T402 | 89.9-91.8 | 54.0 | DISC | MP-20 | | 89.9-93.9 | 3/4 | (R)WC-T558 | WK-542 | CUP | 89.9-93.9 | BH-T517 | (R)BH-T518 | 89.9-93.3 | 5/8 | MC-T294 | MK-T236 | 89.9-93.9 | 13/16 | CC-70180 | CK-3144 |
| E－ST181(4WS) | 91.8-93.9 | 15/16 | | TK-T307 | 91.8-93.9 | 57.2 | DISC | A-306P | | | | (L) | | | | | (L)BH-T518 | 93.3-93.9 | 5/8 | MC-T294 | | | | | |
| | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | | | | | | | | | | | | | | |
| | 90.8-91.8 | 15/16 | | TK-T300 | | | | | | | | | | | | | | | | | | | | | |
| | 91.8-93.9 | 1 | | TK-T306 | | | | | | | | | | | | | | | | | | | | | |
| (2000) E－ST182 | 89.9-93.9 | 15/16 | | TK-T307 | 89.9-93.9 | 57.2 | DISC | A-306P | | 89.9-91.8 | 31.7 | DISC | A-222P | | 89.9-93.9 | BH-T517 | (R)BH-T519 | 89.9-93.3 | 5/8 | MC-T294 | MK-T236 | 89.9-93.9 | 13/16 | CC-70180 | CK-3144 |
| E－ST183(4WS) | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | 91.8-93.9 | 31.7 | DISC | A-222P | | | | (L)BH-T519 | 93.3-93.9 | 5/8 | MC-T294 | | <Gﾘﾐﾃｯﾄﾞ> | | | |
| | 89.9-93.9 | 1 | | TK-T306 | | | | | | | | | | | | | | | | | | 89.9-93.9 | 13/16 | | CK-3144 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CARINA ED : 200 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) | E−ST200・201 | | 93.9−95.8 | 7/8 | | TK−T341 | 93.9−98.4 | 57.2 | DISC | MP−50 | CPM−68 | 93.9−98.4 | 3/4 | (R)WC−T600 | WK−542 | CUP | 93.9−98.4 | (R)BH−T597 | (R)BH−T590 | 93.9−94.4 | 5/8 | MC−T413 | | 93.9−94.1 | 13/16 | CC−70180 | CK−3144 |
| | | | 95.8−96.6 | 7/8 | | TK−T402 | | | | | | | | (L)WC−T605 | | | | (L)BH−T598 | (L)BH−T590 | 94.4−98.4 | 5/8 | MC−T413 | MK−T244 | 94.1−98.4 | 13/16 | CC−70180 | CK−T201 |
| | | | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | 93.9−97.6 | 15/16 | | TK−T342 | | | | | | | | | | | | | | | | | | | | | |
| | | | 97.6−98.4 | 15/16 | | TK−T401 | | | | | | | | | | | | | | | | | | | | | |
| (2000) | E−ST202・203 | Sﾘﾐﾃｯﾄﾞ・X | 93.9−95.8 | 15/16 | | TK−T349 | 93.9−98.4 | 57.2 | DISC | MP−50 | CPM−68 | 93.9−98.4 | 31.7 | DISC | A−222P | | 93.9−98.4 | (R)BH−T597 | (R)BH−T591 | 93.9−94.4 | 5/8 | MC−T413 | | 93.9−94.1 | 13/16 | CC−70180 | CK−3144 |
| | | | 95.8−96.6 | 15/16 | | TK−T409 | | | | | | | | | | | | (L)BH−T598 | (L)BH−T591 | 94.4−98.4 | 5/8 | MC−T413 | MK−T244 | 94.1−98.4 | 13/16 | CC−70180 | CK−T201 |
| | | | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | 93.9−97.6 | 15/16 | | TK−T342 | | | | | | | | | | | | | | | | | | | | | |
| | | | 97.6−98.4 | 15/16 | | TK−T401 | | | | | | | | | | | | | | | | | | | | | |
| | | Gﾘﾐﾃｯﾄﾞ・GT (ﾉｰﾏﾙｻｽ車) | 93.9−95.8 | 15/16 | | TK−T349 | 93.9−98.4 | 57.2 | DISC | MP−50 | CPM−68 | 93.9−98.4 | | DISC | C−222P | | 93.9−98.4 | (R)BH−T597 | (R)BH−T591 | 93.9−94.4 | 5/8 | MC−T413 | | 93.9−94.1 | 13/16 | | CK−3144 |
| | | | 95.8−96.6 | 15/16 | | TK−T409 | | | | | | | | | | | | (L)BH−T598 | (L)BH−T591 | 94.4−98.4 | 5/8 | MC−T413 | MK−T244 | 94.1−98.4 | 13/16 | | CK−T201 |
| | | | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | 93.9−97.6 | 15/16 | | TK−T342 | | | | | | | | | | | | | | | | | | | | | |
| | | | 97.6−98.4 | 15/16 | | TK−T401 | | | | | | | | | | | | | | | | | | | | | |
| | | Gﾘﾐﾃｯﾄﾞ・GT (ｽｰﾊﾟｰｽﾄﾗｯﾄｻｽ車) | 93.9−95.8 | 15/16 | | TK−T349 | 93.9−98.4 | | DISC | MP−61 | | 93.9−98.4 | | DISC | C−222P | | 93.9−98.4 | (R)BH−T641 | (R)BH−T591 | 93.9−94.4 | 5/8 | MC−T413 | | 93.9−94.1 | 13/16 | | CK−3144 |
| | | | 95.8−96.6 | 15/16 | | TK−T409 | | | | | | | | | | | | (L)BH−T642 | (L)BH−T591 | 94.4−98.4 | 5/8 | MC−T413 | MK−T244 | 94.1−98.4 | 13/16 | | CK−T201 |
| | | | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | 93.9−97.6 | 15/16 | | TK−T342 | | | | | | | | | | | | | | | | | | | | | |
| | | | 97.6−98.4 | 15/16 | | TK−T401 | | | | | | | | | | | | | | | | | | | | | |
| | E−ST205(4WD) | | 94.5−95.8 | 15/16 | | TK−T349 | 94.5−98.4 | | DISC | MP−61 | | 94.5−98.4 | | DISC | C−438P | | 94.5−98.4 | (R)BH−T641 | (R)BH−T643 | 94.5−98.4 | 5/8 | MC−T413 | MK−T244 | 94.5−98.4 | 13/16 | | CK−T201 |
| | | | 95.8−96.6 | 15/16 | | TK−T409 | | | | | | | | | | | | (L)BH−T642 | (L)BH−T644 | | | | | | | | |
| | | | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | 94.5−97.6 | 15/16 | | TK−T342 | | | | | | | | | | | | | | | | | | | | | |
| | | | 97.6−98.4 | 15/16 | | TK−T401 | | | | | | | | | | | | | | | | | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CALDINA : 190 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1500) | R・T－ET196V | | 92.11-96.1 | 7/8 | | TK-T341 | 92.11-94.5 | 54.0 | DISC | MP-20 | CPM-19 | 92.11-02.6 | 3/4 | (R)WC-T600 | WK-542 | CUP | 92.11-02.6 | (R)BH-T596 | (R)BH-T673 | 92.11-94.3 | 5/8 | MC-T394 | | 92.11-94.2 | 13/16 | CC-70179 | CK-3144 |
| | ＜GA－は95．1～＞ | | 96.1-99.8 | 7/8 | | TK-T360 | 94.5-97.11 | 54.0 | DISC | MP-19 | CPM-19 | | | (L)WC-T605 | | | | (L)BH-T610 | (L)BH-T673 | 94.3-94.11 | 5/8 | MC-T394 | | 94.2-95.9 | 13/16 | CC-70179 | CK-T201 |
| | ＜GC・GG－は98．5～＞ | | ＜ｱﾝﾁｽｷｯﾄﾞ付＞ | | | | 97.11-02.6 | 54.0 | DISC | MP-65 | CPM-19 | | | | | | | | | 94.11-02.6 | 5/8 | MC-T394 | MK-T244 | 95.9-96.1 | 13/16 | | CK-T201 |
| | | | 98.5-02.6 | 7/8 | | TK-T359 | | | | | | | | | | | | | | | | | | 96.1-02.6 | 7/8 | | CK-T200 |
| (1800) | E－ST190G | | 92.11-96.1 | 7/8 | | TK-T341 | 92.11-96.1 | 57.2 | DISC | MP-50 | CPM-68 | 92.11-96.1 | 3/4 | (R)WC-T600 | WK-542 | CUP | 92.11-96.1 | (R)BH-T596 | (R)BH-T629 | 92.11-94.3 | 5/8 | MC-T394 | | 92.11-94.2 | 13/16 | CC-70180 | CK-3144 |
| | | | ＜ｱﾝﾁｽｷｯﾄﾞ付＞ | | | | | | | | | | | (L)WC-T605 | | | | (L)BH-T610 | (L)BH-T607 | 94.3-94.11 | 5/8 | MC-T394 | | 94.2-96.1 | 13/16 | CC-70180 | CK-T201 |
| | | | 92.11-96.1 | 15/16 | | TK-T344 | | | | | | | | | | | | | | 94.11-96.1 | 5/8 | MC-T394 | MK-T244 | | | | |
| | E－AT191G | | 96.1-97.8 | 15/16 | | TK-T401 | 96.1-97.8 | 57.2 | DISC | MP-68 | CPM-68 | 96.1-97.8 | 3/4 | (R)WC-T600 | WK-542 | CUP | 96.1-97.8 | (R)BH-T596 | (R)BH-T692 | 96.1-97.8 | 5/8 | MC-T394 | MK-T244 | 96.1-97.8 | 13/16 | | CK-T201 |
| | | | | | | | | | | | | | | (L)WC-T605 | | | | (L)BH-T610 | (L)BH-T729 | | | | | | | | |
| (2000) | E－ST191G | | 92.11-96.1 | 7/8 | | TK-T341 | 92.11-96.1 | 57.2 | DISC | MP-50 | CPM-68 | 92.11-96.1 | 31.7 | DISC | A-222P | | 92.11-96.1 | (R)BH-T596 | (R)BH-T571 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | | | ＜ｱﾝﾁｽｷｯﾄﾞ付＞ | | | | 96.1-97.8 | 57.2 | DISC | MP-68 | CPM-68 | 96.1-97.8 | 3/4 | (R)WC-T600 | WK-542 | CUP | | (L)BH-T610 | (L)BH-T572 | | | | | | | | |
| | | | 92.11-96.1 | 15/16 | | TK-T344 | | | | | | | | (L)WC-T605 | | | 96.1-97.8 | (R)BH-T596 | (R)BH-T692 | | | | | | | | |
| | | | 96.1-97.8 | 15/16 | | TK-T401 | | | | | | | | | | | | (L)BH-T610 | (L)BH-T729 | | | | | | | | |
| | E－ST195G(4WD) CZ・TZ | | 92.11-96.1 | 7/8 | | TK-T341 | 92.11-96.1 | 57.2 | DISC | MP-50 | CPM-68 | 92.11-94.2 | 34.9 | DISC | MP-82 | | 92.11-96.1 | (R)BH-T596 | (R)BH-T631 | 92.11-94.3 | 5/8 | MC-T395 | | 92.11-94.2 | 13/16 | CC-70180 | CK-3144 |
| | | | ＜ｱﾝﾁｽｷｯﾄﾞ付＞ | | | | 96.1-97.8 | 57.2 | DISC | MP-68 | | 94.2-96.1 | | DISC | C-222P | | | (L)BH-T610 | (L)BH-T632 | 94.3-94.11 | 5/8 | MC-T395 | | 94.2-96.1 | 13/16 | CC-70180 | CK-T201 |
| | | | 92.11-96.1 | 15/16 | | TK-T344 | | | | | | 96.1-97.8 | 3/4 | (R)WC-T743 | WK-899 | CUP | 96.1-97.8 | (R)BH-T596 | (R)BH-T732 | 94.11-97.8 | 5/8 | MC-T395 | MK-T244 | 96.1-97.8 | 7/8 | | CK-T200 |
| | | | 96.1-97.8 | 15/16 | | TK-T401 | | | | | | | | (L)WC-T749 | | | | (L)BH-T610 | (L)BH-T731 | | | | | | | | |
| | TZ－G | | 95.2-96.1 | 7/8 | | TK-T341 | 95.2-96.1 | 57.2 | DISC | MP-50 | CPM-68 | 95.2-97.8 | | DISC | C-222P | | 95.2-97.8 | (R)BH-T596 | (R)BH-T631 | 95.2-97.8 | 5/8 | MC-T395 | MK-T244 | 95.2-96.4 | 13/16 | | CK-T201 |
| | | | ＜ｱﾝﾁｽｷｯﾄﾞ付＞ | | | | 96.1-97.8 | 57.2 | DISC | MP-68 | | | | | | | | (L)BH-T610 | (L)BH-T632 | | | | | 96.4-97.8 | 7/8 | | CK-T200 |
| | | | 95.2-96.1 | 15/16 | | TK-T344 | | | | | | | | | | | | | | | | | | | | | |
| | | | 96.1-97.8 | 15/16 | | TK-T401 | | | | | | | | | | | | | | | | | | | | | |
| | GC－ST198V(4WD) | | 99.8-02.6 | 7/8 | | TK-T359 | 99.8-02.6 | 54.0 | DISC | MP-65 | CPM-19 | 99.8-02.6 | 3/4 | (R)WC-T649 | WK-542 | CUP | 99.8-02.6 | (R)BH-T596 | (R) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | | | | | | | | | | | | | | (L)WC-T649 | | | | (L)BH-T610 | (L) | | | | | | | | |
| (2000ディーゼル) | | | 92.11-96.1 | 7/8 | | TK-T341 | 92.11-96.1 | 57.2 | DISC | MP-50 | CPM-68 | 92.11-97.8 | 3/4 | (R)WC-T600 | WK-542 | CUP | 92.11-96.1 | (R)BH-T596 | (R)BH-T629 | 92.11-94.3 | 5/8 | MC-T396 | | 92.11-94.2 | 13/16 | CC-70150 | CK-3144 |
| | X・Y－CT190G | | ＜ｱﾝﾁｽｷｯﾄﾞ付＞ | | | | 96.1-97.8 | 57.2 | DISC | MP-68 | | | | (L)WC-T605 | | | | (L)BH-T610 | (L)BH-T607 | 94.3-94.11 | 5/8 | MC-T396 | | 94.2-97.8 | 13/16 | CC-70150 | CK-T201 |
| | ＜KD－は95．1～＞ | | 92.11-96.1 | 15/16 | | TK-T344 | | | | | | | | | | | 96.1-97.8 | (R)BH-T596 | (R)BH-T692 | 94.11-97.8 | 5/8 | MC-T396 | MK-T244 | | | | |
| | | | 96.1-97.8 | 15/16 | | TK-T401 | | | | | | | | | | | | (L)BH-T610 | (L)BH-T729 | | | | | | | | |
| | S－CT196V | | 92.11-96.1 | 7/8 | | TK-T341 | 92.11-94.5 | 54.0 | DISC | MP-20 | CPM-19 | 92.11-98.5 | 3/4 | (R)WC-T600 | WK-542 | CUP | 92.11-98.5 | (R)BH-T596 | (R)BH-T673 | 92.11-94.3 | 5/8 | MC-T396 | | 92.11-94.2 | 13/16 | CC-70150 | CK-3144 |
| | ＜KB－は94．2～＞ | | 96.1-98.5 | 7/8 | | TK-T360 | 94.5-97.11 | 54.0 | DISC | MP-19 | CPM-19 | | | (L)WC-T605 | | | | (L)BH-T610 | (L)BH-T673 | 94.3-94.11 | 5/8 | MC-T396 | | 94.2-98.5 | 13/16 | CC-70150 | CK-T201 |
| | | | | | | | 97.11-98.5 | 54.0 | DISC | MP-65 | CPM-19 | | | | | | | | | 94.11-98.5 | 5/8 | MC-T396 | MK-T244 | | | | |
| | S－CT198V(4WD) | | 92.11-96.1 | 7/8 | | TK-T341 | 92.11-94.5 | 54.0 | DISC | MP-20 | CPM-19 | 92.11-98.5 | 3/4 | (R)WC-T649 | WK-542 | CUP | 92.11-96.1 | (R)BH-T596 | (R)BH-T546 | 92.11-94.3 | 5/8 | MC-T396 | | 92.11-94.2 | 13/16 | CC-70150 | CK-3144 |
| | ＜KB－は94．2～＞ | | 96.1-98.5 | 7/8 | | TK-T360 | 94.5-97.11 | 54.0 | DISC | MP-19 | CPM-19 | | | (L)WC-T649 | | | | (L)BH-T610 | (L)BH-T546 | 94.3-94.11 | 5/8 | MC-T396 | | 94.2-98.5 | 13/16 | CC-70150 | CK-T201 |
| | | | | | | | 97.11-98.5 | 54.0 | DISC | MP-65 | CPM-19 | | | | | | 96.1-98.5 | (R)BH-T596 | (R) | 94.11-98.5 | 5/8 | MC-T396 | MK-T244 | | | | |
| | | | | | | | | | | | | | | | | | | (L)BH-T610 | (L) | | | | | | | | |
| (2200ディーゼル) | | | 98.5-99.8 | 7/8 | | TK-T360 | 98.5-02.6 | 54.0 | DISC | MP-65 | CPM-19 | 98.5-02.6 | 3/4 | (R)WC-T600 | WK-542 | CUP | 98.5-02.6 | (R)BH-T596 | (R)BH-T673 | 98.5-02.6 | 5/8 | MC-T396 | MK-T244 | 98.5-02.6 | 13/16 | CC-70150 | CK-T201 |
| | KF・KJ－CT197V | | ＜ｱﾝﾁｽｷｯﾄﾞ付＞ | | | | | | | | | | | (L)WC-T605 | | | | (L)BH-T610 | (L)BH-T673 | | | | | | | | |
| | | | 98.5-02.6 | 7/8 | | TK-T359 | | | | | | | | | | | | | | | | | | | | | |
| | KF－CT199V(4WD) | | 98.5-99.8 | 7/8 | | TK-T360 | 98.5-02.6 | 54.0 | DISC | MP-65 | CPM-19 | 98.5-02.6 | 3/4 | (R)WC-T649 | WK-542 | CUP | 98.5-02.6 | (R)BH-T596 | (R) | 98.5-02.6 | 5/8 | MC-T396 | MK-T244 | 98.5-02.6 | 13/16 | CC-70150 | CK-T201 |
| | | | ＜ｱﾝﾁｽｷｯﾄﾞ付＞ | | | | | | | | | | | (L)WC-T649 | | | | (L)BH-T610 | (L) | | | | | | | | |
| | | | 98.5-02.6 | 7/8 | | TK-T359 | | | | | | | | | | | | | | | | | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CALDINA : 210 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) | E−AT211G<br>＜GF−は99．8～＞ | | 97.8-02.9 | 15/16 | | TK-T401 | 97.8-97.11<br>97.11-02.9 | 57.2 | DISC<br>DISC | MP-50<br>MP-103 | CPM-68<br>CPM-68 | 97.8-02.9 | 3/4 | | WK-542 | CUP | 97.8-02.9 | (R)BH-T596<br>(L)BH-T610 | (R)BH-T692<br>(L)BH-T729 | 97.8-02.9 | 5/8 | MC-T394 | MK-T244 | 97.8-02.9 | 13/16 | CC-70183 | CK-T201 |
| (2000) | E−ST210G<br>＜GF−は99．8～＞ | E･G | 97.8-02.9 | 15/16 | | TK-T401 | 97.8-97.11<br>97.11-02.9 | 57.2 | DISC<br>DISC | MP-50<br>MP-103 | CPM-68<br>CPM-68 | 97.8-02.9 | 3/4 | | WK-542 | CUP | 97.8-02.9 | (R)BH-T596<br>(L)BH-T610 | (R)BH-T692<br>(L)BH-T729 | | | (オートマチック) | | | | | |
| | | GT | 99.12-02.9 | 15/16 | | TK-T401 | 99.12-02.9 | | DISC | MP-85 | | 99.12-02.9 | | DISC | C-438P | | 99.12-02.9 | (R)BH-T827<br>(L)BH-T828 | (R)BH-T571<br>(L) | | | (オートマチック) | | | | | |
| | E−ST215G(4WD)<br>＜GF−は99．8～＞ | E･G | 97.8-02.9 | 15/16 | | TK-T401 | 97.8-97.11<br>97.11-02.9 | 57.2 | DISC<br>DISC | MP-50<br>MP-103 | CPM-68<br>CPM-68 | 97.8-02.9 | 3/4 | | WK-899 | CUP | 97.8-02.9 | (R)BH-T596<br>(L)BH-T610 | (R)BH-T732<br>(L)BH-T731 | 97.8-02.9 | 5/8 | MC-T395 | MK-T244 | 97.8-02.9 | 7/8 | | CK-T200 |
| | | GT | 97.8-02.9 | 15/16 | | TK-T401 | 97.8-97.11<br>97.11-02.9 | | DISC<br>DISC | MP-62<br>MP-85 | | 97.8-02.9 | | DISC | C-438P | | 97.8-02.9 | (R)BH-T827<br>(L)BH-T828 | (R)BH-T631<br>(L)BH-T632 | | | (オートマチック) | | | | | |
| | E−ST215W(4WD)<br>＜GF−は99．8～＞ | GT−T | <MT車><br>97.8-02.9<br><AT車><br>97.11-02.9<br><VSC無><br>99.12-02.9 | 15/16<br><br>15/16<br><br>15/16 | | TK-T401<br><br>TK-T439<br><br>TK-T401 | 97.8-97.11<br>97.11-02.9 | | DISC<br>DISC | MP-62<br>MP-85 | | 97.8-02.9 | | DISC | C-438P | | 97.8-02.9 | (R)BH-T827<br>(L)BH-T828 | (R)BH-T631<br>(L)BH-T632 | 97.8-02.9 | 5/8 | | MK-T244 | 97.8-02.9 | 15/16 | | CK-T224 |
| (2200ディーゼル)<br>KH−CT216G(4WD) | | | 97.8-02.9 | 15/16 | | TK-T401 | 97.8-97.11<br>97.11-02.9 | 57.2 | DISC<br>DISC | MP-50<br>MP-103 | CPM-68<br>CPM-68 | 97.8-02.9 | 3/4 | | WK-899 | CUP | 97.8-02.9 | (R)BH-T596<br>(L)BH-T610 | (R)BH-T732<br>(L)BH-T731 | | | (オートマチック) | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CALDINA : 240 ser.(02.9-) | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) | UA-ZZT241W | 02.9- | 13/16 | | | 02.9- | | DISC | MP-103 | CPM-68 | 02.9- | | DISC | MP-98 | CPM-98 | 02.9- | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| (2000) | TA-AZT241W<br>TA-AZT246W(4WD) | 02.9- | 13/16 | | | 02.9- | | DISC | MP-103 | CPM-68 | 02.9- | | DISC | MP-98 | CPM-98 | 02.9- | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| | LA-ST246W(4WDターボ) | 02.9-<br><VSC付><br>02.9- | 13/16<br><br>7/8 | | | 02.9- | | DISC | MP-107 | | 02.9- | | DISC | MP-100 | | 02.9- | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |

| Models | | TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| MR2 : 10, 11 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1500) | E−AW10 | S | 84.6-86.8<br>86.8-89.12 | 7/8<br>7/8 | | TK-T002<br>TK-T016 | 84.6-89.12 | 51.1 | DISC | MP-15 | CPM-15 | 84.6-87.6<br>87.6-89.12 | | DISC<br>DISC | A-146P<br>A-146P | | 84.6-89.12 | BH-02553 | (R)BH-02552<br>(L)BH-02552 | 84.6-89.12 | 5/8 | | | 84.6-89.2<br>89.2-89.12 | 13/16<br>13/16 | CC-70170<br>CC-70170 | CK-3144<br>CK-3144 |
| (1600) | E−AW11 | G・Gリミテッド | 84.6-86.8<br>86.8-89.12 | 7/8<br>7/8 | | TK-T002<br>TK-T016 | 84.6-89.12 | 51.1 | DISC | MP-6 | | 84.6-87.6<br>87.6-89.12 | | DISC<br>DISC | A-146P<br>A-146P | | 84.6-86.8<br>86.8-89.12 | BH-02553<br>BH-02554 | (R)BH-02552<br>(L)BH-02552<br>(R)BH-02552<br>(L)BH-02552 | 84.6-86.9<br>86.9-88.5<br>88.5-89.12 | 5/8<br>5/8<br>5/8 | | MK-4328<br>MK-4353<br>MK-4344 | 84.6-89.2<br>89.2-89.12<br><スーパーチャージャー付><br>86.8-89.2<br>89.2-89.12 | 13/16<br>13/16<br><br>13/16<br>13/16 | CC-70170<br>CC-70170 | CK-3144<br>CK-3144<br><br>CK-3144<br>CK-3144 |

| Models | TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| MR2 : 20 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000) | E－SW20 | G・Gリミテッド<br>GT | 89.12-91.11<br>91.11-91.12<br>91.12-99.8<br><アンチスキッド付><br>89.12-91.12<br>91.12-99.8<br><トラクションコントロール付><br>91.12-99.8 | 7/8<br><br>15/16<br><br>7/8<br>15/16<br><br>15/16 | | TK-T322<br><br>TK-T325<br><br>TK-T323<br>TK-T350<br><br>TK-T350 | 89.12-91.12<br>91.12-99.8 | 36.5<br>36.5 | DISC<br>DISC | MP-44<br>MP-44 | | 89.12-91.12<br>91.12-99.8 | 1 5/8 | DISC<br>DISC | A-321P | | 89.12-91.12<br><br>91.12-99.8 | BH-T581<br><br>BH-T585 | (R)BH-T754<br>(L)BH-T754<br>(R)BH-T754<br>(L)BH-T754 | 89.12-92.5<br>92.5-94.4<br>94.4-94.11<br>94.11-99.8 | 5/8<br>5/8<br>5/8<br>5/8 | MC-T291<br>MC-T291<br>MC-T291<br>MC-T291 | MK-T236<br><br><br>MK-T244 | 89.12-91.12<br>91.12-99.8<br><GT><br>89.12-91.12<br>91.12-93.11<br>93.11-99.8 | 7/8<br>13/16<br><br>7/8<br>13/16<br>7/8 | | CK-T200<br>CK-T201<br><br>CK-T200<br>CK-T201<br>CK-T200 |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| MR-S : 30 ser.(99.10-) | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) GH－ZZW30 <TA－は00. 8～> | 99.10- | | | | 99.10- | | DISC | MP-90 | CPM-90 | 99.10- | | DISC | B-321P | | 99.10- | (R) (L) | (R) (L) | 99.10-02.8 02.8- | 5/8 5/8 | | MK-T244 MK-T244 | 99.10-00.4 00.4- | 13/16 | | CK-T201 CK-T230 |

| Models | TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 86・GR86：ZN ser.(12.3-) | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000) | DBA－ZN6 | G<br>RC | 12.3- | | | ｷｯﾄｾｯﾃｲﾅｼ | 12.3-15.3<br>15.4-16.4<br>16.4-<br><G ｵﾌﾟｼｮﾝｺｰﾄﾞ I##,Q##><br>16.4- | | DISC<br>DISC<br>DISC<br><br>DISC | TP-87<br>TP-123<br>TP-123 | CPT-93<br>CPT-60<br>CPT-60 | 12.3-<br><G ｵﾌﾟｼｮﾝｺｰﾄﾞ I##,Q##><br>16.4- | | DISC | TP-125 | CPT-60 | 12.3-12.7<br><br>12.7-12.12<br><br>12.12-<br><br><G ｵﾌﾟｼｮﾝｺｰﾄﾞ I##,Q##><br>16.4- | (R)<br>(L)<br>(R)<br>(L)<br>(R)<br>(L)<br><br>(R)<br>(L) | (R)<br>(L)<br>(R)<br>(L)<br>(R)<br>(L)<br><br>(R)<br>(L) | 12.3-16.1<br>16.2- | 11/16<br>11/16 | MC-T486<br>MC-T486 | ｷｯﾄｾｯﾃｲﾅｼ<br>ｷｯﾄｾｯﾃｲﾅｼ | 12.3-14.10<br>14.10- | 13/16<br>13/16 | CC-T398<br>CC-T398 | ｷｯﾄｾｯﾃｲﾅｼ<br>ｷｯﾄｾｯﾃｲﾅｼ |
| | | GT<br>RACING | 12.3- | | | ｷｯﾄｾｯﾃｲﾅｼ | 12.3-<br><GT ADVICS><br>12.3-<br><GT ｵﾌﾟｼｮﾝｺｰﾄﾞ I##,Q##><br>16.4- | | DISC<br><br>DISC<br><br>DISC | TP-123<br><br>TP-123 | CPT-60<br><br>CPT-60 | 12.3-<br><GT ADVICS><br>12.3-<br><ｵﾌﾟｼｮﾝｺｰﾄﾞ I##,Q##><br>16.4- | | DISC<br><br>DISC | TP-125<br><br>TP-125 | CPT-60<br><br>CPT-60 | 12.3-12.7<br><br>12.7-12.12<br><br>12.12-<br><br><ｵﾌﾟｼｮﾝｺｰﾄﾞ I##,Q##><br>16.4- | (R)<br>(L)<br>(R)<br>(L)<br>(R)<br>(L)<br><br>(R)<br>(L) | (R)<br>(L)<br>(R)<br>(L)<br>(R)<br>(L)<br><br>(R)<br>(L) | 12.3-16.1<br>16.2- | 11/16<br>11/16 | MC-T486<br>MC-T486 | ｷｯﾄｾｯﾃｲﾅｼ<br>ｷｯﾄｾｯﾃｲﾅｼ | 12.3-14.10<br>14.10- | 13/16<br>13/16 | CC-T398<br>CC-T398 | ｷｯﾄｾｯﾃｲﾅｼ<br>ｷｯﾄｾｯﾃｲﾅｼ |
| | GRMN86 | 限定車 | 16.2- | | | ｷｯﾄｾｯﾃｲﾅｼ | 16.2- | | DISC | | | 16.2- | | DISC | | | 16.2- | (R)<br>(L) | (R)<br>(L) | 16.2- | 11/16 | MC-T486 | ｷｯﾄｾｯﾃｲﾅｼ | 16.2- | 13/16 | CC-T398 | ｷｯﾄｾｯﾃｲﾅｼ |
| (2400) | 3BA－ZN8 | RZ | 21.10- | | | ｷｯﾄｾｯﾃｲﾅｼ | 21.10- | | DISC | TP-123 | CPT-60 | 21.10- | | DISC | TP-125 | CPT-60 | 21.10- | | | 21.10- | 11/16 | MC-T486 | ｷｯﾄｾｯﾃｲﾅｼ | 21.10- | 13/16 | CC-T398 | ｷｯﾄｾｯﾃｲﾅｼ |
| | | RC<br>SZ<br>レーシング | 21.10- | | | ｷｯﾄｾｯﾃｲﾅｼ | 21.10- | | DISC | TP-123 | CPT-60 | 21.10- | | DISC | TP-125 | CPT-60 | 21.10- | | | 21.10- | 11/16 | MC-T486 | ｷｯﾄｾｯﾃｲﾅｼ | 21.10- | 13/16 | CC-T398 | ｷｯﾄｾｯﾃｲﾅｼ |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| RAUM : 10 ser. | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1500) E－EXZ10 | 97.5-99.7 | 13/16 | | TK-T357 | 97.5- | 51.1 | DISC | MP-15 | CPM-15 | 97.5-99.12 | 11/16 | (R)WC-T599 | WK-569 | CUP | 97.5- | (R)BH-T660 | (R)BH-T956 | | | (オートマチック) | | | | | |
| ＜GF－は98．8～＞ | 99.7- | 13/16 | | TK-T358 | | | | | | | | (L)WC-T617 | | | | (L)BH-T661 | (L)BH-T956 | | | | | | | | |
| ＜TA－は02．4～＞ | | | | | | | | | | 99.12- | 11/16 | (R)WC-T599 | WK-569 | CUP | | | | | | | | | | | |
| | | | | | | | | | | | | (L)WC-T599 | | | | | | | | | | | | | |
| E－EXZ15(4WD) | 97.8-99.7 | 13/16 | | TK-T357 | 97.8- | 51.1 | DISC | MP-15 | | 97.8- | 3/4 | (R)WC-T649 | WK-542 | CUP | 97.8- | (R)BH-T660 | (R)BH-T656 | | | (オートマチック) | | | | | |
| ＜GF－は98．8～＞ | 99.7- | 13/16 | | TK-T358 | | | | | | | | (L)WC-T649 | | | | (L)BH-T661 | (L)BH-T532 | | | | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| RAUM : 20 ser.(03.4-) | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1500) | UA-NCZ20 | 03.4-<br><VSC付><br>03.4- | | | | 03.4-04.9<br>04.9- | | DISC<br>DISC | MP-95<br>MP-95 | | 03.4- | 13/16 | (R)<br>(L) | WK-542 | CUP | 03.4- | (R)BH-T778<br>(L)BH-T779 | (R)BH-T941<br>(L)BH-T941 | | | (オートマチック) | | | | | |
| | UA-NCZ25(4WD) | 03.4- | | | | 03.4-04.9<br>04.9- | | DISC<br>DISC | MP-95<br>MP-95 | | 03.4- | 13/16 | (R)<br>(L) | WK-542 | CUP | 03.4- | (R)BH-T780<br>(L)BH-T781 | (R)BH-T782<br>(L)BH-T783 | | | (オートマチック) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| PRIUS：10 ser.(97.12-), 20 ser.(03.8-), 30 ser.(09.4-), 50 ser.(15.11-), 60 ser.(22.12-)PRIUS α：40 ser., | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1500) | HK－NHW10 | | 97.12-00.5 | | | | 97.12-00.5 | 54.0 | DISC | MP-74 | | 97.12-00.5 | 3/4 | (R)WC-T600<br>(L)WC-T605 | WK-542 | CUP | 97.12-00.5 | (R)BH-T825<br>(L)BH-T826 | (R)BH-T824<br>(L)BH-T824 | | | (オートマチック) | | | | | |
| | ZA－NHW11 | リヤードラム車 | 00.5-03.8 | | | | 00.5-03.8 | | DISC | MP-95 | CPM-95 | 00.5-03.8 | 13/16 | (R)WC-T797<br>(L)WC-T798 | WK-999 | CUP | 00.5-03.8 | (R)BH-T849<br>(L)BH-T850 | (R)BH-T824<br>(L)BH-T824 | | | (オートマチック) | | | | | |
| | | 四輪ディスク車 | 01.8-03.8 | | | | 01.8-03.8 | | DISC | MP-102 | CPM-102 | 01.8-03.8 | | DISC | SP-106 | CPS-106 | 01.8-03.8 | (R)BH-T849<br>(L)BH-T850 | (R)BH-T835<br>(L)BH-T835 | | | (オートマチック) | | | | | |
| | ZA－NHW20 | | 03.8-11.12 | | | | 03.8-11.12 | | DISC | MP-95 | | 03.8-11.12 | 3/4 | (R)WC-T780<br>(L)WC-T781 | WK-542 | CUP | 03.8-06.12<br>06.12-11.12 | (R)<br>(L)<br>(R)<br>(L) | (R)BH-T948<br>(L)BH-T948<br>(R)<br>(L) | | | (オートマチック) | | | | | |
| (1800) | DAA－ZVW30 | | 09.4-15.12 | | | | 09.4-15.12 | | DISC | MP-118 | | 09.4-15.12 | | DISC | TP-111 | | 09.4-15.12 | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| | DLA－ZVW35 | | 09.12-17.2 | | | | 09.12-17.2 | | DISC | MP-118 | | 09.12-17.2 | | DISC | TP-111 | | 09.12-17.2 | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| | DAA－ZVW40W<br>DAA－ZVW41W | 7人乗り<br>5人乗り | 11.4- | | | | 11.4- | | DISC | MP-114 | CPM-106 | 11.4-14.11<br>14.11-<br><G's・GR SPORT><br>18.5- | | DISC<br>DISC<br><br>DISC | SP-414 | CPM-117<br>CPM-117<br><br>CPM-117 | 11.4- | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| | DAA－ZVW50 | | 15.11- | | | | 15.11- | | DISC | MP-118 | | 15.11- | | DISC | TP-111 | | 15.11- | (R)<br>(L) | (R)<br>(L) | | | (電気式無段変速機) | | | | | |
| | DAA－ZVW51 | | 15.11- | | | | 15.11- | | DISC | MP-118 | | 15.11- | | DISC | TP-111 | | 15.11- | (R)<br>(L) | (R)<br>(L) | | | (電気式無段変速機) | | | | | |
| | DLA－ZVW52 | | 17.1- | | | | 17.1-19.4<br>19.5- | | DISC<br>DISC | MP-118 | | 17.1- | | DISC | TP-111 | | 17.1- | (R)<br>(L) | (R)<br>(L) | | | (電気式無段変速機) | | | | | |
| | DAA－ZVW55 | | 15.11- | | | | 15.11- | | DISC | MP-118 | | 15.11- | | DISC | TP-111 | | 15.11- | (R)<br>(L) | (R)<br>(L) | | | (電気式無段変速機) | | | | | |
| | 6AA－ZVW60 | 前輪駆動方式(2WD) | 22.12- | | | キットセッテイナシ | 22.12- | | DISC | | | 22.12- | | DISC | | | 22.12- | (R)<br>(L) | (R)<br>(L) | | | (電気式無段変速機) | | | | | |
| | 6AA－ZVW65 | 電気式四輪駆動方式(E-Four) | 22.12- | | | キットセッテイナシ | 22.12- | | DISC | | CPM-116 | 22.12- | | DISC | | | 22.12- | (R)<br>(L) | (R)<br>(L) | | | (電気式無段変速機) | | | | | |
| (2000) | 6AA－MXWH60 | 前輪駆動方式(2WD) | 22.12- | | | キットセッテイナシ | 22.12- | | DISC | | | 22.12- | | DISC | | | 22.12- | (R)<br>(L) | (R)<br>(L) | | | (電気式無段変速機) | | | | | |
| | 6AA－MXWH65 | 電気式四輪駆動方式(E-Four) | 22.12- | | | キットセッテイナシ | 22.12- | | DISC | | CPM-116 | 22.12- | | DISC | | | 22.12- | | | | | | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| AQUA : 10 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1500) | DAA－NHP10<br>DAA－NHP10H | 11.12- | | | ｷｯﾄｾｯﾃｲﾅｼ | 11.12-17.6<br>17.6- | 54 | DISC<br>DISC | MP-110<br>MP-136 | | 11.12- | | (R)WC-T787<br>(L)WC-T787 | WK-900 | | 11.12-14.8<br>14.8- | (R)<br>(L)<br>(R)<br>(L) | (R)BH-T956<br>(L)BH-T957<br>(R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | 6AA－MXPK10<br>6AA－MXPK11 | 21.6- | | | ｷｯﾄｾｯﾃｲﾅｼ | 21.6- | | DISC | MP-136 | | 21.6- | 3/4 | (R)WC-T780<br>(L)WC-T781 | WK-542 | CUP | 21.6- | (R)<br>(L) | (R)<br>(L) | | | (電気式無段変速機) | | | | | |
| | 6AA－MXPK15(4WD)<br>6AA－MXPK16(4WD) | 21.6- | | | ｷｯﾄｾｯﾃｲﾅｼ | 21.6- | | DISC | MP-136 | | 21.6- | 13/16 | (R)WC-T787<br>(L)WC-T787 | WK-900 | CUP | 21.6- | (R)<br>(L) | (R)<br>(L) | | | (電気式無段変速機) | | | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| MIRAI : 10 ser. | | | | | | | | | | | | | | | | | | | | | | | | | |
| ZBA－JPD10 | 14.12-20.5 | | | ｷｯﾄｾｯﾃｲﾅｼ | 14.12-20.5 | | DISC | | CPM-106 | 14.12-20.5 | | DISC | | CPM-113 | 14.12-20.5 | (R)<br>(L) | (R-1)<br>(L-1)<br>(R-2)<br>(L-2) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| ZBA－JPD20 | 20.11- | | | | 20.11- | | DISC | | CPS-400 | 20.11- | | DISC | | | 20.11- | | | | | | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TANK, ROOMY : M900 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1000) | DBA－M900A | G・X | 16.11- | | | ｷｯﾄｾｯﾃｲﾅｼ | 16.11- | | DISC | MP-134 | CPT-81 | 16.11- | 3/4 | (R)WC-D295<br>(L)WC-D296 | WK-542 | CUP | 16.11- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | | | | | | | | | | | | <ﾊﾟｰｷﾝｸﾞﾌﾞﾚｰｷ・電動ﾊﾟｰｷﾝｸﾞﾌﾞﾚｰｷ> | | | | | | | | | | | | | | |
| | | | | | | | | | | | | 20.9- | 3/4 | (R)WC-D296<br>(L)WC-D295 | WK-542 | CUP | | | | | | | | | | | |
| | | カスタムG | 16.11- | | | ｷｯﾄｾｯﾃｲﾅｼ | 16.11- | | DISC | MP-134 | CPT-81 | 16.11-20.9 | 3/4 | (R)WC-D295<br>(L)WC-D296 | WK-542 | CUP | 16.11- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | | | | | | | | | | | | 20.9- | 3/4 | (R)WC-D296<br>(L)WC-D295 | WK-542 | CUP | | | | | | | | | | | |
| | DBA－M910A(4WD) | G・X | 16.11- | | | ｷｯﾄｾｯﾃｲﾅｼ | 16.11- | | DISC | MP-134 | CPT-81 | 16.11-20.9 | 11/16 | (R)WC-D290<br>(L)WC-D290 | WK-699-01 | CUP | 16.11- | (R)<br>(L) | (R)BH-D233<br>(L)BH-D233 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | | | | | | | | | | | | <ｻｲｽﾞ確認> | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | 20.9- | 3/4 | | WK-542 | CUP | | | | | | | | | | | |
| | | | | | | | | | | | | <ｻｲｽﾞ確認> | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | <ﾊﾟｰｷﾝｸﾞﾌﾞﾚｰｷ・電動ﾊﾟｰｷﾝｸﾞﾌﾞﾚｰｷ> | | | | | | | | | | | | | | |
| | | | | | | | | | | | | 20.9- | 11/16 | (R)WC-T778<br>(L)WC-T777 | WK-935 | CUP | | | | | | | | | | | |
| | | カスタムG | 16.11- | | | ｷｯﾄｾｯﾃｲﾅｼ | 16.11- | | DISC | MP-134 | CPT-81 | 16.11-20.9 | 11/16 | (R)WC-D290<br>(L)WC-D290 | WK-699-01 | CUP | 16.11-20.9 | (R)<br>(L) | (R)BH-D233<br>(L)BH-D233 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | | | | | | | | | | | | 20.9- | 11/16 | (R)WC-T778<br>(L)WC-T777 | WK-935 | CUP | 20.9- | (R)<br>(L) | (R)<br>(L) | | | | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CORSA, TARCEL : 10 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1300) | AL11 | 全車 | 78.8-82.4 | 3/4 | | TK-9420 | 78.8-82.4 | 48.1 | DISC | MP-5 | | 78.8-82.4 | 5/8 | (R)WC-50058<br>(L)WC-50058 | WK-442 | CUP | 78.8-82.4 | BH-02364 | (R)BH-02365<br>(L)BH-02365 | | | (ワイヤー式) | | | | | |
| (1500) | AL10・12 | | | | | | | | | | | | | | | | | | | | | | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CORSA, TARCEL, COROLLA 2 : 20 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1300)<br>(1500) | E−AL20<br>E−AL21 | 全車 | 82.5−89.10 | 13/16 | | TK−9422 | 82.5−89.10 | 48.1 | DISC | MP−7 | | 82.5−89.10 | 11/16 | (R)WC−55020<br>(L)WC−57020 | WK−569 | CUP | 82.5−84.8<br>84.8−89.10 | BH−02437<br>BH−T822 | (R)BH−02220<br>(L)BH−02220<br>(R)BH−02220<br>(L)BH−02220 | | | (ワイヤー式) | | | | | |
| (1500) | E−AL25(4WD) | 全車 | 84.8−89.10 | 13/16 | | TK−9422 | 84.8−89.10 | 48.1 | DISC | MP−7 | | 84.8−89.10 | 3/4 | (R)WC−50055<br>(L)WC−50055 | WK−542 | CUP | 84.8−89.10 | BH−02437 | (R)BH−31305<br>(L)BH−95005 | | | (ワイヤー式) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CORSA, TARCEL, COROLLA 2 : 30 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1300) | E－EL30 | | 86.5-90.9 | 13/16 | TD-T640 | TK-T023 | 86.5-90.9 | 48.1 | DISC | MP-7 | | 86.5-90.9 | 11/16 | (R)WC-55020<br>(L)WC-57020 | WK-569 | CUP | 86.5-90.9 | BH-02461 | (R)BH-02509<br>(L)BH-02509 | 86.5-86.11<br>86.11-88.5<br>88.5-90.9 | 5/8<br>5/8<br>5/8 | MC-T384 | MK-4326<br>MK-4353<br>MK-4353 | 86.5-89.2<br>89.2-90.9 | 13/16<br>13/16 | CC-70179<br>CC-70179 | CK-3144<br>CK-3144 |
| (1500) | E－EL31 | 除くターボ車 | 86.5-90.9<br><3EEｴﾝｼﾞﾝ車><br>88.5-89.3<br>89.3-90.9 | 13/16<br><br>13/16 | TD-T640 | TK-T023<br><br>TK-T023<br>TK-T315 | 86.5-90.9 | 48.1 | DISC | MP-7 | | 86.5-90.9 | 11/16 | (R)WC-55020<br>(L)WC-57020 | WK-569 | CUP | 86.5-90.9 | BH-02461 | (R)BH-02509<br>(L)BH-02509 | 86.5-86.11<br>86.11-88.5<br>88.5-90.9 | 5/8<br>5/8<br>5/8 | MC-T384 | MK-4326<br>MK-4353<br>MK-4353 | 86.5-89.2<br>89.2-90.9 | 13/16<br>13/16 | CC-70179<br>CC-70179 | CK-3144<br>CK-3144 |
| | | ターボ車 | 86.9-88.5<br>88.5-90.9 | 7/8<br>7/8 | TD-T641 | TK-T032<br>TK-T033 | 86.9-90.9 | 51.1 | DISC | MP-15 | CPM-15 | 86.9-90.9 | 30.2 | DISC | MP-23 | | 86.9-90.9 | BH-02461 | (R-1)BH-02509<br>(L-1)BH-02509<br>(R-2)BH-02510<br>(L-2)BH-02510 | 86.9-86.11<br>86.11-88.5<br>88.5-88.11<br>88.11-90.9 | 5/8<br>5/8<br>5/8<br>5/8 | MC-T384 | MK-4326<br>MK-4353<br>MK-4353<br>MK-4344 | 86.9-89.2<br>89.2-90.9 | 13/16<br>13/16 | CC-70179<br>CC-70179 | CK-3144<br>CK-3144 |
| (1500ディーゼル) | Q－NL30<br>N－NL30 | ターボ車 | 86.5-90.9 | 13/16 | TD-T640 | TK-T023 | 86.5-90.9 | 48.1 | DISC | MP-7 | | 86.5-90.9 | 11/16 | (R)WC-55020<br>(L)WC-57020 | WK-569 | CUP | 86.5-90.9 | BH-02461 | (R)BH-02509<br>(L)BH-02509 | 86.5-86.11<br>86.11-90.9 | 5/8<br>5/8 | | MK-4329<br>MK-4337 | 86.5-88.5<br>88.5-89.2<br>89.2-90.9 | 13/16<br>13/16<br>13/16 | CC-70186<br><br>CC-70179 | CK-3144<br>CK-3144<br>CK-3144 |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CORSA, TARCEL, COROLLA 2 : 40 ser. | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1300) E－EL41 | 90.9-92.8 | 13/16 | | TK-T023 | 90.9-94.9 | 48.1 | DISC | MP-7 | | 90.9-94.9 | 11/16 | (R)WC-55020 | WK-569 | CUP | 90.9-94.9 | (R)BH-T529 | (R)BH-T956 | 90.9-92.2 | 5/8 | MC-T284 | MK-T236 | 90.9-94.1 | 13/16 | CC-70179 | CK-3144 |
| | 92.8-94.9 | 13/16 | | TK-T327 | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | (L)WC-57020 | | | | (L)BH-T530 | (L)BH-T956 | 92.2-94.3 | 5/8 | MC-T284 | | 94.1-94.9 | 13/16 | CC-70179 | CK-T201 |
| | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | 90.9-94.9 | 51.1 | DISC | MP-15 | CPM-15 | | | | | | | | | 94.3-94.9 | 5/8 | | MK-T244 | | | | |
| | 90.9-94.9 | 7/8 | | TK-T320 | | | | | | | | | | | | | | | | | | | | | |
| (1500) E－EL43 5E－FEエンジン | 90.9-92.8 | 13/16 | | TK-T023 | 90.9-94.9 | 48.1 | DISC | MP-7 | | 90.9-94.9 | 11/16 | (R)WC-55020 | WK-569 | CUP | 90.9-94.9 | (R)BH-T529 | (R)BH-T956 | 90.9-92.2 | 5/8 | MC-T284 | MK-T236 | 90.9-94.1 | 13/16 | CC-70179 | CK-3144 |
| | 92.8-94.9 | 13/16 | | TK-T327 | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | (L)WC-57020 | | | | (L)BH-T530 | (L)BH-T956 | 92.2-94.3 | 5/8 | MC-T284 | | 94.1-94.9 | 13/16 | CC-70179 | CK-T201 |
| | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | 90.9-94.9 | 51.1 | DISC | MP-15 | CPM-15 | | | | | | | | | 94.3-94.9 | 5/8 | | MK-T244 | | | | |
| | 90.9-94.9 | 7/8 | | TK-T320 | | | | | | | | | | | | | | | | | | | | | |
| 5E－FHEエンジン | 90.9-94.9 | 7/8 | | TK-T402 | 90.9-94.9 | 51.1 | DISC | MP-15 | CPM-15 | 90.9-94.9 | 11/16 | (R)WC-55020 | WK-569 | CUP | 90.9-94.9 | (R)BH-T529 | (R)BH-T956 | 90.9-92.2 | 5/8 | MC-T284 | MK-T236 | 90.9-93.1 | 13/16 | CC-70183 | CK-3144 |
| | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | (L)WC-57020 | | | | (L)BH-T530 | (L)BH-T956 | 92.2-94.3 | 5/8 | MC-T284 | | 93.1-94.9 | 13/16 | CC-70183 | CK-T201 |
| | 90.9-94.9 | 7/8 | | TK-T320 | | | | | | | | | | | | | | 94.3-94.9 | 5/8 | | MK-T244 | | | | |
| E－EL45(4WD) | 90.9-92.8 | 13/16 | | TK-T023 | 90.9-94.9 | 48.1 | DISC | MP-45 | | 90.9-94.9 | 11/16 | (R)WC-T639 | WK-569 | CUP | 90.9-94.9 | (R)BH-T529 | (R)BH-T656 | 90.9-92.2 | 5/8 | MC-T284 | MK-T236 | 90.9-94.1 | 13/16 | CC-70179 | CK-3144 |
| | 92.8-94.9 | 13/16 | | TK-T327 | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | (L)WC-T639 | | | | (L)BH-T530 | (L)BH-T532 | 92.2-94.3 | 5/8 | MC-T284 | | 94.1-94.9 | 13/16 | CC-70179 | CK-T201 |
| | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | 90.9-94.9 | 51.1 | DISC | MP-15 | CPM-15 | | | | | | | | | 94.3-94.9 | 5/8 | | MK-T244 | | | | |
| | 90.9-94.9 | 7/8 | | TK-T320 | | | | | | | | | | | | | | | | | | | | | |
| (1500ディーゼル) | 90.9-92.8 | 13/16 | | TK-T023 | 90.9-94.9 | 48.1 | DISC | MP-7 | | 90.9-94.9 | 11/16 | (R)WC-55020 | WK-569 | CUP | 90.9-94.9 | (R)BH-T529 | (R)BH-T956 | 90.9-92.2 | 5/8 | MC-T374 | MK-T236 | 90.9-94.1 | 13/16 | CC-70186 | CK-3144 |
| X－NL40 | 92.8-94.9 | 13/16 | | TK-T327 | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | (L)WC-57020 | | | | (L)BH-T530 | (L)BH-T956 | 92.2-94.3 | 5/8 | MC-T374 | | 94.1-94.9 | 13/16 | CC-70186 | CK-T201 |
| | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | 90.9-94.9 | 51.1 | DISC | MP-15 | CPM-15 | | | | | | | | | 94.3-94.9 | 5/8 | | MK-T244 | | | | |
| | 90.9-94.9 | 7/8 | | TK-T320 | | | | | | | | | | | | | | | | | | | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CORSA, TARCEL, COROLLA 2 : 50 ser.(94.9-) | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1300) E－EL51 | 94.9-95.12 | 3/4 | | TK-T356 | 94.9-99.7 | 48.1 | DISC | MP-7 | | 94.9-99.7 | 11/16 | (R)WC-T599 | WK-569 | CUP | 94.9-99.7 | (R)BH-T660 | (R)BH-T956 | 94.9-99.7 | 5/8 | MC-T374 | MK-T244 | 94.9-95.9 | 13/16 | CC-70179 | CK-T201 |
| | 95.12-99.7 | 3/4 | | TK-T406 | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | (L)WC-T617 | | | | (L)BH-T661 | (L)BH-T956 | | | | | 95.9-99.7 | 7/8 | | CK-T200 |
| | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | 94.9-99.7 | 51.1 | DISC | MP-15 | CPM-15 | | | | | | | | | | | | | | | | |
| | 94.9-99.7 | 13/16 | | TK-T358 | | | | | | | | | | | | | | | | | | | | | |
| (1500) E－EL53 | 94.9-95.12 | 3/4 | | TK-T356 | 94.9-96.8 | 48.1 | DISC | MP-7 | | 94.9-99.7 | 11/16 | (R)WC-T599 | WK-569 | CUP | 94.9-99.7 | (R)BH-T660 | (R)BH-T956 | 94.9-99.7 | 5/8 | MC-T374 | MK-T244 | 94.9-95.9 | 13/16 | CC-70179 | CK-T201 |
| | 95.12-96.8 | 3/4 | | TK-T406 | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | (L)WC-T617 | | | | (L)BH-T661 | (L)BH-T956 | | | | | 95.9-99.7 | 7/8 | | CK-T200 |
| | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | 94.9-99.7 | 51.1 | DISC | MP-15 | CPM-15 | | | | | | | | | | | | | | | | |
| | 94.9-99.7 | 13/16 | | TK-T358 | | | | | | | | | | | | | | | | | | | | | |
| E－EL55(4WD) | 94.9-96.8 | 13/16 | | TK-T357 | 94.9-99.7 | 51.1 | DISC | MP-15 | CPM-15 | 94.9-99.7 | 11/16 | (R)WC-T647 | WK-569 | CUP | 94.9-99.7 | (R)BH-T660 | (R)BH-T656 | 94.9-99.7 | 5/8 | MC-T374 | MK-T244 | 94.9-99.7 | 13/16 | CC-70179 | CK-T201 |
| | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | (L)WC-T647 | | | | (L)BH-T661 | (L)BH-T532 | | | | | | | | |
| | 94.9-99.7 | 13/16 | | TK-T358 | | | | | | | | | | | | | | | | | | | | | |
| (1500ディーゼル) | 94.9-95.12 | 3/4 | | TK-T356 | 94.9-96.8 | 48.1 | DISC | MP-7 | | 94.9-99.7 | 11/16 | (R)WC-T599 | WK-569 | CUP | 94.9-99.7 | (R)BH-T660 | (R)BH-T956 | 94.9-96.8 | 5/8 | MC-T374 | MK-T244 | 94.9-99.7 | 13/16 | CC-70186 | CK-T201 |
| KD－NL50 | 95.12-96.8 | 3/4 | | TK-T406 | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | (L)WC-T617 | | | | (L)BH-T661 | (L)BH-T956 | 96.8-99.7 | 5/8 | MC-T374 | | | | | |
| | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | 94.9-99.7 | 51.1 | DISC | MP-15 | CPM-15 | | | | | | | | | | | | | | | | |
| | 94.9-99.7 | 13/16 | | TK-T358 | | | | | | | | | | | | | | | | | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CYNOS : 40 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | <アルファ仕様> | | | |
| (1500) | E−EL44 | リヤードラム車 | 91.1−94.9 | 7/8 | | TK−T402 | 91.1−95.8 | 51.1 | DISC | MP−15 | CPM−15 | 91.1−94.9 | 11/16 | (R)WC−55020 | WK−569 | CUP | 91.1−94.8 | (R)BH−T529 | (R)BH−T956 | 91.1−92.2 | 5/8 | MC−T284 | MK−T236 | 91.1−94.1 | 13/16 | CC−70179 | CK−3144 |
| | | | 94.9−95.8 | 13/16 | | TK−T357 | | | | | | | | (L)WC−57020 | | | | (L)BH−T530 | (L)BH−T956 | 92.2−94.3 | 5/8 | MC−T284 | | 94.1−95.8 | 13/16 | | CK−T201 |
| | | | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | 94.9−95.8 | 11/16 | | WK−569 | CUP | 94.8−95.8 | (R)BH−T660 | (R)BH−T956 | 94.3−95.8 | 5/8 | | MK−T244 | <ﾍﾞｰﾀ仕様> | | | |
| | | | 91.1−94.9 | 7/8 | | TK−T320 | | | | | | | | | | | | (L)BH−T661 | (L)BH−T956 | | | | | 91.1−93.1 | 13/16 | CC−70183 | CK−3144 |
| | | | 94.9−95.8 | 13/16 | | TK−T358 | | | | | | | | | | | | | | | | | | 93.1−95.8 | 13/16 | CC−70183 | CK−T201 |
| | | 四輪ディスク車 | 91.1−94.9 | 7/8 | | TK−T402 | 91.1−95.8 | 51.1 | DISC | MP−15 | CPM−15 | 91.1−95.8 | 30.2 | DISC | MP−23 | | 91.1−94.8 | (R)BH−T529 | (R−1)BH−T956 | 91.1−92.2 | 5/8 | MC−T284 | MK−T236 | 91.1−93.1 | 13/16 | CC−70183 | CK−3144 |
| | | | 94.9−95.8 | 13/16 | | TK−T357 | | | | | | | | | | | | (L)BH−T530 | (L−1)BH−T956 | 92.2−94.3 | 5/8 | MC−T284 | | 93.1−95.8 | 13/16 | CC−70183 | CK−T201 |
| | | | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | | | | | | (R−2)BH−T558 | 94.3−95.8 | 5/8 | | MK−T244 | | | | |
| | | | 91.1−94.9 | 7/8 | | TK−T320 | | | | | | | | | | | | | (L−2)BH−T558 | | | | | | | | |
| | | | 94.9−95.8 | 13/16 | | TK−T358 | | | | | | | | | | | 94.8−95.8 | (R)BH−T660 | (R−1)BH−T956 | | | | | | | | |
| | | | | | | | | | | | | | | | | | | (L)BH−T661 | (L−1)BH−T956 | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | (R−2)BH−T558 | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | (L−2)BH−T558 | | | | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CYNOS : 50 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1300) | E−EL52 | | 95.8−95.12 | 3/4 | | TK−T356 | 95.8−96.8 | 48.1 | DISC | MP−7 | | 95.8−99.7 | 11/16 | (R)WC−T599 | WK−569 | CUP | 95.8−99.7 | (R)BH−T660 | (R)BH−T956 | 95.8−99.7 | 5/8 | MC−T374 | MK−T244 | 95.8−95.9 | 13/16 | CC−70179 | CK−T201 |
| | | | 95.12−96.8 | 3/4 | | TK−T406 | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | (L)WC−T617 | | | | (L)BH−T661 | (L)BH−T956 | | | | | 95.9−99.7 | 7/8 | | CK−T200 |
| | | | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | 95.8−99.7 | 51.1 | DISC | MP−15 | CPM−15 | | | | | | | | | | | | | | | | |
| | | | 95.8−97.12 | 13/16 | | TK−T358 | | | | | | | | | | | | | | | | | | | | | |
| | | | 97.12−99.7 | 13/16 | | TK−T357 | | | | | | | | | | | | | | | | | | | | | |
| | E−EL52C | コンバーチブル | 96.10−98.2 | 13/16 | | TK−T358 | 96.10−99.7 | 51.1 | DISC | MP−15 | CPM−15 | 96.10−99.7 | 11/16 | (R)WC−T599 | WK−569 | CUP | 96.10−99.7 | (R)BH−T660 | (R)BH−T956 | 96.10−99.7 | 5/8 | MC−T374 | MK−T244 | 96.10−99.7 | 7/8 | | CK−T200 |
| | | | 98.2−99.7 | 13/16 | | TK−T357 | | | | | | | | (L)WC−T617 | | | | (L)BH−T661 | (L)BH−T956 | | | | | | | | |
| (1500) | E−EL54 | | 95.8−96.8 | 13/16 | | TK−T357 | 95.8−99.7 | 51.1 | DISC | MP−15 | CPM−15 | 95.8−99.7 | 11/16 | (R)WC−T599 | WK−569 | CUP | 95.8−99.7 | (R)BH−T660 | (R)BH−T956 | 95.8−99.7 | 5/8 | MC−T374 | MK−T244 | 95.8−99.7 | 13/16 | CC−70183 | CK−T201 |
| | | | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | (L)WC−T617 | | | | (L)BH−T661 | (L)BH−T956 | | | | | | | | |
| | | | 95.8−97.12 | 13/16 | | TK−T358 | | | | | | | | | | | | | | | | | | | | | |
| | | | 97.12−99.7 | 13/16 | | TK−T357 | | | | | | | | | | | | | | | | | | | | | |
| | E−EL54C | コンバーチブル | 96.10−98.2 | 13/16 | | TK−T358 | 96.10−99.7 | 51.1 | DISC | MP−15 | CPM−15 | 96.10−99.7 | 11/16 | (R)WC−T599 | WK−569 | CUP | 96.10−99.7 | (R)BH−T660 | (R)BH−T956 | 96.10−99.7 | 5/8 | MC−T374 | MK−T244 | 96.10−99.7 | 13/16 | CC−70183 | CK−T201 |
| | | | 98.2−99.7 | 13/16 | | TK−T357 | | | | | | | | (L)WC−T617 | | | | (L)BH−T661 | (L)BH−T956 | | | | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| AURIS : 150 ser. 180 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1500) | DBA－NZE151H | | 06.10- | | | キットセッテイナシ | 06.10- | | DISC | MP-116 | CPM-116 | 06.10- | | DISC | TP-111 | | 06.10- | (R)<br>(L) | (R-1)<br>(L-1)<br>(R-2)<br>(L-1) | | | (オートマチック) | | | | | |
| | DBA－NZE154H | 4WD | 06.10- | | | キットセッテイナシ | 06.10- | | DISC | MP-116 | CPM-116 | 06.10- | | DISC | TP-111 | | 06.10- | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| | DBA－NZE181H | | 12.8- | | | キットセッテイナシ | 12.8- | | DISC | MP-116 | CPM-116 | 12.8- | | DISC | TP-112 | | 12.8- | (R)<br>(L) | (R-1)<br>(L-1)<br>(R-2)<br>(L-1) | | | (オートマチック) | | | | | |
| | DBA－NZE184H | 4WD | 12.8- | | | キットセッテイナシ | 12.8- | | DISC | MP-116 | CPM-116 | 12.8- | | DISC | TP-111 | | 12.8- | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| (1800) | DBA－ZRE152H | | 06.10-<br><SRSｴｱﾊﾞｯｸﾞ・膝衝撃吸収ﾊﾟｯﾄ><br>06.10- | | | キットセッテイナシ<br>キットセッテイナシ | 06.10- | | DISC | MP-116 | CPM-116 | 06.10- | | DISC | TP-111 | | 06.10- | (R)<br>(L) | (R-1)<br>(L-1)<br>(R-2)<br>(L-1) | 06.10-<br><MT 6速><br>06.10- | | (オートマチック) | キットナシ | <MT 6速><br>09.10-10.4<br>10.4- | | | キットナシ<br>キットナシ |
| | DBA－ZRE154H | 4WD | 06.10- | | | キットセッテイナシ | 06.10- | | DISC | MP-116 | CPM-116 | 06.10- | | DISC | TP-111 | | 06.10- | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| | DBA－ZRE186H | 除くRS | 12.8- | | | キットセッテイナシ | 12.8- | | DISC | MP-116 | CPM-116 | 12.8- | | DISC | TP-111 | | 12.8- | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| | | RS | 12.8- | | | キットセッテイナシ | 12.8- | | DISC | MP-114 | CPM-106 | 12.8- | | DISC | TP-111 | | 12.8- | (R)<br>(L) | (R)<br>(L) | 12.8- | | | | 12.8- | | | |
| | DAA－ZWE186H | ハイブリッド | 16.4- | | | キットセッテイナシ | 16.4- | | DISC | MP-114 | CPM-106 | 16.4- | | DISC | TP-111 | | 16.4- | (R)<br>(L) | (R)<br>(L) | 16.4- | | | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| SERA : 10 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1500) | E－EXY10 | アンチスキッド無 | 90.3-95.12 | 13/16 | | TK-T023 | 90.3-95.12 | 51.1 | DISC | MP-15 | CPM-15 | 90.3-95.12 | 11/16 | (R)WC-55020<br>(L)WC-57020 | WK-569 | CUP | 90.3-94.5<br><br>94.5-95.12 | (R)BH-T660<br>(L)BH-T661<br>(R)BH-T660<br>(L)BH-T661 | (R)BH-T956<br>(L)BH-T956<br>(R)BH-T956<br>(L)BH-T956 | 90.3-92.2<br>92.2-94.3<br>94.3-95.12 | 5/8<br>5/8<br>5/8 | | MK-T236<br><br>MK-T244 | 90.3-93.1<br>93.1-94.8<br>94.8-95.12 | 3/4<br>3/4<br>3/4 | CC-70183<br>CC-70183 | CK-T218<br>CK-T217<br>CK-T212 |
| | | アンチスキッド車 | 90.3-94.9<br>94.9-95.12 | 7/8<br>7/8 | | TK-T320<br>TK-T425 | 90.3-95.12 | 51.1 | DISC | MP-15 | CPM-15 | 90.3-95.12 | 30.2 | DISC | MP-23 | | 90.3-94.5<br><br><br><br>94.5-95.12 | (R)BH-T660<br>(L)BH-T661<br><br><br><br>(R)BH-T660<br>(L)BH-T661 | (R-1)BH-T956<br>(L-1)BH-T956<br>(R-2)BH-T558<br>(L-2)BH-T558<br>(R-1)BH-T956<br>(L-1)BH-T956<br>(R-2)BH-T558<br>(L-2)BH-T558 | 90.3-92.2<br>92.2-94.3<br>94.3-95.12 | 5/8<br>5/8<br>5/8 | | MK-T236<br><br>MK-T244 | 90.3-93.1<br>93.1-94.8<br>94.8-95.12 | 3/4<br>3/4<br>3/4 | CC-70183<br>CC-70183 | CK-T218<br>CK-T217<br>CK-T212 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| VITZ : 10 ser.(99.1-) | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | <AT> | | | | | | | | | | | | | | | | | | | | | | | | |
| (1000) | GF－SCP10 | | 99.1-99.8 | 13/16 | | TK-T430 | 99.1-05.1 | | DISC | MP-90 | CPM-90 | 99.1-99.8 | 11/16 | (R)WC-T775 | WK-935 | CUP | 99.1-99.8 | (R)BH-T810 | (R) | 99.1-01.9 | 5/8 | | MK-T244 | 99.1-05.1 | 13/16 | | CK-T201 |
| | ＜GH－は99. 8～＞ | | 99.8-01.1 | 13/16 | | TK-T430 | | | | | | | | (L)WC-T776 | | | | (L)BH-T811 | (L) | 01.9-05.1 | 5/8 | MC-T466 | MK-T244 | | | | |
| | ＜TA－は00. 8～＞ | | <MT> | | | | | | | | | 99.8-05.1 | 11/16 | (R)WC-T777 | WK-935 | CUP | 99.8- | (R)BH-T778 | (R)BH-T941 | | | | | | | | |
| | ＜UA－は01. 12～＞ | | 99.1-99.8 | 13/16 | | TK-T430 | | | | | | | | (L)WC-T778 | | | | (L)BH-T779 | (L)BH-T941 | | | | | | | | |
| | | | 99.8-01.1 | 13/16 | | TK-T430 | | | | | | | | | | | | | | | | | | | | | |
| | | | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | 99.1-02.8 | 13/16 | | TK-T429 | | | | | | | | | | | | | | | | | | | | | |
| | | | 02.8-05.1 | | | | | | | | | | | | | | | | | | | | | | | | |
| (1300) | GH･UA－NCP10 | 除くRS | 99.9-02.8 | 13/16 | | TK-T429 | 99.9-05.1 | | DISC | MP-90 | CPM-90 | 99.9-05.1 | 11/16 | (R)WC-T777 | WK-935 | CUP | 99.9- | (R)BH-T778 | (R)BH-T941 | 99.9-05.1 | 5/8 | MC-T472 | MK-T244 | 99.9-04.6 | 3/4 | CC-T392 | CK-T212 |
| | UA－SCP13 | | 02.8-05.1 | | | | | | | | | | | (L)WC-T778 | | | | (L)BH-T779 | (L)BH-T941 | | | | | 04.7-05.1 | 3/4 | CC-T392 | CK-T233 |
| | ＜TA－は00. 8～＞ | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | ＜UA－は02. 8～＞ | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | RS | 00.10-02.8 | 13/16 | | TK-T429 | 00.10-05.1 | | DISC | MP-90 | CPM-90 | 00.10-05.1 | | DISC | SP-222 | CPS-222 | 00.10- | (R)BH-T778 | (R) | 00.10-05.1 | 5/8 | MC-T472 | MK-T244 | 00.10-04.6 | 3/4 | CC-T392 | CK-T212 |
| | | | 02.8-05.1 | | | | | | | | | | | | | | | (L)BH-T779 | (L) | | | | | 04.7-05.1 | 3/4 | CC-T392 | CK-T233 |
| | GH－NCP15(4WD) | | 99.8-02.8 | 13/16 | | TK-T429 | 99.8-05.1 | | DISC | MP-90 | CPM-90 | 99.8-05.1 | 11/16 | (R)WC-T777 | WK-935 | CUP | 99.8- | (R)BH-T780 | (R)BH-T782 | 99.9-05.1 | 5/8 | MC-T472 | MK-T244 | 99.8-04.6 | 3/4 | CC-T392 | CK-T212 |
| | ＜TA－は00. 8～＞ | | 02.8-05.1 | | | | | | | | | | | (L)WC-T778 | | | | (L)BH-T781 | (L)BH-T783 | | | | | 04.7-05.1 | 3/4 | CC-T392 | CK-T233 |
| | ＜UA－は02. 8～＞ | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1500) | TA－NCP13 | RS | 00.10-02.8 | 13/16 | | TK-T429 | 00.10-05.1 | | DISC | MP-90 | CPM-90 | 00.10-05.1 | | DISC | SP-222 | CPS-222 | 00.10- | (R)BH-T778 | (R) | 00.10-05.1 | 5/8 | MC-T472 | MK-T244 | 00.10-04.6 | 3/4 | CC-T392 | CK-T212 |
| | ＜UA－は02. 8～＞ | | 02.8-05.1 | | | | | | | | | | | | | | | (L)BH-T779 | (L) | | | | | 04.7-05.1 | 3/4 | CC-T392 | CK-T233 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| VITZ : 90 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1000) | DBA－KSP90 | | 05.1-10.12 | 13/16 | TD-T914 | ｷｯﾄｾｯﾃｲﾅｼ | 05.1-10.12 | 54 | DISC | MP-110 | | 05.1-10.12 | | (R)WC-T780<br>(L)WC-T781 | WK-542 | CUP | 05.1-10.12 | (R)<br>(L) | (R)BH-T716<br>(L)BH-T957 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (1300) | DBA－SCP90 | | 05.1-10.12 | 13/16 | TD-T914 | ｷｯﾄｾｯﾃｲﾅｼ | 05.1-10.12 | 54 | DISC | MP-110 | | 05.1-10.12 | | (R)WC-T780<br>(L)WC-T781 | WK-542 | CUP | 05.1-10.12 | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | DBA－NCP95 4WD | | 05.1-10.12 | 13/16 | TD-T914 | ｷｯﾄｾｯﾃｲﾅｼ | 05.1-10.12 | 54 | DISC | MP-110 | | 05.1-10.12 | | (R)WC-T780<br>(L)WC-T781 | WK-542 | CUP | 05.1-10.12 | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (1500) | DBA－NCP91 | | 05.1-10.12<br><RS CVT><br>05.1-10.12<br><RS 5MT><br>05.1-10.12 | 13/16<br><br><br><br>7/8 | TD-T914<br><br><br><br>TD-T930 | ｷｯﾄｾｯﾃｲﾅｼ<br><br>ｷｯﾄｾｯﾃｲﾅｼ<br><br>ｷｯﾄｾｯﾃｲﾅｼ | 05.1-10.12<br><RS><br>05.1-10.12 | 54 | DISC<br><br>DISC | MP-110<br><br>MP-111 | | 05.1-10.12<br><br><RS><br>05.1-06.12<br>06.12-07.8<br>07.8-10.12 | | (R)WC-T780<br>(L)WC-T781<br><br>MD-356M<br>MD-356M<br>MD-356M | WK-542<br><br><br>TP-97A<br>TP-111<br>TP-112 | CUP | 05.1-10.12 | (R)<br>(L) | (R)BH-T716<br>(L)BH-T957 | 05.1-10.12 | 5/8 | MC-T487 | ｷｯﾄﾅｼ | 05.1-10.12 | 13/16 | CC-T399 | CK-T232 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| VITZ : 130 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1000) | DBA－KSP130 | | 10.12-12.5<br>12.5-14.4<br>14.4- | 3/4<br>13/16 | TD-T937<br>TD-T939 | ｷｯﾄｾｯﾃｲﾅｼ<br>ｷｯﾄｾｯﾃｲﾅｼ | 10.12-12.5<br>12.5-15.3<br>15.4- | 54 | DISC<br>DISC<br>DISC | MP-123<br>MP-110<br>MP-136 | | 10.12-12.5<br><br>12.5- | | (R)WC-T777<br>(L)WC-T778<br>(R)WC-T780<br>(L)WC-T781 | WK-935<br><br>WK-542 | CUP<br><br>CUP | 10.12-11.11<br><br>11.11-14.4<br><br>14.4- | (R)<br>(L)<br>(R)<br>(L)<br>(R)<br>(L) | (R)BH-T716<br>(L)BH-T957<br>(R)BH-T716<br>(L)BH-T957<br>(R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | |
| (1300) | DBA－NSP130 | <ﾉﾝﾋﾞｸ VSC付><br>10.12-12.5<br>12.5-14.4<br>14.4-<br><VSC付><br>10.12-12.5<br>12.5- | 3/4<br>13/16<br><br><br>3/4 | TD-T937<br>TD-T939<br><br><br>TD-T938 | ｷｯﾄｾｯﾃｲﾅｼ<br>ｷｯﾄｾｯﾃｲﾅｼ<br><br><br>ｷｯﾄｾｯﾃｲﾅｼ | 10.12-12.5<br>12.5-15.3<br>15.4- | 54 | DISC<br>DISC<br>DISC | MP-123<br>MP-110<br>MP-136 | | 10.12-12.5<br><br>12.5- | | (R)WC-T777<br>(L)WC-T778<br>(R)WC-T780<br>(L)WC-T781 | WK-935<br><br>WK-542 | CUP<br><br>CUP | 10.12-11.11<br><br>11.11-14.4<br><br>14.4- | (R)<br>(L)<br>(R)<br>(L)<br>(R)<br>(L) | (R)BH-T716<br>(L)BH-T957<br>(R)BH-T716<br>(L)BH-T957<br>(R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | |
| | DBA－NCP131 除くGRMN | | 10.12-14.4<br>14.4- | 13/16 | TD-T939 | ｷｯﾄｾｯﾃｲﾅｼ | 10.12-15.3<br>15.4- | 54 | DISC<br>DISC | MP-110<br>MP-136 | | 10.12- | | (R)WC-T780<br>(L)WC-T781 | WK-542 | CUP | 10.12-11.11<br><br>11.11-14.4<br><br>14.4- | (R)<br>(L)<br>(R)<br>(L)<br>(R)<br>(L) | (R)BH-T716<br>(L)BH-T957<br>(R)BH-T716<br>(L)BH-T957<br>(R)<br>(L) | 10.12- | 5/8 | MC-T485 | ｷｯﾄｾｯﾃｲﾅｼ | 10.12- | 13/16 | CC-T399 | CK-T232 |
| | RS | <ﾉﾝﾋﾞｸ VSC付><br>10.12-12.3<br>12.4-14.4<br>14.4-<br><VSC付><br>10.12-12.3<br>12.4- | <br>7/8<br>7/8<br><br><br>7/8 | <br>TD-T935<br>TD-T936<br><br><br>TD-T936 | | 10.12- | | DISC | MP-111 | | 10.12- | | DISC | TP-112 | | 10.12-14.4<br><br><br><br>14.4- | (R)<br>(L)<br><br><br><br>(R)<br>(L) | (R-1)BH-T716<br>(L-1)BH-T957<br>(R-2)<br>(L-2)<br>(R-1)<br>(L-1)<br>(R-2)<br>(L-2) | | | (ｵｰﾄﾏﾁｯｸ) | | | | |
| | GRMN | | 13.9-14.2 | | | | 13.9-14.2 | 40.45 | DISC | SP-109 | | 13.9-14.2 | | DISC | TP-112 | | 13.9-14.2 | (R)<br>(L) | (R-1)BH-T716<br>(L-1)BH-T957<br>(R-2)<br>(L-2) | 13.9-14.2 | 5/8 | MC-T485 | ｷｯﾄｾｯﾃｲﾅｼ | | | | CK-T212 |
| | DBA－NSP135 | | 10.12-14.4<br>14.4- | 13/16 | TD-T939 | ｷｯﾄｾｯﾃｲﾅｼ<br>ｷｯﾄｾｯﾃｲﾅｼ | 10.12-15.4<br>15.4- | 54 | DISC<br>DISC | MP-110<br>MP-136 | | 10.12- | 3/4 | (R)WC-T780<br>(L)WC-T781 | WK-542 | CUP | 10.12-11.11<br><br>11.11-14.4<br><br>14.4-15.4<br><br>15.4- | (R)<br>(L)<br>(R)<br>(L)<br>(R)<br>(L)<br>(R)<br>(L) | (R)<br>(L)<br>(R)<br>(L)<br>(R)<br>(L)<br>(R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | |
| (1500) | DAA－NHP130 ハイブリッド | | 17.1- | | | | 17.1-17.6<br>17.6- | 54 | DISC<br>DISC | MP-110<br>MP-136 | | 17.1- | | (R)WC-T787<br>(L)WC-T787 | | | 17.1- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| YARIS, YARIS CROSS, GR YARISU : 10 ser., 200 ser.(2020.2-) | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1000) | 5BA-KSP210 | | 20.2- | | | キットセッテイナシ | 20.2- | | DISC | MP-136 | | 20.2- | | (R)WC-T780<br>(L)WC-T781 | WK-542 | CUP | 20.2- | (R)<br>(L) | (R)<br>(L) | | | | | | | | |
| (1500) | 5BA-MXPA10 | CVT車 | 20.2- | 7/8 | TD-T942 | キットセッテイナシ | 20.2- | | DISC | MP-136 | | 20.2- | | (R)WC-T780<br>(L)WC-T781 | WK-542 | CUP | 20.2- | (R)<br>(L) | (R)<br>(L) | | | | | | | | |
| | | MT車 | 20.2- | 7/8 | TD-T943 | キットセッテイナシ | 20.2- | | DISC | MP-136 | | 20.2- | | (R)WC-T780<br>(L)WC-T781 | WK-542 | CUP | 20.2- | (R)<br>(L) | (R)<br>(L) | 20.2- | | | キットセッテイナシ | | | | |
| | 5BA-MXPB10 | | 20.8- | 7/8 | TD-T942 | キットセッテイナシ | 20.8- | | DISC | | | 20.8-22.11<br>22.11- | | DISC | SP-502 | | 20.8- | (R)<br>(L) | (R)<br>(L) | | | | | | | | |
| | 5BA-MXPA12 | | 20.8- | 7/8 | TD-T942 | キットセッテイナシ | 20.8- | | DISC | | | 20.8- | | DISC | SP-502 | | 20.8- | (R)<br>(L) | (R)<br>(L) | | | | | | | | |
| | 5BA-MXPA15 | | 20.2- | 7/8 | TD-T942 | キットセッテイナシ | 20.2- | | DISC | MP-136 | | 20.2- | | (R)WC-T780<br>(L)WC-T781 | WK-542 | CUP | 20.2- | (R)<br>(L) | (R)<br>(L) | | | | | | | | |
| | 5BA-MXPB15 | | 20.8- | 7/8 | TD-T942 | キットセッテイナシ | 20.8- | | DISC | | | 20.8-22.11<br>22.11- | | DISC<br>DISC | SP-502 | | 20.8- | (R)<br>(L) | (R)<br>(L) | | | | | | | | |
| | 6AA-MXPH10 | | 20.2- | | | キットセッテイナシ | 20.2- | | DISC | MP-136 | | 20.2- | | (R)WC-T780<br>(L)WC-T781 | WK-542 | CUP | 20.2- | (R)<br>(L) | (R)<br>(L) | | | | | | | | |
| | 6AA-MXPJ10 | ハイブリッド | 20.8- | | | キットセッテイナシ | 20.8- | | DISC | | | 20.8-22.11<br>22.11- | | DISC<br>DISC | SP-502 | | 20.8- | (R)<br>(L) | (R)<br>(L) | | | | | | | | |
| | 6AA-MXPH15 | | 20.2- | | | キットセッテイナシ | 20.2- | | DISC | MP-136 | | 20.2- | | (R)WC-T797<br>(L)WC-T798 | WK-999 | CUP | 20.2- | (R)<br>(L) | (R)<br>(L) | | | | | | | | |
| | 6AA-MXPJ15 | ハイブリッド | 20.8- | | | キットセッテイナシ | 20.8- | | DISC | | | 20.8-22.11<br>22.11- | | DISC<br>DISC | SP-502 | | 20.8- | (R)<br>(L) | (R)<br>(L) | | | | | | | | |
| (1600) | 4BA-GXPA16 | RZ | 20.8- | 7/8 | TD-T943 | キットセッテイナシ | 20.8- | | DISC | | | 20.8- | | DISC | | | 20.8- | (R)<br>(L) | (R)<br>(L) | | | | | | | | |
| | | RC<br>除く18インチパッケージ | 20.8- | 7/8 | TD-T943 | キットセッテイナシ | 20.8- | | DISC | | | 20.8- | | DISC | | | 20.8- | (R)<br>(L) | (R)<br>(L) | | | | | | | | |
| | | RC<br>18インチパッケージ | 20.8- | 7/8 | TD-T943 | キットセッテイナシ | 20.8- | | DISC | | | 20.8- | | DISC | | | 20.8- | (R)<br>(L) | (R)<br>(L) | | | | | | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| PLATZ : 10 ser.(99.8-) | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1000) GH－SCP11<br>＜TA－は00. 8～＞<br>＜UA－は01. 12～＞ | <AT><br>99.8-01.1<br><MT><br>99.8-01.1<br><br><ｱﾝﾁｽｷｯﾄﾞ付><br><AT><br>99.8-02.8<br>02.8-<br><MT><br>99.8-02.8<br>02.8- | 13/16<br>13/16<br>13/16 | TD-T923 | TK-T430<br>TK-T430 | 99.8- | | DISC | MP-90 | CPM-90 | 99.8- | 11/16 | (R)WC-T777<br>(L)WC-T778 | WK-935 | CUP | 99.8-03.8<br>03.8- | (R)BH-T771<br>(L)BH-T772<br>(R)BH-T778<br>(L)BH-T779 | (R)BH-T941<br>(L)BH-T941<br>(R)BH-T941<br>(L)BH-T941 | 99.8- | 5/8 | | MK-T244 | 99.8- | 13/16 | | CK-T201 |
| (1300) GH－NCP16(4WD)<br>＜TA－は00. 8～＞<br>＜UA－は02. 8～＞ | 99.8-02.8<br>02.8- | | | | 99.8- | | DISC | MP-90 | CPM-90 | 99.8- | 11/16 | (R)WC-T777<br>(L)WC-T778 | WK-935 | CUP | 99.8- | (R)BH-T780<br>(L)BH-T781 | (R)BH-T782<br>(L)BH-T783 | 99.8- | 5/8 | MC-T472 | MK-T244 | 99.8- | 3/4 | CC-T392 | CK-T212 |
| (1500) GH－NCP12<br>＜TA－は00. 8～＞<br>＜UA－は02. 8～＞ | 99.8-02.8<br>02.8- | | | | 99.8- | | DISC | MP-90 | CPM-90 | 99.8- | 11/16 | (R)WC-T777<br>(L)WC-T778 | WK-935 | CUP | 99.8-03.8<br>03.8- | (R)BH-T771<br>(L)BH-T772<br>(R)BH-T778<br>(L)BH-T779 | (R)BH-T941<br>(L)BH-T941<br>(R)BH-T941<br>(L)BH-T941 | 99.8- | 5/8 | MC-T472 | MK-T244 | 99.8- | 3/4 | CC-T392 | CK-T212 |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| FUN CARGO : 20 ser.(99.8-) | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1300) GH－NCP20 | 99.8- | | | | 99.8-04.11 | | DISC | MP-90 | CPM-90 | 99.8-99.12 | 3/4 | (R)WC-T780 | WK-542 | CUP | 99.8-03.8 | (R)BH-T771 | (R)BH-T941 | | | (オートマチック) | | | | | |
| ＜TA－は00．8～＞ | | | | | 04.11- | | DISC | MP-90 | CPM-90 | | | (L)WC-T781 | | | | (L)BH-T772 | (L)BH-T941 | | | | | | | | |
| ＜UA－は02．8～＞ | | | | | | | | | | 99.12- | 11/16 | (R)WC-T777 | WK-935 | CUP | 03.8- | (R)BH-T778 | (R)BH-T941 | | | | | | | | |
| | | | | | | | | | | | | (L)WC-T778 | | | | (L)BH-T779 | (L)BH-T941 | | | | | | | | |
| (1500) GH－NCP21 | 99.8- | | | | 99.8-04.11 | | DISC | MP-90 | CPM-90 | 99.8-99.12 | 3/4 | (R)WC-T780 | WK-542 | CUP | 99.8-03.8 | (R)BH-T771 | (R)BH-T941 | | | (オートマチック) | | | | | |
| ＜TA－は00．8～＞ | | | | | 04.11- | | DISC | MP-90 | CPM-90 | | | (L)WC-T781 | | | | (L)BH-T772 | (L)BH-T941 | | | | | | | | |
| ＜UA－は02．8～＞ | | | | | | | | | | 99.12- | 11/16 | (R)WC-T777 | WK-935 | CUP | 03.8- | (R)BH-T778 | (R)BH-T941 | | | | | | | | |
| | | | | | | | | | | | | (L)WC-T778 | | | | (L)BH-T779 | (L)BH-T941 | | | | | | | | |
| GH－NCP25(4WD) | 99.8- | | | | 99.8-04.11 | | DISC | MP-90 | CPM-90 | 99.8-99.12 | 3/4 | (R)WC-T780 | WK-542 | CUP | 99.8- | (R)BH-T781 | (R)BH-T782 | | | (オートマチック) | | | | | |
| ＜TA－は00．8～＞ | | | | | 04.11- | | DISC | MP-90 | CPM-90 | | | (L)WC-T781 | | | | (L)BH-T781 | (L)BH-T783 | | | | | | | | |
| ＜UA－は02．8～＞ | | | | | | | | | | 99.12- | 11/16 | (R)WC-T777 | WK-935 | CUP | | | | | | | | | | | |
| | | | | | | | | | | | | (L)WC-T778 | | | | | | | | | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| IST : 60 ser., 110 ser.(02.4-) | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1300) | UA－NCP60<br>＜CBA-は04．2～＞<br>＜DBA-は05．5～＞ | 02.4-03.5<br>03.5- | 13/16 | | | 02.4- | | DISC | MP-90 | CPM-90 | 02.4- | 11/16 | (R)WC-T777<br>(L)WC-T778 | WK-935 | CUP | 02.4-03.8<br><br>03.8- | (R)BH-T771<br>(L)BH-T772<br>(R)BH-T778<br>(L)BH-T779 | (R)BH-T941<br>(L)BH-T941<br>(R)BH-T941<br>(L)BH-T941 | | | (オートマチック) | | | | | |
| (1500) | UA－NCP61<br>＜CBA-は04．2～＞ | 02.4-03.5<br>03.5-<br><VSC付><br>03.4- | 13/16 | | | 02.4- | | DISC | MP-90 | CPM-90 | 02.4- | | DISC | SP-222 | CPS-222 | 02.4-03.8<br><br>03.8- | (R)BH-T771<br>(L)BH-T772<br>(R)BH-T778<br>(L)BH-T779 | (R)<br>(L)<br>(R)<br>(L) | | | (オートマチック) | | | | | |
| | UA－NCP65 4WD<br>＜CBA-は04．2～＞ | 02.4-03.5<br>03.5- | 13/16 | | | 02.4- | | DISC | MP-90 | CPM-90 | 02.4- | 11/16 | (R)WC-T777<br>(L)WC-T778 | WK-935 | CUP | 02.4- | (R)BH-T780<br>(L)BH-T781 | (R)BH-T782<br>(L)BH-T782 | | | (オートマチック) | | | | | |
| (1500) | DBA－NCP110 | 07.7- | | | | 07.7- | | DISC | MP-116 | CPM-116 | 07.7- | | (R)WC-T787<br>(L)WC-T787 | WK-900 | CUP | 07.7- | | | | | (オートマチック) | | | | | |
| | DBA－NCP115 4WD | 07.7- | | | | 07.7- | | DISC | MP-116 | CPM-116 | 07.7- | | DISC | TP-111 | | 07.7- | | | | | (オートマチック) | | | | | |
| (1800) | DBA－ZSP110 | 07.7- | | | | 07.7- | | DISC | MP-116 | CPM-116 | 07.7- | | (R)WC-T787<br>(L)WC-T787 | WK-900 | CUP | 07.7- | | | | | (オートマチック) | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| bB : 30 ser.(00.1-05.12) | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1300) | GH－NCP30<br>＜TA－は00．8～＞<br>＜UA－は02．8～＞ | 00.1-03.8<br>03.8-05.12 | | | キットセッテイナシ<br>キットセッテイナシ | 00.1-04.11<br>04.11-05.12 | | DISC<br>DISC | MP-90<br>MP-90 | CPM-90<br>CPM-90 | 00.1-05.12 | 11/16 | (R)WC-T777<br>(L)WC-T778 | WK-935 | CUP | 00.1-03.8<br><br>03.8-05.12 | (R)BH-T771<br>(L)BH-T772<br>(R)BH-T778<br>(L)BH-T779 | (R)BH-T941<br>(L)BH-T941<br>(R)BH-T941<br>(L)BH-T941 | | | (ｵｰﾄﾏﾁｯｸ) | | | | |
| (1500) | GH－NCP31<br>＜TA－は00．8～＞<br>＜UA－は02．8～＞<br>＜CBA－は04．2～＞ | 00.1-03.8<br>03.8-05.12 | | | キットセッテイナシ<br>キットセッテイナシ | ＜VSC無＞<br>00.1-05.1<br>05.1-05.12<br>＜VSC付＞<br>03.5-04.9<br>04.9-05.12 | | DISC<br>DISC<br><br>DISC<br>DISC | MP-90<br>MP-90<br><br>MP-95<br>MP-95 | CPM-90<br>CPM-90<br><br>CPM-95<br>CPM-95 | 00.1-05.12 | 11/16 | (R)WC-T777<br>(L)WC-T778 | WK-935 | CUP | 00.1-03.8<br><br>03.8-05.12 | (R)BH-T771<br>(L)BH-T772<br>(R)BH-T778<br>(L)BH-T779 | (R)BH-T941<br>(L)BH-T941<br>(R)BH-T941<br>(L)BH-T941 | | | (ｵｰﾄﾏﾁｯｸ) | | | | |
| | GH－NCP34<br>＜TA－は00．8～＞<br>＜UA－は02．8～＞ | 00.1-03.8<br>03.8-05.12 | | | キットセッテイナシ<br>キットセッテイナシ | 00.1-05.1<br>05.1-05.12 | | DISC<br>DISC | MP-90<br>MP-90 | CPM-90<br>CPM-90 | 00.1-05.12 | 11/16 | (R)WC-T777<br>(L)WC-T778 | WK-935 | CUP | 00.1-03.8<br><br>03.8-05.12 | (R)BH-T771<br>(L)BH-T772<br>(R)BH-T778<br>(L)BH-T779 | (R)BH-T941<br>(L)BH-T941<br>(R)BH-T941<br>(L)BH-T941 | | | (ｵｰﾄﾏﾁｯｸ) | | | | |
| | GH－NCP35（4WD）<br>＜TA－は00．8～＞<br>＜UA－は02．8～＞ | ＜VSCﾂｷ＞<br>00.1-05.12<br>＜VSCﾅｼ＞<br>00.1-03.8<br>03.8-05.12 | | | <br><br><br>キットセッテイナシ<br>キットセッテイナシ | 00.1-04.11<br>04.11-05.12 | | DISC<br>DISC | MP-90<br>MP-90 | CPM-90<br>CPM-90 | 00.1-05.12 | 11/16 | (R)WC-T777<br>(L)WC-T778 | WK-935 | CUP | 00.1-05.12 | (R)BH-T780<br>(L)BH-T781 | (R)BH-T782<br>(L)BH-T783 | | | (ｵｰﾄﾏﾁｯｸ) | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| bB : 20 ser.(05.12-16.7) | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1300) | DBA－QNC20 | 05.12-16.7 | | | | 05.12-16.7 | | DISC | TP-127 | CPT-80 | 05.12-16.7 | 11/16 | (R)WC-T777<br>(L)WC-T778 | WK-935 | CUP | 05.12-16.7 | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| | DBA－QNC25(4WD) | 05.12-16.7 | | | | 05.12-16.7 | | DISC | TP-127 | CPT-80 | 05.12-16.7 | 11/16 | (R)WC-D290<br>(L)WC-D290 | WK-699-01 | CUP | 05.12-16.7 | (R)<br>(L) | (R)BH-D233<br>(L)BH-D233 | | | (オートマチック) | | | | | |
| (1500) | DBA－QNC21 | 05.12-16.7 | | | | 05.12-16.7 | | DISC | TP-127 | CPT-80 | 05.12-16.7 | 11/16 | (R)WC-T777<br>(L)WC-T778 | WK-935 | CUP | 05.12-16.7 | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| SPRINTER CARIB : AL25 ser. | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1500) E－AL25G(ワゴン) | 82.8-88.1 | 13/16 | | TK-9422 | 82.8-88.1 | 48.1 | DISC | MP-7 | | 82.8-88.1 | 3/4 | (R)WC-50055<br>(L)WC-50055 | WK-542 | CUP | 82.8-88.1 | BH-02437 | (R)BH-31305<br>(L)BH-95005 | | | (ワイヤー式) | | | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| SPRINTER CARIB : AE95 ser. | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1600) E－AE95G(ワゴン) | 88.2-89.8 | 13/16 | | TK-T023 | 88.2-93.8 | 51.1 | DISC | MP-15 | CPM-15 | 88.2-95.8 | 3/4 | (R)WC-50055 | WK-542 | CUP | 88.2-95.8 | BH-02532 | (R)BH-02558 | 88.2-88.6 | 5/8 | MC-T400 | MK-4337 | 88.2-88.5 | 13/16 | CC-70183 | CK-3144 |
| | 89.8-93.8 | 7/8 | | TK-T032 | 93.8-95.8 | 54.0 | DISC | MP-19 | | | | (L)WC-50055 | | | | | (L)BH-02558 | 88.6-89.8 | 5/8 | MC-T378 | MK-4342 | 88.5-93.1 | 13/16 | CC-70183 | CK-3144 |
| | 93.8-95.8 | 13/16 | | TK-T307 | | | | | | | | | | | | | | 89.8-90.4 | 5/8 | MC-T378 | MK-T236 | 93.1-95.8 | 13/16 | CC-70183 | CK-T201 |
| | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | | | | | | | 90.4-94.2 | 5/8 | MC-T378 | | | | | |
| | 90.9-95.8 | 15/16 | | TK-T300 | | | | | | | | | | | | | | 94.2-95.8 | 5/8 | | MK-T244 | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| SPRINTER CARIB : 110 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1600) | E−AE111G<br><GF−は98．4〜> | Sツーリング・Zツーリング<br>ロッソ | 96.5-02.7 | 13/16 | | TK-T357 | 96.5-02.7 | 51.1 | DISC | MP-15 | CPM-15 | 96.5-02.7 | 11/16 | (R)WC-T599<br>(L)WC-T617 | WK-569 | CUP | 96.5-97.4<br><br>97.4-02.7 | (R)BH-T543<br>(L)BH-T544<br>(R)BH-T543<br>(L)BH-T544 | (R)BH-T648<br>(L)BH-T648<br>(R)BH-T698<br>(L)BH-T698 | 96.5-97.4<br>97.4-02.7 | 5/8<br>5/8 | MC-T350 | MK-T244<br>MK-T244 | 96.5-02.7 | 13/16 | CC-70183 | CK-T201 |
| | | BZツーリング | 96.5-02.7 | 7/8 | | TK-T360 | 96.5-02.7 | 54.0 | DISC | MP-19 | | 96.5-02.7 | | DISC | A-464P | | 96.5-97.4<br><br>97.4-99.10<br><br>99.10-02.7 | (R)BH-T543<br>(L)BH-T544<br>(R)BH-T543<br>(L)BH-T544<br>(R)BH-T543<br>(L)BH-T544 | (R)BH-T580<br>(L)BH-T580<br>(R)BH-T699<br>(L)BH-T699<br>(R)<br>(L) | 96.5-02.7 | 5/8 | | MK-T244 | 96.5-02.7 | 13/16 | CC-70183 | CK-T201 |
| | E−AE114G(4WD)<br><GF−は98．4〜> | | 95.8-96.5<br><ｱﾝﾁｽｷｯﾄﾞ付><br>95.8-96.5<br>96.5-02.7 | 7/8<br><br>7/8<br>7/8 | | TK-T360<br><br>TK-T359<br>TK-T360 | 95.8-02.7 | 54.0 | DISC | MP-19 | | 95.8-02.7 | 3/4 | (R)WC-T600<br>(L)WC-T605 | WK-542 | CUP | 96.5-02.7 | (R)BH-T551<br>(L)BH-T552 | (R)BH-T545<br>(L)BH-T545 | 95.8-02.7 | 5/8 | | MK-T244 | 95.8-02.7 | 13/16 | CC-70183 | CK-T201 |
| (1800) | E−AE115G(4WD)<br><GF−は98．4〜> | | 95.8-96.5<br><ｱﾝﾁｽｷｯﾄﾞ付><br>95.8-96.5<br>96.5-02.7 | 7/8<br><br>7/8<br>7/8 | | TK-T360<br><br>TK-T359<br>TK-T360 | 95.8-02.7 | 54.0 | DISC | MP-19 | | 95.8-02.7 | 3/4 | (R)WC-T600<br>(L)WC-T605 | WK-542 | CUP | 96.5-02.7 | (R)BH-T551<br>(L)BH-T552 | (R)BH-T545<br>(L)BH-T545 | 95.8-02.7 | 5/8 | | MK-T244 | 95.8-02.7 | 13/16 | CC-70183 | CK-T201 |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| VOLTS : 130 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) | UA－ZZE136 | 02.8-04.2 | | | | 02.8-04.2 | | DISC | | | 02.8-04.2 | 3/4 | (R)WC-T785<br>(L)WC-T785 | WK-899 | CUP | 02.8-04.2 | (R)BH-T946<br>(L)BH-T947 | (R)BH-T948<br>(L)BH-T948 | | | (オートマチック) | | | | | |
| | TA－ZZE137 | 02.8-04.2 | | | | 02.8-04.2 | | DISC | | | 02.8-04.2 | | DISC | SP-106 | CPS-106 | 02.8-04.2 | (R)BH-T946<br>(L)BH-T947 | (R)BH-T949<br>(L)BH-T949 | 02.8-04.2 | 5/8 | MC-T480 | MK-T244 | 02.8-04.2 | 13/16 | CC-T381 | CK-T230 |
| | UA－ZZE138(4WD) | 02.8-04.2 | | | | 02.8-04.2 | | DISC | | | 02.8-04.2 | 3/4 | (R)WC-T785<br>(L)WC-T785 | WK-899 | CUP | 02.8-04.2 | (R)BH-T946<br>(L)BH-T947 | (R)BH-T846<br>(L)BH-T846 | | | (オートマチック) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| WISH : 10 ser.(03.1-) | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) | UA-ZNE10G | リヤードラム車 | 03.1-09.3 | 7/8 | | | 03.1-09.3 | | DISC | MP-106 | CPM-106 | 03.1-09.3 | 13/16 | (R)WC-T787<br>(L)WC-T787 | WK-900 | CUP | 03.1-06.11<br><br>06.11-09.3 | (R)<br>(L)<br>(R)<br>(L) | (R)BH-T948<br>(L)BH-T948<br>(R)<br>(L) | | | (オートマチック) | | | | | |
| | | 四輪ディスク車 | 03.1-09.3 | 7/8 | | | 03.1-09.3 | | DISC | MP-106 | CPM-106 | 03.1-09.3 | | DISC | MP-100 | | 03.1-09.3 | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| | UA-ZNE14G(4WD) | | 03.1-09.3 | 7/8 | | | 03.1-09.3 | | DISC | MP-106 | CPM-106 | 03.1-09.3 | | DISC | MP-100 | | 03.1-09.3 | (R)<br>(L) | (R)BH-T836<br>(L)BH-T836 | | | (オートマチック) | | | | | |
| (2000) | UA-ANE10G | | 03.4-09.3 | 7/8 | | | 03.4-09.3 | | DISC | MP-106 | CPM-106 | 03.4-09.3 | | DISC | MP-100 | | 03.4-09.3 | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| | UA-ANE11W | | 03.4-09.3 | | | | 03.4-09.3 | | DISC | MP-106 | CPM-106 | 03.4-09.3 | | DISC | MP-100 | | 03.4-09.3 | (R)<br>(L) | (R)BH-T836<br>(L)BH-T836 | | | (オートマチック) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| WISH : 20 ser.(09.3-) | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) | DBA－ZGE20G<br>DBA－ZGE20W | リヤードラム車 | 09.3- | | | | 09.3- | | DISC | MP-114 | CPM-106 | 09.3- | 7/8 | (R)WC-T796<br>(L)WC-T796 | WK-1051 | CUP | 09.3- | | | 09.3- | | (オートマチック) | | | | | |
| | | 四輪ディスク車 | 09.3- | | | | 09.3- | | DISC | MP-114 | CPM-106 | 要確認<br><ピン径Φ17.5><br>09.3-<br><ピン径Φ21.6><br>09.3- | <br><br><br>38.1 | DISC<br><br><br>DISC | MP-100<br><br><br>SP-420 | | 09.3- | | | 09.3- | | (オートマチック) | | | | | |
| | DBA－ZGE25G<br>DBA－ZGE25W | | 09.3- | | | | 09.3- | | DISC | MP-114 | CPM-106 | 要確認<br><ピン径Φ17.5><br>09.3-<br><ピン径Φ21.6><br>09.3- | <br><br><br>38.1 | DISC<br><br><br>DISC | MP-100<br><br><br>SP-420 | | 09.3- | | | 09.3- | | (オートマチック) | | | | | |
| (2000) | DBA－ZGE21G | | 09.3- | | | | 09.3- | | DISC | MP-114 | CPM-106 | 要確認<br><ピン径Φ17.5><br>09.3-<br><ピン径Φ21.6><br>09.3- | <br><br><br>38.1 | DISC<br><br><br>DISC | MP-100<br><br><br>SP-420 | | 09.3- | | | 09.3- | | (オートマチック) | | | | | |
| | DBA－ZGE21W | | 09.3- | | | | 09.3- | | DISC | MP-114 | CPM-106 | 要確認<br><ピン径Φ17.5><br>09.3-<br><ピン径Φ21.6><br>09.3- | <br><br><br>38.1 | DISC<br><br><br>DISC | MP-100<br><br><br>SP-420 | | 09.3- | | | 09.3- | | (オートマチック) | | | | | |
| | DBA－ZGE22W | | 09.3- | | | | 09.3- | | DISC | MP-114 | CPM-106 | 要確認<br><ピン径Φ17.5><br>09.3-<br><ピン径Φ21.6><br>09.3- | <br><br><br>38.1 | DISC<br><br><br>DISC | MP-100<br><br><br>SP-420 | | 09.3- | | | 09.3- | | (オートマチック) | | | | | |

| Models | TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| COROLLA, SPRINTER : 20 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1200) | KE20・25 | STD・DX(ドラム車) | 70.5-73.9<br>73.9-75.11<br>73.6-74.8 | 11/16<br>11/16<br>13/16 | <br><br>*33 | MK-3048<br>TK-9328<br>TK-9314 | 70.5-75.11 | 7/8 | (R-1)WC-2036<br>(R-2)WC-1046<br>(L-1)WC-4036<br>(L-2)WC-3046 | WK-054 | CUP | 70.5-75.11 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 70.5-75.11 | | BH-31282 | | | (ワイヤー式) | | | | | |
| | | STD・DX(ディスク車)<br>HDX | 70.5-72.7<br>72.8-73.9<br>73.9-74.3<br>73.6-74.3 | 11/16<br>11/16<br>11/16<br>13/16 | <br><br><br>*33 | MK-3048<br>TK-9317<br>TK-9328<br>TK-9314 | 70.5-74.3<br>71.9-74.3 | 1 7/8<br>1 7/8 | (アケボノ型)<br>(住友電工型) | C-12<br>SP-215 | | 70.5-74.3 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 70.5-74.3 | BH-02129 | BH-31282 | | | (ワイヤー式) | | | | | |
| | | SL | 70.5-72.4<br>72.4-72.7<br>72.8-73.9<br>73.9-74.3<br>73.6-74.3 | 11/16<br>11/16<br>11/16<br>11/16<br>13/16 | <br><br><br><br>*33 | TK-9315<br>TK-9316<br>TK-9317<br>TK-9328<br>TK-9314 | 70.5-74.3<br>71.9-74.3 | 1 7/8<br>1 7/8 | (アケボノ型)<br>(住友電工型) | C-12<br>SP-215 | | 70.5-74.3 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 70.5-74.3 | BH-02129 | BH-31282 | | | (ワイヤー式) | | | | | |
| | | SR | 73.4-73.9<br>73.9-74.3<br>73.6-74.3 | 11/16<br>11/16<br>13/16 | <br><br>*33 | TK-9317<br>TK-9328<br>TK-9314 | 73.4-74.3<br>73.4-74.3 | 1 7/8<br>1 7/8 | (アケボノ型)<br>(住友電工型) | C-12<br>SP-215 | | 73.4-74.3 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 70.5-74.3 | BH-02129 | BH-31282 | | | (ワイヤー式) | | | | | |
| | KE26V(バン) | ドラム車 | 70.5-73.9<br>73.9-77.12<br>73.6-74.8 | 11/16<br>11/16<br>13/16 | <br><br>*33 | MK-3048<br>TK-9328<br>TK-9314 | 70.5-77.12 | 7/8 | (R-1)WC-2036<br>(R-2)WC-1046<br>(L-1)WC-4036<br>(L-2)WC-3046 | WK-054 | CUP | 70.5-73.9<br><br>73.9-77.1<br><br>77.1-77.12 | 13/16<br><br>3/4<br><br>3/4 | (R)WC-50059<br>(L)WC-50059<br>(R)WC-50060<br>(L)WC-50060<br>(R)WC-50052<br>(L)WC-50052 | WK-492<br><br>WK-491<br><br>WK-491 | CUP<br><br>CUP<br><br>CUP | 70.5-77.12 | | BH-31282 | | | (ワイヤー式) | | | | | |
| | | ディスク車 | 70.5-72.7<br>72.8-73.9<br>73.9-75.11<br>73.6-74.8 | 11/16<br>11/16<br>11/16<br>13/16 | <br><br><br>*33 | MK-3048<br>TK-9317<br>TK-9328<br>TK-9314 | 70.5-75.11<br>71.9-74.8 | 1 7/8<br>1 7/8 | (アケボノ型)<br>(住友電工型) | C-12<br>SP-215 | | 70.5-75.11 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 70.5-75.11 | BH-02129 | BH-31282 | | | (ワイヤー式) | | | | | |
| (1400) | TE20・25 | DX(ドラム車) | 71.9-73.9<br>73.9-74.3<br>72.8-74.3 | 11/16<br>11/16<br>13/16 | <br><br>*33 | MK-3048<br>TK-9328<br>TK-9314 | 71.9-73.9<br><br><br><br>73.9-74.3 | 15/16<br><br><br><br>7/8 | (R-1)WC-1066<br>(R-2)WC-2056<br>(L-1)WC-3066<br>(L-2)WC-4056<br>(R-1)WC-51000<br>(R-2)WC-52000<br>(L-1)WC-53000<br>(L-2)WC-54000 | WK-082<br><br><br><br>WK-054 | CUP<br><br><br><br>CUP | 71.9-74.3 | 11/16 | (R)WC-50041<br>(L)WC-50041 | WK-083 | CUP | 71.9-74.3 | | BH-31382 | 71.9-74.3 | 5/8 | MC-10048 | MK-4300 | 71.9-73.12<br>73.12-74.3 | 3/4<br>3/4 | CC-14011<br>CC-14012 | CK-41480<br>CK-3108 |
| | | DX・HDX(ディスク車) | 70.9-72.7<br>72.8-74.3 | 11/16<br>13/16 | <br> | MK-3048<br>TK-9314 | 70.9-74.3 | 1 7/8 | DISC | C-16 | | 70.9-74.3 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 70.9-74.3 | BH-02129 | BH-31282 | 70.9-74.3 | 5/8 | MC-10048 | MK-4300 | 70.9-73.12<br>73.12-74.3 | 3/4<br>3/4 | CC-14011<br>CC-14012 | CK-41480<br>CK-3108 |
| | | SL・SR | 70.9-72.7<br>72.8-74.3 | 3/4<br>13/16 | <br> | TK-9318<br>TK-9314 | 70.9-74.3 | 1 7/8 | DISC | C-16 | | 70.9-74.3 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 70.9-74.3 | BH-02129 | BH-31282 | 70.9-74.3 | 5/8 | MC-10048 | MK-4300 | 70.9-73.12<br>73.12-74.3 | 3/4<br>3/4 | CC-14011<br>CC-14012 | CK-41480<br>CK-3108 |
| (1600) | TE21 | | 73.4-74.3 | 13/16 | | TK-9314 | 73.4-74.3 | 1 7/8 | DISC | C-16 | | 73.4-74.3 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 73.4-74.3 | BH-02129 | BH-31282 | 73.4-74.3 | 5/8 | MC-10048 | MK-4300 | 73.4-73.12<br>73.12-74.3 | 3/4<br>3/4 | CC-14011<br>CC-14012 | CK-41480<br>CK-3108 |
| | TE27 | SL・SR | 73.4-74.3 | 13/16 | | TK-9314 | 73.4-74.3 | 1 7/8 | DISC | C-16 | | 73.4-74.3 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 73.4-74.3 | BH-02129 | BH-31282 | 73.4-74.3 | 5/8 | MC-10048 | MK-4300 | 73.4-73.12<br>73.12-74.3 | 3/4<br>3/4 | CC-14011<br>CC-14012 | CK-41480<br>CK-3108 |
| | | レビン・トレノ | 72.3-72.7<br>72.8-74.3 | 3/4<br>3/4 | | TK-9318<br>TK-9330 | 72.3-72.7<br>72.8-74.3 | 1 7/8<br>2 | DISC<br>DISC | C-16<br>A-16P | | 72.3-74.3 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 72.3-74.3 | BH-02129 | BH-31282 | 72.3-74.3 | 5/8 | MC-10048 | MK-4300 | 72.3-74.3 | 3/4 | CC-14011 | CK-41480 |
| | | レビンJ・トレノJ | 73.4-74.3 | 13/16 | | TK-9314 | 73.4-74.3 | 1 7/8 | DISC | C-16 | | 73.4-74.3 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 73.4-74.3 | BH-02129 | BH-31282 | 73.4-74.3 | 5/8 | MC-10048 | MK-4300 | 73.4-73.12<br>73.12-74.3 | 3/4<br>3/4 | CC-14011<br>CC-14012 | CK-41480<br>CK-3108 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| COROLLA, SPRINTER : 30, 40 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1200) | KE30・35<br>KE40・45 | ドラム車 | 74.4-75.11 | 11/16 | | TK-9328 | 74.4-75.11 | 7/8 | (R-1)WC-1075<br>(R-2)WC-2065<br>(L-1)WC-3075<br>(L-2)WC-4065 | WK-054 | CUP | 74.4-75.11 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 74.4-75.11 | | BH-31304 | | | (ワイヤー式) | | | | | |
| | | ディスク車 | 74.4-75.11 | 3/4 | | TK-9329 | 74.4-75.11 | 1 7/8 | DISC | SP-215 | | 74.4-75.11 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 74.4-75.11 | (1)<br>(2)BH-02224 | BH-31304 | | | (ワイヤー式) | | | | | |
| | KE36V(バン) | ドラム車 | 74.4-77.1<br>77.1-79.8 | 11/16<br>3/4 | | TK-9328<br>TK-9373 | 74.4-79.8 | 7/8 | (R-1)WC-1075<br>(R-2)WC-2065<br>(L-1)WC-3075<br>(L-2)WC-4065 | WK-054 | CUP | 74.4-77.1<br>77.1-79.8 | 3/4<br>3/4 | (R)WC-50060<br>(L)WC-50060<br>(R)WC-50052<br>(L)WC-50052 | WK-491<br>WK-491 | CUP<br>CUP | 74.4-79.8 | | BH-31304 | | | (ワイヤー式) | | | | | |
| | | ディスク車 | 74.4-77.1<br>77.1-79.8 | 3/4<br>3/4 | | TK-9329<br>TK-9373 | 74.4-79.8 | 1 7/8 | DISC | SP-215 | | 74.4-77.1<br>77.1-79.8 | 13/16<br>13/16 | (R)WC-50059<br>(L)WC-50059<br>(R)WC-50053<br>(L)WC-50053 | WK-492<br>WK-492 | CUP<br>CUP | 74.4-79.8 | (1)<br>(2)BH-02224 | BH-31304 | | | (ワイヤー式) | | | | | |
| (1400) | TE30・35 | DX(ドラム車) | 74.4-77.1 | 13/16 | | TK-9345 | 74.4-77.1 | 7/8 | (R-1)WC-51000<br>(R-2)WC-52000<br>(L-1)WC-53000<br>(L-2)WC-54000 | WK-054 | CUP | 74.4-77.1 | 11/16 | (R)WC-50041<br>(L)WC-50041 | WK-083 | CUP | 74.4-77.1 | | BH-31304 | 74.4-77.1 | 5/8 | MC-10049 | MK-4300 | 74.4-77.1 | 3/4 | CC-70102 | CK-3108 |
| | | DX(ディスク車)<br>HDX・SL | 74.4-77.1 | 13/16 | | TK-9345 | 74.4-77.1 | 2 | DISC | A-16P | | 74.4-77.1 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 74.4-77.1 | (1)<br>(2)BH-02224 | BH-31304 | 74.4-77.1 | 5/8 | MC-10049 | MK-4300 | 74.4-77.1 | 3/4 | CC-70102 | CK-3108 |
| | | スペシャル | 74.4-75.11 | 3/4 | | TK-9330 | 74.4-75.11 | 2 | DISC | A-16P | | 74.4-75.11 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 74.4-75.11 | (1)<br>(2)BH-02224 | BH-31304 | 74.4-75.11 | 5/8 | MC-10049 | MK-4300 | 74.4-75.11 | 3/4 | CC-70102 | CK-3108 |
| | TE36V(バン) | ドラム車 | 74.4-77.1<br>77.1-79.8 | 13/16<br>13/16 | | TK-9345<br>TK-9374 | 74.4-79.8 | 7/8 | (R-1)WC-51000<br>(R-2)WC-52000<br>(L-1)WC-53000<br>(L-2)WC-54000 | WK-054 | CUP | 74.4-79.8 | 11/16 | (R)WC-50041<br>(L)WC-50041 | WK-083 | CUP | 74.4-79.8 | | BH-31304 | 74.4-78.5<br>78.5-79.8 | 5/8<br>5/8 | MC-10049<br>MC-10078 | MK-4300<br>MK-4308 | 74.4-77.8<br>77.8-79.8 | 3/4<br>13/16 | CC-70102<br>CC-70110 | CK-3108<br>CK-3113 |
| | | ディスク車 | 74.4-77.1<br>77.1-79.8 | 13/16<br>13/16 | | TK-9345<br>TK-9374 | 74.4-79.8 | 2 | DISC | A-16P | | 74.4-77.1<br>77.1-79.8 | 13/16<br>13/16 | (R)WC-50059<br>(L)WC-50059<br>(R)WC-50053<br>(L)WC-50053 | WK-492<br>WK-492 | CUP<br>CUP | 74.4-79.8 | (1)<br>(2)BH-02224 | BH-31304 | 74.4-78.5<br>78.5-79.8 | 5/8<br>5/8 | MC-10049<br>MC-10078 | MK-4300<br>MK-4308 | 74.4-77.8<br>77.8-79.8 | 3/4<br>13/16 | CC-70102<br>CC-70110 | CK-3108<br>CK-3113 |
| (1400) | TE40・45 | DX・XL・ST | 74.4-77.1 | 13/16 | | TK-9345 | 74.4-77.1 | 2 | DISC | A-16P | | 74.4-77.1 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 74.4-77.1 | (1)<br>(2)BH-02224 | BH-31304 | 74.4-77.1 | 5/8 | MC-10049 | MK-4300 | 74.4-77.1 | 3/4 | CC-70102 | CK-3108 |
| | | スペシャル | 74.4-75.11 | 3/4 | | TK-9330 | 74.4-75.11 | 2 | DISC | A-16P | | 74.4-75.11 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 74.4-75.11 | (1)<br>(2)BH-02224 | BH-31304 | 74.4-75.11 | 5/8 | MC-10049 | MK-4300 | 74.4-75.11 | 3/4 | CC-70102 | CK-3108 |
| (1600) | TE31・41 | | 74.4-76.4 | 13/16 | | TK-9345 | 74.4-76.4 | 2 | DISC | A-16P | | 74.4-76.4 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 74.4-76.4 | (1)<br>(2)BH-02224 | BH-31304 | 74.4-76.4 | 5/8 | MC-10049 | MK-4300 | 74.4-76.4 | 3/4 | CC-70102 | CK-3108 |
| | TE37・47 | ブースター付 | 74.4-76.4 | 13/16 | | TK-9345 | 74.4-76.4 | 2 | DISC | A-16P | | 74.4-76.4 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 74.4-76.4 | (1)<br>(2)BH-02224 | BH-31304 | 74.4-76.4 | 5/8 | MC-10049 | MK-4300 | 74.4-76.4 | 3/4 | CC-70102 | CK-3108 |
| | | ブースター無 | 74.4-75.11 | 3/4 | | TK-9330 | 74.4-75.11 | 2 | DISC | A-16P | | 74.4-75.11 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 74.4-75.11 | (1)<br>(2)BH-02224 | BH-31304 | 74.4-75.11 | 5/8 | MC-10049 | MK-4300 | 74.4-75.11 | 3/4 | CC-70102 | CK-3108 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| COROLLA, SPRINTER : 50, 60 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1200) | KE50・60 | ドラム車 | 76.1-77.1<br>77.1-78.5 | 11/16<br>11/16 | | TK-9328<br>TK-9372 | 76.1-78.5 | 7/8 | (R-1)WC-1075<br>(R-2)WC-2065<br>(L-1)WC-3075<br>(L-2)WC-4065 | WK-054 | CUP | 76.1-77.1<br><br>77.1-78.5 | 3/4<br><br>3/4 | (R)WC-50060<br>(L)WC-50060<br>(R)WC-50052<br>(L)WC-50052 | WK-491<br><br>WK-491 | CUP<br><br>CUP | 76.1-78.5 | | BH-31304 | | | (ワイヤー式) | | | | | |
| | | ディスク車 | 76.1-77.1<br>77.1-78.5 | 3/4<br>3/4 | | TK-9329<br>TK-9373 | 76.1-78.5 | 1 7/8 | DISC | SP-215 | | 76.1-77.1<br><br>77.1-78.5 | 13/16<br><br>13/16 | (R)WC-50059<br>(L)WC-50059<br>(R)WC-50053<br>(L)WC-50053 | WK-492<br><br>WK-492 | CUP<br><br>CUP | 76.1-78.5 | (1)<br>(2)BH-02224 | BH-31304 | | | (ワイヤー式) | | | | | |
| (1300) | KE55・65 | ドラム車 | 77.10-79.2 | 11/16 | | TK-9372 | 77.10-79.2 | 7/8 | (R-1)WC-1075<br>(R-2)WC-2065<br>(L-1)WC-3075<br>(L-2)WC-4065 | WK-054 | CUP | 77.10-79.2 | 3/4 | (R)WC-50052<br>(L)WC-50052 | WK-491 | CUP | 77.10-79.2 | | BH-31304 | | | (ワイヤー式) | | | | | |
| | | ディスク車 | 77.10-79.2 | 3/4 | | TK-9373 | 77.10-79.2 | 1 7/8 | DISC | SP-215 | | 77.10-79.2 | 13/16 | (R)WC-50053<br>(L)WC-50053 | WK-492 | CUP | 77.10-79.2 | (1)<br>(2)BH-02224 | BH-31304 | | | (ワイヤー式) | | | | | |
| (1400) | TE50 | ドラム車 | 77.1-79.2 | 13/16 | | TK-9374 | 77.1-79.2 | 7/8 | (R-1)WC-51000<br>(R-2)WC-52000<br>(L-1)WC-53000<br>(L-2)WC-54000 | WK-054 | CUP | 77.1-79.2 | 11/16 | (R)WC-50041<br>(L)WC-50041 | WK-083 | CUP | 77.1-79.2 | | BH-31304 | 77.1-78.5<br>78.5-79.2 | 5/8<br>5/8 | MC-10049<br>MC-10078 | MK-4300<br>MK-4308 | 77.1-77.8<br>77.8-79.2 | 3/4<br>13/16 | CC-70102<br>CC-70110 | CK-3108<br>CK-3113 |
| | | ディスク車 | 77.1-79.2 | 13/16 | | TK-9374 | 77.1-79.2 | 2 | DISC | A-16P | | 77.1-79.2 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 77.1-79.2 | (1)<br>(2)BH-02224 | BH-31304 | 77.1-78.5<br>78.5-79.2 | 5/8<br>5/8 | MC-10049<br>MC-10078 | MK-4300<br>MK-4308 | 77.1-77.8<br>77.8-79.2 | 3/4<br>13/16 | CC-70102<br>CC-70110 | CK-3108<br>CK-3113 |
| | TE60 | | 77.1-79.2 | 13/16 | | TK-9374 | 77.1-79.2 | 2 | DISC | A-16P | | 77.1-79.2 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 77.1-79.2 | (1)<br>(2)BH-02224 | BH-31304 | 77.1-78.5<br>78.5-79.2 | 5/8<br>5/8 | MC-10049<br>MC-10078 | MK-4300<br>MK-4308 | 77.1-77.8<br>77.8-79.2 | 3/4<br>13/16 | CC-70102<br>CC-70110 | CK-3108<br>CK-3113 |
| (1600) | TE51・61 | DX・HDX・XL<br>SR・GS・GSL | 76.5-77.1<br>77.1-78.5 | 13/16<br>13/16 | | TK-9345<br>TK-9374 | 76.5-78.5 | 2 | DISC | A-16P | | 76.5-78.5 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 76.5-78.5 | (1)<br>(2)BH-02224 | BH-31304 | 76.5-78.5 | 5/8 | MC-10049 | MK-4300 | 76.5-77.8<br>77.8-78.5 | 3/4<br>13/16 | CC-70102<br>CC-70110 | CK-3108<br>CK-3113 |
| | | GT・トレノ・レビン | 77.1-78.5 | 13/16 | | TK-9374 | 77.1-78.5 | 2 | DISC | A-16P | | 77.1-78.5 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 77.1-78.5 | (1)<br>(2)BH-02224 | BH-31304 | 77.1-78.5 | 5/8 | MC-10049 | MK-4300 | 77.1-77.8<br>77.8-78.5 | 3/4<br>13/16 | CC-70102<br>CC-70110 | CK-3108<br>CK-3113 |
| | TE52・62 | | 76.1-77.1<br>77.1-77.8 | 13/16<br>13/16 | | TK-9345<br>TK-9374 | 76.1-77.8 | 2 | DISC | A-16P | | 76.1-77.8 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 76.1-77.8 | (1)<br>(2)BH-02224 | BH-31304 | 76.1-77.8 | 5/8 | MC-10049 | MK-4300 | 76.1-77.8 | 3/4 | CC-70102 | CK-3108 |
| (1600) | TE55・65 | | 78.5-79.2 | 13/16 | | TK-9374 | 78.5-79.2 | 2 | DISC | A-16P | | 78.5-79.2 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 78.5-79.2 | (1)<br>(2)BH-02224 | BH-31304 | 78.5-79.2 | 5/8 | MC-10078 | MK-4308 | 78.5-79.2 | 13/16 | CC-70110 | CK-3113 |
| | TE56・66 | | 77.8-79.2 | 13/16 | | TK-9374 | 77.8-79.2 | 2 | DISC | A-16P | | 77.8-79.2 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 77.8-79.2 | (1)<br>(2)BH-02224 | BH-31304 | 77.8-78.5<br>78.5-79.2 | 5/8<br>5/8 | MC-10049<br>MC-10078 | MK-4300<br>MK-4308 | 77.8-79.2 | 13/16 | CC-70110 | CK-3113 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| COROLLA, SPRINTER : 70 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1300) | E−KE70 | | 79.3−83.4 | 3/4 | | TK−9401 | 79.3−83.4 | 48.1 | DISC | MP−5 | | 79.3−82.1 | 13/16 | (R)WC−50056<br>(L)WC−50056 | WK−543 | CUP | 79.3−83.4 | (1)BH−02393<br>(2)BH−02224 | BH−T822 | | | (ワイヤー式) | | | | | |
| | | | | | | | | | | | | 82.1−83.4 | 13/16 | (R)WC−50056<br>(L)WC−50056 | WK−543 | CUP | | | | | | | | | | | |
| | J−KE71V(バン) | | 79.8−81.8 | 3/4 | | TK−9401 | 79.8−81.8 | 48.1 | DISC | MP−5 | | 79.8−81.8 | 13/16 | (R)WC−50056<br>(L)WC−50056 | WK−543 | CUP | 79.8−81.8 | (1)BH−02393<br>(2)BH−02224 | BH−T871 | | | (ワイヤー式) | | | | | |
| | L−KE72V(バン) | | 81.8−83.8<br>83.8−87.7 | 3/4<br>3/4 | | TK−9401<br>TK−9440 | 81.8−84.11<br>84.11−87.7 | 48.1<br>48.1 | DISC<br>DISC | MP−5<br>MP−14 | | 81.8−82.1 | 13/16 | (R)WC−50056<br>(L)WC−50056 | WK−543 | CUP | 81.8−85.8 | (1)BH−02393<br>(2)BH−02224 | BH−T871 | | | (ワイヤー式) | | | | | |
| | | | | | | | | | | | | 82.1−87.7 | 13/16 | (R)WC−50056<br>(L)WC−50056 | WK−543 | CUP | 85.8−87.7 | BH−02476 | BH−T871 | | | | | | | | |
| | E−KE73G(ワゴン) | | 82.5−83.8<br>83.8−87.7 | 3/4<br>3/4 | | TK−9401<br>TK−9440 | 82.5−84.11<br>84.11−87.7 | 48.1<br>48.1 | DISC<br>DISC | MP−5<br>MP−14 | | 82.5−87.7 | 13/16 | (R)WC−50056<br>(L)WC−50056 | WK−543 | CUP | 82.5−85.8<br>85.8−87.7 | (1)BH−02393<br>(2)BH−02224<br>BH−02476 | BH−T871<br>BH−T871 | | | (ワイヤー式) | | | | | |
| (1500) | E−AE70 | | 79.3−83.4 | 3/4 | | TK−9401 | 79.3−83.4 | 48.1 | DISC | MP−5 | | 79.3−82.1 | 13/16 | (R)WC−50056<br>(L)WC−50056 | WK−543 | CUP | 79.3−83.4 | (1)BH−02393<br>(2)BH−02224 | BH−T822 | | | (ワイヤー式) | | | | | |
| | | | | | | | | | | | | 82.1−83.4 | 13/16 | (R)WC−50056<br>(L)WC−50056 | WK−543 | CUP | | | | | | | | | | | |
| | L−KE74V(バン) | | 83.8−87.7 | 3/4 | | TK−9440 | 83.8−84.11<br>84.11−87.7 | 48.1<br>48.1 | DISC<br>DISC | MP−5<br>MP−14 | | 83.8−87.7 | 13/16 | (R)WC−50056<br>(L)WC−50056 | WK−543 | CUP | 83.8−85.8<br>85.8−87.7 | (1)BH−02393<br>(2)BH−02224<br>BH−02476 | BH−T871<br>BH−T871 | 83.8−87.7 | 5/8 | MC−T232 | | 83.8−87.7 | 13/16 | CC−70111 | CK−3144 |
| (1600) | E−TE71 | 四輪ディスク車 | 79.3−83.4 | 13/16 | | TK−9389 | 79.3−83.4 | 2 | DISC | A−80P | | 79.3−83.4 | 1 3/8 | DISC | A−43P<br>A−46LP | | 79.3−83.4 | (1)BH−02393<br>(2)BH−02224 | (C)BH−T822<br>(R)BH−02377<br>(L)BH−02377 | 79.3−83.4 | 5/8 | MC−T232 | | 79.3−80.8<br>80.8−80.12<br>80.12−83.4 | 13/16<br>13/16<br>13/16 | CC−70110<br>CC−70111<br>CC−70111 | CK−3113<br>CK−3113<br>CK−3144 |
| | | リヤードラム車 | 81.8−83.4 | 13/16 | | TK−9389 | 81.8−83.4 | 2 | DISC | A−80P | | 81.8−83.4 | 3/4 | (R)WC−50060<br>(L)WC−50060 | WK−491 | CUP | 81.8−83.4 | (1)BH−02393<br>(2)BH−02224 | BH−T822 | 81.8−83.4 | 5/8 | MC−T232 | | 81.8−83.4 | 13/16 | CC−70111 | CK−3144 |
| | J−TE73V(バン) | | 79.8−81.8 | 13/16 | | TK−9389 | 79.8−81.8 | 2 | DISC | A−80P | | 79.8−81.8 | 13/16 | (R)WC−50056<br>(L)WC−50056 | WK−543 | CUP | 79.8−81.8 | (1)BH−02393<br>(2)BH−02224 | BH−T871 | 79.8−81.8 | 5/8 | MC−T232 | | 79.8−80.8<br>80.8−80.12<br>80.12−81.8 | 13/16<br>13/16<br>13/16 | CC−70110<br>CC−70111<br>CC−70111 | CK−3113<br>CK−3113<br>CK−3144 |
| | L−TE74V(バン) | | 81.8−83.8 | 13/16 | | TK−9389 | 81.8−83.8 | 2 | DISC | A−80P | | 81.8−82.1 | 13/16 | (R)WC−50056<br>(L)WC−50056 | WK−543 | CUP | 81.8−83.8 | (1)BH−02393<br>(2)BH−02224 | BH−T871 | 81.8−83.8 | 5/8 | MC−T232 | | 81.8−83.8 | 13/16 | CC−70111 | CK−3144 |
| | | | | | | | | | | | | 82.1−83.8 | 13/16 | (R)WC−50056<br>(L)WC−50056 | WK−543 | CUP | | | | | | | | | | | |
| (1800) | E−TE70 | リヤードラム車 | 79.8−81.8 | 13/16 | | TK−9389 | 79.8−81.8 | 2 | DISC | A−80P | | 79.8−81.8 | 13/16 | (R)WC−50056<br>(L)WC−50056 | WK−543 | CUP | 79.8−81.8 | (1)BH−02393<br>(2)BH−02224 | BH−T822 | 79.8−81.8 | 5/8 | MC−T232 | | 79.8−80.8<br>80.8−80.12<br>80.12−81.8 | 13/16<br>13/16<br>13/16 | CC−70110<br>CC−70111<br>CC−70111 | CK−3113<br>CK−3113<br>CK−3144 |
| | | 四輪ディスク車 | 79.8−81.8 | 13/16 | | TK−9389 | 79.8−81.8 | 2 | DISC | A−80P | | 79.8−81.8 | 1 3/8 | DISC | A−43P<br>A−46LP | | 79.8−81.8 | (1)BH−02393<br>(2)BH−02224 | (C)BH−T822<br>(R)BH−02377<br>(L)BH−02377 | 79.8−81.8 | 5/8 | MC−T232 | | 79.8−80.8<br>80.8−80.12<br>80.12−81.8 | 13/16<br>13/16<br>13/16 | CC−70110<br>CC−70111<br>CC−70111 | CK−3113<br>CK−3113<br>CK−3144 |
| (1800ディーゼル) | N−CE70 | | 82.2−83.4 | 13/16 | | TK−9389 | 82.2−83.4 | 2 | DISC | A−80P | | 82.2−83.4 | 13/16 | (R)WC−50056<br>(L)WC−50056 | WK−543 | CUP | 82.2−83.4 | (1)BH−02393<br>(2)BH−02224 | BH−T822 | 82.2−83.4 | 5/8 | MC−10137 | MK−4313 | 82.2−83.4 | 13/16 | CC−70151 | CK−3144 |
| | N−CE71V(バン) | | 82.2−83.8<br>83.8−87.7 | 13/16<br>13/16 | | TK−9389<br>TK−9442 | 82.2−87.7 | 2 | DISC | A−80P | | 82.2−87.7 | 13/16 | (R)WC−50056<br>(L)WC−50056 | WK−543 | CUP | 82.2−85.8<br>85.8−87.7 | (1)BH−02393<br>(2)BH−02224<br>BH−02476 | BH−T871<br>BH−T871 | 82.2−86.9<br>86.9−87.7 | 5/8<br>5/8 | MC−10137<br>MC−10137 | MK−4313<br>MK−4340 | 82.2−85.8<br>85.8−87.7 | 13/16<br>13/16 | CC−70151<br>CC−70149 | CK−3144<br>CK−3144 |
| | N−CE72G(ワゴン) | | 83.8−87.7 | 13/16 | | TK−9442 | 83.8−87.7 | 2 | DISC | A−80P | | 83.8−87.7 | 13/16 | (R)WC−50056<br>(L)WC−50056 | WK−543 | CUP | 83.8−85.8<br>85.8−87.7 | (1)BH−02393<br>(2)BH−02224<br>BH−02476 | BH−T871<br>BH−T871 | 83.8−86.9<br>86.9−87.7 | 5/8<br>5/8 | MC−10137<br>MC−10137 | MK−4313<br>MK−4340 | 83.8−85.8<br>85.8−87.7 | 13/16<br>13/16 | CC−70151<br>CC−70149 | CK−3144<br>CK−3144 |

| Models | TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| COROLLA, SPRINTER : 80 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1300) | E−EE80 | 全車 | 85.5-87.4 | 13/16 | | TK-9439 | 85.5-87.4 | 48.1 | DISC | MP-7 | | 85.5-87.4 | 11/16 | (R)WC-55020<br>(L)WC-57020 | WK-569 | CUP | 85.5-87.4 | BH-02455 | (R)BH-02465<br>(L)BH-02465 | 85.5-86.9<br>86.9-87.4 | 5/8<br>5/8 | MC-T205 | MK-4326<br>MK-4353 | 85.5-85.12<br>85.12-87.4 | 7/8<br>13/16 | CC-70172<br>CC-70179 | CK-3122<br>CK-3144 |
| | E−AE80 | 全車 | 83.5-85.5 | 13/16 | | TK-9439 | 83.5-85.5 | 48.1 | DISC | MP-7 | | 83.5-85.5 | 11/16 | (R)WC-55020<br>(L)WC-57020 | WK-569 | CUP | 83.5-84.5<br>84.5-85.5 | BH-02455<br>BH-02455 | (R)BH-95007<br>(L)BH-95007<br>(R)BH-02465<br>(L)BH-02465 | 83.5-84.2<br>84.2-85.5 | 5/8<br>5/8 | MC-10124 | MK-4315<br>MK-4310 | 83.5-85.5 | 13/16 | CC-70152 | CK-3131 |
| (1500) | E−AE81 | 全車 | 83.5-87.4 | 13/16 | | TK-9439 | 83.5-87.4 | 48.1 | DISC | MP-7 | | 83.5-87.4 | 11/16 | (R)WC-55020<br>(L)WC-57020 | WK-569 | CUP | 83.5-84.5<br>84.5-87.4 | BH-02455<br>BH-02455 | (R)BH-95007<br>(L)BH-95007<br>(R)BH-02465<br>(L)BH-02465 | 83.5-84.2<br>84.2-85.5<br>85.5-86.9<br>86.9-87.4 | 5/8<br>5/8<br>5/8<br>5/8 | MC-10124<br>MC-T205 | MK-4315<br>MK-4310<br>MK-4326<br>MK-4353 | 83.5-87.4 | 13/16 | CC-70152 | CK-3131 |
| (1600) | E−AE82 | SR・SX・ZX<br>FX−SR<br>SE・SEサルーン | 83.5-87.4 | 13/16 | | TK-9439 | 83.5-87.4 | 48.1 | DISC | MP-7 | | 83.5-87.4 | 11/16 | (R)WC-55020<br>(L)WC-57020 | WK-569 | CUP | 83.5-84.5<br>84.5-87.4 | BH-02455<br>BH-02455 | (R)BH-95007<br>(L)BH-95007<br>(R)BH-02465<br>(L)BH-02465 | 83.5-84.2<br>84.2-85.5<br>85.5-86.9<br>86.9-87.4 | 5/8<br>5/8<br>5/8<br>5/8 | MC-10124<br>MC-T205 | MK-4315<br>MK-4310<br>MK-4326<br>MK-4353 | 83.5-87.4 | 13/16 | CC-70152 | CK-3131 |
| | | GT・FX−GT | 84.10-87.4 | 7/8 | | TK-9421 | 84.10-87.4 | 51.1 | DISC | MP-6 | | 84.10-87.4 | 31.7 | DISC | A-222P<br>A-128LP | | 84.10-87.4 | BH-02455 | (R)BH-02463<br>(L)BH-02463 | 84.10-85.5<br>85.5-86.9<br>86.9- | 5/8<br>5/8<br>5/8 | MC-T205 | MK-4310<br>MK-4326<br>MK-4353 | 84.10-87.4 | 7/8 | CC-70173 | CK-3140 |
| (1800ディーゼル) | N−CE80 | 全車 | 83.5-87.4 | 13/16 | | TK-9439 | 83.5-87.4 | 48.1 | DISC | MP-7 | | 83.5-87.4 | 11/16 | (R)WC-55020<br>(L)WC-57020 | WK-569 | CUP | 83.5-84.5<br>84.5-87.4 | BH-02455<br>BH-02455 | (R)BH-95007<br>(L)BH-95007<br>(R)BH-02465<br>(L)BH-02465 | 83.5-86.9<br>86.9-87.4 | 5/8<br>5/8 | MC-10125<br>MC-10125 | MK-4353 | 83.5-84.5<br>84.5-87.4 | 13/16<br>13/16 | CC-70150<br>CC-70150 | CK-3129<br>CK-3144 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| COROLLA, SPRINTER, COROLLA LEVIN, SPRINTER TRUENO : 80 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1500) | E－AE85 | | 83.5-87.4 | 13/16 | | TK-9438 | 83.5-87.4 | 2 | DISC | A-80P | | 83.5-87.4 | 13/16 | (R)WC-50056<br>(L)WC-50056 | WK-543 | CUP | 83.5-85.5<br>85.5-87.4 | (1)BH-02393<br>(2)BH-02224<br>BH-02476 | BH-T822<br>BH-T822 | | | (ワイヤー式) | | | | | |
| (1600) | E－AE86 | リヤードラム車 | 83.5-83.12<br>83.12-87.4 | 13/16<br>13/16 | TD-T920 | TK-9438<br>TK-9438 | 83.5-87.4 | 2 | DISC | A-102P | | 83.5-87.4 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 83.5-85.5<br>85.5-87.4 | (1)BH-02393<br>(2)BH-02224<br>BH-02476 | BH-T822<br>BH-T822 | 83.5-86.11<br>86.11-87.4 | 5/8<br>5/8 | MC-T232<br>MC-T232 | MK-4308<br>MK-4341 | 83.5-87.4 | 13/16 | CC-70153 | CK-3144 |
| | | 四輪ディスク車 | 83.5-83.12<br>83.12-87.4 | 13/16<br>13/16 | TD-T920 | TK-9438<br>TK-9438 | 83.5-87.4 | 2 | DISC | A-102P | | 83.5-87.4 | 1 3/8 | DISC | A-126P | | 83.5-85.5<br>85.5-87.4 | (1)BH-02393<br>(2)BH-02224<br>BH-02476 | BH-T822<br>(R)BH-94010<br>(L)BH-94010<br>BH-T822<br>(R)BH-94010<br>(L)BH-94010 | 83.5-86.11<br>86.11-87.4 | 5/8<br>5/8 | MC-T232<br>MC-T232 | MK-4308<br>MK-4341 | 83.5-87.4 | 13/16 | CC-70153 | CK-3144 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| COROLLA, SPRINTER, COROLLA LEVIN, SPRINTER TRUENO : 90 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1300) | E－EE90 | | 87.5-91.6 | 13/16 | | TK-T023 | 87.5-91.6 | 51.1 | DISC | MP-15 | CPM-15 | 87.5-91.6 | 11/16 | (R)WC-55020<br>(L)WC-57020 | WK-569 | CUP | 87.5-91.6 | BH-02532 | (R)BH-02533<br>(L)BH-02533 | 87.5-88.6<br>88.6-89.5<br>89.5-91.6 | 5/8<br>5/8<br>5/8 | MC-T400<br>MC-T400<br>MC-T350 | MK-4337<br>MK-4342<br>MK-T236 | 87.5-88.5<br>88.5-91.6 | 13/16<br>13/16 | CC-70179<br>CC-70179 | CK-3144<br>CK-3144 |
| (1500) | E－AE91 | リヤードラム車 | 87.5-92.5 | 13/16 | | TK-T023 | 87.5-92.5 | 51.1 | DISC | MP-15 | CPM-15 | 87.5-92.5 | 11/16 | (R)WC-55020<br>(L)WC-57020 | WK-569 | CUP | 87.5-92.5 | BH-02532 | (R)BH-02533<br>(L)BH-02533 | 87.5-88.6<br>88.6-89.5<br>89.5-92.4<br>92.4-92.5 | 5/8<br>5/8<br>5/8<br>5/8 | MC-T400<br>MC-T400<br>MC-T350 | MK-4337<br>MK-4342<br>MK-T236 | 87.5-88.5<br>88.5-92.5 | 13/16<br>13/16 | CC-70183<br>CC-70183 | CK-3144<br>CK-3144 |
| | | 四輪ディスク車 | 89.5-92.5<br><アンチスキッド付><br>89.5-92.5 | 13/16<br><br>15/16 | | TK-T023<br><br>TK-T300 | 89.5-92.5<br><アンチスキッド付><br>89.5-92.5 | 51.1<br><br>54.0 | DISC<br><br>DISC | MP-15<br><br>MP-19 | CPM-15<br><br>CPM-19 | 89.5-92.5 | 30.2 | DISC | A-464P | | 89.5-92.5<br><アンチスキッド付><br>89.5-92.5 | BH-02532 | (R)BH-02533<br>(L)BH-02533<br><br>(R)BH-02463<br>(L)BH-02463 | 89.5-92.4<br>92.4-92.5 | 5/8<br>5/8 | MC-T350<br>MC-T350 | MK-T236 | 89.5-92.5 | 13/16 | CC-70183 | CK-3144 |
| (1600) | E－AE92 | GT(リヤードラム車) | 87.5-89.5 | 7/8 | | TK-T032 | 87.5-89.5 | 51.1 | DISC | MP-15 | CPM-15 | 87.5-89.5 | 11/16 | (R)WC-55020<br>(L)WC-57020 | WK-569 | CUP | 87.5-89.5 | BH-02532 | (R)BH-02533<br>(L)BH-02533 | 87.5-88.6<br>88.6-89.5 | 5/8<br>5/8 | MC-T400<br>MC-T400 | MK-4337<br>MK-4342 | 87.5-88.5<br>88.5-89.5 | 13/16<br>13/16 | CC-70183<br>CC-70183 | CK-3144<br>CK-3144 |
| | | GT・FXGT・GTV・GT－APEX<br>四輪ディスク車 | 87.5-92.5<br><アンチスキッド付><br>89.5-92.5 | 7/8<br><br>15/16 | | TK-T032<br><br>TK-T300 | 87.5-89.5<br>89.5-92.5 | 51.1<br>54.0 | DISC<br>DISC | MP-15<br>MP-19 | CPM-15<br>CPM-19 | 87.5-92.5 | 30.2 | DISC | A-464P | | 87.5-92.5 | BH-02532 | (R)BH-02463<br>(L)BH-02463 | 87.5-88.6<br>88.6-89.5<br>89.5-92.4<br>92.4-92.5 | 5/8<br>5/8<br>5/8<br>5/8 | MC-T400<br>MC-T400<br>MC-T378<br>MC-T378 | MK-4337<br>MK-4342<br>MK-T236 | 87.5-88.5<br>88.5-92.5 | 13/16<br>13/16 | CC-70183<br>CC-70183 | CK-3144<br>CK-3144 |
| | | スーパーチャージャーGTZ<br>(レビン・トレノ) | 87.5-91.6<br><アンチスキッド付><br>89.5-91.6 | 15/16<br><br>15/16 | | TK-T349<br><br>TK-T300 | 87.5-89.5<br>89.5-91.6 | 54.0<br>54.0 | DISC<br>DISC | MP-20<br>MP-19 | <br>CPM-19 | 87.5-91.6 | 30.2 | DISC | A-464P | | 87.5-91.6 | BH-02532 | (R)BH-02463<br>(L)BH-02463 | 87.5-88.6<br>88.6-89.5<br>89.5-91.6 | 5/8<br>5/8<br>5/8 | MC-T400<br>MC-T400<br>MC-T378 | MK-4337<br>MK-4342<br>MK-T236 | 87.5-88.5<br>88.5-91.6 | 13/16<br>13/16 | CC-70183<br>CC-70183 | CK-3144<br>CK-3144 |
| | E－AE95(4WD) | | 87.10-89.5<br>89.5-91.6 | 13/16<br>7/8 | | TK-T023<br>TK-T032 | 87.10-91.6 | 51.1 | DISC | MP-15 | CPM-15 | 87.10-91.6 | 3/4 | (R)WC-50055<br>(L)WC-50055 | WK-542 | CUP | 87.10-91.6 | BH-02532 | (R)BH-02558<br>(L)BH-02558 | 87.10-88.6<br>88.6-89.5<br>89.5-91.6 | 5/8<br>5/8<br>5/8 | <br>MC-10122<br>MC-T378 | MK-4337<br>MK-4342<br>MK-T236 | 87.10-88.5<br>88.5-91.6 | 13/16<br>13/16 | CC-70183<br>CC-70183 | CK-3144<br>CK-3144 |
| (1800ディーゼル) | Q－CE90 | | 87.5-91.6 | 13/16 | | TK-T023 | 87.5-91.6 | 51.1 | DISC | MP-15 | CPM-15 | 87.5-91.6 | 11/16 | (R)WC-55020<br>(L)WC-57020 | WK-569 | CUP | 87.5-91.6 | BH-02532 | (R)BH-02533<br>(L)BH-02533 | 87.5-88.6<br>88.6-89.5<br>89.5-91.6 | 5/8<br>5/8<br>5/8 | <br>MC-10122<br>MC-T378 | MK-4337<br>MK-4342<br>MK-T236 | 87.5-89.2<br>89.2-91.6 | 13/16<br>13/16 | CC-70150<br>CC-70150 | CK-3144<br>CK-3144 |
| (2000ディーゼル) | Q－CE95(4WD) | | 89.10-91.6 | 7/8 | | TK-T032 | 89.10-91.6 | 51.1 | DISC | MP-15 | CPM-15 | 89.10-91.6 | 3/4 | (R)WC-50055<br>(L)WC-50055 | WK-542 | CUP | 89.10-91.6 | BH-02532 | (R)BH-02558<br>(L)BH-02558 | 89.10-91.6 | 5/8 | MC-T378 | MK-T236 | 89.10-91.6 | 13/16 | CC-70150 | CK-3144 |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| COROLLA, COROLLA VAN/WAGON, SPRINTER, SPRINTER VAN/WAGON : 90 ser. | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1300) E－EE97G(ワゴン)<br>L－EE96V(バン)<br>＜R－は89．8～＞ | 87.8-91.9 | 13/16 | | TK-T023 | 87.8-91.9 | 51.1 | DISC | MP-15 | CPM-15 | 87.8-91.9 | 11/16 | (R)WC-55020<br>(L)WC-57020 | WK-569 | CUP | 87.8-91.9 | BH-02532 | (R)BH-02539<br>(L)BH-02539 | 87.8-88.6<br>88.6-89.8<br>89.8-91.9 | 5/8<br>5/8<br>5/8 | MC-T400<br>MC-T400<br>MC-T350 | MK-4337<br>MK-4342<br>MK-T236 | 87.8-88.5<br>88.5-91.9 | 13/16<br>13/16 | CC-70179<br>CC-70179 | CK-3144<br>CK-3144 |
| (1500) E－AE91G(ワゴン)<br>L－EE98V(バン)<br>＜R－は89．8～＞ | 87.8-91.9 | 13/16 | | TK-T023 | 87.8-91.9 | 51.1 | DISC | MP-15 | CPM-15 | 87.8-91.9 | 11/16 | (R)WC-55020<br>(L)WC-57020 | WK-569 | CUP | <EE98V><br>87.8-91.9<br><AE91G><br>87.8-91.9 | BH-02532<br>BH-02532 | (R)BH-02539<br>(L)BH-02539<br>(R)BH-02533<br>(L)BH-02533 | 87.8-88.6<br>88.6-89.8<br>89.8-91.9 | 5/8<br>5/8<br>5/8 | MC-T400<br>MC-T400<br>MC-T350 | MK-4337<br>MK-4342<br>MK-T236 | <EE98V><br>87.8-88.5<br>88.5-91.9<br><AE91G><br>87.8-88.5<br>88.5-91.9 | 13/16<br>13/16<br>13/16<br>13/16 | CC-70179<br>CC-70179<br>CC-70183<br>CC-70183 | CK-3144<br>CK-3144<br>CK-3144<br>CK-3144 |
| (1800ディーゼル) Q－CE97G(ワゴン)<br>N－CE96V(バン)<br>S－CE96V(バン) | 87.8-91.9 | 13/16 | | TK-T023 | 87.8-91.9 | 51.1 | DISC | MP-15 | CPM-15 | 87.8-91.9 | 11/16 | (R)WC-55020<br>(L)WC-57020 | WK-569 | CUP | 87.8-91.9 | BH-02532 | (R)BH-02539<br>(L)BH-02539 | 87.8-88.6<br>88.6-89.8<br>89.8-91.9 | 5/8<br>5/8<br>5/8 | MC-T400<br>MC-10122<br>MC-T378 | MK-4337<br>MK-4342<br>MK-T236 | 87.8-89.2<br>89.2-91.9 | 13/16<br>13/16 | CC-70150<br>CC-70150 | CK-3144<br>CK-3144 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| COROLLA, SPRINTER, LEVIN, TRUENO, CERES, MARINO : 100 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1300) | E−EE101 | | 91.6−95.5 | 13/16 | | TK−T023 | 91.6−95.5 | 51.1 | DISC | MP−15 | CPM−15 | 91.6−95.5 | 11/16 | (R)WC−T599<br>(L)WC−T617 | WK−569 | CUP | 91.6−95.5 | (R)BH−T543<br>(L)BH−T544 | (R)BH−T545<br>(L)BH−T545 | 91.6−93.11<br>93.11−96.5 | 5/8<br>5/8 | MC−T350<br>MC−T350 | MK−T244 | 91.6−94.1<br>94.1−95.5 | 13/16<br>13/16 | CC−70179<br>CC−70179 | CK−3144<br>CK−T201 |
| | | <アンチスキッド付> | 91.6−95.5 | 7/8 | | TK−T320 | | | | | | | | | | | | | | | | | | | | | |
| (1500) | E−AE100 | | 91.6−95.5 | 13/16 | | TK−T023 | 91.6−98.8 | 51.1 | DISC | MP−15 | CPM−15 | 91.6−98.8 | 11/16 | (R)WC−T599<br>(L)WC−T617 | WK−569 | CUP | 91.6−95.5 | (R)BH−T543<br>(L)BH−T544 | (R)BH−T545<br>(L)BH−T545 | 91.6−93.11<br>93.11−97.5 | 5/8<br>5/8 | MC−T350<br>MC−T350 | MK−T244 | 91.6−93.1<br>93.1−98.8 | 13/16<br>13/16 | CC−70183<br>CC−70183 | CK−3144<br>CK−T201 |
| | | | 95.5−96.5 | 13/16 | | TK−T357 | | | | | | | | | | | 95.5−98.8 | (R)BH−T543<br>(L)BH−T544 | (R)BH−T648<br>(L)BH−T648 | 97.5−98.8 | 5/8 | | MK−T244 | | | | |
| | | <アンチスキッド付> | 91.6−95.5 | 7/8 | | TK−T320 | | | | | | | | | | | | | | | | | | | | | |
| | | | 95.5−96.5 | 13/16 | | TK−T358 | | | | | | | | | | | | | | | | | | | | | |
| | | | 96.5−98.8 | 13/16 | | TK−T357 | | | | | | | | | | | | | | | | | | | | | |
| (1600) | E−AE101 | SEG・SJ・X | 91.6−95.5 | 13/16 | | TK−T023 | 91.6−98.8 | 51.1 | DISC | MP−15 | CPM−15 | 91.6−98.8 | 11/16 | (R)WC−T599<br>(L)WC−T617 | WK−569 | CUP | 91.6−95.5 | (R)BH−T543<br>(L)BH−T544 | (R)BH−T545<br>(L)BH−T545 | 91.6−93.11<br>93.11−97.5 | 5/8<br>5/8 | MC−T350<br>MC−T350 | MK−T244 | 91.6−93.1<br>93.1−98.8 | 13/16<br>13/16 | CC−70183<br>CC−70183 | CK−3144<br>CK−T201 |
| | | | 95.5−96.5 | 13/16 | | TK−T357 | | | | | | | | | | | 95.5−98.8 | (R)BH−T543<br>(L)BH−T544 | (R)BH−T648<br>(L)BH−T648 | 97.5−98.8 | 5/8 | | MK−T244 | | | | |
| | | <アンチスキッド付> | 91.6−95.5 | 7/8 | | TK−T320 | | | | | | | | | | | | | | | | | | | | | |
| | | | 95.5−96.5 | 13/16 | | TK−T358 | | | | | | | | | | | | | | | | | | | | | |
| | | | 96.5−98.8 | 13/16 | | TK−T357 | | | | | | | | | | | | | | | | | | | | | |
| | | SJ(障害者用) | 91.6−95.5 | 15/16 | | TK−T300 | 91.6−95.5 | 51.1 | DISC | MP−15 | CPM−15 | 91.6−95.5 | 11/16 | (R)WC−T599<br>(L)WC−T617 | WK−569 | CUP | 91.6−95.5 | (R)BH−T543<br>(L)BH−T544 | (R)BH−T545<br>(L)BH−T545 | | | (オートマチック) | | | | | |
| | | G・GT・GTAPEX<br>(ノーマルサス車) | 91.6−95.5 | 7/8 | | TK−T402 | 91.6−98.8 | 54.0 | DISC | MP−19 | CPM−19 | 91.6−95.5 | 30.2 | DISC | A−464P | | 91.6−97.4 | (R)BH−T543<br>(L)BH−T544 | (R)BH−T580<br>(L)BH−T580 | 91.6−92.8<br>92.8−98.8 | 5/8<br>5/8 | | MK−T244 | 91.6−93.1<br>93.1−98.8 | 13/16<br>13/16 | CC−70183<br>CC−70183 | CK−3144<br>CK−T201 |
| | | | 95.5−96.5 | 7/8 | | TK−T360 | | | | | | 95.5−98.8 | | DISC | A−464P | | 97.4−98.8 | (R)BH−T543<br>(L)BH−T544 | (R)BH−T699<br>(L)BH−T699 | | | | | | | | |
| | | <アンチスキッド付> | 91.6−95.5 | 15/16 | | TK−T300 | | | | | | | | | | | | | | | | | | | | | |
| | | | 95.5−96.5 | 7/8 | | TK−T359 | | | | | | | | | | | | | | | | | | | | | |
| | | | 96.5−98.8 | 7/8 | | TK−T360 | | | | | | | | | | | | | | | | | | | | | |
| | | GT・GTAPEX・GTZ<br>(スーパーストラットサス車) | 91.6−95.5 | 7/8 | | TK−T320 | 91.6−95.5 | 38.1 | DISC | MP−42 | | 91.6−95.5 | 30.2 | DISC | A−464P | | 91.6−94.5 | (R−1)BH−T956<br>(L−1)BH−T956<br>(R−2)BH−T548<br>(L−2)BH−T549 | (R)BH−T580<br>(L)BH−T580 | 91.6−92.8<br>92.8−95.5 | 5/8<br>5/8 | | MK−T244 | 91.6−93.1<br>93.1−95.5 | 13/16<br>13/16 | CC−70183<br>CC−70183 | CK−3144<br>CK−T201 |
| | | | | | | | | | | | | | | | | | 94.5−95.5 | (R−1)BH−T956<br>(L−1)BH−T956<br>(R−2)BH−T630<br>(L−2)BH−T651 | (R)BH−T580<br>(L)BH−T580 | | | | | | | | |
| (1600) | E−AE104(4WD) | | 91.9−95.5 | 7/8 | | TK−T402 | 91.9−95.5 | 51.1 | DISC | MP−15 | CPM−15 | 91.9−95.5 | 11/16 | (R)WC−T599<br>(L)WC−T617 | WK−569 | CUP | 91.9−95.5 | (R)BH−T551<br>(L)BH−T552 | (R)BH−T545<br>(L)BH−T545 | 91.9−93.11<br>93.11−95.5 | 5/8<br>5/8 | | MK−T244 | 91.9−93.1<br>93.1−95.5 | 13/16<br>13/16 | CC−70183<br>CC−70183 | CK−3144<br>CK−T201 |
| | | <アンチスキッド付> | 91.9−95.5 | 7/8 | | TK−T320 | | | | | | | | | | | | | | | | | | | | | |
| (2000ディーゼル) | | | 91.6−95.5 | 13/16 | | TK−T023 | 91.6−95.5 | 51.1 | DISC | MP−15 | CPM−15 | 91.6−95.5 | 11/16 | (R)WC−T599<br>(L)WC−T617 | WK−569 | CUP | 91.6−95.5 | (R)BH−T543<br>(L)BH−T544 | (R)BH−T545<br>(L)BH−T545 | 91.6−93.11<br>93.11−95.5 | 5/8<br>5/8 | MC−T379<br>MC−T379 | MK−T244 | 91.6−94.1<br>94.1−95.5 | 13/16<br>13/16 | CC−70150<br>CC−70150 | CK−3144<br>CK−T201 |
| | X−CE100 | <アンチスキッド付> | 91.6−95.5 | 7/8 | | TK−T320 | | | | | | | | | | | | | | | | | | | | | |
| | X−CE104(4WD) | | 91.9−95.5 | 7/8 | | TK−T402 | 91.9−95.5 | 51.1 | DISC | MP−15 | CPM−15 | 91.9−95.5 | 11/16 | (R)WC−T599<br>(L)WC−T617 | WK−569 | CUP | 91.9−95.5 | (R)BH−T551<br>(L)BH−T552 | (R)BH−T545<br>(L)BH−T545 | 91.9−93.11<br>93.11−95.5 | 5/8<br>5/8 | MC−T379<br>MC−T379 | MK−T244 | 91.9−94.1<br>94.1−95.5 | 13/16<br>13/16 | CC−70150<br>CC−70150 | CK−3144<br>CK−T201 |
| | | <アンチスキッド付> | 91.9−95.5 | 7/8 | | TK−T320 | | | | | | | | | | | | | | | | | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| COROLLA, COROLLA VAN/WAGON, SPRINTER, SPRINTER VAN/WAGON : 100 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1300) | R－EE102V・106V<br>＜GG－は98．4～＞<br>＜TB－は00．8～＞ | バン | 91.9-95.8<br>95.8-02.6<br>＜ｱﾝﾁｽｷｯﾄﾞ付＞<br>98.4-02.6 | 13/16<br>13/16<br><br>13/16 | | TK-T023<br>TK-T357<br><br>TK-T358 | 91.9-02.6 | 51.1 | DISC | MP-15 | CPM-15 | 91.9-02.6 | 11/16 | (R)WC-T599<br>(L)WC-T617 | WK-569 | CUP | 91.9-97.4<br><br>97.4-02.6 | (R)BH-T543<br>(L)BH-T544<br>(R)BH-T543<br>(L)BH-T544 | (R)BH-T801<br>(L)BH-T801<br>(R)BH-T801<br>(L)BH-T801 | 91.9-93.11<br>93.11-97.5<br>97.5-02.6 | 5/8<br>5/8<br>5/8 | MC-T350<br>MC-T350 | <br>MK-T244<br>MK-T244 | 91.9-94.1<br>94.1-95.10<br>95.10-02.6 | 13/16<br>13/16<br>7/8 | CC-70179<br>CC-70179 | CK-3144<br>CK-T201<br>CK-T200 |
| (1500) | E－AE100G<br>＜GF－は98．4～＞ | ワゴン | 91.9-95.5<br>95.5-96.5<br>＜ｱﾝﾁｽｷｯﾄﾞ付＞<br>91.9-95.5<br>95.5-96.5<br>96.5-00.8 | 13/16<br>13/16<br><br>7/8<br>13/16<br>13/16 | | TK-T023<br>TK-T357<br><br>TK-T320<br>TK-T358<br>TK-T357 | 91.9-00.8 | 51.1 | DISC | MP-15 | CPM-15 | 91.9-00.8 | 11/16 | (R)WC-T599<br>(L)WC-T617 | WK-569 | CUP | 91.9-95.5<br><br>95.5-00.8 | (R)BH-T543<br>(L)BH-T544<br>(R)BH-T543<br>(L)BH-T544 | (R)BH-T545<br>(L)BH-T545<br>(R)BH-T648<br>(L)BH-T648 | 91.9-93.11<br>93.11-97.5<br>97.5-00.8 | 5/8<br>5/8<br>5/8 | MC-T350<br>MC-T350 | <br>MK-T244<br>MK-T244 | 91.9-93.1<br>93.1-00.8 | 13/16<br>13/16 | CC-70183<br>CC-70183 | CK-3144<br>CK-T201 |
| | R－EE103V・107V<br>E－EE104G・108G<br>＜GF・GG－は98．4～＞<br>＜TA・TB－は00．8～＞ | バン・ワゴン | 91.9-95.8<br>95.8-02.6<br>＜ｱﾝﾁｽｷｯﾄﾞ付＞<br>98.4-02.6 | 13/16<br>13/16<br><br>13/16 | | TK-T023<br>TK-T357<br><br>TK-T358 | 91.9-02.6 | 51.1 | DISC | MP-15 | CPM-15 | 91.9-02.6 | 11/16 | (R)WC-T599<br>(L)WC-T617 | WK-569 | CUP | 91.9-97.4<br><br>97.4-02.6 | (R)BH-T543<br>(L)BH-T544<br>(R)BH-T543<br>(L)BH-T544 | (R)BH-T801<br>(L)BH-T801<br>(R)BH-T801<br>(L)BH-T801 | 91.9-93.11<br>93.11-97.5<br>97.5-02.6 | 5/8<br>5/8<br>5/8 | MC-T350<br>MC-T350 | <br>MK-T244<br>MK-T244 | 91.9-94.1<br>94.1-95.10<br>95.10-02.6 | 13/16<br>13/16<br>7/8 | CC-70179<br>CC-70179 | CK-3144<br>CK-T201<br>CK-T200 |
| (1600) | E－AE101G<br>＜GF－は98．4～＞ | ワゴン | 96.5-00.8 | 7/8 | | TK-T360 | 96.5-00.8 | 54.0 | DISC | MP-19 | CPM-19 | 96.5-00.8 | | DISC | A-464P | | 96.5-97.5<br><br>97.5-99.10<br><br>99.10-00.8 | (R)BH-T543<br>(L)BH-T544<br>(R)BH-T543<br>(L)BH-T544<br>(R)BH-T543<br>(L)BH-T544 | (R)BH-T580<br>(L)BH-T580<br>(R)BH-T699<br>(L)BH-T699<br>(R)<br>(L) | 96.5-97.4<br>97.4-97.5<br>97.5-00.8 | 5/8<br>5/8<br>5/8 | MC-T350 | MK-T244<br><br>MK-T244 | 96.5-00.8 | 13/16 | CC-70183 | CK-T201 |
| | E－AE104G<br>＜GF－は98．4～＞ | 4WDワゴン | 95.5-96.5<br>＜ｱﾝﾁｽｷｯﾄﾞ付＞<br>95.5-96.5<br>96.5-00.8 | 7/8<br><br>7/8<br>7/8 | | TK-T360<br><br>TK-T359<br>TK-T360 | 95.5-00.8 | 54.0 | DISC | MP-19 | CPM-19 | 95.5-96.5<br><br>96.5-00.8 | 11/16<br><br>3/4 | (R)WC-T599<br>(L)WC-T617<br>(R)WC-T600<br>(L)WC-T605 | WK-569<br><br>WK-542 | CUP<br><br>CUP | 95.5-00.8 | (R)BH-T551<br>(L)BH-T552 | (R)BH-T545<br>(L)BH-T545 | 96.5-97.4<br>97.4-97.5<br>97.5-00.8 | 5/8<br>5/8<br>5/8 | MC-T350 | MK-T244<br><br>MK-T244 | 95.5-00.8 | 13/16 | CC-70183 | CK-T201 |
| | R－AE109V<br>＜GG－は98．4～＞ | 4WDバン | 96.5-02.6<br>＜ｱﾝﾁｽｷｯﾄﾞ付＞<br>98.4-02.6 | 7/8<br><br>7/8 | | TK-T360<br><br>TK-T359 | 96.5-02.6 | 54.0 | DISC | MP-19 | CPM-19 | 96.5-02.6 | 11/16 | (R)WC-T647<br>(L)WC-T647 | WK-569 | CUP | 96.5-97.4<br><br>97.4-02.6 | (R)BH-T551<br>(L)BH-T552<br>(R)BH-T551<br>(L)BH-T552 | (R)BH-T674<br>(L)BH-T674<br>(R)BH-T674<br>(L)BH-T674 | 96.5-02.6 | 5/8 | | MK-T244 | 96.5-02.6 | 13/16 | CC-70183 | CK-T201 |
| (2000ディーゼル) | KD－CE100G | ワゴン | 95.5-96.5<br>＜ｱﾝﾁｽｷｯﾄﾞ付＞<br>95.5-96.5<br>96.5-98.4 | 13/16<br><br>13/16<br>13/16 | | TK-T357<br><br>TK-T358<br>TK-T357 | 95.5-98.4 | 51.1 | DISC | MP-15 | CPM-15 | 95.5-98.4 | 11/16 | (R)WC-T599<br>(L)WC-T617 | WK-569 | CUP | 95.5-98.4 | (R)BH-T543<br>(L)BH-T544 | (R)BH-T648<br>(L)BH-T648 | 95.5-98.4 | 5/8 | MC-T379 | MK-T244 | 95.5-98.4 | 13/16 | CC-70150 | CK-T201 |
| | S・X－CE106V・108G<br>＜KA－は94．1～＞<br>＜KD－は95．8～＞ | バン・ワゴン | 91.9-95.8<br>95.8-98.4 | 13/16<br>13/16 | | TK-T023<br>TK-T357 | 91.9-98.4 | 51.1 | DISC | MP-15 | CPM-15 | 91.9-98.4 | 11/16 | (R)WC-T599<br>(L)WC-T617 | WK-569 | CUP | 91.9-97.4<br><br>97.4-98.4 | (R)BH-T543<br>(L)BH-T544<br>(R)BH-T543<br>(L)BH-T544 | (R)BH-T801<br>(L)BH-T801<br>(R)BH-T801<br>(L)BH-T801 | 91.9-98.4 | 5/8 | MC-T379 | MK-T244 | 91.9-94.1<br>94.1-98.4 | 13/16<br>13/16 | CC-70150<br>CC-70150 | CK-3144<br>CK-T201 |
| | S－CE109V<br>＜KA－は94．1～＞ | 4WDバン | 91.9-95.8<br>95.8-98.4 | 13/16<br>7/8 | | TK-T023<br>TK-T360 | 91.9-95.8<br>95.8-98.4 | 51.1<br>54.0 | DISC<br>DISC | MP-15<br>MP-19 | CPM-15<br>CPM-19 | 91.9-94.9<br><br>94.9-98.4 | 11/16<br><br>11/16 | (R)WC-T647<br>(L)WC-T647<br>(R)WC-T647<br>(L)WC-T647 | WK-569<br><br>WK-569 | CUP<br><br>CUP | 91.9-95.8<br><br>95.8-97.4<br><br>97.4-98.4 | (R)BH-T551<br>(L)BH-T552<br>(R)BH-T551<br>(L)BH-T552<br>(R)BH-T551<br>(L)BH-T552 | (R)BH-T546<br>(L)BH-T546<br>(R)BH-T674<br>(L)BH-T674<br>(R)BH-T674<br>(L)BH-T674 | 91.9-98.4 | 5/8 | MC-T379 | MK-T244 | 91.9-94.1<br>94.1-98.4 | 13/16<br>13/16 | CC-70150<br>CC-70150 | CK-3144<br>CK-T201 |
| (2200ディーゼル) | KE－CE101G | ワゴン | 98.4-00.8 | 13/16 | | TK-T357 | 98.4-00.8 | 51.1 | DISC | MP-15 | CPM-15 | 98.4-00.8 | 11/16 | (R)WC-T599<br>(L)WC-T617 | WK-569 | CUP | 98.4-00.8 | (R)BH-T543<br>(L)BH-T544 | (R)BH-T648<br>(L)BH-T648 | 98.4-00.8 | 5/8 | MC-T379 | MK-T244 | 98.4-00.8 | 13/16 | CC-70150 | CK-T201 |
| | KE－CE102G・107V | バン・ワゴン | 98.4-02.6<br>＜ｱﾝﾁｽｷｯﾄﾞ付＞<br>98.4-02.6 | 13/16<br><br>13/16 | | TK-T357<br><br>TK-T358 | 98.4-02.6 | 51.1 | DISC | MP-15 | CPM-15 | 98.4-02.6 | 11/16 | (R)WC-T599<br>(L)WC-T617 | WK-569 | CUP | 98.4-02.6 | (R)BH-T543<br>(L)BH-T544 | (R)BH-T801<br>(L)BH-T801 | 98.4-02.6 | 5/8 | MC-T379 | MK-T244 | 98.4-02.6 | 13/16 | CC-70150 | CK-T201 |
| | KE－CE105V<br>＜KF－は00．8～＞ | 4WDバン | 98.4-02.6<br>＜ｱﾝﾁｽｷｯﾄﾞ付＞<br>98.4-02.6 | 7/8<br><br>7/8 | | TK-T360<br><br>TK-T359 | 98.4-02.6 | 54.0 | DISC | MP-19 | CPM-19 | 98.4-02.6 | 11/16 | (R)WC-T647<br>(L)WC-T647 | WK-569 | CUP | 98.4-02.6 | (R)BH-T551<br>(L)BH-T552 | (R)BH-T674<br>(L)BH-T674 | 98.4-02.6 | 5/8 | MC-T379 | MK-T244 | 98.4-02.6 | 13/16 | CC-70150 | CK-T201 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| COROLLA, SPRINTER, LEVIN, TRUENO : 110 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | <ｻｲｽﾞ確認> | | | |
| (1300) | E－EE111 | | 95.5-96.5 | 13/16 | | TK-T357 | 95.5-00.8 | 51.1 | DISC | MP-15 | CPM-15 | 95.5-00.8 | 11/16 | (R)WC-T599 | WK-569 | CUP | 95.5-97.4 | (R)BH-T543 | (R)BH-T648 | 95.5-97.4 | 5/8 | MC-T350 | MK-T244 | 95.5-00.8 | 13/16 | | CK-T201 |
| | ＜GF－は98．4～＞ | | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | (L)WC-T617 | | | | (L)BH-T544 | (L)BH-T648 | 97.4-00.8 | 5/8 | | MK-T244 | 95.5-00.8 | 7/8 | | CK-T200 |
| | | | 95.5-96.5 | 13/16 | | TK-T358 | | | | | | | | | | | 97.4-00.8 | (R)BH-T543 | (R)BH-T698 | | | | | | | | |
| | | | 96.5-00.8 | 13/16 | | TK-T357 | | | | | | | | | | | | (L)BH-T544 | (L)BH-T698 | | | | | | | | |
| (1500) | E－AE110 | | 95.5-96.5 | 13/16 | | TK-T357 | 95.5-00.8 | 51.1 | DISC | MP-15 | CPM-15 | 95.5-00.8 | 11/16 | (R)WC-T599 | WK-569 | CUP | 95.5-97.4 | (R)BH-T543 | (R)BH-T648 | 95.5-97.4 | 5/8 | MC-T350 | MK-T244 | 95.5-00.8 | 13/16 | CC-70183 | CK-T201 |
| | ＜GF－は98．4～＞ | | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | (L)WC-T617 | | | | (L)BH-T544 | (L)BH-T648 | 97.4-00.8 | 5/8 | | MK-T244 | | | | |
| | | | 95.5-96.5 | 13/16 | | TK-T358 | | | | | | | | | | | 97.4-00.8 | (R)BH-T543 | (R)BH-T698 | | | | | | | | |
| | | | 96.5-00.8 | 13/16 | | TK-T357 | | | | | | | | | | | | (L)BH-T544 | (L)BH-T698 | | | | | | | | |
| (1600) | E－AE111 カローラ・スプリンター | | 95.5-97.4 | 13/16 | | TK-T357 | 95.5-97.4 | | DISC | MP-15 | CPM-15 | 95.5-00.8 | 11/16 | (R)WC-T599 | WK-569 | CUP | 95.5-97.4 | (R)BH-T543 | (R)BH-T648 | 95.5-97.4 | 5/8 | | MK-T244 | 95.5-00.8 | 13/16 | CC-70183 | CK-T201 |
| | ＜GF－は98．4～＞ Sクルーズ | | 97.4-00.8 | 7/8 | | TK-T360 | 97.4-00.8 | | DISC | MP-19 | CPM-19 | | | (L)WC-T617 | | | | (L)BH-T544 | (L)BH-T648 | 97.4-00.8 | 5/8 | | MK-T244 | | | | |
| | ＧＴ | | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | | | | 97.4-99.10 | (R)BH-T543 | (R)BH-T699 | | | | | | | | |
| | | | 95.5-00.8 | 13/16 | | TK-T358 | | | | | | | | | | | | (L)BH-T544 | (L)BH-T699 | | | | | | | | |
| | | | | | | | | | | | | | | | | | 99.10-00.8 | (R)BH-T543 | (R) | | | | | | | | |
| | | | | | | | | | | | | | | | | | | (L)BH-T544 | (L) | | | | | | | | |
| | レビン・トレノ | | 95.5-96.5 | 13/16 | | TK-T357 | 95.5-00.8 | 51.1 | DISC | MP-15 | CPM-15 | 95.5-00.8 | 11/16 | (R)WC-T599 | WK-569 | CUP | 95.5-97.4 | (R)BH-T543 | (R)BH-T648 | 95.5-97.4 | 5/8 | MC-T350 | MK-T244 | 95.5-00.8 | 13/16 | CC-70183 | CK-T201 |
| | XZ・XZリミテッド | | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | (L)WC-T617 | | | | (L)BH-T544 | (L)BH-T648 | 97.4-00.8 | 5/8 | | MK-T244 | | | | |
| | | | 95.5-96.5 | 13/16 | | TK-T358 | | | | | | | | | | | 97.4-00.8 | (R)BH-T543 | (R)BH-T698 | | | | | | | | |
| | | | 96.5-00.8 | 13/16 | | TK-T357 | | | | | | | | | | | | (L)BH-T544 | (L)BH-T698 | | | | | | | | |
| | BZ－G | | 95.5-96.5 | 7/8 | | TK-T360 | 95.5-00.8 | 54.0 | DISC | MP-19 | CPM-19 | 95.5-00.8 | | DISC | A-464P | | 95.5-97.4 | (R)BH-T543 | (R)BH-T580 | 95.5-00.8 | 5/8 | | MK-T244 | 95.5-00.8 | 13/16 | CC-70183 | CK-T201 |
| | （ノーマルサス車） | | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | | | | | (L)BH-T544 | (L)BH-T580 | | | | | | | | |
| | | | 95.5-96.5 | 7/8 | | TK-T359 | | | | | | | | | | | 97.4-99.10 | (R)BH-T543 | (R)BH-T699 | | | | | | | | |
| | | | 96.5-00.8 | 7/8 | | TK-T360 | | | | | | | | | | | | (L)BH-T544 | (L)BH-T699 | | | | | | | | |
| | | | | | | | | | | | | | | | | | 99.10-00.8 | (R)BH-T543 | (R) | | | | | | | | |
| | | | | | | | | | | | | | | | | | | (L)BH-T544 | (L) | | | | | | | | |
| | BZ－G・BZ－V・BZ－R | | 95.5-96.5 | 7/8 | | TK-T360 | 95.5-00.8 | 38.1 | DISC | MP-42 | | 95.5-00.8 | | DISC | A-464P | | 95.5-97.4 | (R-1)BH-T956 | (R)BH-T580 | 95.5-00.8 | 5/8 | | MK-T244 | 95.5-00.8 | 13/16 | CC-70183 | CK-T201 |
| | （スーパーストラットサス車） | | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | | | | | (L-1)BH-T956 | (L)BH-T580 | | | | | | | | |
| | | | 95.5-96.5 | 7/8 | | TK-T359 | | | | | | | | | | | | (R-2)BH-T630 | | | | | | | | | |
| | | | 96.5-00.8 | 7/8 | | TK-T360 | | | | | | | | | | | | (L-2)BH-T651 | | | | | | | | | |
| | | | | | | | | | | | | | | | | | 97.4-99.10 | (R-1)BH-T956 | (R)BH-T699 | | | | | | | | |
| | | | | | | | | | | | | | | | | | | (L-1)BH-T956 | (L)BH-T699 | | | | | | | | |
| | | | | | | | | | | | | | | | | | | (R-2) | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | (L-2) | | | | | | | | | |
| | | | | | | | | | | | | | | | | | 99.10-00.8 | (R-1)BH-T956 | (R) | | | | | | | | |
| | | | | | | | | | | | | | | | | | | (L-1)BH-T956 | (L) | | | | | | | | |
| | | | | | | | | | | | | | | | | | | (R-2) | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | (L-2) | | | | | | | | | |
| (1600) | E－AE114（4WD） | | 95.5-96.5 | 7/8 | | TK-T360 | 95.5-00.8 | 54.0 | DISC | MP-19 | | 95.5-00.8 | 11/16 | (R)WC-T599 | WK-569 | CUP | 95.5-00.8 | (R)BH-T551 | (R)BH-T545 | 95.5-00.8 | 5/8 | | MK-T244 | 95.5-00.8 | 13/16 | CC-70183 | CK-T201 |
| | ＜GF－は98．4～＞ | | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | (L)WC-T617 | | | | (L)BH-T552 | (L)BH-T545 | | | | | | | | |
| | | | 95.5-96.5 | 7/8 | | TK-T359 | | | | | | | | | | | | | | | | | | | | | |
| | | | 96.5-00.8 | 7/8 | | TK-T360 | | | | | | | | | | | | | | | | | | | | | |
| (2000ディーゼル) | | | 95.5-96.5 | 13/16 | | TK-T357 | 95.5-98.4 | 51.1 | DISC | MP-15 | CPM-15 | 95.5-98.4 | 11/16 | (R)WC-T599 | WK-569 | CUP | 95.5-97.4 | (R)BH-T543 | (R)BH-T648 | 95.5-98.4 | 5/8 | MC-T379 | MK-T244 | 95.5-98.4 | 13/16 | CC-70150 | CK-T201 |
| | KD－CE110 | | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | (L)WC-T617 | | | | (L)BH-T544 | (L)BH-T648 | | | | | | | | |
| | | | 95.5-96.5 | 13/16 | | TK-T358 | | | | | | | | | | | 97.4-98.4 | (R)BH-T543 | (R)BH-T698 | | | | | | | | |
| | | | 96.5-98.4 | 13/16 | | TK-T357 | | | | | | | | | | | | (L)BH-T544 | (L)BH-T698 | | | | | | | | |
| | KD－CE114（4WD） | | 95.5-96.5 | 7/8 | | TK-T360 | 95.5-98.4 | 54.0 | DISC | MP-19 | | 95.5-98.4 | 11/16 | (R)WC-T599 | WK-569 | CUP | 95.5-98.4 | (R)BH-T551 | (R)BH-T545 | 95.5-98.4 | 5/8 | MC-T379 | MK-T244 | 95.5-98.4 | 13/16 | CC-70150 | CK-T201 |
| | | | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | (L)WC-T617 | | | | (L)BH-T552 | (L)BH-T545 | | | | | | | | |
| | | | 95.5-96.5 | 7/8 | | TK-T359 | | | | | | | | | | | | | | | | | | | | | |
| | | | 96.5-98.4 | 7/8 | | TK-T360 | | | | | | | | | | | | | | | | | | | | | |
| (2200ディーゼル) | | | 98.4-00.8 | 13/16 | | TK-T357 | 98.4-00.8 | 51.1 | DISC | MP-15 | CPM-15 | 98.4-00.8 | 11/16 | (R)WC-T599 | WK-569 | CUP | 98.4-00.8 | (R)BH-T543 | (R)BH-T698 | 98.4-00.8 | 5/8 | MC-T379 | MK-T244 | 98.4-00.8 | 13/16 | CC-70150 | CK-T201 |
| | KE－CE113 | | | | | | | | | | | | | (L)WC-T617 | | | | (L)BH-T544 | (L)BH-T698 | | | | | | | | |
| | KE－CE116（4WD） | | 98.4-00.8 | 13/16 | | TK-T360 | 98.4-00.8 | 54.0 | DISC | MP-19 | | 98.4-00.8 | 11/16 | (R)WC-T599 | WK-569 | CUP | 98.4-00.8 | (R)BH-T551 | (R)BH-T545 | 98.4-00.8 | 5/8 | MC-T379 | MK-T244 | 98.4-00.8 | 13/16 | CC-70150 | CK-T201 |
| | | | | | | | | | | | | | | (L)WC-T617 | | | | (L)BH-T552 | (L)BH-T545 | | | | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| COROLLA FIRLDER, CORROLLA RUNX, COROLLA ALEX : 120 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1300) | TA－NZE120<br>＜UA－は02．9～＞<br>＜CBA－は04．4～＞ | <AT><br>00.8-04.4<br>04.4-06.9<br><MT><br>00.8-04.4<br>04.4-06.9 | 13/16<br>13/16<br><br>13/16<br>13/16 | TD-T921<br>TD-T921<br><br>TD-T922<br>TD-T922 | TK-T451<br>TK-T451<br><br>TK-T451<br>TK-T451 | 00.8-06.9 | | DISC | MP-95 | CPM-95 | 00.8-06.9 | 11/16 | (R)WC-T777<br>(L)WC-T778 | WK-935 | CUP | 00.8-06.9 | (R)BH-T946<br>(L)BH-T947 | (R)BH-T948<br>(L)BH-T948 | 00.8-06.9 | 5/8 | MC-T480 | MK-T244 | 00.8-06.9 | 3/4 | CC-T392 | CK-T212 |
| (1500) | TA－NZE121・121G<br>＜UA－は02．9～＞<br>＜CBA－は04．4～＞ | <AT><br>00.8-04.4<br>04.4-06.9<br><MT><br>00.8-04.4<br>04.4-06.9 | 13/16<br>13/16<br><br>13/16<br>13/16 | TD-T921<br>TD-T921<br><br>TD-T922<br>TD-T922 | TK-T451<br>TK-T451<br><br>TK-T451<br>TK-T451 | 00.8-06.9 | | DISC | MP-95 | CPM-95 | 00.8-06.9 | 11/16 | (R)WC-T777<br>(L)WC-T778 | WK-935 | CUP | 00.8-06.9 | (R)BH-T946<br>(L)BH-T947 | (R)BH-T948<br>(L)BH-T948 | 00.8-06.9 | 5/8 | MC-T480 | MK-T244 | 00.8-06.9 | 3/4 | CC-T392 | CK-T212 |
| | TA－NZE124（4WD）<br>TA－NZE124G（4WD）<br>＜UA－は02．9～＞<br>＜CBA－は04．4～＞ | 00.8-04.4<br>04.4-06.9 | 13/16<br>13/16 | TD-T921<br>TD-T921 | TK-T451<br>TK-T451 | 00.8-06.9 | | DISC | MP-102 | CPM-102 | 00.8-06.9 | 3/4 | (R)WC-T780<br>(L)WC-T781 | WK-542 | CUP | 00.8-06.9 | (R)BH-T946<br>(L)BH-T947 | (R)BH-T846<br>(L)BH-T846 | | | (オートマチック) | | | | | |
| (1800) | TA－ZZE122<br>＜UA－は02．9～＞<br>＜CBA－は04．4～＞ | <AT><br>00.8-04.4<br>04.4-06.9<br><MT><br>00.8-04.4<br>04.4-06.9<br><VSC付><br>00.8-06.9 | 13/16<br>13/16<br><br>13/16<br>13/16<br><br>13/16 | TD-T921<br>TD-T921<br><br>TD-T922<br>TD-T922 | TK-T451<br>TK-T451<br><br>TK-T451<br>TK-T451 | 00.8- | | DISC | MP-102 | CPM-102 | <LUXEL><br>00.8-<br><RUNX・ALLEX><br>02.9- | <br><br><br>11/16 | DISC<br><br>(R)WC-T777<br>(L)WC-T778 | SP-294<br><br>WK-935 | <br><br>CUP | 00.8-06.9<br><br><VSC付><br>00.8-06.9 | (R)BH-T946<br>(L)BH-T947<br><br>(R)BH-T946<br>(L)BH-T947 | (R)BH-T948<br>(L)BH-T948<br><br>(R)BH-T949<br>(L)BH-T949 | | | (オートマチック) | | | | |
| | TA－ZZE122G<br>＜UA－は02．9～＞<br>＜CBA－は04．4～＞ | <AT><br>00.8-04.4<br>04.4-06.9<br><MT><br>00.8-04.4<br>04.4-06.9 | 13/16<br>13/16<br><br>13/16<br>13/16 | TD-T921<br>TD-T921<br><br>TD-T922<br>TD-T922 | TK-T451<br>TK-T451<br><br>TK-T451<br>TK-T451 | 00.8-06.9 | | DISC | MP-102 | CPM-102 | 00.8-06.9 | 11/16 | (R)WC-T777<br>(L)WC-T778 | WK-935 | CUP | 00.8-06.9 | (R)BH-T946<br>(L)BH-T947 | (R)BH-T948<br>(L)BH-T948 | 00.8-06.9 | 5/8 | MC-T480 | MK-T244 | 00.8-06.9 | 13/16 | CC-T381 | CK-T230 |
| | TA－ZZE123・123G | <AT><br>00.8-04.4<br>04.4-06.9<br><MT><br>00.8-04.4<br>04.4-06.9 | 13/16<br>13/16<br><br>13/16<br>13/16 | TD-T921<br>TD-T921<br><br>TD-T922<br>TD-T922 | TK-T451<br>TK-T451<br><br>TK-T451<br>TK-T451 | 00.8-06.9 | | DISC | MP-103 | CPM-68 | 00.8-06.9 | | DISC | SP-106 | CPS-106 | 00.8-06.9 | (R)BH-T946<br>(L)BH-T947 | (R)BH-T949<br>(L)BH-T949 | 00.8-06.9 | 5/8 | MC-T480 | MK-T244 | 00.8-06.9 | 13/16 | CC-T381 | CK-T230 |
| | TA－ZZE124（4WD）<br>TA－ZZE124G（4WD）<br>＜UA－は02．9～＞<br>＜CBA－は04．4～＞ | 00.8-<br>04.4-06.9 | 13/16<br>13/16 | TD-T921<br>TD-T922 | TK-T451<br>TK-T451 | 00.8- | | DISC | MP-102 | CPM-102 | 00.8- | 3/4 | (R)WC-T780<br>(L)WC-T781 | WK-542 | CUP | 00.8- | (R)BH-T946<br>(L)BH-T947 | (R)BH-T846<br>(L)BH-T846 | | | (オートマチック) | | | | | |
| (2200ディーゼル) | KE－CE121・121G | <AT><br>00.8-04.4<br><MT><br>00.8-04.4 | 13/16<br><br>13/16 | TD-T921<br><br>TD-T922 | TK-T451<br><br>TK-T451 | 00.8- | | DISC | MP-102 | CPM-102 | 00.8- | 11/16 | (R)WC-T777<br>(L)WC-T778 | WK-935 | CUP | 00.8- | (R)BH-T946<br>(L)BH-T947 | (R)BH-T948<br>(L)BH-T948 | 00.8- | 5/8 | | MK-T244 | 00.8- | 13/16 | CC-70150 | CK-T201 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| COROLLA AXIO, COROLLA FIELDER : 140 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1500) | DBA－NZE141 | G | 06.10-12.4 | | | キットセッテイナシ | 06.10-08.10<br>08.10-12.4 | <br>54 | DISC<br>DISC | MP-116<br>MP-110 | CPM-116 | 06.10-12.4 | 7/8 | (R)WC-T796<br>(L)WC-T796 | WK-1051 | CUP | 06.10-12.4 | (R)<br>(L) | (R)<br>(L) | 06.10-12.4 | 5/8 | MC-T477 | キットセッテイナシ | 06.10-12.4 | 3/4 | CC-T392 | CK-T212 |
| | | X | 06.10-12.4 | | | キットセッテイナシ | <ターボ車><br>09.2-12.4<br><除くターボ車><br>06.10-12.4 | <br><br><br>54 | DISC<br><br>DISC | MP-116<br><br>MP-110 | CPM-116 | <ターボ車><br>09.2-12.4<br><br><除くターボ車><br>06.10-12.4 | 7/8<br><br><br>13/16 | (R)WC-T796<br>(L)WC-T796<br><br>(R)WC-T797<br>(L)WC-T798 | WK-1051<br><br>WK-999 | CUP<br><br>CUP | 06.10-12.4<br><br>06.10-12.4 | (R)<br>(L)<br><br>(R)<br>(L) | (R)<br>(L)<br><br>(R)<br>(L) | 06.10-12.4 | 5/8 | MC-T477 | キットセッテイナシ | 06.10-12.4 | 3/4 | CC-T392 | CK-T212 |
| | DBA－NZE141G | | 06.10-12.4 | | | キットセッテイナシ | 06.10-12.4 | | DISC | MP-116 | CPM-116 | 06.10-12.4 | 7/8 | (R)WC-T796<br>(L)WC-T796 | WK-1051 | CUP | 06.10-12.4 | (R)<br>(L) | (R)<br>(L) | 06.10-12.4 | 5/8 | MC-T477 | キットセッテイナシ | 06.10-12.4 | 3/4 | CC-T392 | CK-T212 |
| | DBA－NZE144 | 4WD | 06.10-12.4 | | | キットセッテイナシ | 06.10-12.4 | | DISC | MP-116 | CPM-116 | 06.10-12.4 | 7/8 | (R)WC-T796<br>(L)WC-T796 | WK-1051 | CUP | 06.10-12.4 | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| | DBA－NZE144G | 4WD | 06.10-12.4 | | | キットセッテイナシ | 06.10-12.4 | | DISC | MP-116 | CPM-116 | 06.10-12.4 | 7/8 | (R)WC-T796<br>(L)WC-T796 | WK-1051 | CUP | 06.10-12.4 | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| (1800) | DBA－ZRE142<br>DBA－ZRE142G | | 06.10-12.2<br>12.3-12.4<br><VSC,TRC,ブリクラッシュセーフティシステム付><br>06.10-12.4 | | | キットセッテイナシ<br>キットセッテイナシ | 06.10-12.4 | | DISC | MP-116 | CPM-116 | 06.10-12.4 | 7/8 | (R)WC-T796<br>(L)WC-T796 | WK-1051 | CUP | 06.10-12.4 | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| | DBA－ZRE144 | 4WD | 06.10-12.4 | | | キットセッテイナシ | 06.10-12.4 | | DISC | MP-116 | CPM-116 | 06.10-12.4 | 7/8 | (R)WC-T796<br>(L)WC-T796 | WK-1051 | CUP | 06.10-12.4 | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| | DBA－ZRE144G | 4WD | 06.10-12.4 | | | キットセッテイナシ | 06.10-12.4 | | DISC | MP-116 | CPM-116 | 06.10-12.4 | 7/8 | (R)WC-T796<br>(L)WC-T796 | WK-1051 | CUP | 06.10-12.4 | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| COROLLA AXIO, COROLLA FIELDER : 160 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1300) | DBA－NRE160 | 4ドア | 12.4- | | | キットセッテイナシ | 12.4-15.3<br>15.3- | 54 | DISC<br>DISC | MP-110<br>MP-136 | | 12.4- | 3/4 | (R)WC-T780<br>(L)WC-T781 | WK-542 | CUP | 12.4-14.8<br><br>14.8- | (R)<br>(L)<br>(R)<br>(L) | (R)BH-T956<br>(L)BH-T957<br>(R)<br>(L) | | | (オートマチック) | | | | | |
| (1500) | DBA－NRE161 | 4ドア | 12.4- | | | キットセッテイナシ | 15.3- | | DISC | MP-136 | | 15.3- | 3/4 | (R)WC-T780<br>(L)WC-T781 | WK-542 | CUP | 15.3- | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| | DBA－NRE161G | 5ドア | 15.3- | 7/8 | TD-T936 | キットセッテイナシ | 15.3-17.10<br>17.10- | | DISC<br>DISC | MP-111<br>MP-136 | | 15.3- | 13/16 | (R)WC-T787<br>(L)WC-T787 | WK-900 | CUP | 15.3- | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| | DBA－NZE161 | 4ドア | 12.4- | | | キットセッテイナシ | 12.4-15.3<br>15.3- | 54 | DISC<br>DISC | MP-110<br>MP-136 | | 12.4- | 3/4 | (R)WC-T780<br>(L)WC-T781 | WK-542 | CUP | 12.4-14.8<br><br>14.8- | (R)<br>(L)<br>(R)<br>(L) | (R)BH-T956<br>(L)BH-T957<br>(R)<br>(L) | 12.4- | 5/8 | MC-T485 | キットセッテイナシ | 12.4- | 13/16 | CC-T399 | CK-T232 |
| | | 4ドア<br>教習車 | 18.2- | | | キットセッテイナシ | 18.2- | | DISC | MP-136 | | 18.2- | 3/4 | (R)WC-T780<br>(L)WC-T781 | WK-542 | CUP | 18.2- | (R)<br>(L) | (R)<br>(L) | 18.2- | 5/8 | MC-T485 | キットセッテイナシ | 18.2- | 13/16 | CC-T399 | CK-T232 |
| | DBA－NZE161G | 5ドア | 12.4-12.5<br>12.5- | 7/8 | TD-T936 | キットセッテイナシ<br>キットセッテイナシ | 12.4- | | DISC | MP-111 | | 12.4- | 13/16 | (R)WC-T787<br>(L)WC-T787 | WK-900 | CUP | 12.4-14.8<br><br>14.8- | (R)<br>(L)<br>(R)<br>(L) | (R)BH-T956<br>(L)BH-T957<br>(R)<br>(L) | 12.4- | 5/8 | MC-T485 | キットセッテイナシ | 12.4- | 13/16 | CC-T399 | CK-T232 |
| | DBA－NZE164<br>DBA－NZE164G | | 12.4-12.5<br>12.5- | 7/8 | TD-T936 | キットセッテイナシ<br>キットセッテイナシ | 12.4- | | DISC | MP-111 | | 12.4- | 13/16 | (R)WC-T787<br>(L)WC-T787 | WK-900 | CUP | 12.4- | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| | DAA－NKE165<br>DAA－NKE165G | ハイブリット | 12.4- | | | キットセッテイナシ | 12.4-17.6<br>17.6- | 54 | DISC<br>DISC | MP-110<br>MP-136 | | 12.4- | 13/16 | (R)WC-T787<br>(L)WC-T787 | WK-900 | CUP | 12.4-14.8<br><br>14.8- | (R)<br>(L)<br>(R)<br>(L) | (R)BH-T956<br>(L)BH-T957<br>(R)<br>(L) | | | (オートマチック) | | | | | |
| (1800) | DBA－ZRE162 | | 12.4-12.5<br>12.5- | | | キットセッテイナシ<br>キットセッテイナシ | 12.4- | | DISC | MP-111 | | 12.4- | 13/16 | (R)WC-T787<br>(L)WC-T787 | WK-900 | CUP | 12.4-14.8<br><br>14.8- | (R)<br>(L)<br>(R)<br>(L) | (R)BH-T956<br>(L)BH-T957<br>(R)<br>(L) | | | (オートマチック) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| COROLLA RUMION : 150 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1500) | DBA－NZE151N | | 07.10-15.12 | | | | 07.10-15.12 | | DISC | MP-116 | CPM-116 | 07.10-15.12 | | DISC | TP-111 | | 07.10-15.12 | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| (1800) | DBA－ZRE152N | | 07.10-15.12 | | | | 07.10-15.12 | | DISC | MP-116 | CPM-116 | 07.10-15.12 | | DISC | TP-111 | | 07.10-15.12 | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| | DBA－ZRE154N | 4WD | 07.10-15.12 | | | | 07.10-15.12 | | DISC | MP-114 | CPM-106 | 07.10-15.12 | | DISC | TP-111 | | 07.10-15.12 | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| COROLLA, COROLLA TOURING : 210 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1200) | 3BA－NRE210<br>3BA－NRE210W | AT | 19.8- | 7/8 | TD-T945 | ｷｯﾄｾｯﾃｲﾅｼ | 19.8- | | DISC | | | 19.8- | | DISC | SP-502 | | 19.8- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | | MT | 19.8- | 7/8 | TD-T945 | ｷｯﾄｾｯﾃｲﾅｼ | 19.8- | | DISC | | | 19.8- | | DISC | SP-502 | | 19.8- | (R)<br>(L) | (R)<br>(L) | 19.8- | | | ｷｯﾄﾅｼ | | 19.8- | | ｷｯﾄﾅｼ |
| | 5BA－MZEA17<br>5BA－MZEA17W | | 22.10- | 7/8 | TD-T944 | ｷｯﾄｾｯﾃｲﾅｼ | 22.10- | | DISC | | | 22.10- | | DISC | SP-502 | | 22.10- | (R)<br>(L) | (R)<br>(L) | | | | | | | | |
| (1800) | 3BA－ZRE212<br>3BA－ZRE212W | | 19.8- | 7/8 | TD-T944 | ｷｯﾄｾｯﾃｲﾅｼ | 19.8- | | DISC | | | <電動ﾊﾟｰｷﾝｸﾞﾌﾞﾚｰｷ><br>19.8-<br><除く電動ﾊｰｷﾝｸﾞﾌﾞﾚｰｷ><br>19.8- | | DISC<br>DISC | SP-502<br><br>TP-111 | | <電動ﾊﾟｰｷﾝｸﾞﾌﾞﾚｰｷ><br>19.8-<br><除く電動ﾊｰｷﾝｸﾞﾌﾞﾚｰｷ><br>19.8- | (R)<br>(L) | (R)<br>(L)<br>(R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | 6AA－ZWE211<br>6AA－ZWE214 | | <ﾊｲﾌﾞﾘｯﾄﾞG-X,ﾊｲﾌﾞﾘｯﾄﾞS<除く17ｲﾝﾁﾌﾞﾗｯｸｱﾙﾐ>><br>19.8-<br><ﾊｲﾌﾞﾘｯﾄﾞWxB,ﾊｲﾌﾞﾘｯﾄﾞS<17ｲﾝﾁﾌﾞﾗｯｸｱﾙﾐ>><br>19.8- | | | ｷｯﾄｾｯﾃｲﾅｼ<br>ｷｯﾄｾｯﾃｲﾅｼ | 19.8- | | DISC | | | 19.8- | | DISC | SP-502 | | 19.8- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | 6AA－ZWE211W<br>6AA－ZWE214W | | <ﾊｲﾌﾞﾘｯﾄﾞG-X,ﾊｲﾌﾞﾘｯﾄﾞS<除く17ｲﾝﾁﾌﾞﾗｯｸｱﾙﾐ>><br>19.8-<br><ﾊｲﾌﾞﾘｯﾄﾞWxB,ﾊｲﾌﾞﾘｯﾄﾞS<17ｲﾝﾁﾌﾞﾗｯｸｱﾙﾐ>><br>19.8- | | | ｷｯﾄｾｯﾃｲﾅｼ<br>ｷｯﾄｾｯﾃｲﾅｼ | 19.8- | | DISC | | | 19.8- | | DISC | SP-502 | | 19.8- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | 6AA－ZWE215<br>6AA－ZWE215W | 4WD<br>ﾊｲﾌﾞﾘｯﾄﾞ | 22.10- | | | | 22.10- | | DISC | | | 22.10- | | DISC | SP-502 | | 22.10- | (R)<br>(L) | (R)<br>(L) | | | | | | | | |
| | 6AA－ZWE219<br>6AA－ZWE219W | 2WD<br>ﾊｲﾌﾞﾘｯﾄﾞ | 22.10- | | | | 22.10- | | DISC | | | 22.10- | | DISC | SP-502 | | 22.10- | (R)<br>(L) | (R)<br>(L) | | | | | | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| COROLLA SPACIO : AE111N, 115N | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1600) E－AE111N | 97.1-99.4 | 7/8 | | TK-T360 | 97.1-01.5 | 54.0 | DISC | MP-19 | CPM-19 | 97.1-01.5 | 11/16 | (R)WC-T599 | WK-569 | CUP | 97.1-01.5 | (R)BH-T543 | (R)BH-T698 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| ＜GF－は98．4～＞ | 99.4-01.5 | 7/8 | | TK-T359 | | | | | | | | (L)WC-T617 | | | | (L)BH-T544 | (L)BH-T698 | | | | | | | | |
| (1800) E－AE115N(4WD) | 97.1-99.4 | 7/8 | | TK-T360 | 97.1-01.5 | 54.0 | DISC | MP-19 | CPM-19 | 97.1-01.5 | 3/4 | (R)WC-T600 | WK-542 | CUP | 97.1-01.5 | (R)BH-T551 | (R)BH-T545 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| ＜GF－は98．4～＞ | 99.4-01.5 | 7/8 | | TK-T359 | | | | | | | | (L)WC-T605 | | | | (L)BH-T552 | (L)BH-T545 | | | | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| COROLLA SPACIO : 120 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1500) | TA－NZE121N<br>＜UA－は03．4～＞ | 7人乗り | 01.5-07.6 | 13/16 | | TK-T451 | 01.5-07.6 | | DISC | MP-102 | | 01.5-07.6 | 3/4 | (R)WC-T785<br>(L)WC-T785 | WK-899 | CUP | 01.5-07.6 | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| | | 5人乗り | 01.5-03.4 | 13/16 | | TK-T451 | 01.5-03.4 | | DISC | MP-95 | | 01.5-03.4 | 11/16 | (R)WC-T777<br>(L)WC-T778 | WK-935 | CUP | 01.5-03.4 | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| (1800) | TA－ZZE122N<br>＜UA－は03．4～＞ | | 01.5-07.6 | 13/16 | | TK-T451 | 01.5-07.6 | | DISC | MP-102 | | 01.5-07.6 | 3/4 | (R)WC-T785<br>(L)WC-T785 | WK-899 | CUP | 01.5-07.6 | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| | TA－ZZE124N(4WD)<br>＜UA－は03．4～＞ | | 01.8-07.6 | 13/16 | | TK-T451 | 01.8-07.6 | | DISC | MP-102 | | 01.8-07.6 | 3/4 | (R)WC-T785<br>(L)WC-T785 | WK-899 | CUP | 01.8-07.6 | (R)<br>(L) | (R)BH-T846<br>(L)BH-T846 | | | (オートマチック) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| COROLLA SPORT : 210 ser.(2018.6-) | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1200) | 3BA-NRE210H | AT | 18.6- | 7/8 | TD-T944 | ｷｯﾄｾｯﾃｲﾅｼ | 18.6- | | DISC | | | 18.6- | | DISC | | | 18.6- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | | MT | 18.8- | 7/8 | TD-T945 | ｷｯﾄｾｯﾃｲﾅｼ | 18.8- | | DISC | | | 18.8- | | DISC | | | 18.8- | (R)<br>(L) | (R)<br>(L) | 18.8- | | | ｷｯﾄﾅｼ | 18.8- | | | ｷｯﾄﾅｼ |
| | 3BA-NRE214H | 4WD | 18.6- | 7/8 | TD-T944 | ｷｯﾄｾｯﾃｲﾅｼ | 18.6- | | DISC | | | 18.6- | | DISC | | | | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (1800) | 6AA-ZWE211H | | 18.6- | | | ｷｯﾄｾｯﾃｲﾅｼ | 18.6- | | DISC | | | 18.6- | | DISC | | | | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | 6AA-ZWE219H | 2WD<br>ﾊｲﾌﾞﾘｯﾄﾞ | 22.10- | | | | 22.10- | | DISC | | | 22.10- | | DISC | SP-502 | | 22.10- | (R)<br>(L) | (R)<br>(L) | | | (電気式無段変速機) | | | | | |
| (2000) | 6BA-MZEA12H | ｶﾞｿﾘﾝ2WD | 22.10- | 7/8 | TD-T944 | ｷｯﾄｾｯﾃｲﾅｼ | 22.10- | | DISC | | | 22.10- | | DISC | SP-502 | | 22.10- | (R)<br>(L) | (R)<br>(L) | | | | | | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| WILL VI : (00.1-01.12) | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1300) GH－NCP19 <TA－は00. 8～> | 00.1-01.12 | 13/16 | | TK-T429 | 00.1-01.12 | | DISC | MP-90 | CPM-90 | 00.1-01.12 | 11/16 | (R)WC-T777<br>(L)WC-T778 | WK-935 | CUP | 00.1-01.12 | (R)BH-T771<br>(L)BH-T772 | (R)BH-T941<br>(L)BH-T941 | | | (オートマチック) | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| WILL VS : 120 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1500) | TA－NZE127<br>UA－NZE127<br>＜UA－は02. 10～＞ | 02.1-04.4 | 13/16 | TD-T921 | | 02.1-04.4 | | DISC | MP-102 | CPM-102 | 02.1-04.4 | 11/16 | (R)WC-T777<br>(L)WC-T778 | WK-935 | CUP | 02.1-04.4 | (R)BH-T946<br>(L)BH-T947 | (R)BH-T948<br>(L)BH-T948 | | | | | | | | |
| (1800) | TA－ZZE127 | 01.4-04.4 | 13/16 | TD-T921 | | 01.4-04.4 | | DISC | MP-102 | CPM-102 | 01.4-04.4 | | DISC | SP-294 | | 01.4-04.4 | (R)BH-T946<br>(L)BH-T947 | (R)BH-T949<br>(L)BH-T949 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | TA－ZZE128 | ＜AT＞<br>01.4-04.4<br>＜MT＞<br>01.4-04.4 | 13/16<br>13/16 | TD-T921<br>TD-T922 | | 01.4-04.4 | | DISC | MP-103 | CPM-68 | 01.4-04.4 | | DISC | SP-106 | CPS-106 | 01.4-04.4 | (R)BH-T946<br>(L)BH-T947 | (R)BH-T949<br>(L)BH-T949 | 01.4-02.1<br>02.1-04.4 | 5/8 | (ｵｰﾄﾏﾁｯｸ)<br>MC-T480 | MK-T244 | 02.1-04.4 | 13/16 | CC-T381 | CK-T230 |
| | TA－ZZE129(4WD) | 01.4-04.4 | 13/16 | TD-T921 | | 01.4-04.4 | | DISC | MP-102 | CPM-102 | 01.4-04.4 | 3/4 | (R)WC-T780<br>(L)WC-T781 | WK-542 | CUP | 01.4-04.4 | (R)BH-T946<br>(L)BH-T947 | (R)BH-T846<br>(L)BH-T846 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| WILL CYPHA : 70 ser.(02.9-) | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1300) UA－NCP70<br>＜CBA－は04．2～＞ | 02.9-03.5<br>03.5-05.7 | 13/16 | | | 02.9-05.7 | | DISC | MP-90 | CPM-90 | 02.9-05.7 | 11/16 | (R)WC-T777<br>(L)WC-T778 | WK-935 | CUP | 02.9-02.12<br>02.12-05.7 | (R)BH-T771<br>(L)BH-T772<br>(R)BH-T778<br>(L)BH-T779 | (R)BH-T941<br>(L)BH-T941<br>(R)BH-T941<br>(L)BH-T941 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (1500) UA－NCP75(4WD)<br>＜CBA－は04．2～＞ | 02.9-03.5<br>03.5-05.7 | 13/16 | | | 02.9-05.7 | | DISC | MP-90 | CPM-90 | 02.9-05.7 | 11/16 | (R)WC-T777<br>(L)WC-T778 | WK-935 | CUP | 02.9-05.7 | (R)BH-T780<br>(L)BH-T781 | (R)BH-T782<br>(L)BH-T783 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| SIENTA : 80 ser.(03.9-) | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1500) UA－NCP81G<br>＜CBA－は04．2～＞<br>＜DBA－は05．8～＞ | 03.9-15.6 | | | キットセッテイナシ | 03.9-04.10<br>04.10-15.6 | | DISC<br>DISC | MP-102<br>MP-102 | CPM-102<br>CPM-102 | 03.9-15.6 | 13/16 | (R)WC-T787<br>(L)WC-T787 | WK-900 | CUP | 03.9-06.11<br><br>06.11-15.6 | (R)BH-T778<br>(L)BH-T779<br>(R)BH-T778<br>(L)BH-T779 | (R)BH-T948<br>(L)BH-T948<br>(R)<br>(L) | | | (オートマチック) | | | | | |
| UA－NCP85G(4WD)<br>＜CBA－は04．2～＞<br>＜DBA－は11．6～＞ | 03.9-15.6 | | | キットセッテイナシ | 03.9-04.10<br>04.10-15.6 | | DISC<br>DISC | MP-102<br>MP-102 | CPM-102<br>CPM-102 | 03.9-15.6 | 13/16 | (R)WC-T787<br>(L)WC-T787 | WK-900 | CUP | 03.9-06.9<br><br>06.9-15.6 | (R)BH-T780<br>(L)BH-T781<br>(R)BH-T780<br>(L)BH-T781 | (R)BH-T846<br>(L)BH-T846<br>(R)<br>(L) | | | (オートマチック) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| SIENTA : 170 ser.(15.6-) | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | DBA－NCP175G(4WD) | | 15.6- | | | ｷｯﾄｾｯﾃｲﾅｼ | 15.6- | | DISC | MP-116 | CPM-116 | 15.6- | | DISC | SP-483 | | 15.6- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | DAA－NHP170G | ハイブリッド | 15.6- | | | | 15.6- | | DISC | MP-116 | CPM-116 | 15.6- | | DISC | SP-483 | | 15.6- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | DBA－NSP170G | | 15.6- | | | ｷｯﾄｾｯﾃｲﾅｼ | 15.6- | | DISC | MP-116 | CPM-116 | 15.6- | | DISC | SP-483 | | 15.6- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | DBA－NSP172G | 車いす仕様車 | 15.6- | | | ｷｯﾄｾｯﾃｲﾅｼ | 15.6- | | DISC | MP-116 | CPM-116 | 15.6- | | DISC | SP-483 | | 15.6- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| SIENTA : 10 ser.(22.4-) | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1500) | 6AA-MXPL10G(2WD) | ハイブリット | 22.4- | | | ｷｯﾄｾｯﾃｲﾅｼ | 22.4- | | DISC | MP-136 | | 22.4- | | DISC | SP-483 | | 22.4- | | | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | 6AA-MXPL15G(4WD) E-Fou | 電気自動車 | 22.4- | | | ｷｯﾄｾｯﾃｲﾅｼ | 22.4- | | DISC | MP-136 | | 22.4- | | DISC | SP-483 | | 22.4- | | | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | 5BA-MXPC10G | ガソリン車 | 22.4- | 7/8 | TD-T942 | ｷｯﾄｾｯﾃｲﾅｼ | 22.4- | | DISC | MP-136 | | 22.4- | | DISC | SP-483 | | 22.4- | | | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| STARLET : 50, 60 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1200) | B－KP51 | ドラム車 | 76.1-78.1 | 11/16 | (ブースター付) | | 76.1-78.1 | 7/8 | (R-1)WC-2036 | WK-054 | CUP | 76.1-77.2 | 3/4 | (R)WC-50060 | WK-491 | CUP | 76.1-78.1 | BH-02202 | BH-02204 | | | (ワイヤー式) | | | | | |
| | | | 76.1-78.1 | 11/16 | (ブースター無) | TK-9319 | | | (R-2)WC-1046 | | | | | (L)WC-50060 | | | | | | | | | | | | | |
| | | | | | | | | | (L-1)WC-4036 | | | 77.2-78.1 | 3/4 | (R)WC-50052 | WK-491 | CUP | | | | | | | | | | | |
| | | | | | | | | | (L-2)WC-3046 | | | | | (L)WC-50052 | | | | | | | | | | | | | |
| | | ディスク車 | 76.1-78.1 | 11/16 | (ブースター付) | | 76.1-78.1 | 1 7/8 | DISC | MP-2 | | 76.1-77.2 | 13/16 | (R)WC-50059 | WK-492 | CUP | 76.1-78.1 | (1)BH-02203 | BH-02204 | | | (ワイヤー式) | | | | | |
| | | | 76.1-78.1 | 11/16 | (ブースター無) | TK-9319 | | | | | | | | (L)WC-50059 | | | | (2)BH-02201 | | | | | | | | | |
| | | | | | | | | | | | | 77.2-78.1 | 13/16 | (R)WC-50053 | WK-492 | CUP | | | | | | | | | | | |
| | | | | | | | | | | | | | | (L)WC-50053 | | | | | | | | | | | | | |
| | J－KP62V(バン) | | 78.10-82.1 | 11/16 | (ブースター無) | TK-9384 | 78.10-82.1 | 48.1 | DISC | MP-5 | | 78.10-82.1 | 13/16 | (R)WC-50056 | WK-543 | CUP | 78.2-80.5 | (1)BH-02362 | BH-31324 | | | (ワイヤー式) | | | | | |
| | | | 78.10-82.1 | 3/4 | (ブースター付) | TK-9411 | | | | | | | | (L)WC-50056 | | | | (2)BH-02201 | | | | | | | | | |
| | | | | | | | | | | | | | | | | | 80.5-82.1 | BH-02414 | BH-31324 | | | | | | | | |
| (1300) | E－KP61 | STD・DX－A | 78.2-84.9 | 11/16 | (ブースター無) | TK-9384 | 78.2-84.9 | 48.1 | | MP-5 | | 78.2-84.9 | 3/4 | (R)WC-50055 | WK-542 | CUP | 78.2-80.5 | (1)BH-02362 | BH-31324 | | | (ワイヤー式) | | | | | |
| | | | 78.2-81.8 | 3/4 | (ブースター付) | TK-9411 | <5速フロア・DX-A> | | | | | | | (L)WC-50055 | | | | (2)BH-02201 | | | | | | | | | |
| | | | | | | | 82.8-84.9 | 48.1 | DISC | MP-14 | | | | | | | 80.5-84.9 | BH-02414 | BH-31324 | | | | | | | | |
| | | DX・XL | 78.2-80.5 | 11/16 | (ブースター無) | TK-9384 | 78.2-84.9 | 48.1 | DISC | MP-5 | | 78.2-84.9 | 3/4 | (R)WC-50055 | WK-542 | CUP | 78.2-80.5 | (1)BH-02362 | BH-31324 | | | (ワイヤー式) | | | | | |
| | | S・SE・SI | 78.2-84.9 | 3/4 | (ブースター付) | TK-9411 | <オートマチック・S仕様> | | | | | | | (L)WC-50055 | | | | (2)BH-02201 | | | | | | | | | |
| | | | | | | | 82.8-84.9 | 48.1 | DISC | MP-14 | | | | | | | 80.5-84.9 | BH-02414 | BH-31324 | | | | | | | | |
| | L－KP61V(バン) | | 82.1-84.9 | 11/16 | (ブースター無) | TK-9384 | 82.1-84.9 | 48.1 | DISC | MP-5 | | 82.1-84.9 | 13/16 | (R)WC-50056 | WK-543 | CUP | 82.1-84.9 | BH-02414 | BH-31324 | | | (ワイヤー式) | | | | | |
| | | | 82.1-84.9 | 3/4 | (ブースター付) | TK-9411 | | | | | | | | (L)WC-50056 | | | | | | | | | | | | | |

| Models | TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| STARLET : 70 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1300) | E－EP71<br>L－EP76V(バン) | 84.10-89.12<br>84.10-89.12 | 3/4<br>11/16 | (ﾌﾞｰｽﾀｰ付)<br>(ﾌﾞｰｽﾀｰ無) | TK-T007<br>TK-T008 | 84.10-89.12 | 48.1 | DISC | MP-14 | | 84.10-89.12 | 11/16 | (R)WC-55020<br>(L)WC-57020 | WK-569 | CUP | 84.10-86.9<br><br>86.9-89.12<br><br><ﾀｰﾎﾞ車><br>86.1-86.9<br><br>86.9-87.12 | BH-02461<br><br>(R)BH-02511<br>(L)BH-02512<br><br>BH-02461<br><br>(R)BH-02511<br>(L)BH-02512 | (R)BH-95009<br>(L)BH-95009<br>(R)BH-95009<br>(L)BH-95009<br><br>(R)BH-95009<br>(L)BH-95009<br>(R)BH-95009<br>(L)BH-95009 | 84.10-86.9<br>86.9-89.12 | 5/8<br>5/8 | | MK-4326<br>MK-4353 | 84.10-89.12<br><3ﾄﾞｱ4速ﾌﾛｱDX><br>84.10-85.12<br>85.12-89.12<br><ﾀｰﾎﾞ車><br>86.1-89.12 | 13/16<br><br>13/16<br>3/4<br><br>3/4 | CC-70179<br><br>CC-70179 | CK-3144<br><br>CK-3144<br>CK-T218<br><br>CK-T218 |
| (1500ディーゼル) | N－NP70<br>Q－NP70<br>N－NP76V(バン) | 86.12-89.12 | 3/4 | | TK-T007 | 86.12-89.12 | 48.1 | DISC | MP-14 | | 86.12-89.12 | 11/16 | (R)WC-55020<br>(L)WC-57020 | WK-569 | CUP | 86.12-89.12 | (R)BH-02511<br>(L)BH-02512 | (R)BH-95009<br>(L)BH-95009 | 86.12-89.12 | 5/8 | | MK-4337 | 86.12-89.12 | 3/4 | | CK-T218 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| STARLET : 80 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1300) | E−EP82 | 除くGTターボ | 89.12-94.9 | 3/4 | | TK-T318 | 89.12-96.1 | | DISC | MP-36 | | 89.12-96.1 | 11/16 | (R)WC-55020 | WK-569 | CUP | 89.12-92.1 | (R)BH-T660 | (R)BH-T956 | 89.12-92.2 | 5/8 | MC-T374 | MK-T236 | 89.12-96.1 | 3/4 | CC-70179 | CK-T222 |
| | | | 94.9-96.1 | 3/4 | | TK-T356 | <アンチスキッド付> | | | | | | | (L)WC-57020 | | | | (L)BH-T661 | (L)BH-T956 | 92.2-94.3 | 5/8 | MC-T374 | | | | | |
| | | | <アンチスキッド付> | | | | 89.12-96.1 | 51.1 | DISC | MP-15 | CPM-15 | | | | | | 92.1-94.5 | (R)BH-T529 | (R)BH-T956 | 94.3-96.1 | 5/8 | MC-T374 | MK-T244 | | | | |
| | | | 89.12-94.9 | 13/16 | | TK-T319 | | | | | | | | | | | | (L)BH-T530 | (L)BH-T956 | | | | | | | | |
| | | | 94.9-96.1 | 13/16 | | TK-T379 | | | | | | | | | | | 94.5-96.1 | (R)BH-T660 | (R)BH-T956 | | | | | | | | |
| | | | | | | | | | | | | | | | | | | (L)BH-T661 | (L)BH-T956 | | | | | | | | |
| | | GTターボ | 89.12-90.5 | 13/16 | | TK-T023 | 89.12-96.1 | 51.1 | DISC | MP-15 | CPM-15 | 89.12-96.1 | 30.2 | DISC | MP-23 | | 89.12-92.1 | (R)BH-T660 | (R-1)BH-T956 | 89.12-92.2 | 5/8 | MC-T374 | MK-T236 | 89.12-96.1 | 3/4 | CC-70179 | CK-T222 |
| | | 四輪ディスク車 | 90.5-92.1 | 13/16 | | TK-T023 | | | | | | | | | | | | (L)BH-T661 | (L-1)BH-T956 | 92.2-94.3 | 5/8 | MC-T374 | | | | | |
| | | | 92.1-94.9 | 7/8 | | TK-T402 | | | | | | | | | | | | | (R-2)BH-T558 | 94.3-96.1 | 5/8 | MC-T374 | MK-T244 | | | | |
| | | | 94.9-96.1 | 7/8 | | TK-T402 | | | | | | | | | | | | | (L-2)BH-T558 | | | | | | | | |
| | | | <アンチスキッド付> | | | | | | | | | | | | | | 92.1-94.5 | (R)BH-T529 | (R-1)BH-T956 | | | | | | | | |
| | | | 89.12-94.9 | 7/8 | | TK-T320 | | | | | | | | | | | | (L)BH-T530 | (L-1)BH-T956 | | | | | | | | |
| | | | 94.9-96.1 | 7/8 | | TK-T363 | | | | | | | | | | | | | (R-2)BH-T558 | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | (L-2)BH-T558 | | | | | | | | |
| | | | | | | | | | | | | | | | | | 94.5-96.1 | (R)BH-T660 | (R-1)BH-T956 | | | | | | | | |
| | | | | | | | | | | | | | | | | | | (L)BH-T661 | (L-1)BH-T956 | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | (R-2)BH-T558 | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | (L-2)BH-T558 | | | | | | | | |
| | E−EP85(4WD) | | 90.8-94.9 | 13/16 | | TK-T023 | 90.8-96.1 | 48.1 | DISC | MP-45 | | 90.8-96.1 | 11/16 | (R)WC-T639 | WK-569 | CUP | 90.8-92.1 | (R)BH-T660 | (R)BH-T656 | 90.8-92.2 | 5/8 | MC-T374 | MK-T236 | 89.12-96.1 | 3/4 | CC-70179 | CK-T222 |
| | | | 94.9-96.1 | 13/16 | | TK-T023 | <アンチスキッド付> | | | | | | | (L)WC-T639 | | | | (L)BH-T661 | (L)BH-T532 | 92.2-94.3 | 5/8 | MC-T374 | | | | | |
| | | | <アンチスキッド付> | | | | 90.8-96.1 | 51.1 | DISC | MP-15 | CPM-15 | | | | | | 92.1-94.5 | (R)BH-T529 | (R)BH-T656 | 94.3-96.1 | 5/8 | MC-T374 | MK-T244 | | | | |
| | | | 90.8-94.9 | 7/8 | | TK-T320 | | | | | | | | | | | | (L)BH-T530 | (L)BH-T532 | | | | | | | | |
| | | | 94.9-96.1 | 7/8 | | TK-T363 | | | | | | | | | | | 94.5-96.1 | (R)BH-T660 | (R)BH-T656 | | | | | | | | |
| | | | | | | | | | | | | | | | | | | (L)BH-T661 | (L)BH-T532 | | | | | | | | |
| (1500ディーゼル) | | | 89.12-94.9 | 3/4 | | TK-T318 | 89.12-95.9 | | DISC | MP-36 | | 89.12-95.9 | 11/16 | (R)WC-55020 | WK-569 | CUP | 89.12-92.1 | (R)BH-T660 | (R)BH-T956 | 89.12-92.2 | 5/8 | MC-T374 | MK-T236 | 89.12-95.9 | 3/4 | | CK-T222 |
| | Q−NP80 | | 94.9-95.9 | 3/4 | | TK-T356 | <アンチスキッド付> | | | | | | | (L)WC-57020 | | | | (L)BH-T661 | (L)BH-T956 | 92.2-94.3 | 5/8 | MC-T374 | | | | | |
| | X−NP80 | | <アンチスキッド付> | | | | 92.1-95.9 | 51.1 | DISC | MP-15 | CPM-15 | | | | | | 92.1-94.5 | (R)BH-T529 | (R)BH-T956 | 94.3-95.9 | 5/8 | MC-T374 | MK-T244 | | | | |
| | <X−は92. 1〜> | | 92.1-94.9 | 13/16 | | TK-T319 | | | | | | | | | | | | (L)BH-T530 | (L)BH-T956 | | | | | | | | |
| | | | 94.9-95.9 | 13/16 | | TK-T379 | | | | | | | | | | | 94.5-95.9 | (R)BH-T660 | (R)BH-T956 | | | | | | | | |
| | | | | | | | | | | | | | | | | | | (L)BH-T661 | (L)BH-T956 | | | | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| STARLET : 90 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1300) | E−EP91 | ルフレ | 96.1-99.7 | 3/4 | | TK-T406 | 96.1-97.4 | | DISC | MP-36 | | 96.1-99.7 | 11/16 | (R)WC-T599 | WK-569 | CUP | 96.1-99.7 | (R)BH-T660 | (R)BH-T956 | 96.1-99.7 | 5/8 | MC-T374 | MK-T244 | 96.1-99.7 | 7/8 | | CK-T200 |
| | | | <アンチスキッド付> | | | | 97.4-99.7 | 48.1 | DISC | MP-7 | | | | (L)WC-T617 | | | | (L)BH-T661 | (L)BH-T956 | | | | | | | | |
| | | | 96.1-99.7 | 13/16 | | TK-T358 | <アンチスキッド付> | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | 96.1-99.7 | 51.1 | DISC | MP-15 | CPM-15 | | | | | | | | | | | | | | | | |
| | | ルフレX・ルフレf<br>カラット・グランツァS<br>リミックス | 96.1-99.7 | 13/16 | | TK-T358 | 96.1-99.7 | 51.1 | DISC | MP-15 | CPM-15 | 96.1-99.7 | 11/16 | (R)WC-T599<br>(L)WC-T617 | WK-569 | CUP | 96.1-99.7 | (R)BH-T660<br>(L)BH-T661 | (R)BH-T956<br>(L)BH-T956 | 96.1-99.7 | 5/8 | MC-T374 | MK-T244 | 96.1-99.7 | 7/8 | | CK-T200 |
| | | グランツァV | 96.1-99.7 | 13/16 | | TK-T357 | 96.1-99.7 | 51.1 | DISC | MP-15 | CPM-15 | 96.1-99.7 | 30.2 | DISC | MP-23 | | 96.1-96.6 | (R)BH-T660<br>(L)BH-T661 | (R-1)BH-T956<br>(L-1)BH-T956<br>(R-2)BH-T558<br>(L-2)BH-T558 | 96.1-99.7 | 5/8 | MC-T374 | MK-T244 | 96.1-99.7 | 7/8 | | CK-T200 |
| | | | <アンチスキッド付> | | | | | | | | | | | | | | 96.6-99.7 | (R)BH-T660<br>(L)BH-T661 | (R-1)BH-T956<br>(L-1)BH-T956<br>(R-2)BH-T558<br>(L-2)BH-T558 | | | | | | | | |
| | | | 96.1-99.7 | 13/16 | | TK-T358 | | | | | | | | | | | | | | | | | | | | | |
| | E−EP95(4WD) | | 96.1-99.7 | 13/16 | | TK-T358 | 96.1-99.7 | 51.1 | DISC | MP-15 | CPM-15 | 96.1-99.7 | 11/16 | (R)WC-T647<br>(L)WC-T647 | WK-569 | CUP | 96.1-99.7 | (R)BH-T660<br>(L)BH-T661 | (R)BH-T656<br>(L)BH-T532 | 96.1-99.7 | 5/8 | MC-T374 | MK-T244 | 96.1-99.7 | 7/8 | | CK-T200 |
| (1500ディーゼル) | | | 96.1-99.7 | 3/4 | | TK-T406 | 96.1-97.4 | | DISC | MP-36 | | 96.1-99.7 | 11/16 | (R)WC-T599 | WK-569 | CUP | 96.1-99.7 | (R)BH-T660 | (R)BH-T956 | 96.1-97.12 | 5/8 | MC-T374 | MK-T244 | 96.1-99.7 | 13/16 | | CK-T201 |
| | KD−NP90 | | <アンチスキッド付> | | | | 97.4-99.7 | 48.1 | DISC | MP-7 | | | | (L)WC-T617 | | | | (L)BH-T661 | (L)BH-T956 | 97.12-99.7 | 5/8 | MC-T374 | | | | | |
| | | | 96.1-99.7 | 13/16 | | TK-T358 | <アンチスキッド付> | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | 96.1-99.7 | 51.1 | DISC | MP-15 | CPM-15 | | | | | | | | | | | | | | | | |

| Models | TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| IQ : 10 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1000) | DBA－KGJ10 | ドラム車 | 08.11- | | | | 08.11- | | DISC | MP-123 | | 08.11- | 11/16 | (R)WC-T777<br>(L)WC-T778 | WK-935 | CUP | 08.11- | (R)<br>(L) | (R)<br>(L) | 08.11- | | (オートマチック) | | 08.11- | | | |
| | | ディスク車 | 08.11- | | | | 08.11- | | DISC | MP-123 | | 08.11- | | DISC | TP-112 | | 08.11- | (R)<br>(L) | (R-1)<br>(L-1)<br>(R-2)<br>(L-2) | 08.11- | | (オートマチック) | | 08.11- | | | |
| (1300) | DBA－NGJ10 | ドラム車 | 09.8- | | | | 09.8- | | DISC | MP-123 | | 09.8- | 11/16 | (R)WC-T777<br>(L)WC-T778 | WK-935 | CUP | 09.8- | (R)<br>(L) | (R)<br>(L) | 08.11- | | (オートマチック) | | 08.11- | | | |
| | | ディスク車 | 09.8- | | | | 09.8- | | DISC | MP-123 | | 09.8- | | DISC | TP-112 | | 09.8- | (R)<br>(L) | (R-1)<br>(L-1)<br>(R-2)<br>(L-2) | 08.11- | | (オートマチック) | | 08.11- | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| EQ : 10 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| ZAA－KPJ10 | EV | | 12.9-12.12 | | | ｷｯﾄｾｯﾃｲﾅﾝ | 12.9-12.12 | 54 | DISC | MP-110 | | 12.9-12.12 | | (R)WC-T787<br>(L)WC-T787 | WK-900 | CUP | 12.9-12.12 | (R)<br>(L) | (R)<br>(L) | | | | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| PUBLICA VAN/PICKUP : KP37 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1200) | KP37V(バン) | STD・DX | 75.11-78.9 | 11/16 | | TK-9319 | 75.11-76.5 | 13/16 | (R-1)WC-1035<br>(R-2)WC-2025<br>(L-1)WC-3035<br>(L-2)WC-4025 | | CUP | 75.11-76.5 | 11/16 | (R)WC-50041<br>(L)WC-50041 | WK-083 | CUP | 75.11-78.9 | BH-02186 | BH-02267 | | | (ワイヤー式) | | | | | |
| | | | | | | | | | | | | 76.5-77.2 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | | | | | | | | | | | |
| | | | | | | | 76.5-78.9 | 7/8 | (R-1)WC-51008<br>(R-2)WC-52008<br>(L-1)WC-53008<br>(L-2)WC-54008 | WK-318 | CUP | 77.2-78.9 | 3/4 | (R)WC-50052<br>(L)WC-50052 | WK-491 | CUP | | | | | | | | | | | |
| | | HDX | 75.11-78.9 | 11/16 | | TK-9319 | 75.11-76.5 | 1 3/4 | DISC | MP-1 | | 75.11-76.5 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 75.11-78.9 | (1)BH-02187<br>(2)BH-02188 | BH-02267 | | | (ワイヤー式) | | | | | |
| | | | | | | | 76.5-78.9 | 1 7/8 | DISC | MP-2 | | 76.5-77.2 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | | | | | | | | | | | |
| | | | | | | | | | | | | 77.2-78.9 | 13/16 | (R)WC-50053<br>(L)WC-50053 | WK-492 | CUP | | | | | | | | | | | |
| | KP37(ピックアップ) | STD・DX | 75.11-79.7 | 11/16 | | TK-9319 | 75.11-76.5 | 13/16 | (R-1)WC-1035<br>(R-2)WC-2025<br>(L-1)WC-3035<br>(L-2)WC-4025 | | CUP | 75.11-77.2 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 75.11-79.7 | BH-02186 | BH-02131 | | | (ワイヤー式) | | | | | |
| | | | | | | | | | | | | 77.2-79.7 | 3/4 | (R)WC-50052<br>(L)WC-50052 | WK-491 | CUP | | | | | | | | | | | |
| | | | | | | | 76.5-79.7 | 7/8 | (R-1)WC-51008<br>(R-2)WC-52008<br>(L-1)WC-53008<br>(L-2)WC-54008 | WK-318 | CUP | | | | | | | | | | | | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| PUBLICA VAN/PICKUP : KP38, 39 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| JーKP38(ピックアップ)<br>LーKP39(ピックアップ) | STD・DX | 79.7-88.8 | 11/16 | | TK-9319 | 79.7-88.8 | 7/8 | (R-1)WC-51008<br>(R-2)WC-52008<br>(L-1)WC-53008<br>(L-2)WC-54008 | WK-318 | CUP | 79.7-88.8 | 3/4 | (R)WC-50052<br>(L)WC-50052 | WK-491 | CUP | 79.7-88.8 | BH-02186 | BH-02131 | | | (ワイヤー式) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| PUBLICA : KP50 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1200) | KP50 | ドラム車 | 76.1-78.2 | 11/16 | | TK-9319 | 76.1-78.2 | 7/8 | (R-1)WC-51008<br>(R-2)WC-52008<br>(L-1)WC-53008<br>(L-2)WC-54008 | WK-318 | CUP | 76.1-77.2<br><br>77.2-78.2 | 3/4<br><br>3/4 | (R)WC-50060<br>(L)WC-50060<br>(R)WC-50052<br>(L)WC-50052 | WK-491<br><br>WK-491 | CUP<br><br>CUP | 76.1-78.2 | BH-02186 | BH-02267 | | | (ワイヤー式) | | | | | |
| | | ディスク車 | 76.1-78.2 | 11/16 | | TK-9319 | 76.1-78.2 | 1 7/8 | DISC | MP-2 | | 76.1-77.2<br><br>77.2-78.2 | 13/16<br><br>13/16 | (R)WC-50059<br>(L)WC-50059<br>(R)WC-50053<br>(L)WC-50053 | WK-492<br><br>WK-492 | CUP<br><br>CUP | 76.1-78.2 | (1)BH-02187<br>(2)BH-02188 | BH-02267 | | | (ワイヤー式) | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| DUET : M100 ser.(98.9-) | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1000) | GF－M100A<br>＜TA－は00．5～＞<br>＜UA－は01．12～＞ | 98.9-04.6<br>〈ｱﾝﾁｽｷｯﾄﾞ付〉<br>98.9-04.6 | 13/16<br>13/16 | | TK-D217<br><br>TK-D218 | 98.9-04.6 | | DISC | A-607P | CPA-496 | 98.9-04.6 | 11/16 | (R)WC-D284<br>(L)WC-D284 | WK-699-01 | CUP | 98.9-04.6 | BH-D230 | (R)BH-D231<br>(L)BH-D231 | | | (ﾜｲﾔｰ式) | | | | | |
| | GF－M110A(4WD)<br>＜TA－は00．5～＞<br>＜LA－は01．12～＞ | 98.9-04.6<br>〈ｱﾝﾁｽｷｯﾄﾞ付〉<br>98.9-04.6 | 13/16<br>13/16 | | TK-D217<br><br>TK-D218 | 98.9-04.6 | | DISC | A-607P | CPA-496 | 98.9-04.6 | 11/16 | (R)WC-D275<br>(L)WC-D275 | WK-867 | CUP | 98.9-04.6 | BH-D230 | (R)BH-D232<br>(L)BH-D232 | | | (ﾜｲﾔｰ式) | | | | | |
| (1300) | TA－M101A<br>＜LA･UA－は01．12～＞ | 00.5-04.6<br>〈VSC付〉<br>00.5-04.6 | 13/16<br><br>13/16 | | TK-D218 | 〈V･X〉<br>00.5-04.6<br>〈VS〉<br>00.5-01.12<br><br>01.12-04.6 | <br><br><br><br>51.1 | DISC<br><br>DISC<br><br>DISC | A-607P<br><br>A-607P<br><br>TP-127 | CPA-496<br><br>CPA-496<br><br>CPT-80 | 00.5-04.6 | 11/16 | (R)WC-D284<br>(L)WC-D284 | WK-699-01 | CUP | 00.5-04.6 | BH-D230 | (R)BH-D231<br>(L)BH-D231 | | | (ﾜｲﾔｰ式) | | | | | |
| | TA－M111A(4WD)<br>＜LA－は01．12～＞ | 00.5-04.6 | 13/16 | | TK-D218 | 〈V･X〉<br>00.5-04.6<br>〈VS〉<br>00.5-01.12<br>01.12-04.6 | <br><br><br><br>51.1 | DISC<br><br>DISC<br>DISC | A-607P<br><br>A-607P<br>TP-127 | CPA-496<br><br>CPA-496<br>CPT-80 | 00.5-04.6 | 11/16 | (R)WC-D275<br>(L)WC-D275 | WK-867 | CUP | 00.5-04.6 | BH-D230 | (R)BH-D232<br>(L)BH-D232 | | | (ﾜｲﾔｰ式) | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| CAMI : J100 ser.(99.5-) | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1300) | GF－J100E(4WD) | 99.5-00.5 | 7/8 | | | 99.5-00.5 | | DISC | SP-297 | CPS-297 | 99.5-00.5 | 13/16 | (R)WC-D265<br>(L)WC-D266 | WK-900 | CUP | 99.5-00.5 | BH-D229 | BH-D237 | | | (ワイヤー式) | | | | | |
| | GF－J102E(4WD)<br>GF－J122E(2WD)<br><TA－は01．12～> | 00.5-05.12 | 7/8 | | | 00.5-05.12 | | DISC | SP-297 | CPS-297 | 00.5-05.12 | 13/16 | (R)WC-D266<br>(L)WC-D266 | WK-900 | CUP | 00.5-00.7<br><br>00.7-05.12 | BH-D229<br><br>BH-D229 | (R)<br>(L)BH-D239<br>(R)BH-D240<br>(L)BH-D239 | 00.5-05.12 | 5/8 | MC-D107 | | 00.5-05.12 | 13/16 | CC-D108 | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| SPARKY : (00.9-) | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1300) TA－S221E | 00.9- | | | | 00.9-02.6 | 51.1 | DISC | MP-59 | CPM-59 | 00.9-02.6 | 13/16 | | WK-956 | CUP | 00.9- | BH-D251 | (R)BH-D238 | | | (ワイヤー式) | | | | | |
| TA－S231E(4WD) | | | | | 02.6- | 51.1 | DISC | MP-59 | CPM-59 | 02.6- | 11/16 | | WK-867 | CUP | | | (L)BH-D238 | | | | | | | | |
| ＜UA・LA－は02. 6～＞ | | | | | | | | | | | | | | | | | | | | | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| PASSO : 10, 30 ser.(04.6-) | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1000) | DBA－KGC10 | 04.6-10.2 | 3/4 | TD-D175 | TK-D235 | 04.6-10.2 | | DISC | TP-127 | CPT-80 | 04.6-10.2 | 11/16 | (R)WC-D285<br>(L)WC-D285 | WK-699-01 | CUP | 04.6-10.2 | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| | DBA－KGC15(4WD) | 04.6-10.2 | 3/4 | TD-D175 | TK-D235 | 04.6-10.2 | | DISC | TP-127 | CPT-80 | 04.6-10.2 | 11/16 | (R)WC-D275<br>(L)WC-D275 | WK-867 | CUP | 04.6-10.2 | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| | DBA－KGC30 | <VSC無><br>10.2-14.4<br>14.4-<br><VSC付><br>10.2- | <br>3/4<br>3/4<br><br>3/4 | | TK-D235<br>キットセッテイナシ<br><br>TK-D235 | 10.2- | | DISC | TP-127 | CPT-80 | 10.2- | 11/16 | (R)WC-D285<br>(L)WC-D285 | WK-699-01 | CUP | 10.2- | (R)BH-T944<br>(L)BH-T945 | (R)<br>(L) | | | (オートマチック) | | | | | |
| | DBA－KGC35(4WD) | <VSC無><br>10.2-14.4<br>14.4-<br><VSC付><br>10.2- | <br>3/4<br>3/4<br><br>3/4 | | TK-D235<br>キットセッテイナシ<br><br>TK-D235 | 10.2-<br><br><+HANAバージョン><br>10.2- | | DISC<br><br><br>DISC | TP-127<br><br><br>TP-103 | CPT-80<br><br><br>CPT-81 | 10.2- | 11/16 | (R)WC-D290<br>(L)WC-D290 | WK-699-01 | CUP | 10.2-<br><br><+HANAバージョン><br>10.2- | (R)BH-T944<br>(L)BH-T945<br><br>(R)<br>(L) | (R)BH-D233<br>(L)BH-D233<br><br>(R)BH-D233<br>(L)BH-D233 | | | (オートマチック) | | | | | |
| (1300) | DBA－QNC10 | 04.6- | 3/4 | | TK-D235 | 04.6- | | DISC | TP-127 | CPT-80 | 04.6- | 11/16 | (R)WC-D285<br>(L)WC-D285 | WK-699-01 | CUP | 04.6- | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| | DBA－NGC30 | <VSC無><br>10.2-14.4<br>14.4-<br><VSC付><br>10.2- | <br>3/4<br>3/4<br><br>3/4 | | TK-D235<br>TK-D235<br><br>TK-D235 | 10.2- | | DISC | TP-127 | CPT-80 | 10.2- | 11/16 | (R)WC-D285<br>(L)WC-D285 | WK-699-01 | CUP | 10.2- | (R)BH-T944<br>(L)BH-T945 | (R)<br>(L) | | | (オートマチック) | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| PASSO : M700 ser.(16.4-) | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1000) | DBA－M700A | 16.4- | | | ｷｯﾄｾｯﾃｲﾅｼ | 16.4- | | DISC | | CPT-80 | 16.4- | 3/4 | (R)WC-D295<br>(L)WC-D296 | WK-542 | CUP | 16.4- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | DBA－M710A(4WD) | 16.4- | | | ｷｯﾄｾｯﾃｲﾅｼ | 16.4- | | DISC | | CPT-80 | 16.4- | 11/16 | (R)WC-D290<br>(L)WC-D290 | WK-699-01 | CUP | 16.4- | (R)<br>(L) | (R)BH-D233<br>(L)BH-D233 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| PASSO SETTE : M500 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1500) | CBA－M502E | 08.12- | | | | <VSC無><br>08.12-<br><VSC付><br>08.12- | | DISC<br><br>DISC | MP-119<br><br>MP-120 | | 08.12- | 13/16 | (R)WC-T787<br>(L)WC-T787 | WK-900 | CUP | 08.12- | (R)BH-D259<br>(L)BH-D260 | (R)<br>(L) | | | (オートマチック) | | | | | |
| | CBA－M512E 4WD | 08.12- | | | | 08.12- | | DISC | MP-120 | | 08.12- | 13/16 | (R)WC-T787<br>(L)WC-T787 | WK-900 | CUP | 08.12- | (R)BH-D259<br>(L)BH-D260 | (R)<br>(L) | | | (オートマチック) | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| PORTE : 10 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1300) | CBA－NNP10<br>＜DBA－10．8～＞ | 04.7- | | | | 04.7- | | DISC | MP-95 | CPM-95 | 04.7- | | (R)WC-T780<br>(L)WC-T781 | WK-542 | CUP | 04.7- | (R)BH-T778<br>(L)BH-T779 | (R)BH-T941<br>(L)BH-T941 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (1500) | CBA－NNP11<br>＜DBA－10．8～＞ | ＜VSC無＞<br>04.7-<br>＜VSC付＞<br>04.11- | | | | 04.7- | | DISC | MP-95 | CPM-95 | 04.7- | | (R)WC-T780<br>(L)WC-T781 | WK-542 | CUP | 04.7- | (R)BH-T778<br>(L)BH-T779 | (R)BH-T941<br>(L)BH-T941 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | CBA－NNP15　4WD<br>＜DBA－10．8～＞ | 05.12- | | | | 05.12- | | DISC | MP-95 | CPM-95 | 05.12- | | (R)WC-T780<br>(L)WC-T781 | WK-542 | CUP | 05.12- | (R)BH-T780<br>(L)BH-T781 | (R)BH-T782<br>(L)BH-T783 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| PORTE : 140 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1300) | DBA－NSP140 | 12.7- | | | ｷｯﾄｾｯﾃｲﾅｼ | 12.7-15.3<br>15.4- | 54 | DISC<br>DISC | MP-110<br>MP-136 | | 12.7- | | (R)WC-T787<br>(L)WC-T787 | WK-900 | CUP | 12.7- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (1500) | DBA－NCP141 | 12.7- | | | ｷｯﾄｾｯﾃｲﾅｼ | 12.7-15.3<br>15.4- | 54 | DISC<br>DISC | MP-110<br>MP-136 | | 12.7- | | (R)WC-T787<br>(L)WC-T787 | WK-900 | CUP | 12.7- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | DBA－NCP145 | 12.7- | 7/8 | TD-T936 | ｷｯﾄｾｯﾃｲﾅｼ | 12.7- | | DISC | MP-111 | | 12.7- | | (R)WC-T787<br>(L)WC-T787 | WK-900 | CUP | 12.7- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | DBA－NSP141 | 15.7- | | | ｷｯﾄｾｯﾃｲﾅｼ | 15.7- | | DISC | MP-136 | | 15.7- | | (R)WC-T787<br>(L)WC-T787 | WK-900 | CUP | 15.7- | (R)<br>(L) | (R)<br>(L) | | | | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| SPADE : 140 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1300) | DBA－NSP140 | 12.7- | | | ｷｯﾄｾｯﾃｲﾅｼ | 12.7-15.3<br>15.4- | 54 | DISC<br>DISC | MP-110<br>MP-136 | | 12.7- | | (R)WC-T787<br>(L)WC-T787 | WK-900 | CUP | 12.7- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (1500) | DBA－NCP141 | 12.7- | | | ｷｯﾄｾｯﾃｲﾅｼ | 12.7-15.3<br>15.4- | 54 | DISC<br>DISC | MP-110<br>MP-136 | | 12.7- | | (R)WC-T787<br>(L)WC-T787 | WK-900 | CUP | 12.7- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | DBA－NCP145 | 12.7- | 7/8 | TD-T936 | ｷｯﾄｾｯﾃｲﾅｼ | 12.7- | | DISC | MP-111 | | 12.7- | | (R)WC-T787<br>(L)WC-T787 | WK-900 | CUP | 12.7- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | DBA－NSP141 | 15.7- | | | ｷｯﾄｾｯﾃｲﾅｼ | 15.7- | | DISC | MP-136 | | 15.7- | | (R)WC-T787<br>(L)WC-T787 | WK-900 | CUP | 15.7- | (R)<br>(L) | (R)<br>(L) | | | | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| BELTA : 90 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1000) | DBA－KSP92 | | 05.11-12.6 | 13/16 | TD-T914 | ｷｯﾄｾｯﾃｲﾅｼ | 05.11- | 54 | DISC | MP-110 | | 05.11-12.6 | | (R)WC-T780<br>(L)WC-T781 | WK-542 | CUP | 05.11-12.6 | | | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (1300) | DBA－SCP92 | VSC付 | 05.11-12.6 | | | ｷｯﾄｾｯﾃｲﾅｼ | 05.11- | | DISC | MP-111 | | 05.11-12.6 | | (R)WC-T780<br>(L)WC-T781 | WK-542 | CUP | 05.11-12.6 | | | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | | VSC無 | 05.11-12.6 | 13/16 | TD-T914 | ｷｯﾄｾｯﾃｲﾅｼ | 05.11- | 54 | DISC | MP-110 | | 05.11-06.12<br>06.12-12.6 | | DISC<br>DISC | TP-99A<br>TP-112 | | 05.11-12.6 | | | | | | | | | | |
| | CBA－NCP96 | | 05.11-12.6 | 13/16 | TD-T914 | ｷｯﾄｾｯﾃｲﾅｼ | 05.11- | 54 | DISC | MP-110 | | 05.11-12.6 | | | WK-542 | CUP | 05.11-12.6 | | | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| RACTIS : 100 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1300) | DBA－NSP120 | | 10.11-16.7 | | | | 10.11-16.7 | | DISC | MP-111 | | 10.11-16.7 | 13/16 | (R)WC-T787<br>(L)WC-T787 | WK-900 | CUP | 10.11-11.11<br><br>11.11-14.5<br><br>14.5-16.7 | (R)<br>(L)<br>(R)<br>(L)<br>(R)<br>(L) | (R)BH-T716<br>(L)BH-T957<br>(R)BH-T956<br>(L)BH-T957 | | | | | | | | |
| (1300) | DBA－SCP100 | | 05.10-10.8 | 13/16 | TD-T914 | ｷｯﾄｾｯﾃｲﾅｼ | 05.10-10.8 | | DISC | MP-111 | | 05.10-10.8 | | (R)WC-T787<br>(L)WC-T787 | WK-900 | CUP | 05.10-10.8 | (R)<br>(L) | (R)BH-T716<br>(L)BH-T957 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (1500) | DBA－NCP100 | Sﾊﾟｯｹｰｼﾞ | 05.10-10.8 | | | | 05.10-10.8 | | DISC | MP-111 | | 05.10-96.2<br>06.12-10.8 | | DISC<br>DISC | TP-99A<br>TP-112 | | 05.10-10.8 | (R)<br>(L) | (R-1)BH-T716<br>(L-1)<br>(R-2)BH-T957<br>(L-2) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | | 除くSﾊﾟｯｹｰｼﾞ | 05.10-10.8 | 13/16 | TD-T914 | ｷｯﾄｾｯﾃｲﾅｼ | 05.10-10.8 | | DISC | MP-111 | | 05.10-10.8 | | (R)WC-T787<br>(L)WC-T787 | WK-900 | CUP | 05.10-10.8 | (R)<br>(L) | (R)BH-T716<br>(L)BH-T957 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | CBA－NCP105 | | 05.10-10.8 | 13/16 | TD-T914 | ｷｯﾄｾｯﾃｲﾅｼ | 05.10-10.8 | | DISC | MP-111 | | 05.10-10.8 | | (R)WC-T787<br>(L)WC-T787 | WK-900 | CUP | 05.10-10.8 | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | DBA－NCP120 | 四輪ディスク車 | <ﾉﾝﾌﾞｸ VSC付><br>10.11-12.2<br>12.3-13.10<br>13.10-<br><VSC付><br>10.11-12.2<br>12.3- | <br><br>7/8<br>7/8<br><br><br>7/8 | <br><br>TD-T935<br>TD-T936<br><br><br>TD-T936 | | 10.11- | | DISC | MP-111 | | 10.11- | | DISC | TP-112 | | 10.11-11.11 | (R)<br>(L) | (R)BH-T716<br>(L)BH-T957 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | | リヤドラム車 | <ﾉﾝﾌﾞｸ VSC付><br>10.11-12.2<br>12.3-13.10<br>13.10-<br><VSC付><br>10.11-12.2<br>12.3-16.7 | <br><br>7/8<br>7/8<br><br><br>7/8 | <br><br>TD-T935<br>TD-T936<br><br><br>TD-T936 | | 10.11-16.7 | | DISC | MP-111 | | 10.11-16.7 | | (R)WC-T787<br>(L)WC-T787 | WK-900 | CUP | 11.11-14.5<br><br>14.5-16.7 | (R)<br>(L)<br>(R)<br>(L) | (R)BH-T956<br>(L)BH-T957<br>(R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | DBA－NCP122 | | 10.11-12.2<br>12.3-13.10<br>13.10-16.7 | <br>7/8<br>7/8 | <br>TD-T935<br>TD-T936 | | 10.11-16.7 | | DISC | MP-111 | | 10.11-16.7 | | (R)WC-T787<br>(L)WC-T787 | WK-900 | CUP | 10.11-11.11<br><br>11.11-14.5<br><br>14.5-16.7 | (R)<br>(L)<br>(R)<br>(L)<br>(R)<br>(L) | (R)BH-T716<br>(L)BH-T957<br>(R)BH-T956<br>(L)BH-T957<br>(R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | DBA－NCP125 | | 10.11-12.2<br>12.3-13.10<br>13.10-16.7 | <br>7/8<br>7/8 | <br>TD-T935<br>TD-T936 | | 10.11-16.7 | | DISC | MP-111 | | 10.11-16.7 | | (R)WC-T787<br>(L)WC-T787 | WK-900 | CUP | 10.11-11.11<br><br>11.11-14.5<br><br>14.5-16.7 | (R)<br>(L)<br>(R)<br>(L)<br>(R)<br>(L) | (R)<br>(L)<br>(R)<br>(L)<br>(R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | DBA－NSP122 | | 10.11-12.2<br>12.3-13.10<br>13.10-16.7 | <br>7/8<br>7/8 | <br>TD-T935<br>TD-T936 | | 10.11-16.7 | | DISC | MP-111 | | 10.11-16.7 | | (R)WC-T787<br>(L)WC-T787 | WK-900 | CUP | 10.11-11.11<br><br>11.11-14.5<br><br>14.5-16.7 | (R)<br>(L)<br>(R)<br>(L)<br>(R)<br>(L) | (R)BH-T716<br>(L)BH-T957<br>(R)BH-T956<br>(L)BH-T957<br>(R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| PIXIS SPACE : L570, 580 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (660) | CBA・DBA－L575A | 2WD<br>L・X<br>カスタムG<br>カスタムX | <X・カスタムG><br>11.9-16.12<br><L・カスタムX><br>11.9-C/#0028106<br>C/#0028107- | 3/4 | | キットセッテイナシ<br><br>TK-D235<br>キットセッテイナシ | 11.9-13.6<br>13.6-16.12 | | DISC<br>DISC | C-608P<br>TP-127 | CPA-496<br>CPT-80 | 11.9-13.6<br><br>13.6- | 11/16<br><br>11/16 | (R)WC-D277<br>(L)WC-D277<br>(R)WC-T777<br>(L)WC-T778 | WK-867<br><br>WK-935 | CUP<br><br>CUP | 11.9- | (R)BH-D254<br>(L)BH-D255 | (R)<br>(L) | | | (オートマチック) | | | | |
| | | 2WD<br>カスタムRS | 11.9-C/#0028111<br>C/#0028112- | 3/4 | | TK-D235<br>キットセッテイナシ | <12インチブレーキ><br>11.9-13.6<br><13インチブレーキ><br>11.11-16.12 | | DISC<br><br>DISC | C-608P<br><br>TP-127 | CPA-496<br><br>CPT-80 | 11.9-13.6<br><br>13.6-16.12 | 11/16<br><br>11/16 | (R)WC-D277<br>(L)WC-D277<br>(R)WC-T777<br>(L)WC-T778 | WK-867<br><br>WK-935 | CUP<br><br>CUP | 11.9-16.12 | (R)BH-D254<br>(L)BH-D255 | (R)<br>(L) | | | (オートマチック) | | | | |
| | CBA・DBA－L585A | 4WD<br>L・X<br>カスタムG<br>カスタムX | <X・カスタムG><br>11.9-<br><L・カスタムX><br>11.9-C/#0005998<br>C/#0005999- | 3/4 | | キットセッテイナシ<br><br>TK-D235<br>キットセッテイナシ | 11.9-13.6<br>13.6-16.12 | | DISC<br>DISC | C-608P<br>TP-127 | CPA-496<br>CPT-80 | 11.9-16.12 | 11/16 | (R)WC-D290<br>(L)WC-D290 | WK-699-01 | CUP | 11.9-16.12 | (R)BH-D254<br>(L)BH-D255 | (R)BH-D257<br>(L)BH-D257 | | | (オートマチック) | | | | |
| | | 4WD<br>カスタムRS | 11.9-12.5<br>12.5-16.12 | 3/4 | | TK-D235<br>キットセッテイナシ | 11.9-16.12 | | DISC | TP-127 | CPT-80 | 11.9-16.12 | 11/16 | (R)WC-D290<br>(L)WC-D290 | WK-699-01 | CUP | 11.9-16.12 | (R)BH-D254<br>(L)BH-D255 | (R)BH-D257<br>(L)BH-D257 | | | (オートマチック) | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| PIXIS EPOCH : LA300, 310 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (660) | DBA－LA300 | 12.4- | | | ｷｯﾄｾｯﾃｲﾅｼ | 12.4- | | DISC | C-608P | CPA-496 | 12.4- | 11/16 | (R)WC-D294<br>(L)WC-D294 | WK-1082 | CUP | 12.4- | (R)BH-D261<br>(L)BH-D262 | (R)<br>(L) | | | (ﾜｲﾔｰ式) | | | | | |
| | DBA－LA310(4WD) | 12.4- | | | ｷｯﾄｾｯﾃｲﾅｼ | 12.4- | | DISC | C-608P | CPA-496 | 12.4- | | (R)WC-D290<br>(L)WC-D290 | WK-699-01 | CUP | 12.4- | (R)BH-D261<br>(L)BH-D262 | (R)BH-D257<br>(L)BH-D257 | | | (ﾜｲﾔｰ式) | | | | | |
| | DBA－LA350A | 17.5- | | | ｷｯﾄｾｯﾃｲﾅｼ | 17.5- | | DISC | C-608P | CPA-496 | 17.5- | | (R)WC-D285<br>(L)WC-D285 | WK-699-01 | CUP | 17.5- | (R)<br>(L) | (R)<br>(L) | | | | | | | | |
| | DBA－LA360A(4WD) | 17.5- | | | ｷｯﾄｾｯﾃｲﾅｼ | 17.5- | | DISC | C-608P | CPA-496 | 17.5- | 11/16 | (R)WC-D290<br>(L)WC-D290 | WK-699-01 | CUP | 17.5- | (R)<br>(L) | (R)<br>(L) | | | | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| PIXIS MEGA : LA700, 710 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (660) | DBA－LA700A | 15.7- | | | ｷｯﾄｾｯﾃｲﾅｼ | 15.7-16.5<br>16.5- | | DISC<br>DISC | TP-127<br>TP-107 | CPT-80<br>CPT-80 | 15.7- | 11/16 | (R)WC-T777<br>(L)WC-T778 | WK-935 | WC-21401 | 15.7- | (R)BH-D261<br>(L)BH-D262 | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | DBA－LA710A(4WD) | 15.7- | | | ｷｯﾄｾｯﾃｲﾅｼ | 15.7-16.5<br>16.5- | | DISC<br>DISC | TP-127<br>TP-107 | CPT-80<br>CPT-80 | 15.7- | 11/16 | (R)WC-D290<br>(L)WC-D290 | WK-699-01 | WC-31243 | 15.7- | (R)BH-D261<br>(L)BH-D262 | (R)BH-D257<br>(L)BH-D257 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| PIXIS JOY : LA250, 260 ser. | | | | | | | | | | | | | | | | | | | | | | | | | |
| (660) DBA－LA250A | 16.9- | | | ｷｯﾄｾｯﾃｲﾅｼ | 16.9- | | DISC | TP-107 | CPT-80 | 16.9- | 11/16 | (R)WC-T777<br>(L)WC-T778 | WK-935 | CUP | 16.9- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| DBA－LA260A(4WD) | 16.9- | | | ｷｯﾄｾｯﾃｲﾅｼ | 16.9- | | DISC | TP-107 | CPT-80 | 16.9- | 11/16 | (R)WC-D290<br>(L)WC-D290 | WK-699-01 | CUP | 16.9- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |

| Models | TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| PIXIS VAN : S320, 330 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (660) | EBD－S321M | アンチスキッド無 | 11.11-21.12 | 3/4 | | TK-D236 | 11.11-17.11<br>17.11-21.12 | | DISC<br>DISC | SP-129<br>MP-133 | CPS-243<br>CPS-257 | 11.11-17.11<br><br>17.11-21.12 | 11/16<br><br>11/16 | (R)WC-D289<br>(L)WC-D290<br>(R)WC-T777<br>(L)WC-T778 | WK-699-01<br><br>WK-935 | CUP<br><br>CUP | 11.11-17.11<br><br>17.11-21.12 | (R)BH-D241<br>(L)BH-D241<br>(R)<br>(L) | <br><br>(R)<br>(L) | | | (ワイヤー式) | | | | |
| | | アンチスキッド付 | 11.11-21.12 | 3/4 | | TK-D230 | 11.11-17.11<br>17.11-21.12 | | DISC<br>DISC | SP-129<br>MP-133 | CPS-243<br>CPS-257 | 11.11-17.11<br><br>17.11-21.12 | 5/8<br><br>11/16 | (R)WC-D292<br>(L)WC-D292<br>(R)WC-T777<br>(L)WC-T778 | WK-1041<br><br>WK-935 | CUP<br><br>CUP | 11.11-17.11<br><br>17.11-21.12 | (R)BH-D241<br>(L)BH-D241<br>(R)<br>(L) | (R)<br>(L)<br>(R)<br>(L) | | | (ワイヤー式) | | | | |
| | EBD－S331M | アンチスキッド無 | 11.11-21.12 | 3/4 | | TK-D236 | 11.11-17.11<br>17.11-21.12 | | DISC<br>DISC | SP-129<br>MP-133 | CPS-243<br>CPS-257 | 11.11-17.11<br><br>17.11-21.12 | 11/16<br><br>11/16 | (R)WC-D289<br>(L)WC-D290<br>(R)WC-T777<br>(L)WC-T778 | WK-699-01<br><br>WK-935 | CUP<br><br>CUP | 11.11-17.11<br><br>17.11-21.12 | (R)BH-D241<br>(L)BH-D241<br>(R)<br>(L) | <br><br>(R)<br>(L) | | | (ワイヤー式) | | | | |
| | | アンチスキッド付 | 11.11-21.12 | 3/4 | | TK-D230 | 11.11-17.11<br>17.11-21.12 | | DISC<br>DISC | SP-129<br>MP-133 | CPS-243<br>CPS-257 | 11.11-17.11<br><br>17.11-21.12 | 5/8<br><br>11/16 | (R)WC-D292<br>(L)WC-D292<br>(R)WC-T777<br>(L)WC-T778 | WK-1041<br><br>WK-935 | CUP<br><br>CUP | 11.11-17.11<br><br>17.11-21.12 | (R)BH-D241<br>(L)BH-D241<br>(R)<br>(L) | (R)<br>(L)<br>(R)<br>(L) | | | (ワイヤー式) | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| PIXIS TRUCK : S200, 210 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (660) | EBD－S201U | アンチスキッド無 | 11.11-12.12<br>12.12-14.7 | 3/4 | TD-D169 | TK-D207<br>ｷｯﾄｾｯﾃｲﾅｼ | 11.11-14.7 | | DISC | SP-129 | CPS-243 | <SRSｴｱﾊﾞｯｸﾞ無><br>11.11-14.7<br><SRSｴｱﾊﾞｯｸﾞ付><br>11.11-14.7 | 5/8<br><br>11/16 | (R)WC-D291<br>(L)WC-D292<br><br>(R)WC-D289<br>(L)WC-D290 | WK-1041<br><br>WK-699-01 | CUP<br><br>CUP | 11.11-14.7 | (R)BH-D235<br>(L)BH-D235 | | | | (ﾜｲﾔｰ式) | | | | |
| | | アンチスキッド付 | 11.11-14.7 | | | | 11.11-14.7 | | DISC | SP-129 | CPS-243 | <SRSｴｱﾊﾞｯｸﾞ無><br>11.11-14.7<br><SRSｴｱﾊﾞｯｸﾞ付><br>11.11-14.7 | 5/8<br><br>11/16 | (R)WC-D291<br>(L)WC-D292<br><br>(R)WC-D289<br>(L)WC-D290 | WK-1041<br><br>WK-699-01 | CUP<br><br>CUP | 11.11-14.7 | (R)BH-D235<br>(L)BH-D235 | | | | (ﾜｲﾔｰ式) | | | | |
| | EBD－S211U | アンチスキッド無 | 11.11-12.12<br>12.12-14.7 | 3/4 | TD-D169 | TK-D207<br>ｷｯﾄｾｯﾃｲﾅｼ | 11.11-14.7 | | DISC | SP-129 | CPS-243 | <SRSｴｱﾊﾞｯｸﾞ無><br>11.11-14.7<br><SRSｴｱﾊﾞｯｸﾞ付><br>11.11-14.7 | 5/8<br><br>11/16 | (R)WC-D291<br>(L)WC-D292<br><br>(R)WC-D289<br>(L)WC-D290 | WK-1041<br><br>WK-699-01 | CUP<br><br>CUP | 11.11-14.7 | (R)BH-D235<br>(L)BH-D235 | | | | (ﾜｲﾔｰ式) | | | | |
| | | アンチスキッド付 | 11.11-14.7 | | | | 11.11-14.7 | | DISC | SP-129 | CPS-243 | <SRSｴｱﾊﾞｯｸﾞ無><br>11.11-14.7<br><SRSｴｱﾊﾞｯｸﾞ付><br>11.11-14.7 | 5/8<br><br>11/16 | (R)WC-D291<br>(L)WC-D292<br><br>(R)WC-D289<br>(L)WC-D290 | WK-1041<br><br>WK-699-01 | CUP<br><br>CUP | 11.11-14.7 | (R)BH-D235<br>(L)BH-D235 | | | | (ﾜｲﾔｰ式) | | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| PIXIS TRUCK : S500, 510 ser. | | | | | | | | | | | | | | | | | | | | | | | | | |
| (660) EBD－S500U<br>＜3BD－は20．8～＞ | 14.9-15.11 | | | ｷｯﾄｾｯﾃｲﾅｼ | 14.9-15.11 | | DISC | SP-129 | CPS-243 | 14.9-18.6 | 5/8 | (R)WC-D291<br>(L)WC-D292 | WK-1041 | CUP | 14.9-14.11 | (R)<br>(L) | | | | (ﾜｲﾔｰ式) | | | | | | |
| | | | | | | | | | | 18.6- | 5/8 | (R)WC-D292<br>(L)WC-D292 | WK-1041 | CUP | 14.12-15.11 | (R)<br>(L) | | | | | | | | | | |
| | 15.11- | | | ｷｯﾄｾｯﾃｲﾅｼ | 15.11- | | DISC | MP-133 | CPS-257 | | | | | | 15.11- | (R)<br>(L) | | | | | | | | | | | |
| | | | | | | | | | | (ﾌﾟﾘｸﾗｯｼｭｼｽﾃﾑ無)<br>18.6-20.9 | 5/8 | (R)WC-D291<br>(L)WC-D292 | WK-1041 | CUP | | | | | | | | | | | | |
| | | | | | | | | | | (ｱﾝﾁｽｷｯﾄﾞ付)<br>20.9- | 5/8 | (R)WC-D291<br>(L)WC-D292 | WK-1041 | CUP | | | | | | | | | | | | |
| EBD－S510U<br>＜3BD－は20．8～＞ | 14.9-15.11 | | | ｷｯﾄｾｯﾃｲﾅｼ | 14.9-15.11 | | DISC | SP-129 | CPS-243 | 14.9-18.6 | 5/8 | (R)WC-D291<br>(L)WC-D292 | WK-1041 | CUP | 14.9-14.11 | (R)<br>(L) | | | | (ﾜｲﾔｰ式) | | | | | | |
| | | | | | | | | | | 18.6- | 5/8 | (R)WC-D292<br>(L)WC-D292 | WK-1041 | CUP | 14.12-15.11 | (R)<br>(L) | | | | | | | | | | |
| | 15.11- | | | ｷｯﾄｾｯﾃｲﾅｼ | 15.11- | | DISC | MP-133 | CPS-257 | | | | | | 15.11- | (R)<br>(L) | | | | | | | | | | | |
| | | | | | | | | | | (ﾌﾟﾘｸﾗｯｼｭｼｽﾃﾑ無)<br>18.6-20.9 | 5/8 | (R)WC-D291<br>(L)WC-D292 | WK-1041 | CUP | | | | | | | | | | | | |
| | | | | | | | | | | (ｱﾝﾁｽｷｯﾄﾞ付)<br>20.9- | 5/8 | (R)WC-D291<br>(L)WC-D292 | WK-1041 | CUP | | | | | | | | | | | | |

| Models TOYOTA | | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| COPEN : LA400 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (660) | 3BA－LA400A | GR SPORT | AT | 19.10- | | | ｷｯﾄｾｯﾃｲﾅｼ | 19.10- | | DISC | | CPT-80 | 19.10- | 11/16 | (R)WC-T777<br>(L)WC-T778 | WK-935 | CUP | 19.10- | (R)BH-D254<br>(L)BH-D255 | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | | | MT | 19.10- | | | ｷｯﾄｾｯﾃｲﾅｼ | 19.10- | | DISC | | CPT-80 | 19.10- | 11/16 | (R)WC-T777<br>(L)WC-T778 | WK-935 | CUP | 19.10- | (R)BH-D254<br>(L)BH-D255 | (R)<br>(L) | | | (ﾜｲﾔｰ式) | | | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| FJ CRUISER : 10 ser. | | | | | | | | | | | | | | | | | | | | | | | | | |
| (4000) CBA－GSJ15W | 10.11-11.8<br>11.8-12.8<br>12.8-<br><VSC付><br>12.8- | | | キットセッテイナシ<br>キットセッテイナシ<br>キットセッテイナシ<br><br>キットセッテイナシ | 10.11- | | MD-321M | SP-119A | CPS-292 | 10.11- | | MD-088 | SP-120 | | 10.11-12.7<br><br>12.8-13.7<br><br>13.8- | (R)<br>(L)<br>(R)<br>(L)<br>(R)<br>(L) | (R)<br>(L)<br>(R)<br>(L)<br>(R)<br>(L) | | | (オートマチック) | | | | | |

| Models | TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LAND CRUISER : FJ40, 43 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (3900) | FJ40・40V | シングルM／C使用車 | 69.3-71.9 | 1 | | MK-5515-M | 69.3-71.9 | 1 1/8 | (R-1)WC-95510 | WK-056 | CUP | 69.3-71.9 | 1 | (R-1)WC-46560 | | CUP | 69.3-69.10 | BH-02138 | FC-31402 | 69.3-70.7 | 3/4 | MC-10052 | MK-51400 | 69.3-70.7 | 3/4 | CC-60021 | CK-3102 |
| | | | 71.9-73.9 | 1 | | MK-5515-M | | | (R-2)WC-95510 | | | | | (R-2)WC-46560 | | | 69.10-71.9 | BH-02138 | BH-02135 | 70.7-73.9 | 3/4 | MC-10053 | MK-51400 | 70.7-73.9 | 3/4 | CC-60022 | CK-3102 |
| | | | | | | | | | (L-1)WC-95520 | | | | | (L-1)WC-46570 | | | 71.9-73.9 | (C)BH-02078 | BH-02133 | | | | | | | | |
| | | | | | | | | | (L-2)WC-95520 | | | | | (L-2)WC-46570 | | | | BH-31222 | | | | | | | | | |
| | | | | | | | 71.9-73.9 | 1 1/8 | (R-1)WC-51003 | WK-056 | CUP | 71.9-73.9 | 1 | (R-1)WC-55003 | | CUP | | | | | | | | | | | |
| | | | | | | | | | (R-2)WC-51003 | | | | | (R-2)WC-56003 | | | | | | | | | | | | | |
| | | | | | | | | | (L-1)WC-53003 | | | | | (L-1)WC-57003 | | | | | | | | | | | | | |
| | | | | | | | | | (L-2)WC-53003 | | | | | (L-2)WC-58003 | | | | | | | | | | | | | |
| | | タンデムM／C使用車 | 71.9-75.1 | 1 | | TK-9324 | 71.9-73.9 | 1 1/4 | (R-1)WC-51004 | | CUP | 71.9-73.9 | 7/8 | (R-1)WC-55001 | | CUP | 71.9-74.9 | (C)BH-02078 | BH-02133 | 71.9-75.1 | 3/4 | MC-10053 | MK-51400 | 71.9-74.8 | 3/4 | CC-60022 | CK-3102 |
| | | | 75.1-75.9 | 1 | | TK-9342 | | | (R-2)WC-51004 | | | | | (R-2)WC-56001 | | | | BH-31222 | | 75.1-75.9 | 3/4 | MC-10055 | MK-4305 | 74.8-75.9 | 13/16 | CC-60071 | CK-3109 |
| | | | | | | | | | (L-1)WC-53004 | | | | | (L-1)WC-57001 | | | 74.9-75.9 | (C) | BH-02133 | | | | | | | | |
| | | | | | | | | | (L-2)WC-53004 | | | | | (L-2)WC-58001 | | | | BH-31222 | | | | | | | | | |
| | | | | | | | 73.9-75.9 | 1 1/4 | (R-1)WC-51004 | WK-407 | CUP | 73.9-75.9 | 7/8 | (R-1)WC-55001 | WK-446 | CUP | | | | | | | | | | | |
| | | | | | | | | | (R-2)WC-51004 | | | | | (R-2)WC-56001 | | | | | | | | | | | | | |
| | | | | | | | | | (L-1)WC-53004 | | | | | (L-1)WC-57001 | | | | | | | | | | | | | |
| | | | | | | | | | (L-2)WC-53004 | | | | | (L-2)WC-58001 | | | | | | | | | | | | | |
| | FJ43 | シングルM／C使用車 | 69.3-71.9 | 1 | | MK-5515-M | 69.3-71.9 | 1 1/8 | (R-1)WC-95510 | WK-056 | CUP | 69.3-71.9 | 1 1/8 | (R-1)WC-45560 | WK-057 | CUP | 69.3-69.10 | BH-02138 | FC-31402 | 69.3-70.7 | 3/4 | MC-10052 | MK-51400 | 69.3-70.7 | 3/4 | CC-60021 | CK-3102 |
| | | | 71.9-73.9 | 1 | | MK-5515-M | | | (R-2)WC-95510 | | | | | (R-2)WC-45560 | | | 69.10-71.9 | BH-02138 | BH-02135 | 70.7-73.9 | 3/4 | MC-10053 | MK-51400 | 70.7-73.9 | 3/4 | CC-60022 | CK-3102 |
| | | | | | | | | | (L-1)WC-95520 | | | | | (L-1)WC-45570 | | | 71.9-73.9 | (C)BH-02078 | BH-02133 | | | | | | | | |
| | | | | | | | | | (L-2)WC-95520 | | | | | (L-2)WC-45570 | | | | BH-31222 | | | | | | | | | |
| | | | | | | | 71.9-73.9 | 1 1/8 | (R-1)WC-51003 | WK-056 | CUP | 71.9-73.9 | 1 1/8 | (R-1)WC-55000 | WK-057 | CUP | | | | | | | | | | | |
| | | | | | | | | | (R-2)WC-51003 | | | | | (R-2)WC-56000 | | | | | | | | | | | | | |
| | | | | | | | | | (L-1)WC-53003 | | | | | (L-1)WC-57000 | | | | | | | | | | | | | |
| | | | | | | | | | (L-2)WC-53003 | | | | | (L-2)WC-58000 | | | | | | | | | | | | | |
| | | タンデムM／C使用車 | 73.1-75.1 | 1 | | TK-9324 | 73.1-73.9 | 1 1/4 | (R-1)WC-51004 | | CUP | 73.1-73.9 | 15/16 | (R-1)WC-55002 | | CUP | 73.1-74.9 | (C)BH-02078 | BH-02133 | 73.1-75.1 | 3/4 | MC-10053 | MK-51400 | 73.1-74.8 | 3/4 | CC-60022 | CK-3102 |
| | | | 75.1-75.9 | 1 | | TK-9342 | | | (R-2)WC-51004 | | | | | (R-2)WC-56002 | | | | BH-31222 | | 75.1-75.9 | 3/4 | MC-10055 | MK-4305 | 74.8-75.9 | 13/16 | CC-60071 | CK-3109 |
| | | | | | | | | | (L-1)WC-53004 | | | | | (L-1)WC-57002 | | | 74.9-75.9 | (C) | BH-02133 | | | | | | | | |
| | | | | | | | | | (L-2)WC-53004 | | | | | (L-2)WC-58002 | | | | BH-31222 | | | | | | | | | |
| | | | | | | | 73.9-75.9 | 1 1/4 | (R-1)WC-51004 | WK-407 | CUP | 73.9-75.9 | 15/16 | (R-1)WC-55002 | WK-447 | CUP | | | | | | | | | | | |
| | | | | | | | | | (R-2)WC-51004 | | | | | (R-2)WC-56002 | | | | | | | | | | | | | |
| | | | | | | | | | (L-1)WC-53004 | | | | | (L-1)WC-57002 | | | | | | | | | | | | | |
| | | | | | | | | | (L-2)WC-53004 | | | | | (L-2)WC-58002 | | | | | | | | | | | | | |

| Models | TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LAND CRUISER : FJ55, 56 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (3900) | FJ55V シングルM／C使用車 | 69.3-73.9 | 1 | | MK-5515-M | 69.3-71.9 | 1 1/8 | (R-1)WC-95510<br>(R-2)WC-95510<br>(L-1)WC-95520<br>(L-2)WC-95520 | WK-056 | CUP | 69.3-71.9 | 1 1/8 | (R-1)WC-45560<br>(R-2)WC-45560<br>(L-1)WC-45570<br>(L-2)WC-45570 | WK-057 | CUP | 69.3-69.5<br>69.5-69.10<br>69.10-70.1<br>70.1-71.9 | BH-02073<br>BH-02073<br>BH-02073<br>BH-02134 | BH-02123<br>BH-02093<br>BH-02123<br>BH-02123 | 69.3-73.9 | 3/4 | MC-10054 | MK-51400 | 69.3-73.9 | 3/4 | CC-60030 | CK-3102 |
| | | | | | | 71.9-73.9 | 1 1/8 | (R-1)WC-51003<br>(R-2)WC-51003<br>(L-1)WC-53003<br>(L-2)WC-53003 | WK-056 | CUP | 71.9-73.9 | 1 1/8 | (R-1)WC-55000<br>(R-2)WC-56000<br>(L-1)WC-57000<br>(L-2)WC-58000 | WK-057 | CUP | 71.9-73.9 | (C)BH-02133<br>BH-31222 | BH-02093 | | | | | | | | |
| | タンデムM／C使用車 | 71.9-75.1 | 1 | | TK-9324 | 71.9-73.9 | 1 1/4 | (R-1)WC-51004<br>(R-2)WC-51004<br>(L-1)WC-53004<br>(L-2)WC-53004 | | CUP | 71.9-73.9 | 15/16 | (R-1)WC-55002<br>(R-2)WC-56002<br>(L-1)WC-57002<br>(L-2)WC-58002 | | CUP | 71.9-74.9<br>74.9-75.1 | (C)BH-02133<br>BH-31222<br>(C)BH-02133<br>BH-31222 | BH-02093<br>BH-02123 | 71.9-75.1 | 3/4 | MC-10053 | MK-51400 | 71.9-74.8<br>74.8-75.1 | 3/4<br>13/16 | CC-60030<br>CC-60071 | CK-3102<br>CK-3109 |
| | | | | | | 73.9-75.1 | 1 1/4 | (R-1)WC-51004<br>(R-2)WC-51004<br>(L-1)WC-53004<br>(L-2)WC-53004 | WK-407 | CUP | 73.9-75.1 | 15/16 | (R-1)WC-55002<br>(R-2)WC-56002<br>(L-1)WC-57002<br>(L-2)WC-58002 | WK-447 | CUP | | | | | | | | | | | |
| (4200) | FJ56V | 75.1-80.7 | 1 | | TK-9342 | 75.1-75.9 | 1 1/4 | (R-1)WC-51004<br>(R-2)WC-51004<br>(L-1)WC-53004<br>(L-2)WC-53004 | WK-407 | CUP | 75.1-79.6 | 15/16 | (R-1)WC-55002<br>(R-2)WC-56002<br>(L-1)WC-57002<br>(L-2)WC-58002 | WK-447 | CUP | 75.1-75.9<br>75.9-80.7 | (C)BH-02133<br>BH-31222<br>(C)BH-31264<br>BH-31222 | BH-02123<br>BH-02123 | 75.1-80.7 | 3/4 | MC-10055 | MK-4305 | 75.1-80.7 | 13/16 | CC-60071 | CK-3109 |
| | | | | | | 75.9-78.2 | 1 1/4 | (R-1)WC-5185<br>(R-2)WC-5185<br>(L-1)WC-5385<br>(L-2)WC-5385 | WK-407 | CUP | 79.6-80.7 | 15/16 | (R-1)WC-55016<br>(R-2)WC-56016<br>(L-1)WC-57016<br>(L-2)WC-58016 | WK-447 | CUP | | | | | | | | | | | |
| | | | | | | 78.2-80.7 | 1 1/4 | (R-1)WC-51019<br>(R-2)WC-51019<br>(L-1)WC-53019<br>(L-2)WC-53019 | WK-407 | CUP | | | | | | | | | | | | | | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LAND CRUISER : BJ40, 43 ser. | | | | | | | | | | | | | | | | | | | | | | | | | |
| (3000ディーゼル) | 74.2-75.1 | 1 | | TK-9324 | 74.2-75.9 | 1 1/4 | (R-1)WC-51004 | WK-407 | CUP | 74.2-79.2 | 7/8 | (R-1)WC-55001 | WK-446 | CUP | 74.2-79.2 | (C)BH-02133 | BH-02133 | 74.2-75.1 | 3/4 | MC-10053 | MK-51400 | 74.2-79.2 | 7/8 | CC-60050 | CK-3105 |
| BJ40・40V | 75.1-79.2 | 1 | | TK-9342 | | | (R-2)WC-51004 | | | | | (R-2)WC-56001 | | | | BH-31222 | | 75.1-79.2 | 3/4 | MC-10055 | MK-4305 | | | | |
| | | | | | | | (L-1)WC-53004 | | | | | (L-1)WC-57001 | | | | | | | | | | | | | |
| | | | | | | | (L-2)WC-53004 | | | | | (L-2)WC-58001 | | | | | | | | | | | | | |
| | | | | | 75.9-78.2 | 1 1/4 | (R-1)WC-5185 | WK-407 | CUP | | | | | | | | | | | | | | | | |
| | | | | | | | (R-2)WC-5185 | | | | | | | | | | | | | | | | | | |
| | | | | | | | (L-1)WC-5385 | | | | | | | | | | | | | | | | | | |
| | | | | | | | (L-2)WC-5385 | | | | | | | | | | | | | | | | | | |
| | | | | | 78.2-79.2 | 1 1/4 | (R-1)WC-51019 | WK-407 | CUP | | | | | | | | | | | | | | | | |
| | | | | | | | (R-2)WC-51019 | | | | | | | | | | | | | | | | | | |
| | | | | | | | (L-1)WC-53019 | | | | | | | | | | | | | | | | | | |
| | | | | | | | (L-2)WC-53019 | | | | | | | | | | | | | | | | | | |
| BJ43 | 74.2-75.1 | 1 | | TK-9324 | 74.2-75.9 | 1 1/4 | (R-1)WC-51004 | WK-407 | CUP | 74.2-79.2 | 15/16 | (R-1)WC-55002 | WK-447 | CUP | 74.2-79.2 | (C)BH-02133 | BH-02133 | 74.2-75.1 | 3/4 | MC-10053 | MK-51400 | 74.2-79.2 | 7/8 | CC-60050 | CK-3105 |
| | 75.1-79.2 | 1 | | TK-9342 | | | (R-2)WC-51004 | | | | | (R-2)WC-56002 | | | | BH-31222 | | 75.1-79.2 | 3/4 | MC-10055 | MK-4305 | | | | |
| | | | | | | | (L-1)WC-53004 | | | | | (L-1)WC-57002 | | | | | | | | | | | | | |
| | | | | | | | (L-2)WC-53004 | | | | | (L-2)WC-58002 | | | | | | | | | | | | | |
| | | | | | 75.9-78.2 | 1 1/4 | (R-1)WC-5185 | WK-407 | CUP | | | | | | | | | | | | | | | | |
| | | | | | | | (R-2)WC-5185 | | | | | | | | | | | | | | | | | | |
| | | | | | | | (L-1)WC-5385 | | | | | | | | | | | | | | | | | | |
| | | | | | | | (L-2)WC-5385 | | | | | | | | | | | | | | | | | | |
| | | | | | 78.2-79.2 | 1 1/4 | (R-1)WC-51019 | WK-407 | CUP | | | | | | | | | | | | | | | | |
| | | | | | | | (R-2)WC-51019 | | | | | | | | | | | | | | | | | | |
| | | | | | | | (L-1)WC-53019 | | | | | | | | | | | | | | | | | | |
| | | | | | | | (L-2)WC-53019 | | | | | | | | | | | | | | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LAND CRUISER : BJ41, 44 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (3200ディーゼル) BJ41・41V | ドラム車 | 79.2-80.7<br>80.8-81.10 | 1<br>1 | | TK-9342<br>TK-9412 | 79.2-79.6 | 1 1/4 | (R-1)WC-5185<br>(R-2)WC-5185<br>(L-1)WC-5385<br>(L-2)WC-5385 | WK-407 | CUP | 79.2-80.7 | 7/8 | (R-1)WC-55001<br>(R-2)WC-56001<br>(L-1)WC-57001<br>(L-2)WC-58001 | WK-446 | CUP | 79.2-80.7<br>80.8-81.10 | (C)BH-02133<br>BH-31222<br>(C)BH-94000<br>BH-91001 | BH-02133<br>BH-94000 | 79.2-80.7<br>80.8-81.10 | 3/4<br>3/4 | MC-10055<br>MC-10093 | MK-4305<br>MK-4305 | 79.2-81.10 | 7/8 | CC-60050 | CK-3105 |
| | | | | | | 79.6-80.7 | 1 1/4 | (R-1)WC-51019<br>(R-2)WC-51019<br>(L-1)WC-53019<br>(L-2)WC-53019 | WK-407 | CUP | 80.8-81.10 | 1 | (R)WC-50063<br>(L)WC-50063 | WK-886 | CUP | | | | | | | | | | | |
| | | | | | | 80.8-81.10 | 1 1/4 | (R-1)WC-52015<br>(R-2)WC-51019<br>(L-1)WC-54015<br>(L-2)WC-53019 | WK-407 | CUP | | | | | | | | | | | | | | | |
| | ディスク車 | 79.2-80.7<br>80.8-82.10 | 7/8<br>7/8 | | TK-9377<br>TK-9413 | 79.2-82.10 | | DISC | SP-217 | CPS-217+CPS-217B | 79.2-80.7<br>80.8-82.10 | 7/8<br>1 | (R-1)WC-55001<br>(R-2)WC-56001<br>(L-1)WC-57001<br>(L-2)WC-58001<br>(R)WC-50063<br>(L)WC-50063 | WK-446<br>WK-886 | CUP<br>CUP | 79.2-80.7<br>80.8-82.10 | (C)BH-02133<br>BH-31222<br>(C)BH-94000<br>BH-91001 | BH-02133<br>BH-94000 | 79.2-80.7<br>80.8-82.10 | 3/4<br>3/4 | MC-10055<br>MC-10093 | MK-4305<br>MK-4305 | 79.2-81.10<br>8110-8210 | 7/8<br>15/16 | CC-60050<br>CC-70154 | CK-3105<br>CK-3133 |
| BJ44・44V | ドラム車 | 79.2-80.7<br>80.8-81.10 | 1<br>1 | | TK-9342<br>TK-9412 | 79.2-79.6 | 1 1/4 | (R-1)WC-5185<br>(R-2)WC-5185<br>(L-1)WC-5385<br>(L-2)WC-5385 | WK-407 | CUP | 79.2-79.6 | 15/16 | (R-1)WC-55002<br>(R-2)WC-56002<br>(L-1)WC-57002<br>(L-2)WC-58002 | WK-447 | CUP | 79.2-80.7<br>80.8-81.10 | (C)BH-02133<br>BH-31222<br>(C)BH-94000<br>BH-31222 | BH-02133<br>BH-94000 | 79.2-80.7<br>80.8-81.10 | 3/4<br>3/4 | MC-10055<br>MC-10093 | MK-4305<br>MK-4305 | 79.2-81.10 | 7/8 | CC-60050 | CK-3105 |
| | | | | | | 79.6-80.7 | 1 1/4 | (R-1)WC-51019<br>(R-2)WC-51019<br>(L-1)WC-53019<br>(L-2)WC-53019 | WK-407 | CUP | 79.6-80.7 | 15/16 | (R-1)WC-55016<br>(R-2)WC-56016<br>(L-1)WC-57016<br>(L-2)WC-58016 | WK-447 | CUP | | | | | | | | | | | |
| | | | | | | 80.8-81.10 | 1 1/4 | (R-1)WC-52015<br>(R-2)WC-51019<br>(L-1)WC-54015<br>(L-2)WC-53019 | WK-407 | CUP | 80.8-81.10 | 1 | (R)WC-50063<br>(L)WC-50063 | WK-886 | CUP | | | | | | | | | | | |
| | ディスク車 | 79.2-80.7<br>80.8-82.10 | 7/8<br>7/8 | | TK-9377<br>TK-9413 | 79.2-82.10 | | DISC | SP-217 | CPS-217+CPS-217B | 79.2-80.7<br>80.8-82.10 | 7/8<br>1 | (R-1)WC-55001<br>(R-2)WC-56001<br>(L-1)WC-57001<br>(L-2)WC-58001<br>(R)WC-50063<br>(L)WC-50063 | WK-446<br>WK-886 | CUP<br>CUP | 79.2-80.7<br>80.8-82.10 | (C)BH-02133<br>BH-31222<br>(C)BH-94000<br>BH-91001 | BH-02133<br>BH-94000 | 79.2-80.7<br>80.8-82.10 | 3/4<br>3/4 | MC-10055<br>MC-10093 | MK-4305<br>MK-4305 | 79.2-81.10<br>8110-8210 | 7/8<br>15/16 | CC-60050<br>CC-70154 | CK-3105<br>CK-3133 |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LAND CRUISER : BJ42, 46 ser. | | | | | | | | | | | | | | | | | | | | | | | | | |
| (3400ディーゼル) N－BJ42・42V | 8210-8410 | 7/8 | | TK-9413 | 8210-8410 | | DISC | SP-217 | CPS-217+CPS-217B | 8210-8410 | 1 | (R)WC-50063<br>(L)WC-50063 | WK-886 | CUP | 82.10-84.10 | (C)BH-94000<br>BH-91001 | BH-94006 | 8210-8410 | 3/4 | MC-10093 | MK-4305 | 8210-8410 | 15/16 | CC-70154 | CK-3133 |
| N－BJ46・46V | 8210-8410 | 7/8 | | TK-9413 | 8210-8410 | | DISC | SP-217 | CPS-217+CPS-217B | 8210-8410 | 1 | (R)WC-50063<br>(L)WC-50063 | WK-886 | CUP | 82.10-84.10 | (C)BH-94000<br>BH-91001 | BH-94000 | 8210-8410 | 3/4 | MC-10093 | MK-4305 | 8210-8410 | 15/16 | CC-70154 | CK-3133 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LAND CRUISER : 60 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (3400ディーゼル) | | ドラム車 | 80.8-81.10 | 1 | | TK-9412 | 80.8-81.10 | 1 1/4 | | WK-407 | CUP | 80.8-81.10 | 1 | (R)WC-50063<br>(L)WC-50063 | WK-886 | CUP | 80.8-81.10 | (C)BH-94000<br>BH-94003 | BH-02492 | 80.8-81.10 | 3/4 | MC-10093 | MK-4305 | 80.8-81.10 | 7/8 | CC-60050 | CK-3105 |
| | K－BJ60V | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | ディスク車 | 80.8-82.10 | 7/8 | | TK-9413 | 80.8-82.10 | | DISC | SP-217 | CPS-217+CPS-217B | 80.8-82.10 | 1 | (R)WC-50063<br>(L)WC-50063 | WK-886 | CUP | 80.8-82.10 | (C)BH-94000<br>BH-94003 | BH-02492 | 80.8-82.10 | 3/4 | MC-10093 | MK-4305 | 80.8-81.10<br>8110-8210 | 7/8<br>15/16 | CC-60050<br>CC-70154 | CK-3105<br>CK-3133 |
| | N－BJ61V | | 82.10-84.11<br>84.11-86.8 | 7/8<br>7/8 | | TK-9413<br>TK-9457 | 82.10-86.8 | | DISC | SP-217 | CPS-217+CPS-217B | 82.10-86.8 | 1 | (R)WC-50063<br>(L)WC-50063 | WK-886 | CUP | 82.10-84.11<br>84.11-86.8 | (C)BH-94000<br>BH-94003<br>(C)BH-94000<br>BH-94003 | BH-02492<br>BH-02342 | 82.10-86.8 | 3/4 | MC-10136 | MK-4316 | 8210-8411<br>84.11-85.10<br>85.10-86.8 | 15/16<br>15/16<br>15/16 | CC-70154<br>CC-70169<br>CC-70191 | CK-3133<br>CK-3139<br>CK-3139 |
| (4000ディーゼル) | | | 82.10-84.11<br>84.11-87.8<br>87.8-90.1 | 7/8<br>7/8<br>15/16 | | TK-9413<br>TK-9457<br>TK-T308 | 82.10-90.1 | | DISC | SP-217 | CPS-217+CPS-217B | 82.10-90.1 | 1 | (R)WC-50063<br>(L)WC-50063 | WK-886 | CUP | 82.10-84.11<br>84.11-90.1 | (C)BH-31304<br>BH-94003<br>(C)BH-31304<br>BH-94003 | BH-02492<br>BH-02342 | 82.10-90.1 | 3/4 | MC-10136 | MK-4316 | 8210-8411<br>84.11-90.1 | 13/16<br>13/16 | CC-70155<br>CC-70168 | CK-3109<br>CK-3138 |
| | N－HJ60V | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | P－HJ61V | | 85.10-87.8<br>87.8-90.1 | 7/8<br>15/16 | | TK-9457<br>TK-T308 | 85.10-90.1 | | DISC | SP-217 | CPS-217+CPS-217B | 85.10-90.1 | 1 | (R)WC-50063<br>(L)WC-50063 | WK-886 | CUP | 85.10-90.1 | (C)BH-31304<br>BH-94003 | BH-02342 | 85.10-90.1 | 3/4 | MC-10136 | MK-4316 | 85.10-90.1 | 13/16 | CC-70168 | CK-3138 |
| (4200) | J－FJ60V | ドラム車 | 80.8-81.10 | 1 | | TK-9412 | 80.8-81.10 | 1 1/4 | | WK-407 | CUP | 80.8-81.10 | 1 | (R)WC-50063<br>(L)WC-50063 | WK-886 | CUP | 80.8-81.10 | (C)BH-31304<br>BH-94003 | BH-02492 | 80.8-81.10 | 3/4 | MC-10093 | MK-4305 | 80.8-81.10 | 13/16 | CC-70138 | CK-3109 |
| | | ディスク車 | 80.8-82.10 | 7/8 | | TK-9413 | 80.8-82.10 | | DISC | SP-217 | CPS-217+CPS-217B | 80.8-82.10 | 1 | (R)WC-50063<br>(L)WC-50063 | WK-886 | CUP | 80.8-82.10 | (C)BH-31304<br>BH-94003 | BH-02492 | 80.8-82.10 | 3/4 | MC-10093 | MK-4305 | 80.8-82.10 | 13/16 | CC-70138 | CK-3109 |
| | | 消防車 | 8011-8210 | 1 | TD-T197 | TK-9416 | 8011-8210 | 1 1/8 | (R-1)WC-52023<br>(R-2)WC-51023<br>(L-1)WC-54023<br>(L-2)WC-53023 | WK-406 | CUP | 8011-8210 | 1 1/8 | (R)WC-50064<br>(L)WC-50064 | WK-539 | CUP | 80.11-82.10 | (C)BH-31304<br>BH-94003 | BH-02492 | 8011-8210 | 3/4 | MC-10093 | MK-4305 | 8011-8210 | 13/16 | CC-70138 | CK-3109 |
| (4200) | M－FJ61V | | 8210-8411 | 7/8 | | TK-9413 | 8210-8411 | | DISC | SP-217 | CPS-217+CPS-217B | 8210-8411 | 1 | (R)WC-50063<br>(L)WC-50063 | WK-886 | CUP | 82.10-84.11 | (C)BH-31304<br>BH-94003 | BH-02492 | 8210-8411 | 3/4 | MC-10136 | MK-4316 | 8210-8411 | 13/16 | CC-70138 | CK-3109 |
| | | 消防車 | 8210-8411 | 1 | TD-T197 | TK-9416 | 8210-8411 | 1 1/8 | (R-1)WC-52023<br>(R-2)WC-51023<br>(L-1)WC-54023<br>(L-2)WC-53023 | WK-406 | CUP | 8210-8411 | 1 1/8 | (R)WC-50064<br>(L)WC-50064 | WK-539 | CUP | 82.10-84.11 | (C)BH-31304<br>BH-94003 | BH-02492 | 8210-8411 | 3/4 | MC-10093 | MK-4305 | 8210-8411 | 13/16 | CC-70138 | CK-3109 |
| | E－FJ62G<br>M－FJ62V | | 84.11-87.8<br>87.8-90.1 | 7/8<br>15/16 | | TK-9457<br>TK-T308 | 84.11-90.1 | | DISC | SP-217 | CPS-217+CPS-217B | 84.11-90.1 | 1 | (R)WC-50063<br>(L)WC-50063 | WK-886 | CUP | 84.11-90.1 | (C)BH-31304<br>BH-94003 | BH-02342 | 84.11-90.1 | 3/4 | MC-10136 | MK-4316 | 84.11-90.1 | 13/16 | CC-70168 | CK-3138 |
| | | 消防車 | 87.8-90.1 | 7/8 | | TK-9457 | 87.8-90.1 | | DISC | SP-217 | CPS-217+CPS-217B | 87.8-90.1 | 1 | (R)WC-50063<br>(L)WC-50063 | WK-886 | CUP | 87.8-90.1 | (C)BH-31304<br>BH-94003 | BH-02342 | 87.8-90.1 | 3/4 | | MK-4322 | 87.8-90.1 | 13/16 | CC-70168 | CK-3138 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LAND CRUISER : 70 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2400ディーゼル) | | | 85.10-90.3 | 7/8 | | TK-9457 | 85.10-90.1 | | DISC | SP-217 | CPS-217+CPS-217B | 85.10-90.3 | 15/16 | (R)WC-50047 | WK-309 | CUP | 85.10-90.3 | (C)BH-02364 | BH-94017 | 85.10-87.10 | 5/8 | MC-T261 | MK-4328 | 85.10-90.3 | 13/16 | CC-70177 | CK-3144 |
| | N－LJ71G | | 90.4-93.5 | 15/16 | | | 90.1-93.5 | | DISC | SP-217 | CPS-217+CPS-217B | | | (L)WC-50047 | | | | BH-02467 | | 87.10-90.3 | 5/8 | | MK-4353 | 90.4-93.5 | 13/16 | | CK-3144 |
| | ＜Q－は87．8～＞ | | | | | | | | | | | 90.4-93.5 | 48.1 | DISC | SP-259 | CPS-259 | 90.4-93.5 | (C)BH-02364 | (C)BH-94000 | 90.4-93.5 | 5/8 | | | | | | |
| | | | | | | | | | | | | | | | | | | BH-94003 | (R)BH-T577 | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | (L)BH-T578 | | | | | | | | |
| | Q－LJ78G･78W | | 90.4-93.5 | 15/16 | | | 90.4-93.5 | 42.8 | DISC | SP-253 | CPS-253 | 90.4-93.5 | 48.1 | DISC | SP-259 | CPS-259 | 90.4-93.5 | (C)BH-02364 | (C)BH-94000 | 90.4-93.5 | 5/8 | | | 90.4-93.5 | 13/16 | | CK-3144 |
| | | | | | | | | | | | | | | | | | | BH-94003 | (R)BH-T577 | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | (L)BH-T578 | | | | | | | | |
| (3000ディーゼル) | | | 93.5-96.4 | 15/16 | | TK-T338 | 93.5-96.4 | 42.8 | DISC | SP-253 | CPS-253 | 93.5-96.4 | 48.1 | DISC | SP-259 | CPS-259 | 93.5-96.4 | (C)BH-02364 | (C)BH-94000 | 93.5-94.5 | 5/8 | | MK-T236 | 93.5-93.11 | 3/4 | CC-T389 | |
| | Y－KZJ71G･71W | | | | | | | | | | | | | | | | | BH-94003 | (R)BH-T577 | 94.5-96.4 | 5/8 | | MK-T244 | 93.11-96.4 | 3/4 | CC-T389 | CK-T212 |
| | Y－KZJ78G･78W | | | | | | | | | | | | | | | | | | (L)BH-T578 | | | | | | | | |
| | ＜KD－は95．1～＞ | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | <BJ70･73> | | | |
| (3400ディーゼル) | | | 84.11-90.1 | 7/8 | | TK-9457 | 84.11-90.1 | | DISC | SP-217 | CPS-217+CPS-217B | 84.11-90.1 | 1 | (R)WC-50063 | WK-886 | CUP | 84.11-90.1 | (C)BH-94014 | BH-02492 | 84.11-90.1 | 3/4 | MC-T259 | MK-4322 | 84.11-85.10 | 15/16 | CC-70169 | CK-3139 |
| | N－BJ70･70V･73V | | | | | | | | | | | | | (L)WC-50063 | | | | BH-94003 | | <ブースター付> | | | | 85.10-90.1 | 15/16 | CC-70191 | CK-3139 |
| | P－BJ71V･74V | | | | | | | | | | | | | | | | | | | 84.11-85.10 | 3/4 | MC-10136 | MK-4316 | <BJ71･74> | | | |
| | ＜P－は85．10～＞ | | | | | | | | | | | | | | | | | | | 85.10-90.1 | 3/4 | MC-T371 | MK-4316 | 85.10-90.1 | 7/8 | CC-70184 | CK-3141 |
| | ＜S－は87．8～＞ | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (3500ディーゼル) | | | 90.1-91.8 | 15/16 | | | 90.1-94.1 | 42.8 | DISC | SP-253 | CPS-253 | 90.1-94.1 | 1 | (R)WC-50063 | WK-886 | CUP | 90.1-94.1 | (C)BH-T871 | BH-94001 | 90.1-94.1 | 3/4 | | | 90.1-91.9 | 7/8 | | CK-T204 |
| | S－PZJ70･70V | | 91.8-94.1 | 15/16 | | TK-T338 | | | | | | | | (L)WC-50063 | | | | BH-94003 | | <ブースター付> | | | | 91.9-94.1 | 7/8 | | CK-T204 |
| | S－PZJ77V･77HV | | | | | | | | | | | | | | | | | | | 90.1-94.1 | 3/4 | MC-T283 | | | | | |
| | ＜U－は90．4～＞ | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (4000) | T－FJ75 | 消防車 | 90.6-92.8 | 15/16 | | | 90.6-92.8 | 42.8 | DISC | SP-253 | CPS-253 | 90.6-92.8 | 1 | (R)WC-50063 | WK-886 | CUP | 90.6-92.8 | (C)BH-T871 | BH-94001 | 90.6-92.8 | 3/4 | | | 90.6-92.8 | 13/16 | CC-70168 | CK-T203 |
| | | | | | | | | | | | | | | (L)WC-50063 | | | | BH-94003 | | | | | | | | | |
| | CBF－GRJ76K | 限定車 | 14.8- | | | | 14.8- | | DISC | SP-001 | | 14.8- | | DISC | SP-259 | CPS-259 | 14.8- | (R) | (R) | 14.8- | | | | 14.8- | | | |
| | CBF－GRJ79K | | | | | | | | | | | | | | | | | (L) | (L) | | | | | | | | |
| (4200ディーゼル) | | | | | | | | | | | | <ZX> | | | | | <ZX> | | | | | | | | | | |
| | U－HZJ70･70V | | 90.1-91.8 | 15/16 | | | 90.1-97.8 | 42.8 | DISC | SP-253 | CPS-253 | 90.1-99.8 | 48.1 | DISC | SP-259 | CPS-259 | 90.1-99.8 | (C)BH-T871 | (C)BH-94001 | 90.1-99.8 | 3/4 | MC-T283 | | 90.1-99.8 | 13/16 | | CK-T203 |
| | S･U－HZJ73V･73HV | | 91.8-99.8 | 15/16 | | TK-T338 | 97.8-99.8 | 42.8 | DISC | SP-253 | CPS-253B | <LX> | | | | | | BH-94003 | (R)BH-T577 | | | | | <HZJ70ブースター無> | | | |
| | U－HZJ77V･77HV | | | | | | | | | | | 94.1-99.8 | 1 | (R)WC-50063 | WK-886 | CUP | | | (L)BH-T578 | | | | | 94.1-99.8 | 7/8 | | CK-T204 |
| | ＜KB－は94．1～＞ | | | | | | | | | | | | | (L)WC-50063 | | | <LX> | | | | | | | <HZJ70ブースター付> | | | |
| | ＜KC－は95．1～＞ | | | | | | | | | | | | | | | | 94.1-99.8 | (C)BH-T871 | BH-94001 | | | | | 94.1-99.8 | 13/16 | | CK-T203 |
| | | | | | | | | | | | | | | | | | | BH-94003 | | | | | | | | | |
| | U－HZJ75 | 消防車 | 92.12-99.8 | 15/16 | | TK-T338 | 92.12-97.8 | 42.8 | DISC | SP-253 | CPS-253 | 92.12-99.8 | 1 | (R)WC-50063 | WK-886 | CUP | 92.12-99.8 | (C)BH-T871 | BH-94001 | 92.12-99.8 | 3/4 | | | 92.12-99.8 | 13/16 | | CK-T203 |
| | ＜KC－は95．1～＞ | | | | | | 97.8-99.8 | 42.8 | DISC | SP-253 | CPS-253B | | | (L)WC-50063 | | | | BH-94003 | | | | | | | | | |
| (4200ディーゼル) | | | 99.8-04.8 | 15/16 | | TK-T411 | 99.8-04.8 | | DISC | SP-001 | | 99.8-04.8 | 1 | (R)WC-50063 | WK-886 | CUP | 99.8-04.8 | (C) | BH-T920 | 99.8-04.8 | 3/4 | | | 99.8-04.8 | 7/8 | | CK-T225 |
| | KG－HZJ71･71V | | | | | | | | | | | | | (L)WC-50063 | | | | BH-T921 | | | | | | | | | |
| | KG－HZJ74K･74V | Z X | 99.8-04.8 | 15/16 | | TK-T411 | 99.8-04.8 | | DISC | SP-001 | | 99.8-04.8 | 48.1 | DISC | SP-259 | CPS-259 | 99.8-04.8 | (C) | (C)BH-T920 | 99.8-04.8 | 3/4 | | | 99.8-04.8 | 7/8 | | CK-T225 |
| | KG－HZJ76K･76V | | | | | | | | | | | | | | | | | BH-T921 | (R) | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | (L) | | | | | | | | |
| | | L X | 99.8-04.8 | 15/16 | | TK-T411 | 99.8-04.8 | | DISC | SP-001 | | 99.8-04.8 | 1 | (R)WC-50063 | WK-886 | CUP | 99.8-04.8 | (C) | BH-T920 | 99.8-04.8 | 3/4 | | | 99.8-04.8 | 7/8 | | CK-T225 |
| | | | | | | | | | | | | | | (L)WC-50063 | | | | BH-T921 | | | | | | | | | |
| | KG－HZJ79 | 消防車 | 99.11-04.8 | 15/16 | | TK-T411 | 99.11-04.8 | | DISC | SP-001 | | 99.11-04.8 | 1 | | WK-886 | CUP | 99.11-04.8 | (C) | BH-T920 | 99.11-04.8 | 3/4 | | | 99.11-04.8 | 7/8 | | CK-T225 |
| | | | | | | | | | | | | | | | | | | BH-T921 | | | | | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LAND CRUISER : 80 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (4000) | E−FJ80G | | 90.1−92.8 | 1 | | TK−T378 | 90.1−92.8 | 45.4 | DISC | SP−265 | CPS−265 | 90.1−92.8 | 48.1 | DISC | SP−259 | CPS−259 | 90.1−92.8 | (C)BH−T579<br>(R)BH−T576<br>(L)BH−T575 | (C)BH−94006<br>(R)BH−T577<br>(L)BH−T578 | | | (オートマチック) | | | | | |
| (4500) | E−FZJ80G | 四輪ディスク・アンチスキッド無<br>(VX・VXリミテッド) | 92.8−95.1<br>95.1−96.8 | 1<br>1 | | TK−T378<br>TK−T378 | 92.8−96.8 | 45.4 | DISC | SP−265 | CPS−265 | 92.8−96.8 | 48.1 | DISC | SP−259 | CPS−259 | 92.8−95.1<br><br>95.1−96.8 | (C)BH−T579<br>BH−T623<br><br>(C)<br>BH−T623 | (C)BH−94006<br>(R)BH−T577<br>(L)BH−T578<br>(C)BH−T797<br>(R)BH−T577<br>(L)BH−T578 | 92.8−95.1<br>95.1−96.8 | 3/4 | (オートマチック) | | 95.1−96.8 | 7/8 | | CK−T209 |
| | | 四輪ディスク・アンチスキッド車<br>(GX・VX・VXリミテッド) | 92.8−95.1<br>95.1−98.1 | 1<br>1 | | TK−T328<br>TK−T377 | 92.8−98.1 | 45.4 | DISC | SP−265 | CPS−265 | 92.8−98.1 | 48.1 | DISC | SP−259 | CPS−259 | 92.8−95.1<br><br>95.1−98.1 | (R−1)<br>(L−1)BH−T579<br>(2)BH−T623<br>(R−1)BH−T664<br>(L−1)<br>(2)BH−T623 | (C)BH−94006<br>(R)BH−T577<br>(L)BH−T578<br>(C)BH−T797<br>(R)BH−T577<br>(L)BH−T578 | 92.8−95.1<br>95.1−98.1 | 3/4 | (オートマチック) | | 95.1−98.1 | 7/8 | | CK−T209 |
| | | リヤードラム車<br>(GX) | 93.5−95.1<br>95.1−96.8 | 1<br>1 | | TK−T378<br>TK−T378 | 93.5−96.8 | 45.4 | DISC | SP−265 | CPS−265 | 93.5−96.8 | 1 | (R)WC−50063<br>(L)WC−50063 | WK−886 | CUP | 93.5−95.1<br><br>95.1−96.8 | (C)BH−T579<br>BH−T623<br>(C)<br>BH−T623 | BH−94006<br><br>BH−T797 | 93.5−95.1<br>95.1−96.8 | 3/4 | (オートマチック) | | 95.1−96.8 | 7/8 | | CK−T209 |
| (4200ディーゼル)<br>U−HZJ81V<br><KC−は95．1〜> | | リヤードラム車<br>(STD・GX) | 90.1−92.8<br>92.8−98.1 | 1<br>1 | | TK−T378<br>TK−T378 | 90.1−98.1 | 45.4 | DISC | SP−265 | CPS−265 | 90.1−98.1 | 1 | (R)WC−50063<br>(L)WC−50063 | WK−886 | CUP | 90.1−92.8<br><br>92.8−95.1<br><br>95.1−98.1 | (C)BH−T579<br>(R)BH−T576<br>(L)BH−T575<br>(C)BH−T579<br>BH−T623<br>(C)<br>BH−T623 | BH−94006<br><br>BH−94006<br><br>BH−T797 | 90.1−98.1<br><ブースター付><br>91.8−95.1 | 3/4<br><br>3/4 | MC−T337 | | 90.1−95.1<br>95.1−98.1 | 13/16<br>7/8 | | CK−T203<br>CK−T209 |
| | | 四輪ディスク・アンチスキッド車<br>(GX・VX・VXリミテッド) | 92.8−95.1<br>95.1−98.1 | 1<br>1 | | TK−T328<br>TK−T377 | 92.8−98.1 | 45.4 | DISC | SP−265 | CPS−265 | 92.8−98.1 | 48.1 | DISC | SP−259 | CPS−259 | 92.8−95.1<br><br>95.1−98.1 | (R−1)<br>(L−1)BH−T579<br>(2)BH−T623<br>(R−1)BH−T664<br>(L−1)<br>(2)BH−T623 | (C)BH−94006<br>(R)BH−T577<br>(L)BH−T578<br>(C)BH−T797<br>(R)BH−T577<br>(L)BH−T578 | 92.8−95.1<br>95.1−98.1 | 3/4<br>3/4 | MC−T372 | | 92.8−95.1<br>95.1−98.1 | 13/16<br>7/8 | | CK−T203<br>CK−T209 |
| | | 四輪ディスク・アンチスキッド無<br>(VX・VXリミテッド) | 93.5−96.8 | 1 | | TK−T378 | 93.5−96.8 | 45.4 | DISC | SP−265 | CPS−265 | 93.5−96.8 | 48.1 | DISC | SP−259 | CPS−259 | 93.5−95.1<br><br>95.1−96.8 | (C)BH−T579<br>BH−T623<br><br>(C)<br>BH−T623 | (C)BH−94006<br>(R)BH−T577<br>(L)BH−T578<br>(C)BH−T797<br>(R)BH−T577<br>(L)BH−T578 | 93.5−95.1<br>95.1−96.8 | 3/4<br>3/4 | MC−T372 | | 93.5−95.1<br>95.1−96.8 | 13/16<br>7/8 | | CK−T203<br>CK−T209 |
| (4200ディーゼル)<br>S−HDJ81V<br><KC−は95．1〜> | | アンチスキッド無<br>(VX・VXリミテッド) | 90.1−92.8<br>92.8−96.8 | 1<br>1 | | TK−T378<br>TK−T378 | 90.1−96.8 | 45.4 | DISC | SP−265 | CPS−265 | 90.1−96.8 | 48.1 | DISC | SP−259 | CPS−259 | 90.1−92.8<br><br>92.8−95.1<br><br>95.1−96.8 | (C)BH−T579<br>(R)BH−T576<br>(L)BH−T575<br>(C)BH−T579<br>BH−T623<br><br>(C)<br>BH−T623 | (C)BH−94006<br>(R)BH−T577<br>(L)BH−T578<br>(C)BH−94006<br>(R)BH−T577<br>(L)BH−T578<br>(C)BH−T797<br>(R)BH−T577<br>(L)BH−T578 | 90.1−95.1<br>95.1−96.8 | 3/4<br>3/4 | MC−T372 | | 90.1−95.1<br>95.1−96.8 | 13/16<br>7/8 | | CK−T203<br>CK−T209 |
| | | アンチスキッド車<br>(GX・VX・VXリミテッド) | 92.8−95.1<br>95.1−98.1 | 1<br>1 | | TK−T328<br>TK−T377 | 92.8−98.1 | 45.4 | MD−101M | SP−265 | CPS−265 | 92.8−98.1 | 48.1 | MD−088 | SP−259 | CPS−259 | 92.8−95.1<br><br>95.1−98.1 | (R−1)<br>(R−2)BH−T623<br>(L−1)BH−T579<br>(L−2)BH−T623<br>(R−1)BH−T664<br>(R−2)BH−T623<br>(L−1)<br>(R−2)BH−T623 | (C)BH−94006<br>(R)BH−T577<br>(L)BH−T578<br><br>(C)BH−T797<br>(R)BH−T577<br>(L)BH−T578 | 92.8−95.1<br>95.1−98.1 | 3/4<br>3/4 | MC−T372 | | 92.8−95.1<br>95.1−98.1 | 13/16<br>7/8 | | CK−T203<br>CK−T209 |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LAND CRUISER PRADO : 90 ser. | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2700) E－RZJ90W･95W<br>＜GF－は99．6～＞ | 96.4-02.9 | 1 | | TK-T377 | 96.4-02.9 | | DISC | SP-292 | CPS-292 | 96.4-02.9 | 48.1 | DISC | SP-259 | CPS-259 | 96.4-99.6<br>99.6-02.9 | BH-T716<br>BH-T837 | (R)BH-T577<br>(L)BH-T578<br>(R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (3400) E－VZJ90W･95W<br>＜GF－は99．6～＞ | 96.4-02.9<br>＜油圧ﾌﾞｰｽﾀｰ＞<br>99.6-02.9 | 1 | | TK-T377 | 96.4-02.9 | | DISC | SP-292 | CPS-292 | 96.4-02.9 | 48.1 | DISC | SP-259 | CPS-259 | 96.4-99.6<br>99.6-02.9<br>＜油圧ﾌﾞｰｽﾀｰ＞<br>99.6-02.9 | BH-T716<br>BH-T837 | (R)BH-T577<br>(L)BH-T578<br>(R)<br>(L) | 96.4-02.9 | 5/8 | MC-T461 | MK-T244 | 96.4-02.9 | 13/16 | | CK-T201 |
| (3000ディーゼル)<br>KD－KZJ90W･95W<br>＜KH－は99．6～＞ | 96.4-00.8<br>＜油圧ﾌﾞｰｽﾀｰ＞<br>99.6-00.8 | 1 | | TK-T377 | 96.4-00.8 | | DISC | SP-292 | CPS-292 | 96.4-00.8 | 48.1 | DISC | SP-259 | CPS-259 | 96.4-99.6<br>99.6-00.8<br>＜油圧ﾌﾞｰｽﾀｰ＞<br>99.6-00.8 | BH-T716<br>BH-T837 | (R)BH-T577<br>(L)BH-T578<br>(R)<br>(L) | 96.4-00.8 | 5/8 | | MK-T244 | 96.4-00.8 | 3/4 | CC-T391 | CK-T212 |
| KH－KDJ90W･95W | 00.8-02.11<br>＜油圧ﾌﾞｰｽﾀｰ＞<br>00.8-02.11 | 1 | | TK-T377 | 00.8-02.11 | | DISC | SP-292 | CPS-292 | 00.8-02.11 | 48.1 | DISC | SP-259 | CPS-259 | 00.8-02.11<br>＜油圧ﾌﾞｰｽﾀｰ＞<br>00.8-02.11 | BH-T837 | (R)<br>(L) | 00.8-02.11 | 5/8 | | MK-T244 | 00.8-01.5<br>01.5-02.11 | 3/4 | CC-T391<br>CC-T391 | CK-T212 |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LAND CRUISER : 100 ser.(98.1-) | | | | | | | | | | | | | | | | | | | | | | | | | |
| (4700) GF-UZJ100W<br><GH-は02. 8～> | 98.1- | | | | 98.1-02.8<br>02.8- | | DISC<br>DISC | SP-101<br>SP-101A | CPS-101+CPS-101B<br>CPS-101AB+CPS-101A | 98.1- | | DISC | SP-100 | CPS-137 | 98.1-<br><VSC付><br>99.7- | (R)BH-T925<br>(L)BH-T798<br>(R)BH-T925<br>(L)BH-T798 | (C)BH-T922<br>(R)BH-T923<br>(L)BH-T924<br>(R-1)<br>(L-1)<br>(R-2)BH-T923<br>(L-2)BH-T924 | | | (オートマチック) | | | | |
| (4200ディーゼル)<br>KG-HDJ101K<br><KR-は02. 8～> | 98.1- | | | | 98.1-02.8<br>02.8- | | DISC<br>DISC | SP-101<br>SP-101A | CPS-101+CPS-101B<br>CPS-101AB+CPS-101A | 98.1- | | DISC | SP-100 | CPS-137 | 98.1-<br><VSC付><br>99.7- | (R)BH-T925<br>(L)BH-T798<br>(R)BH-T925<br>(L)BH-T798 | (C)BH-T922<br>(R)BH-T923<br>(L)BH-T924<br>(R-1)<br>(L-1)<br>(R-2)BH-T923<br>(L-2)BH-T924 | 98.1-02.8<br>02.8- | 3/4 | (オートマチック) | | 98.1- | 15/16 | | CK-T228 |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LAND CRUISER PRADO : 120 ser.(02.9-) | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2700) | LA－RZJ120W<br>LA－RZJ125W | 02.9-04.8 | | | ｷｯﾄｾｯﾃｲﾅｼ | 02.9-04.8 | | DISC | MP-141 | CPS-292 | 02.9-04.8 | | DISC | SP-259 | CPS-259 | 02.9-04.8 | (R)<br>(L) | (C)<br>(R)BH-T926<br>(L)BH-T927 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | CBA－TRJ120W | 04.8-09.9 | | | ｷｯﾄｾｯﾃｲﾅｼ | 04.8-05.9<br>05.9-09.9 | | DISC<br>DISC | MP-141<br>SP-119A | CPS-292<br>CPS-292 | 04.8-09.9 | | DISC | SP-259 | CPS-259 | 04.8-09.9 | (R)<br>(L) | (R-1)<br>(L-1)<br>(R-2)BH-T926<br>(L-2)BH-T927 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | CBA－TRJ125W | 04.8-09.9 | | | ｷｯﾄｾｯﾃｲﾅｼ | 04.8-05.9<br>05.9-09.9 | | DISC<br>DISC | MP-141<br>SP-119A | CPS-292<br>CPS-292 | 04.8-07.7<br>07.7-09.9 | | DISC<br>DISC | SP-259<br>SP-120 | CPS-259 | 04.8-09.9 | (R)<br>(L) | (R-1)<br>(L-1)<br>(R-2)BH-T926<br>(L-2)BH-T927 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (3400) | TA－VZJ120W<br>TA－VZJ121W<br>TA－VZJ125W | 02.9-05.8<br><VSC付><br>02.9-04.8<br>04.8-05.8 | | | ｷｯﾄｾｯﾃｲﾅｼ | 02.9-05.8 | | DISC | MP-141 | CPS-292 | 02.9-05.8 | | DISC | SP-259 | CPS-259 | 02.9-05.8 | (R)<br>(L) | (C)<br>(R)BH-T926<br>(L)BH-T927 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (3000ディーゼル) | KN－KDJ120W<br>KN－KDJ121W<br>KN－KDJ125W | 02.9-07.7<br><VSC付><br>02.9-04.8<br>04.8-07.7 | | | ｷｯﾄｾｯﾃｲﾅｼ | 02.9-05.9<br>05.9-07.7 | | DISC<br>DISC | MP-141<br>SP-119A | CPS-292<br>CPS-292 | 02.9-07.7 | | DISC | SP-259 | CPS-259 | 02.9-07.7 | (R)<br>(L) | (C)<br>(R)BH-T926<br>(L)BH-T927 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (4000) | CBA－GRJ120W<br>CBA－GRJ121W | 05.8-09.9<br><VSC付><br>05.8-09.9 | | | ｷｯﾄｾｯﾃｲﾅｼ<br>ｷｯﾄｾｯﾃｲﾅｼ | 05.8-05.9<br>05.9-09.9 | | DISC<br>DISC | MP-141<br>SP-119A | CPS-292<br>CPS-292 | 05.8-09.9 | | DISC | SP-259 | CPS-259 | 02.9- | (R)<br>(L) | (R-1)<br>(L-1)<br>(R-2)BH-T926<br>(L-2)BH-T927 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LAND CRUISER PRADO : 150 ser.(09.8-) | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2700) CBA－TRJ150W<br>(4000) CBA－GRJ150W | 09.8- | | | | 09.8- | | DISC | SP-004 | CPS-004 | 09.8- | | DISC | SP-259 | CPS-259 | 09.8-12.7<br><br><br><br>12.8-13.8<br><br><br><br>13.8- | (R)<br>(L)<br><br><br><br>(R)<br>(L)<br><br><br><br>(R)<br>(L) | (R-1)<br>(L-1)<br>(R-2)<br>(L-2)<br>(R-1)<br>(L-1)<br>(R-2)<br>(L-2)<br>(R-1)<br>(L-1)<br>(R-2)<br>(L-2) | | | (オートマチック) | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LAND CRUISER PRADO : 200, 300 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2700) | 3BA－TRJ250W | 24.4- | | | ｷｯﾄｾｯﾃｲﾅｼ | 24.4- | | DISC | | | 24.4- | | DISC | | | 24.4- | | | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (2800ディーゼル) | 3DA－GDJ250W | 24.4- | | | ｷｯﾄｾｯﾃｲﾅｼ | 24.4- | | DISC | SP-139 | | 24.4- | | DISC | | | 24.4- | | | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (3300) | 3DA-FJA300W | 21.7- | | | ｷｯﾄｾｯﾃｲﾅｼ | 21.7- | | DISC | SP-139 | | 21.7- | | DISC | | | 21.7- | | | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (3500) | 3BA-VJA300W | 21.7- | | | ｷｯﾄｾｯﾃｲﾅｼ | 21.7- | | DISC | SP-139 | | 21.7- | | DISC | | | 21.7- | | | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (4600) | CBA－URJ202W | 09.5- | | | | 09.5- | | DISC | SP-139 | CPS-139 | 09.5- | | DISC | MP-128 | CPM-128 | 09.5- | | | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (4700) | CBA－UZJ200W | 07.9-09.5 | | | | 07.9-09.5 | | DISC | SP-139 | CPS-139 | 07.9-09.5 | | DISC | MP-128 | CPM-128 | 07.9-09.5 | | | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| HARRIER : 10 ser.(97.12-) | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2200) | GF－SXU10W | 97.12-00.11 | 1 | | TK-T370 | 97.12-00.11 | | DISC | A-678P | CPA-678 | 97.12-00.11 | | DISC | MP-75 | CPM-75 | 97.12-00.11 | (R)BH-T702<br>(L)BH-T703 | (R)BH-T877<br>(L)BH-T878 | | | (オートマチック) | | | | | |
| | GF－SXU15W(4WD) | 97.12-00.11 | 1 | | TK-T370 | 97.12-00.11 | | DISC | A-678P | CPA-678 | 97.12-00.11 | | DISC | MP-75 | CPM-75 | 97.12-00.11 | (R)BH-T702<br>(L)BH-T703 | (R)BH-T707<br>(L)BH-T706 | | | (オートマチック) | | | | | |
| (2400) | TA－ACU10W | 00.11-03.2 | 1 | | TK-T370 | 00.11-03.2 | | DISC | A-678P | CPA-678 | 00.11-03.2 | | DISC | MP-75 | CPM-75 | 00.11-03.2 | (R)BH-T702<br>(L)BH-T703 | (R)BH-T877<br>(L)BH-T878 | | | (オートマチック) | | | | | |
| | TA－ACU15W(4WD) | 00.11-03.2 | 1 | | TK-T370 | 00.11-03.2 | | DISC | A-678P | CPA-678 | 00.11-03.2 | | DISC | MP-75 | CPM-75 | 00.11-03.2 | (R)BH-T702<br>(L)BH-T703 | (R)BH-T707<br>(L)BH-T706 | | | (オートマチック) | | | | | |
| (3000) | GF－MCU10W<br>＜TA－は00．11～＞ | 97.12-03.2<br><トラクションコントロール付><br>97.12-00.11<br><VSC付><br>00.11-03.2 | 1<br><br>1 | | TK-T370<br><br>TK-T414 | 97.12-01.8<br>01.8-03.2 | | DISC<br>DISC<br><br>DISC | A-678P<br>A-678P | CPA-678<br>CPA-678 | 97.12-00.11<br>00.11-03.2 | | DISC<br>DISC | MP-75<br>MP-75 | CPM-75<br>CPM-75 | 97.12-03.2 | (R)BH-T702<br>(L)BH-T703 | (R)BH-T877<br>(L)BH-T878 | | | (オートマチック) | | | | | |
| | GF－MCU15W(4WD)<br>＜TA－は00．11～＞ | 97.12-03.2<br><VSC付><br>00.11-03.2 | 1 | | TK-T370 | 97.12-01.8<br>01.8-03.2 | | DISC<br>DISC | A-678P<br>A-678P | CPA-678<br>CPA-678 | 97.12-00.11<br>00.11-03.2 | | DISC<br>DISC | MP-75<br>MP-75 | CPM-75<br>CPM-75 | 97.12-03.2 | (R)BH-T702<br>(L)BH-T703 | (R)BH-T707<br>(L)BH-T706 | | | (オートマチック) | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| HARRIER : 30 ser.(03.2-) | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2400) | ACU30W<br>＜CBA－は04．2～＞ | 03.2-12.7 | | | | 03.2-12.7 | | DISC | A-687P | CPA-667 | 03.2-12.7 | | DISC | A-688P | CPA-688 | 03.2-07.5<br><br>07.5-12.7 | (R)BH-T954<br>(L)BH-T955<br>(R)BH-T954<br>(L)BH-T955 | (R)<br>(L)<br>(R)<br>(L) | | | (オートマチック) | | | | | |
| | ACU35W(4WD)<br>＜CBA－は04．2～＞ | 03.2-12.7 | | | | 03.2-12.7 | | DISC | A-687P | CPA-667 | 03.2-12.7 | | DISC | A-688P | CPA-688 | 03.2-12.7 | (R)BH-T954<br>(L)BH-T955 | (R)BH-T952<br>(L)BH-T953 | | | (オートマチック) | | | | | |
| (3000) | MCU30W<br>MCU31W(エアサス)<br>＜CBA－は04．2～＞ | 03.2-06.1 | | | | 03.2-06.1 | | DISC | A-687P | CPA-667 | 03.2-06.1 | | DISC | A-688P | CPA-688 | 03.2-06.1 | (R)BH-T954<br>(L)BH-T955 | (R)<br>(L) | | | (オートマチック) | | | | | |
| | MCU35W(4WD)<br>MCU36W(4WDエアサス)<br>＜CBA－は04．2～＞ | 03.2-06.1 | | | | 03.2-06.1 | | DISC | A-687P | CPA-667 | 03.2-06.1 | | DISC | A-688P | CPA-688 | 03.2-06.1 | (R)BH-T954<br>(L)BH-T955 | (R)BH-T952<br>(L)BH-T953 | | | (オートマチック) | | | | | |
| (3300) | MHU38W(ハイブリッド・4WD) | 05.3-12.7 | | | | 05.3-12.7 | | DISC | A-687P | CPA-667 | 05.3-12.7 | | DISC | A-688P | CPA-688 | 05.3-12.7 | (R)BH-T954<br>(L)BH-T955 | (R)BH-T952<br>(L)BH-T953 | | | (オートマチック) | | | | | |
| (3500) | GSU30W<br>GSU31W | 06.1-10.8 | | | | 06.1-10.8 | | DISC | A-687P | CPA-667 | 06.1-10.8 | | DISC | A-688P | CPA-688 | 06.1-07.5<br><br>07.5-10.8 | (R)BH-T954<br>(L)BH-T955<br>(R)BH-T954<br>(L)BH-T955 | (R)<br>(L)<br>(R)<br>(L) | | | (オートマチック) | | | | | |
| | GSU35W(4WD)<br>GSU36W(4WD) | 06.1-10.8 | | | | 06.1-10.8 | | DISC | A-687P | CPA-667 | 06.1-10.8 | | DISC | A-688P | CPA-688 | 06.1-10.8 | (R)BH-T954<br>(L)BH-T955 | (R)BH-T952<br>(L)BH-T953 | | | (オートマチック) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| HARRIER : 60 ser.(13.12-) | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000) | DBA－ZSU60W | | 13.12- | | | ｷｯﾄｾｯﾃｲﾅｼ | 13.12-17.5<br>17.5- | | DISC<br>DISC | MP-114<br>C-815P | CPM-106 | 13.12- | | DISC | SP-422 | CPS-134 | 13.12- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | | エレガンス仕様<br>G's | 15.1- | | | ｷｯﾄｾｯﾃｲﾅｼ | 15.1- | | DISC | C-815P | | 15.1- | | DISC | SP-422 | CPS-134 | 15.1- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | DBA－ZSU65W | 4WD | 13.12- | | | ｷｯﾄｾｯﾃｲﾅｼ | 13.12-17.5<br>17.5- | | DISC<br>DISC | MP-114<br>C-815P | CPM-106 | 13.12- | | DISC | SP-422 | CPS-134 | 13.12- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | | エレガンス仕様<br>G's | 15.1- | | | ｷｯﾄｾｯﾃｲﾅｼ | 15.1- | | DISC | C-815P | | 15.1- | | DISC | SP-422 | CPS-134 | 15.1- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | DBA－ASU60W･65W | ターボ | 17.5- | | | ｷｯﾄｾｯﾃｲﾅｼ | 17.5- | | DISC | C-815P | | 17.5- | | DISC | | | 17.5- | (R)<br>(L) | (R)<br>(L) | | | | | | | | |
| (2500) | DAA－AVU65W | ハイブリッド | 13.12- | | | ｷｯﾄｾｯﾃｲﾅｼ | 13.12-17.5<br>17.5- | | DISC<br>DISC | MP-114<br>C-815P | CPM-106 | 13.12- | | DISC | SP-422 | CPS-134 | 13.12- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| HARRIER : 80 ser.(2020.6-) | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000) | 6BA-MXUA80 | | 20.6- | 15/16 | TD-T947 | ｷｯﾄｾｯﾃｲﾅｼ | 20.6- | | DISC | | CPM-116 | 20.6- | | MD-462 | | | 20.6- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | 6BA-MXUA85(4WD) | | 20.6- | 15/16 | TD-T947 | ｷｯﾄｾｯﾃｲﾅｼ | 20.6- | | DISC | | CPM-116 | 20.6- | | MD-462 | | | 20.6- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (2500) | 6AA-AXUH80 | ﾊｲﾌﾞﾘｯﾄﾞ | 20.6- | | | ｷｯﾄｾｯﾃｲﾅｼ | 20.6- | | DISC | | CPM-116 | 20.6- | | MD-462 | | | 20.6- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | 6AA-AXUH85(4WD) | ﾊｲﾌﾞﾘｯﾄﾞ | 20.6- | | | ｷｯﾄｾｯﾃｲﾅｼ | 20.6- | | DISC | | CPM-116 | 20.6- | | MD-462 | | | 20.6- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| KLUGER : L/V 20 ser.(00.11-) | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2400) | TA-ACU20W<br>＜UA-は03．8～＞ | | 00.11-07.5 | | | | 00.11-07.5 | | DISC | A-658P | CPA-735 | 00.11-03.8<br>03.8-07.5 | | DISC<br>DISC | MP-100<br>C-688P | | 00.11-03.8<br>03.8-07.5 | (R)BH-T916<br>(L)BH-T912<br>(R)BH-T954<br>(L)BH-T955 | (R)BH-T913<br>(L)BH-T914<br>(R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | |
| | TA-ACU25W(4WD)<br>＜UA-は03．8～＞ | | 00.11-07.5 | | | | 00.11-07.5 | | DISC | A-658P | CPA-735 | 00.11-03.8<br>03.8-07.5 | | DISC<br>DISC | MP-100<br>C-688P | | 00.11-03.8<br>03.8-07.5 | (R)BH-T916<br>(L)BH-T912<br>(R)BH-T954<br>(L)BH-T955 | (R)BH-T707<br>(L)BH-T706<br>(R)BH-T952<br>(L)BH-T953 | | | (ｵｰﾄﾏﾁｯｸ) | | | | |
| (3000) | TA-MCU20W<br>＜UA-は03．8～＞ | | 00.11-07.5 | | | | 00.11-07.5 | | DISC | A-658P | CPA-735 | 00.11-03.8<br>03.8-07.5 | | DISC<br>DISC | MP-100<br>C-688P | | 00.11-03.8<br>03.8-07.5 | (R)BH-T916<br>(L)BH-T912<br>(R)BH-T954<br>(L)BH-T955 | (R)BH-T913<br>(L)BH-T914<br>(R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | |
| | TA-MCU25W(4WD)<br>＜UA-は03．8～＞ | | 00.11-07.5 | | | | 00.11-07.5 | | DISC | A-658P | CPA-735 | 00.11-03.8<br>03.8-07.5 | | DISC<br>DISC | MP-100<br>C-688P | | 00.11-03.8<br>03.8-07.5 | (R)BH-T916<br>(L)BH-T912<br>(R)BH-T954<br>(L)BH-T955 | (R)BH-T707<br>(L)BH-T706<br>(R)BH-T952<br>(L)BH-T953 | | | (ｵｰﾄﾏﾁｯｸ) | | | | |
| (3300) | DAA-MHU28W ﾊｲﾌﾞﾘｯﾄ | | 05.3-07.5 | | | ｾｯﾃｲﾅｼ | 05.3-07.5 | | DISC | A-687P | CPA-667 | 05.3-07.5 | | DISC | A-688P | CPA-688 | 05.3-07.5 | (R)BH-T954<br>(L)BH-T955 | (R)BH-T952<br>(L)BH-T953 | | | (ｵｰﾄﾏﾁｯｸ) | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| RAV4 : 10 ser.(94.4-00.5) | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000) | E－SXA10・11・15・16<br>＜GF－は98．8～＞ | リヤードラム車 | 94.4-00.5 | 7/8 | | TK-T363 | 94.4-00.5 | 54.0 | DISC | SP-290 | CPS-290 | 94.4-00.5 | 11/16 | (R)WC-T604<br>(L)WC-T604 | WK-834 | CUP | 94.4-00.5 | (R)BH-T646<br>(L)BH-T647 | (R)BH-T645<br>(L)BH-T645 | 94.4-00.5 | 5/8 | MC-T429 | MK-T244 | 94.4-96.8<br>96.8-00.5 | 7/8<br>15/16 | | CK-T200<br>CK-T224 |
| | | 四輪ディスク車 | 97.9-00.5 | 7/8 | | TK-T363 | 97.9-00.5 | 54.0 | DISC | SP-290 | CPS-290 | 97.9-00.5 | | DISC | SP-294 | | 97.9-00.5 | (R)BH-T646<br>(L)BH-T647 | (R-1)BH-T645<br>(L-1)BH-T645<br>(R-2)<br>(L-2) | 97.9-00.5 | 5/8 | MC-T429 | MK-T244 | 97.9-00.5 | 15/16 | | CK-T224 |
| (電気自動車) | ECA10 | LEV車 | 96.8-03.4 | | | | 96.8-03.4 | 54.0 | MD-010M | SP-290 | CPS-290 | 96.8-03.4 | | (R)WC-50065<br>(L)WC-50065 | WK-541 | WC-41042 | 96.8-03.4 | (R)BH-T646<br>(L)BH-T647 | (R)BH-T645<br>(L)BH-T645 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | BEA11 | | 96.8-03.4 | | | | 96.8-03.4 | | MD-010M | SP-290 | CPS-290 | 96.8-03.4 | | (R)WC-50065<br>(L)WC-50065 | WK-541 | WC-41042 | 96.8-03.4 | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| RAV4 : 20 ser.(00.5-) | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) | TA-ZCA25W・26W<br>＜UA-は03．8～＞<br>＜CBA-は04．2～＞ | | 00.5-02.8<br>02.8-05.11 | | | | 00.5-05.11 | | DISC | SP-102 | CPS-102 | 00.5-05.11 | 3/4 | (R)WC-T785<br>(L)WC-T785 | WK-899 | CUP | 00.5-05.11 | (R)BH-T795<br>(L)BH-T796 | (R)BH-T876<br>(L)BH-T876 | | | (オートマチック) | | | | | |
| (2000) | TA-ACA20W(4WD)<br>TA-ACA21W(4WD)<br>＜UA-は03．8～＞<br>＜CBA-は04．2～＞ | リヤードラム車 | 00.5-02.8<br>02.8-05.11 | | | | 00.5-05.11 | | DISC | SP-102 | CPS-102 | 00.5-05.11 | 3/4 | | WK-899 | CUP | 00.5-05.11 | (R)BH-T795<br>(L)BH-T796 | (R)BH-T876<br>(L)BH-T876 | 00.5-05.11 | 5/8 | | MK-T244 | 00.5-05.11 | 13/16 | | CK-T201 |
| | | 四輪ディスク車 | 03.7-05.11<br><VSC付><br>03.7-05.11 | | | | 03.7-05.11 | | DISC | SP-102 | CPS-102 | 03.7-05.11 | | DISC | SP-294 | | 03.7-05.11 | (R)BH-T795<br>(L)BH-T796 | (R)<br>(L) | 03.7-05.11 | 5/8 | | MK-T244 | 03.7-05.11 | 13/16 | | CK-T201 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| RAV4 : ACA30 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2400) | DBA－ACA36W | | 05.11-16.6 | | | | 05.11-16.6 | | DISC | MP-114 | CPM-106 | 05.11-11.6<br>11.6-16.6 | | DISC<br>DISC | SP-134<br>SP-422 | CPS-134<br>CPS-134 | 05.11-16.6 | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| | DBA－ACA31W | 4WD | 05.11-16.6 | | | | 05.11-16.6 | | DISC | MP-114 | CPM-106 | 05.11-11.6<br>11.6-16.6 | | DISC<br>DISC | SP-134<br>SP-422 | CPS-134<br>CPS-134 | 05.11-16.6 | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |

| Models TOYOTA | | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| RAV4 : AXAH50, MXAA50 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000) | 6AA－MXAA52 | 2WD | | 19.4- | 15/16 | TD-T947 | ｷｯﾄｾｯﾃｲﾅｼ | 19.4- | | DISC | | CPM-116 | 19.4- | | DISC | | | 19.4- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | 6AA－MXAA54 | 4WD | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2500) | 6AA－AXAH52 | 2WD | | 19.4- | | | ｷｯﾄｾｯﾃｲﾅｼ | 19.4- | | DISC | | CPM-116 | 19.4- | | DISC | | | 19.4- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | 6AA－AXAH54 | 4WD | | 19.4- | | | ｷｯﾄｾｯﾃｲﾅｼ | 19.4- | | DISC | | CPM-116 | 19.4- | | DISC | | | 19.4- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | 6LA－AXAP54 | 4WD | PHV | 20.6- | | | ｷｯﾄｾｯﾃｲﾅｼ | 20.6- | | DISC | | | 20.6- | | DISC | | | 20.6- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| VANGUARD : ACA, GSA ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2400) | DBA－ACA38W | | 08.8-13.11 | | | | 08.8-13.11 | | DISC | MP-114 | CPM-106 | 08.8-11.6<br>11.6-13.11 | | DISC<br>DISC | SP-134<br>SP-422 | CPS-134<br>CPS-134 | 08.8-13.11 | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| | DBA－ACA33W | 4WD | 07.8-13.11 | | | | 07.8-13.11 | | DISC | MP-114 | CPM-106 | 07.8-11.6<br>11.6-13.11 | | DISC<br>DISC | SP-134<br>SP-422 | CPS-134<br>CPS-134 | 07.8-13.11 | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| (3500) | DBA－GSA33W | 4WD | 07.8-12.12 | | | | 07.8-12.12 | | DISC | MP-114 | CPM-106 | 07.8-11.6<br>11.6-12.12 | | DISC<br>DISC | SP-134<br>SP-422 | CPS-134<br>CPS-134 | 07.8-12.12 | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |

| Models TOYOTA | | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| C-HR : NGX, ZYX ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1200) | DBA－NGX10 | 2WD | AT | 19.10- | | | キットセッテイナシ | 19.10- | | DISC | | (GR SPORT)<br>(R)<br>(L)<br>(除くGR SPORT)<br>(R)<br>(L) | 19.10- | | DISC | | | 19.10- | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| | | | MT | 19.10- | | | キットセッテイナシ | 19.10- | | DISC | | (GR SPORT)<br>(R)<br>(L)<br>(除くGR SPORT)<br>(R)<br>(L) | 19.10- | | DISC | | | 19.10- | (R)<br>(L) | (R)<br>(L) | 19.10- | | | キットナシ | 19.10- | | | キットナシ |
| (1200) | DBA－NGX50 | | 4WD | 16.12- | | | キットセッテイナシ | 16.12- | | DISC | | (R)<br>(L) | 16.12-19.10<br>19.10- | | DISC | SP-502 | | 16.12- | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| (1800) | DAA－ZYX10 | | | 16.12-19.10 | | | キットセッテイナシ | 16.12-19.10 | | DISC | | (R)<br>(L) | 16.12-19.10 | | DISC | SP-502 | | 16.12-19.10 | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| | 6AA－ZYX11 | 2WD | | 19.10- | | | キットセッテイナシ | 19.10- | | DISC | | (S)<br>(R)<br>(L)<br>(除くS)<br>(R)<br>(L) | 19.10- | | DISC | | | 19.10- | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |

| Models | TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| BLIZZARD : LD10, 20 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2200ディーゼル) | K－LD10・10V<br>＜N－は82．10～＞ | 80.3-84.4 | 15/16 | | TK-9473 | 80.3-81.10<br>81.10-84.4 | 1<br>2 1/8 | DISC | WK-307<br>A-34AP | CUP | 80.3-84.4 | 7/8 | | WK-464 | CUP | 80.3-81.10<br>81.10-84.4 | BH-2257<br>BH-2272 | BH-2238<br>BH-2273 | | | (ワイヤー式) | | | | | |
| (2400ディーゼル) | N－LD20・20V・21G<br>＜Q－は87．9～＞ | 84.5-90.2 | 15/16 | | TK-9482 | 84.5-88.12<br>88.12-90.2 | 2 1/8<br>2 1/8 | DISC<br>DISC | A-117P<br>A-304P | | 84.5-90.2 | 1 | | WK-308 | CUP | 84.5-90.2 | BH-2298 | BH-2248 | | | (ワイヤー式) | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| RUSH : J200(06.1-) | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1500) | CBA－J200E | 06.1-16.5 | | | | 06.1-16.5 | | DISC | SP-297 | CPS-297 | 06.1-16.5 | 3/4 | (R)WC-D293<br>(L)WC-D293 | WK-899 | CUP | 06.1-16.5 | (R)BH-D245<br>(L)BH-D246 | (R)BH-D247<br>(L)BH-D250 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | CBA－J210E(4WD) | 06.1-16.5 | | | | 06.1-16.5<br><VSC付><br>06.1-16.5 | | DISC<br><br>DISC | SP-297<br><br>SP-297A | CPS-297<br><br>CPS-297 | 06.1-16.5 | 3/4 | (R)WC-D293<br>(L)WC-D293 | WK-899 | CUP | 06.1-16.5 | (R)BH-D245<br>(L)BH-D246 | (R)BH-D247<br>(L)BH-D250 | 06.1-16.5 | 5/8 | MC-D107 | | 06.1-06.7<br>06.8-16.5 | 13/16 | CC-D108 | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| RAIZE : A200 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1000) | 5BA－A200A 2WD | | 19.10-21.11 | | | ｷｯﾄｾｯﾃｲﾅｼ | 19.10-21.11 | | DISC | MP-139 | | 19.10-21.11 | 3/4 | (R)WC-D295<br>(L)WC-D296 | WK-542 | CUP | 19.10-21.11 | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | 5BA－A210A 4WD<br>＜3BA－は21．11～＞ | | 19.10- | | | ｷｯﾄｾｯﾃｲﾅｼ | 19.10- | | DISC | MP-139 | | ＜G,Xｸﾞﾚｰﾄﾞ＞<br>19.10- | 3/4 | (R)WC-D297<br>(L)WC-D297 | WK-1099 | CUP | 19.10-21.10 | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | | | | | | | | | | | | ＜Zｸﾞﾚｰﾄﾞ＞<br>19.10-21.11 | 3/4 | (R)WC-D297<br>(L)WC-D297 | WK-1099 | CUP | 21.11- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | | | | | | | | | | | | 21.11- | 3/4 | (R)WC-D293<br>(L)WC-D293 | WK-899 | CUP | | | | | | | | | | | |
| (1200) | 5BA－A201A 2WD | | 21.11- | | | ｷｯﾄｾｯﾃｲﾅｼ | 21.11- | | DISC | MP-139 | | ＜G,Xｸﾞﾚｰﾄﾞ＞<br>21.11- | 3/4 | (R)WC-D295<br>(L)WC-D296 | WK-542 | CUP | 21.11- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | | | | | | | | | | | | ＜Zｸﾞﾚｰﾄﾞ＞<br>21.11- | 3/4 | (R)WC-D296<br>(L)WC-D295 | WK-542 | CUP | | | | | | | | | | | |
| | 3BA－A202A 2WD | ﾊｲﾌﾞﾘｯﾄﾞ | 21.11- | | | ｷｯﾄｾｯﾃｲﾅｼ | 21.11- | | DISC | MP-139 | | 21.11- | 3/4 | (R)WC-D293<br>(L)WC-D293 | WK-899 | CUP | 21.11- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| MINIACE : UP100 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (800) | UP100(トラック) | STD・DX | 67.11-68.4 | 5/8 | | MK-01048-B | 67.11-68.4 | 3/4 | | WK- | CUP | 67.11-69.9 | 3/4 | | | CUP | <標準ﾃﾞｯｷ><br>67.11-68.12 | BH-31360-A | BH-02219 | | | (ﾜｲﾔｰ式) | | | | | |
| | UP100V(バン) | | 68.4-70.1 | 3/4 | | MK- | 68.4-69.9 | 7/8 | | WK- | CUP | 69.9-71.2 | 13/16 | | | CUP | 68.12-70.8 | BH-31360-A | BH-02011 | | | | | | | | |
| | UP100G(コーチ) | | 70.1-73.9 | 3/4 | | MK-4403 | 69.9-71.2 | 15/16 | | WK- | CUP | 71.2-73.9 | 13/16 | (R)WC-50059 | WK-492 | CUP | 70.8-71.2 | BH-31360-A | BH-02219 | | | | | | | | |
| | | | 73.9-75.1 | 13/16 | | TK-9375 | 71.2-75.11 | 7/8 | (R-1)WC-1046 | WK-054 | CUP | | | (L)WC-50059 | | | 71.2-72.3 | BH-02218 | BH-02170 | | | | | | | | |
| | | | | | | | | | (R-2)WC-2036 | | | 73.9-75.11 | 3/4 | (R)WC-50060 | WK-491 | CUP | 72.3-75.11 | BH-02218 | BH-02219 | | | | | | | | |
| | | | | | | | | | (L-1)WC-3046 | | | | | (L)WC-50060 | | | <ﾊﾞﾝ・ｺｰﾁ> | | | | | | | | | | |
| | | | | | | | | | (L-2)WC-4036 | | | | | | | | <高床三方開> | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | 67.11-71.2 | BH-31360-A | BH-02219 | | | | | | | | |
| | | | | | | | | | | | | | | | | | 71.2-72.3 | BH-02218 | BH-02170 | | | | | | | | |
| | | | | | | | | | | | | | | | | | 72.3-75.11 | BH-02218 | BH-02219 | | | | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| DELIBOY : 10 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1500) | T－KXC10V | STD・DX | 89.7-95.11 | 15/16 | | TK-T314 | 89.7-91.5<br>91.5-95.11 | 2 3/8<br>2 3/8 | DISC<br>DISC | C-226P<br>C-226P | CPC-226<br>CPC-226 | 89.7-95.11 | 15/16 | (R)WC-T657<br>(L)WC-T657 | WK-733 | CUP | 89.7-95.11 | BH-T822 | BH-02221 | 89.7-92.8<br>92.8-94.3<br>94.3-95.11 | 5/8<br>5/8<br>5/8 | MC-T405<br>MC-T405 | MK-T236 | 89.7-94.10<br>94.10-95.11 | 13/16<br>13/16 | CC-70176 | CK-3144<br>CK-T201 |
| (2000ディーゼル) | S－CXC10V | DX | 91.5-94.9 | 15/16 | | TK-T314 | 91.5-94.9 | 2 3/8 | DISC | C-226P | CPC-226 | 91.5-94.9 | 15/16 | (R)WC-T657<br>(L)WC-T657 | WK-733 | CUP | 91.5-94.9 | BH-T822 | BH-02221 | 91.5-92.8<br>92.8-94.3<br>94.3-94.9 | 5/8<br>5/8<br>5/8 | MC-T405<br>MC-T405 | MK-T236 | 91.5-94.9 | 13/16 | CC-70182 | CK-3144 |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| PROBOX, SUCCEED : 50 ser.(02.6-) | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1300) | UB－NCP50V | <ｱﾝﾁｽｷｯﾄﾞ無><br><AT><br>02.6-14.9<br><MT><br>02.6-10.6<br><ｱﾝﾁｽｷｯﾄﾞ付><br><AT><br>02.6-08.8<br>08.8-14.9<br><MT><br>02.6-14.9 | 13/16<br><br>13/16<br><br><br><br>13/16<br><br>13/16 | <br><br>TD-T925<br><br><br><br>TD-T924<br><br>TD-T923 | TK-T430<br><br>TK-T430 | 02.6-14.9 | | DISC | MP-95 | CPM-95 | 02.6-14.9<br><br><br><ｱﾝﾁｽｷｯﾄﾞ無><br>02.6-14.9 | 11/16<br><br><br><br>3/4 | (R)WC-T786<br>(L)WC-T786<br><br><br>(R)WC-T785<br>(L)WC-T785 | WK-834<br><br><br><br>WK-899 | CUP<br><br><br><br>CUP | 02.6-03.8<br><br><br>03.8-14.9 | (R)BH-T771<br>(L)BH-T772<br>(R)BH-T778<br>(L)BH-T779 | (R)BH-T942<br>(L)BH-T942<br>(R)BH-T942<br>(L)BH-T942 | 02.6-14.9 | 5/8 | MC-T472 | MK-T244 | 02.6-14.9 | 3/4 | CC-T392 | CK-T212 |
| (1500) | UB－NCP51V<br>UP－NCP52V<br>＜UP－は03．4～＞ | <ｱﾝﾁｽｷｯﾄﾞ無><br><AT><br>02.6-14.9<br><MT><br>02.6-10.6<br><ｱﾝﾁｽｷｯﾄﾞ付><br><AT><br>02.6-08.8<br>08.8-14.9<br><MT><br>02.6-14.9 | 13/16<br><br>13/16<br><br><br><br>13/16<br><br>13/16 | <br><br>TD-T925<br><br><br><br>TD-T924<br><br>TD-T923 | TK-T430<br><br>TK-T430 | 02.6-14.9 | | DISC | MP-95 | CPM-95 | 02.6-14.9<br><br><br><ｱﾝﾁｽｷｯﾄﾞ無><br>02.6-14.9 | 11/16<br><br><br><br>3/4 | (R)WC-T786<br>(L)WC-T786<br><br><br>(R)WC-T785<br>(L)WC-T785 | WK-834<br><br><br><br>WK-899 | CUP<br><br><br><br>CUP | 02.6-03.8<br><br><br>03.8-14.9 | (R)BH-T771<br>(L)BH-T772<br>(R)BH-T778<br>(L)BH-T779 | (R)BH-T942<br>(L)BH-T942<br>(R)BH-T942<br>(L)BH-T942 | 02.6-14.9 | 5/8 | MC-T472 | MK-T244 | 02.6-14.9 | 3/4 | CC-T392 | CK-T212 |
| | UA－NCP58G | <AT><br>02.6-08.8<br>08.8-14.4<br><MT><br>02.6-14.4 | <br><br>13/16<br><br>13/16 | <br><br>TD-T924<br><br>TD-T923 | | 02.6-14.4<br><14インチホイール><br>02.6-04.11<br>04.11-14.4 | | DISC<br><br>DISC<br>DISC | MP-95<br><br>MP-90<br>MP-90 | CPM-95<br><br>CPM-90<br>CPM-90 | 02.6-14.4 | 11/16 | (R)WC-T786<br>(L)WC-T786 | WK-834 | CUP | 02.6-03.8<br><br>03.8-14.4 | (R)BH-T771<br>(L)BH-T772<br>(R)BH-T778<br>(L)BH-T779 | (R)BH-T942<br>(L)BH-T942<br>(R)BH-T942<br>(L)BH-T942 | 02.6-14.4 | 5/8 | MC-T472 | MK-T244 | 02.6-14.4 | 3/4 | CC-T392 | CK-T212 |
| | UB－NCP55V（4WDバン） | <ｱﾝﾁｽｷｯﾄﾞ無><br><AT><br>02.6-10.9<br><MT><br>02.6-10.6<br><ｱﾝﾁｽｷｯﾄﾞ付><br><AT><br>02.6-08.8<br>08.8-14.9<br><MT><br>02.6-14.9 | 13/16<br><br>13/16<br><br><br><br>13/16<br><br>13/16 | <br><br>TD-T925<br><br><br><br>TD-T924<br><br>TD-T923 | TK-T430<br><br>TK-T430 | 02.6-14.9 | | DISC | MP-95 | CPM-95 | 02.6-14.9<br><br><br><ｱﾝﾁｽｷｯﾄﾞ無><br>02.6-14.9 | 11/16<br><br><br><br>3/4 | (R)WC-T786<br>(L)WC-T786<br><br><br>(R)WC-T785<br>(L)WC-T785 | WK-834<br><br><br><br>WK-899 | CUP<br><br><br><br>CUP | 02.6-14.9 | (R)BH-T780<br>(L)BH-T781 | (R)BH-T942<br>(L)BH-T942 | 02.6-14.9 | 5/8 | MC-T472 | MK-T244 | 02.6-14.9 | 3/4 | CC-T392 | CK-T212 |
| | UA－NCP59G（4WDワゴン） | <AT><br>02.6-08.8<br>08.8-14.4<br><MT><br>02.6-14.4 | <br><br>13/16<br><br>13/16 | <br><br>TD-T924<br><br>TD-T923 | | 02.6-14.4<br><14インチホイール><br>02.6-04.11<br>04.11-14.4 | | DISC<br><br>DISC<br>DISC | MP-95<br><br>MP-90<br>MP-90 | CPM-95<br><br>CPM-90<br>CPM-90 | 02.6-14.4 | 11/16 | (R)WC-T786<br>(L)WC-T786 | WK-834 | CUP | 02.6-14.4 | (R)BH-T780<br>(L)BH-T781 | (R)BH-T942<br>(L)BH-T942 | 02.6-14.4 | 5/8 | MC-T472 | MK-T244 | 02.6-14.4 | 3/4 | CC-T392 | CK-T212 |
| (1400ディーゼル)<br>KP－NLP51V | | <ｱﾝﾁｽｷｯﾄﾞ無><br>02.6-07.8<br><ｱﾝﾁｽｷｯﾄﾞ付><br>02.6-07.8 | 13/16<br><br>13/16 | TD-T925<br><br>TD-T923 | TK-T430 | 02.6-07.8 | | DISC | MP-95 | CPM-95 | 02.6-07.8<br><ｱﾝﾁｽｷｯﾄﾞ無><br>02.6-07.8 | 11/16<br><br>3/4 | (R)WC-T786<br>(L)WC-T786<br><br>(R)WC-T785<br>(L)WC-T785 | WK-834<br><br>WK-899 | CUP<br><br>CUP | 02.6-03.8<br><br>03.8-07.8 | (R)BH-T771<br>(L)BH-T772<br>(R)BH-T778<br>(L)BH-T779 | (R)BH-T942<br>(L)BH-T942<br>(R)BH-T942<br>(L)BH-T942 | 02.6-07.8 | 5/8 | MC-T472 | MK-T244 | 02.6-07.8 | | | CK-T232 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| PROBOX, SUCCEED : 160 ser.(14.9-) | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1300) | DBE-NSP160V | | 14.9- | | | ｷｯﾄｾｯﾃｲﾅｼ | 14.9-15.3<br>15.4- | 54 | DISC<br>DISC | MP-110<br>MP-136 | | 14.9- | 13/16 | (R)WC-T787<br>(L)WC-T787 | WK-900 | CUP | 14.9- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (1500) | DBE-NCP160V | | 14.9- | | | ｷｯﾄｾｯﾃｲﾅｼ | 14.9-15.3<br>15.4- | 54 | DISC<br>DISC | MP-110<br>MP-136 | | 14.9- | 13/16 | (R)WC-T787<br>(L)WC-T787 | WK-900 | CUP | 14.9- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | DBE-NCP165V | | 14.9- | | | ｷｯﾄｾｯﾃｲﾅｼ | 14.9-15.3<br>15.4- | 54 | DISC<br>DISC | MP-110<br>MP-136 | | 14.9- | 13/16 | (R)WC-T787<br>(L)WC-T787 | WK-900 | CUP | 14.9- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | 6AE-NHP160V | ﾊｲﾌﾞﾘｯﾄﾞ | 18.11- | | | ｷｯﾄｾｯﾃｲﾅｼ | 18.11- | | DISC | MP-136 | | 18.11- | 13/16 | (R)WC-T787<br>(L)WC-T787 | WK-900 | CUP | 18.11- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LITEACE, TOWNACE : 10 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1200) | KR10V(バン) | | 76.10-78.2 | 13/16 | | TK-9357 | 76.10-78.2 | 7/8 | (R-1)WC-51001<br>(R-2)WC-52001<br>(L-1)WC-53001<br>(L-2)WC-54001 | WK-113 | CUP | 76.10-78.2<br><LSPV付><br>76.10-78.2 | 11/16<br><br>3/4 | (R)WC-50041<br>(L)WC-50041<br><br>(R)WC-50060<br>(L)WC-50060 | WK-083<br><br>WK-491 | CUP<br><br>CUP | 76.10-78.2 | BH-31405 | BH-31404 | | | (ワイヤー式) | | | | | |
| | KM10(トラック)<br>KM10V(バン)<br>KM10G(ワゴン) | ブースター無 | 70.11-73.9<br>73.9-75.11<br>75.11-78.2 | 3/4<br>3/4<br>3/4 | | MK-4403<br>TK-9332<br>TK-9348 | 70.11-71.10<br><br>71.10-76.10<br><br><br><br>76.10-78.2 | 7/8<br><br>15/16<br><br><br><br>15/16 | (R)WC-31012<br>(L)WC-31011<br>(R-1)WC-5176<br>(R-2)WC-5176<br>(L-1)WC-5376<br>(L-2)WC-5376<br>(R-1)WC-51010<br>(R-2)WC-52010<br>(L-1)WC-53010<br>(L-2)WC-54010 | WK-545<br><br>WK-105<br><br><br><br>WK-105 | CUP<br><br>CUP<br><br><br><br>CUP | 70.11-71.10<br><br>71.10-78.2 | 11/16<br><br>5/8 | (R)WC-50011<br>(L)WC-50011<br>(R)WC-50031<br>(L)WC-50031 | <br><br>WK-045-R | CUP<br><br>CUP | 70.11-71.5<br>71.6-78.2 | BH-02166<br>BH-02202 | BH-02217<br>BH-02217 | | | (ワイヤー式) | | | | | |
| | | ブースター付 | 73.7-75.11<br>75.11-78.2 | 7/8<br>7/8 | | TK-9333<br>TK-9349 | 73.7-76.10<br><br><br><br>76.10-78.2 | 15/16<br><br><br><br>15/16 | (R-1)WC-5176<br>(R-2)WC-5176<br>(L-1)WC-5376<br>(L-2)WC-5376<br>(R-1)WC-51010<br>(R-2)WC-52010<br>(L-1)WC-53010<br>(L-2)WC-54010 | WK-105<br><br><br><br>WK-105 | CUP<br><br><br><br>CUP | 73.7-78.2 | 5/8 | (R)WC-50031<br>(L)WC-50031 | WK-045-R | CUP | 73.7-78.2 | BH-02202 | BH-02217 | | | (ワイヤー式) | | | | | |
| (1300) | KR11V(バン) | | 78.2-79.10 | 13/16 | | TK-9357 | 78.2-79.10 | 7/8 | (R-1)WC-51001<br>(R-2)WC-52001<br>(L-1)WC-53001<br>(L-2)WC-54001 | WK-113 | CUP | 78.2-79.10<br><LSPV付><br>78.2-79.10 | 11/16<br><br>3/4 | (R)WC-50041<br>(L)WC-50041<br><br>(R)WC-50060<br>(L)WC-50060 | WK-083<br><br>WK-491 | CUP<br><br>CUP | 78.2-79.10 | BH-31405 | BH-31404 | | | (ワイヤー式) | | | | | |
| | KM11(トラック)<br>KM11V(バン) | ブースター無 | 78.2-79.9 | 3/4 | | TK-9348 | 78.2-79.9 | 15/16 | (R-1)WC-51010<br>(R-2)WC-52010<br>(L-1)WC-53010<br>(L-2)WC-54010 | WK-105 | CUP | 78.2-79.9 | 5/8 | (R)WC-50031<br>(L)WC-50031 | WK-045-R | CUP | 78.2-79.9 | BH-02202 | BH-02217 | | | (ワイヤー式) | | | | | |
| | | ブースター付 | 78.2-79.9 | 7/8 | | TK-9349 | 78.2-79.9 | 15/16 | (R-1)WC-51010<br>(R-2)WC-52010<br>(L-1)WC-53010<br>(L-2)WC-54010 | WK-105 | CUP | 78.2-79.9 | 5/8 | (R)WC-50031<br>(L)WC-50031 | WK-045-R | CUP | 78.2-79.9 | BH-02202 | BH-02217 | | | (ワイヤー式) | | | | | |
| | KR12V(バン) | ドラム車 | 79.10-82.10 | 7/8 | | TK-9406 | 79.10-82.10 | 15/16 | (R-1)WC-51017<br>(R-2)WC-52017<br>(L-1)WC-53017<br>(L-2)WC-54017 | WK-105 | CUP | 79.10-82.10<br><LSPV付><br>79.10-82.10 | 3/4<br><br>13/16 | (R)WC-50060<br>(L)WC-50060<br><br>(R)WC-50059<br>(L)WC-50059 | WK-491<br><br>WK-492 | CUP<br><br>CUP | 79.10-82.3<br>82.3-82.10 | BH-31405<br>BH-95004 | BH-31404<br>BH-31404 | | | (ワイヤー式) | | | | | |
| | | ディスク車 | 81.1-82.10 | 13/16 | | TK-9407 | 81.1-82.10 | 2 | DISC | C-16P | | 81.1-82.10 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 81.1-82.10 | BH-31404 | BH-31404 | | | (ワイヤー式) | | | | | |
| (1600) | RR10(トラック) | | 78.8-78.9<br>78.9-79.11 | 7/8<br>7/8 | | TK-9393<br>TK-9395 | 78.8-79.11 | 1 | (R-1)WC-51011<br>(R-2)WC-52011<br>(L-1)WC-53011<br>(L-2)WC-54011 | WK-439 | CUP | 78.8-79.11 | 5/8 | (R)WC-50057<br>(L)WC-50057 | WK-440 | CUP | 78.8-79.11 | BH-31305 | BH-02492 | 78.8-79.11 | 5/8 | | MK-4300 | 78.8-79.11 | 15 | CC-70122 | CK-3119 | |
| | RR11(トラック) | | 79.11-82.10 | 7/8 | | TK-9406 | 79.11-82.10 | 15/16 | (R-1)WC-52017<br>(R-2)WC-51017<br>(L-1)WC-54017<br>(L-2)WC-53017 | WK-105 | CUP | 79.11-82.10<br><ジャストロー><br>79.11-82.10 | 5/8<br><br>5/8 | (R)WC-50057<br>(L)WC-50057<br><br>(R)WC-50061<br>(L)WC-50061 | WK-440<br><br>WK-493 | CUP<br><br>CUP | 79.11-82.10 | BH-31305 | BH-31404 | 79.11-82.10 | 5/8 | | MK-4300 | 79.11-82.10 | 15 | CC-70122 | CK-3119 | |
| | TR10V(バン) | | 76.10-79.10 | 13/16 | | TK-9357 | 76.10-79.10 | 7/8 | (R-1)WC-51001<br>(R-2)WC-52001<br>(L-1)WC-53001<br>(L-2)WC-54001 | WK-113 | CUP | 76.10-79.10<br><LSPV付><br>76.10-79.10 | 11/16<br><br>3/4 | (R)WC-50041<br>(L)WC-50041<br><br>(R)WC-50060<br>(L)WC-50060 | WK-083<br><br>WK-491 | CUP<br><br>CUP | 76.10-79.10 | BH-31405 | BH-31404 | 76.10-79.10 | 5/8 | | MK-4300 | 76.10-79.10 | 13/16 | CC-70094 | CK-3107 | |
| | TR11G(ワゴン) | STD・DX | 76.10-78.8 | 13/16 | | TK-9357 | 76.10-78.8 | 7/8 | (R-1)WC-51001<br>(R-2)WC-52001<br>(L-1)WC-53001<br>(L-2)WC-54001 | WK-113 | CUP | 76.10-78.8<br><LSPV付><br>76.10-78.8 | 11/16<br><br>3/4 | (R)WC-50041<br>(L)WC-50041<br><br>(R)WC-50060<br>(L)WC-50060 | WK-083<br><br>WK-491 | CUP<br><br>CUP | 76.10-78.8 | BH-31405 | BH-31404 | 76.10-78.8 | 5/8 | | MK-4300 | 76.10-78.8 | 13/16 | CC-70094 | CK-3107 | |
| | | カスタム | 76.10-78.8 | 13/16 | | TK-9357 | 76.10-78.8 | 2 | DISC | A-16P | | 76.10-78.8 | 11/16 | (R)WC-50041<br>(L)WC-50041 | WK-083 | CUP | 76.10-78.8 | BH-31404 | BH-31404 | 76.10-78.8 | 5/8 | | MK-4300 | 76.10-78.8 | 13/16 | CC-70094 | CK-3107 | |
| | TR11V(バン) | ドラム車 | 79.10-82.10 | 7/8 | | TK-9406 | 79.10-82.10 | 15/16 | (R-1)WC-51017<br>(R-2)WC-52017<br>(L-1)WC-53017<br>(L-2)WC-54017 | WK-105 | CUP | 79.10-82.10<br><LSPV付><br>79.10-82.10 | 3/4<br><br>13/16 | (R)WC-50060<br>(L)WC-50060<br><br>(R)WC-50059<br>(L)WC-50059 | WK-491<br><br>WK-492 | CUP<br><br>CUP | 79.10-82.3<br>82.3-82.10 | BH-31405<br>BH-95004 | BH-31404<br>BH-31404 | 79.10-82.10 | 5/8 | | MK-4300 | 79.10-81.1<br>81.1-82.10<br><5速フロアシフト><br>81.1-82.10 | 13/16<br>13/16<br><br>7/8 | CC-70094<br>CC-70128<br><br>CC-70127 | CK-3107<br>CK-3125<br><br>CK-3122 | |
| | | ディスク車 | 81.1-82.10 | 13/16 | | TK-9407 | 81.1-82.10 | 2 | DISC | C-16P | | 81.1-82.10 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 81.1-82.10 | BH-31404 | BH-31404 | 81.1-82.10 | 5/8 | | MK-4300 | 81.1-82.10<br><5速フロアシフト><br>81.1-82.10 | 13/16<br><br>7/8 | CC-70128<br><br>CC-70127 | CK-3125<br><br>CK-3122 | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| (1800) | TR15G(ワゴン) | STD・DX | 78.8-79.10<br>79.10-82.10 | 13/16<br>7/8 | | TK-9357<br>TK-9406 | 78.8-79.10<br><br><br><br>79.10-82.10 | 7/8<br><br><br><br>15/16 | (R-1)WC-51001<br>(R-2)WC-52001<br>(L-1)WC-53001<br>(L-2)WC-54001<br>(R-1)WC-51017<br>(R-2)WC-52017<br>(L-1)WC-53017<br>(L-2)WC-54017 | WK-113<br><br><br><br>WK-105 | CUP<br><br><br><br>CUP | 78.8-79.10<br>79.10-82.10<br><LSPV付><br>78.8-79.10 | 11/16<br>13/16<br><br>3/4 | (R)WC-50041<br>(L)WC-50041<br>(R)WC-50059<br>(L)WC-50059<br>(R)WC-50060<br>(L)WC-50060 | WK-083<br><br>WK-492<br><br>WK-491 | CUP<br><br>CUP<br><br>CUP | 78.8-82.3<br>82.3-82.10 | BH-31405<br>BH-95004 | BH-31404<br>BH-31404 | 78.8-82.10 | 5/8 | | MK-4300 | 78.8-81.2<br>81.2-82.10 | 7/8<br>7/8 | CC-70103<br>CC-70103 | CK-3110<br>CK-3121 |
| | | カスタム<br>スーパーエクストラ<br>キャニオンパッケージ | 79.10-82.10 | 7/8 | | TK-9406 | 79.10-82.10 | 15/16 | (R-1)WC-51017<br>(R-2)WC-52017<br>(L-1)WC-53017<br>(L-2)WC-54017 | WK-105 | CUP | 79.10-82.10 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 79.10-81.1<br>81.1-82.3<br>82.3-82.10 | BH-31404<br>BH-31405<br>BH-95004 | BH-31404<br>BH-31404<br>BH-31404 | 79.10-82.10 | 5/8 | | MK-4300 | 79.10-81.2<br>81.2-82.10<br><5速フロアシフト><br>81.1-82.10 | 7/8<br>7/8<br><br>7/8 | CC-70103<br>CC-70103<br><br>CC-70127 | CK-3110<br>CK-3121<br><br>CK-3122 |
| | | カスタム<br>カスタムエクストラ<br>スーパーエクストラ<br>キャニオンパッケージ | 78.8-79.10<br>79.10-82.10 | 13/16<br>13/16 | | TK-9357<br>TK-9407 | 78.8-79.10<br>79.10-82.10 | 2<br>2 | DISC<br>DISC | A-16P<br>C-16P | | 78.8-79.10<br>79.10-82.10 | 11/16<br>3/4 | (R)WC-50041<br>(L)WC-50041<br>(R)WC-50060<br>(L)WC-50060 | WK-083<br><br>WK-491 | CUP<br><br>CUP | 78.8-82.10 | BH-31404 | BH-31404 | 78.8-82.10 | 5/8 | | MK-4300 | 78.8-81.2<br>81.2-82.10<br><5速フロアシフト><br>81.1-82.10 | 7/8<br>7/8<br><br>7/8 | CC-70103<br>CC-70103<br><br>CC-70127 | CK-3110<br>CK-3121<br><br>CK-3122 |
| | | グランドエクストラ | 81.1-82.10 | 13/16 | | TK-9414 | 81.1-82.10 | 2 | DISC | C-16P | | 81.1-82.10 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 81.1-82.10 | BH-31404 | BH-31404 | 81.1-82.10 | 5/8 | | MK-4300 | 81.1-82.10 | 7/8 | CC-70127 | CK-3122 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LITEACE, TOWNACE : 20 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1300) | KM20(トラック)<br>KM20V(バン)<br>L−KM21(トラック)<br>L−KM21V(バン) | Sタイヤ(ドラム車) | 79.10−82.10<br>82.10−86.9 | 7/8<br>7/8 | | TK−9406<br>TK−9427 | 79.10−86.9 | 15/16 | (R−1)WC−52017<br>(R−2)WC−51017<br>(L−1)WC−54017<br>(L−2)WC−53017 | WK−105 | CUP | 79.10−86.9<br><LSPV付><br>79.10−86.9 | 3/4<br><br>13/16 | (R)WC−50060<br>(L)WC−50060<br>(R)WC−50059<br>(L)WC−50059 | WK−491<br><br>WK−492 | CUP<br><br>CUP | 79.10−82.10<br>82.10−85.8<br><トラック><br>79.10−82.10<br>82.10−86.9 | BH−32805<br>BH−95006<br><br>BH−32805<br>BH−95006 | BH−02342<br>BH−02342<br><br>BH−02342<br>BH−94005 | | | (ワイヤー式) | | | | | |
| | | Sタイヤ(ディスク車) | 79.10−82.10<br>82.10−86.9 | 13/16<br>7/8 | | TK−9407<br>TK−9427 | 79.10−82.10<br>82.10−86.9 | 2<br>2 1/4 | DISC<br>DISC | C−16P<br>A−124P | | 79.10−86.9<br><LSPV付><br>79.10−86.9 | 3/4<br><br>13/16 | (R)WC−50060<br>(L)WC−50060<br>(R)WC−50059<br>(L)WC−50059 | WK−491<br><br>WK−492 | CUP<br><br>CUP | 79.10−83.10<br>83.10−85.8<br><トラック><br>79.10−82.10<br>82.10−83.10<br>83.10−86.9 | BH−T822<br>BH−02394<br><br>BH−T822<br>BH−T822<br>BH−02394 | BH−02342<br>BH−02342<br><br>BH−02342<br>BH−94005<br>BH−94005 | | | (ワイヤー式) | | | | | |
| | | Wタイヤ(ドラム車) | 79.10−82.10<br>82.10−86.9 | 7/8<br>7/8 | | TK−9406<br>TK−9427 | 79.10−86.9 | 15/16 | (R−1)WC−52017<br>(R−2)WC−51017<br>(L−1)WC−54017<br>(L−2)WC−53017 | WK−105 | CUP | 79.10−86.9 | 5/8 | (R)WC−50061<br>(L)WC−50061 | WK−493 | CUP | 79.10−82.10<br>82.10−85.8<br><トラック><br>79.10−82.10<br>82.10−86.9 | BH−32805<br>BH−95006<br><br>BH−32805<br>BH−95006 | BH−94005<br>BH−94008<br><br>BH−02342<br>BH−94005 | | | (ワイヤー式) | | | | | |
| | | Wタイヤ(ディスク車) | 81.1−82.10<br>82.10−86.9 | 13/16<br>7/8 | | TK−9407<br>TK−9427 | 81.1−82.10<br>82.10−86.9 | 2<br>2 1/4 | DISC<br>DISC | C−16P<br>A−124P | | 81.1−86.9 | 5/8 | (R)WC−50061<br>(L)WC−50061 | WK−493 | CUP | 81.1−82.10<br>82.10−83.10<br>83.10−85.8<br><トラック><br>81.1−82.10<br>82.10−83.10<br>83.10−86.9 | BH−T822<br>BH−T822<br>BH−02394<br><br>BH−T822<br>BH−T822<br>BH−02394 | BH−94005<br>BH−94008<br>BH−94008<br><br>BH−02342<br>BH−94005<br>BH−94005 | | | (ワイヤー式) | | | | | |
| | L−KR26V(バン) | ドラム車 | 82.11−85.8 | 7/8 | | TK−9427 | 82.11−85.8 | 15/16 | (R−1)WC−52017<br>(R−2)WC−51017<br>(L−1)WC−54017<br>(L−2)WC−53017 | WK−105 | CUP | 82.11−85.8 | 11/16 | (R)WC−50041<br>(L)WC−50041 | WK−083 | CUP | 82.11−85.8 | BH−95006 | BH−31324 | | | (ワイヤー式) | | | | | |
| | | ディスク車 | 82.11−85.8<br>85.8−90.8 | 15/16<br>15/16 | | TK−9428<br>TK−T011 | 82.11−85.8<br>85.8−88.8<br>88.8−90.8 | 2 1/4<br>60.3<br>60.3 | DISC<br>DISC<br>DISC | A−124P<br>C−226P<br>C−226P | | 82.11−90.8 | 13/16 | (R)WC−50059<br>(L)WC−50059 | WK−492 | CUP | 82.11−83.10<br>83.10−86.8<br>86.8−88.8<br>88.8−90.8 | BH−T822<br>BH−02394<br>BH−02505<br>BH−02505 | BH−31324<br>BH−31324<br>BH−31324<br>BH−02576 | | | (ワイヤー式) | | | | | |
| (1500) | T−KR27V(バン)<br><GAーは95．8〜> | | 90.8−92.1<br>92.1−96.10 | 15/16<br>1 | | TK−T011<br>TK−T335 | 90.8−92.1<br>92.1−96.10 | 60.3<br>2 3/8 | DISC<br>DISC | C−226P<br>A−379P | CPA−379 | 90.8−92.1<br><br>92.1−96.10 | 13/16<br><br>13/16 | (R)WC−50059<br>(L)WC−50059<br>(R)WC−50059<br>(L)WC−50059 | WK−492<br><br>WK−492 | CUP<br><br>CUP | 90.8−92.1<br><低床車><br>92.1−96.10<br><ジャストロー><br>92.1−96.10 | BH−02505<br><br>BH−02505<br><br>BH−02505 | BH−02576<br><br>BH−31324 | 90.8−92.1<br>92.1−94.3<br>94.3−96.10 | 5/8<br>5/8<br>5/8 | MC−T329 | MK−4353 | 90.8−94.10<br>94.10−96.10 | 13/16<br>13/16 | CC−70176 | CK−3144<br>CK−T201 |
| (1600) | RR20(トラック)<br>RR21(トラック) | | 78.8−78.9<br>78.9−79.11<br>79.11−82.10 | 7/8<br>7/8<br>7/8 | | TK−9393<br>TK−9395<br>TK−9406 | 78.8−79.11<br><br><br>79.11−82.10 | 1<br><br><br>15/16 | (R−1)WC−51011<br>(R−2)WC−52011<br>(L−1)WC−53011<br>(L−2)WC−54011<br>(R−1)WC−52017<br>(R−2)WC−51017<br>(L−1)WC−54017<br>(L−2)WC−53017 | WK−439<br><br><br><br>WK−105 | CUP<br><br><br><br>CUP | 78.8−82.10<br><ジャストロー><br>79.11−82.10 | 5/8<br><br>5/8 | (R)WC−50057<br>(L)WC−50057<br><br>(R)WC−50061<br>(L)WC−50061 | WK−440<br><br><br>WK−493 | CUP<br><br><br>CUP | 78.8−82.10<br><br><br>

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | | | | | | (L)WC-50060 | | | | | | | | | | | | | |
| | | DX・XL・GXL(ドラム車) | 79.10-82.10 | 7/8 | | TK-9406 | 79.10-82.10 | 15/16 | (R-1)WC-52017<br>(R-2)WC-51017<br>(L-1)WC-54017<br>(L-2)WC-53017 | WK-105 | CUP | <サイズ確認><br>79.10-82.10<br><br>79.10-82.10 | 13/16<br><br><br>3/4 | (R)WC-50059<br>(L)WC-50059<br>(R)WC-50060<br>(L)WC-50060 | WK-492<br><br>WK-491 | CUP<br><br>CUP | 79.10-82.10 | BH-32805 | BH-02342 | 79.10-82.10 | 5/8 | | MK-4300 | 79.10-80.1<br>80.11-82.10<br><5速フロアシフト><br>81.1-82.10 | 7/8<br>7/8<br><br>7/8 | CC-70103<br>CC-70103<br><br>CC-70127 | CK-3110<br>CK-3122<br><br>CK-3122 |
| | | DX・XL・GXL(ディスク車) | 79.10-82.10 | 13/16 | | TK-9407 | 79.10-82.10 | 2 | DISC | C-16P | | <サイズ確認><br>79.10-82.10<br><br>79.10-82.10 | 13/16<br><br><br>3/4 | (R)WC-50059<br>(L)WC-50059<br>(R)WC-50060<br>(L)WC-50060 | WK-492<br><br>WK-491 | CUP<br><br>CUP | 79.10-82.10 | BH-T822 | BH-02342 | 79.10-82.10 | 5/8 | | MK-4300 | 79.10-80.1<br>80.11-82.10<br><5速フロアシフト><br>81.1-82.10 | 7/8<br>7/8<br><br>7/8 | CC-70103<br>CC-70103<br><br>CC-70127 | CK-3110<br>CK-3122<br><br>CK-3122 |
| | | FXV | 81.1-82.10 | 13/16 | | TK-9414 | 81.1-82.10 | 2 | DISC | C-16P | | 81.1-82.10 | 3/4 | (R)WC-50060<br>(L)WC-50060 | WK-491 | CUP | 81.1-82.10 | BH-T822 | BH-02342 | 81.1-82.10 | 5/8 | | MK-4300 | 81.1-82.10 | 7/8 | CC-70127 | CK-3122 |
| (1800) | E−YR20G(ワゴン) | | 82.11-85.8<br>85.8-92.1 | 15/16<br>1 | | TK-9428<br>TK-T010 | 82.11-85.8<br>85.8-88.8<br>88.8-92.1 | 2 1/4<br>60.3<br>60.3 | DISC<br>DISC<br>DISC | A-124P<br>C-226P<br>C-226P | | <13インチホイール><br>82.11-92.1<br><br><14インチホイール><br>84.8-92.1 | 13/16<br><br><br>7/8 | (R)WC-50059<br>(L)WC-50059<br><br>(R)WC-50035<br>(L)WC-50035 | WK-492<br><br><br>WK-545 | CUP<br><br><br>CUP | 82.11-83.10<br>83.10-86.8<br>86.8-88.8<br>88.8-92.1 | BH-T822<br>BH-02394<br>BH-02505<br>BH-02505 | BH-T871<br>BH-T871<br>BH-T871<br>BH-T871 | 82.11-86.9<br>86.9-92.1 | 5/8<br>5/8 | | MK-4300<br>MK-4353 | 82.11-88.8<br>88.8-92.1 | 13/16<br>13/16 | CC-70145<br>CC-70145 | CK-3144<br>CK-3144 |
| | | ロイヤルラウンジ | 82.11-85.8<br>85.8-88.8 | 15/16<br>1 | | TK-9428<br>TK-T010 | 82.11-85.8<br>85.8-86.8<br>86.8-88.8 | 2 1/4<br>60.3<br>2 1/4 | DISC<br>DISC<br>DISC | A-124P<br>C-226P<br>A-124P | | 82.11-88.8 | 7/8 | (R)WC-50035<br>(L)WC-50035 | WK-545 | CUP | 82.11-83.10<br>83.10-86.8<br>86.8-88.8 | BH-T822<br>BH-02394<br>BH-02505 | BH-T871<br>BH-T871<br>BH-T871 | 82.11-86.9<br>86.9-88.8 | 5/8<br>5/8 | | MK-4300<br>MK-4353 | 82.11-88.8 | 13/16 | CC-70145 | CK-3144 |
| | E−YR28G(ワゴン) | | 85.8-92.1 | 15/16 | | TK-T011 | 85.8-86.8<br>86.8-92.1 | 60.3<br>60.3 | DISC<br>DISC | C-226P<br>C-226P | | 85.8-92.1 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 85.8-86.8<br>86.8-88.8<br>88.8-92.1 | BH-02394<br>BH-02505<br>BH-02505 | BH-31324<br>BH-31324<br>BH-02576 | 85.8-86.9<br>86.9-92.1 | 5/8<br>5/8 | | MK-4300<br>MK-4353 | 85.8-88.8<br>88.8-92.1 | 13/16<br>13/16 | CC-70145<br>CC-70145 | CK-3144<br>CK-3144 |
| | T−YR25V(バン)<br><GA−は95．8〜> | | 88.8-92.1<br>92.1-96.10 | 15/16<br>1 | | TK-T011<br>TK-T335 | 88.8-92.1<br>92.1-96.10 | 60.3<br>2 3/8 | DISC<br>DISC | C-226P<br>A-379P | CPA-379 | 88.8-92.1<br><br>92.1-96.10 | 13/16<br><br>13/16 | (R)WC-50059<br>(L)WC-50059<br>(R)WC-50059<br>(L)WC-50059 | WK-492<br><br>WK-492 | CUP<br><br>CUP | 88.8-92.1<br><低床車><br>92.1-96.10<br><ｼｬｽﾄﾛｰ><br>92.1-96.10 | BH-02505<br><br>BH-02505<br><br>BH-02505 | BH-02576<br><br>BH-31324 | 88.8-92.1<br>92.1-94.3<br>94.3-96.10 | 5/8<br>5/8<br>5/8 | <br>MC-T329<br>MC-T329 | MK-4353 | 88.8-94.10<br>94.10-96.10 | 13/16<br>13/16 | CC-70145<br>CC-70145 | CK-3144<br>CK-T201 |
| (1800ディーゼル) | N−CM20G(ワゴン) | | 82.10-85.8 | 7/8 | | TK-9427 | 82.10-85.8 | 2 1/4 | DISC | A-124P | | 82.10-85.8 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 82.10-83.10<br>83.10-85.8 | BH-T822<br>BH-02394 | BH-02342<br>BH-02342 | 82.10-85.8 | 5/8 | | MK-4300 | 82.10-85.8 | 13/16 | CC-70149 | CK-3144 |
| | N−CR26V(バン)<br><S−は87．8〜> | ドラム車 | 82.11-85.8 | 7/8 | | TK-9427 | 82.11-85.8 | 15/16 | (R-1)WC-52017<br>(R-2)WC-51017<br>(L-1)WC-54017<br>(L-2)WC-53017 | WK-105 | CUP | 82.11-85.8 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 82.11-85.8 | BH-95006 | BH-31324 | 82.11-85.8 | 5/8 | | MK-4300 | 82.11-85.8 | 13/16 | CC-70149 | CK-3144 |
| | | ディスク車 | 82.11-85.8<br>85.8-88.8 | 15/16<br>15/16 | | TK-9428<br>TK-T011 | 82.11-85.8<br>85.8-88.8 | 2 1/4<br>60.3 | DISC<br>DISC | A-124P<br>C-226P | | 82.11-88.8 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 82.11-83.10<br>83.10-86.8<br>86.8-88.8 | BH-T822<br>BH-02394<br>BH-02505 | BH-31324<br>BH-31324<br>BH-31324 | 82.11-85.8<br>85.8-88.8 | 5/8<br>5/8 | | MK-4300<br>MK-4353 | 82.11-85.8<br>85.8-88.8 | 13/16<br>13/16 | CC-70149<br>CC-70182 | CK-3144<br>CK-3144 |
| | CM20・25・26(トラック)<br>CM20V(バン)<br><N−は82．10〜> | Sタイヤ(ドラム車) | 82.10-86.9 | 7/8 | | TK-9427 | 82.10-86.9 | 15/16 | (R-1)WC-52017<br>(R-2)WC-51017<br>(L-1)WC-54017<br>(L-2)WC-53017 | WK-105 | CUP | 82.10-86.9<br><br><LSPV付><br>82.10-86.9 | 3/4<br><br><br>13/16 | (R)WC-50060<br>(L)WC-50060<br><br>(R)WC-50059<br>(L)WC-50059 | WK-491<br><br><br>WK-492 | CUP<br><br><br>CUP | 82.10-85.8<br><トラック><br>82.10-86.9 | BH-95006<br><br>BH-95006 | BH-02342<br><br>BH-94005 | 82.10-86.9 | 5/8 | | MK-4300 | 82.10-86.9 | 13/16 | CC-70149 | CK-3144 |
| | | Sタイヤ(ディスク車) | 82.10-86.9 | 7/8 | | TK-9427 | 82.10-86.9 | 2 1/4 | DISC | A-124P | | 82.10-86.9<br><br><LSPV付><br>82.10-86.9 | 3/4<br><br><br>13/16 | (R)WC-50060<br>(L)WC-50060<br><br>(R)WC-50059<br>(L)WC-50059 | WK-491<br><br><br>WK-492 | CUP<br><br><br>CUP | 82.10-83.10<br>83.10-85.8<br><トラック><br>82.10-83.10<br>83.10-86.9 | BH-T822<br>BH-02394<br><br>BH-T822<br>BH-02394 | BH-02342<br>BH-02342<br><br>BH-94005<br>BH-94005 | 82.10-86.9 | 5/8 | | MK-4300 | 82.10-86.9 | 13/16 | CC-70149 | CK-3144 |
| | | Wタイヤ(ドラム車) | 82.10-86.9 | 7/8 | | TK-9427 | 82.10-86.9 | 15/16 | (R-1)WC-52017<br>(R-2)WC-51017<br>(L-1)WC-54017<br>(L-2)WC-53017 | WK-105 | CUP | 82.10-86.9 | 5/8 | (R)WC-50061<br>(L)WC-50061 | WK-493 | CUP | 82.10-85.8<br><トラック><br>82.10-86.9 | BH-95006<br><br>BH-95006 | BH-94008<br><br>BH-94005 | 82.10-86.9 | 5/8 | | MK-4300 | 82.10-86.9 | 13/16 | CC-70149 | CK-3144 |
| | | Wタイヤ(ディスク車) | 82.10-86.9 | 7/8 | | TK-9427 | 82.10-86.9 | 2 1/4 | DISC | A-124P | | 82.10-86.9 | 5/8 | (R)WC-50061<br>(L)WC-50061 | WK-493 | CUP | 82.10-83.10<br>83.10-85.8<br><トラック><br>82.10-83.10<br>83.10-86.9 | BH-T822<br>BH-02394<br><br>BH-T822<br>BH-02394 | BH-94008<br>BH-94008<br><br>BH-94005<br>BH-94005 | 82.10-86.9 | 5/8 | | MK-4300 | 82.10-86.9 | 13/16 | CC-70149 | CK-3144 |
| (2000) | E−YM21G(ワゴン) | | 82.10-85.8 | 7/8 | | TK-9427 | 82.10-85.8 | 2 1/4 | DISC | A-124P | | 82.10-85.8 | 13/16 | (R)WC-50059<br>(L)WC-50059 | WK-492 | CUP | 82.10-83.10<br>83.10-85.8 | BH-T822<br>BH-02394 | BH-02342<br>BH-02342 | 82.10-85.8 | 5/8 | | MK-4300 | 82.10-85.8 | 13/16 | CC-70145 | CK-3144 |
| | E−YR21G(ワゴン) | | 83.5-85.8<br>85.8-92.1<br>92.1-96.10<br><ｱﾝﾁｽｷｯﾄﾞ付><br>92.1-96.10 | 15/16<br>1<br>1<br><br>1 | | TK-9428<br>TK-T010<br>TK-T335<br><br>TK-T336 | 83.5-85.8<br>85.8-86.8<br>86.8-88.8<br>88.8-92.1<br>92.1-96.10 | 2 1/4<br>60.3<br>2 1/4<br>60.3<br>2 3/8 | DISC<br>DISC<br>DISC<br>DISC<br>DISC | A-124P<br>C-226P<br>A-124P<br>C-226P<br>A-379P | <br><br><br><br>CPA-379 | 83.5-96.10<br><br><ｱﾝﾁｽｷｯﾄﾞ付><br>92.1-96.10 | 7/8<br><br><br>13/16 | (R)WC-50035<br>(L)WC-50035<br><br>(R)WC-T661<br>(L)WC-T661 | WK-545<br><br><br>WK-802 | CUP<br><br><br>CUP | 83.5-83.10<br>83.10-86.8<br>86.8-88.8<br>88.8-92.1<br>92.1-96.10 | BH-T822<br>BH-02394<br>BH-02505<br>BH-02505<br>BH-02505 | BH-T871<br>BH-T871<br>BH-T871<br>BH-T871<br>BH-T871 | 83.5-86.9<br>86.9-92.1<br>92.1-94.3<br>94.3-96.10 | 5/8<br>5/8<br>5/8<br>5/8 | <br><br>MC-T445<br>MC-T445 | MK-4300<br>MK-4353<br><br>MK-T244 | 83.5-88.8<br>88.8-92.1<br>92.1-94.10<br>94.10-95.10<br>95.10-96.10 | 13/16<br>13/16<br>13/16<br>13/16 | CC-70127<br>CC-70145<br>CC-70127<br>CC-70127 | CK-3122<br>CK-3144<br>CK-3122<br>CK-T213<br>CK-T214 |
| (2000ディーゼル) | | | 83.4-85.8 | 15/16 | | TK-9428 | 83.4-85.8 | 2 1/4 | DISC | A-124P | | <13インチホイール><br>83.4-92.1 | 13/16 | (R)WC-50059 | WK-492 | CUP | 83.4-83.10 | BH-T822 | BH-T871 | 83.4-88.8 | 5/8 | | MK-4300 | 83.4-85.8 | 13/16 | CC-70149 | CK-3144 |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| N－CR21G(ワゴン) | | 85.8-92.1 | 1 | | TK-T010 | 85.8-86.8 | 60.3 | DISC | C-226P | | | | (L)WC-50059 | | | 83.10-86.8 | BH-02394 | BH-T871 | 88.8-92.1 | 5/8 | | MK-4353 | 85.8-90.6 | 13/16 | CC-70182 | CK-3144 |
| ＜Q－は87．8～＞ | | 92.1-93.9 | 1 | | TK-T335 | 86.8-88.8 | 2 1/4 | DISC | A-124P | | ＜14インチホイール＞ | | | | | 86.8-88.8 | BH-02505 | BH-T871 | 92.1-93.9 | 5/8 | MC-T445 | | 90.6-93.9 | 13/16 | CC-70182 | CK-3144 |
| | | ＜アンチスキッド付＞ | | | | 88.8-92.1 | 60.3 | DISC | C-226P | | 83.4-93.9 | 7/8 | (R)WC-50035 | WK-545 | CUP | 88.8-92.1 | BH-02505 | BH-T871 | | | | | | | | |
| | | 92.1-93.9 | 1 | | TK-T336 | 92.1-93.9 | 2 3/8 | DISC | A-379P | CPA-379 | | | (L)WC-50035 | | | 92.1-93.9 | BH-02505 | BH-T871 | | | | | | | | |
| | | | | | | | | | | | ＜アンチスキッド付＞ | | | | | | | | | | | | | | | |
| | | | | | | | | | | | 92.1-93.9 | 13/16 | (R)WC-T661 | WK-802 | CUP | | | | | | | | | | | |
| | | | | | | | | | | | | | (L)WC-T661 | | | | | | | | | | | | | |
| N－CR27V(バン) | | 84.9-85.8 | 15/16 | | TK-9428 | 84.9-85.8 | 2 1/4 | DISC | A-124P | | 84.9-92.1 | 13/16 | (R)WC-50059 | WK-492 | CUP | 84.9-86.8 | BH-02394 | BH-31324 | 84.9-88.8 | | (オートマチック) | | | | | |
| ＜S－は87．8～＞ | | 85.8-92.1 | 15/16 | | TK-T011 | 85.8-86.8 | 60.3 | DISC | C-226P | | | | (L)WC-50059 | | | 86.8-88.8 | BH-02505 | BH-31324 | 88.8-92.1 | 5/8 | | MK-4353 | 88.8-90.6 | 13/16 | CC-70182 | CK-3144 |
| ＜KB－は93．9～＞ | | 92.1-96.10 | 1 | | TK-T335 | 86.8-88.8 | 2 1/4 | DISC | A-124P | | 92.1-96.10 | 13/16 | (R)WC-50059 | WK-492 | CUP | 88.8-92.1 | BH-02505 | BH-02576 | 92.1-94.3 | 5/8 | MC-T445 | | 90.6-94.10 | 13/16 | CC-70182 | CK-3144 |
| | | | | | | 88.8-92.1 | 60.3 | DISC | C-226P | | | | (L)WC-50059 | | | ＜低床車＞ | | | 94.3-96.10 | 5/8 | MC-T445 | MK-T244 | 94.10-96.10 | 13/16 | CC-70182 | CK-T201 |
| | | | | | | 92.1-96.10 | 2 3/8 | DISC | A-379P | CPA-379 | | | | | | 92.1-96.10 | BH-02505 | BH-31324 | | | | | | | | |
| | | | | | | | | | | | | | | | | ＜シャストロー＞ | | | | | | | | | | |
| | | | | | | | | | | | | | | | | 92.1-96.10 | BH-02505 | | | | | | | | | |
| N－CR28G(ワゴン) | | 85.8-92.1 | 15/16 | | TK-T011 | 85.8-86.8 | 60.3 | DISC | C-226P | | 85.8-87.8 | 13/16 | (R)WC-50059 | WK-492 | CUP | 85.8-86.8 | BH-02394 | BH-31324 | 85.8-86.9 | 5/8 | | MK-4300 | 85.8-90.6 | 13/16 | CC-70182 | CK-3144 |
| ＜Q－は87．8～＞ | | 92.1-93.9 | 1 | | TK-T335 | 86.8-88.8 | 2 1/4 | DISC | A-124P | | | | (L)WC-50059 | | | 86.8-88.8 | BH-02505 | BH-31324 | 86.9-92.1 | 5/8 | | MK-4353 | 90.6-93.9 | 13/16 | CC-70182 | CK-3144 |
| | | | | | | 88.8-92.1 | 60.3 | DISC | C-226P | | 87.8-93.9 | 7/8 | (R)WC-50035 | WK-545 | CUP | 88.8-92.1 | BH-02505 | BH-02576 | 92.1-93.9 | 5/8 | MC-T445 | | | | | |
| | | | | | | 92.1-93.9 | 2 3/8 | DISC | A-379P | CPA-379 | | | (L)WC-50035 | | | 92.1-93.9 | BH-02505 | BH-31324 | | | | | | | | |
| | | | | | | | | | | | ＜MT車＞ | | | | | | | | | | | | | | | |
| (2200ディーゼル) | アンチスキッド無 | 93.9-96.10 | 1 | | TK-T335 | 93.9-96.10 | 2 3/8 | DISC | A-379P | CPA-379 | 93.9-96.10 | 13/16 | (R)WC-50065 | WK-541 | CUP | 93.9-96.10 | BH-02505 | BH-02492 | 93.9-94.3 | 5/8 | MC-T445 | | 93.9-96.10 | 7/8 | | CK-T200 |
| Y－CR22G(ワゴン) | | | | | | | | | | | | | (L)WC-50065 | | | | | | 94.3-96.10 | 5/8 | MC-T445 | MK-T244 | | | | |
| ＜KD－は94．8～＞ | | | | | | | | | | | ＜AT車＞ | | | | | | | | | | | | | | | |
| | | | | | | | | | | | 93.9-96.10 | 7/8 | (R)WC-50035 | WK-545 | CUP | | | | | | | | | | | |
| | | | | | | | | | | | | | (L)WC-50035 | | | | | | | | | | | | | |
| | アンチスキッド車 | 93.9-96.10 | 1 | | TK-T336 | 93.9-96.10 | 2 3/8 | DISC | A-379P | CPA-379 | 93.9-96.10 | 13/16 | (R)WC-T661 | WK-802 | CUP | 93.9-96.10 | BH-02505 | BH-02492 | 93.9-94.3 | 5/8 | MC-T445 | | 93.9-96.10 | 7/8 | | CK-T200 |
| | | | | | | | | | | | | | (L)WC-T661 | | | | | | 94.3-96.10 | 5/8 | MC-T445 | MK-T244 | | | | |
| | | | | | | | | | | | ＜MT車＞ | | | | | | | | | | | | | | | |
| Y－CR29G(ワゴン) | | 93.9-96.10 | 1 | | TK-T335 | 93.9-96.10 | 2 3/8 | DISC | A-379P | CPA-379 | 93.9-96.10 | 13/16 | (R)WC-50065 | WK-541 | CUP | 93.9-96.10 | BH-02505 | BH-31324 | 93.9-94.3 | 5/8 | MC-T445 | | 93.9-96.10 | 7/8 | | CK-T200 |
| ＜KD－は94．8～＞ | | | | | | | | | | | | | (L)WC-50065 | | | | | | 94.3-96.10 | 5/8 | MC-T445 | MK-T244 | | | | |
| | | | | | | | | | | | ＜AT車＞ | | | | | | | | | | | | | | | |
| | | | | | | | | | | | 93.9-96.10 | 7/8 | (R)WC-50035 | WK-545 | CUP | | | | | | | | | | | |
| | | | | | | | | | | | | | (L)WC-50035 | | | | | | | | | | | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LITEACE, TOWNACE : 30 ser. | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1300) L−KM35V(バン) | 85.9−90.8 | 7/8 | | TK−T013 | 85.9−86.8<br>86.8−88.8<br>88.8−90.8 | 2 1/4<br>2 1/4<br>2 1/4 | DISC<br>DISC<br>DISC | A−124P<br>C−124P<br>C−124P | | 85.9−90.8 | 13/16 | (R)WC−50059<br>(L)WC−50059 | WK−492 | CUP | <低床車><br>85.9−86.8<br>86.8−90.8<br><ジャストロー><br>85.9−86.8<br>86.8−90.8 | BH−T822<br>BH−02505<br><br>BH−T822<br>BH−02505 | BH−02210<br>BH−02210<br><br>BH−02492<br>BH−02492 | | | (ワイヤー式) | | | | |
| (1500) E−KM30G(ワゴン)<br>L−KM31V・36V(バン)<br><T−は90. 8〜> | 85.9−92.1 | 7/8 | | TK−T013 | 85.9−86.8<br>86.8−88.8<br>88.8−89.10<br>89.10−92.1 | 2 1/4<br>2 1/4<br>2 1/4<br>2 1/4 | DISC<br>DISC<br>DISC<br>DISC | A−124P<br>C−124P<br>C−124P<br>C−124P | | 85.9−92.1 | 13/16 | (R)WC−50059<br>(L)WC−50059 | WK−492 | CUP | <低床車><br>85.9−86.8<br>86.8−92.1<br><ジャストロー><br>85.9−86.8<br>86.8−92.1 | BH−T822<br>BH−02505<br><br>BH−T822<br>BH−02505 | BH−02210<br>BH−02210<br><br>BH−02492<br>BH−02492 | <5速車><br>85.9−92.1<br><4速車><br>85.9−92.1 | 5/8 | (ワイヤー式) | MK−4327 | 85.9−88.8<br>88.8−92.1 | 13/16<br>13/16 | CC−70176<br>CC−70176 | CK−3144<br>CK−3144 |
| (1800) E−YM30G(ワゴン)<br>T−YM31V(バン) | 85.9−92.1 | 7/8 | | TK−T013 | 85.9−86.8<br>86.8−92.1 | 2 1/4<br>2 1/4 | DISC<br>DISC | A−124P<br>C−124P | | 85.9−92.1 | 13/16 | (R)WC−50059<br>(L)WC−50059 | WK−492 | CUP | 85.9−86.8<br>86.8−92.1 | BH−T822<br>BH−02505 | BH−02210<br>BH−02210 | 85.9−92.1 | 5/8 | | MK−4327 | 85.9−88.8<br>88.8−92.1 | 13/16<br>7/8 | CC−70145<br>CC−70127 | CK−3144<br>CK−3122 |
| (1800ディーゼル)<br>N−CM35V(バン)<br><S−は87. 8〜> | 85.9−88.8 | 7/8 | | TK−T013 | 85.9−86.8<br>86.8−88.8 | 2 1/4<br>2 1/4 | DISC<br>DISC | A−124P<br>C−124P | | 85.9−88.8 | 13/16 | (R)WC−50059<br>(L)WC−50059 | WK−492 | CUP | <低床車><br>85.9−86.8<br>86.8−88.8<br><ジャストロー><br>85.9−86.8<br>86.8−88.8 | BH−T822<br>BH−02505<br><br>BH−T822<br>BH−02505 | BH−02210<br>BH−02210<br><br>BH−02492<br>BH−02492 | 85.9−88.8 | 5/8 | | MK−4327 | 85.9−88.8 | 13/16 | CC−70182 | CK−3144 |
| (2000) E−YR30G(4WDワゴン) | 85.10−92.1<br>92.1−96.10 | 1 | | TK−T010<br>TK−T335 | 85.10−88.8<br>88.8−92.1<br>92.1−96.10 | 1 3/4<br>1 3/4<br>1 3/4 | DISC<br>DISC<br>DISC | A−239P<br>A−239P<br>A−239P | CPA−239<br>CPA−239<br>CPA−239 | 85.10−96.10 | 13/16 | (R)WC−50065<br>(L)WC−50065 | WK−541 | CUP | 85.10−92.1<br>92.1−96.10 | BH−02221<br>BH−T589 | BH−02492<br>BH−02492 | 85.10−86.9<br>86.9−92.1<br>92.1−96.10 | 5/8<br>5/8 | (オートマチック) | MK−4300<br>MK−4353 | 85.10−92.1 | 7/8 | CC−70127 | CK−3122 |
| E−YR36G(4WDワゴン) | 86.8−92.1 | 1 | | TK−T010 | 85.10−88.8<br>88.8−92.1 | 1 3/4<br>1 3/4 | DISC<br>DISC | A−239P<br>A−239P | CPA−239<br>CPA−239 | 86.8−92.1 | 13/16 | (R)WC−50065<br>(L)WC−50065 | WK−541 | CUP | 86.8−88.8<br>88.8−89.2<br>89.2−92.1 | BH−02221<br>BH−02221<br>BH−02221 | BH−31324<br>BH−02576<br>BH−T681 | 86.8−92.1 | 5/8 | | MK−4353 | 86.8−92.1 | 7/8 | CC−70127 | CK−3122 |
| (2000ディーゼル)<br>N−CM30G(ワゴン)<br><Q−は87. 8〜> | 85.9−92.1 | 7/8 | | TK−T013 | 85.9−86.8<br>86.8−92.1 | 2 1/4<br>2 1/4 | DISC<br>DISC | A−124P<br>C−124P | | 85.9−92.1 | 13/16 | (R)WC−50059<br>(L)WC−50059 | WK−492 | CUP | 85.9−86.8<br>86.8−92.1 | BH−T822<br>BH−02505 | BH−02210<br>BH−02210 | 85.9−92.1 | 5/8 | | MK−4327 | 85.9−90.6<br>90.6−92.1 | 13/16<br>13/16 | CC−70182<br>CC−70182 | CK−3144<br>CK−3144 |
| N−CM36V(バン)<br>S−CM31V・36V(バン)<br><S−は88. 8〜> | 85.9−92.1 | 7/8 | | TK−T013 | 85.9−86.8<br>86.8−92.1 | 2 1/4<br>2 1/4 | DISC<br>DISC | A−124P<br>C−124P | | 85.9−92.1 | 13/16 | (R)WC−50059<br>(L)WC−50059 | WK−492 | CUP | <低床車><br>85.9−86.8<br>86.8−92.1<br><ジャストロー><br>88.8−92.1 | BH−T822<br>BH−02505<br><br>BH−02505 | BH−02210<br>BH−02210<br><br>BH−02492 | 85.9−88.8<br>88.8−92.1 | 5/8 | (オートマチック) | MK−4327 | 88.8−90.6<br>90.6−92.1 | 13/16<br>13/16 | CC−70182<br>CC−70182 | CK−3144<br>CK−3144 |
| N−CR30G(4WDワゴン) | 85.8−92.1 | 1 | | TK−T010 | 85.8−88.8 | 1 3/4 | DISC | A−239P | CPA−239 | 85.8−93.9 | 13/16 | (R)WC−50065 | WK−541 | CUP | 85.8−92.1 | BH−02221 | BH−02492 | 85.8−86.9 | 5/8 | | MK−4300 | 85.8−90.6 | 13/16 | CC−70182 | CK−3144 |
| <Q−は92. 1〜> | 92.1−93.9 | 1 | | TK−T335 | 88.8−92.1<br>92.1−96.10 | 1 3/4<br>1 3/4 | DISC<br>DISC | A−239P<br>A−239P | CPA−239<br>CPA−239 | | | (L)WC−50065 | | | 92.1−93.9 | BH−T589 | BH−02492 | 86.9−92.1<br>92.1−93.9 | 5/8<br>5/8 | MC−T445 | MK−4353 | 90.6−93.9 | 13/16 | CC−70182 | CK−3144 |
| Q−CR37G(4WDワゴン)<br>N−CR36V(4WDバン)<br>S−CR36V(4WDバン)<br><KB−は93. 9〜> | 85.10−92.1<br>92.1−96.10 | 1<br>1 | | TK−T010<br>TK−T335 | 85.8−88.8<br>88.8−92.1<br>92.1−96.10 | 1 3/4<br>1 3/4<br>1 3/4 | DISC<br>DISC<br>DISC | A−239P<br>A−239P<br>A−239P | CPA−239<br>CPA−239<br>CPA−239 | 85.10−96.10 | 13/16 | (R)WC−50065<br>(L)WC−50065 | WK−541 | CUP | 85.10−88.8<br>88.8−89.2<br>89.2−92.1<br>92.1−96.10 | BH−02221<br>BH−02221<br>BH−02221<br>BH−T589 | BH−31324<br>BH−02576<br>BH−T681 | 85.10−86.9<br>86.9−92.1<br>92.1−94.3<br>94.3−96.10 | 5/8<br>5/8<br>5/8<br>5/8 | MC−T445 | MK−4300<br>MK−4353<br>MK−T244 | 85.10−90.6<br>90.6−93.9<br>93.9−96.10 | 13/16<br>13/16<br>7/8 | CC−70182<br>CC−70182 | CK−3144<br>CK−3144<br>CK−T200 |
| (2200ディーゼル)<br>Y−CR31G(4WDワゴン)<br><KD−は94. 8〜> | 93.9−96.10 | 1 | | TK−T335 | 93.9−96.10 | 1 3/4 | DISC | A−239P | CPA−239 | 93.9−96.10 | 13/16 | (R)WC−50065<br>(L)WC−50065 | WK−541 | CUP | 93.9−96.10 | BH−T589 | BH−02492 | 93.9−94.3<br>94.3−96.10 | 5/8<br>5/8 | MC−T445 | MK−T244 | 93.9−96.10 | 7/8 | | CK−T200 |
| Y−CR38G(4WDワゴン)<br><KD−は94. 8〜> | 93.9−96.10 | 1 | | TK−T335 | 93.9−96.10 | 1 3/4 | DISC | A−239P | CPA−239 | 93.9−96.10 | 13/16 | (R)WC−50065<br>(L)WC−50065 | WK−541 | CUP | 93.9−96.10 | BH−T589 | | 93.9−94.3<br>94.3−96.10 | 5/8<br>5/8 | MC−T445 | MK−T244 | 93.9−96.10 | 7/8 | | CK−T200 |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LITEACE, TOWNACE : 40 ser. | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000) E－YM40G(4WDワゴン) | 85.10-92.1 | 7/8 | | TK-T013 | 85.10-92.1 | 2 1/4 | DISC | C-124P | | 85.10-92.1 | 13/16 | (R)WC-50065<br>(L)WC-50065 | WK-541 | CUP | 85.10-92.1 | BH-02221 | BH-02210 | 85.10-92.1 | 5/8 | | MK-4327 | 85.10-88.8<br>88.8-92.1 | 13/16<br>7/8 | CC-70145<br>CC-70127 | CK-3144<br>CK-3122 |
| (2000ディーゼル)<br>N－CM40G(4WDワゴン)<br>N－CM41V(4WDバン)<br>＜Q・S－は88. 8～＞ | 85.10-92.1 | 7/8 | | TK-T013 | 85.10-92.1 | 2 1/4 | DISC | C-124P | | 85.10-92.1 | 13/16 | (R)WC-50065<br>(L)WC-50065 | WK-541 | CUP | 85.10-92.1 | BH-02221 | BH-02210 | 85.10-92.1 | 5/8 | | MK-4327 | 85.10-90.6<br>90.6-92.1 | 13/16<br>13/16 | CC-70182<br>CC-70182 | CK-3144<br>CK-3144 |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LITEACE, TOWNACE, TOWNACE TRUCK : 50, 60 ser. | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1300) L−KM50 | 86.10-90.8 | 15/16 | | TK-T011 | 86.10-88.8<br>88.8-90.8 | 60.3<br>60.3 | DISC<br>DISC | C-226P<br>C-226P | CPC-226<br>CPC-226 | 86.10-90.8 | 7/8 | (R)WC-50035<br>(L)WC-50035 | WK-545 | CUP | 86.10-90.8 | BH-02505 | BH-02492 | | | (ワイヤー式) | | | | | |
| (1500) L−KM51<br><T−は90. 8〜><br><GA−は95. 8〜> | 86.10-99.6 | 15/16 | | TK-T011 | 86.10-88.8<br>88.8-99.6 | 60.3<br>60.3 | DISC<br>DISC | C-226P<br>C-226P | CPC-226<br>CPC-226 | 86.10-99.2<br><br>99.2-99.6 | 7/8<br><br>7/8 | (R)WC-50035<br>(L)WC-50035<br>(R)WC-T650<br>(L)WC-T650 | WK-545<br><br>WK-770 | CUP<br><br>CUP | 86.10-95.8<br>95.8-99.6 | BH-02505<br>BH-02505 | BH-02492<br>BH-02492 | 86.10-99.6 | 5/8 | | MK-4327 | 86.10-88.6<br>88.6-94.10<br>94.10-99.6 | 13/16<br>13/16<br>13/16 | CC-70176<br>CC-70176<br>CC-70176 | CK-3144<br>CK-3144<br>CK-T201 |
| (1800) L−YM55<br><T−は90. 8〜><br><GA−は95. 8〜> | 86.10-99.6 | 15/16 | | TK-T011 | 86.10-88.8<br>88.8-99.6 | 60.3<br>60.3 | DISC<br>DISC | C-226P<br>C-226P | CPC-226<br>CPC-226 | 86.10-99.2<br><br>99.2-99.6 | 7/8<br><br>7/8 | (R)WC-50035<br>(L)WC-50035<br>(R)WC-T650<br>(L)WC-T650 | WK-545<br><br>WK-770 | CUP<br><br>CUP | 86.10-95.8<br>95.8-99.6 | BH-02505<br>BH-02505 | BH-02492<br>BH-02492 | 86.10-99.6 | 5/8 | | MK-4327 | 86.10-88.6<br>88.6-94.10<br>94.10-99.6 | 13/16<br>13/16<br>13/16 | CC-70145<br>CC-70145<br>CC-70145 | CK-3144<br>CK-3144<br>CK-T201 |
| L−YM60・65(4WD)<br><T−は90. 8〜><br><GA−は95. 8〜> | 86.10-99.6 | 15/16 | | TK-T011 | 86.10-99.6 | 60.3 | DISC | C-226P | CPC-226 | 86.10-99.6 | 13/16 | (R)WC-50065<br>(L)WC-50065 | WK-541 | CUP | 86.10-95.8<br>95.8-99.6 | BH-02221<br>BH-02221 | BH-02492<br>BH-02492 | 86.10-99.6 | 5/8 | | MK-4327 | 86.10-88.6<br>88.6-94.10<br>94.10-99.6 | 13/16<br>13/16<br>13/16 | CC-70145<br>CC-70145<br>CC-70145 | CK-3144<br>CK-3144<br>CK-T201 |
| (1800ディーゼル)<br>N−CM50<br><S−は87. 8〜> | 86.10-89.10 | 15/16 | | TK-T011 | 86.10-88.8<br>88.8-89.10 | 60.3<br>60.3 | DISC<br>DISC | C-226P<br>C-226P | CPC-226<br>CPC-226 | 86.10-89.10 | 7/8 | (R)WC-50035<br>(L)WC-50035 | WK-545 | CUP | 86.10-89.10 | BH-02505 | BH-02492 | 86.10-89.10 | 5/8 | | MK-4327 | 86.10-89.10 | 13/16 | CC-70182 | CK-3144 |
| (2000ディーゼル)<br>N−CM51・55<br><S−は87. 8〜><br><KB−は93. 10〜> | 86.10-99.6 | 15/16 | | TK-T011 | 86.10-88.8<br>88.8-99.6<br><高所作業車><br>94.4-99.6 | 60.3<br>60.3<br><br>2 3/8 | DISC<br>DISC<br><br>DISC | C-226P<br>C-226P<br><br>A-379P | CPC-226<br>CPC-226<br><br>CPA-379 | 86.10-99.2<br><br>99.2-99.6<br><br><高所作業車><br>94.4-99.6 | 7/8<br><br>7/8<br><br>7/8 | (R)WC-50035<br>(L)WC-50035<br>(R)WC-T650<br>(L)WC-T650<br><br>(R)WC-50054<br>(L)WC-50054 | WK-545<br><br>WK-770<br><br>WK-405 | CUP<br><br>CUP<br><br>CUP | 86.10-95.8<br>95.8-99.6 | BH-02505<br>BH-02505 | BH-02492<br>BH-02492 | 86.10-99.6 | 5/8 | | MK-4327 | 86.10-90.6<br>90.6-94.10<br>94.10-99.6 | 13/16<br>13/16<br>13/16 | CC-70182<br>CC-70182<br>CC-70182 | CK-3144<br>CK-3144<br>CK-T201 |
| N−CM60・65(4WD)<br><S−は87. 8〜><br><KB−は93. 10〜> | 86.10-99.6 | 15/16 | | TK-T011 | 86.10-99.6<br><高所作業車><br>96.11-99.6 | 60.3<br><br>2 3/8 | DISC<br><br>DISC | C-226P<br><br>A-239P | CPC-226<br><br>CPA-239 | 86.10-99.6<br><高所作業車><br>96.11-99.6 | 13/16<br><br>15/16 | (R)WC-50065<br>(L)WC-50065<br><br>(R)WC-50047<br>(L)WC-50047 | WK-541<br><br>WK-309 | CUP<br><br>CUP | 86.10-95.8<br>95.8-99.6<br><高所作業車><br>96.11-99.6 | BH-02221<br>BH-02221 | BH-02492<br>BH-02492<br><br>BH-02492 | 86.10-99.6 | 5/8 | | MK-4327 | 86.10-90.6<br>90.6-93.10<br>93.10-99.6 | 13/16<br>13/16<br>7/8 | CC-70182<br>CC-70182 | CK-3144<br>CK-T200 |
| S−CM52<br>S−CM61(4WD)<br><KB−は93. 10〜> | 91.10-99.6 | 15/16 | | TK-T011 | 91.10-99.6 | 60.3 | DISC | C-226P | CPC-226 | 91.10-99.6 | 13/16 | (R)<br>(L) | WK-541 | CUP | 91.10-95.8<br><br><br>95.8-99.6 | BH-02221<br><br><br>BH-02221 | (C)BH-02576<br>(R)BH-95001<br>(L)BH-95001<br>(C)BH-T685<br>(R)BH-95001<br>(L)BH-95001 | 91.10-99.6 | 5/8 | | MK-4327 | <CM52><br>91.10-94.10<br>94.10-99.6<br><CM61><br>91.10-93.10<br>93.10-99.6 | 13/16<br>13/16<br><br>13/16<br>7/8 | CC-70182<br>CC-70182<br>CC-70182 | CK-3144<br>CK-T201<br>CK-3144<br>CK-T200 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LITEACE, TOWNACE : 70, 80 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) | GC－KM70・75 | スーパーシングルジャストロー | 99.6-<br><ｱﾝﾁｽｷｯﾄﾞ付><br>99.6- | | | | 99.6- | 2 3/8 | DISC | A-379P | CPA-379 | 99.6- | 7/8 | (R)WC-T650<br>(L)WC-T650 | WK-770 | CUP | 99.6- | BH-T808 | BH-T784 | 99.6- | 5/8 | | MK-T244 | 99.6- | 7/8 | CC-70127 | CK-3122 |
| | | シングルジャストロー<br>低床車 | 99.6-<br><ｱﾝﾁｽｷｯﾄﾞ付><br>99.6- | | | | <KM70><br>99.6-<br><KM75><br>02.8- | 2 3/8<br><br>2 3/8 | DISC<br><br>DISC | A-379P<br><br>A-379P | CPA-379<br><br>CPA-379 | <KM70><br>99.6-<br><br><KM75><br>02.8- | 7/8<br><br>13/16 | (R)WC-T650<br>(L)WC-T650<br><br>(R)<br>(L) | WK-770<br><br>WK-802 | CUP<br><br>CUP | 99.6- | BH-T809 | | 99.6- | 5/8 | | MK-T244 | 99.6- | 7/8 | CC-70127 | CK-3122 |
| | GC－KM80・85(4WD)<br><GK－は02. 8～> | | 99.6-07.8<br><ｱﾝﾁｽｷｯﾄﾞ付><br>99.6-07.8 | | | | 99.6-07.8 | 2 3/8 | DISC | A-379P | CPA-379 | 99.6-07.8 | 13/16 | (R)<br>(L) | WK-802 | CUP | 99.6-07.8 | BH-T809 | BH-T784 | 99.6-07.8 | 5/8 | | MK-T244 | 99.6-07.8 | 7/8 | CC-70127 | CK-3122 |
| (2200ディーゼル) | KF・KJ－CM70 | | 99.6-04.8<br><ｱﾝﾁｽｷｯﾄﾞ付><br>99.6-04.8 | | | | 99.6-04.8 | 2 3/8 | DISC | A-379P | CPA-379 | 99.6-04.8 | 7/8 | (R)WC-T650<br>(L)WC-T650 | WK-770 | CUP | <ｽｰﾊﾟｰｼﾝｸﾞﾙｼﾞｬｽﾄﾛｰ><br>99.6-04.8<br><ｼﾝｸﾞﾙｼﾞｬｽﾄﾛｰ><br>99.6-04.8 | BH-T808<br>BH-T809 | BH-T784 | 99.6-04.8 | 5/8 | | MK-T244 | 99.6-04.8 | 7/8 | | CK-T200 |
| | KF・KJ－CM75 | スーパーシングルジャストロー | 99.6-04.8<br><ｱﾝﾁｽｷｯﾄﾞ付><br>99.6-04.8 | | | | 99.6-04.8 | 2 3/8 | DISC | A-379P | CPA-379 | 99.6-04.8<br><br><ﾔﾏﾄ運輸仕様><br><高所作業車><br>99.6-04.8 | 7/8<br><br><br>7/8 | (R)WC-T650<br>(L)WC-T650<br><br><br>(R)WC-T799<br>(L)WC-T799 | WK-770<br><br><br>WK-887 | CUP<br><br><br>CUP | 99.6-04.8 | BH-T808 | BH-T784 | 99.6-04.8 | 5/8 | | MK-T244 | 99.6-04.8 | 7/8 | | CK-T200 |
| | | シングルジャストロー | 02.8-04.8<br><ｱﾝﾁｽｷｯﾄﾞ付><br>02.8-04.8 | | | | 02.8-04.8 | 2 3/8 | DISC | A-379P | CPA-379 | 02.8-04.8 | 13/16 | (R)<br>(L) | WK-802 | CUP | 02.8-04.8 | BH-T809 | | 02.8-04.8 | 5/8 | | MK-T244 | 02.8-04.8 | 7/8 | | CK-T200 |
| | KF・KJ－CM80(4WD) | | 99.6-<br><ｱﾝﾁｽｷｯﾄﾞ付><br>99.6- | | | | 99.6- | 2 3/8 | DISC | A-379P | CPA-379 | 99.6- | 13/16 | (R)<br>(L) | WK-802 | CUP | 99.6- | BH-T809 | BH-T784 | 99.6- | 5/8 | | MK-T244 | 99.6- | 7/8 | | CK-T200 |
| | KJ－CM85(4WD) | | 99.6-<br><ｱﾝﾁｽｷｯﾄﾞ付><br>99.6- | | | | 99.6-<br><ﾔﾏﾄ運輸仕様><br><高所作業車><br>99.6- | 2 3/8<br><br><br>DISC | DISC<br><br><br>C-379P | A-379P<br><br><br>C-379P | CPA-379<br><br><br>CPA-379 | 99.6-<br><ﾔﾏﾄ運輸仕様><br><高所作業車><br>99.6- | 13/16<br><br><br>7/8 | (R)<br>(L)<br><br><br>(R)WC-T787<br>(L)WC-T787 | WK-802<br><br><br>WK-887 | CUP<br><br><br>CUP | 99.6- | BH-T809 | BH-T784 | 99.6- | 5/8 | | MK-T244 | 99.6- | 7/8 | | CK-T200 |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LITEACE, TOWNACE : 400 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1500) | ABF－S402M<br>＜DBF－は14．4～＞ | 08.2-20.7 | | | ｷｯﾄｾｯﾃｲﾅｼ | 08.2-20.7 | | DISC | MP-135 | | 08.2-20.7 | 13/16 | (R)WC-T803<br>(L)WC-T804 | WK-1060 | CUP | 08.2-20.7 | (R)<br>(L) | | 08.2-20.7 | | | ｷｯﾄﾅｼ | 08.2-20.7 | 13/16 | | CK-T232 |
| | ABF－S402U<br>＜DBF－は14．4～＞ | 08.2-20.7 | | | ｷｯﾄｾｯﾃｲﾅｼ | 08.2-20.7 | | DISC | MP-135 | | 08.2-20.7 | 13/16 | (R)WC-T803<br>(L)WC-T804 | WK-1060 | CUP | 08.2-20.7 | (R)<br>(L) | | 08.2-20.7 | | | ｷｯﾄﾅｼ | 08.2-20.7 | 13/16 | | CK-T232 |
| | 5BF－S403M | 20.7- | | | ｷｯﾄｾｯﾃｲﾅｼ | 20.7- | | DISC | MP-135 | | 20.7- | 13/16 | (R)<br>(L) | WK-1101 | CUP | 20.7- | (R)<br>(L) | (R)<br>(L) | 20.7- | | | ｷｯﾄﾅｼ | 20.7- | 13/16 | | CK-T232 |
| | 5BF－S403U | 20.7- | | | ｷｯﾄｾｯﾃｲﾅｼ | 20.7- | | DISC | MP-135 | | 20.7- | 13/16 | (R)<br>(L) | WK-1101 | CUP | 20.7- | (R)<br>(L) | (R)<br>(L) | 20.7- | | | ｷｯﾄﾅｼ | 20.7- | 13/16 | | CK-T232 |
| | ABF－S412M<br>＜DBF－は14．4～＞ | 10.7-20.7 | | | ｷｯﾄｾｯﾃｲﾅｼ | 10.7-20.7 | | DISC | MP-135 | | 10.7-20.7 | 13/16 | (R)WC-T803<br>(L)WC-T804 | WK-1060 | CUP | 10.7-20.7 | (R)<br>(L) | | 10.7-20.7 | | | ｷｯﾄﾅｼ | 10.7-20.7 | 13/16 | | CK-T232 |
| | ABF－S412U<br>＜DBF－は14．4～＞ | 10.7-20.7 | | | ｷｯﾄｾｯﾃｲﾅｼ | 10.7-20.7 | | DISC | MP-135 | | 10.7-20.7 | 13/16 | (R)WC-T803<br>(L)WC-T804 | WK-1060 | CUP | 10.7-20.7 | (R)<br>(L) | | 10.7-20.7 | | | ｷｯﾄﾅｼ | 10.7-20.7 | 13/16 | | CK-T232 |
| | 5BF－S413M | 20.7- | | | ｷｯﾄｾｯﾃｲﾅｼ | 20.7- | | DISC | MP-135 | | 20.7- | 13/16 | (R)<br>(L) | WK-1101 | CUP | 20.7- | (R)<br>(L) | (R)<br>(L) | 20.7- | | | ｷｯﾄﾅｼ | 20.7- | 13/16 | | CK-T232 |
| | 5BF－S413U | 20.7- | | | ｷｯﾄｾｯﾃｲﾅｼ | 20.7- | | DISC | MP-135 | | 20.7- | 13/16 | (R)<br>(L) | WK-1101 | CUP | 20.7- | (R)<br>(L) | (R)<br>(L) | 20.7- | | | ｷｯﾄﾅｼ | 20.7- | 13/16 | | CK-T232 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LITEACE, TOWNACE, TOWNACE NOAH : 40, 50 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1500) | GA－KR41V | | 96.11-98.12<br><ｱﾝﾁｽｷｯﾄﾞ付><br>96.11-98.12 | 15/16<br><br>15/16 | | TK-T411<br><br>TK-T415 | 96.11-98.12 | 2 3/8 | DISC | A-379P | CPA-379 | 96.11-98.12 | 7/8 | (R)WC-T650<br>(L)WC-T650 | WK-770 | CUP | <低床車><br>96.11-98.12<br><ｽｰﾊﾟｰｼﾝｸﾞﾙｼﾞｬｽﾄﾛｰ><br>96.11-98.12 | BH-T744<br><br>BH-T744 | BH-T712<br><br>BH-T710 | 96.11-98.12 | 5/8 | MC-T325 | MK-T244 | 96.11-98.12 | 7/8 | CC-70127 | CK-3122 |
| (1800) | GA－KR42V<br>＜GC－は98．12～＞<br>＜GK－は02．8～＞ | | 96.11-<br><ｱﾝﾁｽｷｯﾄﾞ付><br>96.11- | 15/16<br><br>15/16 | | TK-T411<br><br>TK-T415 | 96.11- | 2 3/8 | DISC | A-379P | CPA-379 | 96.11- | 7/8 | (R)WC-T650<br>(L)WC-T650 | WK-770 | CUP | <低床車><br>96.11-98.12<br>98.12-<br><ｽｰﾊﾟｰｼﾝｸﾞﾙｼﾞｬｽﾄﾛｰ><br>96.11-98.12<br>98.12- | BH-T744<br>BH-T785<br><br>BH-T744<br>BH-T785 | BH-T712<br><br>BH-T710 | 96.11- | 5/8 | MC-T325 | MK-T244 | 96.11- | 7/8 | CC-70127 | CK-3122 |
| | GK－KR52V | | 04.12-07.8 | 15/16 | | TK-T415 | 04.12-07.8 | 2 3/8 | DISC | A-379P | CPA-379 | 04.12-07.8 | 7/8 | (R)WC-T799<br>(L)WC-T799 | WK-887 | CUP | 04.12-07.8 | (R)BH-T786<br>(L)BH-T787 | | 04.12-07.8 | 5/8 | MC-T325 | MK-T244 | 04.12-07.8 | 7/8 | CC-70127 | CK-3122 |
| (2000) | E－SR40G<br>＜GF－は98．12～＞ | 除くSW | 96.10-01.11<br><ｱﾝﾁｽｷｯﾄﾞ付><br>96.10-98.12<br>98.12-01.11 | 15/16<br><br>15/16<br>15/16 | | TK-T400<br><br>TK-T415<br>TK-T400 | 96.10-01.11 | 2 3/8 | DISC | A-379P | CPA-379 | 96.10-01.11 | 7/8 | (R)WC-T650<br>(L)WC-T650 | WK-770 | CUP | 96.10-98.12<br>98.12-01.11 | BH-T744<br>BH-T785 | BH-T712 | 96.10-01.11 | 5/8 | MC-T433 | MK-T244 | 96.10-01.11 | 7/8 | CC-T395 | CK-T225 |
| | | SW | 96.11-98.12<br><ｱﾝﾁｽｷｯﾄﾞ付><br>96.11-01.11 | 15/16<br><br>15/16 | | TK-T411<br><br>TK-T415 | 96.11-01.11 | 2 3/8 | DISC | A-379P | CPA-379 | 96.11-01.11 | 7/8 | (R)WC-T650<br>(L)WC-T650 | WK-770 | CUP | 96.11-98.12<br>98.12-01.11 | BH-T744<br>BH-T785 | BH-T712 | 96.11-01.11 | 5/8 | MC-T433 | MK-T244 | 96.11-01.1 | 7/8 | CC-T395 | CK-T225 |
| | E－SR50G(4WD)<br>＜GF－は98．12～＞ | 除くSW | 96.10-01.11 | 15/16 | | TK-T400 | 96.10-98.12<br>98.12-01.11 | 2 3/8<br>2 3/8 | DISC<br>DISC | A-379P<br>A-379P | CPA-379<br>CPA-379 | 96.10-01.11 | 7/8 | (R)WC-T799<br>(L)WC-T799 | WK-887 | CUP | 96.10-98.12<br>98.12-01.11 | (R)BH-T708<br>(L)BH-T709<br>(R)BH-T786<br>(L)BH-T787 | BH-T711 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | | SW | 96.11-98.12<br><ｱﾝﾁｽｷｯﾄﾞ付><br>96.11-01.11 | 15/16<br><br>15/16 | | TK-T411<br><br>TK-T400 | 96.10-01.11 | 2 3/8 | DISC | A-379P | CPA-379 | 96.11-01.11 | 7/8 | (R)WC-T799<br>(L)WC-T799 | WK-887 | CUP | 96.11-98.12<br>98.12-01.11 | (R)BH-T708<br>(L)BH-T709<br>(R)BH-T786<br>(L)BH-T787 | BH-T711 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (2000ディーゼル) | KB－CR41V | | 96.11-98.12<br><ｱﾝﾁｽｷｯﾄﾞ付><br>96.11-98.12 | 15/16<br><br>15/16 | | TK-T411<br><br>TK-T415 | 96.11-98.12 | 2 3/8 | DISC | A-379P | CPA-379 | 96.11-98.12 | 7/8 | (R)WC-T650<br>(L)WC-T650 | WK-770 | CUP | <低床車><br>96.11-98.12<br><ｽｰﾊﾟｰｼﾝｸﾞﾙｼﾞｬｽﾄﾛｰ><br>96.11-98.12 | BH-T744<br><br>BH-T744 | BH-T712<br><br>BH-T710 | 96.11-98.12 | 5/8 | MC-T433 | MK-T244 | 96.11-98.12 | 13/16 | CC-70182 | CK-T201 |
| | KB－CR51V(4WD) | | 96.11-98.12<br><ｱﾝﾁｽｷｯﾄﾞ付><br>96.11-98.12 | 15/16<br><br>15/16 | | TK-T411<br><br>TK-T415 | 96.11-98.12 | 2 3/8 | DISC | A-379P | CPA-379 | 96.11-98.12 | 7/8 | (R)WC-T799<br>(L)WC-T799 | WK-887 | CUP | 96.11-98.12 | (R)BH-T708<br>(L)BH-T709 | BH-T711 | 96.11-98.12 | 5/8 | MC-T433 | MK-T244 | 96.11-98.12 | 7/8 | CC-T395 | CK-T225 |
| (2200ディーゼル) | KD－CR40G<br>＜KH－は98．12～＞ | | 96.10-01.11<br><ｱﾝﾁｽｷｯﾄﾞ付><br>96.11-98.12<br>98.12-01.11 | 15/16<br><br>15/16<br>15/16 | | TK-T400<br><br>TK-T415<br>TK-T400 | 96.10-01.11 | 2 3/8 | DISC | A-379P | CPA-379 | 96.10-01.11 | 7/8 | (R)WC-T650<br>(L)WC-T650 | WK-770 | CUP | 96.10-98.12<br>98.12-01.11 | BH-T744<br>BH-T785 | BH-T712 | 96.10-01.11 | 5/8 | MC-T433 | MK-T244 | 96.10-01.11 | 7/8 | CC-T395 | CK-T225 |
| | KD－CR50G(4WD)<br>＜KH－は98．12～＞ | | 96.10-01.11 | 15/16 | | TK-T400 | 96.10-98.12<br>98.12-01.11 | 2 3/8<br>2 3/8 | DISC<br>DISC | A-379P<br>A-379P | CPA-379<br>CPA-379 | 96.10-01.11 | 7/8 | (R)WC-T799<br>(L)WC-T799 | WK-887 | CUP | 96.10-98.12<br>98.12-01.11 | (R)BH-T708<br>(L)BH-T709<br>(R)BH-T786<br>(L)BH-T787 | BH-T711 | 96.10-01.11 | 5/8 | MC-T433 | MK-T244 | 96.10-01.11 | 7/8 | CC-T395 | CK-T225 |
| | KF･KJ－CR42V | | 98.12-04.8<br><ｱﾝﾁｽｷｯﾄﾞ付><br>98.12-04.8 | 15/16<br><br>15/16 | | TK-T411<br><br>TK-T415 | 98.12-04.8 | 2 3/8 | DISC | A-379P | CPA-379 | 98.12-04.8 | 7/8 | (R)WC-T650<br>(L)WC-T650 | WK-770 | CUP | 98.12-04.8 | BH-T785 | | 98.12-04.8 | 5/8 | MC-T433 | MK-T244 | 98.12-04.8 | 7/8 | CC-T395 | CK-T225 |
| | KF･KJ－CR52V(4WD) | | 98.12-<br><ｱﾝﾁｽｷｯﾄﾞ付><br>98.12- | 15/16<br><br>15/16 | | TK-T411<br><br>TK-T415 | 98.12- | 2 3/8 | DISC | A-379P | CPA-379 | 98.12- | 7/8 | (R)WC-T799<br>(L)WC-T799 | WK-887 | CUP | 98.12- | (R)BH-T786<br>(L)BH-T787 | | 98.12- | 5/8 | MC-T433 | MK-T244 | 98.12- | 7/8 | CC-T395 | CK-T225 |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| GRANACE : 300 ser. | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2800ディーゼル)<br>3DA－GDH303W | 19.12- | | | セッテイナシ | 19.12- | | DISC | | | 19.12- | | DISC | | | 19.12- | (R)<br>(L) | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | | | (オートマチック) | | | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| NOAH, VOXY : 60 ser.(01.11-) | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000) TA－AZR60G | 01.11-07.6 | | | | 01.11-07.6 | | DISC | A-667P | CPA-667 | 01.11-07.6 | 13/16 | (R)WC-T787<br>(L)WC-T787 | WK-900 | CUP | 01.11-07.6 | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| TA－AZR65G(4WD) | <VSC無><br>01.11-07.6<br><VSC付><br>01.11-07.6 | 13/16<br>13/16 | TD-T913<br>TD-T934 | | 01.11-07.6 | | DISC | A-667P | CPA-667 | 01.11-07.6 | 13/16 | (R)WC-T787<br>(L)WC-T787 | WK-900 | CUP | 01.11-07.6 | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| NOAH, VOXY : 70 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000) | DBA－ZRR70G | ドラム車 | 07.6- | | | | 07.6- | | DISC | MP-114 | CPM-106 | 07.6- | 7/8 | (R)WC-T796<br>(L)WC-T796 | WK-1051 | CUP | 07.6- | (R)<br>(L) | (R-1)<br>(L-1)<br>(R-2)BH-T841<br>(L-2)BH-T841 | | | (オートマチック) | | | | | |
| | | ディスク車 | 07.6- | | | | 07.6- | | DISC | MP-114 | CPM-106 | 07.6-11.4<br>11.4- | | DISC<br>DISC | MP-94 | | 07.6- | (R)<br>(L) | (R-1)<br>(L-1)<br>(R-2)BH-T841<br>(L-2)BH-T841 | | | (オートマチック) | | | | | |
| | DBA－ZRR70W | | 07.6- | | | | 07.6- | | DISC | MP-114 | CPM-106 | 07.6-11.4<br>11.4- | | DISC<br>DISC | MP-94 | | 07.6- | (R)<br>(L) | (R-1)<br>(L-1)<br>(R-2)BH-T841<br>(L-2)BH-T841 | | | (オートマチック) | | | | | |
| | DBA－ZRR75G | 4WD | 07.6- | | | | 07.6- | | DISC | MP-114 | CPM-106 | 07.6-11.4<br>11.4- | | DISC<br>DISC | MP-94 | | 07.6- | (R)<br>(L) | (R-1)<br>(L-1)<br>(R-2)BH-T841<br>(L-2)BH-T841 | | | (オートマチック) | | | | | |
| | DBA－ZRR75W | 4WD | 07.6- | | | | 07.6- | | DISC | MP-114 | CPM-106 | 07.6-11.4<br>11.4- | | DISC<br>DISC | MP-94 | | 07.6- | (R)<br>(L) | (R-1)<br>(L-1)<br>(R-2)BH-T841<br>(L-2)BH-T841 | | | (オートマチック) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| NOAH, VOXY, ESQUIRE : 80 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) | DAA－ZWR80G | ハイブリッド<br>エスクァイア含む | 14.1- | | | | 14.1- | | DISC | MP-114 | CPM-106 | 14.1- | | DISC | SP-433 | | 14.1- | (R)<br>(L) | (R-1)<br>(L-1)<br>(R-2)<br>(L-2) | | | (オートマチック) | | | | | |
| | DAA－ZWR80W | ハイブリッド | 16.1-17.6<br>17.6- | | | キットセッテイナシ<br>キットセッテイナシ | 16.1- | | DISC | MP-114 | CPM-106 | 16.1- | | DISC | SP-433 | | 16.1- | (R)<br>(L) | (R-1)<br>(L-1)<br>(R-2)<br>(L-2) | | | (オートマチック) | | | | | |
| (2000) | DBA－ZRR80G | エスクァイア含む | 14.1- | | | | 14.1- | | DISC | MP-114 | CPM-106 | 14.1- | 7/8 | (R)WC-T796<br>(L)WC-T796 | WK-1051 | CUP | 14.1- | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| (2000) | DBA－ZRR80W | ドラム車 | 14.1- | | | | 14.1- | | DISC | MP-114 | CPM-106 | 14.1- | 7/8 | (R)WC-T796<br>(L)WC-T796 | WK-1051 | CUP | 14.1- | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| | | ディスク車 | 14.1- | | | | 14.1- | | DISC | MP-114 | CPM-106 | 14.1- | | DISC | SP-433 | | <ノヅ゛ク SI・ZS><br>14.1-<br><br><br><br><SI・ZS><br>14.1- | (R)<br>(L)<br><br><br><br>(R)<br>(L) | (R-1)<br>(L-1)<br>(R-2)<br>(L-2)<br><br>(R-1)<br>(L-1)<br>(R-2)<br>(L-2) | | | (オートマチック) | | | | | |
| | DBA－ZRR85G | 4WD<br>エスクァイア含む | 14.1- | | | | 14.1- | | DISC | MP-114 | CPM-106 | 14.1- | | DISC | SP-433 | | <ノヅ゛ク SI・ZS><br>14.1-<br><br><br><br><SI・ZS><br>14.1- | (R)<br>(L)<br><br><br><br>(R)<br>(L) | (R-1)<br>(L-1)<br>(R-2)<br>(L-2)<br><br>(R-1)<br>(L-1)<br>(R-2)<br>(L-2) | | | (オートマチック) | | | | | |
| | DBA－ZRR85W | 4WD | 14.1- | | | | 14.1- | | DISC | MP-114 | CPM-106 | 14.1- | | DISC | SP-433 | | <ノヅ゛ク SI・ZS><br>14.1-<br><br><br><br><SI・ZS><br>14.1- | (R)<br>(L)<br><br><br><br>(R)<br>(L) | (R-1)<br>(L-1)<br>(R-2)<br>(L-2)<br><br>(R-1)<br>(L-1)<br>(R-2)<br>(L-2) | | | (オートマチック) | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| MASTERACE SURF : 20, 30 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) | E−YR20G(ワゴン) | 82.11−85.8<br>85.8−92.1 | 15/16<br>1 | | TK−9428<br>TK−T010 | 82.11−85.8<br>85.8−92.1 | 2 1/4<br>60.3 | DISC<br>DISC | A−124P<br>C−226P | CPC−226 | <13インチホイール><br>82.11−92.1<br><14インチホイール><br>84.8−92.1 | 13/16<br><br>7/8 | (R)WC−50059<br>(L)WC−50059<br>(R)WC−50035<br>(L)WC−50035 | WK−492<br><br>WK−545 | CUP<br><br>CUP | 82.11−83.10<br>83.10−86.8<br>86.8−88.8<br>88.8−92.1 | BH−T822<br>BH−02394<br>BH−02505<br>BH−02505 | BH−94201<br>BH−94201<br>BH−94201<br>BH−T871 | 82.11−86.9<br>86.9−88.8<br>88.8−92.1 | 5/8<br>5/8<br>5/8 | | MK−4300<br>MK−4353<br>MK−4353 | 82.11−88.8 | 13/16<br>13/16 | CC−70145<br>CC−70145 | CK−3144<br>CK−3144 |
| | グランドサルーン | 82.11−85.8<br>85.8−88.8 | 15/16<br>1 | | TK−9428<br>TK−T010 | 82.11−85.8<br>85.8−88.8 | 2 1/4<br>60.3 | DISC<br>DISC | A−124P<br>C−226P | CPC−226 | 82.11−88.8 | 7/8 | (R)WC−50035<br>(L)WC−50035 | WK−545 | CUP | 82.11−83.10<br>83.10−86.8<br>86.8−88.8 | BH−T822<br>BH−02394<br>BH−02505 | BH−94201<br>BH−94201<br>BH−94201 | 82.11−86.9<br>86.9−88.8 | 5/8<br>5/8 | | MK−4300<br>MK−4353 | 82.11−88.8 | 13/16 | CC−70145 | CK−3144 |
| | E−YR28G(ワゴン) | 85.8−92.1 | 15/16 | | TK−T011 | 85.8−88.8<br>88.8−92.1 | 60.3<br>60.3 | DISC<br>DISC | C−226P<br>C−226P | CPC−226<br>CPC−226 | 85.8−92.1 | 13/16 | (R)WC−50059<br>(L)WC−50059 | WK−492 | CUP | 85.8−86.8<br>86.8−88.8<br>88.8−92.1 | BH−02394<br>BH−02505<br>BH−02505 | BH−31324<br>BH−31324<br>BH−02576 | 85.8−86.9<br>86.9−88.8<br>88.8−92.1 | 5/8<br>5/8<br>5/8 | | MK−4300<br>MK−4353<br>MK−4353 | 85.8−88.8 | 13/16<br>13/16 | CC−70145<br>CC−70145 | CK−3144<br>CK−3144 |
| (2000) | E−YR21G(ワゴン) | 83.5−85.8<br>85.8−92.1 | 15/16<br>1 | | TK−9428<br>TK−T010 | 83.5−85.8<br>85.8−92.1 | 2 1/4<br>60.3 | DISC<br>DISC | A−124P<br>C−226P | CPC−226 | 83.5−92.1 | 7/8 | (R)WC−50035<br>(L)WC−50035 | WK−545 | CUP | 83.5−83.10<br>83.10−86.8<br>86.8−88.8<br>88.8−92.1 | BH−T822<br>BH−02394<br>BH−02505<br>BH−02505 | BH−94201<br>BH−94201<br>BH−94201<br>BH−T871 | 83.5−86.9<br>86.9−88.8<br>88.8−92.1 | 5/8<br>5/8<br>5/8 | MC−T439 | MK−4300<br>MK−4353<br>MK−4353 | 83.5−88.8<br>88.8−92.1 | 7/8<br>13/16 | CC−70127<br>CC−70145 | CK−3122<br>CK−3144 |
| | E−YR30G(4WDワゴン) | 85.10−92.1 | 1 | | TK−T010 | 85.10−88.8<br>88.8−92.1 | 1 3/4<br>1 3/4 | DISC<br>DISC | A−239P<br>A−239P | CPA−239<br>CPA−239 | 85.10−92.1 | 13/16 | (R)WC−50065<br>(L)WC−50065 | WK−541 | CUP | 85.10−92.1 | BH−02221 | BH−02492 | 85.10−86.9<br>86.9−88.8<br>88.8−92.1 | 5/8<br>5/8<br>5/8 | MC−T439 | MK−4300<br>MK−4353<br>MK−4353 | 85.10−92.1 | 7/8 | CC−70127 | CK−3122 |
| | E−YR36G(4WDワゴン) | 86.8−92.1 | 1 | | TK−T010 | 86.8−88.8<br>88.8−92.1 | 1 3/4<br>1 3/4 | DISC<br>DISC | A−239P<br>A−239P | CPA−239<br>CPA−239 | 86.8−92.1 | 13/16 | (R)WC−50065<br>(L)WC−50065 | WK−541 | CUP | 86.8−88.8<br>88.8−89.2<br>89.2−92.1 | BH−02221<br>BH−02221<br>BH−02221 | BH−31324<br>BH−02576<br>BH−T681 | 86.8−88.8<br>88.8−92.1 | 5/8<br>5/8 | MC−T439 | MK−4353<br>MK−4353 | 86.8−92.1 | 7/8 | CC−70127 | CK−3122 |
| (2000ディーゼル) | | 83.4−85.8 | 15/16 | | TK−9428 | 83.4−85.8 | 2 1/4 | DISC | A−124P | | <13インチホイール><br>83.4−92.1 | 13/16 | (R)WC−50059 | WK−492 | CUP | 83.4−83.10 | BH−T822 | BH−94201 | 83.4−86.9 | 5/8 | | MK−4300 | 83.4−85.8 | 13/16 | CC−70149 | CK−3144 |
| | N−CR21G(ワゴン)<br><Q−は87. 8〜> | 85.8−92.1 | 1 | | TK−T010 | 85.8−88.8<br>88.8−92.1 | 60.3<br>60.3 | DISC<br>DISC | C−226P<br>C−226P | CPC−226<br>CPC−226 | <14インチホイール><br>83.4−92.1 | <br>7/8 | (L)WC−50059<br>(R)WC−50035<br>(L)WC−50035 | <br>WK−545 | <br>CUP | 83.10−86.8<br>86.8−88.8<br>88.8−92.1 | BH−02394<br>BH−02505<br>BH−02505 | BH−94201<br>BH−94201<br>BH−T871 | 86.9−92.1 | 5/8 | | MK−4353 | 85.8−90.6<br>90.6−92.1 | 13/16<br>13/16 | CC−70182<br>CC−70182 | CK−3144<br>CK−3144 |
| | N−CR28G(ワゴン)<br><Q−は87. 8〜> | 85.8−92.1 | 15/16 | | TK−T011 | 85.8−88.8<br>88.8−92.1 | 60.3<br>60.3 | DISC<br>DISC | C−226P<br>C−226P | CPC−226<br>CPC−226 | 85.8−87.8<br>87.8−92.1 | 13/16<br>7/8 | (R)WC−50059<br>(L)WC−50059<br>(R)WC−50035<br>(L)WC−50035 | WK−492<br><br>WK−545 | CUP<br><br>CUP | 85.8−86.8<br>86.8−88.8<br>88.8−92.1 | BH−02394<br>BH−02505<br>BH−02505 | BH−31324<br>BH−31324<br>BH−02576 | 85.8−86.9<br>86.9−92.1 | 5/8<br>5/8 | | MK−4300<br>MK−4353 | 85.8−90.6<br>90.6−92.1 | 13/16<br>13/16 | CC−70182<br>CC−70182 | CK−3144<br>CK−3144 |
| | N−CR30G(4WDワゴン)<br><Q−は87. 8〜> | 85.10−92.1 | 1 | | TK−T010 | 85.10−88.8<br>88.8−92.1 | 1 3/4<br>1 3/4 | DISC<br>DISC | A−239P<br>A−239P | CPA−239<br>CPA−239 | 85.10−92.1 | 13/16 | (R)WC−50065<br>(L)WC−50065 | WK−541 | CUP | 85.10−92.1<br>87.8−88.8 | BH−02221<br>BH−02221 | BH−02492<br>BH−31324 | 85.10−86.9<br>86.9−92.1 | 5/8<br>5/8 | | MK−4300<br>MK−4353 | 85.10−90.6<br>90.6−92.1 | 13/16<br>13/16 | CC−70182<br>CC−70182 | CK−3144<br>CK−3144 |
| | Q−CR37G(4WDワゴン) | 87.8−92.1 | 1 | | TK−T010 | 87.8−88.8<br>88.8−92.1 | 1 3/4<br>1 3/4 | DISC<br>DISC | A−239P<br>A−239P | CPA−239<br>CPA−239 | 87.8−92.1 | 13/16 | (R)WC−50065<br>(L)WC−50065 | WK−541 | CUP | 88.8−89.2<br>89.2−92.1 | BH−02221<br>BH−02221 | BH−02576<br>BH−T681 | 87.8−92.1 | 5/8 | | MK−4353 | 87.8−90.6<br>90.6−92.1 | 13/16<br>13/16 | CC−70182<br>CC−70182 | CK−3144<br>CK−3144 |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| ISIS : 10 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) | CBA－ZNM10G | 04.9- | | | | 04.9- | | DISC | MP-106 | CPM-106 | 04.9- | 13/16 | (R)WC-T787<br>(L)WC-T787 | WK-900 | CUP | 04.9- | (R)<br>(L) | (R)<br>(L) | 04.9- | | | | 04.9- | | | |
| | CBA－ZNM10W | 04.9- | | | | 04.9- | | DISC | MP-106 | CPM-106 | 04.9- | 13/16 | (R)WC-T787<br>(L)WC-T787 | WK-900 | CUP | 04.9- | (R)<br>(L) | (R)<br>(L) | 04.9- | | | | 04.9- | | | |
| | DBA－ZGM10G | 09.9- | | | | 09.9- | | DISC | MP-106 | CPM-106 | 09.9- | 13/16 | (R)WC-T787<br>(L)WC-T787 | WK-900 | CUP | 09.9- | (R)<br>(L) | (R)<br>(L) | 09.9- | | | | 09.9- | | | |
| | DBA－ZGM10W | 09.9- | | | | 09.9- | | DISC | MP-106 | CPM-106 | 09.9- | 13/16 | (R)WC-T787<br>(L)WC-T787 | WK-900 | CUP | 09.9- | (R)<br>(L) | (R)<br>(L) | 09.9- | | | | 09.9- | | | |
| | DBA－ZGM15G(4WD) | 09.9- | | | | 09.9- | | DISC | MP-106 | CPM-106 | 09.9- | | DISC | MP-99 | | 09.9- | (R)<br>(L) | (R-1)<br>(L-1)<br>(R-2)BH-T841<br>(L-2)BH-T841 | 09.9- | | | | 09.9- | | | |
| | DBA－ZGM15W(4WD) | 09.9- | | | | 09.9- | | DISC | MP-106 | CPM-106 | 09.9- | | DISC | MP-99 | | 09.9- | (R)<br>(L) | (R-1)<br>(L-1)<br>(R-2)BH-T841<br>(L-2)BH-T841 | 09.9- | | | | 09.9- | | | |
| (2000) | CBA－ANM10G<br>＜DBA－は05．11～＞ | 04.9- | | | | 04.9- | | DISC | MP-106 | CPM-106 | 04.9- | | DISC | MP-99 | | 04.9- | (R)<br>(L) | (R-1)<br>(L-1)<br>(R-2)BH-T841<br>(L-2)BH-T841 | 04.9- | | | | 04.9- | | | |
| | CBA－ANM10W<br>＜DBA－は05．11～＞ | 04.9- | | | | 04.9- | | DISC | MP-106 | CPM-106 | 04.9- | | DISC | MP-99 | | 04.9- | (R)<br>(L) | (R-1)<br>(L-1)<br>(R-2)BH-T841<br>(L-2)BH-T841 | 04.9- | | | | 04.9- | | | |
| | CBA－ANM15G<br>＜DBA－は05．11～＞ | 04.9- | | | | 04.9- | | DISC | MP-106 | CPM-106 | 04.9- | | DISC | MP-99 | | 04.9- | (R)<br>(L) | (R-1)<br>(L-1)<br>(R-2)BH-T841<br>(L-2)BH-T841 | 04.9- | | | | 04.9- | | | |
| | CBA－ANM15W<br>＜DBA－は05．11～＞ | 04.9- | | | | 04.9- | | DISC | MP-106 | CPM-106 | 04.9- | | DISC | MP-99 | | 04.9- | (R)<br>(L) | (R-1)<br>(L-1)<br>(R-2)BH-T841<br>(L-2)BH-T841 | 04.9- | | | | 04.9- | | | |
| | DBA－ZGM11G | 09.9- | | | | 09.9- | | DISC | MP-106 | CPM-106 | 09.9- | | DISC | MP-99 | | 09.9- | (R)<br>(L) | (R-1)<br>(L-1)<br>(R-2)BH-T841<br>(L-2)BH-T841 | 09.9- | | | | 09.9- | | | |
| | DBA－ZGM11W | 09.9- | | | | 09.9- | | DISC | MP-106 | CPM-106 | 09.9- | | DISC | MP-99 | | 09.9- | (R)<br>(L) | (R-1)<br>(L-1)<br>(R-2)BH-T841<br>(L-2)BH-T841 | 09.9- | | | | 09.9- | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| ESTIMA : 10, 20 ser. | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2400) E－TCR11W | 90.5-96.8 | 1 | | TK-T328 | 90.5-92.9 | | DISC | A-239P | CPA-239 | 90.5-99.12 | 42.8 | DISC | MP-41 | | 90.5-96.8 | (1)BH-T566 | (R)BH-T568 | | | (オートマチック) | | | | | |
| E－TCR21W(4WD) | 96.8-99.12 | 1 | | TK-T412 | 92.9-96.8 | | DISC | A-239P | CPA-239 | | | | | | | (2)BH-T567 | (L)BH-T568 | | | | | | | | |
| ＜GF－は98．1～＞ | | | | | 96.8-99.12 | 2 3/8 | DISC | A-379P | CPA-379 | | | | | | 96.8-99.12 | (1)BH-T566 | (R)BH-T568 | | | | | | | | |
| | | | | | | | | | | | | | | | | (2)BH-T714 | (L)BH-T568 | | | | | | | | |
| E－TCR10W | 93.2-95.8 | 1 | | TK-T347 | 93.2-96.8 | 2 3/8 | DISC | A-379P | CPA-379 | 93.2-99.12 | 42.8 | DISC | MP-41 | | 93.2-96.8 | (1)BH-T566 | (C)BH-T620 | | | (オートマチック) | | | | | |
| E－TCR20W(4WD) | 95.8-96.8 | 1 | | TK-T364 | ＜ｱﾝﾁｽｷｯﾄﾞ付＞ | | | | | | | | | | | (2)BH-T567 | (R)BH-T603 | | | | | | | | |
| ＜GF－は98．1～＞ | ＜ｱﾝﾁｽｷｯﾄﾞ付＞ | | | | 93.2-96.8 | | DISC | A-239P | CPA-239 | | | | | | | | (L)BH-T603 | | | | | | | | |
| | 93.2-96.8 | 1 | | TK-T328 | 96.8-99.12 | 2 3/8 | DISC | A-379P | CPA-379 | | | | | | 96.8-98.1 | (1)BH-T566 | (C)BH-T620 | | | | | | | | |
| | 96.8-99.12 | 1 | | TK-T412 | | | | | | | | | | | | (2)BH-T714 | (R)BH-T603 | | | | | | | | |
| | | | | | | | | | | | | | | | | | (L)BH-T603 | | | | | | | | |
| | | | | | | | | | | | | | | | 98.1-99.12 | (1)BH-T566 | (C)BH-T620 | | | | | | | | |
| | | | | | | | | | | | | | | | | (2)BH-T714 | (R)BH-T866 | | | | | | | | |
| | | | | | | | | | | | | | | | | | (L)BH-T880 | | | | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| ESTIMA EMINA, ESTIMA LUCIDA : | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2400) | E−TCR10G | アンチスキッド無 | 92.1−93.8 | 1 | | TK−T347 | 92.1−93.8 | 2 3/8 | DISC | A−379P | CPA−379 | 92.1−96.7 | 7/8 | (R)WC−T589 | WK−405 | CUP | 92.1−96.8 | (1)BH−T566 | BH−T620 | 92.1−93.4 | 5/8 | MC−T440 | MK−T236 | 92.1−94.9 | 13/16 | | CK−3144 |
| | E−TCR20G(4WD) | | 93.8−96.8 | 1 | | TK−T364 | 93.8−96.8 | 2 3/8 | DISC | A−379P | CPA−379 | | | (L)WC−T589 | | | | (2)BH−T567 | | 93.4−94.3 | 5/8 | MC−T440 | | 94.9−96.8 | 13/16 | | CK−T201 |
| | ＜GF−は98．1～＞ | | ＜AT車＞ | | | | | | | | | 96.7−96.8 | 7/8 | (R)WC−T660 | WK−887 | CUP | | | | 94.3−96.8 | 5/8 | | MK−T244 | | | | |
| | | | 92.1−95.1 | 1 | | TK−T347 | | | | | | | | (L)WC−T660 | | | | | | | | | | | | | |
| | | | 95.1−96.8 | 1 | | TK−T364 | | | | | | | | | | | | | | | | | | | | | |
| | | アンチスキッド車 | 93.8−96.8 | 1 | | TK−T328 | 93.8−95.1 | | DISC | A−239P | CPA−239 | 93.8−99.12 | 42.8 | DISC | MP−41 | | 93.8−96.8 | (1)BH−T566 | (C)BH−T620 | 93.8−94.3 | 5/8 | | | 93.8−94.9 | 13/16 | | CK−3144 |
| | | | 96.8−99.12 | 1 | | TK−T412 | 95.1−96.8 | 2 3/8 | DISC | A−379P | CPA−379 | | | | | | | (2)BH−T567 | (R)BH−T603 | 94.3−96.8 | 5/8 | | MK−T244 | 94.9−96.8 | 13/16 | | CK−T201 |
| | | | | | | | 96.8−99.12 | 2 3/8 | DISC | A−379P | CPA−379 | | | | | | | | (L)BH−T603 | 96.8−99.12 | | (オートマチック) | | | | |
| | | | | | | | | | | | | | | | | | 96.8−98.1 | (1)BH−T566 | (C)BH−T620 | | | | | | | | |
| | | | | | | | | | | | | | | | | | | (2)BH−T714 | (R)BH−T603 | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | (L)BH−T603 | | | | | | | | |
| | | | | | | | | | | | | | | | | | 98.1−99.12 | (1)BH−T566 | (C)BH−T620 | | | | | | | | |
| | | | | | | | | | | | | | | | | | | (2)BH−T714 | (R)BH−T866 | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | (L)BH−T880 | | | | | | | | |
| | E−TCR11G | リヤードラム車 | 92.1−95.1 | 1 | | TK−T347 | 92.1−93.8 | 2 3/8 | DISC | A−379P | CPA−379 | 92.1−96.7 | 7/8 | (R)WC−T589 | WK−405 | CUP | 92.1−96.8 | (1)BH−T566 | (R)BH−T621 | 92.1−93.4 | 5/8 | MC−T440 | MK−T236 | 92.1−93.8 | 13/16 | | CK−3144 |
| | E−TCR21G(4WD) | | 95.1−96.8 | 1 | | TK−T364 | 93.8−96.8 | 2 3/8 | DISC | A−379P | CPA−379 | | | (L)WC−T589 | | | | (2)BH−T567 | (L)BH−T617 | 93.4−93.8 | 5/8 | MC−T440 | | | | | |
| | ＜GF−は98．1～＞ | | | | | | | | | | | 96.7−96.8 | 7/8 | (R)WC−T660 | WK−887 | CUP | | | | 93.8−96.8 | | (オートマチック) | | | | | |
| | | | | | | | | | | | | | | (L)WC−T660 | | | | | | | | | | | | | |
| | | 四輪ディスク車 | 92.1−96.8 | 1 | | TK−T347 | 92.1−93.8 | | DISC | A−239P | CPA−239 | 92.1−99.12 | 42.8 | DISC | MP−41 | | 92.1−96.8 | (1)BH−T566 | (R)BH−T618 | 92.1−93.4 | 5/8 | MC−T440 | MK−T236 | 92.1−93.8 | 13/16 | | CK−3144 |
| | | | ＜ｱﾝﾁｽｷｯﾄﾞ付＞ | | | | 93.8−96.8 | 2 3/8 | DISC | A−379P | CPA−379 | | | | | | | (2)BH−T567 | (L)BH−T568 | 93.4−93.8 | 5/8 | MC−T440 | | | | | |
| | | | 92.1−96.8 | 1 | | TK−T328 | ＜ｱﾝﾁｽｷｯﾄﾞ付＞ | | | | | | | | | | 96.8−99.12 | (1)BH−T566 | (R)BH−T618 | 93.8−99.12 | | (オートマチック) | | | | | |
| | | | 96.8−99.12 | 1 | | TK−T412 | 92.1−95.1 | | DISC | A−239P | CPA−239 | | | | | | | (2)BH−T714 | (L)BH−T568 | | | | | | | | |
| | | | | | | | 95.1−96.8 | 2 3/8 | DISC | A−379P | CPA−379 | | | | | | | | | | | | | | | | |
| | | | | | | | 96.8−99.12 | 2 3/8 | DISC | A−379P | CPA−379 | | | | | | | | | | | | | | | | |
| (2200ディーゼル) | | アンチスキッド無 | 92.1−95.1 | 1 | | TK−T347 | 92.1−93.8 | 2 3/8 | DISC | A−379P | CPA−379 | 92.1−96.7 | 7/8 | (R)WC−T589 | WK−405 | CUP | 92.1−96.8 | (1)BH−T566 | BH−T620 | 92.1−93.4 | 5/8 | MC−T440 | MK−T236 | 92.1−94.9 | 13/16 | | CK−3144 |
| | Q−CXR10G | | 95.1−96.8 | 1 | | TK−T364 | 93.8−96.8 | 2 3/8 | DISC | A−379P | CPA−379 | | | (L)WC−T589 | | | | (2)BH−T567 | | 93.4−94.3 | 5/8 | MC−T440 | | 94.9−96.8 | 13/16 | | CK−T201 |
| | Q−CXR20G(4WD) | | | | | | | | | | | 96.7−96.8 | 7/8 | (R)WC−T660 | WK−887 | CUP | | | | 94.3−96.8 | 5/8 | | MK−T244 | | | | |
| | ＜Y−は93．8～＞ | | | | | | | | | | | | | (L)WC−T660 | | | | | | | | | | | | | |
| | ＜KD−は95．1～＞ | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | アンチスキッド車 | 93.8−96.8 | 1 | | TK−T328 | 93.8−95.1 | | DISC | A−239P | CPA−239 | 93.8−99.8 | 42.8 | DISC | MP−41 | | 93.8−96.8 | (1)BH−T566 | (C)BH−T620 | 93.8−94.3 | 5/8 | | | 93.8−94.9 | 13/16 | | CK−3144 |
| | | | 96.8−99.8 | 1 | | TK−T412 | 95.1−96.8 | 2 3/8 | DISC | A−379P | CPA−379 | | | | | | | (2)BH−T567 | (R)BH−T603 | 94.3−99.8 | 5/8 | | MK−T244 | 94.9−99.8 | 13/16 | | CK−T201 |
| | | | | | | | 96.8−99.8 | 2 3/8 | DISC | A−379P | CPA−379 | | | | | | | | (L)BH−T603 | 99.8−99.12 | | (オートマチック) | | | | |
| | | | | | | | | | | | | | | | | | 96.8−98.1 | (1)BH−T566 | (C)BH−T620 | | | | | | | | |
| | | | | | | | | | | | | | | | | | | (2)BH−T714 | (R)BH−T603 | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | (L)BH−T603 | | | | | | | | |
| | | | | | | | | | | | | | | | | | 98.1−99.8 | (1)BH−T566 | (C)BH−T620 | | | | | | | | |
| | | | | | | | | | | | | | | | | | | (2)BH−T714 | (R)BH−T866 | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | (L)BH−T880 | | | | | | | | |
| | Q−CXR11G | リヤードラム車 | 92.1−95.1 | 1 | | TK−T347 | 92.1−93.8 | 2 3/8 | DISC | A−379P | CPA−379 | 92.1−96.7 | 7/8 | (R)WC−T589 | WK−405 | CUP | 92.1−96.8 | (1)BH−T566 | (R)BH−T621 | 92.1−93.4 | 5/8 | MC−T440 | MK−T236 | 92.1−93.8 | 13/16 | | CK−3144 |
| | Q−CXR21G(4WD) | | 95.1−96.8 | 1 | | TK−T364 | 93.8−96.8 | 2 3/8 | DISC | A−379P | CPA−379 | | | (L)WC−T589 | | | | (2)BH−T567 | (L)BH−T617 | 93.4−93.8 | 5/8 | MC−T440 | | | | | |
| | ＜Y−は93．8～＞ | | | | | | | | | | | 96.7−96.8 | 7/8 | (R)WC−T660 | WK−887 | CUP | | | | 93.8−96.8 | | (オートマチック) | | | | | |
| | ＜KD−は95．1～＞ | | | | | | | | | | | | | (L)WC−T660 | | | | | | | | | | | | | |
| | | 四輪ディスク車 | 92.1−95.1 | 1 | | TK−T347 | 92.1−93.8 | 1 3/4 | DISC | A−239P | CPA−239 | 92.1−99.8 | 42.8 | DISC | MP−41 | | 92.1−96.8 | (1)BH−T566 | (R)BH−T618 | 92.1−93.4 | 5/8 | MC−T440 | MK−T236 | 92.1−93.8 | 13/16 | | CK−3144 |
| | | | 95.1−96.8 | 1 | | TK−T364 | 93.8−96.8 | 2 3/8 | DISC | A−379P | CPA−379 | | | | | | | (2)BH−T567 | (L)BH−T568 | 93.4−93.8 | 5/8 | MC−T440 | | | | | |
| | | | ＜ｱﾝﾁｽｷｯﾄﾞ付＞ | | | | ＜ｱﾝﾁｽｷｯﾄﾞ付＞ | | | | | | | | | | 96.8−99.8 | (1)BH−T566 | (R)BH−T618 | 93.8−99.8 | | (オートマチック) | | | | | |
| | | | 92.1−96.8 | 1 | | TK−T328 | 92.1−95.1 | 1 3/4 | DISC | A−239P | CPA−239 | | | | | | | (2)BH−T714 | (L)BH−T568 | | | | | | | | |
| | | | 96.8−99.8 | 1 | | TK−T412 | 95.1−96.8 | 2 3/8 | DISC | A−379P | CPA−379 | | | | | | | | | | | | | | | | |
| | | | | | | | 96.8−99.8 | 2 3/8 | DISC | A−379P | CPA−379 | | | | | | | | | | | | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| ESTIMA : T/L30, 40 ser.(99.12-) | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2400) | GH－ACR30W<br>GH－ACR40W(4WD)<br><TA－は01．4～><br><UA－は03．4～> | 00.2-03.4<br>03.4-06.1 | | | | 00.2-03.4<br>03.4-06.1 | | DISC<br>DISC | A-638P<br>MP-106 | CPA-667<br>CPM-106 | 00.2-06.1 | | DISC | MP-94 | | 00.2-03.4<br><br><br><br>03.4-06.1 | (R)BH-T799<br>(L)BH-T800<br><br><br><br>(R)<br>(L) | (R-1)BH-T838<br>(L-1)BH-T838<br>(R-2)BH-T841<br>(L-2)BH-T841<br>(R-1)BH-T905<br>(L-1)BH-T905<br>(R-2)BH-T841<br>(L-2)BH-T841 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (3000) | GH－MCR30W<br>GH－MCR40W(4WD)<br><TA－は01．4～> | 99.12-03.4<br>03.4-06.1<br><VSC付><br>99.12-03.4<br>03.4-06.1 | 13/16 | TD-T934 | ｷｯﾄｾｯﾃｲﾅｼ | 99.12-03.4<br>03.4-06.1 | | DISC<br>DISC | A-638P<br>MP-106 | CPA-667<br>CPM-106 | 99.12-06.1 | | DISC | MP-94 | | 99.12-03.4<br><br><br><br>03.4-06.1 | (R)BH-T799<br>(L)BH-T800<br><br><br><br>(R)<br>(L) | (R-1)BH-T838<br>(L-1)BH-T838<br>(R-2)BH-T841<br>(L-2)BH-T841<br>(R-1)BH-T905<br>(L-1)BH-T905<br>(R-2)BH-T841<br>(L-2)BH-T841 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| ESTIMA HYBRID : | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2400) | ZA－AHR10W(4WD) | 01.5- | | | | 01.5-03.8<br>03.8- | | DISC<br>DISC | A-638P<br>A-667P | CPA-667<br>CPA-667 | 01.5- | | DISC | MP-94 | | 01.5- | (R)BH-T799<br>(L)BH-T800 | (R-1)BH-T905<br>(L-1)BH-T905<br>(R-2)BH-T841<br>(L-2)BH-T841 | | | (オートマチック) | | | | | |
| | DAA－AHR20W | 06.6-12.04<br>12.04- | | | キットセッテイナシ<br>キットセッテイナシ | 06.6- | | DISC | A-735P | CPA-735 | 06.6- | | DISC | | | 06.6- | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| ESTIMA : 50 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2400) | DBA－ACR50W | | <VSC有><br>06.1-14.9<br>14.9- | 7/8 | TD-T926 | キットセッテイナシ<br>キットセッテイナシ | 06.1- | | DISC | A-735P | CPA-735 | 06.1- | | DISC | | | 06.1- | | | 06.1- | | | | 06.1- | | | |
| | | | <VSC無><br>06.1-14.9<br>14.9- | 13/16 | TD-T927 | キットセッテイナシ<br>キットセッテイナシ | | | | | | | | | | | | | | | | | | | | | |
| | DBA－ACR55W | 4WD | <VSC有><br>06.1-14.9<br>14.9- | 7/8 | TD-T926 | キットセッテイナシ<br>キットセッテイナシ | 06.1- | | DISC | A-735P | CPA-735 | 06.1- | | DISC | | | 06.1- | | | 06.1- | | | | 06.1- | | | |
| | | | <VSC無><br>06.1-14.9<br>14.9- | 13/16 | TD-T927 | キットセッテイナシ<br>キットセッテイナシ | | | | | | | | | | | | | | | | | | | | | |
| (3500) | DBA－GSR50W | | <VSC有><br>06.1-14.9<br>14.9- | 7/8 | TD-T926 | キットセッテイナシ<br>キットセッテイナシ | 06.1- | | DISC | A-735P | CPA-735 | 06.1- | | DISC | | | 06.1- | | | 06.1- | | | | 06.1- | | | |
| | | | <VSC無><br>06.1-12.4<br>12.4-14.9<br>14.9- | 13/16<br>7/8 | TD-T927<br>TD-T926 | キットセッテイナシ<br>キットセッテイナシ<br>キットセッテイナシ | | | | | | | | | | | | | | | | | | | | | |
| | DBA－GSR55W | 4WD | <VSC有><br>06.1-14.9<br>14.9- | 7/8 | TD-T926 | キットセッテイナシ<br>キットセッテイナシ | 06.1- | | DISC | A-735P | CPA-735 | 06.1- | | DISC | | | 06.1- | | | 06.1- | | | | 06.1- | | | |
| | | | <VSC無><br>06.1-12.4<br>12.4-14.9<br>14.9- | 13/16<br>7/8 | TD-T927<br>TD-T926 | キットセッテイナシ<br>キットセッテイナシ<br>キットセッテイナシ | | | | | | | | | | | | | | | | | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| GRANVIA, GRAND HIACE : 10, 20 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2700) | E−RCH11W | リヤードラム車 | 95.8−97.8 | 1 | | TK−T377 | 95.8−97.8 | | DISC | MP−86 | CPM−86 | 95.8−96.8<br>96.8−97.8 | 15/16<br>15/16 | (R)WC−50047<br>(L)WC−50047<br>(R)WC−T746<br>(L)WC−T746 | WK−309<br>WK−884 | CUP<br>CUP | 95.8−97.8 | (R)BH−T667<br>(L)BH−T668 | (R)BH−T665<br>(L)BH−T665 | | | (オートマチック) | | | | | |
| | | 4輪ディスク車 | 97.8−98.4 | 1 | | TK−T412 | 97.8−98.4 | | DISC | MP−86 | CPM−86 | 97.8−98.4 | | DISC | MP−63 | CPM−63 | 97.8−98.4 | (R)BH−T667<br>(L)BH−T668 | (R−1)BH−T665<br>(L−1)BH−T665<br>(R−2)BH−T756<br>(L−2)BH−T757 | | | (オートマチック) | | | | | |
| (3400) | E−VCH10W<br><GF−は99．7〜> | | 97.8−02.5 | 1 | | TK−T412 | 97.8−02.5 | | DISC | MP−86 | CPM−86 | 97.8−02.5 | | DISC | MP−63 | CPM−63 | 97.8−99.7<br>99.7−02.5 | (R)BH−T667<br>(L)BH−T668<br>(R)BH−T844<br>(L)BH−T845 | (R−1)BH−T665<br>(L−1)BH−T665<br>(R−2)BH−T756<br>(L−2)BH−T757<br>(R−1)BH−T789<br>(L−1)BH−T789<br>(R−2)BH−T842<br>(L−2)BH−T843 | | | (オートマチック) | | | | | |
| | E−VCH16W(4WD)<br><GF−は99．7〜> | | 97.8−02.5 | 1 | | TK−T412 | 97.8−02.5 | | DISC | MP−86 | CPM−86 | 97.8−02.5 | | DISC | MP−63 | CPM−63 | 97.8−99.7<br>99.7−02.5 | BH−T666 | (R−1)BH−T665<br>(L−1)BH−T665<br>(R−2)BH−T756<br>(L−2)BH−T757<br>(R−1)BH−T789<br>(L−1)BH−T789<br>(R−2)BH−T842<br>(L−2)BH−T843 | | | (オートマチック) | | | | | |
| | GE−VCH22K(バン) | | 99.7− | 1 | | TK−T412 | 99.7− | | DISC | MP−86 | CPM−86 | 99.7− | 1 | (R)<br>(L) | WK−898 | CUP | 99.7− | (R)BH−T844<br>(L)BH−T845 | (R)BH−T789<br>(L)BH−T789 | | | (オートマチック) | | | | | |
| | GE−VCH28K(4WDバン) | | 99.7− | 1 | | TK−T412 | 99.7− | | DISC | MP−86 | CPM−86 | 99.7− | 1 | (R)<br>(L) | WK−898 | CUP | 99.7− | | (R)BH−T789<br>(L)BH−T789 | | | (オートマチック) | | | | | |
| (3000ディーゼル) | | リヤードラム車 | 95.8−97.8 | 1 | | TK−T377 | 95.8−97.8 | | DISC | MP−86 | CPM−86 | 95.8−96.8<br>96.8−97.8 | 15/16<br>15/16 | (R)WC−50047<br>(L)WC−50047<br>(R)WC−T746<br>(L)WC−T746 | WK−309<br>WK−884 | CUP<br>CUP | 95.8−97.8 | (R)BH−T667<br>(L)BH−T668 | (R)BH−T665<br>(L)BH−T665 | | | (オートマチック) | | | | | |
| | KD−KCH10W<br><KH−は99．7〜> | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | 4輪ディスク車 | 97.8−02.5<br><油圧ﾌﾞｰｽﾀｰ><br>97.8−99.7<br>99.7−02.5 | 1 | | TK−T412 | 97.8− | | DISC | MP−86 | CPM−86 | 97.8−02.5 | | DISC | MP−63 | CPM−63 | 97.8−99.7<br>99.7−02.5<br><油圧ﾌﾞｰｽﾀｰ><br>97.8−99.7<br>99.7−02.5 | (R)BH−T667<br>(L)BH−T668<br>(R)BH−T844<br>(L)BH−T845<br>(R)<br>(L)<br>(R)<br>(L) | (R−1)BH−T665<br>(L−1)BH−T665<br>(R−2)BH−T756<br>(L−2)BH−T757<br>(R−1)BH−T789<br>(L−1)BH−T789<br>(R−2)BH−T842<br>(L−2)BH−T843<br>(R−1)<br>(L−1)<br>(R−2)BH−T758<br>(L−2)<br>(R−1)<br>(L−1)<br>(R−2)<br>(L−2) | | | (オートマチック) | | | | | |
| | KD−KCH16W(4WD)<br><KH−は99．7〜> | リヤードラム車 | 95.10−97.8 | 1 | | TK−T377 | 95.10−97.8 | | DISC | MP−86 | CPM−86 | 95.10−96.8<br>96.8−97.8 | 15/16<br>15/16 | (R)WC−50047<br>(L)WC−50047<br>(R)WC−T746<br>(L)WC−T746 | WK−309<br>WK−884 | CUP<br>CUP | 95.10−97.8 | BH−T666 | (R)BH−T665<br>(L)BH−T665 | | | (オートマチック) | | | | | |
| | | 4輪ディスク車 | 97.8−02.5<br><油圧ﾌﾞｰｽﾀｰ><br>99.7−02.5 | 1 | | TK−T412 | 97.8−02.5 | | DISC | MP−86 | CPM−86 | 97.8−02.5 | | DISC | MP−63 | | 97.8−99.7<br>99.7−02.5<br><油圧ﾌﾞｰｽﾀｰ><br>99.7−02.5 | BH−T666 | (R−1)BH−T665<br>(L−1)BH−T665<br>(R−2)BH−T756<br>(L−2)BH−T757<br>(R−1)BH−T789<br>(L−1)BH−T789<br>(R−2)BH−T842<br>(L−2)BH−T843<br>(R−1)<br>(L−1)<br>(R−2)<br>(L−2) | | | (オートマチック) | | | | | |
| | KC−KCH12K(バン) | | 95.8−97.8<br><ｱﾝﾁｽｷｯﾄﾞ付><br>95.8−97.8 | 1<br><br>1 | | TK−T378<br><br>TK−T377 | 95.8−97.8 | | DISC | MP−86 | CPM−86 | 95.8−96.8<br>96.8−97.8 | 1<br>1 | (R)WC−50048<br>(L)WC−50048<br>(R)<br>(L) | WK−795<br>WK−898 | CUP<br>CUP | 95.8−97.8 | (R)BH−T667<br>(L)BH−T668 | (R)BH−T665<br>(L)BH−T665 | | | (オートマチック) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| ALPHARD : 10 ser.(02.5-) | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2400) | UA-ANH10W<br>UA-ANH15W(4WD)<br><CBA-は04. 12~><br><DBA-は04. 12~> | | 02.5- | | | | 02.5- | | DISC | MP-106 | CPM-106 | 02.5- | | DISC | MP-94 | | 02.5- | (R)<br>(L) | (R-1)BH-T905<br>(L-1)BH-T905<br>(R-2)<br>(L-2) | | | (オートマチック) | | | | | |
| | ZA-ATH10W<br><CAA-は04. 2~><br><DAA-は06. 6~> | ハイブリッド車 | 03.7- | | | | 03.7- | | DISC | MP-106 | CPM-106 | 03.7- | | DISC | MP-94 | | 03.7- | (R)<br>(L) | (R-1)BH-T905<br>(L-1)BH-T905<br>(R-2)<br>(L-2) | | | (オートマチック) | | | | | |
| (3000) | TA-MNH10W<br>TA-MNH15W(4WD)<br><CBA-は07. 6~> | | 02.5- | | | | 02.5- | | DISC | MP-106 | CPM-106 | 02.5- | | DISC | MP-94 | | 02.5- | (R)<br>(L) | (R-1)BH-T905<br>(L-1)BH-T905<br>(R-2)<br>(L-2) | | | (オートマチック) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| ALPHARD, VERFIRE : 20, 30 , 40ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2400) | DBA－ANH20W | | 08.5-11.10<br>11.10-15.1 | 7/8 | TD-T926 | ｷｯﾄｾｯﾃｲﾅｼ | 08.5-15.1<br><G SPORTS><br>12.11-15.1 | | DISC<br>DISC | A-735P<br>C-815P | CPA-735 | 08.5-15.1<br><G SPORTS><br>12.11-15.1 | | DISC<br>DISC | | | 08.5-15.1<br><G SPORTS><br>12.11-15.1 | (R)<br>(L)<br>(R)<br>(L) | (R)<br>(L)<br>(R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | |
| | DAA－ATH20W | ハイブリッド | 11.11-15.1 | 3/4 | TD-T940 | ｷｯﾄｾｯﾃｲﾅｼ | 11.11-15.1 | | DISC | A-735P | CPA-735 | 11.11-15.1 | | DISC | | | 11.11-15.1 | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | |
| (2500) | DBA－AGH30W | | 15.1- | | | | 15.1- | | DISC | A-735P | CPA-735 | 15.1- | | DISC | SP-482 | | 15.1- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | |
| | DBA－AGH35W | | 15.1- | | | | 15.1- | | DISC | A-735P | CPA-735 | 15.1- | | DISC | SP-482 | | 15.1- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | |
| | DAA－AYH30W | ハイブリッド | 15.1- | | | | 15.1- | | DISC | A-735P | CPA-735 | 15.1- | | DISC | SP-482 | | 15.1- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | |
| | DBA－ANH25W | 4WD | 08.5-11.10<br>11.10-15.1 | 7/8 | TD-T926 | ｷｯﾄｾｯﾃｲﾅｼ | 08.5-15.1 | | DISC | A-735P | CPA-735 | 08.5-15.1 | | DISC | | | 08.5-15.1 | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | |
| | 6AA－AAHH40W | ハイブリッド | 23.5- | | | | 23.5- | | DISC | C-815P | | 23.5- | | DISC | | | 23.5- | (R)<br>(L) | (R)<br>(L) | | | (電気式無段変速機) | | | | |
| | 6AA－AAHH45W | 電気式 | 23.5- | | | | 23.5- | | DISC | C-815P | | 23.5- | | DISC | | | 23.5- | (R)<br>(L) | (R)<br>(L) | | | (電気式無段変速機) | | | | |
| | 3BA－AGH40W | | 23.5- | | | ｷｯﾄｾｯﾃｲﾅｼ | 23.5- | | DISC | C-815P | | 23.5- | | DISC | | | 23.5- | (R)<br>(L) | (R)<br>(L) | | | (自動無段変速機) | | | | |
| | 3BA－AGH45W | 4WD | 23.5- | | | ｷｯﾄｾｯﾃｲﾅｼ | 23.5- | | DISC | C-815P | | 23.5- | | DISC | | | 23.5- | (R)<br>(L) | (R)<br>(L) | | | (自動無段変速機) | | | | |
| (3500) | DBA－GGH20W | | 08.5-11.10<br>11.10-15.1 | 7/8 | TD-T926 | ｷｯﾄｾｯﾃｲﾅｼ | 08.5-15.1<br><G SPORTS><br>12.11-15.1 | | DISC<br>DISC | A-735P<br>C-815P | CPA-735 | 08.5-15.1<br><G SPORTS><br>12.11-15.1 | | DISC<br>DISC | | | 08.5-15.1<br><G SPORTS><br>12.11-15.1 | (R)<br>(L)<br>(R)<br>(L) | (R)<br>(L)<br>(R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | |
| | DBA－GGH25W | 4WD | 08.5-11.10<br>11.10-15.1 | 7/8 | TD-T926 | ｷｯﾄｾｯﾃｲﾅｼ | 08.5-15.1 | | DISC | A-735P | CPA-735 | 08.5-15.1 | | DISC | | | 08.5-15.1 | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | |
| | DBA－GGH30W | | 15.1- | | | | 15.1-18.1<br>18.1- | | DISC<br>DISC | A-735P | CPA-735<br>C-815P | 15.1- | | DISC | SP-482 | | 15.1- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | |
| | DBA－GGH35W | | 15.1- | | | | 15.1-18.1<br>18.1- | | DISC<br>DISC | A-735P | CPA-735<br>C-815P | 15.1- | | DISC | SP-482 | | 15.1- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| NADIA : 10 ser.(98.7-) | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000) | GF-SXN10<br>TA-ACN10<br><TA-は01. 4～> | | 98.7-01.4<br>01.4- | 15/16<br>15/16 | | TK-T438<br>TK-T401 | 98.7-01.4<br>01.4- | | DISC<br>DISC | A-678P | CPA-678 | 98.7- | 13/16 | (R)WC-T788<br>(L)WC-T788 | WK-900 | CUP | 98.7-99.12<br><br>99.12- | (R)BH-T745<br>(L)BH-T700<br>(R)BH-T745<br>(L)BH-T700 | (R)BH-T701<br>(L)BH-T701<br>(R)BH-T847<br>(L)BH-T847 | | | (オートマチック) | | | | | |
| | GF-SXN10H<br>TA-ACN10H<br><TA-は01. 4～> | SU | 99.6-01.4<br>01.4- | 15/16<br>15/16 | | TK-T438<br>TK-T401 | 99.6-01.4<br>01.4- | | DISC<br>DISC | A-678P | CPA-678 | 99.6- | 13/16 | (R)WC-T788<br>(L)WC-T788 | WK-900 | CUP | 99.6-99.12<br><br>99.12- | (R)BH-T898<br>(L)BH-T899<br>(R)BH-T898<br>(L)BH-T899 | (R)BH-T701<br>(L)BH-T701<br>(R)BH-T847<br>(L)BH-T847 | | | (オートマチック) | | | | | |
| | GF-SXN15(4WD)<br>TA-ACN15<br><TA-は02. 7～> | | 98.7- | 15/16 | | TK-T401 | 98.7-01.4<br>01.4- | | DISC<br>DISC | A-678P | CPA-678 | 98.7- | 13/16 | (R)WC-T788<br>(L)WC-T788 | WK-900 | CUP | 98.7-99.12<br><br>99.12- | (R)BH-T745<br>(L)BH-T700<br>(R)BH-T745<br>(L)BH-T700 | (R)BH-T701<br>(L)BH-T701<br>(R)BH-T847<br>(L)BH-T847 | | | (オートマチック) | | | | | |
| | GF-SXN15H(4WD)<br>TA-ACN15H<br><TA-は02. 7～> | SU | 99.6- | 15/16 | | TK-T401 | 99.6-01.4<br>01.4- | | DISC<br>DISC | A-678P | CPA-678 | 99.6- | 13/16 | (R)WC-T788<br>(L)WC-T788 | WK-900 | CUP | 99.6-99.12<br><br>99.12- | (R)BH-T898<br>(L)BH-T899<br>(R)BH-T898<br>(L)BH-T899 | (R)BH-T701<br>(L)BH-T701<br>(R)BH-T847<br>(L)BH-T847 | | | (オートマチック) | | | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| GAIA : 10 ser.(98.5-) | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000) GF－SXM10G<br>TA－ACM10G<br>＜TA－は01．4～＞ | 98.5-01.4<br>01.4- | 15/16<br>15/16 | | TK-T438<br>TK-T401 | 98.5-01.4<br>01.4- | 57.2 | DISC<br>DISC | MP-68<br>A-678P | CPM-68<br>CPA-678 | 98.5- | 13/16 | (R)WC-T788<br>(L)WC-T788 | WK-900 | CUP | 98.5-00.4<br><br>00.4- | (R)BH-T745<br>(L)BH-T700<br>(R)BH-T745<br>(L)BH-T700 | (R)BH-T701<br>(L)BH-T701<br>(R)BH-T847<br>(L)BH-T847 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | | |
| GF－SXM15G(4WD)<br>TA－ACM15G<br>＜TA－は02．8～＞ | 98.5- | 15/16 | | TK-T401 | 98.5-01.4<br>01.4- | 57.2 | DISC<br>DISC | MP-68<br>A-678P | CPM-68<br>CPA-678 | 98.5- | 13/16 | (R)WC-T788<br>(L)WC-T788 | WK-900 | CUP | 98.5-00.4<br><br>00.4- | (R)BH-T745<br>(L)BH-T700<br>(R)BH-T745<br>(L)BH-T700 | (R)BH-T701<br>(L)BH-T701<br>(R)BH-T847<br>(L)BH-T847 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | | |
| (2200ディーゼル)<br>KH－CXM10G | 98.5-01.4<br>01.4- | 15/16<br>15/16 | | TK-T438<br>TK-T401 | 98.5-01.4<br>01.4- | 57.2 | DISC<br>DISC | MP-68<br>A-678P | CPM-68<br>CPA-678 | 98.5- | 13/16 | (R)WC-T788<br>(L)WC-T788 | WK-900 | CUP | 98.5-00.4<br><br>00.4- | (R)BH-T745<br>(L)BH-T700<br>(R)BH-T745<br>(L)BH-T700 | (R)BH-T701<br>(L)BH-T701<br>(R)BH-T847<br>(L)BH-T847 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| IPSUM : 10 ser. | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000) E－SXM10G<br>＜GF－は98．4～＞ | 96.5-97.8<br>97.8-01.5 | 15/16<br>15/16 | | TK-T367<br>TK-T438 | 96.5-01.5 | 57.2 | DISC | MP-68 | CPM-68 | 96.5-01.5 | 13/16 | (R)WC-T788<br>(L)WC-T788 | WK-900 | CUP | 96.5-00.4<br><br>00.4-01.5 | (R)BH-T745<br>(L)BH-T700<br>(R)BH-T745<br>(L)BH-T700 | (R)BH-T701<br>(L)BH-T701<br>(R)BH-T847<br>(L)BH-T847 | | | (オートマチック) | | | | | |
| E－SXM15G(4WD)<br>＜GF－は98．4～＞ | 96.5-97.8<br>97.8-98.4<br>98.4-01.5 | 15/16<br>15/16<br>15/16 | | TK-T367<br>TK-T438<br>TK-T401 | 96.5-01.5 | 57.2 | DISC | MP-68 | CPM-68 | 96.5-01.5 | 13/16 | (R)WC-T788<br>(L)WC-T788 | WK-900 | CUP | 96.5-00.4<br><br>00.4-01.5 | (R)BH-T745<br>(L)BH-T700<br>(R)BH-T745<br>(L)BH-T700 | (R)BH-T701<br>(L)BH-T701<br>(R)BH-T847<br>(L)BH-T847 | | | (オートマチック) | | | | | |
| (2200ディーゼル)<br>KH－CXM10G | 97.8-01.5 | 15/16 | | TK-T438 | 97.8-01.5 | 57.2 | DISC | MP-68 | CPM-68 | 96.5-01.5 | 13/16 | (R)WC-T788<br>(L)WC-T788 | WK-900 | CUP | 97.8-00.4<br><br>00.4-01.5 | (R)BH-T745<br>(L)BH-T700<br>(R)BH-T745<br>(L)BH-T700 | (R)BH-T701<br>(L)BH-T701<br>(R)BH-T847<br>(L)BH-T847 | | | (オートマチック) | | | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| IPSUM : 20 ser. | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2400) TA－ACM21W<br>＜UA－は03．10～＞<br>＜CBA－は04．2～＞<br>＜DBA－は05．8～＞ | 01.5-09.12 | 13/16 | TD-T913 | | 01.5-09.12 | | DISC | A-667P | CPA-667 | 01.5-09.12 | | DISC | MP-99 | | 01.5-09.12 | (R)<br>(L) | (R-1)<br>(L-1)<br>(R-2)BH-T841<br>(L-2)BH-T841 | | | (オートマチック) | | | | | |
| TA－ACM26W(4WD)<br>＜UA－は03．10～＞<br>＜CBA－は04．2～＞<br>＜DBA－は05．8～＞ | <VSC無><br>01.5-09.12<br><VSC付><br>01.5-09.12 | 13/16<br>13/16 | TD-T913<br>TD-T934 | | 01.5-09.12 | | MD-300 | A-667P | CPA-667 | 01.5-09.12 | | MD-277M | MP-99 | | 01.5-09.12 | (R)<br>(L) | (R-1)<br>(L-1)<br>(R-2)BH-T841<br>(L-2)BH-T841 | | | (オートマチック) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| HIACE : RH10 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | <トラック> | | | | | | | | | | |
| (1350) | PH10 | トラック・バン | 67.9-71.8 | 1 | | MK-5515-M | 67.9-73.9 | 1 1/4 | (R-1)WC-29035 | WK-058 | CUP | 67.9-72.3 | 7/8 | (R)WC-39015 | WK-059 | CUP | 67.9-68.2 | BH-02069 | BH-02121 | 67.9-72.2 | 3/4 | | MK-41400 | 67.9-70.10 | 15 | CC-40381 | FC-31480-B |
| (1500) | RH11・15・16 | ワゴン・バス | 71.9-73.9 | 1 | *56 | MK-4404 | | | (R-2)WC-29035 | | | | | (L)WC-39015 | | | 68.2-69.5 | BH-02077 | BH-02121 | 72.2-75.11 | 3/4 | MC-10097 | MK-41400 | 7010-7511 | 15 | CC-70097 | FC-31480-B |
| | | | 73.1-73.9 | 1 | *33 | MK-4405 | | | (L-1)WC-29037 | | | 72.3-73.9 | 13/16 | (R)WC-5565 | WK-104 | CUP | 69.5-75.11 | BH-02077 | BH-31400 | | | | | | | | |
| | | | 73.9-75.11 | 1 | | TK-9335 | | | (L-2)WC-29037 | | | | | (L)WC-5565 | | | <ワゴン・バン・バス> | | | | | | | | | | |
| | | | | | | | 73.9-75.11 | 1 1/4 | (R-1)WC-51005 | WK-058 | CUP | 73.9-75.5 | 7/8 | (R)WC-39015 | WK-059 | CUP | 67.9-68.2 | BH-02069 | BH-02121 | | | | | | | | |
| | | | | | | | | | (R-2)WC-51005 | | | | | (L)WC-39015 | | | 68.2-75.11 | BH-02077 | BH-02121 | | | | | | | | |
| | | | | | | | | | (L-1)WC-53005 | | | 75.5-75.11 | 7/8 | (R)WC-39015 | WK-317 | CUP | | | | | | | | | | | |
| | | | | | | | | | (L-2)WC-53005 | | | | | (L)WC-39015 | | | | | | | | | | | | | | |
| | | | | | | | | | | | | <LSPV付> | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | 73.1-73.9 | 7/8 | (R)WC-39015 | WK-059 | CUP | | | | | | | | | | | |
| | | | | | | | | | | | | | | (L)WC-39015 | | | | | | | | | | | | | |
| (1600) | RH11・13 | トラック・バン・バス | 75.11-77.1 | 15/16 | | TK-9351 | 7511-7912 | 1 1/8 | (R-1)WC-52006 | WK-314 | CUP | 7511-7912 | 7/8 | (R)WC-50046 | WK-048 | CUP | 75.11-77.1 | BH-31305 | BH-31422 | 75.11-77.1 | 3/4 | MC-10097 | MK-41400 | 7511-7711 | 15 | CC-70097 | FC-31480-B |
| | | | 77.2-79.12 | 15/16 | | TK-9358 | | | (R-2)WC-51006 | | | | | (L)WC-50046 | | | 77.2-79.12 | BH-02350 | BH-31360 | 77.2-79.12 | 5/8 | MC-10070 | MK-4300 | 7711-7912 | 15 | CC-70122 | CK-3119 |
| | | | | | | | | | (L-1)WC-54006 | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | (L-2)WC-53006 | | | | | | | | | | | | | | | | | | | |
| | RH12・14 | バン | 75.11-77.1 | 15/16 | | TK-9351 | 75.11-77.1 | 1 1/8 | (R-1)WC-52006 | WK-314 | CUP | 75.11-77.1 | 7/8 | (R)WC-50046 | WK-048 | CUP | 75.11-77.1 | BH-31305 | BH-31422 | 75.11-77.1 | 3/4 | MC-10097 | MK-41400 | 75.11-77.1 | 3/4 | CC-70090 | CK-3108 |
| | | | | | | | | | (R-2)WC-51006 | | | | | (L)WC-50046 | | | | | | | | | | | | | |
| | | | | | | | | | (L-1)WC-54006 | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | (L-2)WC-53006 | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | <RH16> | | | |
| | RH16・17 | バン・バス | 75.11-77.1 | 15/16 | | TK-9351 | 75.11-77.1 | 1 1/8 | (R-1)WC-52006 | WK-314 | CUP | 75.11-77.1 | 13/16 | (R)WC-50051 | WK-106 | CUP | 75.11-77.1 | BH-31305 | BH-31422 | 75.11-77.1 | 3/4 | MC-10097 | MK-41400 | 75.11-77.1 | 15 | CC-70097 | FC-31480-B |
| | | | | | | | | | (R-2)WC-51006 | | | | | (L)WC-50051 | | | | | | | | | | <RH17> | | | |
| | | | | | | | | | (L-1)WC-54006 | | | | | | | | | | | | | | | 75.11-77.1 | 3/4 | CC-70090 | CK-3108 |
| | | | | | | | | | (L-2)WC-53006 | | | | | | | | | | | | | | | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| HIACE : 20, 30, 40 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1600) | RH20V・30V(バン)<br>RH20B・30B(バス) | | 77.2-79.12 | 15/16 | | TK-9358 | 77.2-79.12 | 1 1/8 | (R-1)WC-52006<br>(R-2)WC-51006<br>(L-1)WC-54006<br>(L-2)WC-53006 | WK-314 | CUP | 77.2-79.12 | 7/8 | (R)WC-50046<br>(L)WC-50046 | WK-048 | CUP | 77.2-79.12 | BH-02350 | BH-31360 | 77.2-79.12 | 5/8 | MC-10070 | MK-4300 | 77.2-77.11<br>7711-7912 | 15<br>15 | CC-70097<br>CC-70122 | FC-31480-B<br>CK-3119 |
| (1800) | RH21V・31V(バン) | | 77.2-79.12 | 15/16 | | TK-9358 | 77.2-79.12 | 1 1/8 | (R-1)WC-52006<br>(R-2)WC-51006<br>(L-1)WC-54006<br>(L-2)WC-53006 | WK-314 | CUP | 77.2-79.12 | 7/8 | (R)WC-50046<br>(L)WC-50046 | WK-048 | CUP | 77.2-79.12 | BH-02350 | BH-31360 | 77.2-79.12 | 5/8 | MC-10070 | MK-4300 | 77.2-79.12 | 3/4 | CC-70090 | CK-3108 |
| (2000) | RH22G(ワゴン) | ドラム車 | 77.4-79.3 | 15/16 | | TK-9358 | 77.4-79.3 | 1 1/8 | (R-1)WC-52006<br>(R-2)WC-51006<br>(L-1)WC-54006<br>(L-2)WC-53006 | WK-314 | CUP | 77.4-79.3 | 7/8 | (R)WC-50046<br>(L)WC-50046 | WK-048 | CUP | 77.4-79.3 | BH-02350 | BH-31360 | 77.4-79.3 | 5/8 | MC-10070 | MK-4300 | 77.4-79.3 | 3/4 | CC-70090 | CK-3108 |
| | | ディスク車 | 77.4-79.3 | 15/16 | | TK-9386 | 77.4-79.3 | 2 3/8 | DISC | MP-4 | | 77.4-79.3 | 13/16 | (R)WC-50051<br>(L)WC-50051 | WK-106 | CUP | 77.4-79.3 | (1)BH-31305<br>(2)BH-02311 | BH-31360 | 77.4-79.3 | 5/8 | MC-10070 | MK-4300 | 77.4-79.3 | 3/4 | CC-70090 | CK-3108 |
| | RH23G・33G(ワゴン) | | 79.3-82.11 | 15/16 | | TK-9408 | 79.3-82.11<br>82.11 | 2 3/8<br>2 3/8 | DISC<br>DISC | MP-4<br>MP-9 | | 79.3-82.11 | 7/8 | (R)WC-50054<br>(L)WC-50054 | WK-405 | CUP | 79.3-82.11 | (1)BH-31305<br>(2)BH-02311 | BH-31360 | 79.3-81.5<br>81.5-82.11 | 5/8<br>5/8 | MC-10070 | MK-4300<br>MK-4300 | 79.3-80.12<br>8012-8211 | 3/4<br>3/4 | CC-70090<br>CC-70140 | CK-3108<br>CK-3126 |
| (1600) | RH24(トラック) | Sタイヤ | 79.12-82.11 | 15/16 | | TK-9358 | 79.12-82.7 | 1 1/8 | (R-1)WC-52006<br>(R-2)WC-51006<br>(L-1)WC-54006<br>(L-2)WC-53006 | WK-314 | CUP | <LSPV付><br>79.12-82.11 | 7/8 | (R)WC-50046<br>(L)WC-50046 | WK-048 | CUP | 79.12-82.11 | BH-02350 | BH-31380 | 79.12-81.5<br>81.5-82.11 | 5/8<br>5/8 | MC-10070 | MK-4300<br>MK-4300 | 7912-8211 | 15 | CC-70122 | CK-3119 |
| | | | | | | | 82.7-82.11 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-314 | CUP | | | | | | | | | | | | | | | | |
| | | Wタイヤジャストロー | 79.12-82.11 | 15/16 | | TK-9358 | 79.12-82.7 | 1 1/8 | (R-1)WC-52006<br>(R-2)WC-51006<br>(L-1)WC-54006<br>(L-2)WC-53006 | WK-314 | CUP | 79.12-82.11 | 11/16 | (R)WC-50062<br>(L)WC-50062 | WK-494 | CUP | 79.12-82.11 | BH-02350 | BH-91000 | 79.12-81.5<br>81.5-82.11 | 5/8<br>5/8 | MC-10070 | MK-4300<br>MK-4300 | 7912-8211 | 15 | CC-70122 | CK-3119 |
| | | | | | | | 82.7-82.11 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-314 | CUP | | | | | | | | | | | | | | | | |
| (1600) | RH24V・34V(バン) | ドラム車 | 79.12-82.11 | 15/16 | | TK-9358 | 79.12-82.7 | 1 1/8 | (R-1)WC-52006<br>(R-2)WC-51006<br>(L-1)WC-54006<br>(L-2)WC-53006 | WK-314 | CUP | <LSPV付><br>79.12-82.11 | 7/8 | (R)WC-50046<br>(L)WC-50046 | WK-048 | CUP | 79.12-82.11 | BH-02350 | BH-31360 | 79.12-81.5<br>81.5-82.11 | 5/8<br>5/8 | MC-10070 | MK-4300<br>MK-4300 | 7912-8211 | 15 | CC-70122 | CK-3119 |
| | | | | | | | 82.7-82.11 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-314 | CUP | | | | | | | | | | | | | | | | |
| | | ディスク車 | 80.12-82.11 | 15/16 | | TK-9386 | 80.12-82.11<br>82.11 | 2 3/8<br>2 3/8 | DISC<br>DISC | MP-4<br>MP-9 | | <LSPV付><br>80.12-82.11 | 7/8 | (R)WC-50046<br>(L)WC-50046 | WK-048 | CUP | 80.12-82.11 | (1)BH-31305<br>(2)BH-02311 | BH-31360 | 80.12-81.5<br>81.5-82.11 | 5/8<br>5/8 | MC-10070 | MK-4300<br>MK-4300 | 8012-8211 | 15 | CC-70122 | CK-3119 |
| (2000) | RH35V(バン)<br>RH35B(バス) | ドラム車 | 79.12-82.11 | 15/16 | | TK-9358 | 79.12-82.7 | 1 1/8 | (R-1)WC-52006<br>(R-2)WC-51006<br>(L-1)WC-54006<br>(L-2)WC-53006 | WK-314 | CUP | <LSPV付><br>79.12-82.11 | 7/8 | (R)WC-50046<br>(L)WC-50046 | WK-048 | CUP | 79.12-82.11 | BH-02350 | BH-31360 | 79.12-81.5<br>81.5-82.11 | 5/8<br>5/8 | MC-10070 | MK-4300<br>MK-4300 | 7912-8012<br>8012-8211 | 3/4<br>3/4 | CC-70090<br>CC-70090 | CK-3108<br>CK-3124 |
| | | | | | | | 82.7-82.11 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-314 | CUP | | | | | | | | | | | | | | | | |
| | | ディスク車 | 80.12-82.11 | 15/16 | | TK-9386 | 80.12-82.11<br>82.11 | 2 3/8<br>2 3/8 | DISC<br>DISC | MP-4<br>MP-9 | | <LSPV付><br>80.12-82.11 | 7/8 | (R)WC-50046<br>(L)WC-50046 | WK-048 | CUP | 80.12-82.11 | (1)BH-31305<br>(2)BH-02311 | BH-31360 | 80.12-81.5<br>81.5-82.11 | 5/8<br>5/8 | MC-10070 | MK-4300<br>MK-4300 | 8012-8211 | 3/4 | CC-70090 | CK-3124 |
| (1600)<br>(1800)<br>(2000) | RH40V・40B(バン・バス)<br>RH41V・41B(バン・バス)<br>RH42V(バン) | | 77.2-79.12 | 15/16 | | TK-9358 | 77.2-79.12 | 1 1/8 | (R-1)WC-52006<br>(R-2)WC-51006<br>(L-1)WC-54006<br>(L-2)WC-53006 | WK-314 | CUP | <サイズ確認><br>77.2-79.12<br>77.2-79.12 | 7/8<br>13/16 | (R)WC-50046<br>(L)WC-50046<br>(R)WC-50051<br>(L)WC-50051 | WK-048<br>WK-106 | CUP<br>CUP | 77.2-79.12 | BH-02350 | BH-31360 | 77.2-79.12 | 5/8 | MC-10070 | MK-4300 | <RH40V・B><br>77.2-77.11<br>7711-7912<br><RH41H・B・42V><br>77.2-79.12 | 15<br>15<br>3/4 | CC-70097<br>CC-70122<br>CC-70090 | FC-31480-B<br>CK-3119<br>CK-3108 |
| (2000) | RH45V(バン)<br>RH45B(バス) | ドラム車 | 79.12-82.11 | 15/16 | | TK-9358 | 79.12-82.7 | 1 1/8 | (R-1)WC-52006<br>(R-2)WC-51006<br>(L-1)WC-54006<br>(L-2)WC-53006 | WK-314 | CUP | 79.12-82.11<br><LSPV付><br>79.12-82.11 | 13/16<br>7/8 | (R)WC-50051<br>(L)WC-50051<br>(R)WC-50046<br>(L)WC-50046 | WK-106<br>WK-048 | CUP<br>CUP | 79.12-82.11 | BH-02350 | BH-31360 | 79.12-81.5<br>81.5-82.11 | 5/8<br>5/8 | MC-10070 | MK-4300<br>MK-4300 | 7912-8012<br>8012-8211 | 3/4<br>3/4 | CC-70090<br>CC-70090 | CK-3108<br>CK-3124 |
| | | | | | | | 82.7-82.11 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-314 | CUP | | | | | | | | | | | | | | | | |
| | | ディスク車 | 80.12-82.11 | 15/16 | | TK-9386 | 80.12-82.11<br>82.11 | 2 3/8<br>2 3/8 | DISC<br>DISC | MP-4<br>MP-9 | | 80.12-82.11<br><LSPV付><br>80.12-82.11 | 13/16<br>7/8 | (R)WC-50051<br>(L)WC-50051<br>(R)WC-50046 | WK-106<br>WK-048 | CUP<br>CUP | 80.12-82.11 | (1)BH-31305<br>(2)BH-02311 | BH-31360 | 80.12-81.5<br>81.5-82.11 | 5/8<br>5/8 | MC-10070 | MK-4300<br>MK-4300 | 8012-8211 | 3/4 | CC-70090 | CK-3124 |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | | | | | (L)WC-50046 | | | | | | | | | | | | | |
| (2200ディーゼル)<br>LH20V(バン) | ドラム車 | 79.7-82.11 | 15/16 | | TK-9358 | 79.7-82.7<br><br><br><br>82.7-82.11 | 1 1/8<br><br><br><br>1 1/8 | (R-1)WC-52006<br>(R-2)WC-51006<br>(L-1)WC-54006<br>(L-2)WC-53006<br>(R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-314<br><br><br><br>WK-314 | CUP<br><br><br><br>CUP | 79.7-82.11 | 7/8 | (R)WC-50046<br>(L)WC-50046 | WK-048 | CUP | 79.7-82.11 | BH-02350 | BH-31360 | 79.7-81.5<br>81.5-82.11 | 5/8<br>5/8 | MC-10070 | MK-4300<br>MK-4300 | 79.7-80.12<br>8012-8211 | 3/4<br>3/4 | CC-70091<br>CC-70091 | CK-3108<br>CK-3124 |
| | ディスク車 | 80.12-82.11 | 15/16 | | TK-9386 | 80.12-82.11<br>82.11 | 2 3/8<br>2 3/8 | DISC<br>DISC | MP-4<br>MP-9 | | <LSPV付><br>80.12-82.11 | 7/8 | (R)WC-50046<br>(L)WC-50046 | WK-048 | CUP | 80.12-82.11 | (1)BH-31305<br>(2)BH-02311 | BH-31360 | 80.12-81.5<br>81.5-82.11 | 5/8<br>5/8 | MC-10070 | MK-4300<br>MK-4300 | 8012-8211 | 3/4 | CC-70091 | CK-3124 |
| (2200ディーゼル)<br>LH20G(ワゴン) | | 79.12-82.11 | 15/16 | | TK-9408 | 79.12-82.11<br>82.11 | 2 3/8<br>2 3/8 | DISC<br>DISC | MP-4<br>MP-9 | | 79.12-82.11 | 7/8 | (R)WC-50054<br>(L)WC-50054 | WK-405 | CUP | 79.12-82.11 | (1)BH-31305<br>(2)BH-02311 | BH-31360 | 79.12-81.5<br>81.5-82.11 | 5/8<br>5/8 | MC-10070 | MK-4300<br>MK-4300 | 7912-8012<br>8012-8211 | 3/4<br>3/4 | CC-70091<br>CC-70091 | CK-3108<br>CK-3124 |
| (2200ディーゼル)<br>LH24(トラック) | Sタイヤ | 79.12-82.11 | 15/16 | | TK-9358 | 79.12-82.7<br><br><br><br>82.7-82.11 | 1 1/8<br><br><br><br>1 1/8 | (R-1)WC-52006<br>(R-2)WC-51006<br>(L-1)WC-54006<br>(L-2)WC-53006<br>(R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-314<br><br><br><br>WK-314 | CUP<br><br><br><br>CUP | 79.12-82.11 | 7/8 | (R)WC-50046<br>(L)WC-50046 | WK-048 | CUP | 79.12-82.11 | BH-02350 | BH-31380 | 79.12-81.5<br>81.5-82.11 | 5/8<br>5/8 | MC-10070 | MK-4300<br>MK-4300 | 7912-8012<br>8012-8211 | 3/4<br>3/4 | CC-70091<br>CC-70091 | CK-3108<br>CK-3124 |
| | Wタイヤ | 79.12-82.11 | 15/16 | | TK-9358 | 79.12-82.7<br><br><br><br>82.7-82.11 | 1 1/8<br><br><br><br>1 1/8 | (R-1)WC-52006<br>(R-2)WC-51006<br>(L-1)WC-54006<br>(L-2)WC-53006<br>(R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-314<br><br><br><br>WK-314 | CUP<br><br><br><br>CUP | 79.12-82.11 | 11/16 | (R)WC-50062<br>(L)WC-50062 | WK-494 | CUP | 79.12-82.11 | BH-02350 | BH-91000 | 79.12-81.5<br>81.5-82.11 | 5/8<br>5/8 | MC-10070 | MK-4300<br>MK-4300 | 7912-8012<br>8012-8211 | 3/4<br>3/4 | CC-70091<br>CC-70091 | CK-3108<br>CK-3124 |
| (2200ディーゼル)<br>LH30V(バン)<br>LH30B(バス) | ドラム車 | 79.7-82.11 | 15/16 | | TK-9358 | 79.7-82.7<br><br><br><br>82.7-82.11 | 1 1/8<br><br><br><br>1 1/8 | (R-1)WC-52006<br>(R-2)WC-51006<br>(L-1)WC-54006<br>(L-2)WC-53006<br>(R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-314<br><br><br><br>WK-314 | CUP<br><br><br><br>CUP | 79.7-82.11 | 7/8 | (R)WC-50046<br>(L)WC-50046 | WK-048 | CUP | 79.7-82.11 | BH-02350 | BH-31360 | 79.7-81.5<br>81.5-82.11 | 5/8<br>5/8 | MC-10070 | MK-4300<br>MK-4300 | 79.7-80.12<br>8012-8211 | 3/4<br>3/4 | CC-70091<br>CC-70091 | CK-3108<br>CK-3124 |
| | ディスク車 | 80.12-82.11 | 15/16 | | TK-9386 | 80.12-82.11<br>82.11 | 2 3/8<br>2 3/8 | DISC<br>DISC | MP-4<br>MP-9 | | <LSPV付><br>80.12-82.11 | 7/8 | (R)WC-50046<br>(L)WC-50046 | WK-048 | CUP | 80.12-82.11 | (1)BH-31305<br>(2)BH-02311 | BH-31360 | 80.12-81.5<br>81.5-82.11 | 5/8<br>5/8 | MC-10070 | MK-4300<br>MK-4300 | 8012-8211 | 3/4 | CC-70091 | CK-3124 |
| (2200ディーゼル)<br>LH30G(ワゴン) | | 79.12-82.11 | 15/16 | | TK-9408 | 79.12-82.11<br>82.11 | 2 3/8<br>2 3/8 | DISC<br>DISC | MP-4<br>MP-9 | | 79.12-82.11 | 7/8 | (R)WC-50054<br>(L)WC-50054 | WK-405 | CUP | 79.12-82.11 | (1)BH-31305<br>(2)BH-02311 | BH-31360 | 79.12-81.5<br>81.5-82.11 | 5/8<br>5/8 | MC-10070 | MK-4300<br>MK-4300 | 7912-8012<br>8012-8211 | 3/4<br>3/4 | CC-70091<br>CC-70091 | CK-3108<br>CK-3124 |
| (2200ディーゼル)<br>LH40V(バン)<br>LH40B(バス) | ドラム車 | 79.12-82.11 | 15/16 | | TK-9358 | 79.12-82.7<br><br><br><br>82.7-82.11 | 1 1/8<br><br><br><br>1 1/8 | (R-1)WC-52006<br>(R-2)WC-51006<br>(L-1)WC-54006<br>(L-2)WC-53006<br>(R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-314<br><br><br><br>WK-314 | CUP<br><br><br><br>CUP | 79.12-82.11<br><LSPV付><br>79.12-82.11 | 13/16<br><br>7/8 | (R)WC-50051<br>(L)WC-50051<br><br>(R)WC-50046<br>(L)WC-50046 | WK-106<br><br><br>WK-048 | CUP<br><br><br>CUP | 79.12-82.11 | BH-02350 | BH-31360 | 79.12-81.5<br>81.5-82.11 | 5/8<br>5/8 | MC-10070 | MK-4300<br>MK-4300 | 7912-8012<br>8012-8211 | 3/4<br>3/4 | CC-70091<br>CC-70091 | CK-3108<br>CK-3124 |
| | ディスク車 | 80.12-82.11 | 15/16 | | TK-9386 | 80.12-82.11<br>82.11 | 2 3/8<br>2 3/8 | DISC<br>DISC | MP-4<br>MP-9 | | 80.12-82.11<br><LSPV付><br>80.12-82.11 | 13/16<br><br>7/8 | (R)WC-50051<br>(L)WC-50051<br><br>(R)WC-50046<br>(L)WC-50046 | WK-106<br><br><br>WK-048 | CUP<br><br><br>CUP | 80.12-82.11 | (1)BH-31305<br>(2)BH-02311 | BH-31360 | 80.12-81.5<br>81.5-82.11 | 5/8<br>5/8 | MC-10070 | MK-4300<br>MK-4300 | 8012-8211 | 3/4 | CC-70091 | CK-3124 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| HIACE : 24, 50, 60, 70 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1600) | L－RH24(トラック) | Sタイヤ(ドラム車) | 82.11-85.7 | 15/16 | | TK-9431 | 82.11-85.7 | 1 1/8 | | WK-314 | CUP | 82.11-85.7 | 7/8 | (R)WC-50046<br>(L)WC-50046 | WK-048 | CUP | 82.11-85.7 | BH-02350 | BH-31380 | 82.11-85.7 | 5/8 | | MK-4300 | 82.11-85.7 | 15 | CC-70122 | CK-3119 |
| | | Sタイヤ(ディスク車) | 82.11-85.7 | 15/16 | | TK-9430 | 82.11-85.7 | 2 3/8 | DISC | MP-9 | | 82.11-85.7 | 7/8 | (R)WC-50046<br>(L)WC-50046 | WK-048 | CUP | 82.11-85.7 | (1)BH-31305<br>(2)BH-02311 | BH-31380 | 82.11-85.7 | 5/8 | | MK-4300 | 82.11-85.7 | 15 | CC-70122 | CK-3119 |
| | | Wタイヤ | 82.11-85.7 | 15/16 | | TK-9431 | 82.11-85.7 | 1 1/8 | | WK-314 | CUP | 82.11-85.7 | 11/16 | (R)WC-50062<br>(L)WC-50062 | WK-494 | CUP | 82.11-85.7 | BH-02350 | BH-91000 | 82.11-85.7 | 5/8 | | MK-4300 | 82.11-85.7 | 15 | CC-70122 | CK-3119 |
| (2200ディーゼル) | N－LH24(トラック) | Sタイヤ(ドラム車) | 82.11-85.7 | 15/16 | | TK-9431 | 82.11-85.7 | 1 1/8 | | WK-314 | CUP | 82.11-85.7 | 7/8 | (R)WC-50046<br>(L)WC-50046 | WK-048 | CUP | 82.11-85.7 | BH-02350 | BH-31380 | 82.11-84.1<br>84.1-85.7 | 5/8<br>5/8 | | MK-4300<br>MK-4308 | 82.11-84.1<br>84.1-85.7 | 3/4<br>3/4 | CC-70091<br>CC-70159 | CK-3124<br>CK-T218 |
| | | Sタイヤ(ディスク車) | 82.11-85.7 | 15/16 | | TK-9430 | 82.11-85.7 | 2 3/8 | DISC | MP-9 | | 82.11-85.7 | 7/8 | (R)WC-50046<br>(L)WC-50046 | WK-048 | CUP | 82.11-85.7 | (1)BH-31305<br>(2)BH-02311 | BH-31380 | 82.11-84.1<br>84.1-85.7 | 5/8<br>5/8 | | MK-4300<br>MK-4308 | 82.11-84.1<br>84.1-85.7 | 3/4<br>3/4 | CC-70091<br>CC-70159 | CK-3124<br>CK-T218 |
| | | Wタイヤ | 82.11-85.7 | 15/16 | | TK-9431 | 82.11-85.7 | 1 1/8 | | WK-314 | CUP | 82.11-85.7 | 11/16 | (R)WC-50062<br>(L)WC-50062 | WK-494 | CUP | 82.11-85.7 | BH-02350 | BH-91000 | 82.11-84.1<br>84.1-85.7 | 5/8<br>5/8 | | MK-4300<br>MK-4308 | 82.11-84.1<br>84.1-85.7 | 3/4<br>3/4 | CC-70091<br>CC-70159 | CK-3124<br>CK-T218 |
| | N－LH24HV(宅配車) | クイックデリバリー | 82.5-82.11<br>82.11-85.7 | 15/16<br>15/16 | | TK-9358<br>TK-9431 | 82.5-82.7<br><br><br><br>82.7-85.7 | 1 1/8<br><br><br><br>1 1/8 | (R-1)WC-52006<br>(R-2)WC-51006<br>(L-1)WC-54006<br>(L-2)WC-53006 | WK-314<br><br><br><br>WK-314 | CUP<br><br><br><br>CUP | 82.5-85.7 | 11/16 | (R)WC-50062<br>(L)WC-50062 | WK-494 | CUP | 82.5-85.7 | BH-02350 | BH-91000 | 82.5-84.1<br>84.1-85.7 | 5/8<br>5/8 | | MK-4312<br>MK-4318 | 82.5-84.1<br>84.1-85.7 | 3/4<br>3/4 | CC-70091<br>CC-70159 | CK-3124<br>CK-T218 |
| (1800)<br>(2000) | M－YH50V(LPG含)・61V・VH<br>L－YH52V・62V・71B<br>M－YH71V<br>M－YH51V | ドラム車 | 82.12-85.8 | 15/16 | | TK-9431 | 82.12-85.8 | 1 1/8 | | WK-314 | CUP | 82.12-85.8<br><YH61V Wタイヤ><br>82.12-85.8 | 13/16<br><br>11/16 | (R)WC-50051<br>(L)WC-50051<br><br>(R)WC-50062<br>(L)WC-50062 | WK-106<br><br>WK-494 | CUP<br><br>CUP | 82.12-85.8<br><YH61V Wタイヤ><br>82.12-85.8 | BH-02436<br><br>BH-02436 | BH-31324<br><br>BH-94000 | 82.12-85.8 | 5/8 | | MK-4300 | 82.12-85.8 | 13/16 | CC-70145 | CK-3144 |
| | | ディスク車 | 82.12-85.8<br>85.8-87.8<br>87.8-89.8 | 15/16<br>15/16<br>15/16 | | TK-9430<br>TK-T012<br>TK-T035 | 82.12-89.8 | 60.3 | DISC | MP-10 | CPM-10 | 82.12-89.8<br><YH61V Wタイヤ><br>82.12-89.8 | 7/8<br><br>3/4 | (R)WC-50046<br>(L)WC-50046<br><br>(R)<br>(L) | WK-048<br><br>WK-590 | CUP<br><br>CUP | 82.12-85.8<br>85.8-89.8<br><YH61V Wタイヤ><br>82.12-85.8<br>85.8-89.8 | BH-02436<br>BH-02477<br><br>BH-02436<br>BH-02477 | BH-31324<br>BH-31324<br><br>BH-94000<br>BH-94000 | 82.12-87.8<br>87.8-89.8 | 5/8<br>5/8 | <br>MC-T267 | MK-4300<br>MK-4353 | 82.12-88.8<br>88.8-89.8 | 13/16<br>13/16 | CC-70145<br>CC-70145 | CK-3144<br>CK-3144 |
| (2000) | E－YH51G・61G | | 82.12-85.8<br>85.8-87.8<br>87.8-89.8 | 15/16<br>15/16<br>15/16 | | TK-9432<br>TK-T012<br>TK-T035 | 82.12-89.8 | 60.3 | DISC | MP-10 | CPM-10 | 82.12-89.8 | 7/8 | (R)WC-50054<br>(L)WC-50054 | WK-405 | CUP | 82.12-85.8<br>85.8-89.8 | BH-02436<br>BH-02477 | BH-31324<br>BH-31324 | 82.12-87.8<br>87.8-89.8 | 5/8<br>5/8 | MC-10134<br>MC-10134 | MK-4300<br>MK-4353 | 82.12-88.8<br>88.8-89.8 | 13/16<br>13/16 | CC-70145<br>CC-70145 | CK-3144<br>CK-3144 |
| (2000) | E－YH57G(4WD) | | 87.8-89.8 | 1 | | TK-T029 | 87.8-89.8 | 66.6 | DISC | MP-27 | | 87.8-89.8 | 15/16 | (R)WC-50075<br>(L)WC-50075 | WK-885 | CUP | 87.8-89.8 | BH-02502 | BH-02492 | 87.8-89.8 | 5/8 | MC-10134 | MK-4353 | 87.8-88.8<br>88.8-89.8 | 13/16<br>13/16 | CC-70176<br>CC-70176 | CK-3144<br>CK-3144 |
| (2200ディーゼル)<br>(2400ディーゼル) | N－LH50V・60V・70V<br>N－LH60B・70B・61VH<br>N－LH51V・61V・71V<br>N－LH61B・71B | ドラム車 | 82.12-85.8 | 15/16 | | TK-9431 | 82.12-85.8 | 1 1/8 | | WK-314 | CUP | 82.12-85.8<br><LH60V・61VWタイヤ><br>82.12-85.8 | 13/16<br><br>11/16 | (R)WC-50051<br>(L)WC-50051<br><br>(R)WC-50062<br>(L)WC-50062 | WK-106<br><br>WK-494 | CUP<br><br>CUP | 82.12-85.8<br><LH60V・61VWタイヤ><br>82.12-85.8 | BH-02436<br><br>BH-02436 | BH-31324<br><br>BH-94000 | 82.12-85.8 | 5/8 | MC-10134 | MK-4300 | 82.12-84.1<br>84.1-85.8 | 13/16<br>13/16 | CC-70148<br>CC-70133 | CK-3144<br>CK-3144 |
| | | ディスク車 | 82.12-85.8<br>85.8-87.8<br>87.8-89.8 | 15/16<br>15/16<br>15/16 | | TK-9430<br>TK-T012<br>TK-T035 | 82.12-89.8 | 60.3 | DISC | MP-10 | CPM-10 | 82.12-89.8<br><LH60V・61VWタイヤ><br>82.12-89.8 | 7/8<br><br>3/4 | (R)WC-50046<br>(L)WC-50046<br><br>(R)<br>(L) | WK-048<br><br>WK-590 | CUP<br><br>CUP | 82.12-85.8<br>85.8-89.8<br><LH60V・61VWタイヤ><br>82.12-85.8<br>85.8-89.8 | BH-02436<br>BH-02477<br><br>BH-02436<br>BH-02477 | BH-31324<br>BH-31324<br><br>BH-94000<br>BH-94000 | 82.12-87.8<br>87.8-89.8 | 5/8<br>5/8 | MC-10134<br>MC-10134 | MK-4300<br>MK-4353 | 82.12-84.1<br>84.1-88.8<br>88.8-89.8 | 13/16<br>13/16<br>13/16 | CC-70148<br>CC-70133<br>CC-70133 | CK-3144<br>CK-3144<br>CK-3144 |
| (2400ディーゼル) | N－LH56V・66V(4WD) | | 86.8-89.8 | 1 | | TK-T029 | 86.8-89.8 | 66.6 | DISC | MP-27 | | 86.8-89.8 | 1 | (R)WC-50063<br>(L)WC-50063 | WK-886 | CUP | 86.8-89.8 | BH-02502 | BH-94014 | 86.8-87.8<br>87.8-89.8 | 5/8<br>5/8 | MC-10134<br>MC-10134 | MK-4300<br>MK-4353 | 86.8-89.8 | 13/16 | CC-70177 | CK-3144 |
| (2200ディーゼル)<br>(2400ディーゼル) | N－LH50G・60G<br>N－LH51G・61G<br>Q－LH51G・61G<br><Q－は87. 8～> | | 82.12-85.8<br>85.8-87.8<br>87.8-89.8 | 15/16<br>15/16<br>15/16 | | TK-9432<br>TK-T012<br>TK-T035 | 82.12-89.8 | 60.3 | DISC | MP-10 | CPM-10 | 82.12-89.8 | 7/8 | (R)WC-50054<br>(L)WC-50054 | WK-405 | CUP | 82.12-85.8<br>85.8-89.8 | BH-02436<br>BH-02477 | BH-31324<br>BH-31324 | 82.12-87.8<br>87.8-89.8 | 5/8<br>5/8 | MC-10134<br>MC-10134 | MK-4300<br>MK-4353 | 82.12-84.1<br>84.1-88.8<br>88.8-89.8 | 13/16<br>13/16<br>13/16 | CC-70148<br>CC-70133<br>CC-70133 | CK-3144<br>CK-3144<br>CK-3144 |
| (2400ディーゼル) | N－LH71G<br>Q－LH71G<br><Q－は87. 8～> | | 87.8-89.8 | 15/16 | | TK-T035 | 87.8-89.8 | 60.3 | DISC | MP-10 | CPM-10 | 87.8-89.8 | 7/8 | (R)WC-50054<br>(L)WC-50054 | WK-405 | CUP | 87.8-89.8 | BH-02477 | BH-31324 | 87.8-89.8 | 5/8 | MC-10134 | MK-4353 | 87.8-88.8<br>88.8-89.8 | 13/16<br>13/16 | CC-70133<br>CC-70133 | CK-3144<br>CK-3144 |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| HIACE : 80, 90 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1600) | L−YH80 | 85.8−87.8 | 15/16 | | TK−T012 | 85.8−87.8 | 60.3 | DISC | MP−10 | CPM−10 | 85.8−87.8<br><ジャストローWタイヤ><br>85.8−87.8<br><ジャストローSタイヤ><br>85.8−87.8 | 7/8<br><br>3/4<br><br>13/16 | (R)WC−50046<br>(L)WC−50046<br><br>(R)<br>(L)<br><br>(R)WC−50051<br>(L)WC−50051 | WK−048<br><br>WK−590<br><br>WK−106 | CUP<br><br>CUP<br><br>CUP | 85.8−87.8<br><ジャストロー><br>85.8−87.8 | BH−02477<br><br>BH−02477 | BH−T681<br><br>BH−02342 | 85.8−87.8 | 5/8 | | MK−4328 | 85.8−87.8 | 13/16 | CC−70145 | CK−3144 |
| (1800) | L−YH81 低床(Sタイヤ)<br><T−は89．10〜> シングルジャストロー(Sタイヤ)<br>ダブルキャブ(Sタイヤ) | 87.8−95.5 | 15/16 | | TK−T035 | 87.8−95.5 | 60.3 | DISC | MP−10 | CPM−10 | 87.8−95.5 | 7/8 | (R)WC−50046<br>(L)WC−50046 | WK−048 | CUP | 87.8−95.5 | BH−02477 | BH−T681 | 87.8−88.8<br>88.8−95.5 | 5/8<br>5/8 | MC−T445 | MK−4346<br>MK−T236 | 87.8−88.8<br>88.8−94.10<br>94.10−95.5 | 13/16<br>13/16<br>13/16 | CC−70145<br>CC−70145 | CK−3144<br>CK−3144<br>CK−T201 |
| | スーパーシングルジャストロー(Sタイヤ) | 87.8−95.5 | 15/16 | | TK−T035 | 87.8−95.5 | 60.3 | DISC | MP−10 | CPM−10 | 87.8−95.5 | 13/16 | (R)WC−50051<br>(L)WC−50051 | WK−106 | CUP | 87.8−89.10<br>89.10−91.9<br>91.9−95.5 | BH−02477<br>BH−02477<br>BH−02477 | BH−02210<br>BH−T560<br>BH−02342 | 87.8−88.8<br>88.8−95.5 | 5/8<br>5/8 | MC−T445 | MK−4346<br>MK−T236 | 87.8−88.8<br>88.8−94.10<br>94.10−95.5 | 13/16<br>13/16<br>13/16 | CC−70145<br>CC−70145 | CK−3144<br>CK−3144<br>CK−T201 |
| | ジャストロー(Wタイヤ) | 87.8−95.5 | 15/16 | | TK−T035 | 87.8−95.5 | 60.3 | DISC | MP−10 | CPM−10 | 87.9−95.5 | 3/4 | (R)<br>(L) | WK−590 | CUP | 87.8−95.5 | BH−02477 | BH−02342 | 87.8−88.8<br>88.8−95.5 | 5/8<br>5/8 | MC−T445 | MK−4346<br>MK−T236 | 87.8−88.8<br>88.8−94.10<br>94.10−95.5 | 13/16<br>13/16<br>13/16 | CC−70145<br>CC−70145 | CK−3144<br>CK−3144<br>CK−T201 |
| (2400ディーゼル) | 低床(Sタイヤ) | 85.8−87.8 | 15/16 | | TK−T012 | 85.8−87.8 | 60.3 | DISC | MP−10 | CPM−10 | 85.8−95.5 | 7/8 | (R)WC−50046 | WK−048 | CUP | 85.8−95.5 | BH−02477 | BH−T681 | 85.8−87.8 | 5/8 | | MK−4328 | 85.8−88.8 | 13/16 | CC−70133 | CK−3144 |
| | N−LH80 シングルジャストロー(Sタイヤ) | 87.8−95.5 | 15/16 | | TK−T035 | 87.8−95.5 | 60.3 | DISC | MP−10 | CPM−10 | | | (L)WC−50046 | | | | | | 87.8−88.8 | 5/8 | | MK−4346 | 88.8−94.5 | 13/16 | CC−70133 | CK−3144 |
| | (除くクイックデリバリー) ダブルキャブ(Sタイヤ)<br>U−LH80・90 | | | | | | | | | | | | | | | | | | 88.8−95.5 | 5/8 | MC−T445 | MK−T236 | 94.5−95.5 | 13/16 | | CK−T201 |
| | ジャストロー(Wタイヤ) | 85.8−87.8<br>87.8−95.5 | 15/16<br>15/16 | | TK−T012<br>TK−T035 | 85.8−87.8<br>87.8−95.5 | 60.3<br>60.3 | DISC<br>DISC | MP−10<br>MP−10 | CPM−10<br>CPM−10 | 85.8−95.5 | 3/4 | (R)<br>(L) | WK−590 | CUP | 85.8−95.5 | BH−02477 | BH−02342 | 85.8−87.8<br>87.8−88.8<br>88.8−95.5 | 5/8<br>5/8<br>5/8 | MC−T445 | MK−4328<br>MK−4346<br>MK−T236 | 85.8−88.8<br>88.8−94.5<br>94.5−95.5 | 13/16<br>13/16<br>13/16 | CC−70133<br>CC−70133 | CK−3144<br>CK−3144<br>CK−T201 |
| | スーパーシングルジャストロー(Sタイヤ)<br>ジャストロー(Sタイヤ) | 85.8−87.8<br>87.8−95.5 | 15/16<br>15/16 | | TK−T012<br>TK−T035 | 85.8−87.8<br>87.8−95.5 | 60.3<br>60.3 | DISC<br>DISC | MP−10<br>MP−10 | CPM−10<br>CPM−10 | 85.8−95.5 | 13/16 | (R)WC−50051<br>(L)WC−50051 | WK−106 | CUP | 85.8−87.8<br>87.8−89.10<br>89.10−91.9<br>91.9−95.5 | BH−02477<br>BH−02477<br>BH−02477<br>BH−02477 | BH−02342<br>BH−02210<br>BH−T560<br>BH−02342 | 85.8−87.8<br>87.8−88.8<br>88.8−95.5 | 5/8<br>5/8<br>5/8 | MC−T445 | MK−4328<br>MK−4346<br>MK−T236 | 85.8−88.8<br>88.8−94.5<br>94.5−95.5 | 13/16<br>13/16<br>13/16 | CC−70133<br>CC−70133 | CK−3144<br>CK−3144<br>CK−T201 |
| | N−LH85 シングルジャストロー(Sタイヤ)<br>(除くクイックデリバリー) ダブルキャブ(Sタイヤ)<br>U−LH85・95<br><U−は89．10〜> | 87.10−95.5 | 1 | | TK−T029 | 87.10−95.5 | 66.6 | DISC | MP−27 | CPM−86 | 87.10−95.5 | 15/16 | (R)WC−50075<br>(L)WC−50075 | WK−885 | CUP | 87.10−91.9<br>91.9−95.5 | BH−02522<br>BH−02522 | BH−02210<br>BH−02342 | 87.10−88.8<br>88.8−95.5 | 5/8<br>5/8 | MC−T445 | MK−4346<br>MK−T236 | 87.10−90.6<br>90.6−93.4<br>93.4−95.5 | 13/16<br>13/16<br>13/16 | CC−70177<br>CC−70177 | CK−3144<br>CK−3144<br>CK−T201 |
| | ジャストロー(Sタイヤ)<br>スーパーシングルジャストロー(Sタイヤ) | 87.10−95.5 | 1 | | TK−T029 | 87.10−95.5 | 66.6 | DISC | MP−27 | CPM−86 | 87.10−95.5 | 13/16 | (R)WC−50051<br>(L)WC−50051 | WK−106 | CUP | 87.10−89.10<br>89.10−95.5 | BH−02522<br>BH−02522 | BH−94005<br>BH−94008 | 87.10−88.8<br>88.8−95.5 | 5/8<br>5/8 | MC−T445 | MK−4346<br>MK−T236 | 87.10−90.6<br>90.6−93.4<br>93.4−95.5 | 13/16<br>13/16<br>13/16 | CC−70177<br>CC−70177 | CK−3144<br>CK−3144<br>CK−T201 |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| HIACE, REGIUS ACE : 100 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000) | E－RZH100G | 89.8-93.8 | 1 | | TK-T029 | 89.8-93.8 | 66.6 | DISC | MP-30 | | 89.8-93.8 | 7/8 | (R)WC-50054 | WK-405 | CUP | 89.8-93.8 | (R)BH-T599 | BH-31304 | 89.8-95.8 | 5/8 | | MK-4351 | 89.8-90.6 | 13/16 | CC-70182 | CK-3144 |
| | | 93.8-95.8 | 1 1/16 | TD-T798 | TK-T346 | 93.8-95.8 | | DISC | MP-86 | CPM-86 | | | (L)WC-50054 | | | | (L)BH-T600 | | | | | | 90.6-94.10 | 13/16 | CC-70182 | CK-3144 |
| | | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | 93.8-95.8 | 15/16 | (R)WC-50047 | WK-309 | CUP | 93.8-95.8 | (R)BH-T592 | BH-02576 | | | | | 94.10-95.8 | 13/16 | CC-T371 | CK-T201 |
| | | 93.8-95.8 | 1 1/16 | | | | | | | | | | (L)WC-50047 | | | | (L)BH-T873 | | | | | | | | | |
| | E－RZH110G | 89.8-93.8 | 1 | | TK-T029 | 89.8-93.8 | 66.6 | DISC | MP-30 | | 89.8-93.8 | 7/8 | (R)WC-50054 | WK-405 | CUP | 89.8-93.8 | (R)BH-T599 | BH-T510 | 89.8-93.8 | 5/8 | MC-T331 | MK-4351 | 89.8-90.6 | 13/16 | CC-70182 | CK-3144 |
| | | | | | | | | | | | | | (L)WC-50054 | | | | (L)BH-T600 | | | | | | 90.6-93.8 | 13/16 | CC-70182 | CK-3144 |
| | T－RZH102V･122V | 89.8-93.8 | 1 | | TK-T029 | 89.8-96.8 | 66.6 | DISC | MP-30 | | 89.8-96.7 | 15/16 | (R)WC-50047 | WK-309 | CUP | 89.8-96.8 | (R)BH-T599 | BH-T510 | 89.8-93.8 | 5/8 | | MK-4351 | 89.8-90.6 | 13/16 | CC-70182 | CK-3144 |
| | T－RZH112V･112K | 93.8-03.8 | 1 | TD-T918 | TK-T364 | 96.8-03.8 | | DISC | MP-86 | CPM-86 | | | (L)WC-50047 | | | | (L)BH-T600 | | 93.8-95.8 | 5/8 | MC-T331 | MK-4351 | 90.6-94.10 | 13/16 | CC-70182 | CK-3144 |
| | GE－RZH182K | | 1 | | | | | | | | 96.7-03.8 | 15/16 | (R)WC-T746 | WK-884 | CUP | 96.8-98.8 | (R)BH-T592 | BH-02221 | 95.8-96.6 | 5/8 | MC-T331 | | 94.10-03.8 | 13/16 | CC-T371 | CK-T201 |
| | ＜Z－は93. 8～＞ | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | (L)WC-T746 | | | | (L)BH-T873 | | 96.6-03.8 | 5/8 | MC-T331 | MK-T244 | | | | |
| | ＜GB－は95. 8～＞ | 98.8-03.8 | 1 1/16 | | | | | | | | | | | | | 98.8-99.7 | (R)BH-T592 | BH-T871 | | | | | | | | |
| | ＜GE－は98. 8～＞ | | | | | | | | | | | | | | | | (L)BH-T873 | | | | | | | | | |
| | | | | | | | | | | | | | | | | 99.7- | (R)BH-T592 | BH-T871 | | | | | | | | |
| | | | | | | | | | | | | | | | | | (L)BH-T873 | | | | | | | | | |
| | | | | | | | | | | | | | | | | <ｼﾞｬｽﾄﾛｰ> | | | | | | | | | | |
| | | | | | | | | | | | | | | | | 89.8-96.8 | (R)BH-T599 | BH-T511 | | | | | | | | |
| | | | | | | | | | | | | | | | | | (L)BH-T600 | | | | | | | | | |
| | | | | | | | | | | | | | | | | 96.8-99.7 | (R)BH-T592 | BH-94000 | | | | | | | | |
| | | | | | | | | | | | | | | | | | (L)BH-T873 | | | | | | | | | |
| | | | | | | | | | | | | | | | | 99.7- | (R)BH-T592 | BH-T872 | | | | | | | | |
| | | | | | | | | | | | | | | | | | (L)BH-T873 | | | | | | | | | |
| | T－RZH124B | 89.8-93.8 | 1 | | TK-T029 | 89.8-96.8 | 66.6 | DISC | MP-30 | | 89.8-96.7 | 15/16 | (R)WC-50047 | WK-309 | CUP | 89.8-96.8 | (R)BH-T599 | BH-T510 | 89.8-93.8 | 5/8 | | MK-4351 | 89.8-90.6 | 13/16 | CC-70182 | CK-3144 |
| | ＜Z－は93. 8～＞ | 93.8-03.8 | 1 | TD-T918 | TK-T364 | 96.8-03.8 | | DISC | MP-86 | CPM-86 | | | (L)WC-50047 | | | | (L)BH-T600 | | 93.8-95.8 | 5/8 | MC-T331 | MK-4351 | 90.6-94.10 | 13/16 | CC-70182 | CK-3144 |
| | ＜GB－は95. 8～＞ | | | | | | | | | | 96.7-03.8 | 15/16 | (R)WC-T746 | WK-884 | CUP | 96.8-98.8 | (R)BH-T592 | BH-T510 | 95.8-96.6 | 5/8 | MC-T331 | | 94.10-03.8 | 13/16 | CC-T371 | CK-T201 |
| | ＜GE－は98. 8～＞ | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | (L)WC-T746 | | | | (L)BH-T873 | | 96.6-03.8 | 5/8 | MC-T331 | MK-T244 | | | | |
| | | 98.8-03.8 | 1 1/16 | | | | | | | | | | | | | 98.8-99.7 | (R)BH-T592 | BH-T871 | | | | | | | | |
| | | | | | | | | | | | | | | | | | (L)BH-T873 | | | | | | | | | |
| | | | | | | | | | | | | | | | | 99.7-03.8 | (R)BH-T592 | BH-T871 | | | | | | | | |
| | | | | | | | | | | | | | | | | | (L)BH-T873 | | | | | | | | | |
| | GE－RZH182K | 00.12-03.8 | 1 | TD-T918 | TK-T364 | 00.12-03.8 | | DISC | MP-86 | CPM-86 | 00.12-03.8 | 15/16 | (R)WC-T746 | WK-884 | CUP | 00.12-03.8 | (R)BH-T592 | BH-T871 | 00.12-03.8 | 5/8 | MC-T331 | MK-T244 | 00.12-03.8 | 13/16 | CC-T371 | CK-T201 |
| | | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | (L)WC-T746 | | | | (L)BH-T873 | | | | | | | | | |
| | | 00.12-03.8 | | | | | | | | | | | | | | | | | | | | | | | | |
| (2400) | E－RZH101G･111G | 89.8-93.8 | 1 | | TK-T029 | 89.8-93.8 | 66.6 | DISC | MP-30 | | 89.8-93.8 | 7/8 | (R)WC-50054 | WK-405 | CUP | 89.8-93.8 | (R)BH-T599 | BH-31304 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | ＜GB－は95. 8～＞ | 93.8-99.7 | 1 1/16 | TD-T798 | TK-T346 | 93.8-02.8 | | DISC | MP-86 | CPM-86 | | | (L)WC-50054 | | | | (L)BH-T600 | | | | | | | | | |
| | ＜GF－は99. 7～＞ | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | 93.8-96.7 | 15/16 | (R)WC-50047 | WK-309 | CUP | 93.8-99.7 | (R)BH-T592 | BH-02576 | | | | | | | | |
| | | 93.8-02.8 | 1 1/16 | | | | | | | | | | (L)WC-50047 | | | | (L)BH-T873 | | | | | | | | | |
| | | | | | | | | | | | 96.7-02.8 | 15/16 | (R)WC-T746 | WK-884 | CUP | 99.7-02.8 | (R)BH-T592 | BH-T888 | | | | | | | | |
| | | | | | | | | | | | | | (L)WC-T746 | | | | (L)BH-T873 | | | | | | | | | |
| | GE－RZH125B | 98.8-03.8 | 1 | TD-T918 | TK-T364 | 98.8-03.8 | | DISC | MP-86 | CPM-86 | 98.8-03.8 | 15/16 | (R)WC-T746 | WK-884 | CUP | 98.8-99.7 | (R)BH-T592 | BH-T871 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | (L)WC-T746 | | | | (L)BH-T873 | | | | | | | | | |
| | | 98.8-03.8 | 1 1/16 | | | | | | | | | | | | | 99.7-03.8 | (R)BH-T592 | BH-T871 | | | | | | | | |
| | | | | | | | | | | | | | | | | | (L)BH-T873 | | | | | | | | | |
| | GB－RZH133V | 95.8-99.7 | 1 1/16 | TD-T798 | TK-T346 | 95.8-99.7 | | DISC | MP-86 | CPM-86 | 95.8-96.7 | 15/16 | (R)WC-50047 | WK-309 | CUP | 95.8-99.7 | (R)BH-T592 | BH-T871 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | (L)WC-50047 | | | | (L)BH-T873 | | | | | | | | | |
| | | 95.8-99.7 | 1 1/16 | | | | | | | | 96.7-99.7 | 15/16 | (R)WC-T746 | WK-884 | CUP | | | | | | | | | | | |
| | | | | | | | | | | | | | (L)WC-T746 | | | | | | | | | | | | | |
| | GE－RZH183K | 00.12-03.8 | 1 | TD-T918 | TK-T364 | 00.12-03.8 | | DISC | MP-86 | CPM-86 | 00.12-03.8 | 15/16 | (R)WC-T746 | WK-884 | CUP | 00.12-03.8 | (R)BH-T592 | BH-T871 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | (L)WC-T746 | | | | (L)BH-T873 | | | | | | | | | |
| | | 00.12-03.8 | | | | | | | | | | | | | | | | | | | | | | | | |
| | TC－TRH102V | 03.8-05.1 | 1 | TD-T918 | TK-T364 | 03.8-05.1 | | DISC | MP-86 | CPM-86 | 03.8-05.1 | 15/16 | (R)WC-T746 | WK-884 | CUP | 03.8-05.1 | (R)BH-T592 | BH-T871 | 03.8-05.1 | 5/8 | MC-T331 | MK-T244 | 03.8-05.1 | 13/16 | CC-T371 | CK-T201 |
| | TC－TRH112K･112V | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | (L)WC-T746 | | | | (L)BH-T873 | | | | | | | | | |
| | | 03.8-05.1 | | | | | | | | | | | | | | <ｼﾞｬｽﾄﾛｰ> | | | | | | | | | | |
| | | | | | | | | | | | | | | | | 03.8-05.1 | (R)BH-T592 | BH-T872 | | | | | | | | |
| | | | | | | | | | | | | | | | | | (L)BH-T873 | | | | | | | | | |
| | TC－TRH122K･124B | 03.8-05.1 | 1 | TD-T918 | TK-T364 | 03.8-05.1 | | DISC | MP-86 | CPM-86 | 03.8-05.1 | 15/16 | (R)WC-T746 | WK-884 | CUP | 03.8-05.1 | (R)BH-T592 | BH-T871 | 03.8-05.1 | 5/8 | MC-T331 | MK-T244 | 03.8-05.1 | 13/16 | CC-T371 | CK-T201 |
| | | | | | | | | | | | | | (L)WC-T746 | | | | (L)BH-T873 | | | | | | | | | |
| (2400ディーゼル) | | 89.8-93.8 | 1 | | TK-T029 | 89.8-93.8 | 66.6 | DISC | MP-30 | | 89.8-93.8 | 7/8 | (R)WC-50054 | WK-405 | CUP | 89.8-93.8 | (R)BH-T599 | BH-31304 | 89.8-93.8 | 5/8 | MC-T331 | MK-4351 | 89.8-93.8 | 13/16 | CC-T344 | CK-3144 |
| | Q－LH100G | | | | | | | | | | | | (L)WC-50054 | | | | (L)BH-T600 | | | | | | <ﾀｰﾎﾞ車> | | | |
| | | | | | | | | | | | | | | | | | | | | | | | 89.8-90.6 | 13/16 | CC-70177 | CK-3144 |
| | | | | | | | | | | | | | | | | | | | | | | | 90.6-90.8 | 13/16 | CC-70177 | CK-3144 |
| | | | | | | | | | | | | | | | | | | | | | | | 90.8-93.8 | 13/16 | CC-70177 | CK-T201 |
| | U－LH102V | 89.8-93.8 | 1 | | TK-T029 | 89.8-93.8 | 66.6 | DISC | MP-30 | | 89.8-93.8 | 15/16 | (R)WC-50047 | WK-309 | CUP | 89.8-93.8 | (R)BH-T599 | BH-T510 | 89.8-93.8 | 5/8 | MC-T331 | MK-4351 | 89.8-93.8 | 13/16 | CC-T344 | CK-3144 |
| | Q－LH140G | | | | | | | | | | | | (L)WC-50047 | | | | (L)BH-T600 | | | | | | | | | |
| | | | | | | | | | | | | | | | | <ｼﾞｬｽﾄﾛｰ> | | | | | | | | | | |
| | | | | | | | | | | | | | | | | 89.8-93.8 | (R)BH-T599 | BH-T511 | | | | | | | | |
| | | | | | | | | | | | | | | | | | (L)BH-T600 | | | | | | | | | |
| | | | | | | | | | | | <10人乗り> | | | | | | | | | | | | | | | |
| | Q－LH110G | 89.8-93.8 | 1 | | TK-T029 | 89.8-93.8 | 66.6 | DISC | MP-30 | | 89.8-93.8 | 7/8 | (R)WC-50054 | WK-405 | CUP | 89.8-93.8 | (R)BH-T599 | BH-T510 | 89.8-93.8 | 5/8 | MC-T331 | MK-4351 | 89.8-93.8 | 13/16 | CC-T344 | CK-3144 |
| | | | | | | | | | | | | | (L)WC-50054 | | | | (L)BH-T600 | | | | | | | | | |
| | | | | | | | | | | | <9人乗り> | | | | | | | | | | | | | | | |
| | | | | | | | | | | | 90.10-93.8 | 15/16 | (R)WC-50047 | WK-309 | CUP | | | | | | | | | | | |
| | | | | | | | | | | | | | (L)WC-50047 | | | | | | | | | | | | | |
| | Q－LH120G | 89.8-93.8 | 1 | | TK-T029 | 89.8-93.8 | 66.6 | DISC | MP-30 | | 89.8-92.5 | 7/8 | (R)WC-50054 | WK-405 | CUP | 89.8-93.8 | (R)BH-T599 | BH-T510 | 89.8-93.8 | 5/8 | MC-T331 | MK-4351 | 89.8-90.6 | 13/16 | CC-70177 | CK-3144 |
| | | | | | | | | | | | | | (L)WC-50054 | | | | (L)BH-T600 | | | | | | 90.6-90.8 | 13/16 | CC-70177 | CK-3144 |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | | 92.5-93.8 | 15/16 | (R)WC-50047<br>(L)WC-50047 | WK-309 | CUP | | | | | | | | 90.8-93.8 | 13/16 | CC-70177 | CK-T201 |
| (2800ディーゼル) | 89.8-93.8 | 1 | | TK-T029 | 89.8-96.8 | 66.6 | DISC | MP-30 | | 89.8-96.7 | 15/16 | (R)WC-50047 | WK-309 | CUP | 89.8-96.8 | (R)BH-T599 | BH-T510 | 89.8-95.8 | 5/8 | MC-T331 | MK-4351 | 89.8-94.10 | 13/16 | CC-T344 | CK-3144 |
| U－LH103V・123V | 93.8-98.8 | 1 | TD-T918 | TK-T364 | 96.8-98.8 | | DISC | MP-86 | CPM-86 | | | (L)WC-50047 | | | | (L)BH-T600 | | 95.8-96.6 | 5/8 | MC-T331 | | 94.10-98.8 | 13/16 | CC-T344 | CK-T201 |
| U－LH113V・113K | | | | | | | | | | 96.7-98.8 | 15/16 | (R)WC-T746 | WK-884 | CUP | 96.8-98.8 | (R)BH-T592 | BH-02221 | 96.6-98.8 | 5/8 | MC-T331 | MK-T244 | | | | |
| ＜KC－は95．8～＞ | | | | | | | | | | | | (L)WC-T746 | | | | (L)BH-T873 | | | | | | | | | |
| | | | | | | | | | | | | | | | <ｼﾞｬｽﾄﾛｰ> | | | | | | | | | | |
| | | | | | | | | | | | | | | | 89.8-96.8 | (R)BH-T599 | BH-T511 | | | | | | | | |
| | | | | | | | | | | | | | | | | (L)BH-T600 | | | | | | | | | |
| | | | | | | | | | | | | | | | 96.8-98.8 | (R)BH-T592 | BH-94000 | | | | | | | | |
| | | | | | | | | | | | | | | | | (L)BH-T873 | | | | | | | | | |
| S－LH115B | 89.8-93.8 | 1 | | TK-T029 | 89.8-96.8 | 66.6 | DISC | MP-30 | | 89.8-96.7 | 15/16 | (R)WC-50047 | WK-309 | CUP | 89.8-96.8 | (R)BH-T599 | BH-T510 | 89.8-95.8 | 5/8 | MC-T331 | MK-4351 | 89.8-94.10 | 13/16 | CC-T344 | CK-3144 |
| U－LH125B | 93.8-98.8 | 1 | TD-T918 | TK-T364 | 96.8-98.8 | | DISC | MP-86 | CPM-86 | | | (L)WC-50047 | | | | (L)BH-T600 | | 95.8-96.6 | 5/8 | MC-T331 | | 94.10-98.8 | 13/16 | CC-T344 | CK-T201 |
| ＜KC－は95．8～＞ | | | | | | | | | | 96.7-98.8 | 15/16 | (R)WC-T746 | WK-884 | CUP | 96.8-98.8 | (R)BH-T592 | BH-T510 | 96.6-98.8 | 5/8 | MC-T331 | MK-T244 | | | | |
| | | | | | | | | | | | | (L)WC-T746 | | | | (L)BH-T873 | | | | | | | | | |
| Q－LH107G・107W (4WD) | 89.8-93.8 | 1 | | TK-T029 | 89.8-93.8 | 66.6 | DISC | MP-31 | | 89.8-93.8 | 15/16 | (R)WC-50075<br>(L)WC-50075 | WK-885 | CUP | 89.8-93.8 | BH-T508 | BH-02576 | 89.8-93.8 | 5/8 | MC-T331 | MK-4351 | 89.8-93.8 | 13/16 | CC-T344 | CK-3144 |
| Q・U－LH109V・117G (4WD) | 89.8-93.8 | 1 | | TK-T029 | 89.8-93.8 | 66.6 | DISC | MP-31 | | 89.8-95.8 | 15/16 | (R)WC-50075 | WK-885 | CUP | 89.8-93.8 | BH-T508 | BH-02342 | 89.8-95.8 | 5/8 | MC-T331 | MK-4351 | 89.8-94.10 | 13/16 | CC-T344 | CK-3144 |
| U－LH119V・129V | 93.8-98.8 | 1 | TD-T918 | TK-T364 | 93.8-98.8 | | DISC | MP-86 | CPM-86 | | | (L)WC-50075 | | | 93.8-95.8 | BH-T601 | BH-02342 | 95.8-96.6 | 5/8 | MC-T331 | | 94.10-98.8 | 13/16 | CC-T344 | CK-T201 |
| ＜KC－は95．8～＞ | | | | | | | | | | 95.8-96.6 | 15/16 | (R)WC-50075 | WK-885 | CUP | 95.8-98.8 | BH-T666 | BH-02342 | 96.6-98.8 | 5/8 | MC-T331 | MK-T244 | | | | |
| | | | | | | | | | | | | (L)WC-50075 | | | | | | | | | | | | | |
| | | | | | | | | | | 96.7-96.8 | 15/16 | (R)<br>(L) | WK-885 | | | | | | | | | | | | |
| | | | | | | | | | | 96.8-98.8 | 1 | (R)WC-50063<br>(L)WC-50063 | WK-886 | CUP | | | | | | | | | | | |
| (3000ディーゼル) | 98.8-04.8 | 1 | TD-T918 | TK-T364 | 98.8-04.8 | | DISC | MP-86 | CPM-86 | 98.8-04.8 | 15/16 | (R)WC-T746 | WK-884 | CUP | 98.8-99.7 | (R)BH-T592 | BH-T871 | 98.8-04.8 | 5/8 | MC-T331 | MK-T244 | 98.8-04.8 | 13/16 | CC-T344 | CK-T201 |
| KG－LH162V・172V | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | (L)WC-T746 | | | | (L)BH-T873 | | | | | | | | | |
| KG－LH172K | 98.8-04.8 | 1 1/16 | | | | | | | | | | | | | 99.7-04.8 | (R)BH-T592 | BH-T871 | | | | | | | | |
| KG－LH182K・184B | | | | | | | | | | | | | | | | (L)BH-T873 | | | | | | | | | |
| | | | | | | | | | | | | | | | <ｼﾞｬｽﾄﾛｰ> | | | | | | | | | | |
| | | | | | | | | | | | | | | | 98.8-99.7 | (R)BH-T592 | BH-94000 | | | | | | | | |
| | | | | | | | | | | | | | | | | (L)BH-T873 | | | | | | | | | |
| | | | | | | | | | | | | | | | 99.7-04.8 | (R)BH-T592 | BH-T872 | | | | | | | | |
| | | | | | | | | | | | | | | | | (L)BH-T873 | | | | | | | | | |
| KG－LH168V・178V (4WD) | 98.8-04.8 | 1 | TD-T918 | TK-T364 | 98.8-04.8 | | DISC | MP-86 | CPM-86 | 98.8-04.8 | 1 | (R)WC-50063 | WK-886 | CUP | 98.8-99.7 | BH-T666 | BH-T871 | 98.8-04.8 | 5/8 | MC-T331 | MK-T244 | 98.8-04.8 | 13/16 | CC-T344 | CK-T201 |
| KG－LH186B・188K | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | (L)WC-50063 | | | 99.7-04.8 | | BH-T871 | | | | | | | | |
| | 98.8-04.8 | 1 1/16 | | | | | | | | | | | | | | | | | | | | | | | |
| (3000ディーゼル) (2WD) | 93.8-96.8 | 1 1/16 | TD-T798 | TK-T346 | 93.8-04.8 | | DISC | MP-86 | CPM-86 | 93.8-96.7 | 15/16 | (R)WC-50047 | WK-309 | CUP | 93.8-99.7 | (R)BH-T592 | BH-02576 | 93.8-95.8 | 5/8 | MC-T331 | MK-4351 | 93.8-93.11 | 3/4 | | CK-T206 |
| Y－KZH100G・110G | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | (L)WC-50047 | | | | (L)BH-T873 | | 95.8-96.6 | 5/8 | MC-T331 | | 93.11-94.8 | 3/4 | | CK-T217 |
| Y－KZH120G | 93.8-04.8 | 1 1/16 | | | | | | | | 96.7-04.8 | 15/16 | (R)WC-T746 | WK-884 | CUP | 99.7-04.8 | (R)BH-T592 | BH-T919 | 96.6-99.7 | 5/8 | MC-T331 | MK-T244 | 94.8-99.7 | 3/4 | | CK-T212 |
| ＜KD－は95．8～＞ | | | | | | | | | | | | (L)WC-T746 | | | | (L)BH-T873 | | 99.7-04.8 | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| ＜KH－は99．7～＞ | | | | | | | | | | | | | | | | | | | | | | | | | |
| KH－KZH120G (4WD) | 99.7-04.8 | | | | 99.7-04.8 | | DISC | MP-86 | CPM-86 | 99.7-04.8 | 15/16 | (R)WC-50075<br>(L)WC-50075 | WK-885 | CUP | 99.7-04.8 | | BH-T919 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| Y－KZH106G・106W (4WD) | 93.8-96.8 | 1 1/16 | TD-T798 | TK-T346 | 93.8-04.8 | | DISC | MP-86 | CPM-86 | 93.8-04.8 | 15/16 | (R)WC-50075 | WK-885 | CUP | 93.8-95.8 | BH-T601 | BH-T681 | 93.8-95.8 | 5/8 | MC-T331 | MK-4351 | 93.8-93.11 | 3/4 | | CK-T206 |
| Y－KZH116G・126G | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | (L)WC-50075 | | | 95.8-99.7 | BH-T666 | BH-T681 | 95.8-96.6 | 5/8 | MC-T331 | | 93.11-94.8 | 3/4 | | CK-T217 |
| ＜KD－は95．8～＞ | 93.8-04.8 | 1 1/16 | | | | | | | | | | | | | 99.7-04.8 | | BH-T919 | 96.6-99.7 | 5/8 | MC-T331 | MK-T244 | 94.8-99.7 | 3/4 | | CK-T212 |
| ＜KH－は99．7～＞ | | | | | | | | | | | | | | | | | | 99.7-04.8 | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| KC－KZH132V | 95.8-99.7 | 1 1/16 | TD-T798 | TK-T346 | 95.8-96.8 | | DISC | MP-86 | CPM-86 | 95.8-96.7 | 15/16 | (R)WC-50047 | WK-309 | CUP | 95.8-99.7 | (R)BH-T592 | BH-02576 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| ＜KJ－は99．7～＞ | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | 96.8-04.8 | | DISC | MP-86 | CPM-86 | | | (L)WC-50047 | | | | (L)BH-T873 | | | | | | | | | |
| | 96.8-04.8 | 1 1/16 | | | | | | | | 96.7-04.8 | 15/16 | (R)WC-T746 | WK-884 | CUP | 99.7-04.8 | (R)BH-T592 | BH-02576 | | | | | | | | |
| | | | | | | | | | | | | (L)WC-T746 | | | | (L)BH-T873 | | | | | | | | | |
| KC－KZH138V (4WD) | 95.8-99.7 | 1 1/16 | TD-T798 | TK-T346 | 95.8-04.8 | | DISC | MP-86 | CPM-86 | 95.8-96.6 | 15/16 | (R)WC-50075 | WK-885 | CUP | 95.8-99.7 | BH-T666 | BH-T681 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| ＜KJ－は99．7～＞ | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | (L)WC-50075 | | | 99.7-04.8 | | BH-T919 | | | | | | | | |
| | 96.8-04.8 | 1 1/16 | | | | | | | | 96.7-96.8 | 15/16 | (R)<br>(L) | WK-885 | CUP | | | | | | | | | | | |
| | | | | | | | | | | 96.8-04.8 | 15/16 | (R)WC-50075<br>(L)WC-50075 | WK-885 | CUP | | | | | | | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| HIACE, REGIUS ACE : 200 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000) | CBF－TRH200K<br>CBF－TRH200V | AT | 04.8-15.1<br>15.1- | 13/16 | TD-T917 | TK-T450 | 04.8- | | DISC | MP-86 | CPM-86 | 04.8- | 7/8 | (R)WC-T795<br>(L)WC-T795 | WK-1046 | CUP | 04.8- | (R)<br>(L) | | | | (オートマチック) | | | | | |
| | | MT | 04.8-15.1<br>15.1- | 13/16 | TD-T917 | TK-T450 | 04.8- | | DISC | MP-86 | CPM-86 | 04.8- | 7/8 | (R)WC-T795<br>(L)WC-T795 | WK-1046 | CUP | 04.8- | (R)<br>(L) | | 04.8- | | MC-T475 | | 04.8- | 13/16 | CC-T371 | CK-T201 |
| (2500) | KR－KDH200K | | 04.8-07.9 | 13/16 | TD-T917 | TK-T450 | 04.8-07.9 | | DISC | MP-86 | CPM-86 | 04.8-07.9 | 7/8 | (R)WC-T795<br>(L)WC-T795 | WK-1046 | CUP | 04.8-07.9 | (R)<br>(L) | | 04.8-07.9 | | MC-T475 | | 04.8-07.9 | 3/4 | CC-T389 | CK-T212 |
| | KR－KDH200V | | 04.8-07.9 | 13/16 | TD-T917 | TK-T450 | 04.8-07.9 | | DISC | MP-86 | CPM-86 | 04.8-07.9 | 7/8 | (R)WC-T795<br>(L)WC-T795 | WK-1046 | CUP | 04.8-07.9 | (R)<br>(L) | | 04.8-07.9 | | MC-T475 | | 04.8-07.9 | 3/4 | CC-T389 | CK-T212 |
| | KR－KDH205K | | 04.8-07.9 | 13/16 | TD-T917 | TK-T450 | 04.8-07.9 | | DISC | MP-86 | CPM-86 | 04.8-07.9 | 7/8 | (R)WC-T795<br>(L)WC-T795 | WK-1046 | CUP | 04.8-07.9 | (R)<br>(L) | | 04.8-07.9 | | MC-T475 | | 04.8-07.9 | 3/4 | CC-T389 | CK-T212 |
| | KR－KDH205V | 4WD | 05.1-07.9 | 13/16 | TD-T917 | TK-T450 | 05.1-07.9 | | DISC | MP-86 | CPM-86 | 05.1-07.9 | 7/8 | (R)WC-T795<br>(L)WC-T795 | WK-1046 | CUP | 05.1-07.9 | (R)<br>(L) | | 05.1-07.9 | | MC-T475 | | 05.1-07.9 | 3/4 | CC-T389 | CK-T212 |
| | KR－KDH220K | | 05.1-07.9 | 13/16 | TD-T917 | TK-T450 | 05.1-07.9 | | DISC | MP-86 | CPM-86 | 05.1-07.9 | 7/8 | (R)WC-T795<br>(L)WC-T795 | WK-1046 | CUP | 05.1-07.9 | (R)<br>(L) | | | | (オートマチック) | | | | | |
| | KR－KDH222B | | 05.1-07.9 | 13/16 | TD-T917 | TK-T450 | 05.1-07.9 | | DISC | MP-86 | CPM-86 | 05.1-07.9 | 7/8 | (R)WC-T795<br>(L)WC-T795 | WK-1046 | CUP | 05.1-07.9 | (R)<br>(L) | | | | (オートマチック) | | | | | |
| | KR－KDH225K | 4WD | 05.1-07.9 | 13/16 | TD-T917 | TK-T450 | 05.1-07.9 | | DISC | MP-86 | CPM-86 | 05.1-07.9 | 7/8 | (R)WC-T795<br>(L)WC-T795 | WK-1046 | CUP | 05.1-07.9 | (R)<br>(L) | | | | (オートマチック) | | | | | |
| | KR－KDH227B | 4WD | 05.1-07.9 | 13/16 | TD-T917 | TK-T450 | 05.1-07.9 | | DISC | MP-86 | CPM-86 | 05.1-07.9 | 7/8 | (R)WC-T795<br>(L)WC-T795 | WK-1046 | CUP | 05.1-07.9 | (R)<br>(L) | | | | (オートマチック) | | | | | |
| (2700) | CBF－TRH211K | | 07.9-13.12 | 13/16 | TD-T917 | TK-T450 | 07.9- | | DISC | MP-86 | CPM-86 | 07.9- | 7/8 | (R)WC-T795<br>(L)WC-T795 | WK-1046 | CUP | 07.9- | (R)<br>(L) | | | | (オートマチック) | | | | | |
| | CBA－TRH214W | | 04.8-15.1<br>15.1- | 13/16 | TD-T917 | TK-T450 | 04.8- | | DISC | MP-86 | CPM-86 | 04.8- | 7/8 | (R)WC-T795<br>(L)WC-T795 | WK-1046 | CUP | 04.8- | (R)<br>(L) | | | | (オートマチック) | | | | | |
| | CBF－TRH216K | 4WD | 07.9-15.1<br>15.1- | 13/16 | TD-T917 | TK-T450 | 07.9- | | DISC | MP-86 | CPM-86 | 07.9- | 7/8 | (R)WC-T795<br>(L)WC-T795 | WK-1046 | CUP | 07.9- | (R)<br>(L) | | | | (オートマチック) | | | | | |
| | CBA－TRH219W | 4WD | 04.8-15.1<br>15.1- | 13/16 | TD-T917 | TK-T450 | 04.8- | | DISC | MP-86 | CPM-86 | 04.8- | 7/8 | (R)WC-T795<br>(L)WC-T795 | WK-1046 | CUP | 04.8- | (R)<br>(L) | | | | (オートマチック) | | | | | |
| | CBF－TRH221K | | 05.1-15.1<br>15.1- | 13/16 | TD-T917 | TK-T450 | 05.1- | | DISC | MP-86 | CPM-86 | 05.1- | 7/8 | (R)WC-T795<br>(L)WC-T795 | WK-1046 | CUP | 05.1- | (R)<br>(L) | | | | (オートマチック) | | | | | |
| | CBF－TRH223B | | 05.1-15.1<br>15.1- | 13/16 | TD-T917 | TK-T450 | 05.1- | | DISC | MP-86 | CPM-86 | 05.1- | 7/8 | (R)WC-T795<br>(L)WC-T795 | WK-1046 | CUP | 05.1- | (R)<br>(L) | | | | (オートマチック) | | | | | |
| | CBA－TRH224W | | 05.1-15.1<br>15.1- | 13/16 | TD-T917 | TK-T450 | 05.1- | | DISC | MP-86 | CPM-86 | 05.1- | 7/8 | (R)WC-T795<br>(L)WC-T795 | WK-1046 | CUP | 05.1- | (R)<br>(L) | | | | (オートマチック) | | | | | |
| | CBF－TRH226K | 4WD | 05.1-15.1<br>15.1- | 13/16 | TD-T917 | TK-T450 | 05.1- | | DISC | MP-86 | CPM-86 | 05.1- | 7/8 | (R)WC-T795<br>(L)WC-T795 | WK-1046 | CUP | 05.1- | (R)<br>(L) | | | | (オートマチック) | | | | | |
| | CBF－TRH228B | 4WD | 05.1-15.1<br>15.1- | 13/16 | TD-T917 | TK-T450 | 05.1- | | DISC | MP-86 | CPM-86 | 05.1- | 7/8 | (R)WC-T795<br>(L)WC-T795 | WK-1046 | CUP | 05.1- | (R)<br>(L) | | | | (オートマチック) | | | | | |
| | CBA－TRH229W | 4WD | 05.1-15.1<br>15.1- | 13/16 | TD-T917 | TK-T450 | 05.1- | | DISC | MP-86 | CPM-86 | 05.1- | 7/8 | (R)WC-T795<br>(L)WC-T795 | WK-1046 | CUP | 05.1- | (R)<br>(L) | | | | (オートマチック) | | | | | |
| (2800) | QDF－GDH201V | | 17.12- | | | キットセッテイナシ | 17.12- | | DISC | MP-86 | CPM-86 | 17.12- | 7/8 | (R)WC-T795<br>(L)WC-T795 | WK-1046 | CUP | 17.12- | (R)<br>(L) | | | | | | | | | |
| (2800) | QDF－GDH206K<br>QDF－GDH226K | 4WD<br>4WD | <ABS付><br>17.12-<br><ABS無><br>17.12- | | | キットセッテイナシ<br>キットセッテイナシ | 17.12- | | DISC | MP-86 | CPM-86 | 17.12- | 7/8 | (R)WC-T795<br>(L)WC-T795 | WK-1046 | CUP | 17.12- | (R)<br>(L) | | | | (オートマチック) | | | | | |
| (3000) | ADF－KDH201K | | 07.9-15.1<br>15.1- | 13/16 | TD-T917 | TK-T450 | 07.9- | | DISC | MP-86 | CPM-86 | 07.9- | 7/8 | (R)WC-T795<br>(L)WC-T795 | WK-1046 | CUP | 07.9- | (R)<br>(L) | | 07.9- | | MC-T475 | | 07.9- | 3/4 | CC-T389 | CK-T212 |
| | ADF－KDH201V | | 07.9-15.1<br>15.1- | 13/16 | TD-T917 | TK-T450 | 07.9- | | DISC | MP-86 | CPM-86 | 07.9- | 7/8 | (R)WC-T795<br>(L)WC-T795 | WK-1046 | CUP | 07.9- | (R)<br>(L) | | 07.9- | | MC-T475 | | 07.9- | 3/4 | CC-T389 | CK-T212 |
| | ADF－KDH206K | 4WD | 07.9-15.1<br>15.1- | 13/16 | TD-T917 | TK-T450 | 07.9- | | DISC | MP-86 | CPM-86 | 07.9- | 7/8 | (R)WC-T795<br>(L)WC-T795 | WK-1046 | CUP | 07.9- | (R)<br>(L) | | 07.9- | | MC-T475 | | 07.9- | 3/4 | CC-T389 | CK-T212 |
| | ADF－KDH206V | 4WD | 07.9-15.1<br>15.1- | 13/16 | TD-T917 | TK-T450 | 07.9- | | DISC | MP-86 | CPM-86 | 07.9- | 7/8 | (R)WC-T795<br>(L)WC-T795 | WK-1046 | CUP | 07.9- | (R)<br>(L) | | 07.9- | | MC-T475 | | 07.9- | 3/4 | CC-T389 | CK-T212 |
| | ADF－KDH211K | | 07.9-15.1<br>15.1- | 13/16 | TD-T917 | TK-T450 | 07.9- | | DISC | MP-86 | CPM-86 | 07.9- | 7/8 | (R)WC-T795<br>(L)WC-T795 | WK-1046 | CUP | 07.9- | (R)<br>(L) | | | | (オートマチック) | | | | | |
| | ADF－KDH221K | | 07.9-15.1<br>15.1- | 13/16 | TD-T917 | TK-T450 | 07.9- | | DISC | MP-86 | CPM-86 | 07.9- | 7/8 | (R)WC-T795<br>(L)WC-T795 | WK-1046 | CUP | 07.9- | (R)<br>(L) | | | | (オートマチック) | | | | | |
| | ADF－KDH223B | | 07.9-15.1<br>15.1- | 13/16 | TD-T917 | TK-T450 | 07.9- | | DISC | MP-86 | CPM-86 | 07.9- | 7/8 | (R)WC-T795<br>(L)WC-T795 | WK-1046 | CUP | 07.9- | (R)<br>(L) | | | | (オートマチック) | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| HIACE REGIUS, TOURING HIACE : 40 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000) | GB－RCH42V<br>＜GE－は99．7～＞ | 97.6-02.5<br>〈ｱﾝﾁｽｷｯﾄﾞ付〉<br>97.6-02.5 | 1<br><br>1 | | TK-T378<br><br>TK-T377 | 97.6-02.5 | | DISC | MP-86 | CPM-86 | 97.6-02.5 | 1 | (R)<br>(L) | WK-898 | CUP | 97.6-99.7<br><br>99.7-02.5 | (R)BH-T667<br>(L)BH-T668<br>(R)BH-T844<br>(L)BH-T845 | (R)BH-T665<br>(L)BH-T665<br>(R)BH-T789<br>(L)BH-T789 | 97.6-99.7<br>99.7-02.5 | 5/8 | MC-T474<br>(ｵｰﾄﾏﾁｯｸ) | MK-T244 | 97.6-99.7 | 13/16 | CC-T390 | CK-T201 |
| (2700) | E－RCH41W<br>＜GF－は99．7～＞ | 97.4-02.5 | 1 | | TK-T412 | 97.4-02.5 | | DISC | MP-86 | CPM-86 | 97.4-02.5 | | DISC | MP-63 | CPM-63 | 97.4-99.7<br><br><br><br>99.7-02.5 | (R)BH-T667<br>(L)BH-T668<br><br><br><br>(R)BH-T844<br>(L)BH-T845 | (R-1)BH-T665<br>(L-1)BH-T665<br>(R-2)BH-T756<br>(L-2)BH-T757<br>(R-1)BH-T789<br>(L-1)BH-T789<br>(R-2)BH-T842<br>(L-2)BH-T843 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | E－RCH47W(4WD)<br>＜GF－は99．7～＞ | 97.4-02.5 | 1 | | TK-T412 | 97.4-02.5 | | DISC | MP-86 | CPM-86 | 97.4-02.5 | | DISC | MP-63 | CPM-63 | 97.4-99.7<br><br><br><br>99.7-02.5 | BH-T666 | (R-1)BH-T665<br>(L-1)BH-T665<br>(R-2)BH-T756<br>(L-2)BH-T757<br>(R-1)BH-T789<br>(L-1)BH-T789<br>(R-2)BH-T842<br>(L-2)BH-T843 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (3000ディーゼル) | KD－KCH40G・40W<br>＜KH－は99．7～＞ | 97.4-02.5 | 1 | | TK-T412 | 97.4-02.5 | | DISC | MP-86 | CPM-86 | 97.4-02.5 | | DISC | MP-63 | CPM-63 | 97.4-99.7<br><br><br><br>99.7-02.5 | (R)BH-T667<br>(L)BH-T668<br><br><br><br>(R)BH-T844<br>(L)BH-T845 | (R-1)BH-T665<br>(L-1)BH-T665<br>(R-2)BH-T756<br>(L-2)BH-T757<br>(R-1)BH-T789<br>(L-1)BH-T789<br>(R-2)BH-T842<br>(L-2)BH-T843 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | KD－KCH46G(4WD)<br>KD－KCH46W(4WD)<br>＜KH－は99．7～＞ | 97.4-02.5 | 1 | | TK-T412 | 97.4-02.5 | | DISC | MP-86 | CPM-86 | 97.4-02.5 | | DISC | MP-63 | CPM-63 | 97.4-99.7<br><br><br><br>99.7-02.5 | BH-T666 | (R-1)BH-T665<br>(L-1)BH-T665<br>(R-2)BH-T756<br>(L-2)BH-T757<br>(R-1)BH-T789<br>(L-1)BH-T789<br>(R-2)BH-T842<br>(L-2)BH-T843 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | KG－LXH43V | 97.6-02.5<br>〈ｱﾝﾁｽｷｯﾄﾞ付〉<br>97.6-02.5 | 1<br><br>1 | | TK-T378<br><br>TK-T377 | 97.6-02.5 | | DISC | MP-86 | CPM-86 | 97.6-02.5 | 1 | (R)<br>(L) | WK-898 | CUP | 97.6-99.7<br><br>99.7-02.5 | (R)BH-T667<br>(L)BH-T668<br>(R)BH-T844<br>(L)BH-T845 | (R)BH-T665<br>(L)BH-T665<br>(R)BH-T789<br>(L)BH-T789 | 97.6-02.5 | 5/8 | | MK-T244 | 97.6-02.5 | 13/16 | CC-T344 | CK-T201 |
| | KG－LXH49V(4WD) | 97.6-02.5<br>〈ｱﾝﾁｽｷｯﾄﾞ付〉<br>97.6-02.5 | 1<br><br>1 | | TK-T378<br><br>TK-T377 | 97.6-02.5 | | DISC | MP-86 | CPM-86 | 97.6-02.5 | 1 | (R)<br>(L) | WK-898 | CUP | 97.6-99.7<br><br>99.7-02.5 | BH-T666 | (R)BH-T665<br>(L)BH-T665<br>(R)BH-T789<br>(L)BH-T789 | 97.6-02.5 | 5/8 | | MK-T244 | 97.6-02.5 | 13/16 | CC-T344 | CK-T201 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| HIACE TRUCK : YY, LY100-160 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000) | GB－YY101 | Wキャブ シングルジャストロー | 95.5-96.10 | 15/16 | | TK-T380 | 95.5-96.10 | 60.3 | DISC | MP-10 | | 95.5-96.10 | 7/8 | (R)WC-50046 (L)WC-50046 | WK-048 | CUP | 95.5-96.10 | BH-02477 | BH-T681 | 95.5-96.10 | 5/8 | | MK-T244 | 95.5-96.10 | 13/16 | CC-70145 | CK-T201 |
| | | スーパーシングルジャストロー | 95.5-96.10 | 15/16 | | TK-T380 | 95.5-96.10 | 60.3 | DISC | MP-10 | | 95.5-96.10 | 13/16 | (R)WC-50051 (L)WC-50051 | WK-106 | CUP | 95.5-96.10 | BH-02477 | BH-02342 | 95.5-96.10 | 5/8 | | MK-T244 | 95.5-96.10 | 13/16 | CC-70145 | CK-T201 |
| (2800ディーゼル) | | 低床・Wキャブ | 95.5-96.10 | 15/16 | | TK-T380 | 95.5-96.10 | 60.3 | DISC | MP-10 | | 95.5-96.10 | 7/8 | (R)WC-50046 (L)WC-50046 | WK-048 | CUP | 95.5-96.10 | BH-02477 | BH-T681 | 95.5-96.10 | 5/8 | | MK-T244 | 95.5-96.10 | 13/16 | | CK-T201 |
| | KC－LY101・111 | シングルジャストロー | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | スーパーシングルジャストロー | 95.5-96.10 | 15/16 | | TK-T380 | 95.5-96.10 | 60.3 | DISC | MP-10 | | 95.5-96.10 | 13/16 | (R)WC-50051 (L)WC-50051 | WK-106 | CUP | 95.5-96.10 | BH-02477 | BH-02342 | 95.5-96.10 | 5/8 | | MK-T244 | 95.5-96.10 | 13/16 | | CK-T201 |
| | KC－LY151・161 | Wキャブ シングルジャストロー | 95.5-96.10 | 1 | | TK-T364 | 95.5-96.10 | 66.6 | DISC | MP-27 | | 95.5-96.10 | 15/16 | (R)WC-50075 (L)WC-50075 | WK-885 | CUP | 95.5-96.10 | BH-02522 | BH-02342 | 95.5-96.10 | 5/8 | | MK-T244 | 95.5-96.10 | 13/16 | | CK-T201 |
| | | スーパーシングルジャストロー | 95.5-96.10 | 1 | | TK-T364 | 95.5-96.10 | 66.6 | DISC | MP-27 | | 95.5-96.10 | 13/16 | (R)WC-50051 (L)WC-50051 | WK-106 | CUP | 95.5-96.10 | BH-02522 | BH-94008 | 95.5-96.10 | 5/8 | | MK-T244 | 95.5-96.10 | 13/16 | | CK-T201 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| HILUX : 20, 30, 40 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | <RN20,25> | | | |
| (1600) | RN20・25 | STD・DX | 72.5-78.7 | 1 | | TK-9323 | 72.5-75.7 | 1 1/8 | (R-1)WC-5195<br>(R-2)WC-5265<br>(L-1)WC-5395<br>(L-2)WC-5465 | | CUP | 72.5-78.7<br><LSPV付> | 7/8 | (R)WC-50046<br>(L)WC-50046 | WK-048 | CUP | 72.5-74.1<br>74.1-74.8<br>74.8-78.7 | BH-02108<br>BH-02231<br>BH-31305 | BH-31462<br>BH-31462<br>BH-31462 | 72.5-74.8<br>74.8-78.7 | 5/8<br>5/8 | MC-10104<br>MC-10068 | MK-3001<br>MK-4300 | 72.5-78.7<br><RN22> | 15 | CC-70097 | FC-31480-B |
| (2000) | RN22 | | | | | | | | | | | 72.5-78.7 | 15/16 | (R)WC-50045<br>(L)WC-50045 | | CUP | | | | | | | | 72.5-73.9<br>73.9-75.11 | 3/4<br>3/4 | CC-70071<br>CC-70090 | CK-41480<br>CK-3108 |
| | | | | | | | 75.7-75.11 | 1 1/8 | (R-1)WC-5195<br>(R-2)WC-5265<br>(L-1)WC-5395<br>(L-2)WC-5465 | WK-314 | CUP | | | | | | | | | | | | | | | | | |
| | | | | | | | 75.11-78.7 | 1 1/8 | (R-1)WC-51007<br>(R-2)WC-50056<br>(L-1)WC-53006<br>(L-2)WC-54007 | WK-314 | CUP | | | | | | | | | | | | | | | | | |
| (1600) | H－RN30・40<br>J－RN33・43<br>L－RN35 | STD | 78.8-88.9 | 15/16 | | TK-9391 | 78.8-88.9 | 1 1/8 | (R-1)WC-52006<br>(R-2)WC-51006<br>(L-1)WC-54006<br>(L-2)WC-53006 | WK-314 | CUP | 78.8-88.9 | 13/16 | (R)WC-50051<br>(L)WC-50051 | WK-106 | CUP | 78.8-88.9 | BH-02378 | BH-31441 | 78.8-86.11<br>86.11-88.9 | 5/8<br>5/8 | MC-10079 | MK-4300<br>MK-4353 | 78.8-85.8<br>85.8-88.9 | 15<br>13/16 | CC-70122 | CK-3119<br>CK-3144 |
| | H－RN30・40<br>J－RN33・43<br>L－RN35・45 | DX・スーパーDX | 78.8-88.9 | 15/16 | | TK-9392 | 78.8-82.12<br>82.12-88.9 | 2 3/8<br>2 3/8 | DISC<br>DISC | MP-4<br>MP-9 | | 78.8-88.9 | 7/8 | (R)WC-50046<br>(L)WC-50046 | WK-048 | CUP | 78.8-88.9 | (1)BH-02382<br>(2)BH-02381 | BH-31441 | 78.8-86.11<br>86.11-88.9 | 5/8<br>5/8 | MC-10079 | MK-4300<br>MK-4353 | 78.8-85.8<br>85.8-88.9 | 15<br>13/16 | CC-70122 | CK-3119<br>CK-3144 |
| (2000) | J－RN36(4WD)<br>L－RN39(4WD) | DX | 7910-8310 | 13/16 | | TK-9346 | 7910-8310 | | DISC | SP-217 | CPS-217+CPS-217B | 7910-8310 | 3/4 | (R)WC-50049<br>(L)WC-50049 | WK-043 | CUP | 79.10-83.10 | BH-02383 | BH-34801 | 7910-8310 | 5/8 | MC-10079 | MK-4300 | 79.10-81.5<br>81.5-83.10 | 3/4<br>3/4 | CC-70090<br>CC-70090 | CK-3108<br>CK-3124 |
| (2200ディーゼル) | K－LN30・40<br>N－LN30・40・41<br><N－は83. 4～> | DX・スーパーDX | 79.12-88.9 | 15/16 | | TK-9392 | 7912-8212<br>82.12-88.9 | 2 3/8<br>2 3/8 | DISC<br>DISC | MP-4<br>MP-9 | | 79.12-88.9 | 7/8 | (R)WC-50046<br>(L)WC-50046 | WK-048 | CUP | 79.12-88.9 | (1)BH-02382<br>(2)BH-02381 | BH-31441 | 79.12-81.3<br>81.3-88.9<br><LN41><br>85.8-86.11<br>86.11-88.9 | 5/8<br>5/8<br><br>5/8<br>5/8 | MC-10072<br>MC-10110 | MK-4300<br>MK-4312<br><br>MK-4312<br>MK-4337 | 79.12-81.5<br>81.5-81.10<br>81.10-84.1<br>84.1-88.9 | 3/4<br>3/4<br>3/4<br>13/16 | CC-70091<br>CC-70091<br>CC-70143<br>CC-70133 | CK-3108<br>CK-3124<br>CK-T218<br>CK-3144 |
| | K－LN36・46(4WD)<br>N－LN36・46(4WD)<br><N－は83. 4～> | DX | 8110-8310 | 13/16 | | TK-9346 | 8110-8310 | | DISC | SP-217 | CPS-217+CPS-217B | 8110-8310 | 3/4 | (R)WC-50049<br>(L)WC-50049 | WK-043 | CUP | 81.10-83.10 | BH-02383 | BH-34801 | 8110-8310 | 5/8 | MC-10110 | MK-4312 | 8110-8310 | 3/4 | CC-70143 | CK-T218 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| HILUX : 50, 60 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1800) | L−YN51・56 | DX・スーパーDX | 83.11-88.8 | 15/16 | | TK-9445 | 83.11-88.8 | 60.3 | DISC | MP-10 | | 83.11-88.8 | 7/8 | (R)WC-50046<br>(L)WC-50046 | WK-048 | CUP | 83.11-88.8 | BH-02581 | BH-31424 | 83.11-86.11<br>86.11-88.8<br><YN56LPG車><br>85.8-86.11<br>86.11-88.8 | 5/8<br>5/8<br><br>5/8<br>5/8 | MC-10129<br>MC-10129<br><br>MC-10110<br>MC-T302 | MK-4300<br>MK-4353<br><br>MK-4312<br>MK-4337 | 83.11-88.8 | 13/16 | CC-70145 | CK-3144 |
| | | スーパーシングルジャストローDX | 87.1-88.8 | 15/16 | | TK-9445 | 87.1-88.8 | 60.3 | DISC | MP-10 | | 87.1-88.8 | 13/16 | (R)WC-50051<br>(L)WC-50051 | WK-106 | CUP | 87.1-88.8 | BH-02581 | BH-31424 | 87.1-88.8 | 5/8 | MC-10129 | MK-4353 | 87.1-88.8 | 13/16 | CC-70145 | CK-3144 |
| (2000) | E−YN61G<br>L−YN60・60V・61V<br>L−YN65(4WD) | DX・SR・SSR | 83.11-84.8<br>84.8-89.3 | 13/16<br>13/16 | | TK-9444<br>TK-9458 | 83.11-89.3 | | DISC | SP-217 | CPS-217+CPS-217B | 83.11-88.8<br><YN61V・61G><br>85.8-86.8<br><br>86.8-89.3 | 3/4<br><br>7/8<br><br>7/8 | (R)WC-50049<br>(L)WC-50049<br><br>(R)WC-T560<br>(L)WC-T560<br>(R)WC-50072<br>(L)WC-50072 | WK-043<br><br>WK-689<br><br>WK-694 | CUP<br><br>CUP<br><br>CUP | 83.11-85.8<br>85.8-88.8<br><YN61V・61G><br>85.8-88.12<br>88.12-89.3 | BH-02383<br>BH-02383<br><br>BH-02209<br>BH-02209 | BH-94012<br>BH-94000<br><br>BH-94000<br>BH-94000 | 83.11-85.8<br>85.8-86.11<br>86.11-89.3 | 5/8<br>5/8<br>5/8 | MC-10129<br>MC-10110<br>MC-T302 | MK-4300<br>MK-4312<br>MK-4337 | 83.11-89.3 | 13/16 | CC-70145 | CK-3144 |
| (2200ディーゼル)<br>(2400ディーゼル) | N−LN50・51・55<br>N−LN56 | DX・スーパーDX<br>DX・スーパーDX | 83.11-88.8 | 15/16 | | TK-9445 | 83.11-88.8 | 60.3 | DISC | MP-10 | CPM-10 | 83.11-88.8 | 7/8 | (R)WC-50046<br>(L)WC-50046 | WK-048 | CUP | 83.11-88.8 | BH-02581 | BH-31424 | 83.11-85.8<br>85.8-86.11<br>86.11-88.8 | 5/8<br>5/8<br>5/8 | MC-10110<br>MC-10110<br>MC-T302 | MK-4312<br>MK-4312<br>MK-4337 | 83.11-88.8 | 13/16 | CC-70133 | CK-3144 |
| | | スーパーシングルジャストローDX | 87.1-88.8 | 15/16 | | TK-9445 | 87.1-88.8 | 60.3 | DISC | MP-10 | CPM-10 | 87.1-88.8 | 13/16 | (R)WC-50051<br>(L)WC-50051 | WK-106 | CUP | 87.1-88.8 | BH-02581 | BH-31424 | 87.1-88.8 | 5/8 | | MK-4337 | 87.1-88.8 | 13/16 | CC-70133 | CK-3144 |
| (2400ディーゼル) | N−LN60・60V・61V<br>N−LN65(4WD) | DX・SR | 83.11-84.8<br>84.8-89.3 | 13/16<br>13/16 | | TK-9444<br>TK-9458 | 83.11-89.3 | | DISC | SP-217 | CPS-217+CPS-217B | <LN60・60V・65><br>83.11-88.8<br><LN61V><br>85.8-86.8<br><br>86.8-89.3 | 3/4<br><br>7/8<br><br>7/8 | (R)WC-50049<br>(L)WC-50049<br><br>(R)WC-T560<br>(L)WC-T560<br>(R)WC-50072<br>(L)WC-50072 | WK-043<br><br>WK-689<br><br>WK-694 | CUP<br><br>CUP<br><br>CUP | <LN60・60V・65><br>83.11-85.8<br>85.8-88.8<br><LN61V><br>85.8-88.12<br>88.12-89.3 | BH-02383<br>BH-02383<br><br>BH-02209<br>BH-02209 | BH-94012<br>BH-94000<br><br>BH-94000<br>BH-94000 | 83.11-85.8<br>85.8-86.11<br>86.11-89.3 | 5/8<br>5/8<br>5/8 | MC-10110<br>MC-10110<br>MC-T302 | MK-4312<br>MK-4312<br>MK-4337 | 83.11-89.3 | 13/16 | CC-70133 | CK-3144 |
| | N−LN60V・61V(4WDターボ) | SR・SSR | 84.11-89.3 | 13/16 | | TK-9458 | 84.11-89.3 | | DISC | SP-217 | CPS-217+CPS-217B | <LN60V><br>84.11-88.8<br><LN61V><br>85.8-86.8<br><br>86.8-89.3 | 3/4<br><br>7/8<br><br>7/8 | (R)WC-50049<br>(L)WC-50049<br><br>(R)WC-T560<br>(L)WC-T560<br>(R)WC-50072<br>(L)WC-50072 | WK-043<br><br>WK-689<br><br>WK-694 | CUP<br><br>CUP<br><br>CUP | <LN60V><br>84.11-85.8<br>85.8-88.8<br><LN61V><br>85.8-88.12<br>88.12-89.3 | BH-02383<br>BH-02383<br><br>BH-02209<br>BH-02209 | BH-94012<br>BH-94000<br><br>BH-94000<br>BH-94000 | 84.11-86.11<br>86.11-89.3 | 5/8<br>5/8 | MC-T422<br>MC-T422 | MK-4312<br>MK-4337 | 84.11-89.3 | 13/16 | CC-70133 | CK-3144 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| HILUX : 80, 100, 130 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | <除くジャストロー> | | | | | | | | | | | | | | | |
| (1800) | T−YN80・85 | | 88.9−91.8 | 1 | | TK−T043 | 88.9−97.8 | 60.3 | DISC | MP−10 | CPM−10 | 88.9−94.8 | 7/8 | (R)WC−50046 | WK−048 | CUP | 88.9−97.8 | BH−02581 | BH−31424 | 88.9−92.4 | 5/8 | MC−T250 | MK−T236 | 88.9−91.10 | 13/16 | CC−70145 | CK−3144 |
| | GA−YN81・86 | | 91.8−97.8 | 1 | | TK−T378 | | | | | | | | (L)WC−50046 | | | | | | 92.4−94.3 | 5/8 | MC−T250 | | 91.10−97.8 | 13/16 | CC−T317 | CK−T201 |
| | <GA−は94．8〜> | | | | | | | | | | | 94.8−97.8 | 1 | (R)WC−50048 | WK−795 | CUP | | | | 94.3−97.8 | 5/8 | MC−T250 | MK−T244 | | | | |
| | | | | | | | | | | | | | | (L)WC−50048 | | | | | | | | | | | | | |
| | | | | | | | | | | | | <ジャストロー> | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | 88.9−97.8 | 13/16 | (R)WC−50051 | WK−106 | CUP | | | | | | | | | | | |
| | | | | | | | | | | | | | | (L)WC−50051 | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | <YN100,105> | | | | | | | | | | |
| (2000) | T−YN100・105(4WD) | | 88.9−91.8 | 15/16 | | TK−T044 | 88.9−97.8 | 42.8 | DISC | SP−253 | CPS−253 | 88.9−97.8 | 7/8 | (R)WC−50072 | WK−694 | CUP | 88.9−94.8 | BH−02383 | BH−94000 | 88.9−92.4 | 5/8 | MC−T312 | MK−T236 | 88.9−91.10 | 13/16 | CC−70145 | CK−3144 |
| | T−YN107(4WD) | | 91.8−97.8 | 15/16 | | TK−T380 | | | | | | | | (L)WC−50072 | | | <YN107> | | | 92.4−94.3 | 5/8 | MC−T312 | | 91.10−97.8 | 13/16 | CC−T317 | CK−T201 |
| | <GA−は94．8〜> | | | | | | | | | | | | | | | | 91.8−97.8 | BH−02209 | BH−94000 | 94.3−97.8 | 5/8 | MC−T312 | MK−T244 | | | | |
| | E−YN130G(4WD) | サーフ | 89.4−91.8 | 1 | | TK−T043 | 89.4−91.8 | 42.8 | DISC | SP−253 | CPS−253 | 89.4−91.8 | 7/8 | (R)WC−50072 | WK−694 | CUP | 89.4−91.8 | BH−02209 | BH−T507 | 89.4−91.8 | 5/8 | MC−T312 | MK−T236 | 89.4−91.8 | 13/16 | CC−70145 | CK−3144 |
| | | | | | | | | | | | | | | (L)WC−50072 | | | | | | | | | | | | | |
| (3000) | E−VZN130G(4WD) | サーフ | 90.8−91.8 | 1 | | TK−T043 | 90.8−91.8 | 42.8 | DISC | SP−253 | CPS−253 | 90.8−91.8 | 7/8 | (R)WC−50072 | WK−694 | CUP | 90.8−95.8 | BH−02209 | BH−T507 | 90.8−94.3 | 5/8 | | | 90.8−95.11 | 13/16 | | CK−T201 |
| | | | 91.8−95.11 | 1 | | TK−T378 | 91.8−95.11 | 45.4 | DISC | SP−265 | CPS−265 | | | (L)WC−50072 | | | 95.8−95.11 | BH−02209 | BH−T763 | 94.3−95.11 | 5/8 | | MK−T244 | | | | |
| | | | | | | | | | | | | 91.8−95.11 | 15/16 | (R)WC−50075 | WK−885 | CUP | | | | | | | | | | | |
| | | | | | | | | | | | | | | (L)WC−50075 | | | | | | | | | | | | | |
| | | | | | | | | | | | | <除くジャストロー> | | | | | | | | | | | | | | | |
| (2400ディーゼル) | | | 88.9−91.8 | 1 | | TK−T043 | 88.9−97.8 | 60.3 | DISC | MP−10 | CPM−10 | 88.9−94.8 | 7/8 | (R)WC−50046 | WK−048 | CUP | 88.9−97.8 | BH−02581 | BH−31424 | 88.9−92.4 | 5/8 | MC−T312 | MK−T236 | 88.9−94.5 | 13/16 | CC−70133 | CK−3144 |
| | S−LN80・85 | | 91.8−97.8 | 1 | | TK−T378 | | | | | | | | (L)WC−50046 | | | | | | 92.4−94.3 | 5/8 | MC−T312 | | 94.5−97.8 | 13/16 | | CK−T201 |
| | KB−LN81 | | | | | | | | | | | 94.8−97.8 | 1 | (R)WC−50048 | WK−795 | CUP | | | | 94.3−97.8 | 5/8 | MC−T312 | MK−T244 | | | | |
| | KC−LN86 | | | | | | | | | | | | | (L)WC−50048 | | | | | | | | | | | | | |
| | <KB・KC−は94．8〜> | | | | | | | | | | | <ジャストロー> | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | 88.9−97.8 | 13/16 | (R)WC−50051 | WK−106 | CUP | | | | | | | | | | | |
| | | | | | | | | | | | | | | (L)WC−50051 | | | | | | | | | | | | | |
| | KB−LN108・112(4WD) | | 95.8−97.8 | 1 | | TK−T378 | 95.8−97.8 | 42.8 | DISC | SP−253 | CPS−253 | 95.8−97.8 | 7/8 | (R)WC−50072 | WK−694 | CUP | 95.8−97.8 | BH−02209 | BH−94000 | | | (オートマチック) | | | | | |
| | | | | | | | | | | | | | | (L)WC−50072 | | | | | | | | | | | | | |
| | Q−LN130G(4WD) | サーフ | 89.4−91.8 | 1 | | TK−T043 | 89.4−91.8 | 42.8 | DISC | SP−253 | CPS−253 | 89.4−91.8 | 7/8 | (R)WC−50072 | WK−694 | CUP | 89.4−93.8 | BH−02209 | BH−T507 | 89.4−91.12 | 5/8 | | MK−T202 | 89.4−93.5 | 13/16 | CC−70177 | CK−3144 |
| | Q−LN130W(4WD) | | 91.8−93.8 | 1 | | TK−T378 | 91.8−93.8 | 45.4 | DISC | SP−265 | CPS−265 | | | (L)WC−50072 | | | | | | 91.12−93.8 | | | MK−T236 | 93.5−93.8 | 13/16 | CC−70177 | CK−T201 |
| | | | | | | | | | | | | 91.8−93.8 | 15/16 | (R)WC−50075 | WK−885 | CUP | | | | | | | | | | | |
| | | | | | | | | | | | | | | (L)WC−50075 | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | <LN100,106> | | | | | | | | | | |
| (2800ディーゼル) | S−LN100・106(4WD) | | 88.9−91.8 | 15/16 | | TK−T044 | 88.9−97.8 | 42.8 | DISC | SP−253 | CPS−253 | 88.9−97.8 | 7/8 | (R)WC−50072 | WK−694 | CUP | 88.9−97.8 | BH−02383 | BH−94000 | 88.9−92.4 | 5/8 | MC−T312 | MK−T236 | 88.9−94.5 | 13/16 | CC−70133 | CK−3144 |
| | S−LN107(4WD) | | 91.8−97.8 | 15/16 | | TK−T380 | | | | | | | | (L)WC−50072 | | | <LN107,109> | | | 92.4−94.3 | 5/8 | MC−T312 | | 94.5−97.8 | 13/16 | | CK−T201 |
| | KB−LN109(4WD) | | | | | | | | | | | | | | | | 91.8−97.8 | BH−02209 | BH−94000 | 94.3−97.8 | 5/8 | MC−T312 | MK−T244 | | | | |
| | <KB−は94．8〜> | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | S−LN131V(4WD) | サーフ | 89.4−91.8 | 1 | | TK−T043 | 89.4−91.8 | 42.8 | DISC | SP−253 | CPS−253 | 89.4−91.8 | 7/8 | (R)WC−50072 | WK−694 | CUP | 89.4−93.8 | BH−02209 | BH−T507 | 89.4−93.8 | 5/8 | | MK−T236 | 89.4−93.8 | 13/16 | CC−70133 | CK−3144 |
| | | | 91.8−93.8 | 1 | | TK−T378 | 91.8−93.8 | 45.4 | DISC | SP−265 | CPS−265 | | | (L)WC−50072 | | | | | | | | | | | | | |
| | | | | | | | | | | | | 91.8−93.8 | 15/16 | (R)WC−50075 | WK−885 | CUP | | | | | | | | | | | |
| | | | | | | | | | | | | | | (L)WC−50075 | | | | | | | | | | | | | |
| (3000ディーゼル) | | サーフ | 93.8−95.11 | 1 1/16 | | TK−T346 | 93.8−95.11 | 42.8 | DISC | SP−265 | CPS−265 | 93.8−95.11 | 15/16 | (R)WC−50075 | WK−885 | CUP | 93.8−95.8 | BH−T514 | BH−T507 | 93.8−94.3 | 5/8 | | MK−T236 | 93.8−93.11 | 3/4 | CC−T389 | |
| | Y−KZN130G(4WD) | | | | | | | | | | | | | (L)WC−50075 | | | 95.8−95.11 | BH−02209 | BH−T507 | 94.3−95.11 | 5/8 | | MK−T244 | 93.11−95.11 | 3/4 | CC−T389 | CK−T212 |
| | Y−KZN130W(4WD) | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | <KD−は94．8〜> | | | | | | | | | | | | | | | | | | | | | | | | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| HILUX : 120-170 ser. | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000) GA－RZN147<br>＜GC－は99．8～＞ | 97.8-<br>＜ｱﾝﾁｽｷｯﾄﾞ付＞<br>97.8- | 1<br><br>1 | | TK-T378<br><br>TK-T377 | 97.8- | 60.3 | DISC | MP-10 | CPM-10 | 97.8- | 1 | (R)<br>(L) | WK-898 | CUP | 97.8- | BH-T759 | BH-T761 | 97.8- | 5/8 | MC-T420 | MK-T244 | 97.8- | 13/16 | CC-T330 | CK-T201 |
| GC－RZN152H | 99.8- | 1 | | TK-T377 | 99.8- | 60.3 | DISC | MP-10 | CPM-10 | 99.8- | 1 | (R)WC-T744<br>(L)WC-T744 | WK-898 | CUP | 99.8- | BH-T759 | BH-T761 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| GA－RZN167 | 97.8-99.8 | 15/16 | | TK-T415 | 97.8-99.8 | 42.8 | DISC | SP-253 | CPS-253B | 97.8-99.8 | 7/8 | (R)WC-50072<br>(L)WC-50072 | WK-694 | CUP | 97.8-99.8 | BH-T760 | BH-T762 | 97.8-99.8 | 5/8 | MC-T420 | MK-T244 | 97.8-99.8 | 13/16 | CC-T330 | CK-T201 |
| (2700) GC－RZN169H | 99.8- | 15/16 | | TK-T415 | 99.8- | 42.8 | DISC | SP-253 | CPS-253B | 99.8- | 7/8 | (R)WC-50072<br>(L)WC-50072 | WK-694 | CUP | 99.8- | BH-T760 | BH-T762 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| GC－RZN174H | 99.8- | 15/16 | | TK-T415 | 99.8- | 42.8 | DISC | SP-253 | CPS-253B | 99.8- | 7/8 | (R)WC-50072<br>(L)WC-50072 | WK-694 | CUP | 99.8- | BH-T760 | BH-T762 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (2400ﾃﾞｨｰｾﾞﾙ)<br>KB－LN165･165H | 97.8-99.8 | 15/16 | | TK-T415 | 97.8-99.8 | 42.8 | DISC | SP-253 | CPS-253B | 97.8-99.8 | 7/8 | (R)WC-50072<br>(L)WC-50072 | WK-694 | CUP | 97.8-99.8 | BH-T760 | BH-T762 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| KB－LN170H | 97.11-99.8 | 15/16 | | TK-T415 | 97.11-99.8 | 42.8 | DISC | SP-253 | CPS-253B | 97.11-99.8 | 7/8 | (R)WC-50072<br>(L)WC-50072 | WK-694 | CUP | 97.11-99.8 | BH-T760 | BH-T762 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| QDF－GUN125<br>＜3DF－は20．6～＞ | 17.8- | | | ｷｯﾄｾｯﾃｲﾅｼ | 17.8- | | DISC | SP-292 | CPS-292 | 17.8- | | (R)<br>(L) | ｷｯﾄｾｯﾃｲﾅｼ | | 17.8- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (3000ﾃﾞｨｰｾﾞﾙ)<br>KF－LN147 | 97.8-<br>＜ｱﾝﾁｽｷｯﾄﾞ付＞<br>97.8- | 1<br><br>1 | | TK-T378<br><br>TK-T377 | 97.8- | 60.3 | DISC | MP-10 | CPM-10 | 97.8- | 1 | (R)<br>(L) | WK-898 | CUP | 97.8- | BH-T759 | BH-T761 | 97.8- | 5/8 | MC-T420 | MK-T244 | 97.8- | 13/16 | CC-T330 | CK-T201 |
| KF－LN167 | 97.8-<br>＜ｱﾝﾁｽｷｯﾄﾞ付＞<br>97.8- | 15/16<br><br>15/16 | | TK-T411<br><br>TK-T415 | 97.8- | 42.8 | DISC | SP-253 | CPS-253B | 97.8- | 7/8 | (R)WC-50072<br>(L)WC-50072 | WK-694 | CUP | 97.8- | BH-T760 | BH-T762 | 97.8- | 5/8 | MC-T420 | MK-T244 | 97.8- | 13/16 | CC-T330 | CK-T201 |
| KF－LN172H | 97.11- | 15/16 | | TK-T415 | 97.11- | 42.8 | DISC | SP-253 | CPS-253B | 97.11- | 7/8 | (R)<br>(L) | WK-694 | CUP | 97.11- | BH-T760 | BH-T762 | 97.11- | 5/8 | MC-T420 | MK-T244 | 97.11- | 13/16 | CC-T330 | CK-T201 |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| HILUX SURF : 180 ser. | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2700) E−RZN185W<br>GF−RZN185W・180W<br>＜GF−は98．7～＞<br>＜GH−は01．12～＞ | 95.11-02.11 | 1 | | TK-T412 | 95.11-02.11<br><GKMSK・GKPXK><br>95.11-98.7 | | DISC | SP-292<br><br>SP-210 | CPS-292 | 95.11-02.11<br><br><GKMSK・GKPXK><br>95.11-98.7 | 1<br><br><br>15/16 | (R)WC-T669<br>(L)WC-T669<br><br>(R)<br>(L) | WK-886<br><br><br>WK-885 | CUP<br><br><br>CUP | 95.11-00.8<br>00.8-02.11 | BH-T716<br>BH-T837 | BH-94016<br>BH-T851 | 95.11-00.8<br>00.8- | 5/8 | (オートマチック) | MK-T244 | 95.11-00.8 | 13/16 | CC-T330 | CK-T201 |
| (3400) E−VZN185W<br>GF−VZN185W・180W<br>＜GF−は98．7～＞ | 95.11-02.11 | 1 | | TK-T412 | 95.11-02.11 | | DISC | SP-292 | CPS-292 | 95.11-02.11 | 1 | (R)WC-T669<br>(L)WC-T669 | WK-886 | CUP<br>CUP | 95.11-00.8<br>00.8-02.11 | BH-T716<br>BH-T837 | BH-94016<br>BH-T851 | | | (オートマチック) | | | | | |
| (3000ディーゼル)<br>KD−KZN185G<br>＜KH−は98．7～＞ | 95.11-00.8 | 1 | | TK-T412 | 95.11-00.8 | | DISC | SP-210 | | 95.11-00.8 | 15/16 | (R)<br>(L) | WK-885 | CUP | 95.11-00.8 | BH-T716 | BH-94016 | 95.11-96.4<br>96.4-98.7<br>98.7-00.8 | 5/8<br>5/8<br>5/8 | | MK-T244<br>MK-T244<br>MK-T244 | 95.11-00.8 | 3/4 | CC-T391 | CK-T212 |
| KD−KZN185W<br>＜KH−は98．7～＞ | 95.11-00.8 | 1 | | TK-T412 | 95.11-00.8 | | DISC | SP-292 | CPS-292 | 95.11-00.8 | 1 | (R)WC-T669<br>(L)WC-T669 | WK-886 | CUP | 95.11-00.8 | BH-T716 | BH-94016 | 95.11-96.4<br>96.4-98.7<br>98.7-00.8 | 5/8<br>5/8<br>5/8 | | MK-T244<br>MK-T244<br>MK-T244 | 95.11-00.8 | 3/4 | CC-T391 | CK-T212 |
| KH−KDN185G | 00.8-02.11 | 1 | | TK-T412 | 00.8-02.11 | | DISC | SP-210 | | 00.8-02.11 | 15/16 | (R)<br>(L) | WK-885 | CUP | 00.8-02.11 | BH-T837 | BH-T851 | | | (オートマチック) | | | | | |
| KH−KDN185W | 00.8-02.11 | 1 | | TK-T412 | 00.8-02.11 | | DISC | SP-292 | CPS-292 | 00.8-02.11 | 1 | (R)WC-T669<br>(L)WC-T669 | WK-886 | CUP | 00.8-02.11 | BH-T837 | BH-T851 | | | (オートマチック) | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| HILUX SURF : 210 ser.(02.11-) | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2700) | LA－RZN210W<br>LA－RZN215W(4WD) | 02.11-04.8 | | | ｷｯﾄｾｯﾃｲﾅｼ | 02.11-04.8 | | DISC | MP-141 | CPS-292 | 02.11-04.8 | | DISC | SP-120 | | 02.11-04.8 | (R)<br>(L) | (R-1)<br>(L-1)<br>(R-2)BH-T926<br>(L-2)BH-T927 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | CBA－TRN210<br>CBA－TRN215(4WD) | 04.8-09.8 | | | ｷｯﾄｾｯﾃｲﾅｼ | 04.8-05.9<br>05.10-09.8 | | DISC<br>DISC | MP-141<br>SP-119A | CPS-292<br>CPS-292 | 04.8-09.8 | | DISC | SP-120 | | 04.8-09.8 | (R)<br>(L) | (R-1)<br>(L-1)<br>(R-2)BH-T926<br>(L-2)BH-T927 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (3400) | TA－VZN210W<br>TA－VZN215W(4WD) | 02.11-05.8 | | | ｷｯﾄｾｯﾃｲﾅｼ | 02.11-05.8 | | DISC | MP-141 | CPS-292 | 02.11-05.8 | | DISC | SP-120 | | 02.11-05.8 | (R)<br>(L) | (R-1)<br>(L-1)<br>(R-2)BH-T926<br>(L-2)BH-T927 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (3000ディーゼル) | KN－KDN215W(4WD) | 02.11-05.8 | | | ｷｯﾄｾｯﾃｲﾅｼ | 02.11-05.8 | | DISC | MP-141 | CPS-292 | 02.11-05.8 | | DISC | SP-120 | | 02.11-05.8 | (R)<br>(L) | (R-1)<br>(L-1)<br>(R-2)BH-T926<br>(L-2)BH-T927 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (4000) | CBA－GRN215 | 05.8-09.8 | | | ｷｯﾄｾｯﾃｲﾅｼ | 05.8-05.9<br>05.10-09.8 | | DISC<br>DISC | MP-141<br>SP-119A | CPS-292<br>CPS-292 | 05.8-09.8 | | DISC | SP-120 | | 05.8-09.8 | (R)<br>(L) | (R-1)<br>(L-1)<br>(R-2)BH-T926<br>(L-2)BH-T927 | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| STOUT : RK101 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000) | RK101 | 2t | 67.9-75.2<br>75.2-77.8<br>77.8-79.2 | 1<br>1<br>1 | | MK-5515-M<br>MK-4408<br>TK-9387 | 67.9-72.3 | 1 1/8 | (R-1)WC-95510<br>(R-2)WC-95510<br>(L-1)WC-95520<br>(L-2)WC-95520 | WK-056 | CUP | 67.9-72.3 | 1 1/8 | (R-1)WC-45560<br>(R-2)WC-45560<br>(L-1)WC-45570<br>(L-2)WC-45570 | WK-057 | CUP | 67.9-68.4<br>68.4-69.11<br>69.11-72.3<br>72.3-79.2 | BH-31360-A<br>BH-31360<br>BH-02492<br>BH-02576 | BH-31440<br>BH-31440<br>BH-31440<br>BH-31440 | 67.9-77.8<br>77.8-79.2 | 3/4<br>3/4 | | MK-51400<br>MK-4305 | 67.9-79.2 | 15 | CC-70098 | FC-31480-B |
| | | | | | | | 72.3-73.9 | 1 1/8 | (R-1)WC-5175<br>(R-2)WC-5175<br>(L-1)WC-5375<br>(L-2)WC-5375 | WK-056 | CUP | 72.3-73.9 | 1 1/8 | (R-1)WC-5555<br>(R-2)WC-5656<br>(L-1)WC-5745<br>(L-2)WC-5845 | WK-057 | CUP | | | | | | | | | | | |
| | | | | | | | 73.9-79.2 | 1 1/8 | (R-1)WC-5175<br>(R-2)WC-5175<br>(L-1)WC-5375<br>(L-2)WC-5375 | WK-406 | CUP | 73.9-77.3 | 1 1/8 | (R-1)WC-5555<br>(R-2)WC-5656<br>(L-1)WC-5745<br>(L-2)WC-5845 | WK-409 | CUP | | | | | | | | | | | |
| | | | | | | | | | | | | 77.3-79.2 | 1 1/8 | (R-1)WC-55011<br>(R-2)WC-56011<br>(L-1)WC-57011<br>(L-2)WC-58011 | WK-409 | CUP | | | | | | | | | | |
| | | 1．75t<br>Wキャブ | 67.9-75.2<br>75.2-77.8<br>77.8-79.2 | 1<br>1<br>1 | | MK-5515-M<br>MK-4408<br>TK-9387 | 67.9-72.3 | 1 1/8 | (R-1)WC-95510<br>(R-2)WC-95510<br>(L-1)WC-95520<br>(L-2)WC-95520 | WK-056 | CUP | 67.9-72.3 | 1 1/8 | (R-1)WC-45560<br>(R-2)WC-45560<br>(L-1)WC-45570<br>(L-2)WC-45570 | WK-057 | CUP | 67.9-68.4<br>68.4-69.11<br>69.11-72.3<br>72.3-79.2 | BH-31360-A<br>BH-31360<br>BH-02492<br>BH-02576 | BH-31440<br>BH-31440<br>BH-31440<br>BH-31440 | 67.9-77.8<br>77.8-79.2 | 3/4<br>3/4 | | MK-51400<br>MK-4305 | 67.9-79.2 | 15 | CC-70098 | FC-31480-B |
| | | | | | | | 72.3-73.9 | 1 1/8 | (R-1)WC-5175<br>(R-2)WC-5175<br>(L-1)WC-5375<br>(L-2)WC-5375 | WK-056 | CUP | 72.3-73.9 | 1 1/8 | (R-1)WC-5585<br>(R-2)WC-5615<br>(L-1)WC-5715<br>(L-2)WC-5815 | WK-057 | CUP | | | | | | | | | | | |
| | | | | | | | 73.9-79.2 | 1 1/8 | (R-1)WC-5175<br>(R-2)WC-5175<br>(L-1)WC-5375<br>(L-2)WC-5375 | WK-406 | CUP | 73.9-79.2 | 1 1/8 | (R-1)WC-5585<br>(R-2)WC-5615<br>(L-1)WC-5715<br>(L-2)WC-5815 | WK-409 | CUP | | | | | | | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| STOUT : RK110, 111 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000) | J－RK110 | 1．75t Wキャブ | 79.3-82.1 | 1 1/16 | | TK-9400 | 79.3-82.1 | 1 1/8 | (R-1)WC-51018<br>(R-2)WC-52018<br>(L-1)WC-53018<br>(L-2)WC-54018 | WK-500 | CUP | 79.3-82.1 | 1 1/4 | (R-1)WC-55006<br>(R-2)WC-56006<br>(L-1)WC-57006<br>(L-2)WC-58006 | WK-408 | CUP | 79.3-82.1 | BH-31365 | BH-91000 | 79.3-82.1 | 5/8 | MC-10079 | MK-4300 | 79.3-81.5<br>81.5-82.1 | 3/4<br>3/4 | CC-70096<br>CC-70096 | CK-3108<br>CK-3124 |
| | | 2t | 79.3-82.1 | 1 1/16 | | TK-9400 | 79.3-82.1 | 1 1/8 | (R-1)WC-51018<br>(R-2)WC-52018<br>(L-1)WC-53018<br>(L-2)WC-54018 | WK-500 | CUP | 79.3-82.1 | 1 1/4 | (R-1)WC-55009<br>(R-2)WC-56009<br>(L-1)WC-57009<br>(L-2)WC-58009 | WK-408 | CUP | 79.3-82.1 | BH-31365 | BH-02388 | 79.3-82.1 | 5/8 | MC-10079 | MK-4300 | 79.3-81.5<br>81.5-82.1 | 3/4<br>3/4 | CC-70096<br>CC-70096 | CK-3108<br>CK-3124 |
| | M－RK111 | 1．75t Wキャブ | 82.1-85.4<br>85.4-85.7 | 1 1/16<br>1 1/16 | | TK-9400<br>TK-T014 | 82.1-85.7 | 1 1/8 | (R-1)WC-51018<br>(R-2)WC-52018<br>(L-1)WC-53018<br>(L-2)WC-54018 | WK-500 | CUP | 82.1-85.7 | 1 1/4 | (R-1)WC-55006<br>(R-2)WC-56006<br>(L-1)WC-57006<br>(L-2)WC-58006 | WK-408 | CUP | 82.1-84.6<br>84.6-85.7 | BH-31365<br>BH-31365 | BH-91000<br>BH-31424 | 82.1-85.7 | 5/8 | MC-10079 | MK-4300 | 82.1-85.7 | 3/4 | CC-70096 | CK-3124 |
| | | 2t | 82.1-85.4<br>85.4-86.3 | 1 1/16<br>1 1/16 | | TK-9400<br>TK-T014 | 82.1-86.3 | 1 1/8 | (R-1)WC-51018<br>(R-2)WC-52018<br>(L-1)WC-53018<br>(L-2)WC-54018 | WK-500 | CUP | 82.1-86.3 | 1 1/4 | (R-1)WC-55009<br>(R-2)WC-56009<br>(L-1)WC-57009<br>(L-2)WC-58009 | WK-408 | CUP | 82.1-84.6<br>84.6-86.3 | BH-31365<br>BH-31365 | BH-02430<br>BH-02464 | 82.1-86.3 | 5/8 | MC-10079 | MK-4300 | 82.1-86.3 | 3/4 | CC-70096 | CK-3124 |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| QUICK DELIVERY : (85.8-95.5) | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | <D仕様> | | | | | | | | | | | | | | | | | | | | |
| N－LH80VH | | 85.8-95.5 | 15/16 | TD-T790 | TK-T012 | 85.8-95.5 | 60.3 | DISC | MP-10 | CPM-10 | 85.8-95.5 | 3/4 | (R) | WK-590 | CUP | 85.8-95.5 | BH-02477 | BH-02342 | 85.8-86.9 | 5/8 | | MK-4329 | 85.8-88.8 | 13/16 | CC-70133 | CK-3144 |
| <U－は88．8～> | | | | | | <N仕様> | | | | | | | (L) | | | | | | 86.9-95.5 | 5/8 | | MK-4337 | 88.8-94.5 | 13/16 | CC-70133 | CK-3144 |
| (2L) | | | | | | 85.8-88.8 | 60.3 | DISC | MP-10 | CPM-10 | | | | | | | | | | | | | 94.5-95.5 | 13/16 | | CK-T201 |
| | | | | | | 88.8-95.5 | 60.3 | DISC | MP-10 | CPM-10 | | | | | | | | | | | | | | | | |
| N－LH85(4WD) | | 87.11-95.5 | 1 | | TK-T010 | 87.11-95.5 | 66.6 | DISC | MP-27 | CPM-86 | 87.11-95.5 | 3/4 | (R) | WK-590 | CUP | 87.11-95.5 | BH-02522 | BH-94008 | 87.11-95.5 | 5/8 | | MK-4337 | 87.11-90.6 | 13/16 | CC-70177 | CK-3144 |
| <U－は89．10～> | | | | | | | | | | | | | (L) | | | | | | | | | | 90.6-93.4 | 13/16 | CC-70177 | CK-3144 |
| (2L) | | | | | | | | | | | | | | | | | | | | | | | 93.4-95.5 | 13/16 | | CK-T201 |
| | | | | | | | | | | | | | | | | | | | <ブースター無> | | | | | | | |
| N－BU60VH | ドラム車 | 86.1-95.5 | 1 1/16 | | TK-T028 | 86.1-93.3 | 1 1/8 | | WK-635 | CUP | 86.1-87.8 | 1 | | WK-637 | CUP | 86.1-91.2 | BH-T527 | BH-40012 | 86.1-88.5 | 5/8 | | MK-4329 | 86.1-88.8 | 13/16 | CC-70178 | CK-3144 |
| <U－は90．10～> | | | | | | 93.3-95.5 | 1 1/8 | | WK-814 | CUP | 87.8-93.3 | 1 1/8 | | WK-724 | CUP | 91.2-95.5 | (R) | BH-40012 | 88.5-90.8 | 5/8 | | MK-4354 | 88.8-94.8 | 3/4 | CC-70185 | CK-T218 |
| (B) | | | | | | <オートアジャスター付> | | | | | 93.3-95.5 | 1 1/8 | | WK-816 | CUP | | (L) | | <ブースター付> | | | | 94.8-95.5 | 3/4 | | CK-T218 |
| | | | | | | 86.1-93.3 | 1 1/8 | | WK-636 | CUP | <オートアジャスター付> | | | | | | | | 86.1-88.5 | 5/8 | | MK-4320 | | | | |
| | | | | | | 93.3-95.5 | 1 1/8 | | WK-815 | CUP | 86.1-87.8 | 1 | | WK-640 | CUP | | | | 88.5-95.5 | 5/8 | | MK-T200 | | | | |
| | | | | | | | | | | | 87.8-93.3 | 1 1/8 | | WK-715 | CUP | | | | | | | | | | | | |
| | | | | | | | | | | | 93.3-95.5 | 1 1/8 | | WK-835 | CUP | | | | | | | | | | | | |
| | ディスク車 | 90.8-95.5 | 1 1/16 | | TK-T028 | 90.8-95.5 | 66.6 | DISC | MP-17 | | 90.8-93.3 | 1 1/8 | | WK-715 | CUP | 90.8-92.10 | (1)BH-T681 | BH-40012 | 90.8-95.5 | 5/8 | | MK-T200 | 90.8-94.8 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | | | | | 93.3-95.5 | 1 1/8 | | WK-835 | CUP | | (2)BH-02516 | | | | | | 94.8-95.5 | 3/4 | | CK-T218 |
| | | | | | | | | | | | | | | | | 92.10-95.5 | (1) | BH-40012 | | | | | | | | |
| | | | | | | | | | | | | | | | | | (2)BH-02516 | | | | | | | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| QUICK DELIVERY : (95.5-01.8) | | | | | | | | | | | | | | | | | | | | | | | | | |
| KC－LH81VH<br>KG－LH82K<br>＜KG－は99．5～＞<br>(3L･5L) | 95.5-01.8 | 15/16 | | TK-T012 | 95.5-01.8 | 60.3 | DISC | MP-10 | | 95.5-01.8 | 3/4 | (R)<br>(L) | WK-590 | CUP | 95.5-99.5<br>99.5-01.8 | BH-02477<br>BH-T934 | BH-02342<br>BH-02342 | 95.5-01.8 | 5/8 | | MK-4337 | 95.5-01.8 | 13/16 | CC-70133 | CK-T201 |
| KC－LY151(4WD)<br>KG－LY152(4WD)<br>＜KG－は99．5～＞<br>(3L･5L) | 95.5-01.8 | 1 | | TK-T010 | 95.5-01.8 | 66.6 | DISC | MP-27 | | 95.5-01.8 | 3/4 | (R)<br>(L) | WK-590 | CUP | 95.5-99.5<br>99.5-01.8 | BH-02522<br>BH-T935 | BH-94008<br>BH-94008 | 95.5-01.8 | 5/8 | | MK-4337 | 95.5-01.8 | 13/16 | CC-70177 | CK-T201 |
| KC－BU68VH<br>(3B) | 95.5-99.8 | 1 1/16 | | TK-T373 | 95.5-99.8 | 66.6 | DISC | MP-17 | | 95.5-99.8 | 1 1/8 | (R-1)WC-T676<br>(L-1)<br>(R-2)<br>(L-2) | WK-835 | CUP | 95.5-99.3<br><br>99.3-99.8 | (1)BH-02576<br>(2)BH-T719<br>(1)BH-T888<br>(2)BH-T719 | BH-40012<br><br>BH-T938 | 95.5-99.8 | 5/8 | MC-T473 | MK-T206 | 95.5-99.8 | 3/4 | CC-70185 | CK-T218 |
| GB－RZU68VH<br>(3RZ－FP) | 96.10-99.8 | 1 1/16 | | TK-T373 | 96.10-99.8 | 66.6 | DISC | MP-17 | | 96.10-99.8 | 1 1/8 | (R-1)WC-T676<br>(L-1)<br>(R-2)<br>(L-2) | WK-835 | CUP | 96.10-99.3<br><br>99.3-99.8 | (1)BH-02576<br>(2)BH-T719<br>(1)BH-T888<br>(2)BH-T719 | BH-40012<br><br>BH-T938 | 95.5-99.8 | 5/8 | MC-T473 | MK-T206 | 95.5-99.8 | 7/8 | CC-T387 | CK-3122 |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| QUICK DELIVERY, URBAN SUPPORTER : (01.8-) | | | | | | | | | | | | | | | | | | | | | | | | | |
| KK－LY228K<br>KG･KK－LY270(4WD)<br>(5L) | 01.8-04.7 | | | | 01.8-04.7 | | DISC | MP-27 | | 01.8-04.7 | 1 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-1025 | CUP | 01.8-04.7 | (R)BH-T853<br>(L)BH-T854 | BH-T712 | 01.8-04.7 | 5/8 | | | 01.8-04.7 | 13/16 | CC-70177 | CK-T201 |
| KK－BU280K･281K<br>GE－BU280K<br>PB－RZU280K<br>(4B)<br>(3RZ－FPE) | 99.8-04.6<br><ｱﾝﾁｽｷｯﾄﾞ付><br>99.8-04.8 | 1 3/16 | TD-T928 | TK-T448 | 99.8-04.6 | | DISC | MP-83 | CPM-81 | 99.8-04.6 | 1 1/8 | (R-1)WC-T791<br>(R-2)WC-T792<br>(L-1)WC-T793<br>(L-2)WC-T794 | WK-835 | CUP | 99.8-04.6<br><ｱﾝﾁｽｷｯﾄﾞ付><br>99.8-04.6 | (R)BH-T891<br>(L)BH-T892<br>(R)BH-T891<br>(L)BH-T892 | BH-T820<br>(R)BH-T933<br>(L)BH-T820 | 99.8-03.8<br>03.8-04.6 | 5/8<br>5/8 | MC-T473<br>MC-T369 | MK-T206<br>MK-T206 | 99.8-04.6<br><LPG車><br>00.1-02.10<br>02.10-04.6 | 3/4<br><br>7/8<br>7/8 | CC-T383<br><br>CC-T387<br>CC-T387 | CK-T218<br><br>CK-3122<br>CK-T229 |
| PB－XZU280K･281K<br>(3RZ－FPE)<br>(N04C) | 04.6-06.10<br><ｱﾝﾁｽｷｯﾄﾞ付><br>04.6-06.10 | 1 3/16 | TD-T928 | TK-T448 | 04.6-06.10 | | DISC | MP-83 | CPM-81 | 04.6-06.10 | 1 1/8 | (R-1)WC-T791<br>(R-2)WC-T792<br>(L-1)WC-T793<br>(L-2)WC-T794 | WK-835 | CUP | 04.6-06.10<br><ｱﾝﾁｽｷｯﾄﾞ付><br>04.6-06.10 | (R)BH-T891<br>(L)BH-T892<br>(R)BH-T891<br>(L)BH-T892 | BH-T820<br>(R)BH-T933<br>(L)BH-T820 | 04.6-05.3<br>05.4-06.10 | | | | 04.6-06.10<br><ｺﾓﾝﾚｰﾙ式燃料噴射装置><br>04.6-06.10 | 7/8<br><br>3/4 | CC-T387<br><br>CC-T385 | CK-T229<br><br>CK-T216 |
| SKG－XZU282K<br>(N04C) | 12.3- | 1 3/16 | | TK-T448 | 12.3- | | DISC | MP-83 | CPM-81 | 12.3- | 1 1/8 | (R-1)WC-T791<br>(R-2)WC-T792<br>(L-1)WC-T793<br>(L-2)WC-T794 | WK-835 | CUP | 12.3- | (R)BH-T891<br>(L)BH-T892 | (R)BH-T933<br>(L)BH-T820 | 12.3- | | | | 12.3- | 3/4 | CC-T385 | CK-T216 |
| BCG･BJG－XKU280K<br>(N04C－TN) | 06.10- | 1 3/16 | | TK-T448 | 06.10- | | DISC | MP-83 | CPM-81 | 06.10- | 1 1/8 | (R-1)WC-T791<br>(R-2)WC-T792<br>(L-1)WC-T793<br>(L-2)WC-T794 | WK-835 | CUP | 06.10- | (R)BH-T891<br>(L)BH-T892 | (R)BH-T933<br>(L)BH-T820 | 06.10- | | | | 06.10- | 3/4 | CC-T385 | CK-T216 |

| Models | TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TOYOACE : 10 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1350) | PY10 | 全車 | 71.9-73.9<br>73.9-79.2 | 1<br>1 1/8 | | MK-4404<br>TK-9334 | 71.9-73.9 | 1 1/4 | (R-1)WC-5185<br>(R-2)WC-5185<br>(L-1)WC-5385<br>(L-2)WC-5385 | WK-058 | CUP | 71.9-73.9 | 1 1/8 | (R-1)WC-5585<br>(R-2)WC-5615<br>(L-1)WC-5715<br>(L-2)WC-5815 | WK-057 | CUP | 71.9-73.12<br>73.12-79.2 | BH-31304<br>BH-T871 | BH-31400<br>BH-31400 | 71.9-79.2 | 3/4 | MC-10069 | MK-41400 | 71.9-79.2 | 15 | CC-70098 | FC-31480-B |
| | | | | | | | 73.9-79.2 | 1 1/4 | (R-1)WC-5185<br>(R-2)WC-5185<br>(L-1)WC-5385<br>(L-2)WC-5385 | WK-407 | CUP | 73.9-79.2 | 1 1/8 | (R-1)WC-5585<br>(R-2)WC-5615<br>(L-1)WC-5715<br>(L-2)WC-5815 | WK-409 | CUP | | | | | | | | | | | |
| (1600) | RY10 | 全車 | 71.9-73.9<br>71.9-73.9<br>73.9-79.2 | 1<br>1<br>1 1/8 | *56<br>*33 | MK-4404<br>MK-4405<br>TK-9334 | 71.9-73.9 | 1 1/4 | (R-1)WC-5185<br>(R-2)WC-5185<br>(L-1)WC-5385<br>(L-2)WC-5385 | WK-058 | CUP | 71.9-73.9 | 1 1/8 | (R-1)WC-5585<br>(R-2)WC-5615<br>(L-1)WC-5715<br>(L-2)WC-5815 | WK-057 | CUP | 71.9-73.12<br>73.12-79.2 | BH-31304<br>BH-T871 | BH-31400<br>BH-31400 | 71.9-79.2 | 3/4 | MC-10069 | MK-41400 | 71.9-79.2 | 15 | CC-70098 | FC-31480-B |
| | | | | | | | 73.9-79.2 | 1 1/4 | (R-1)WC-5185<br>(R-2)WC-5185<br>(L-1)WC-5385<br>(L-2)WC-5385 | WK-407 | CUP | 73.9-79.2 | 1 1/8 | (R-1)WC-5585<br>(R-2)WC-5615<br>(L-1)WC-5715<br>(L-2)WC-5815 | WK-409 | CUP | | | | | | | | | | | |
| | RY12 | 全車 | 71.9-73.9<br>71.9-73.9<br>73.9-79.2 | 1<br>1<br>1 1/8 | *56<br>*33 | MK-4404<br>MK-4405<br>TK-9334 | 71.9-73.9 | 1 1/4 | (R-1)WC-5185<br>(R-2)WC-5185<br>(L-1)WC-5385<br>(L-2)WC-5385 | WK-058 | CUP | 71.9-73.9 | 1 1/8 | (R-1)WC-5585<br>(R-2)WC-5615<br>(L-1)WC-5715<br>(L-2)WC-5815 | WK-057 | CUP | 71.9-73.12<br>73.12-79.2 | BH-31304<br>BH-T871 | BH-31400<br>BH-31400 | 71.9-79.2 | 3/4 | MC-10069 | MK-41400 | 71.9-79.2 | 15 | CC-70098 | FC-31480-B |
| | | | | | | | 73.9-79.2 | 1 1/4 | (R-1)WC-5185<br>(R-2)WC-5185<br>(L-1)WC-5385<br>(L-2)WC-5385 | WK-407 | CUP | 73.9-79.2 | 1 1/4 | (R-1)WC-55006<br>(R-2)WC-56006<br>(L-1)WC-57006<br>(L-2)WC-58006 | WK-408 | CUP | | | | | | | | | | | |
| | (1600) RY14 | | 72.7-73.9<br>72.7-73.9<br>73.9-79.2 | 1<br>1<br>1 1/8 | *33 | MK-4404<br>MK-4405<br>TK-9322 | 72.7-73.9 | 1 1/4 | (R-1)WC-5185<br>(R-2)WC-5185<br>(L-1)WC-5385<br>(L-2)WC-5385 | WK-058 | CUP | 72.7-73.9 | 1 1/8 | (R-1)WC-5585<br>(R-2)WC-5615<br>(L-1)WC-5715<br>(L-2)WC-5815 | WK-057 | CUP | 72.7-73.9<br>73.9-73.12<br>73.12-79.2 | BH-31304<br>BH-31304<br>BH-T871 | BH-31440<br>BH-44212<br>BH-44212 | 72.7-79.2 | 3/4 | MC-10069 | MK-41400 | 72.7-79.2 | 15 | CC-70098 | FC-31480-B |
| | | | | | | | 73.9-79.2 | 1 1/4 | (R-1)WC-5185<br>(R-2)WC-5185<br>(L-1)WC-5385<br>(L-2)WC-5385 | WK-407 | CUP | 73.9-79.2<br><LSPV付><br>73.9-79.2 | 1 1/8<br><br>1 1/4 | (R-1)WC-5585<br>(R-2)WC-5615<br>(L-1)WC-5715<br>(L-2)WC-5815<br>(R-1)WC-55006<br>(R-2)WC-56006<br>(L-1)WC-57006<br>(L-2)WC-58006 | WK-409<br><br>WK-408 | CUP<br><br>CUP | | | | | | | | | | | |
| | | ジャストロー | 77.8-79.2 | 1 1/8 | | TK-9322 | 77.8-79.2 | 1 1/4 | (R-1)WC-5185<br>(R-2)WC-5185<br>(L-1)WC-5385<br>(L-2)WC-5385 | WK-407 | CUP | 77.8-79.2 | 1 | (R-1)WC-55007<br>(R-2)WC-56007<br>(L-1)WC-57007<br>(L-2)WC-58007 | WK-411 | CUP | 77.8-79.2 | BH-T871 | BH-48312 | 77.8-79.2 | 3/4 | MC-10069 | MK-41400 | 77.8-79.2 | 15 | CC-70098 | FC-31480-B |
| (2500ディーゼル)<br>JY16 | | 2t | 72.7-79.2 | 1 1/8 | | TK-9322 | 72.7-74.10 | 1 1/4 | (R-1)WC-5146<br>(R-2)WC-5237<br>(L-1)WC-5346<br>(L-2)WC-5436 | WK-100 | CUP | 72.7-74.10 | 1 1/8 | (R-1)WC-55004<br>(R-2)WC-56004<br>(L-1)WC-57004<br>(L-2)WC-58004 | | CUP | 72.7-73.9<br>73.9-73.12<br>73.12-79.2 | BH-31304<br>BH-31304<br>BH-T871 | BH-31440<br>BH-44212<br>BH-44212 | 72.7-79.2 | 3/4 | MC-10069 | MK-41400 | 72.7-79.2 | 3/4 | CC-70099 | CK-41480 |
| | | | | | | | 74.10-77.8 | 1 1/4 | (R-1)WC-51009<br>(R-2)WC-52009<br>(L-1)WC-53009<br>(L-2)WC-54009 | WK-410 | CUP | 74.10-77.8 | 1 1/8 | (R-1)WC-55004<br>(R-2)WC-56004<br>(L-1)WC-57004<br>(L-2)WC-58004 | WK-413 | CUP | | | | | | | | | | | |
| | | | | | | | 77.8-79.2 | 1 1/4 | (R-1)WC-5185<br>(R-2)WC-52015<br>(L-1)WC-5385<br>(L-2)WC-54015 | WK-407 | CUP | 77.8-79.2 | 1 1/8 | (R-1)WC-55008<br>(R-2)WC-56008<br>(L-1)WC-57008<br>(L-2)WC-58008 | WK-409 | CUP | | | | | | | | | | | |
| | | | | | | | | | | | | <LSPV付><br>73.9-74.10 | <br>1 1/4 | (R-1)WC-5536<br>(R-2)WC-5626<br>(L-1)WC-5726<br>(L-2)WC-5826 | WK-101 | CUP | | | | | | | | | |
| | | | | | | | | | | | | 74.10-77.8 | 1 1/4 | (R-1)WC-55005<br>(R-2)WC-56005<br>(L-1)WC-57005<br>(L-2)WC-58005 | WK-412 | CUP | | | | | | | | | |
| | | | | | | | | | | | | 77.8-79.2 | 1 1/4 | (R-1)WC-55009<br>(R-2)WC-56009<br>(L-1)WC-57009<br>(L-2)WC-58009 | WK-408 | CUP | | | | | | | | | |
| | | 1．5t･1．25t | 75.1-79.2 | 1 1/8 | | TK-9322 | 75.1-79.2 | 1 1/4 | (R-1)WC-5185<br>(R-2)WC-5185<br>(L-1)WC-5385<br>(L-2)WC-5385 | WK-407 | CUP | 75.1-79.2<br><LSPV付><br>75.1-79.2 | 1 1/8<br><br>1 1/4 | (R-1)WC-5585<br>(R-2)WC-5615<br>(L-1)WC-5715<br>(L-2)WC-5815<br>(R-1)WC-55006<br>(R-2)WC-56006<br>(L-1)WC-57006<br>(L-2)WC-58006 | WK-409<br><br>WK-408 | CUP<br><br>CUP | 75.1-79.2 | BH-T871 | BH-44212 | 75.1-79.2 | 3/4 | MC-10069 | MK-41400 | 75.1-79.2 | 3/4 | CC-70099 | CK-41480 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TOYOACE : 20, 30 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1600) | J－RY20<br>M－RY21 | Sタイヤ | 79.3-85.7 | 1 1/16 | | TK-9396 | 79.3-85.7 | 1 1/4 | | WK-465 | CUP | 79.3-85.7 | 1 1/8 | (R-1)WC-55008<br>(R-2)WC-56008<br>(L-1)WC-57008<br>(L-2)WC-58008 | WK-409 | CUP | 79.3-79.5<br>79.5-82.1<br>82.1-85.7 | BH-31365<br>BH-31365<br>BH-31365 | BH-31424<br>BH-94001<br>BH-94006 | 79.3-85.7 | 5/8 | MC-10080 | MK-4300 | 79.3-81.5<br>81.5-85.7 | 3/4<br>3/4 | CC-70096<br>CC-70096 | CK-3108<br>CK-3124 |
| (2000) | J－RY31<br>M－RY32 | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1600) | J－RY20・RY20V<br>M－RY21・RY21V | Wタイヤ | 79.3-85.7 | 1 1/16 | | TK-9396 | 79.3-85.7 | 1 1/4 | | WK-465 | CUP | 79.3-85.7 | 1 | | WK-411 | CUP | 79.3-85.7 | BH-31365 | BH-02342 | 79.3-85.7 | 5/8 | MC-10080 | MK-4300 | 79.3-81.5<br>81.5-85.7 | 3/4<br>3/4 | CC-70096<br>CC-70096 | CK-3108<br>CK-3124 |
| (2000) | J－RY31・RY31V<br>M－RY32・RY32V | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2200ディーゼル) | K－LY20・30<br>N－LY20<br><N－は83. 8～> | Sタイヤ | 79.3-85.7 | 1 1/16 | | TK-9396 | 79.3-85.7 | 1 1/4 | | WK-465 | CUP | 79.3-85.7 | 1 1/8 | (R-1)WC-55008<br>(R-2)WC-56008<br>(L-1)WC-57008<br>(L-2)WC-58008 | WK-409 | CUP | 79.3-79.5<br>79.5-82.1<br>82.1-85.7 | BH-31365<br>BH-31365<br>BH-31365 | BH-31424<br>BH-94001<br>BH-94006 | 79.3-85.7 | 5/8 | MC-10080 | MK-4300 | 79.3-81.5<br>81.5-85.7 | 3/4<br>3/4 | CC-70091<br>CC-70091 | CK-3108<br>CK-3124 |
| (2500ディーゼル) | K－LY21・31 | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2200ディーゼル) | K－LY20・30<br>K－LY20V・30V<br>N－LY20<br><N－は83. 8～> | Wタイヤ | 79.3-85.7 | 1 1/16 | | TK-9396 | 79.3-85.7 | 1 1/4 | | WK-465 | CUP | 79.3-85.7 | 1 | | WK-411 | CUP | 79.3-85.7 | BH-31365 | BH-02342 | 79.3-85.7 | 5/8 | MC-10080 | MK-4300 | 79.3-81.5<br>81.5-85.7 | 3/4<br>3/4 | CC-70091<br>CC-70091 | CK-3108<br>CK-3124 |
| (2500ディーゼル) | N－LY21・31<br>N－LY21V・31V | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2500ディーゼル) | K－JY30 | Sタイヤ | 79.3-83.8 | 1 1/16 | | TK-9396 | 79.3-83.8 | 1 1/4 | | WK-465 | CUP | 79.3-83.8 | 1 1/8 | (R-1)WC-55008<br>(R-2)WC-56008<br>(L-1)WC-57008<br>(L-2)WC-58008 | WK-409 | CUP | 79.3-82.1<br>82.1-83.8 | BH-02492<br>BH-31365 | BH-02371<br>BH-02371 | 79.3-83.8 | 5/8 | MC-10080 | MK-4300 | 79.3-81.5<br>81.5-83.8 | 3/4<br>3/4 | CC-70090<br>CC-70090 | CK-3108<br>CK-3124 |
| | | Wタイヤ | 79.3-83.8 | 1 1/16 | | TK-9396 | 79.3-83.8 | 1 1/4 | | WK-465 | CUP | 79.3-83.8 | 1 1/8 | | WK-466 | CUP | 79.3-82.1<br>82.1-83.8 | BH-02492<br>BH-31365 | BH-02373<br>BH-02373 | 79.3-83.8 | 5/8 | MC-10080 | MK-4300 | 79.3-81.5<br>81.5-83.8 | 3/4<br>3/4 | CC-70090<br>CC-70090 | CK-3108<br>CK-3124 |
| | K－JY30D(ダンプ) | Wタイヤ | 80.4-83.8 | 1 1/16 | | TK-9396 | 80.4-80.9<br>80.9-83.8 | 1 1/4<br>1 1/4 | | WK-410<br>WK-544 | CUP<br>CUP | 80.4-83.8 | 1 1/8 | (R-1)WC-55012<br>(R-2)WC-56012<br>(L-1)WC-57012<br>(L-2)WC-58012 | WK-413 | CUP | 80.4-82.1<br>82.1-83.8 | BH-02492<br>BH-31365 | BH-02373<br>BH-02373 | 80.4-83.8 | 5/8 | MC-10080 | MK-4300 | 80.4-81.5<br>81.5-83.8 | 3/4<br>3/4 | CC-70090<br>CC-70090 | CK-3108<br>CK-3124 |
| (3000ディーゼル) | K－BY30(トラック) | Wタイヤ | 80.9-83.8 | 1 1/16 | | TK-9396 | 80.9-83.8 | 1 1/4 | | WK-544 | CUP | 80.9-83.8 | 1 1/8 | (R-1)WC-55012<br>(R-2)WC-56012<br>(L-1)WC-57012<br>(L-2)WC-58012 | WK-413 | CUP | 80.9-82.1<br>82.1-83.8 | BH-02492<br>BH-31365 | BH-02416<br>BH-02373 | 80.9-83.8 | 5/8 | MC-10080 | MK-4300 | 80.9-83.8 | 3/4 | CC-70158 | CK-3124 |
| | | ジャストロー | 82.1-83.8 | 1 1/16 | | TK-9396 | 82.1-83.8 | 1 1/4 | | WK-465 | CUP | 82.1-83.8 | 1 1/8 | | WK-466 | CUP | 82.1-83.8 | BH-31365 | BH-02373 | 82.1-83.8 | 5/8 | MC-10080 | MK-4300 | 82.1-83.8 | 3/4 | CC-70158 | CK-3124 |
| | K－BY30V(パネルバン) | Wタイヤ | 80.9-83.8 | 1 1/16 | | TK-9396 | 80.9-83.8 | 1 1/4 | | WK-544 | CUP | 80.9-83.8 | 1 1/8 | (R-1)WC-55012<br>(R-2)WC-56012<br>(L-1)WC-57012<br>(L-2)WC-58012 | WK-413 | CUP | 80.9-82.1<br>82.1-83.8 | BH-02492<br>BH-31365 | BH-02373<br>BH-02373 | 80.9-83.8 | 5/8 | MC-10080 | MK-4300 | 80.9-83.8 | 3/4 | CC-70158 | CK-3124 |
| | N－BY31(トラック) | Sタイヤ | 83.8-85.7 | 1 1/16 | | TK-9396 | 83.8-85.7 | 1 1/4 | | WK-465 | CUP | 83.8-85.7 | 1 1/8 | (R-1)WC-55008<br>(R-2)WC-56008<br>(L-1)WC-57008<br>(L-2)WC-58008 | WK-409 | CUP | 83.8-85.7 | BH-31365 | BH-02371 | 83.8-85.7 | 5/8 | MC-10080 | MK-4300 | 83.8-85.7 | 3/4 | CC-70158 | CK-3124 |
| | | Wタイヤ | 83.8-85.7 | 1 1/16 | | TK-9396 | 83.8-85.7 | 1 1/4 | | WK-544 | CUP | 83.8-85.7 | 1 1/8 | (R-1)WC-55012<br>(R-2)WC-56012<br>(L-1)WC-57012<br>(L-2)WC-58012 | WK-413 | CUP | 83.8-85.7 | BH-31365 | BH-02373 | 83.8-85.7 | 5/8 | MC-10080 | MK-4300 | 83.8-85.7 | 3/4 | CC-70158 | CK-3124 |
| | | ジャストロー | 83.8-85.7 | 1 1/16 | | TK-9396 | 83.8-85.7 | 1 1/4 | | WK-465 | CUP | 83.8-85.7 | 1 1/8 | | WK-466 | CUP | 83.8-85.7 | BH-31365 | BH-02373 | 83.8-85.7 | 5/8 | MC-10080 | MK-4300 | 83.8-85.7 | 3/4 | CC-70158 | CK-3124 |
| | N－BY31D(ダンプ)<br>N－BY31V(パネルバン) | Wタイヤ | 83.8-85.7 | 1 1/16 | | TK-9396 | 83.8-85.7 | 1 1/4 | | WK-544 | CUP | 83.8-85.7 | 1 1/8 | (R-1)WC-55012<br>(R-2)WC-56012<br>(L-1)WC-57012<br>(L-2)WC-58012 | WK-413 | CUP | 83.8-85.7 | BH-31365 | BH-02373 | 83.8-85.7 | 5/8 | MC-10080 | MK-4300 | 83.8-85.7 | 3/4 | CC-70158 | CK-3124 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| DYNA, TOYOACE : YY, LY | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1600) | M－YY50 | 低床・高床（Sタイヤ） | 85.8-87.8 | 1 | TD-T442 | TK-T009 | 85.8-87.8 | 66.6 | DISC | MP-17 | | 85.8-87.8 | 13/16 | (R)WC-50051<br>(L)WC-50051 | WK-106 | CUP | 85.8-87.8 | BH-31404 | BH-T507 | 85.8-87.8 | 5/8 | | MK-4328 | 85.8-87.8 | 13/16 | CC-70145 | CK-3144 |
| | | ジャストロー（Wタイヤ） | 85.8-87.8 | 1 | TD-T442 | TK-T009 | 85.8-87.8 | 66.6 | DISC | MP-17 | | 85.8-87.8 | 3/4 | (R)<br>(L) | WK-590 | CUP | 85.8-87.8 | BH-31404 | BH-T507 | 85.8-87.8 | 5/8 | | MK-4328 | 85.8-87.8 | 13/16 | CC-70145 | CK-3144 |
| | | ダブルキャブ（Sタイヤ） | 85.8-87.8 | 1 | TD-T442 | TK-T009 | 85.8-87.8 | 66.6 | DISC | MP-17 | | 85.8-87.8 | 15/16 | | WK-681 | CUP | 85.8-87.8 | BH-31404 | BH-T507 | 85.8-87.8 | 5/8 | | MK-4328 | 85.8-87.8 | 13/16 | CC-70176 | CK-3144 |
| (1800) | M－YY51<br>T－YY51<br><T－は90．8～> | 低床・高床（Sタイヤ） | 87.8-93.9 | 1 | | TK-T009 | 87.8-93.9 | 66.6 | DISC | MP-17 | | 87.8-93.9 | 13/16 | (R)WC-50051<br>(L)WC-50051 | WK-106 | CUP | 87.8-88.8<br>88.8-90.6<br>90.6-93.9 | BH-31404<br>BH-94005<br>BH-94005 | BH-T507<br>BH-T507<br>BH-T507 | 87.8-88.8<br>88.8-93.9 | 5/8<br>5/8 | MC-T269<br>MC-T445 | MK-4346<br>MK-T236 | 87.8-88.6<br>88.6-93.9 | 13/16<br>13/16 | CC-70145<br>CC-70145 | CK-3144<br>CK-3144 |
| | | ジャストロー（Sタイヤ） | 87.8-93.9 | 1 | | TK-T009 | 87.8-93.9 | 66.6 | DISC | MP-17 | | 87.8-93.9 | 13/16 | (R)WC-50051<br>(L)WC-50051 | WK-106 | CUP | 87.8-93.9 | BH-94008 | BH-94005 | 87.8-88.8<br>88.8-93.9 | 5/8<br>5/8 | MC-T269<br>MC-T445 | MK-4346<br>MK-T236 | 87.8-88.6<br>88.6-93.9 | 13/16<br>13/16 | CC-70145<br>CC-70145 | CK-3144<br>CK-3144 |
| | | ジャストロー（Wタイヤ） | 87.8-93.9 | 1 | | TK-T009 | 87.8-93.9 | 66.6 | DISC | MP-17 | | 87.8-93.9 | 3/4 | (R)<br>(L) | WK-590 | CUP | 87.8-88.8<br>88.8-90.6<br>90.6-93.9 | BH-31404<br>BH-94005<br>BH-94005 | BH-T507<br>BH-T507<br>BH-T507 | 87.8-88.8<br>88.8-93.9 | 5/8<br>5/8 | MC-T269<br>MC-T445 | MK-4346<br>MK-T236 | 87.8-88.6<br>88.6-93.9 | 13/16<br>13/16 | CC-70145<br>CC-70145 | CK-3144<br>CK-3144 |
| | | ダブルキャブ（Sタイヤ） | 87.8-93.9 | 1 | | TK-T009 | 87.8-93.9 | 66.6 | DISC | MP-17 | | 87.8-88.8<br>88.8-93.9 | 15/16<br>13/16 | (R)WC-50051<br>(L)WC-50051 | WK-681<br>WK-106 | CUP<br>CUP | 87.8-88.8<br>88.8-90.6<br>90.6-93.9 | BH-31404<br>BH-94005<br>BH-94005 | BH-T507<br>BH-T507<br>BH-T507 | 87.8-88.8<br>88.8-93.9 | 5/8<br>5/8 | MC-T269<br>MC-T445 | MK-4346<br>MK-T236 | 87.8-88.6<br>88.6-88.8<br>88.8-93.9 | 13/16<br>13/16<br>13/16 | CC-70176<br>CC-70176<br>CC-70145 | CK-3144<br>CK-3144<br>CK-3144 |
| (2000) | M－YY52<br>T－YY52<br>Z－YY52<br><T－は90．8～><br><Z－は93．8～> | 高床（Sタイヤ） | 85.8-95.5 | 1 | TD-T442 | TK-T009 | 85.8-95.5 | 66.6 | DISC | MP-17 | | 85.8-95.5 | 15/16 | | WK-681 | CUP | 85.8-88.8<br>88.8-90.6<br>90.6-95.5 | BH-31404<br>BH-94005<br>BH-94005 | BH-T507<br>BH-T507<br>BH-T507 | 85.8-87.8<br>87.8-88.8<br>88.8-95.5 | 5/8<br>5/8<br>5/8 | MC-T269<br>MC-T445 | MK-4328<br>MK-4346<br>MK-T236 | 85.8-88.6<br>88.6-95.5 | 13/16<br>13/16 | CC-70176<br>CC-70176 | CK-3144<br>CK-3144 |
| | | ジャストロー（Wタイヤ） | 85.8-95.5 | 1 | TD-T442 | TK-T009 | 85.8-95.5 | 66.6 | DISC | MP-17 | | 85.8-95.5 | 15/16 | | WK-897 | CUP | 85.8-88.8<br>88.8-90.6<br>90.6-95.5 | BH-31404<br>BH-94005<br>BH-94005 | BH-T507<br>BH-T507<br>BH-T507 | 85.8-87.8<br>87.8-88.8<br>88.8-95.5 | 5/8<br>5/8<br>5/8 | MC-T269<br>MC-T445 | MK-4328<br>MK-4346<br>MK-T236 | 85.8-88.6<br>88.6-94.10<br>94.10-95.5 | 13/16<br>13/16<br>13/16 | CC-70176<br>CC-70176 | CK-3144<br>CK-3144<br>CK-T201 |
| (2000)<br>(LPG含む) | M－YY61（ロングボディー）<br>T－YY61（ロングボディー）<br>Z－YY61<br><T－は90．8～><br><Z－は93．8～> | 高床（Sタイヤ）<br>ダブルキャブ（Sタイヤ） | 85.8-95.5 | 1 | TD-T442 | TK-T009 | 85.8-95.5 | 66.6 | DISC | MP-17 | | 85.8-95.5 | 15/16 | | WK-681 | CUP | 85.8-88.8<br>88.8-90.6<br>90.6-95.5 | BH-31404<br>BH-94005<br>BH-94005 | BH-T507<br>BH-T507<br>BH-T507 | 85.8-87.8<br>87.8-88.8<br>88.8-95.5 | 5/8<br>5/8<br>5/8 | MC-T269<br>MC-T445 | MK-4328<br>MK-4346<br>MK-T236 | 85.8-88.6<br>88.6-94.10<br>94.10-95.5 | 13/16<br>13/16<br>13/16 | CC-70176<br>CC-70176 | CK-3144<br>CK-3144<br>CK-T201 |
| | | ジャストロー（Wタイヤ）<br>Wキャブジャストロー（Wタイヤ） | 85.8-95.5 | 1 | TD-T442 | TK-T009 | 85.8-95.5 | 66.6 | DISC | MP-17 | | 85.8-95.5 | 15/16 | | WK-897 | CUP | 85.8-88.8<br>88.8-90.6<br>90.6-95.5<br><YY61MDRT><br>85.8-87.8 | BH-31404<br>BH-94005<br>BH-94005<br><br>BH-31404 | BH-T507<br>BH-T507<br>BH-T507<br><br>BH-94005 | 85.8-87.8<br>87.8-88.8<br>88.8-95.5 | 5/8<br>5/8<br>5/8 | MC-T269<br>MC-T445 | MK-4328<br>MK-4346<br>MK-T236 | 85.8-88.6<br>88.6-95.5 | 13/16<br>13/16 | CC-70176<br>CC-70176 | CK-3144<br>CK-3144 |
| | | フルジャストロー（Wタイヤ） | 87.8-95.5 | 1 | | TK-T009 | 87.8-95.5 | 66.6 | DISC | MP-17 | | 87.8-95.5 | 1 | | WK-640 | CUP | 87.8-95.5 | (1)BH-94006<br>(2)BH-02516 | BH-94005 | 87.8-88.8<br>88.8-95.5 | 5/8<br>5/8 | MC-T269<br>MC-T445 | MK-4346<br>MK-T236 | 87.8-88.6<br>88.6-95.5 | 13/16<br>13/16 | CC-70176<br>CC-70176 | CK-3144<br>CK-3144 |
| (2400ディーゼル) | N－LY50<br>U－LY50<br><U－は88．8～> | 低床・高床（Sタイヤ） | 85.8-95.5 | 1 | TD-T442 | TK-T009 | 85.8-95.5 | 66.6 | DISC | MP-17 | | <1.25T><br>85.8-95.5<br><br><1.5t高床><br>85.8-88.8 | 13/16<br>15/16 | (R)WC-50051<br>(L)WC-50051 | WK-106<br>WK-681 | CUP<br>CUP | 85.8-88.8<br>88.8-90.6<br>90.6-95.5 | BH-31404<br>BH-94005<br>BH-94005 | BH-T507<br>BH-T507<br>BH-T507 | 85.8-87.8<br>87.8-88.8<br>88.8-95.5 | 5/8<br>5/8<br>5/8 | MC-T269<br>MC-T445 | MK-4328<br>MK-4346<br>MK-T236 | <1.25T><br>85.8-88.6<br>88.6-94.5<br>94.5-95.5<br><1.5T><br>85.8-88.8 | 13/16<br>13/16<br>13/16<br>13/16 | CC-70133<br>CC-70133<br>CC-70133<br>CC-70177 | CK-3144<br>CK-3144<br>CK-T201<br>CK-3144 |
| | | ジャストロー（Sタイヤ） | 87.8-95.5 | 1 | | TK-T009 | 87.8-95.5 | 66.6 | DISC | MP-17 | | 87.8-95.5 | 13/16 | (R)WC-50051<br>(L)WC-50051 | WK-106 | CUP | 87.8-95.5 | BH-94008 | BH-94005 | 87.8-88.8<br>88.8-95.5 | 5/8<br>5/8 | MC-T269<br>MC-T445 | MK-4346<br>MK-T236 | 87.8-88.6<br>88.6-94.5<br>94.5-95.5 | 13/16<br>13/16<br>13/16 | CC-70133<br>CC-70133<br>CC-70133 | CK-3144<br>CK-3144<br>CK-T201 |
| | | ジャストロー（Wタイヤ） | 85.8-95.5 | 1 | TD-T442 | TK-T009 | 85.8-95.5 | 66.6 | DISC | MP-17 | | <1.25T><br>85.8-95.5<br><br><1.5T><br>85.8-88.8 | 3/4<br>15/16 | (R)<br>(L) | WK-590<br>WK-897 | CUP<br>CUP | 85.8-88.8<br>88.8-90.6<br>90.6-95.5 | BH-31404<br>BH-94005<br>BH-94005 | BH-T507<br>BH-T507<br>BH-T507 | 85.8-87.8<br>87.8-88.8<br>88.8-95.5 | 5/8<br>5/8<br>5/8 | MC-T269<br>MC-T445 | MK-4328<br>MK-4346<br>MK-T236 | <1.25T><br>85.8-88.6<br>88.6-94.5<br>94.5-95.5<br><1.5T><br>85.8-88.8 | 13/16<br>13/16<br>13/16<br>13/16 | CC-70133<br>CC-70133<br>CC-70133<br>CC-70177 | CK-3144<br>CK-3144<br>CK-T201<br>CK-3144 |
| | | ダブルキャブ（Sタイヤ） | 85.8-95.5 | 1 | TD-T442 | TK-T009 | 85.8-95.5 | 66.6 | DISC | MP-17 | | 85.8-88.8<br>88.8-95.5 | 15/16<br>13/16 | (R)WC-50051<br>(L)WC-50051 | WK-681<br>WK-106 | CUP<br>CUP | 85.8-88.8<br>88.8-90.6<br>90.6-95.5 | BH-31404<br>BH-94005<br>BH-94005 | BH-T507<br>BH-T507<br>BH-T507 | 85.8-87.8<br>87.8-88.8<br>88.8-95.5 | 5/8<br>5/8<br>5/8 | MC-T269<br>MC-T445 | MK-4328<br>MK-4346<br>MK-T236 | 85.8-88.8<br>88.8-94.5<br>94.5-95.5 | 13/16<br>13/16<br>13/16 | CC-70177<br>CC-70133<br>CC-70133 | CK-3144<br>CK-3144<br>CK-T201 |
| (2800ディーゼル) | U－LY51 | 高床（Sタイヤ） | 88.8-95.5 | 1 | | TK-T009 | 88.8-95.5 | 66.6 | DISC | MP-17 | | 88.8-95.5 | 15/16 | | WK-681 | CUP | 88.8-90.6<br>90.6-95.5 | BH-94005<br>BH-94005 | BH-T507<br>BH-T507 | 88.8-95.5 | 5/8 | MC-T445 | MK-T236 | 88.8-90.6<br>90.6-93.4<br>93.4-95.5 | 13/16<br>13/16<br>13/16 | CC-70177<br>CC-70177<br>CC-70177 | CK-3144<br>CK-3144<br>CK-T201 |
| | | ジャストロー（Wタイヤ） | 88.8-95.5 | 1 | | TK-T009 | 88.8-95.5 | 66.6 | DISC | MP-17 | | 88.8-95.5 | 15/16 | | WK-897 | CUP | 88.8-90.6<br>90.6-95.5 | BH-94005<br>BH-94005 | BH-T507<br>BH-T507 | 88.8-95.5 | 5/8 | MC-T445 | MK-T236 | 88.8-90.6<br>90.6-93.4<br>93.4-95.5 | 13/16<br>13/16<br>13/16 | CC-70177<br>CC-70177<br>CC-70177 | CK-3144<br>CK-3144<br>CK-T201 |
| (2400ディーゼル)<br>(2800ディーゼル) | N－LY60<br>U－LY61 | 高床（Sタイヤ）<br>ダブルキャブ（Sタイヤ） | 85.8-95.5 | 1 | TD-T442 | TK-T009 | 85.8-95.5 | 66.6 | DISC | MP-17 | | 85.8-95.5 | 15/16 | | WK-681 | CUP | 85.8-88.8<br>88.8-90.6<br>90.6-95.5 | BH-31404<br>BH-94005<br>BH-94005 | BH-T507<br>BH-T507<br>BH-T507 | 85.8-87.8<br>87.8-88.8<br>88.8-95.5 | 5/8<br>5/8<br>5/8 | MC-T269<br>MC-T445 | MK-4328<br>MK-4346<br>MK-T236 | 85.8-90.6<br>90.6-93.4<br>93.4-95.5 | 13/16<br>13/16<br>13/16 | CC-70177<br>CC-70177<br>CC-70177 | CK-3144<br>CK-3144<br>CK-T201 |
| | | ジャストロー（Wタイヤ）<br>Wキャブジャストロー（Wタイヤ） | 85.8-95.5 | 1 | TD-T442 | TK-T009 | 85.8-95.5 | 66.6 | DISC | MP-17 | | 85.8-95.5 | 15/16 | | WK-897 | CUP | 85.8-88.8<br>88.8-90.6 | BH-31404<br>BH-94005 | BH-T507<br>BH-T507 | 85.8-87.8<br>87.8-88.8 | 5/8<br>5/8 | MC-T269 | MK-4328<br>MK-4346 | 85.8-90.6<br>90.6-93.4 | 13/16<br>13/16 | CC-70177<br>CC-70177 | CK-3144<br>CK-3144 |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | | | | | | | 90.6-95.5<br><LY60MDRT><br>85.8-87.8 | BH-94005<br><br>BH-31404 | BH-T507<br><br>BH-94005 | 88.8-95.5 | 5/8 | MC-T445 | MK-T236 | 93.4-95.5 | 13/16 | CC-70177 | CK-T201 |
| フルジャストロー（Wタイヤ） | 87.8-95.5 | 1 | | TK-T009 | 87.8-95.5 | 66.6 | DISC | MP-17 | | 87.8-95.5 | 1 | | WK-640 | CUP | 87.8-95.5 | (1)BH-94006<br>(2)BH-02516 | BH-94005 | 87.8-88.8<br>88.8-95.5 | 5/8<br>5/8 | MC-T269<br>MC-T445 | MK-4346<br>MK-T236 | 87.8-90.6<br>90.6-93.4<br>93.4-95.5 | 13/16<br>13/16<br>13/16 | CC-70177<br>CC-70177<br>CC-70177 | CK-3144<br>CK-3144<br>CK-T201 |
| ジャストロー（Sタイヤ） | 87.8-95.5 | 1 | | TK-T009 | 87.8-95.5 | 66.6 | DISC | MP-17 | | 87.8-95.5 | 15/16 | | WK-681 | CUP | 87.8-95.5 | BH-94008 | BH-94008 | 87.8-88.8<br>88.8-95.5 | 5/8<br>5/8 | MC-T269<br>MC-T445 | MK-4346<br>MK-T236 | 87.8-90.6<br>90.6-93.4<br>93.4-95.5 | 13/16<br>13/16<br>13/16 | CC-70177<br>CC-70177<br>CC-70177 | CK-3144<br>CK-3144<br>CK-T201 |

| Models | TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| DYNA, TOYOACE : YY, LY100-160 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| GB－YY101<br><GEーは99．5～><br>(3Y) | スーパーシングルジャストロー | 96.10-01.7 | 1 | TD-T915 | TK-T365 | 96.10-01.7 | 60.3 | DISC | MP-10 | CPM-10 | 96.10-01.7 | 13/16 | (R)WC-50051<br>(L)WC-50051 | WK-106 | CUP | 96.10-99.5<br>99.5-01.7 | BH-02477<br>BH-T934 | BH-02342<br>BH-02342 | 96.10-01.7 | 5/8 | | MK-T244 | 96.10-01.7 | 13/16 | CC-70145 | CK-T201 |
| | 除くスーパーシングルジャストロー | 96.10-01.7 | 1 | TD-T915 | TK-T365 | 96.10-01.7 | 60.3 | DISC | MP-10 | CPM-10 | 96.10-01.7 | 7/8 | (R)WC-50046<br>(L)WC-50046 | WK-048 | CUP | 96.10-99.5<br>99.5-01.7 | BH-02477<br>BH-T934 | BH-T681<br>BH-T936 | 96.10-01.7 | 5/8 | | MK-T244 | 96.10-01.7 | 13/16 | CC-70145 | CK-T201 |
| GB－YY121・131<br><GEーは99．5～><br>(3Y) | Sタイヤ | 96.10-01.7 | 1 | TD-T915 | TK-T365 | 96.10-01.7 | 66.6 | DISC | MP-27 | | 96.10-99.5<br>99.5-01.7 | 15/16<br>15/16 | | WK-681<br>WK-998 | CUP<br>CUP | 96.10-99.5<br>99.5-01.7 | BH-02522<br>BH-T935 | BH-94008<br>BH-94008 | 96.10-01.7 | 5/8 | | MK-T244 | 96.10-01.7 | 13/16 | | CK-T201 |
| | Wタイヤ | 96.10-01.7 | 1 | TD-T915 | TK-T365 | 96.10-01.7 | 66.6 | DISC | MP-27 | | 96.10-01.7 | 15/16 | | WK-897 | CUP | 96.10-99.5<br>99.5-01.7 | BH-02522<br>BH-T935 | BH-T720<br>BH-T937 | 96.10-01.7 | 5/8 | | MK-T244 | 96.10-01.7 | 13/16 | | CK-T201 |
| KC－LY101・111<br>KG－LY102・112<br><KGーは99．5～><br>(3L・5L) | スーパーシングルジャストロー | 96.10-01.7 | 1 | TD-T915 | TK-T365 | 96.10-01.7 | 60.3 | DISC | MP-10 | CPM-10 | 96.10-01.7 | 13/16 | (R)WC-50051<br>(L)WC-50051 | WK-106 | CUP | 96.10-99.5<br>99.5-01.7 | BH-02477<br>BH-T934 | BH-02342<br>BH-02342 | 96.10-01.7 | 5/8 | MC-T445 | MK-T244 | 96.10-01.7 | 13/16 | CC-70133 | CK-T201 |
| | 除くスーパーシングルジャストロー | 96.10-01.7 | 1 | TD-T915 | TK-T365 | 96.10-01.7 | 60.3 | DISC | MP-10 | CPM-10 | 96.10-01.7 | 7/8 | (R)WC-50046<br>(L)WC-50046 | WK-048 | CUP | 96.10-99.5<br>99.5-01.7 | BH-02477<br>BH-T934 | BH-T681<br>BH-T936 | 96.10-01.7 | 5/8 | MC-T445 | MK-T244 | 96.10-01.7 | 13/16 | CC-70133 | CK-T201 |
| KC－LY121・131<br>KG－LY122・132<br><KGーは99．5～><br>(3L・5L) | Sタイヤ | 96.10-01.7 | 1 | TD-T915 | TK-T365 | 96.10-01.7 | 66.6 | DISC | MP-27 | | 96.10-99.5<br>99.5-01.7 | 15/16<br>15/16 | | WK-681<br>WK-998 | CUP<br>CUP | 96.10-99.5<br>99.5-01.7 | BH-02522<br>BH-T935 | BH-94008<br>BH-94008 | 96.10-01.7 | 5/8 | MC-T445 | MK-T244 | 96.10-01.7 | 13/16 | | CK-T201 |
| | Wタイヤ | 96.10-01.7 | 1 | TD-T915 | TK-T365 | 96.10-01.7 | 66.6 | DISC | MP-27 | | 96.10-01.7 | 15/16 | | WK-897 | CUP | 96.10-99.5<br>99.5-01.7 | BH-02522<br>BH-T935 | BH-T720<br>BH-T937 | 96.10-01.7 | 5/8 | MC-T445 | MK-T244 | 96.10-01.7 | 13/16 | | CK-T201 |
| KC－LY151(4WD)<br>KG－LY152(4WD)<br><KGーは99．5～><br>(3L・5L) | スーパーシングルジャストロー | 96.10-01.7 | 1 | TD-T915 | TK-T365 | 96.10-01.7 | 66.6 | DISC | MP-27 | | 96.10-01.7 | 13/16 | (R)WC-50051<br>(L)WC-50051 | WK-106 | CUP | 96.10-99.5<br>99.5-01.7 | BH-02522<br>BH-T935 | BH-94008<br>BH-94008 | 96.10-01.7 | 5/8 | MC-T445 | MK-T244 | 96.10-01.7 | 13/16 | CC-70177 | CK-T201 |
| | 除くスーパーシングルジャストロー | 96.10-01.7 | 1 | TD-T915 | TK-T365 | 96.10-01.7 | 66.6 | DISC | MP-27 | | 96.10-01.7 | 15/16 | | WK-885 | CUP | 96.10-99.5<br>99.5-01.7 | BH-02522<br>BH-T935 | BH-02342<br>BH-02342 | 96.10-01.7 | 5/8 | MC-T445 | MK-T244 | 96.10-01.7 | 13/16 | CC-70177 | CK-T201 |
| KC・GB－LY161(4WD)<br>KG・GE－LY162(4WD)<br><GBーは98．5～><br><KG・GEーは99．5～><br>(3L・5L・3Y－P) | Wキャブ（Sタイヤ） | 96.10-01.7 | 1 | TD-T915 | TK-T365 | 96.10-01.7 | 66.6 | DISC | MP-27 | | 96.10-01.7 | 15/16 | | WK-885 | CUP | <1t><br>96.10-99.5<br>99.5-01.7<br><1.25t><br>96.10-99.5<br>99.5-01.7 | BH-02522<br>BH-T935<br><br>BH-02522<br>BH-T935 | BH-02342<br>BH-02342<br><br>BH-94008<br>BH-94008 | 96.10-01.7 | 5/8 | MC-T445 | MK-T244 | 96.10-01.7 | 13/16 | CC-70177 | CK-T201 |
| | スーパーシングルジャストロー | 96.10-01.7 | 1 | TD-T915 | TK-T365 | 96.10-01.7 | 66.6 | DISC | MP-27 | | 96.10-01.7<br><1.5t><br>96.10-01.7 | 13/16<br><br>15/16 | (R)WC-50051<br>(L)WC-50051 | WK-106<br><br>WK-885 | CUP<br><br>CUP | 96.10-99.5<br>99.5-01.7 | BH-02522<br>BH-T935 | BH-94008<br>BH-94008 | 96.10-01.7 | 5/8 | MC-T445 | MK-T244 | 96.10-01.7 | 13/16 | CC-70177 | CK-T201 |
| | シングルジャストロー | 96.10-01.7 | 1 | TD-T915 | TK-T365 | 96.10-01.7 | 66.6 | DISC | MP-27 | | 96.10-01.7 | 15/16 | | WK-885 | CUP | <1.25t><br>96.10-99.5<br>99.5-01.7<br><1.5t><br>96.10-99.5<br>99.5-01.7 | BH-02522<br>BH-T935<br><br>BH-02522<br>BH-T935 | BH-02342<br>BH-02342<br><br>BH-94008<br>BH-94008 | <3L・5L><br>96.10-01.7<br><3Y－P><br>98.5-01.7 | 5/8<br><br>5/8 | MC-T445 | MK-T244<br><br>MK-T244 | <3L・5L><br>96.10-01.7<br><3Y－P><br>98.5-01.7 | 13/16<br><br>13/16 | CC-70177 | CK-T201<br><br>CK-T201 |
| | ジャストロー（Wタイヤ） | 99.5-01.7 | 1 | TD-T915 | TK-T365 | 99.5-01.7 | 66.6 | DISC | MP-27 | | 99.5-01.7 | 3/4 | (R)<br>(L) | WK-590 | CUP | 99.5-01.7 | BH-T935 | BH-T784 | 99.5-01.7 | 5/8 | MC-T445 | MK-T244 | 99.5-01.7 | 13/16 | CC-70177 | CK-T201 |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| DYNA, TOYOACE : YY, LY200 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| GB－YY201<br>＜GE－は99．5～＞<br>(3Y) | 高床(Sタイヤ) | 95.5-01.7 | 1 | TD-T915 | TK-T365 | 95.5-01.7 | 66.6 | DISC | MP-17 | | 95.5-99.5<br>99.5-01.7 | 15/16<br>15/16 | | WK-681<br>WK-998 | CUP<br>CUP | 95.5-99.5<br>99.5-01.7 | BH-94005<br>BH-T930 | BH-94005<br>BH-T932 | 95.5-01.7 | 5/8 | | MK-T244 | 95.5-01.7 | 13/16 | | CK-T201 |
| | 低床(Sタイヤ)<br>Wキャブ(Sタイヤ) | 95.5-96.10 | 1 | TD-T915 | TK-T365 | 95.5-96.10 | 66.6 | DISC | MP-17 | | 95.5-96.10 | 13/16 | (R)WC-50051<br>(L)WC-50051 | WK-106 | CUP | 95.5-96.10 | BH-94005 | BH-94005 | 95.5-96.10 | 5/8 | | MK-T244 | 95.5-96.10 | 13/16 | CC-70145 | CK-T201 |
| | スーパーシングルジャストロー | 95.5-96.10 | 1 | TD-T915 | TK-T365 | 95.5-96.10 | 66.6 | DISC | MP-17 | | 95.5-96.10 | 13/16 | (R)WC-50051<br>(L)WC-50051 | WK-106 | CUP | 95.5-96.10 | BH-94008 | BH-94005 | 95.5-96.10 | 5/8 | | MK-T244 | 95.5-96.10 | 13/16 | CC-70145 | CK-T201 |
| | ジャストロー(Wタイヤ) | 95.5-01.7 | 1 | TD-T915 | TK-T365 | 95.5-01.7 | 66.6 | DISC | MP-17 | | 95.5-01.7 | 15/16 | | WK-897 | CUP | 95.5-99.5<br>99.5-01.7 | BH-94005<br>BH-T930 | BH-T507<br>BH-T784 | 95.5-01.7 | 5/8 | | MK-T244 | 95.5-01.7 | 13/16 | | CK-T201 |
| GB－YY211<br>＜GE－は99．5～＞<br>(3Y･3Y－P) | 高床(Sタイヤ)<br>Wキャブ(Sタイヤ) | 95.5-01.7 | 1 | TD-T915 | TK-T365 | 95.5-01.7 | 66.6 | DISC | MP-17 | | 95.5-99.5<br>99.5-01.7 | 15/16<br>15/16 | | WK-681<br>WK-998 | CUP<br>CUP | 95.5-99.5<br>99.5-01.7 | BH-94005<br>BH-T930 | BH-94005<br>BH-T932 | 95.5-01.7 | 5/8 | | MK-T244 | 95.5-01.7 | 13/16 | | CK-T201 |
| | スーパーシングルジャストロー | 95.5-01.7 | 1 | TD-T915 | TK-T365 | 95.5-01.7 | 66.6 | DISC | MP-17 | | 95.5-99.5<br>99.5-01.7 | 15/16<br>15/16 | | WK-681<br>WK-998 | CUP<br>CUP | 95.5-99.5<br>99.5-01.7 | BH-94008<br>BH-94008 | BH-94005<br>BH-T932 | 95.5-01.7 | 5/8 | | MK-T244 | 95.5-01.7 | 13/16 | | CK-T201 |
| | ジャストロー(Wタイヤ)<br>Wキャブ(Wタイヤ) | 95.5-01.7 | 1 | TD-T915 | TK-T365 | 95.5-01.7 | 66.6 | DISC | MP-17 | | ＜MT車＞<br>95.5-01.7<br>＜AT車＞<br>95.5-01.7 | 15/16<br>3/4 | <br>(R)<br>(L) | WK-897<br>WK-590 | CUP<br>CUP | 95.5-99.5<br>99.5-01.7 | BH-94005<br>BH-T930 | BH-T507<br>BH-T784 | 95.5-01.7 | 5/8 | | MK-T244 | 95.5-01.7 | 13/16 | | CK-T201 |
| | フルジャストロー(Wタイヤ) | 95.5-01.7 | 1 | TD-T915 | TK-T365 | 95.5-01.7 | 66.6 | DISC | MP-17 | | 95.5-99.5<br>99.5-01.7 | 1<br>1 | | WK-640<br>WK-937 | CUP<br>CUP | 95.5-99.5<br>99.5-01.7 | (1)BH-02210<br>(2)BH-T719<br>(1)BH-T931<br>(2)BH-T719 | BH-94008<br>BH-94008 | 95.5-01.7 | 5/8 | | MK-T244 | 95.5-01.7 | 13/16 | | CK-T201 |
| KC－LY201<br>KG－LY202<br>＜KG－は99．5～＞<br>(3L･5L) | 高床(Sタイヤ) | 95.5-01.7 | 1 | TD-T915 | TK-T365 | 95.5-01.7 | 66.6 | DISC | MP-17 | | 95.5-99.5<br>99.5-01.7 | 15/16<br>15/16 | | WK-681<br>WK-998 | CUP<br>CUP | 95.5-99.5<br>99.5-01.7 | BH-94005<br>BH-T930 | BH-94005<br>BH-T932 | 95.5-01.7 | 5/8 | MC-T445 | MK-T244 | 95.5-01.7 | 13/16 | CC-70177 | CK-T201 |
| | 低床(Sタイヤ)<br>Wキャブ(Sタイヤ) | 95.5-96.10 | 1 | TD-T915 | TK-T365 | 95.5-96.10 | 66.6 | DISC | MP-17 | | 95.5-96.10 | 13/16 | (R)WC-50051<br>(L)WC-50051 | WK-106 | CUP | 95.5-96.10 | BH-94005 | BH-94005 | 95.5-96.10 | 5/8 | MC-T445 | MK-T244 | 95.5-96.10 | 13/16 | CC-70133 | CK-T201 |
| | スーパーシングルジャストロー | 95.5-96.10 | 1 | TD-T915 | TK-T365 | 95.5-96.10 | 66.6 | DISC | MP-17 | | 95.5-96.10 | 13/16 | (R)WC-50051<br>(L)WC-50051 | WK-106 | CUP | 95.5-96.10 | BH-94008 | BH-94005 | 95.5-96.10 | 5/8 | MC-T445 | MK-T244 | 95.5-96.10 | 13/16 | CC-70133 | CK-T201 |
| | ジャストロー(Wタイヤ) | 95.5-01.7 | 1 | TD-T915 | TK-T365 | 95.5-01.7 | 66.6 | DISC | MP-17 | | 95.5-01.7 | 15/16 | | WK-897 | CUP | 95.5-99.5<br>99.5-01.7 | BH-94005<br>BH-T930 | BH-T507<br>BH-T784 | 95.5-01.7 | 5/8 | MC-T445 | MK-T244 | 95.5-01.7 | 13/16 | CC-70177 | CK-T201 |
| KC－LY211<br>KG－LY212<br>＜KG－は99．5～＞<br>(3L･5L) | 高床(Sタイヤ)<br>Wキャブ(Sタイヤ) | 95.5-01.7 | 1 | TD-T915 | TK-T365 | 95.5-01.7 | 66.6 | DISC | MP-17 | | 95.5-99.5<br>99.5-01.7 | 15/16<br>15/16 | | WK-681<br>WK-998 | CUP<br>CUP | 95.5-99.5<br>99.5-01.7 | BH-94005<br>BH-T930 | BH-94005<br>BH-T932 | 95.5-01.7 | 5/8 | MC-T445 | MK-T244 | 95.5-01.7 | 13/16 | CC-70177 | CK-T201 |
| | スーパーシングルジャストロー | 95.5-01.7 | 1 | TD-T915 | TK-T365 | 95.5-01.7 | 66.6 | DISC | MP-17 | | 95.5-99.5<br>99.5-01.7 | 15/16<br>15/16 | | WK-681<br>WK-998 | CUP<br>CUP | 95.5-99.5<br>99.5-01.7 | BH-94008<br>BH-94008 | BH-94005<br>BH-T932 | 95.5-01.7 | 5/8 | MC-T445 | MK-T244 | 95.5-01.7 | 13/16 | CC-70177 | CK-T201 |
| | ジャストロー(Wタイヤ)<br>Wキャブ(Wタイヤ) | 95.5-01.7 | 1 | TD-T915 | TK-T365 | 95.5-01.7 | 66.6 | DISC | MP-17 | | 95.5-01.7 | 15/16 | | WK-897 | CUP | 95.5-99.5<br>99.5-01.7 | BH-94005<br>BH-T930 | BH-T507<br>BH-T784 | 95.5-01.7 | 5/8 | MC-T445 | MK-T244 | 95.5-01.7 | 13/16 | CC-70177 | CK-T201 |
| | フルジャストロー(Wタイヤ) | 95.5-01.7 | 1 | TD-T915 | TK-T365 | 95.5-01.7 | 66.6 | DISC | MP-17 | | 95.5-99.5<br>99.5-01.7 | 1<br>1 | | WK-640<br>WK-937 | CUP<br>CUP | 95.5-99.5<br>99.5-01.7 | (1)BH-02210<br>(2)BH-T719<br>(1)BH-T931<br>(2)BH-T719 | BH-94008<br>BH-94008 | 95.5-01.7 | 5/8 | MC-T445 | MK-T244 | 95.5-01.7 | 13/16 | CC-70177 | CK-T201 |

| Models | TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| DYNA, TOYOACE : RZ, LY220-290 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| KR－KDY220・230・270<br>KR－KDY280 | スーパーシングルジャストロー<br>（Sタイヤ） | 04.8-07.8 | | | | 04.8-07.8 | | DISC | MP-27 | CPM-86 | 04.8-07.8 | 15/16 | (R)WC-T746<br>(L)WC-T746 | WK-884 | CUP | 04.8-07.8 | (R)BH-T853<br>(L)BH-T854 | BH-T852 | 04.8-07.8 | 5/8 | MC-T479 | MK-T245 | 04.8-07.8 | 13/16 | CC-T397 | CK-T201 |
| | シングルジャストロー<br>（Sタイヤ） | 04.8-07.8 | | | | 04.8-07.8 | | DISC | MP-27 | CPM-86 | 04.8-07.8 | 15/16 | (R)WC-50075<br>(L)WC-50075 | WK-885 | CUP | 04.8-07.8 | (R)BH-T853<br>(L)BH-T854 | BH-T852 | 04.8-07.8 | 5/8 | MC-T479 | MK-T245 | 04.8-07.8 | 13/16 | CC-T397 | CK-T201 |
| | フルジャストロー<br>（Wタイヤ・Wキャブ含む） | 04.8-07.8 | | | | 04.8-07.8 | | DISC | MP-27 | CPM-86 | 04.8-07.8 | 1 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-1025 | CUP | 04.8-07.8 | (R)BH-T853<br>(L)BH-T854 | BH-T712 | 04.8-07.8 | 5/8 | MC-T479 | MK-T245 | 04.8-07.8 | 13/16 | CC-T397 | CK-T201 |
| | ジャストロー<br>（Wタイヤ・Wキャブ含む） | 04.8-07.8 | | | | 04.8-07.8 | | DISC | MP-27 | CPM-86 | 04.8-07.8 | 15/16 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-998 | CUP | 04.8-07.8 | (R)BH-T853<br>(L)BH-T854 | BH-T761 | 04.8-07.8 | 5/8 | MC-T479 | MK-T245 | 04.8-07.8 | 13/16 | CC-T397 | CK-T201 |
| | 低床<br>（Sタイヤ・Wキャブ含む） | 04.8-07.8 | | | | 04.8-07.8 | | DISC | MP-27 | CPM-86 | 04.8-07.8 | 15/16 | (R)WC-50075<br>(L)WC-50075 | WK-885 | CUP | 04.8-07.8 | (R)BH-T853<br>(L)BH-T854 | BH-T852 | 04.8-07.8 | 5/8 | MC-T479 | MK-T245 | 04.8-07.8 | 13/16 | CC-T397 | CK-T201 |
| | 高床<br>（Wキャブ含む） | 04.8-07.8 | | | | 04.8-07.8 | | DISC | MP-27 | CPM-86 | 04.8-07.8 | 15/16 | (R)WC-50075<br>(L)WC-50075 | WK-885 | CUP | 04.8-07.8 | (R)BH-T853<br>(L)BH-T854 | BH-T852 | 04.8-07.8 | 5/8 | MC-T479 | MK-T245 | 04.8-07.8 | 13/16 | CC-T397 | CK-T201 |
| ADF－KDY221・231・271<br>ADF－KDY241V<br>ADF－KDY281<br>＜LDF－は10．8～＞ | スーパーシングルジャストロー<br>（Sタイヤ） | <ABS付><br>07.9-16.10<br>16.10-<br><ABS無><br>07.9-16.10<br>16.10- | | | ミセッテイ<br>ミセッテイ | 07.9- | | DISC | MP-27 | CPM-86 | 07.9- | 15/16 | (R)WC-T746<br>(L)WC-T746 | WK-884 | CUP | 07.9- | (R)BH-T853<br>(L)BH-T854 | BH-T852 | 07.9- | 5/8 | MC-T479 | MK-T245 | 07.9- | 3/4 | CC-T391 | CK-T231 |
| | シングルジャストロー<br>（Sタイヤ・Wキャブ含む） | <ABS付><br>07.9-16.10<br>16.10-<br><ABS無><br>07.9-16.10<br>16.10- | | | ミセッテイ<br>ミセッテイ | 07.9- | | DISC | MP-27 | CPM-86 | 07.9- | 15/16 | (R)WC-50075<br>(L)WC-50075 | WK-885 | CUP | 07.9- | (R)BH-T853<br>(L)BH-T854 | BH-T852 | 07.9- | 5/8 | MC-T479 | MK-T245 | 07.9- | 3/4 | CC-T391 | CK-T231 |
| | ジャストロー<br>（Wタイヤ・Wキャブ含む） | <ABS付><br>07.9-16.10<br>16.10-<br><ABS無><br>07.9-16.10<br>16.10- | | | ミセッテイ<br>ミセッテイ | 07.9 | | DISC | MP-27 | CPM-86 | 07.9 | 15/16 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-998 | CUP | 07.9 | (R)BH-T853<br>(L)BH-T854 | BH-T761 | 07.9 | 5/8 | MC-T479 | MK-T245 | 07.9- | 3/4 | CC-T391 | CK-T231 |
| | フルジャストロー<br>（Wタイヤ・Wキャブ含む） | <ABS付><br>07.9-16.10<br>16.10-<br><ABS無><br>07.9-16.10<br>16.10- | | | ミセッテイ<br>ミセッテイ | 07.9- | | DISC | MP-27 | CPM-86 | 07.9- | 1 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-1025 | CUP | 07.9- | (R)BH-T853<br>(L)BH-T854 | BH-T712 | 07.9- | 5/8 | MC-T479 | MK-T245 | 07.9- | 3/4 | CC-T391 | CK-T231 |
| | 低床<br>（Sタイヤ・Wキャブ含む） | <ABS付><br>07.9-16.10<br>16.10-<br><ABS無><br>07.9-16.10<br>16.10- | | | ミセッテイ<br>ミセッテイ | 07.9- | | DISC | MP-27 | CPM-86 | 07.9- | 15/16 | (R)WC-50075<br>(L)WC-50075 | WK-885 | CUP | 07.9- | (R)BH-T853<br>(L)BH-T854 | BH-T852 | 07.9- | 5/8 | MC-T479 | MK-T245 | 07.9- | 3/4 | CC-T391 | CK-T231 |
| | 高床<br>（Wキャブ含む） | <ABS付><br>07.9-16.10<br>16.10-<br><ABS無><br>07.9-16.10<br>16.10- | | | ミセッテイ<br>ミセッテイ | 07.9- | | DISC | MP-27 | CPM-86 | 07.9- | 15/16 | (R)WC-50075<br>(L)WC-50075 | WK-885 | CUP | 07.9- | (R)BH-T853<br>(L)BH-T854 | BH-T852 | 07.9- | 5/8 | MC-T479 | MK-T245 | 07.9- | 3/4 | CC-T391 | CK-T231 |
| KR－KDY240V<br>KR－KDY290V | バン・4WD | 04.8-07.8 | | | | 04.8-07.8 | | DISC | MP-27 | CPM-86 | 04.8-07.8 | 1 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-1025 | CUP | 04.8-07.8 | (R)BH-T853<br>(L)BH-T854 | BH-T712 | 04.8-07.8 | 5/8 | MC-T479 | MK-T245 | 04.8-07.8 | 3/4 | CC-T397 | CK-T201 |
| GE－RZY220・230<br>（1RZ－E） | 低床　1．2t未満<br>（Sタイヤ・Wキャブ含む） | 01.7-03.8<br><アンチスキッド付><br>01.7-03.8 | | | | 01.7-03.8 | 66.6 | DISC | MP-27 | | 01.7-03.8 | 15/16 | (R)WC-50075<br>(L)WC-50075 | WK-885 | CUP | 01.7-03.8 | (R)BH-T853<br>(L)BH-T854 | BH-T852 | 01.7-03.8 | 5/8 | MC-T479 | MK-T245 | 01.7-03.8 | 13/16 | CC-T390 | CK-T201 |
| | 1．2t以上 | 01.7-03.8<br><アンチスキッド付><br>01.7-03.8 | | | | 01.7-03.8 | 66.6 | DISC | MP-27 | | 01.7-03.8 | 15/16 | | WK-998 | CUP | 01.7-03.8 | (R)BH-T853<br>(L)BH-T854 | BH-T711 | 01.7-03.8 | 5/8 | MC-T479 | MK-T245 | 01.7-03.8 | 13/16 | CC-T390 | CK-T201 |
| | スーパーシングル 1．5t未満<br>（Sタイヤ） | 01.7-03.8<br><アンチスキッド付><br>01.7-03.8 | | | | 01.7-03.8 | 66.6 | DISC | MP-27 | | 01.7-03.8 | 15/16 | (R)WC-T746<br>(L)WC-T746 | WK-884 | CUP | 01.7-03.8 | (R)BH-T853<br>(L)BH-T854 | BH-T852 | 01.7-03.8 | 5/8 | MC-T479 | MK-T245 | 01.7-03.8 | 13/16 | CC-T390 | CK-T201 |
| | 1．5t以上 | 01.7-03.8<br><アンチスキッド付><br>01.7-03.8 | | | | 01.7-03.8 | 66.6 | DISC | MP-27 | | 01.7-03.8 | 15/16 | | WK-998 | CUP | 01.7-03.8 | (R)BH-T853<br>(L)BH-T854 | BH-T711 | 01.7-03.8 | 5/8 | MC-T479 | MK-T245 | 01.7-03.8 | 13/16 | CC-T390 | CK-T201 |

| Models | TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| GE－RZY220・230<br>（1RZ－E） | シングルジャストロ | 1．5t未満<br>（Sタイヤ・Wキャブ含む） | 01.7-03.8<br><ｱﾝﾁｽｷｯﾄﾞ付><br>01.7-03.8 | | | | 01.7-03.8 | 66.6 | DISC | MP-27 | | 01.7-03.8 | 15/16 | (R)WC-50075<br>(L)WC-50075 | WK-885 | CUP | 01.7-03.8 | (R)BH-T853<br>(L)BH-T854 | BH-T852 | 01.7-03.8 | 5/8 | MC-T479 | MK-T245 | 01.7-03.8 | 13/16 | CC-T390 | CK-T201 |
| | | 1．5t以上 | 01.7-03.8<br><ｱﾝﾁｽｷｯﾄﾞ付><br>01.7-03.8 | | | | 01.7-03.8 | 66.6 | DISC | MP-27 | | 01.7-03.8 | 15/16 | | WK-998 | CUP | 01.7-03.8 | (R)BH-T853<br>(L)BH-T854 | BH-T711 | 01.7-03.8 | 5/8 | MC-T479 | MK-T245 | 01.7-03.8 | 13/16 | CC-T390 | CK-T201 |
| | ジャストロー<br>（Wタイヤ・Wキャブ含む） | | 01.7-03.8<br><ｱﾝﾁｽｷｯﾄﾞ付><br>01.7-03.8 | | | | 01.7-03.8 | 66.6 | DISC | MP-27 | | 01.7-03.8 | 15/16 | | WK-998 | CUP | 01.7-03.8 | (R)BH-T853<br>(L)BH-T854 | BH-T761 | 01.7-03.8 | 5/8 | MC-T479 | MK-T245 | 01.7-03.8 | 13/16 | CC-T390 | CK-T201 |
| | フルジャストロー<br>（Wタイヤ・Wキャブ含む） | | 01.7-03.8<br><ｱﾝﾁｽｷｯﾄﾞ付><br>01.7-03.8 | | | | 01.7-03.8 | 66.6 | DISC | MP-27 | | 01.7-03.8 | 1 | | WK-1025 | CUP | 01.7-03.8 | (R)BH-T853<br>(L)BH-T854 | BH-T712 | 01.7-03.8 | 5/8 | MC-T479 | MK-T245 | 01.7-03.8 | 13/16 | CC-T390 | CK-T201 |
| LD－RZY231H・281H<br>（3RZ－FPE） | | | 03.8-<br><ｱﾝﾁｽｷｯﾄﾞ付><br>03.8- | | | | 03.8- | 66.6 | DISC | MP-27 | | 03.8- | 1 | | WK-1025 | CUP | 03.8- | | | 03.8- | 5/8 | MC-T479 | MK-T245 | 03.8- | 13/16 | CC-T390 | CK-T201 |
| KG・KK－LY220・230<br>KG・KK－LY27C（Sタイヤ・Wキャブ含む）<br>TC－TRY220・230<br>NBG－TRY231・281<br><TC－は03．8～><br><ABF－は07．8～><br><NBG－は07．11～><br>（5L）<br>（3RZ－FPE）<br>（1TR－FE） | 低床 | 1．2t未満 | 01.7-<br><ｱﾝﾁｽｷｯﾄﾞ付><br>01.7- | | | | 01.7- | 66.6 | DISC | MP-27 | | 01.7- | 15/16 | (R)WC-50075<br>(L)WC-50075 | WK-885 | CUP | 01.7- | (R)BH-T853<br>(L)BH-T854 | BH-T852 | 01.7- | 5/8 | MC-T479 | MK-T245 | 01.7- | 13/16 | CC-T390 | CK-T201 |
| | | 1．2t以上 | 01.7-<br><ｱﾝﾁｽｷｯﾄﾞ付><br>01.7- | | | | 01.7- | 66.6 | DISC | MP-27 | | 01.7- | 15/16 | | WK-998 | CUP | 01.7- | (R)BH-T853<br>(L)BH-T854 | BH-T711 | 01.7- | 5/8 | MC-T479 | MK-T245 | 01.7- | 13/16 | CC-T390 | CK-T201 |
| | スーパーシングルジャストロー<br>（Sタイヤ） | 1．5t未満 | 01.7-<br><ｱﾝﾁｽｷｯﾄﾞ付><br>01.7- | | | | 01.7- | 66.6 | DISC | MP-27 | | 01.7- | 15/16 | (R)WC-T746<br>(L)WC-T746 | WK-884 | CUP | 01.7- | (R)BH-T853<br>(L)BH-T854 | BH-T852 | 01.7- | 5/8 | MC-T479 | MK-T245 | 01.7- | 13/16 | CC-T390 | CK-T201 |
| | | 1．5t以上 | 01.7-<br><ｱﾝﾁｽｷｯﾄﾞ付><br>01.7- | | | | 01.7- | 66.6 | DISC | MP-27 | | 01.7- | 15/16 | | WK-998 | CUP | 01.7- | (R)BH-T853<br>(L)BH-T854 | BH-T711 | 01.7- | 5/8 | MC-T479 | MK-T245 | 01.7- | 13/16 | CC-T390 | CK-T201 |
| | シングルジャストロー<br>（Sタイヤ・Wキャブ含む） | 1．5t未満 | 01.7-<br><ｱﾝﾁｽｷｯﾄﾞ付><br>01.7- | | | | 01.7- | 66.6 | DISC | MP-27 | | 01.7- | 15/16 | (R)WC-50075<br>(L)WC-50075 | WK-885 | CUP | 01.7- | (R)BH-T853<br>(L)BH-T854 | BH-T852 | 01.7- | 5/8 | MC-T479 | MK-T245 | 01.7- | 13/16 | CC-T390 | CK-T201 |
| | | 1．5t以上 | 01.7-<br><ｱﾝﾁｽｷｯﾄﾞ付><br>01.7- | | | | 01.7- | 66.6 | DISC | MP-27 | | 01.7- | 15/16 | | WK-998 | CUP | 01.7- | (R)BH-T853<br>(L)BH-T854 | BH-T711 | 01.7- | 5/8 | MC-T479 | MK-T245 | 01.7- | 13/16 | CC-T390 | CK-T201 |
| | ジャストロー<br>（Wタイヤ・Wキャブ含む） | | 01.7-<br><ｱﾝﾁｽｷｯﾄﾞ付><br>01.7- | | | | 01.7- | 66.6 | DISC | MP-27 | | 01.7- | 15/16 | | WK-998 | CUP | 01.7- | (R)BH-T853<br>(L)BH-T854 | BH-T761 | 01.7- | 5/8 | MC-T479 | MK-T245 | 01.7-<br><5Lｴﾝｼﾞﾝ車><br>01.7-04.8 | 13/16<br><br>13/16 | CC-T390<br><br>CC-70133 | CK-T201<br><br>CK-T201 |
| | フルジャストロー<br>（Wタイヤ・Wキャブ含む） | | 01.7-<br><ｱﾝﾁｽｷｯﾄﾞ付><br>01.7- | | | | 01.7- | 66.6 | DISC | MP-27 | | 01.7- | 1 | | WK-1025 | CUP | 01.7- | (R)BH-T853<br>(L)BH-T854 | BH-T712 | 01.7- | 5/8 | MC-T479 | MK-T245 | 01.7-<br><5Lｴﾝｼﾞﾝ車><br>01.7-04.8 | 13/16<br><br>13/16 | CC-T390<br><br>CC-70177 | CK-T201<br><br>CK-T201 |
| KK－LY240V　バン<br>KK－LY290V（4WD）<br>（5L） | | | 01.7-<br><ｱﾝﾁｽｷｯﾄﾞ付><br>01.7- | | | | 01.7- | 66.6 | DISC | MP-27 | | 01.7- | 1 | | WK-1025 | CUP | 01.7- | (R)BH-T853<br>(L)BH-T854 | BH-T712 | 01.7- | 5/8 | MC-T479 | MK-T245 | 01.7- | 13/16 | CC-70177 | CK-T201 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| DYNA : RU, JU, BU10 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000) | RU10(トラック) | Sタイヤ・Wタイヤ | 69.2-72.1 | 1 1/4 | | MK-661 | 69.2-72.1 | 1 3/8 | (R-1)WC-5145<br>(R-2)WC-5235<br>(L-1)WC-5345<br>(L-2)WC-5435 | WK-085 | CUP | 69.2-72.1 | 1 3/8 | (R-1)WC-5535<br>(R-2)WC-5625<br>(L-1)WC-5725<br>(L-2)WC-5825 | WK-086 | CUP | <Sタイヤ><br>69.2-72.1<br>72.2-77.7<br><Wタイヤ><br>69.2-72.1 | BH-02576<br>BH-T681<br>BH-02576 | BH-31440<br>BH-44212<br>BH-31360-A | 69.2-72.1<br>72.2-77.7 | 3/4<br>3/4 | MC-10097 | MK-41400<br>MK-41400 | 69.2-72.1<br>72.2-77.5<br>77.5-77.7<br><オールシンクロ> | 15<br>3/4<br>13/16 | CC-70098<br>CC-70099<br>CC-70115 | FC-31480-B<br>CK-41480<br>CK-3115 |
| | RU10P(Wキャブ) | Sタイヤ | 72.2-77.7 | 1 1/8 | | TK-9321 | | | | | | | | | | | | | | | | | | | | | |
| | RU10V(バン) | Sタイヤ | | | | | | | | | | | | | | | | | | | | | | | | | |
| | RU10D(ダンプ) | Wタイヤ | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | 72.2-74.10 | 1 1/4 | (R-1)WC-5146<br>(R-2)WC-5237<br>(L-1)WC-5346<br>(L-2)WC-5436 | WK-100 | CUP | 72.2-74.10 | 1 1/4 | (R-1)WC-5536<br>(R-2)WC-5626<br>(L-1)WC-5726<br>(L-2)WC-5826 | WK-101 | CUP | 69.2-72.1<br>72.2-74.9<br>74.9-77.7<br><ダンプ><br>69.2-72.1 | BH-T681<br>BH-T681<br>BH-02576 | BH-36212<br>BH-40012<br>BH-31360-A | | | | | 69.2-72.1 | 3/4 | | CK-41480 |
| | | | | | | | 74.10-77.7 | 1 1/4 | (R-1)WC-5146<br>(R-2)WC-5237<br>(L-1)WC-5346<br>(L-2)WC-5436<br>(R-1)ブリーダ付<br>(L-1)ブリーダ付 | WK-410 | CUP | 74.10-77.7 | 1 1/4 | (R-1)WC-5536<br>(R-2)WC-5626<br>(L-1)WC-5726<br>(L-2)WC-5826<br>(R-1)ブリーダ付<br>(L-1)ブリーダ付 | WK-412 | CUP | 72.2-74.1<br>74.1-77.7 | BH-T681<br>BH-T681 | BH-36212<br>BH-40012 | | | | | | | | |
| (2000) | RU12D(ダンプ) | Wタイヤ | 69.2-72.1<br>72.2-77.7 | 1 1/4<br>1 1/8 | | MK-661<br>TK-9321 | 69.2-72.1 | 1 3/8 | (R-1)WC-5145<br>(R-2)WC-5235<br>(L-1)WC-5345<br>(L-2)WC-5435 | WK-085 | CUP | 69.2-72.1 | 1 3/8 | (R-1)WC-5535<br>(R-2)WC-5625<br>(L-1)WC-5725<br>(L-2)WC-5825 | WK-086 | CUP | 69.2-72.1<br>72.2-74.1<br>74.1-77.7 | BH-02576<br>BH-T681<br>BH-T681 | BH-31440<br>BH-44212<br>BH-40012 | 69.2-72.1<br>72.2-77.7 | 3/4<br>3/4 | MC-10097 | MK-41400<br>MK-41400 | 69.2-72.1<br>72.2-77.5<br>77.5-77.7 | 3/4<br>3/4<br>13/16 | CC-70099<br>CC-70115 | CK-41480<br>CK-41480<br>CK-3115 |
| | | | | | | | 72.2-74.10 | 1 1/4 | (R-1)WC-5146<br>(R-2)WC-5237<br>(L-1)WC-5346<br>(L-2)WC-5436 | WK-100 | CUP | 72.2-74.10 | 1 1/4 | (R-1)WC-5536<br>(R-2)WC-5626<br>(L-1)WC-5726<br>(L-2)WC-5826 | WK-101 | CUP | | | | | | | | | | | |
| | | | | | | | 74.10-77.7 | 1 1/4 | (R-1)WC-5146<br>(R-2)WC-5237<br>(L-1)WC-5346<br>(L-2)WC-5436<br>(R-1)ブリーダ付<br>(L-1)ブリーダ付 | WK-410 | CUP | 74.10-77.7 | 1 1/4 | (R-1)WC-5536<br>(R-2)WC-5626<br>(L-1)WC-5726<br>(L-2)WC-5826<br>(R-1)ブリーダ付<br>(L-1)ブリーダ付 | WK-412 | CUP | | | | | | | | | | | |
| (2000) | RU15(トラック) | Sタイヤ・Wタイヤ | 69.2-72.1<br>72.2-77.7 | 1 1/4<br>1 1/4 | | MK-661<br>TK-9321 | 69.2-72.1 | 1 3/8 | (R-1)WC-5145<br>(R-2)WC-5235<br>(L-1)WC-5345<br>(L-2)WC-5435 | WK-085 | CUP | 69.2-72.1 | 1 3/8 | (R-1)WC-5535<br>(R-2)WC-5625<br>(L-1)WC-5725<br>(L-2)WC-5825 | WK-086 | CUP | 69.2-72.1<br>72.2-77.7 | BH-02576<br>BH-T681 | BH-31440<br>BH-44212 | 69.2-72.1<br>72.2-77.7 | 3/4<br>3/4 | MC-10097 | MK-41400<br>MK-41400 | 69.2-72.1<br>72.2-77.5<br>77.5-77.7<br><オールシンクロ> | 15<br>3/4<br>13/16 | CC-70098<br>CC-70099<br>CC-70115 | FC-31480-B<br>CK-41480<br>CK-3115 |
| | | | | | | | 72.2-74.10 | 1 1/4 | (R-1)WC-5146<br>(R-2)WC-5237<br>(L-1)WC-5346<br>(L-2)WC-5436 | WK-100 | CUP | 72.2-74.10 | 1 1/4 | (R-1)WC-5536<br>(R-2)WC-5626<br>(L-1)WC-5726<br>(L-2)WC-5826 | WK-101 | CUP | | | | | | | | 69.2-72.1 | 3/4 | | CK-41480 |
| | | | | | | | 74.10-77.7 | 1 1/4 | (R-1)WC-5146<br>(R-2)WC-5237<br>(L-1)WC-5346<br>(L-2)WC-5436<br>(R-1)ブリーダ付<br>(L-1)ブリーダ付 | WK-410 | CUP | 74.10-77.7 | 1 1/4 | (R-1)WC-5536<br>(R-2)WC-5626<br>(L-1)WC-5726<br>(L-2)WC-5826<br>(R-1)ブリーダ付<br>(L-1)ブリーダ付 | WK-412 | CUP | | | | | | | | | | | |
| | | | | | | | | | | | | <Sタイヤ LSPV付><br>73.9-74.10 | 1 3/8 | (R-1)WC-5535<br>(R-2)WC-5625<br>(L-1)WC-5725<br>(L-2)WC-5825 | WK-086 | CUP | | | | | | | | | | | |
| | | | | | | | | | | | | 74.10-77.7 | 1 3/8 | (R-1)WC-5535<br>(R-2)WC-5625<br>(L-1)WC-5725<br>(L-2)WC-5825<br>(R-1)ブリーダ付<br>(L-1)ブリーダ付 | WK-306 | CUP | | | | | | | | | | | |
| (2500ディーゼル) | | Sタイヤ・Wタイヤ | 69.2-72.1 | 1 1/4 | | MK-661 | 69.2-72.1 | 1 3/8 | (R-1)WC-5145 | WK-085 | CUP | 69.2-72.1 | 1 3/8 | (R-1)WC-5535 | WK-086 | CUP | <Sタイヤ><br>69.2-72.1 | BH-02576 | BH-31440 | 69.2-72.1 | 3/4 | | MK-41400 | <JU10.10D><br>69.2-72.1 | 3/4 | | CK-41480 |
| | JU10(トラック) | Wタイヤ | 72.2-77.7 | 1 1/8 | | TK-9321 | | | (R-2)WC-5235<br>(L-1)WC-5345<br>(L-2)WC-5435 | | | | | (R-2)WC-5625<br>(L-1)WC-5725<br>(L-2)WC-5825 | | | 72.2-77.7<br><Wタイヤ><br>69.2-72.1 | BH-T681<br>BH-02576 | BH-44212<br>BH-31360-A | 72.2-77.7 | 3/4 | MC-10097 | MK-41400 | 72.2-77.7<br><JU10><br>69.2-70.10 | 3/4<br>15 | CC-70099<br>CC-70098 | CK-41480<br>FC-31480-B |
| | JU10D(ダンプ) | | | | | | 72.2-74.10 | 1 1/4 | (R-1)WC-5146<br>(R-2)WC-5237<br>(L-1)WC-5346<br>(L-2)WC-5436 | WK-100 | CUP | 72.2-74.10 | 1 1/4 | (R-1)WC-5536<br>(R-2)WC-5626<br>(L-1)WC-5726<br>(L-2)WC-5826 | WK-101 | CUP | 72.2-77.7 | BH-T681 | BH-44212 | | | | | 70.10-72.1<br>72.2-77.7 | 3/4<br>3/4 | CC-70099 | CK-41480<br>CK-41480 |
| | | | | | | | 74.10-77.7 | 1 1/4 | (R-1)WC-5146<br>(R-2)WC-5237<br>(L-1)WC-5346<br>(L-2)WC-5436<br>(R-1)ブリーダ付<br>(L-1)ブリーダ付 | WK-410 | CUP | 74.10-77.7 | 1 1/4 | (R-1)WC-5536<br>(R-2)WC-5626<br>(L-1)WC-5726<br>(L-2)WC-5826<br>(R-1)ブリーダ付<br>(L-1)ブリーダ付 | WK-412 | CUP | | | | | | | | | | | |
| (2500ディーゼル) | JU12D(ダンプ) | Wタイヤ | 69.2-72.1 | 1 1/4 | | MK-661 | 69.2-72.1 | 1 3/8 | (R-1)WC-5145<br>(R-2)WC-5235<br>(L-1)WC-5345<br>(L-2)WC-5435 | WK-085 | CUP | 69.2-72.1 | 1 3/8 | (R-1)WC-5535<br>(R-2)WC-5625<br>(L-1)WC-5725<br>(L-2)WC-5825 | WK-086 | CUP | 69.2-72.1 | BH-02576 | BH-31440 | 69.2-72.1 | 3/4 | | MK-41400 | 69.2-72.1 | 3/4 | | CK-41480 |
| | JU15(トラック) | Sタイヤ・Wタイヤ | 69.2-72.1 | 1 1/4 | | MK-661 | 69.2-72.1 | 1 3/8 | (R-1)WC-5145<br>(R-2)WC-5235<br>(L-1)WC-5345<br>(L-2)WC-5435<br>(R-1)ブリーダ付<br>(L-1)ブリーダ付 | WK-085 | CUP | 69.2-72.1 | 1 3/8 | (R-1)WC-5535<br>(R-2)WC-5625<br>(L-1)WC-5725<br>(L-2)WC-5825<br>(R-1)ブリーダ付<br>(L-1)ブリーダ付 | WK-086 | CUP | 69.2-72.1 | BH-02576 | BH-31440 | 69.2-72.1 | 3/4 | | MK-41400 | <オールシンクロ><br>69.2-72.1<br><Sタイヤ><br>69.2-70.10<br>70.10-72.1 | 3/4<br>15<br>3/4 | CC-70098 | CK-41480<br>FC-31480-B<br>CK-41480 |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| (3000ディーゼル) | Sタイヤ・Wタイヤ | 72.2-77.7 | 1 1/8 | | TK-9321 | 72.2-74.10 | 1 1/4 | (R-1)WC-5146<br>(R-2)WC-5237<br>(L-1)WC-5346<br>(L-2)WC-5436 | WK-100 | CUP | 72.2-74.10 | 1 1/4 | (R-1)WC-5536<br>(R-2)WC-5626<br>(L-1)WC-5726<br>(L-2)WC-5826 | WK-101 | CUP | <Sタイヤ><br>72.2-77.7<br><Wタイヤ> | BH-T681 | BH-44212 | 72.2-77.7 | 3/4 | MC-10097 | MK-41400 | 72.2-77.7 | 3/4 | CC-70101 | CK-41480 |
| BU10(トラック) | Wタイヤ | | | | | | | | | | | | | | | 72.2-74.9 | BH-T681 | BH-36212 | | | | | | | | |
| BU10D(ダンプ) | Sタイヤ | | | | | | | | | | | | | | | 74.9-77.7 | BH-T681 | BH-40012 | | | | | | | | |
| BU10P(Wキャブ) | | | | | | 74.10-77.7 | 1 1/4 | (R-1)WC-5146<br>(R-2)WC-5237<br>(L-1)WC-5346<br>(L-2)WC-5436 | WK-410 | CUP | 74.10-77.7 | 1 1/4 | (R-1)WC-5536<br>(R-2)WC-5626<br>(L-1)WC-5726<br>(L-2)WC-5826 | WK-412 | CUP | <ダンプ><br>72.2-74.1<br>74.1-77.7 | BH-T681<br>BH-T681 | BH-36212<br>BH-40012 | | | | | | | |
| BU12D(ダンプ) | Wタイヤ | 72.2-77.7 | 1 1/8 | | TK-9321 | 72.4-74.10 | 1 1/4 | (R-1)WC-5146<br>(R-2)WC-5237<br>(L-1)WC-5346<br>(L-2)WC-5436 | WK-100 | CUP | 72.2-74.10 | 1 1/4 | (R-1)WC-5536<br>(R-2)WC-5626<br>(L-1)WC-5726<br>(L-2)WC-5826 | WK-101 | CUP | 72.2-74.1<br>74.1-77.7 | BH-T681<br>BH-T681 | BH-44212<br>BH-40012 | 72.2-77.7 | 3/4 | MC-10097 | MK-41400 | 72.2-77.7 | 3/4 | CC-70101 | CK-41480 |
| | | | | | | 74.10-77.7 | 1 1/4 | (R-1)WC-5146<br>(R-2)WC-5237<br>(L-1)WC-5346<br>(L-2)WC-5436<br>(R-1)ﾌﾟﾘｰﾀﾞ付<br>(L-1)ﾌﾟﾘｰﾀﾞ付 | WK-410 | CUP | 74.10-77.7 | 1 1/4 | (R-1)WC-5536<br>(R-2)WC-5626<br>(L-1)WC-5726<br>(L-2)WC-5826<br>(R-1)ﾌﾟﾘｰﾀﾞ付<br>(L-1)ﾌﾟﾘｰﾀﾞ付 | WK-412 | CUP | | | | | | | | | |
| (3000ディーゼル) | Sタイヤ・Wタイヤ | 72.2-77.7 | 1 1/8 | | TK-9321 | 72.2-74.10 | 1 1/4 | (R-1)WC-5146<br>(R-2)WC-5237<br>(L-1)WC-5346<br>(L-2)WC-5436 | WK-100 | CUP | 72.2-74.10 | 1 1/4 | (R-1)WC-5536<br>(R-2)WC-5626<br>(L-1)WC-5726<br>(L-2)WC-5826 | WK-101 | CUP | 72.2-77.7 | BH-T681 | BH-44212 | 72.2-77.7 | 3/4 | MC-10097 | MK-41400 | 72.2-77.7 | 3/4 | CC-70101 | CK-41480 |
| BU15(トラック) | | | | | | 74.10-77.7 | 1 1/4 | (R-1)WC-5146<br>(R-2)WC-5237<br>(L-1)WC-5346<br>(L-2)WC-5436<br>(R-1)ﾌﾟﾘｰﾀﾞ付<br>(L-1)ﾌﾟﾘｰﾀﾞ付 | WK-410 | CUP | 74.10-77.7 | 1 1/4 | (R-1)WC-5536<br>(R-2)WC-5626<br>(L-1)WC-5726<br>(L-2)WC-5826<br>(R-1)ﾌﾟﾘｰﾀﾞ付<br>(L-1)ﾌﾟﾘｰﾀﾞ付 | WK-412 | CUP | | | | | | | | | |
| | | | | | | | | | | | <Sタイヤ LSPV付><br>73.9-74.10 | 1 3/8 | (R-1)WC-5535<br>(R-2)WC-5625<br>(L-1)WC-5725<br>(L-2)WC-5825 | WK-086 | CUP | | | | | | | | | |
| | | | | | | | | | | | 74.10-77.7 | 1 3/8 | (R-1)WC-5535<br>(R-2)WC-5625<br>(L-1)WC-5725<br>(L-2)WC-5825<br>(R-1)ﾌﾟﾘｰﾀﾞ付<br>(L-1)ﾌﾟﾘｰﾀﾞ付 | WK-306 | CUP | | | | | | | | | |
| (3600ディーゼル) | Wタイヤ | 69.8-72.1 | 1 1/4 | | MK-661 | 69.8-72.1 | 1 3/8 | (R-1)WC-5145<br>(R-2)WC-5235<br>(L-1)WC-5345<br>(L-2)WC-5435 | WK-085 | CUP | 69.8-72.1 | 1 3/8 | (R-1)WC-5535<br>(R-2)WC-5625<br>(L-1)WC-5725<br>(L-2)WC-5825 | WK-086 | CUP | 69.8-72.1 | BH-02576 | BH-31440 | 69.8-72.1 | 3/4 | | MK-41400 | 69.8-77.7 | 11/16 | | CK-3103 |
| HU15(トラック) | | 72.2-77.7 | 1 1/8 | | TK-9321 | | | | | | 72.2-74.10 | 1 1/4 | (R-1)WC-5146<br>(R-2)WC-5237<br>(L-1)WC-5346<br>(L-2)WC-5436 | WK-100 | CUP | 72.2-77.7 | BH-T681 | BH-44212 | 72.2-77.7 | 3/4 | MC-10097 | MK-41400 | | | | |
| | | | | | | 74.10-77.7 | 1 1/4 | (R-1)WC-5146<br>(R-2)WC-5237<br>(L-1)WC-5346<br>(L-2)WC-5436<br>(R-1)ﾌﾟﾘｰﾀﾞ付<br>(L-1)ﾌﾟﾘｰﾀﾞ付 | WK-410 | CUP | 74.10-77.7 | 1 1/4 | (R-1)WC-5536<br>(R-2)WC-5626<br>(L-1)WC-5726<br>(L-2)WC-5826<br>(R-1)ﾌﾟﾘｰﾀﾞ付<br>(L-1)ﾌﾟﾘｰﾀﾞ付 | WK-412 | CUP | | | | | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| DYNA : 20-50 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000) | J－RU20(トラック)<br>J－RU20V(バン) | Sタイヤ | 77.8-82.4 | 1 | | TK-9388 | 77.8-79.4<br><br><br><br>79.4-82.4 | 1 1/4<br><br><br><br>1 1/4 | (R-1)ﾌﾞﾘｰﾀﾞ付<br>(L-1)ﾌﾞﾘｰﾀﾞ付<br>(R-1)WC-5185<br>(R-2)WC-52015<br>(L-1)WC-5385<br>(L-2)WC-54015 | WK-407<br><br><br><br>WK-465 | CUP<br><br><br><br>CUP | 77.8-82.4 | 1 1/8 | (R-1)ﾌﾞﾘｰﾀﾞ付<br>(L-1)ﾌﾞﾘｰﾀﾞ付<br>(R-1)WC-55008<br>(R-2)WC-56008<br>(L-1)WC-57008<br>(L-2)WC-58008 | WK-409 | CUP | 77.8-80.8<br>80.8-82.1<br>82.1-82.4 | BH-02492<br>BH-31365<br>BH-31365 | BH-36212<br>BH-36212 | 77.8-82.4 | 5/8 | MC-10071 | MK-4300 | 77.8-81.5<br>81.5-82.4 | 13/16<br>13/16 | CC-70115<br>CC-70115 | CK-3115<br>CK-3128 |
| | J－RU20(トラック) | ジャストロー | 79.4-82.4 | 1 | | TK-9388 | 79.4-82.4 | 1 1/4 | | WK-465 | CUP | 79.4-82.4 | 1 | | WK-411 | CUP | 79.4-80.1<br>80.1-80.8<br>80.8-82.1<br>82.1-82.4 | BH-02492<br>BH-02492<br>BH-31365<br>BH-31365 | BH-40012<br>BH-38312<br>BH-38312 | 79.4-82.4 | 5/8 | MC-10071 | MK-4300 | 79.4-81.5<br>81.5-82.4 | 13/16<br>13/16 | CC-70115<br>CC-70115 | CK-3115<br>CK-3128 |
| | J－RU20(トラック)<br>J－RU20D(ダンプ) | Wタイヤ | 77.8-82.4 | 1 | | TK-9388 | 77.8-80.8<br>80.8-82.4 | 1 1/4<br>1 1/4 | | WK-410<br>WK-544 | CUP<br>CUP | 77.8-82.4<br><br><br><br><LSPV付><br>77.8-82.4 | 1 1/8<br><br><br><br><br>1 1/4 | (R-1)WC-55012<br>(R-2)WC-56012<br>(L-1)WC-57012<br>(L-2)WC-58012 | WK-413<br><br><br><br>WK-412 | CUP<br><br><br><br>CUP | 77.8-80.8<br>80.8-82.1<br>82.1-82.4 | BH-02492<br>BH-31365<br>BH-31365 | BH-44212<br>BH-44212<br>BH-97003 | 77.8-82.4 | 5/8 | MC-10071 | MK-4300 | 77.8-81.5<br>81.5-82.4 | 13/16<br>13/16 | CC-70115<br>CC-70115 | CK-3115<br>CK-3128 |
| (2000) | M－RU22(トラック)<br>M－RU22V(バン) | Sタイヤ | 82.4-84.8 | 1 | | TK-9388 | 82.4-84.8 | 1 1/4 | | WK-465 | CUP | 82.4-84.8 | 1 1/8 | (R-1)WC-55008<br>(R-2)WC-56008<br>(L-1)WC-57008<br>(L-2)WC-58008 | WK-409 | CUP | 82.4-84.8 | BH-31365 | BH-97001 | 82.4-84.8 | 5/8 | MC-10071 | MK-4300 | 82.4-84.8 | 13/16 | CC-70115 | CK-3128 |
| | M－RU22(トラック) | ジャストロー | 82.4-84.8 | 1 | | TK-9388 | 82.4-84.8 | 1 1/4 | | WK-465 | CUP | 82.4-84.8 | 1 | | WK-411 | CUP | 82.4-84.8 | BH-31365 | | 82.4-84.8 | 5/8 | MC-10071 | MK-4300 | 82.4-84.8 | 13/16 | CC-70115 | CK-3128 |
| (2000) | M－RU22(トラック)<br>M－RU22D(ダンプ) | Wタイヤ | 82.4-84.8 | 1 | | TK-9388 | 82.4-84.8 | 1 1/4 | | WK-544 | CUP | 82.4-84.8<br><br><br><br><LSPV付><br>82.4-84.8 | 1 1/8<br><br><br><br><br>1 1/4 | (R-1)WC-55012<br>(R-2)WC-56012<br>(L-1)WC-57012<br>(L-2)WC-58012 | WK-413<br><br><br><br>WK-412 | CUP<br><br><br><br>CUP | 82.4-84.8 | BH-31365 | BH-97003 | 82.4-84.8 | 5/8 | MC-10071 | MK-4300 | 82.4-84.8 | 13/16 | CC-70115 | CK-3128 |
| (2000) | J－RU30(トラック) | Sタイヤ | 77.8-80.8 | 1 | | TK-9388 | 77.8-79.4<br><br><br><br>79.4-80.8 | 1 1/4<br><br><br><br>1 1/4 | (R-1)ﾌﾞﾘｰﾀﾞ付<br>(L-1)ﾌﾞﾘｰﾀﾞ付<br>(R-1)WC-5185<br>(R-2)WC-52015<br>(L-1)WC-5385<br>(L-2)WC-54015 | WK-407<br><br><br><br>WK-465 | CUP<br><br><br><br>CUP | 77.8-80.8<br><br><br><br><LSPV付><br>77.8-80.8 | 1 1/8<br><br><br><br><br>1 1/4 | (R-1)ﾌﾞﾘｰﾀﾞ付<br>(L-1)ﾌﾞﾘｰﾀﾞ付<br>(R-1)WC-55008<br>(R-2)WC-56008<br>(L-1)WC-57008<br>(L-2)WC-58008<br><br>(R-1)WC-55009<br>(R-2)WC-56009<br>(L-1)WC-57009<br>(L-2)WC-58009 | WK-409<br><br><br><br>WK-408 | CUP<br><br><br><br>CUP | 77.8-80.8 | BH-02492 | BH-36212 | 77.8-80.8 | 5/8 | MC-10071 | MK-4300 | 77.8-80.8 | 13/16 | CC-70115 | CK-3115 |
| | | ジャストロー | 79.4-80.8 | 1 | | TK-9388 | 79.4-80.8 | 1 1/4 | | WK-465 | CUP | 79.4-80.8 | 1 1/8 | | WK-466 | CUP | 79.4-80.8 | BH-02492 | BH-38312 | 79.4-80.8 | 5/8 | MC-10071 | MK-4300 | 79.4-80.8 | 13/16 | CC-70115 | CK-3115 |
| | | Wタイヤ | 77.8-82.4 | 1 | | TK-9388 | 77.8-80.8<br>80.8-82.4 | 1 1/4<br>1 1/4 | | WK-410<br>WK-544 | CUP<br>CUP | 77.8-82.4 | 1 1/4 | | WK-412 | CUP | 77.8-80.8<br>80.8-82.1<br>82.1-82.4 | BH-02492<br>BH-31365<br>BH-31365 | BH-38312<br>BH-38312<br>BH-97003 | 77.8-82.4 | 5/8 | MC-10071 | MK-4300 | 77.8-81.5<br>81.5-82.4 | 13/16<br>13/16 | CC-70115<br>CC-70115 | CK-3115<br>CK-3128 |
| | M－RU32(トラック) | Wタイヤ | 82.4-84.8 | 1 | | TK-9388 | 82.4-84.8 | 1 1/4 | | WK-544 | CUP | 82.4-84.8 | 1 1/4 | | WK-412 | CUP | 82.4-84.8 | BH-31365 | BH-97003 | 82.4-84.8 | 5/8 | MC-10071 | MK-4300 | 82.4-84.8 | 13/16 | CC-70115 | CK-3128 |
| (2500ディーゼル) | K－JU20(トラック) | Sタイヤ | 77.8-80.8 | 1 | | TK-9388 | 77.8-79.4<br><br><br><br>79.4-80.8 | 1 1/4<br><br><br><br>1 1/4 | (R-1)WC-5185<br>(R-2)WC-52015<br>(L-1)WC-5385<br>(L-2)WC-54015<br><br>(R-1)ﾌﾞﾘｰﾀﾞ付<br>(L-1)ﾌﾞﾘｰﾀﾞ付 | WK-407<br><br><br><br>WK-465 | CUP<br><br><br><br>CUP | 77.8-80.8 | 1 1/8 | (R-1)WC-55008<br>(R-2)WC-56008<br>(L-1)WC-57008<br>(L-2)WC-58008<br>(R-1)ﾌﾞﾘｰﾀﾞ付<br>(L-1)ﾌﾞﾘｰﾀﾞ付 | WK-409 | CUP | 77.8-80.8 | BH-02492 | BH-36212 | 77.8-80.8 | 5/8 | MC-10071 | MK-4300 | 77.8-80.8 | 13/16 | CC-70116 | CK-3116 |
| (3000ディーゼル) | K－BU20(トラック)<br>K－BU20V(バン)<br>K－BU20HV(ハイルーフバン)<br>K－BU20K(クレーン) | Sタイヤ | 77.8-83.2 | 1 | | TK-9388 | 77.8-79.4<br><br><br><br>79.4-83.2 | 1 1/4<br><br><br><br>1 1/4 | (R-1)WC-5185<br>(R-2)WC-52015<br>(L-1)WC-5385<br>(L-2)WC-54015<br><br>(R-1)ﾌﾞﾘｰﾀﾞ付<br>(L-1)ﾌﾞﾘｰﾀﾞ付 | WK-407<br><br><br><br>WK-465 | CUP<br><br><br><br>CUP | 77.8-83.2 | 1 1/8 | (R-1)WC-55008<br>(R-2)WC-56008<br>(L-1)WC-57008<br>(L-2)WC-58008<br>(R-1)ﾌﾞﾘｰﾀﾞ付<br>(L-1)ﾌﾞﾘｰﾀﾞ付 | WK-409 | CUP | 77.8-80.8<br>80.8-82.1<br>82.1-82.4<br>82.4-83.2 | BH-02492<br>BH-31365<br>BH-31365<br>BH-31365 | BH-36212<br>BH-36212<br><br>BH-97001 | 77.8-83.2 | 5/8 | MC-10071 | MK-4300 | 77.8-81.5<br>81.5-83.2 | 13/16<br>13/16 | CC-70118<br>CC-70118 | CK-3115<br>CK-3128 |
| | K－BU20(トラック) | ジャストロー | 77.8-83.2 | 1 | | TK-9388 | 77.8-79.4<br><br><br><br>79.4-83.2 | 1 1/4<br><br><br><br>1 1/4 | (R-1)WC-5185<br>(R-2)WC-52015<br>(L-1)WC-5385<br>(L-2)WC-54015 | WK-407<br><br><br><br>WK-465 | CUP<br><br><br><br>CUP | 77.8-83.2 | 1 | | WK-411 | CUP | 77.8-80.1<br>80.1-80.8<br>80.8-82.1<br>82.1-83.2 | BH-02492<br>BH-02492<br>BH-31365<br>BH-31365 | BH-40012<br>BH-38312<br>BH-38312 | 77.8-83.2 | 5/8 | MC-10071 | MK-4300 | 77.8-81.5<br>81.5-83.2 | 13/16<br>13/16 | CC-70118<br>CC-70118 | CK-3115<br>CK-3128 |
| | K－BU20(トラック)<br>K－BU20H(トラック)<br>K－BU20D(ダンプ)<br>K－BU25D(ダンプ) | Wタイヤ | 77.8-83.2 | 1 | | TK-9388 | 77.8-80.8<br>80.8-83.2 | 1 1/4<br>1 1/4 | | WK-410<br>WK-544 | CUP<br>CUP | 77.8-83.2<br><br><br><br><LSPV付><br>77.8-83.2 | 1 1/8<br><br><br><br><br>1 1/4 | (R-1)WC-55012<br>(R-2)WC-56012<br>(L-1)WC-57012<br>(L-2)WC-58012 | WK-413<br><br><br><br>WK-412 | CUP<br><br><br><br>CUP | 77.8-80.8<br>80.8-82.1<br>82.1-83.4<br><三転式ダンプ><br>77.8-80.1<br>80.1-80.8<br>80.8-82.1<br>82.1-82.4 | BH-02492<br>BH-31365<br>BH-31365<br><br>BH-02492<br>BH-02492<br>BH-31365<br>BH-31365 | BH-44212<br>BH-44212<br>BH-97003<br><br>BH-40012<br>BH-38312<br>BH-38312 | 77.8-83.2 | 5/8 | MC-10071 | MK-4300 | 77.8-81.5<br>81.5-83.2 | 13/16<br>13/16 | CC-70118<br>CC-70118 | CK-3115<br>CK-3128 |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| (3000ディーゼル)<br>N－BU22(トラツク)<br>N－BU22V(バン)<br>N－BU22HV(ハイルーフバン)<br>N－BU22K(クレーン) | Sタイヤ | 83.2-84.8 | 1 | | TK-9388 | 83.2-84.8 | 1 1/4 | | WK-465 | CUP | 83.2-84.8 | 1 1/8 | (R-1)WC-55008<br>(R-2)WC-56008<br>(L-1)WC-57008<br>(L-2)WC-58008<br>(R-1)ﾌﾟﾘｰﾀﾞ付<br>(L-1)ﾌﾟﾘｰﾀﾞ付 | WK-409 | CUP | 83.2-84.8 | BH-31365 | BH-97001 | 83.2-84.8 | 5/8 | MC-10071 | MK-4300 | 83.2-84.8 | 13/16 | CC-70118 | CK-3128 |
| N－BU22(トラック) | ジャストロー | 83.2-84.8 | 1 | | TK-9388 | 83.2-84.8 | 1 1/4 | | WK-465 | CUP | 83.2-84.8 | 1 | | WK-411 | CUP | 83.2-84.8 | BH-31365 | | 83.2-84.8 | 5/8 | MC-10071 | MK-4300 | 83.2-84.8 | 13/16 | CC-70118 | CK-3128 |
| | Wタイヤ | 83.2-84.8 | 1 | | TK-9388 | 83.2-84.8 | 1 1/4 | | WK-544 | CUP | 83.2-84.8<br><LSPV付><br>83.2-84.8 | 1 1/8<br><br>1 1/4 | (R-1)WC-55012<br>(R-2)WC-56012<br>(L-1)WC-57012<br>(L-2)WC-58012 | WK-413<br><br>WK-412 | CUP<br><br>CUP | 83.2-84.8 | BH-31365 | BH-97003 | 83.2-84.8 | 5/8 | MC-10071 | MK-4300 | 83.2-84.8 | 13/16 | CC-70118 | CK-3128 |
| (3000ディーゼル)<br>K－BU30(トラック) | Sタイヤ | 77.8-80.8 | 1 | | TK-9388 | 77.8-79.4<br><br>79.4-80.8 | 1 1/4<br><br>1 1/4 | (R-1)ﾌﾟﾘｰﾀﾞ付<br>(L-1)ﾌﾟﾘｰﾀﾞ付<br>(R-1)WC-5185<br>(R-2)WC-52015<br>(L-1)WC-5385<br>(L-2)WC-54015 | WK-407<br><br>WK-465 | CUP<br><br>CUP | 77.8-80.8<br><LSPV付><br>77.8-80.8 | 1 1/8<br><br>1 1/4 | (R-1)WC-55008<br>(R-2)WC-56008<br>(L-1)WC-57008<br>(L-2)WC-58008<br><br>(R-1)WC-55009<br>(R-2)WC-56009<br>(L-1)WC-57009<br>(L-2)WC-58009 | WK-409<br><br>WK-408 | CUP<br><br>CUP | 77.8-80.8 | BH-02492 | BH-36212 | 77.8-80.8 | 5/8 | MC-10071 | MK-4300 | 77.8-80.8 | 13/16 | CC-70118 | CK-3115 |
| | ジャストロー | 79.4-83.2 | 1 | | TK-9388 | 79.4-83.2 | 1 1/4 | | WK-465 | CUP | 79.4-83.2 | 1 1/8 | | WK-466 | CUP | 79.4-80.8<br>80.8-82.1<br>82.1-83.2 | BH-02492<br>BH-31365<br>BH-31365 | BH-38312<br>BH-38312<br>BH-97003 | 79.4-83.2 | 5/8 | MC-10071 | MK-4300 | 79.4-81.5<br>81.5-83.5 | 13/16<br>13/16 | CC-70118<br>CC-70118 | CK-3115<br>CK-3128 |
| K－BU30(トラック) | Wタイヤ | 77.8-82.4 | 1 | | TK-9388 | 77.8-80.8<br>80.8-82.4 | 1 1/4<br>1 1/4 | | WK-410<br>WK-544 | CUP<br>CUP | 77.8-82.4 | 1 1/4 | | WK-412 | CUP | 77.8-80.8<br>80.8-82.1<br>82.1-82.4 | BH-02492<br>BH-31365<br>BH-31365 | BH-38312<br>BH-38312<br>BH-97003 | 77.8-82.4 | 5/8 | MC-10071 | MK-4300 | 77.8-81.5<br>81.5-82.4 | 13/16<br>13/16 | CC-70118<br>CC-70118 | CK-3115<br>CK-3128 |
| N－BU33 | ジャストロー | 83.2-84.8 | 1 | | TK-9388 | 83.2-84.8 | 1 1/4 | | WK-465 | CUP | 83.2-84.8 | 1 1/8 | | WK-466 | CUP | 83.2-84.8 | BH-31365 | BH-97003 | 83.2-84.8 | 5/8 | MC-10071 | MK-4300 | 83.2-84.8 | 13/16 | CC-70118 | CK-3128 |
| K－BU35(トラック) | ジャストロー | 80.8-82.4 | 1 | | TK-9388 | 80.8-82.4 | 1 1/4 | | WK-465 | CUP | 80.8-82.4 | 1 1/8 | | WK-466 | CUP | 80.8-82.1<br>82.1-82.4 | BH-95000<br>BH-95000 | BH-38312<br>BH-97003 | 80.8-82.4 | 5/8 | MC-10071 | MK-4300 | 80.8-81.5<br>81.5-82.4 | 13/16<br>13/16 | CC-70118<br>CC-70118 | CK-3115<br>CK-3128 |
| | Wタイヤ | 80.8-82.4 | 1 | | TK-9388 | 80.8-82.4 | 1 1/4 | | WK-544 | CUP | 80.8-82.4 | 1 1/4 | | WK-412 | CUP | 80.8-82.1<br>82.1-82.4 | BH-95000<br>BH-95000 | BH-38312<br>BH-97003 | 80.8-82.4 | 5/8 | MC-10071 | MK-4300 | 80.8-81.5<br>81.5-82.5 | 13/16<br>13/16 | CC-70118<br>CC-70118 | CK-3115<br>CK-3128 |
| (3200ディーゼル)<br>K－BU31(トラック) | Wタイヤ | 79.4-80.8 | 1 | | TK-9388 | 79.4-80.8 | 1 1/4 | | WK-410 | CUP | 79.4-80.8 | 1 1/4 | | WK-412 | CUP | 79.4-80.8 | BH-02492 | BH-38312 | 79.4-80.8 | 5/8 | MC-10071 | MK-4300 | 79.4-80.8 | 13/16 | CC-70118 | CK-3115 |
| (3400ディーゼル)<br>K－BU21(トラック)<br>K－BU21H(トラック)<br>K－BU21D(ダンプ) | Wタイヤ | 82.4-83.2 | 1 | | TK-9388 | 82.4-83.2 | 1 1/4 | | WK-544 | CUP | 82.4-83.2<br><LSPV付><br>82.4-83.2 | 1 1/8<br><br>1 1/4 | (R-1)WC-55012<br>(R-2)WC-56012<br>(L-1)WC-57012<br>(L-2)WC-58012 | WK-413<br><br>WK-412 | CUP<br><br>CUP | 82.4-83.2<br><三転式ﾀﾞﾝﾌﾟ><br>82.4-83.2 | BH-31365<br><br>BH-31365 | BH-97003 | 82.4-83.2 | 5/8 | MC-10071 | MK-4300 | 82.4-83.2 | 13/16 | CC-70118 | CK-3128 |
| (3400ディーゼル)<br>N－BU23(トラック)<br>N－BU23H(トラック)<br>N－BU23D(ダンプ) | Wタイヤ | 83.2-84.8 | 1 | | TK-9388 | 83.2-84.8 | 1 1/4 | | WK-544 | CUP | 83.2-84.8<br><LSPV付><br>83.2-84.8 | 1 1/8<br><br>1 1/4 | (R-1)WC-55012<br>(R-2)WC-56012<br>(L-1)WC-57012<br>(L-2)WC-58012 | WK-413<br><br>WK-412 | CUP<br><br>CUP | 83.2-84.8<br><三転式ﾀﾞﾝﾌﾟ><br>83.2-84.8 | BH-31365<br><br>BH-31365 | BH-97003 | 83.2-84.8 | 5/8 | MC-10071 | MK-4300 | 83.2-84.8 | 13/16 | CC-70118 | CK-3128 |
| K－BU32(トラック) | Wタイヤ | 82.4-83.2 | 1 | | TK-9388 | 82.4-83.2 | 1 1/4 | | WK-544 | CUP | 82.4-83.2 | 1 1/4 | | WK-412 | CUP | 82.4-83.2 | BH-31365 | BH-97003 | 82.4-83.2 | 5/8 | MC-10071 | MK-4300 | 82.4-83.2 | 13/16 | CC-70118 | CK-3128 |
| N－BU34(トラック) | Wタイヤ | 83.2-84.8 | 1 | | TK-9388 | 83.2-84.8 | 1 1/4 | | WK-544 | CUP | 83.2-84.8 | 1 1/4 | | WK-412 | CUP | 83.2-84.8 | BH-31365 | BH-97003 | 83.2-84.8 | 5/8 | MC-10071 | MK-4300 | 83.2-84.8 | 13/16 | CC-70118 | CK-3128 |
| K－BU36(トラック)<br>K－BU36V(バン)<br>K－BU45(トラック) | Wタイヤ<br>ディスク車 | 82.4-83.2 | 1 1/16 | | TK-9435 | 82.4-83.2 | 51.1 | DISC | MP-8 | CPM-8 | 82.4-83.2 | 1 1/8 | | WK-413 | CUP | 82.4-83.2 | (1)BH-31404<br>(2)BH-02431 | BH-97003 | 82.4-83.2 | 5/8 | MC-10071 | MK-4300 | 82.4-83.2 | 13/16 | CC-70118 | CK-3128 |
| | Wタイヤ<br>ドラム車 | 80.9-82.4<br>82.4-83.2 | 1<br>1 1/16 | <br>TD-T394 | TK-9388<br>TK-9434 | 80.9-83.2 | 1 1/4 | | WK-544 | CUP | 80.9-83.2 | 1 1/4 | | WK-412 | CUP | 80.9-82.1<br>82.1-83.2 | BH-95000<br>BH-95000 | BH-38312<br>BH-97003 | 80.9-83.2 | 5/8 | MC-10071 | MK-4300 | 80.9-81.5<br>81.5-83.2 | 13/16<br>13/16 | CC-70118<br>CC-70118 | CK-3115<br>CK-3128 |
| | ジャストロー | 82.4-83.2 | 1 1/16 | TD-T394 | TK-9434 | 82.4-83.2 | 1 1/4 | | WK-465 | CUP | 82.4-83.2 | 1 1/8 | | WK-466 | CUP | 82.4-83.2 | BH-95000 | BH-97003 | 82.4-83.2 | 5/8 | MC-10071 | MK-4300 | 82.4-83.2 | 13/16 | CC-70118 | CK-3128 |
| N－BU37(トラック)<br>N－BU37V(バン)<br>N－BU46(トラック) | Wタイヤ<br>ディスク車 | 83.2-83.9 | 1 1/16 | | TK-9435 | 83.2-83.9 | 51.1 | DISC | MP-8 | CPM-8 | 83.2-83.9 | 1 1/8 | | WK-413 | CUP | 83.2-83.9 | (1)BH-31404<br>(2)BH-02431 | BH-97003 | 83.2-83.9 | 5/8 | MC-10071 | MK-4300 | 83.2-83.9 | 13/16 | CC-70118 | CK-3128 |
| | Wタイヤ<br>ドラム車 | 83.2-84.8 | 1 1/16 | TD-T394 | TK-9434 | 83.2-84.8 | 1 1/4 | | WK-544 | CUP | 83.2-84.8 | 1 1/4 | | WK-412 | CUP | 83.2-84.8 | BH-95000 | BH-97003 | 83.2-84.8 | 5/8 | MC-10071 | MK-4300 | 83.2-84.8 | 13/16 | CC-70118 | CK-3128 |
| | ジャストロー | 83.2-84.8 | 1 1/16 | TD-T394 | TK-9434 | 83.2-84.8 | 1 1/4 | | WK-465 | CUP | 83.2-84.8 | 1 1/8 | | WK-466 | CUP | 83.2-84.8 | BH-95000 | BH-97003 | 83.2-84.8 | 5/8 | MC-10071 | MK-4300 | 83.2-84.8 | 13/16 | CC-70118 | CK-3128 |
| K－BU40(トラック)<br>K－BU50(トラック) | Wタイヤ | 82.4-83.2 | 1 1/8 | TD-T393 | TK-9436 | 82.4-83.2 | 1 5/16 | | WK-585 | CUP | 82.4-83.2 | 1 1/4 | | WK-412 | CUP | 82.4-83.2 | BH-95004 | BH-97000 | 82.4-83.2 | 5/8 | MC-10071 | MK-4300 | 82.4-83.2 | 13/16 | CC-70118 | CK-3128 |
| N－BU41(トラック)<br>N－BU51(トラック) | Wタイヤ | 83.2-84.8 | 1 1/8 | TD-T393 | TK-9436 | 83.2-84.8 | 1 5/16 | | WK-585 | CUP | 83.2-84.8 | 1 1/4 | | WK-412 | CUP | 83.2-84.8 | BH-95004 | BH-97000 | 83.2-84.8 | 5/8 | MC-10071 | MK-4300 | 83.2-84.8 | 13/16 | CC-70118 | CK-3128 |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| (3600ディーゼル) | Wタイヤ | 77.8-80.8 | 1 | | TK-9388 | 77.8-80.8 | 1 1/4 | | WK-410 | CUP | 77.8-80.8 | 1 1/4 | | WK-412 | CUP | 77.8-80.8 | BH-02492 | BH-38312 | 77.8-80.8 | 5/8 | MC-10071 | MK-4300 | 77.8-80.8 | 3/4 | CC-70117 | CK-3117 |
| K－HU30(トラック) | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (4000ディーゼル) | Wタイヤ | 82.4-83.4 | 1 1/8 | TD-T393 | TK-9436 | 82.4-83.4 | 1 5/16 | | WK-585 | CUP | 82.4-83.4 | 1 1/4 | | WK-412 | CUP | 82.4-83.4 | BH-95004 | BH-97000 | 82.4-83.4 | 5/8 | MC-10071 | MK-4300 | 82.4-83.4 | 3/4 | CC-70160 | CK-3117 |
| N－HU40・50(トラック) | | | | | | | | | | | | | | | | | | | | | | | | | | |
| P－WU40・50(トラック) | Wタイヤ | 83.4-84.8 | 1 1/8 | TD-T393 | TK-9436 | 83.4-84.8 | 1 5/16 | | WK-585 | CUP | 83.4-84.8 | 1 1/4 | | WK-412 | CUP | 83.4-84.8 | BH-95004 | BH-97000 | 83.4-84.8 | 5/8 | MC-10071 | MK-4300 | 83.4-84.4<br>84.4-84.8 | 3/4<br>3/4 | CC-70167<br>CC-70167 | CK-3132<br>CK-3134 |
| N－HU26D(ダンプ) | Wタイヤ | 82.4-83.4 | 1 1/8 | TD-T393 | TK-9436 | 82.4-83.4 | 1 5/16 | | WK-585 | CUP | 82.4-83.4 | 1 1/4 | | WK-412 | CUP | 82.4-83.4 | BH-95004 | BH-97000 | 82.4-83.4 | 5/8 | MC-10071 | MK-4300 | 82.4-83.4 | 3/4 | CC-70160 | CK-3117 |
| P－WU26D(ダンプ) | Wタイヤ | 83.4-84.8 | 1 1/8 | TD-T393 | TK-9436 | 83.4-84.8 | 1 5/16 | | WK-585 | CUP | 83.4-84.8 | 1 1/4 | | WK-412 | CUP | 83.4-84.8 | BH-95004 | BH-97000 | 83.4-84.8 | 5/8 | MC-10071 | MK-4300 | 83.4-84.4<br>84.4-84.8 | 3/4<br>3/4 | CC-70167<br>CC-70167 | CK-3132<br>CK-3134 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| DYNA, TOYOACE : YU ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000)<br>(L. P. G含む) | M－YU60<br>T－YU60<br>Z－YU60<br><T－は90. 8～><br><Z－は93. 9～> | 低床・高床（Sタイヤ）<br>Wキャブ（Sタイヤ）<br>ジャストロー（Wタイヤ）<br>Wキャブジャストロー（Wタイヤ） | 84.9-95.5 | 1 | TD-T397 | TK-9452 | 84.9-93.3<br>93.3-95.5 | 1 1/8<br>1 1/8 | | WK-635<br>WK-814 | CUP<br>CUP | 84.9-95.5 | 1 | | WK-637 | CUP | 84.9-95.5<br><Wタイヤ><br>84.9-95.5 | BH-02220<br><br>BH-02220 | BH-40012<br><br>BH-97001 | 84.9-87.8<br>87.8-95.5 | 5/8<br>5/8 | MC-10132<br>MC-T331 | MK-4328<br>MK-4351 | 84.9-85.8<br>85.8-90.6<br>90.6-90.11<br>90.11-95.5 | 13/16<br>13/16<br>13/16<br>13/16 | CC-70165<br>CC-70189<br>CC-70189 | CK-3144<br>CK-3144<br>CK-3144<br>CK-T201 |
| | | 高床（Wタイヤ）<br>ドラム車 | 84.9-95.5 | 1 | TD-T397 | TK-9452 | 84.9-93.3<br>93.3-95.5 | 1 1/8<br>1 1/8 | | WK-634<br>WK-811 | CUP<br>CUP | 84.9-95.5<br><塵芥車><br>86.7-93.3<br>93.3-95.5 | 1<br><br>1 1/8<br>1 1/8 | | WK-638<br><br>WK-413<br>WK-812 | CUP<br><br>CUP<br>CUP | 84.9-95.5 | BH-95002 | BH-40012 | 84.9-87.8<br>87.8-95.5 | 5/8<br>5/8 | MC-10132<br>MC-T331 | MK-4328<br>MK-4351 | 84.9-85.8<br>85.8-90.6<br>90.6-90.11<br>90.11-95.5 | 13/16<br>13/16<br>13/16<br>13/16 | CC-70165<br>CC-70189<br>CC-70189 | CK-3144<br>CK-3144<br>CK-3144<br>CK-T201 |
| | | ディスク車 | 87.8-95.5 | 1 1/16 | | TK-T031 | 87.8-91.9<br>91.9-95.5 | 51.1<br>51.1 | DISC<br>DISC | MP-8<br>MP-8 | CPM-8<br>CPM-8 | 87.8-93.3<br>93.3-95.5 | 1 1/8<br>1 1/8 | | WK-641<br>WK-813 | CUP<br>CUP | 87.8-95.5 | (1)BH-T681<br>(2)BH-02431 | BH-40012 | 87.8-95.5 | 5/8 | MC-T331 | MK-4351 | 87.8-90.6<br>90.6-90.11<br>90.11-95.5 | 13/16<br>13/16<br>13/16 | CC-70189<br>CC-70189 | CK-3144<br>CK-3144<br>CK-T201 |
| | M－YU61D<br>T－YU61D<br><T－は90. 8～> | ダンプ（Wタイヤ） | 86.1-93.9 | 1 | | TK-9452 | 86.1-93.3<br>93.3-93.9 | 1 1/8<br>1 1/8 | | WK-634<br>WK-811 | CUP<br>CUP | 86.1-93.9 | 1 | | WK-638 | CUP | 86.1-93.9 | BH-95002 | BH-36212 | 86.1-87.8<br>87.8-93.9 | 5/8<br>5/8 | MC-10132<br>MC-T331 | MK-4328<br>MK-4351 | 86.1-90.6<br>90.6-90.11<br>90.11-93.9 | 13/16<br>13/16<br>13/16 | CC-70189<br>CC-70189 | CK-3144<br>CK-3144<br>CK-T201 |
| (2000) | M－YU70V<br>T－YU70V<br><T－は90. 8～> | バン（Sタイヤ） | 84.9-93.9 | 1 | TD-T397 | TK-9452 | 84.9-93.3<br>93.3-93.9 | 1 1/8<br>1 1/8 | | WK-635<br>WK-814 | CUP<br>CUP | 84.9-93.9 | 1 | | WK-637 | CUP | 84.9-93.9 | BH-02220 | BH-40012 | 84.9-87.8<br>87.8-93.9 | 5/8<br>5/8 | MC-10132<br>MC-T331 | MK-4328<br>MK-4351 | 84.9-85.8<br>85.8-90.6<br>90.6-90.11<br>90.11-93.9 | 13/16<br>13/16<br>13/16<br>13/16 | CC-70165<br>CC-70189<br>CC-70189 | CK-3144<br>CK-3144<br>CK-3144<br>CK-T201 |
| (2000L. P. G) | M－YU80(2t) | 高床（Wタイヤ）<br>ドラム車 | 84.9-87.8 | 1 | TD-T397 | TK-9452 | 84.9-87.8 | 1 1/8 | | WK-634 | CUP | 84.9-87.8 | 1 1/8 | | WK-413 | CUP | 84.9-87.8 | BH-95002 | BH-40012 | 84.9-87.8 | 5/8 | MC-10132 | MK-4328 | 84.9-85.8<br>85.8-87.8 | 13/16<br>13/16 | CC-70165<br>CC-70189 | CK-3144<br>CK-3144 |
| | | ディスク車 | 84.9-87.8 | 1 1/16 | TD-T395 | TK-9453 | 84.9-87.8 | 51.1 | DISC | MP-8 | CPM-8 | 84.9-87.8 | 1 1/8 | | WK-641 | CUP | 84.9-87.8 | (1)BH-T681<br>(2)BH-02431 | BH-40012 | 84.9-87.8 | 5/8 | MC-10132 | MK-4328 | 84.9-85.8<br>85.8-87.8 | 13/16<br>13/16 | CC-70165<br>CC-70189 | CK-3144<br>CK-3144 |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| DYNA, TOYOACE : BU60-70 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (3000ディーゼル) | 低床・高床(Sタイヤ) | 84.9-95.5 | 1 | | TK-9452 | 84.9-93.3 | 1 1/8 | (R-1) | WK-635 | CUP | 84.9-95.5 | 1 | | WK-637 | CUP | 84.9-95.5 | BH-02220 | BH-40012 | <ブースター無> | | | | | | | |
| BU60(1．75t) | Wキャブ(Sタイヤ) | | | | | | | (R-2) | | | <オートアジャスター付> | | | | | | | | 84.9-87.8 | 5/8 | MC-10132 | MK-4328 | 84.9-85.8 | 13/16 | CC-70162 | CK-3136 |
| BU70V・70VH(1．75t) | バン(Sタイヤ) | | | | | | | (L-1) | | | 84.9-95.5 | 1 | | WK-640 | CUP | | | | 87.8-95.5 | 5/8 | MC-T331 | MK-4351 | 85.8-88.8 | 13/16 | CC-70178 | CK-3144 |
| BU61(2t) | | | | | | | | (L-2) | | | | | | | | | | | <ブースター付> | | | | 88.8-94.8 | 3/4 | CC-70185 | CK-T218 |
| BU60・61(1．75t・2t) | | | | | | 93.3-95.5 | 1 1/8 | (R-1) | WK-814 | CUP | | | | | | | | | 84.9-87.8 | 5/8 | MC-10135 | MK-4320 | 94.8-95.5 | 3/4 | CC-70185 | CK-T218 |
| BU70V・70VH(1．75t) | | | | | | | | (R-2) | | | | | | | | | | | 87.8-88.11 | 5/8 | MC-10135 | MK-T200 | | | | |
| ＜N・Pーは84．9～＞ | | | | | | | | (L-1) | | | | | | | | | | | 88.11-89.10 | 5/8 | MC-10135 | MK-4353 | | | | |
| ＜Uーは88．8～＞ | | | | | | | | (L-2) | | | | | | | | | | | 89.10-95.5 | 5/8 | MC-T368 | MK-T206 | | | | |
| | | | | | | <オートアジャスター付> | | | | | | | | | | | | | | | | | | | | |
| | | | | | | 84.9-93.3 | 1 1/8 | (R-1) | WK-636 | CUP | | | | | | | | | | | | | | | | |
| | | | | | | | | (R-2) | | | | | | | | | | | | | | | | | | |
| | | | | | | | | (L-1) | | | | | | | | | | | | | | | | | | |
| | | | | | | | | (L-2) | | | | | | | | | | | | | | | | | | |
| | | | | | | 93.3-95.5 | 1 1/8 | (R-1) | WK-815 | CUP | | | | | | | | | | | | | | | | |
| | | | | | | | | (R-2) | | | | | | | | | | | | | | | | | | |
| | | | | | | | | (L-1) | | | | | | | | | | | | | | | | | | |
| | | | | | | | | (L-2) | | | | | | | | | | | | | | | | | | |
| (3000ディーゼル) | 高床(Wタイヤ) | 84.9-95.5 | 1 | | TK-9452 | 84.9-93.3 | 1 1/8 | (R-1) | WK-634 | CUP | 84.9-95.5 | 1 | | WK-638 | CUP | 84.9-95.5 | BH-95002 | BH-40012 | <ブースター無> | | | | | | | |
| Nー BU60(2t) | ドラム車 | | | | | | | (R-2) | | | <オートアジャスター付> | | | | | | | | 84.9-87.8 | 5/8 | MC-10132 | MK-4328 | 84.9-85.8 | 13/16 | CC-70162 | CK-3136 |
| Uー BU60(2t) | | | | | | | | (L-1) | | | 93.9-95.5 | 1 | | WK-688 | CUP | | | | 87.8-95.5 | 5/8 | MC-T331 | MK-4351 | 85.8-88.8 | 13/16 | CC-70178 | CK-3144 |
| ＜Uーは88．8～＞ | | | | | | | | (L-2) | | | <塵芥車> | | | | | | | | <ブースター付> | | | | 88.8-94.8 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | 93.3-95.5 | 1 1/8 | (R-1) | WK-811 | CUP | 84.9-93.3 | 1 1/8 | | WK-413 | CUP | | | | 88.8-88.11 | 5/8 | MC-10135 | MK-T200 | 94.8-95.5 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | | (R-2) | | | 93.3-95.5 | 1 1/8 | | WK-812 | CUP | | | | 88.11-89.10 | 5/8 | MC-10135 | MK-4353 | | | | |
| | | | | | | | | (L-1) | | | | | | | | | | | 89.10-95.5 | 5/8 | MC-T368 | MK-T206 | | | | |
| | | | | | | | | (L-2) | | | | | | | | | | | | | | | | | | |
| | | | | | | <オートアジャスター付> | | | | | | | | | | | | | | | | | | | | |
| | | | | | | 93.9-95.5 | 1 1/8 | (R-1) | WK-817 | CUP | | | | | | | | | | | | | | | | |
| | | | | | | | | (R-2) | | | | | | | | | | | | | | | | | | |
| | | | | | | | | (L-1) | | | | | | | | | | | | | | | | | | |
| | | | | | | | | (L-2) | | | | | | | | | | | | | | | | | | |
| | ディスク車 | 87.8-95.5 | 1 1/16 | | TK-T031 | 87.8-91.9 | 51.1 | DISC | MP-8 | | 87.8-93.3 | 1 1/8 | | WK-641 | CUP | 87.8-95.5 | (1)BH-T681 | BH-40012 | <ブースター無> | | | | | | | |
| | | | | | | 87.8-95.5 | 51.1 | DISC | MP-8 | | 93.3-95.5 | 1 1/8 | | WK-813 | CUP | | (2)BH-02431 | | 87.8-95.5 | 5/8 | MC-T331 | MK-4351 | 87.8-88.8 | 13/16 | CC-70178 | CK-3144 |
| | | | | | | | | | | | | | | | | | | | <ブースター付> | | | | 88.8-94.8 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | | | | | | | | | | | | | 87.8-88.11 | 5/8 | MC-10135 | MK-T200 | 94.8-95.5 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | | | | | | | | | | | | | 88.11-89.10 | 5/8 | MC-10135 | MK-4353 | | | | |
| | | | | | | | | | | | | | | | | | | | 89.10-95.5 | 5/8 | MC-T368 | MK-T206 | | | | |
| (3000ディーゼル) | ジャストロー(Wタイヤ) | 84.9-95.5 | 1 | | TK-9452 | 84.9-93.3 | 1 1/8 | (R-1) | WK-635 | CUP | 84.9-95.5 | 1 | | WK-637 | CUP | 84.9-95.5 | BH-02220 | BH-97001 | <ブースター無> | | | | | | | |
| Nー BU60(2t) | フルジャストロー(Wタイヤ) | | | | | | | (R-2) | | | <オートアジャスター付> | | | | | <フルジャストロー> | | | 84.9-87.8 | 5/8 | MC-10132 | MK-4328 | 84.9-85.8 | 13/16 | CC-70162 | CK-3136 |
| Pー BU61(2t) | ドラム車 | | | | | | | (L-1) | | | 84.9-95.5 | 1 | | WK-640 | CUP | 84.9-91.2 | BH-T527 | BH-97001 | 87.8-95.5 | 5/8 | MC-T331 | MK-4351 | 85.8-88.8 | 13/16 | CC-70178 | CK-3144 |
| Uー BU60・61(2t) | | | | | | | | (L-2) | | | | | | | | 91.2-95.5 | (R) | BH-97001 | <ブースター付> | | | | 88.8-94.8 | 3/4 | CC-70185 | CK-T218 |
| ＜Uーは88．8～＞ | | | | | | 93.3-95.5 | 1 1/8 | (R-1) | WK-814 | CUP | | | | | | | (L) | | 84.9-87.8 | 5/8 | MC-10135 | MK-4320 | 94.8-95.5 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | | (R-2) | | | | | | | | | | | 87.8-88.11 | 5/8 | MC-10135 | MK-T200 | | | | |
| | | | | | | | | (L-1) | | | | | | | | | | | 88.11-89.10 | 5/8 | MC-10135 | MK-4353 | | | | |
| | | | | | | | | (L-2) | | | | | | | | | | | 89.10-95.5 | 5/8 | MC-T368 | MK-T206 | | | | |
| | | | | | | <オートアジャスター付> | | | | | | | | | | | | | | | | | | | | |
| | | | | | | 84.9-93.3 | 1 1/8 | (R-1) | WK-636 | CUP | | | | | | | | | | | | | | | | |
| | | | | | | | | (R-2) | | | | | | | | | | | | | | | | | | |
| | | | | | | | | (L-1) | | | | | | | | | | | | | | | | | | |
| | | | | | | | | (L-2) | | | | | | | | | | | | | | | | | | |
| | | | | | | 93.3-95.5 | 1 1/8 | (R-1) | WK-815 | CUP | | | | | | | | | | | | | | | | |
| | | | | | | | | (R-2) | | | | | | | | | | | | | | | | | | |
| | | | | | | | | (L-1) | | | | | | | | | | | | | | | | | | |
| | | | | | | | | (L-2) | | | | | | | | | | | | | | | | | | |
| | ディスク車 | 86.8-95.5 | 1 | | TK-T027 | 86.8-95.5 | 66.6 | DISC | MP-17 | | 86.8-93.3 | 1 1/8 | | WK-715 | CUP | 86.8-92.10 | (1)BH-T681 | BH-97001 | <ブースター無> | | | | | | | |
| | | | | | | | | | | | 93.3-95.5 | 1 1/8 | (R-1)WC-T676 | WK-835 | CUP | | (2)BH-02516 | | 86.8-87.8 | 5/8 | MC-10132 | MK-4328 | 86.8-88.8 | 13/16 | CC-70178 | CK-3144 |
| | | | | | | | | | | | | | (R-2) | | | | | | 87.8-95.5 | 5/8 | MC-T331 | MK-4351 | 88.8-94.8 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | | | | | | | (L-1) | | | 92.10-95.5 | (1) | BH-97001 | <ブースター付> | | | | 94.8-95.5 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | | | | | | | (L-2) | | | | (2)BH-02516 | | 86.8-87.8 | 5/8 | MC-10135 | MK-4320 | | | | |
| | | | | | | | | | | | | | | | | | | | 87.8-88.11 | 5/8 | MC-10135 | MK-T200 | | | | |
| | | | | | | | | | | | | | | | | | | | 88.11-89.10 | 5/8 | MC-10135 | MK-4353 | | | | |
| | | | | | | | | | | | | | | | | | | | 89.10-95.5 | 5/8 | MC-T368 | MK-T206 | | | | |
| Nー BU60(1．75t) | Wキャブジャストロー(Wタイヤ) | 84.9-95.5 | 1 | | TK-9452 | 84.9-93.3 | 1 1/8 | (R-1) | WK-635 | CUP | 84.9-95.5 | 1 | | WK-637 | CUP | 84.9-95.5 | BH-02220 | BH-97001 | <ブースター無> | | | | | | | |
| Uー BU60(1．75t) | Wキャブフルジャストロー(Wタイヤ) | | | | | | | (R-2) | | | | | | | | <フルジャストロー> | | | 84.9-87.8 | 5/8 | MC-10132 | MK-4328 | 84.9-85.8 | 13/16 | CC-70162 | CK-3136 |
| ＜Uーは90．8～＞ | ドラム車 | | | | | | | (L-1) | | | | | | | | 84.9-91.2 | BH-T527 | BH-97001 | 87.8-95.5 | 5/8 | MC-T331 | MK-4351 | 85.8-88.8 | 13/16 | CC-70178 | CK-3144 |
| | | | | | | | | (L-2) | | | | | | | | 91.2-95.5 | (R) | BH-97001 | <ブースター付> | | | | 88.8-94.8 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | 93.3-95.5 | 1 1/8 | (R-1) | WK-814 | CUP | | | | | | | (L) | | 88.8-88.11 | 5/8 | MC-10135 | MK-T200 | 94.8-95.5 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | | (R-2) | | | | | | | | | | | 88.11-89.10 | 5/8 | MC-10135 | MK-4353 | | | | |
| | | | | | | | | (L-1) | | | | | | | | | | | 89.10-95.5 | 5/8 | MC-T368 | MK-T206 | | | | |
| | | | | | | | | (L-2) | | | | | | | | | | | | | | | | | | |
| | ディスク車 | 86.8-95.5 | 1 | | TK-T027 | 86.8-95.5 | 66.6 | DISC | MP-17 | | 86.8-93.3 | 1 1/8 | | WK-715 | CUP | 86.8-92.10 | (1)BH-T681 | BH-97001 | <ブースター無> | | | | | | | |
| | | | | | | | | | | | 93.3-95.5 | 1 1/8 | (R-1)WC-T676 | WK-835 | CUP | | (2)BH-02516 | | 86.8-87.8 | 5/8 | MC-10132 | MK-4328 | 86.8-88.8 | 13/16 | CC-70178 | CK-3144 |
| | | | | | | | | | | | | | (R-2) | | | | | | 87.8-95.5 | 5/8 | MC-T331 | MK-4351 | 88.8-94.8 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | | | | | | | (L-1) | | | 92.10-95.5 | (1) | BH-97001 | <ブースター付> | | | | 94.8-95.5 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | | | | | | | (L-2) | | | | (2)BH-02516 | | 86.8-87.8 | 5/8 | MC-10135 | MK-4320 | | | | |
| | | | | | | | | | | | | | | | | | | | 87.8-88.11 | 5/8 | MC-10135 | MK-T200 | | | | |
| | | | | | | | | | | | | | | | | | | | 88.11-89.10 | 5/8 | MC-10135 | MK-4353 | | | | |
| | | | | | | | | | | | | | | | | | | | 89.10-95.5 | 5/8 | MC-T368 | MK-T206 | | | | |

| Models | TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| (3400ディーゼル) P－BU62(2t)<br>(3700ディーゼル) U－BU66(2t) | 高床(Sタイヤ) | 84.9-95.5 | 1 | | TK-9452 | 84.9-93.3 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-635 | CUP | 84.9-95.5<br><ｵｰﾄｱｼﾞｬｽﾀｰ付><br>85.8-95.5 | 1<br><br>1 | | WK-637<br><br>WK-640 | CUP<br><br>CUP | 84.9-95.5 | BH-02220 | BH-40012 | <ﾌﾞｰｽﾀｰ無><br>84.9-87.8<br><ﾌﾞｰｽﾀｰ付><br>84.9-87.8<br>87.8-88.11<br>88.11-89.10<br>89.10-95.5 | 5/8<br><br>5/8<br>5/8<br>5/8<br>5/8 | MC-10132<br><br>MC-10135<br>MC-10135<br>MC-10135<br>MC-T368 | MK-4328<br><br>MK-4320<br>MK-T200<br>MK-4353<br>MK-T206 | 84.9-85.8<br>85.8-88.8<br>88.8-94.8<br>94.8-95.5 | 13/16<br>13/16<br>3/4<br>3/4 | CC-70162<br>CC-70178<br>CC-70185<br>CC-70185 | CK-3136<br>CK-3144<br>CK-T218<br>CK-T218 |
| | | | | | | 93.3-95.5 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-814 | CUP | | | | | | | | | | | | | | | | |
| | | | | | | <ｵｰﾄｱｼﾞｬｽﾀｰ付><br>85.8-93.3 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-636 | CUP | | | | | | | | | | | | | | | | |
| | | | | | | 93.3-95.5 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-815 | CUP | | | | | | | | | | | | | | | | |
| | 高床(Wタイヤ)<br>ドラム車 | 87.8-95.5 | 1 | | TK-9452 | 87.8-93.3 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-634 | CUP | 87.8-95.5 | 1 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-638 | CUP | 87.8-95.5 | BH-95002 | BH-40012 | 87.8-88.11<br>88.11-89.10<br>89.10-95.5 | 5/8<br>5/8<br>5/8 | MC-10135<br>MC-10135<br>MC-T368 | MK-T200<br>MK-4353<br>MK-T206 | 87.8-88.8<br>88.8-94.8<br>94.8-95.5 | 13/16<br>3/4<br>3/4 | CC-70178<br>CC-70185<br>CC-70185 | CK-3144<br>CK-T218<br>CK-T218 |
| | | | | | | 93.3-95.5 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-811 | CUP | <ｵｰﾄｱｼﾞｬｽﾀｰ付><br>87.8-95.5<br><塵芥車M/T車><br>87.8-93.3 | 1<br><br>1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-688<br><br>WK-413 | CUP<br><br>CUP | | | | | | | | | | |
| | | | | | | <ｵｰﾄｱｼﾞｬｽﾀｰ付><br>87.8-93.3 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-639 | CUP | | | | | | | | | | | | | | | | |
| | | | | | | 93.3-95.5 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-817 | CUP | 93.3-95.5<br><塵芥車A/T車><br>87.8-93.3 | 1 1/8<br><br>1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-812<br><br>WK-641 | CUP<br><br>CUP | | | | | | | | | | |
| | | | | | | | | | | | 93.3-95.5 | 1 1/8 | | WK-813 | CUP | | | | | | | | | | |
| | ディスク車 | 87.8-95.5 | 1 1/16 | | TK-T031 | 87.8-91.9<br>91.9-95.5 | 51.1<br>51.1 | DISC<br>DISC | MP-8<br>MP-8 | | 87.8-93.3<br>93.3-95.5 | 1 1/8<br>1 1/8 | | WK-641<br>WK-813 | CUP<br>CUP | 87.8-95.5 | (1)BH-T681<br>(2)BH-02431 | BH-40012 | 87.8-88.11<br>88.11-89.10<br>89.10-95.5 | 5/8<br>5/8<br>5/8 | MC-10135<br>MC-10135<br>MC-T368 | MK-T200<br>MK-4353<br>MK-T206 | 87.8-88.8<br>88.8-94.8<br>94.8-95.5 | 13/16<br>3/4<br>3/4 | CC-70178<br>CC-70185<br>CC-70185 | CK-3144<br>CK-T218<br>CK-T218 |
| (3400ディーゼル) P－BU62(1．75t･2t)<br>(3700ディーゼル) U－BU66(1．75t･2t) | ジャストロー(Wタイヤ) | 84.9-95.5 | 1 | | TK-9452 | 84.9-93.3 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-635 | CUP | 84.9-95.5<br><ｵｰﾄｱｼﾞｬｽﾀｰ付><br>85.8-95.5 | 1<br><br>1 | | WK-637<br><br>WK-640 | CUP<br><br>CUP | 84.9-95.5 | BH-02220 | BH-97001 | <ﾌﾞｰｽﾀｰ無><br>84.9-87.8<br><ﾌﾞｰｽﾀｰ付><br>84.9-87.8<br>87.8-88.11<br>88.11-89.10<br>89.10-95.5 | 5/8<br><br>5/8<br>5/8<br>5/8<br>5/8 | MC-10132<br><br>MC-10135<br>MC-10135<br>MC-10135<br>MC-T368 | MK-4328<br><br>MK-4320<br>MK-T200<br>MK-4353<br>MK-T206 | 84.9-85.8<br>85.8-88.8<br>88.8-94.8<br>94.8-95.5 | 13/16<br>13/16<br>3/4<br>3/4 | CC-70162<br>CC-70178<br>CC-70185<br>CC-70185 | CK-3136<br>CK-3144<br>CK-T218<br>CK-T218 |
| | | | | | | 93.3-95.5 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-814 | CUP | | | | | | | | | | | | | | | | |
| | | | | | | <ｵｰﾄｱｼﾞｬｽﾀｰ付><br>85.8-93.3 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-636 | CUP | | | | | | | | | | | | | | | | |
| | | | | | | 93.3-95.5 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-815 | CUP | | | | | | | | | | | | | | | | |
| | フルジャストロー(Wタイヤ)<br>Wキャブフルジャストロー(Wタイヤ)<br>ドラム車 | 84.9-95.5 | 1 | | TK-9452 | 84.9-93.3 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-635 | CUP | 84.9-95.5<br><ｵｰﾄｱｼﾞｬｽﾀｰ付><br><ｴｲｷｮｳｼｬ　ｶｽﾀﾑｼｮｳ><br>84.9-95.5 | 1<br><br><br>1 | | WK-637<br><br><br>WK-640 | CUP<br><br><br>CUP | 84.9-91.2<br>91.2-95.5 | BH-T527<br>(R)<br>(L) | BH-97001<br>BH-97001 | <ﾌﾞｰｽﾀｰ無><br>84.9-87.8<br><ﾌﾞｰｽﾀｰ付><br>84.9-87.8<br>87.8-88.11<br>88.11-89.10<br>89.10-95.5 | 5/8<br><br>5/8<br>5/8<br>5/8<br>5/8 | MC-10132<br><br>MC-10135<br>MC-10135<br>MC-10135<br>MC-T368 | MK-4328<br><br>MK-4320<br>MK-T200<br>MK-4353<br>MK-T206 | 84.9-85.8<br>85.8-88.8<br>88.8-94.8<br>94.8-95.5 | 13/16<br>13/16<br>3/4<br>3/4 | CC-70162<br>CC-70178<br>CC-70185<br>CC-70185 | CK-3136<br>CK-3144<br>CK-T218<br>CK-T218 |
| | | | | | | 93.3-95.5 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-814 | CUP | | | | | | | | | | | | | | | | |
| | | <ｵｰﾄｱｼﾞｬｽﾀｰ付><br><ｴｲｷｮｳｼｬ　ｶｽﾀﾑｼｮｳ><br>84.9-93.3 | 1<br>1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-636 | CUP | | | | | | | | | | | | | | | | | | | | |
| | | 93.3-95.5 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-815 | CUP | | | | | | | | | | | | | | | | | | | | |
| | ディスク車 | 86.8-95.5 | 1 | | TK-T027 | 86.8-95.5 | 66.6 | DISC | MP-17 | | <ｵｰﾄｱｼﾞｬｽﾀｰ付><br>86.8-93.3<br>93.3-95.5 | 1 1/8<br>1 1/8 | (R-1)WC-T676<br>(R-2)<br>(L-1)<br>(L-2) | WK-715<br>WK-835 | CUP<br>CUP | 86.8-92.10<br><br>92.10-95.5 | (1)BH-T681<br>(2)BH-02516<br>(1)<br>(2)BH-02516 | BH-97001<br><br>BH-97001 | <ﾌﾞｰｽﾀｰ無><br>86.8-87.8<br><ﾌﾞｰｽﾀｰ付><br>86.8-87.8<br>87.8-88.11<br>88.11-89.10<br>89.10-95.5 | 5/8<br><br>5/8<br>5/8<br>5/8<br>5/8 | MC-10132<br><br>MC-10135<br>MC-10135<br>MC-10135<br>MC-T368 | MK-4328<br><br>MK-4320<br>MK-T200<br>MK-4353<br>MK-T206 | 86.8-88.8<br>88.8-94.8<br>94.8-95.5 | 13/16<br>3/4<br>3/4 | CC-70178<br>CC-70185<br>CC-70185 | CK-3144<br>CK-T218<br>CK-T218 |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | | | | | | | | | | | <ブースター無> | | | | | | | |
| (3400ディーゼル) P－BU62H(2．75t・3t) | 高床(Wタイヤ) | 84.9-95.5 | 1 | | TK-9452 | 84.9-93.3 | 1 1/8 | (R-1) | WK-634 | CUP | 84.9-95.5 | 1 | | WK-638 | CUP | 84.9-95.5 | BH-95002 | BH-40012 | 84.9-87.8 | 5/8 | MC-10132 | MK-4328 | 84.9-85.8 | 13/16 | CC-70162 | CK-3136 |
| (3700ディーゼル) U－BU66H(2．75t・3t) | 消防車Wキャブ(Wタイヤ) | | | | | | | (R-2) | | | | | | | | | | | <ブースター付> | | | | 85.8-88.8 | 13/16 | CC-70178 | CK-3144 |
| | ドラム車 | | | | | | | (L-1) | | | | | | | | | | | 84.9-87.8 | 5/8 | MC-10135 | MK-4320 | 88.8-94.8 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | | (L-2) | | | | | | | | | | | 87.8-88.11 | 5/8 | MC-10135 | MK-T200 | 94.8-95.5 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | 93.3-95.5 | 1 1/8 | (R-1) | WK-811 | CUP | | | | | | | | | 88.11-89.10 | 5/8 | MC-10135 | MK-4353 | <消防車> | | | |
| | | | | | | | | (R-2) | | | | | | | | | | | 89.10-95.5 | 5/8 | MC-T368 | MK-T206 | 84.9-88.8 | 13/16 | CC-70162 | CK-3136 |
| | | | | | | | | (L-1) | | | | | | | | | | | | | | | 88.8-94.8 | 3/4 | CC-70164 | CK-3137 |
| | | | | | | | | (L-2) | | | | | | | | | | | | | | | 94.8-95.5 | 3/4 | CC-70164 | |
| | ディスク車 | 87.8-95.5 | 1 1/16 | | TK-T031 | 87.8-91.9 | 51.1 | DISC | MP-8 | | 87.8-93.3 | 1 1/8 | | WK-641 | CUP | 87.8-95.5 | (1)BH-T681 | BH-40012 | 87.8-88.11 | 5/8 | MC-10135 | MK-T200 | 87.8-88.8 | 13/16 | CC-70178 | CK-3144 |
| | | | | | | 91.9-95.5 | 51.1 | DISC | MP-8 | | 93.3-95.5 | 1 1/8 | | WK-813 | CUP | | (2)BH-02431 | | 88.11-89.10 | 5/8 | MC-10135 | MK-4353 | 88.8-94.8 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | | | | | | | | | | | | | 89.10-95.5 | 5/8 | MC-T368 | MK-T206 | 94.8-95.5 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | | | | | | | | | | | | | | | | | <消防車> | | | |
| | | | | | | | | | | | | | | | | | | | | | | | 87.8-88.8 | 13/16 | CC-70162 | CK-3136 |
| | | | | | | | | | | | | | | | | | | | | | | | 88.8-94.8 | 3/4 | CC-70164 | CK-3137 |
| | | | | | | | | | | | | | | | | | | | | | | | 94.8-95.5 | 3/4 | CC-70164 | |
| | | | | | | | | | | | <三転式ダンプ> | | | | | | | | <ブースター無> | | | | | | | |
| (3400ディーゼル) P－BU62D(2t) | 三転式ダンプ(Wタイヤ) | 84.9-95.5 | 1 | | TK-9452 | 84.9-93.3 | 1 1/8 | (R-1) | WK-634 | CUP | 84.9-95.5 | 1 | | WK-638 | CUP | 84.9-95.5 | BH-95002 | BH-40012 | 84.9-87.8 | 5/8 | MC-10132 | MK-4328 | 84.9-85.8 | 13/16 | CC-70162 | CK-3136 |
| (3700ディーゼル) U－BU66D・66DH(2t) | 標準ダンプ(Wタイヤ) | | | | | | | (R-2) | | | <標準ダンプ> | | | | | | | | <ブースター付> | | | | 85.8-88.8 | 13/16 | CC-70178 | CK-3144 |
| | ドラム車 | | | | | | | (L-1) | | | 90.8-93.3 | 1 1/8 | | WK-413 | CUP | | | | 84.9-87.8 | 5/8 | MC-10135 | MK-4320 | 88.8-94.8 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | | (L-2) | | | 93.3-95.5 | 1 1/8 | | WK-812 | CUP | | | | 87.8-88.11 | 5/8 | MC-10135 | MK-T200 | 94.8-95.5 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | 93.3-95.5 | 1 1/8 | (R-1) | WK-811 | CUP | | | | | | | | | 88.11-89.10 | 5/8 | MC-10135 | MK-4353 | | | | |
| | | | | | | | | (R-2) | | | | | | | | | | | 89.10-95.5 | 5/8 | MC-T368 | MK-T206 | | | | |
| | | | | | | | | (L-1) | | | | | | | | | | | | | | | | | | |
| | | | | | | | | (L-2) | | | | | | | | | | | | | | | | | | |
| | 標準ダンプ(Wタイヤ) | 93.9-95.5 | 1 1/16 | | TK-T031 | 93.9-95.5 | 51.1 | DISC | MP-8 | | 93.9-95.5 | 1 1/8 | | WK-813 | CUP | 93.9-95.5 | (1)BH-T681 | BH-40012 | 93.9-95.5 | 5/8 | MC-T368 | MK-T206 | 93.9-94.8 | 3/4 | CC-70185 | CK-T218 |
| | ディスク車 | | | | | | | | | | | | | | | | (2)BH-02431 | | | | | | 94.8-95.5 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | | | | | | | | | | <ジャストロー> | | | <ブースター無> | | | | | | | |
| | ジャストローダンプ(Wタイヤ) | 84.9-95.5 | 1 | | TK-9452 | 84.9-93.3 | 1 1/8 | (R-1) | WK-635 | CUP | 84.9-95.5 | 1 | | WK-637 | CUP | 84.9-95.5 | BH-02220 | BH-97001 | 84.9-87.8 | 5/8 | MC-10132 | MK-4328 | 84.9-85.8 | 13/16 | CC-70162 | CK-3136 |
| | フルジャストローダンプ(Wタイヤ) | | | | | | | (R-2) | | | | | | | | <フルジャストロー> | | | <ブースター付> | | | | 85.8-88.8 | 13/16 | CC-70178 | CK-3144 |
| | | | | | | | | (L-1) | | | | | | | | 89.10-91.2 | BH-T527 | BH-97001 | 84.9-87.8 | 5/8 | MC-10135 | MK-4320 | 88.8-94.8 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | | (L-2) | | | | | | | | 91.2-95.5 | (R) | BH-97001 | 87.8-88.11 | 5/8 | MC-10135 | MK-T200 | 94.8-95.5 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | 93.3-95.5 | 1 1/8 | (R-1) | WK-814 | CUP | | | | | | | (L) | | 88.11-89.10 | 5/8 | MC-10135 | MK-4353 | | | | |
| | | | | | | | | (R-2) | | | | | | | | | | | 89.10-95.5 | 5/8 | MC-T368 | MK-T206 | | | | |
| | | | | | | | | (L-1) | | | | | | | | | | | | | | | | | | |
| | | | | | | | | (L-2) | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | <ブースター無> | | | | | | | |
| (3400ディーゼル) P－BU64D | 標準ダンプ(Wタイヤ) | 84.9-95.5 | 1 | | TK-9452 | 84.9-93.3 | 1 1/8 | (R-1) | WK-634 | CUP | 84.9-95.5 | 1 | | WK-638 | CUP | 84.9-95.5 | BH-95002 | BH-36212 | 84.9-87.8 | 5/8 | MC-10132 | MK-4328 | 84.9-85.8 | 13/16 | CC-70162 | CK-3136 |
| | 砕石ダンプ(Wタイヤ) | | | | | | | (R-2) | | | <BU67オートアジャスター付> | | | | | | | | <ブースター付> | | | | 85.8-88.8 | 13/16 | CC-70178 | CK-3144 |
| | | | | | | | | (L-1) | | | 88.8-95.5 | 1 | | WK-688 | CUP | | | | 84.9-87.8 | 5/8 | MC-10135 | MK-4320 | 88.8-94.8 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | | (L-2) | | | | | | | | | | | 87.8-88.11 | 5/8 | MC-10135 | MK-T200 | 94.8-95.5 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | 93.3-95.5 | 1 1/8 | (R-1) | WK-811 | CUP | | | | | | | | | 88.11-89.10 | 5/8 | MC-10135 | MK-4353 | | | | |
| | | | | | | | | (R-2) | | | | | | | | | | | 89.10-95.5 | 5/8 | MC-T368 | MK-T206 | | | | |
| | | | | | | | | (L-1) | | | | | | | | | | | | | | | | | | |
| | | | | | | | | (L-2) | | | | | | | | | | | | | | | | | | |
| | | | | | | <BU67オートアジャスター付> | | | | | | | | | | | | | | | | | | | | |
| | | | | | | 88.8-93.3 | 1 1/8 | (R-1) | WK-639 | CUP | | | | | | | | | | | | | | | | |
| | | | | | | | | (R-2) | | | | | | | | | | | | | | | | | | |
| | | | | | | | | (L-1) | | | | | | | | | | | | | | | | | | |
| | | | | | | | | (L-2) | | | | | | | | | | | | | | | | | | |
| | | | | | | 93.3-95.5 | 1 1/8 | (R-1) | WK-817 | CUP | | | | | | | | | | | | | | | | |
| | | | | | | | | (R-2) | | | | | | | | | | | | | | | | | | |
| | | | | | | | | (L-1) | | | | | | | | | | | | | | | | | | |
| | | | | | | | | (L-2) | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | <ブースター無> | | | | | | | |
| (3400ディーゼル) P－BU64・77 | 高床(Wタイヤ) | 84.9-95.5 | 1 | | TK-9452 | 84.9-93.3 | 1 1/8 | (R-1) | WK-634 | CUP | 84.9-95.5 | 1 | | WK-638 | CUP | 84.9-95.5 | BH-95002 | BH-36212 | 84.9-87.8 | 5/8 | MC-10132 | MK-4328 | 84.9-85.8 | 13/16 | CC-70162 | CK-3136 |
| | ドラム車 | | | | | | | (R-2) | | | <オートアジャスター付> | | | | | <BU77> | | | <ブースター付> | | | | 85.8-88.8 | 13/16 | CC-70178 | CK-3144 |
| | | | | | | | | (L-1) | | | 85.8-87.8 | 1 | | WK-688 | CUP | 85.8-87.8 | BH-95004 | BH-97003 | 84.9-87.8 | 5/8 | MC-10135 | MK-4320 | 88.8-94.8 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | | (L-2) | | | 93.9-95.5 | 1 | | WK-688 | CUP | | | | 87.8-88.11 | 5/8 | MC-10135 | MK-T200 | 94.8-95.5 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | 93.3-95.5 | 1 1/8 | (R-1) | WK-811 | CUP | | | | | | | | | 88.11-89.10 | 5/8 | MC-10135 | MK-4353 | | | | |
| | | | | | | | | (R-2) | | | | | | | | | | | 89.10-95.5 | 5/8 | MC-T368 | MK-T206 | | | | |
| | | | | | | | | (L-1) | | | | | | | | | | | | | | | | | | |
| | | | | | | | | (L-2) | | | | | | | | | | | | | | | | | | |
| | | <オートアジャスター付> | | | | | | | | | | | | | | | | | | | | | | | | |
| | | 85.8-87.8 | 1 1/8 | (R-1) | WK-639 | CUP | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | (R-2) | | | | | | | | | | | | | | | | | | |
| | | | | | | | | (L-1) | | | | | | | | | | | | | | | | | | |
| | | | | | | | | (L-2) | | | | | | | | | | | | | | | | | | |
| | | 93.9-95.5 | 1 1/8 | (R-1) | WK-817 | CUP | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | (R-2) | | | | | | | | | | | | | | | | | | |
| | | | | | | | | (L-1) | | | | | | | | | | | | | | | | | | |
| | | | | | | | | (L-2) | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | <ブースター無> | | | | | | | |
| | ディスク車 | 84.9-87.8 | 1 1/16 | | TK-9453 | 84.9-91.9 | 51.1 | DISC | MP-8 | CPM-8 | 84.9-93.3 | 1 1/8 | | WK-641 | CUP | 84.9-95.5 | (1)BH-T681 | BH-36212 | 84.9-87.8 | 5/8 | MC-10132 | MK-4328 | 84.9-85.8 | 13/16 | CC-70162 | CK-3136 |
| | | 87.8-95.5 | 1 1/16 | | TK-T031 | 91.9-95.5 | 51.1 | DISC | MP-8 | CPM-8 | 93.3-95.5 | 1 1/8 | | WK-813 | CUP | | (2)BH-02431 | | <ブースター付> | | | | 85.8-88.8 | 13/16 | CC-70178 | CK-3144 |
| | | | | | | | | | | | | | | | | <BU77> | | | 84.9-87.8 | 5/8 | MC-10135 | MK-4320 | 88.8-94.8 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | | | | | | | | | | 85.8-87.8 | (1)BH-31404 | BH-97003 | 87.8-88.11 | 5/8 | MC-10135 | MK-T200 | 94.8-95.5 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | | | | | | | | | | | (2)BH-02431 | | 88.11-89.10 | 5/8 | MC-10135 | MK-4353 | | | | |
| | | | | | | | | | | | | | | | | | | | 89.10-95.5 | 5/8 | MC-T368 | MK-T206 | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| (3700ディーゼル) U−BU67 | Wタイヤ | 88.8-95.5 | 1 | | TK-9452 | 88.8-93.3 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-639 | CUP | 88.8-95.5 | 1 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-688 | CUP | 88.8-95.5 | (R)BH-95002<br>(L)BH-95002 | BH-36212 | <ブースター付><br>88.8-95.5<br><ブースター無><br>88.8-95.5 | 5/8<br>5/8 | MC-10135<br>MC-T368 | MK-T200<br>MK-T206 | 93.9-94.8 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | 93.3-95.5 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-817 | CUP | | | | | | | | | | | | | | | | |
| | 除くWタイヤ | 88.8-95.5 | 1 | | TK-9452 | 88.8-93.3 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-634 | CUP | <オートアジャスター付><br>88.8-93.3 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-641 | CUP | 88.8-95.5 | (R)BH-95002<br>(L)BH-95002 | BH-36212 | <ブースター付><br>88.8-95.5<br><ブースター無><br>88.8-95.5 | 5/8<br>5/8 | MC-10135<br>MC-T368 | MK-T200<br>MK-T206 | 93.9-94.8 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | 93.3-95.5 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-811 | CUP | 93.3-95.5 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | | | | | | | | | | | |
| | | | | | | | | | | | <オートアジャスター無><br>88.8-95.5 | 1 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-638 | CUP | | | | | | | | | | | |
| U−BU67D | Wタイヤ | 88.8-95.5 | 1 | | TK-9452 | 88.8-93.3 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-639 | CUP | 88.8-95.5 | 1 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-688 | CUP | 88.8-95.5 | (R)BH-95002<br>(L)BH-95002 | BH-36212 | <ブースター付><br>88.8-95.5<br><ブースター無><br>88.8-95.5 | 5/8<br>5/8 | MC-10135<br>MC-T368 | MK-T200<br>MK-T206 | 93.9-94.8 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | 93.3-95.5 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-817 | CUP | | | | | | | | | | | | | | | | |
| | 除くWタイヤ | 88.8-95.5 | 1 | | TK-9452 | 88.8-93.3 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-634 | CUP | 88.8-95.5 | 1 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-638 | CUP | 88.8-95.5 | (R)BH-95002<br>(L)BH-95002 | BH-36212 | <ブースター付><br>88.8-95.5<br><ブースター無><br>88.8-95.5 | 5/8<br>5/8 | MC-10135<br>MC-T368 | MK-T200<br>MK-T206 | 93.9-94.8 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | 93.3-95.5 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-811 | CUP | | | | | | | | | | | | | | | | |
| (3400ディーゼル)<br>(2700LPG) U−BU68DH | 標準ダンプ(Wタイヤ)<br>ドラム車 | 89.10-95.5 | 1 | | TK-9452 | 89.10-93.3<br>93.3-95.5 | 1 1/8<br>1 1/8 | | WK-634<br>WK-811 | CUP<br>CUP | 89.10-93.3<br>93.3-95.5<br><オートアジャスター付><br>93.3-93.9<br>93.9-95.5 | 1 1/8<br>1 1/8<br><br>1 1/8<br>1 1/8 | | WK-413<br>WK-812<br><br>WK-715<br>WK-813 | CUP<br>CUP<br><br>CUP<br>CUP | 89.10-95.5 | BH-95002 | BH-40012 | 89.10-95.5 | 5/8 | MC-T368 | MK-T206 | 89.10-94.8<br>94.8-95.5<br><LPG車><br>93.11-95.5 | 3/4<br>3/4<br><br>13/16 | CC-70185<br>CC-70185 | CK-T218<br>CK-T218<br><br>CK-T201 |
| | ディスク車 | 93.9-95.5 | 1 1/16 | | TK-T031 | 93.9-95.5 | 51.1 | DISC | MP-8 | | 93.9-95.5 | 1 1/8 | | WK-813 | CUP | 93.9-95.5 | (1)BH-T681<br>(2)BH-02431 | BH-40012 | 93.9-95.5 | 5/8 | MC-T368 | MK-T206 | 93.9-94.8<br>94.8-95.5<br><LPG車><br>93.11-95.5 | 3/4<br><br><br>13/16 | CC-70185 | CK-T218<br>CK-T218<br><br>CK-T201 |
| (3700ディーゼル)<br>U−BU73(4WD) | 高床(Wタイヤ)<br>Wキャブ(Wタイヤ)<br>消防車Wキャブ(Wタイヤ) | 90.5-95.5 | 1 | | TK-9452 | 90.5-93.3 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-634 | CUP | 90.5-95.5<br><オートアジャスター付><br>92.3-95.5 | 1<br><br>1 | | WK-638<br><br>WK-688 | CUP<br><br>CUP | 90.5-95.5 | BH-31405 | BH-T528 | 90.5-95.5 | 5/8 | MC-T368 | MK-T206 | 90.5-94.8<br>94.8-95.5 | 3/4<br>3/4 | CC-70185<br>CC-70185 | CK-T218<br>CK-T218 |
| | | | | | | 93.3-95.5 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-811 | CUP | | | | | | | | | | | | | | | | |
| | | | | | | <オートアジャスター付><br>92.3-93.3 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-639 | CUP | | | | | | | | | | | | | | | | |
| | | | | | | 93.3-95.5 | 1 1/8 | | WK-817 | CUP | | | | | | | | | | | | | | | | |
| (3700ディーゼル)<br>U−BU78 | フルジャストロー(Wタイヤ)<br>ドラム車 | 89.10-95.5 | 1 | | TK-9452 | 89.10-93.3 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-634 | CUP | 89.10-95.5<br><オートアジャスター付><br>89.10-95.5 | 1<br><br>1 | | WK-638<br><br>WK-688 | CUP<br><br>CUP | 89.10-95.5 | BH-02249 | BH-97003 | 89.10-95.5 | 5/8 | MC-T368 | MK-T206 | 89.10-94.8<br>94.8-95.5 | 3/4<br>3/4 | CC-70185<br>CC-70185 | CK-T218<br>CK-T218 |
| | | | | | | 93.3-95.5 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-811 | CUP | | | | | | | | | | | | | | | | |
| | | | | | | <オートアジャスター付><br>89.10-93.3 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-639 | CUP | | | | | | | | | | | | | | | | |
| | | | | | | 93.3-95.5 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-817 | CUP | | | | | | | | | | | | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | ディスク車 | 89.10-95.5 | 1 1/16 | | TK-T031 | 89.10-91.9 | 51.1 | DISC | MP-8 | | 89.10-93.3 | 1 1/8 | | WK-641 | CUP | 89.10-92.10 | (1)BH-02567<br>(2)BH-02431 | BH-02518 | 89.10-95.5 | 5/8 | MC-T368 | MK-T206 | 89.10-94.8 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | 91.9-95.5 | 51.1 | DISC | MP-8 | | 93.3-95.5 | 1 1/8 | | WK-813 | CUP | 92.10-95.5 | (1)BH-T678<br>(2)BH-02431 | BH-02518 | | | | | 94.8-95.5 | 3/4 | CC-70185 | CK-T218 |
| (3700ディーゼル)<br>U－BU72D(4WD) | フルジャストローダンプ(Wタイヤ) | 89.10-95.5 | 1 | | TK-9452 | 89.10-93.3 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-635 | CUP | 89.10-93.3<br>93.3-95.5 | 1 1/8<br>1 1/8 | | WK-724<br>WK-816 | CUP<br>CUP | 89.10-95.5 | BH-31405 | BH-40012 | 89.10-95.5 | 5/8 | MC-T368 | MK-T206 | 89.10-94.8<br>94.8-95.5 | 3/4<br>3/4 | CC-70185<br>CC-70185 | CK-T218<br>CK-T218 |
| | | | | | | 93.3-95.5 | 1 1/8 | | WK-814 | CUP | | | | | | | | | | | | | | | | |
| U－BU72DH(4WD) | 砕石ダンプ(Wタイヤ)<br>三転式ダンプ(Wタイヤ) | 89.10-95.5 | 1 | | TK-9452 | 89.10-93.3 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-634 | CUP | 89.10-95.5 | 1 | | WK-638 | CUP | 89.10-95.5 | BH-31405 | BH-40012 | 89.10-95.5 | 5/8 | MC-T368 | MK-T206 | 89.10-94.8<br>94.8-95.5 | 3/4<br>3/4 | CC-70185<br>CC-70185 | CK-T218<br>CK-T218 |
| | | | | | | 93.3-95.5 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-811 | CUP | | | | | | | | | | | | | | | | |
| (3700ディーゼル)<br>U－BU72H(4WD) | 高床(Wタイヤ) | 89.10-92.10 | 1 | | TK-9452 | 89.10-92.10 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-634 | CUP | 89.10-92.10 | 1<br>1 | | WK-638<br>WK-688 | CUP<br>CUP | 89.10-92.10 | BH-31405 | BH-40012 | 89.10-92.10 | 5/8 | MC-T368 | MK-T206 | 89.10-92.10 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | <オートアジャスター付> | | | | | <オートアジャスター付> | | | | | | | | | | | | | | | |
| | | | | | | 89.10-92.10 | 1 1/8 | | WK-639 | CUP | 89.10-92.10 | | | | | | | | | | | | | | | |
| (3700ディーゼル)<br>U－BU72(4WD) | フルジャストロー(Wタイヤ) | 89.10-95.5 | 1 | | TK-9452 | 89.10-93.3 | 1 1/8 | | WK-635 | CUP | 89.10-93.3<br>93.3-95.5 | 1 1/8<br>1 1/8 | | WK-724<br>WK-816 | CUP<br>CUP | 89.10-95.5 | BH-31405 | BH-40012 | 89.10-95.5 | 5/8 | MC-T368 | MK-T206 | 89.10-94.8<br>94.8-95.5 | 3/4<br>3/4 | CC-70185<br>CC-70185 | CK-T218<br>CK-T218 |
| | | | | | | | | | | | <オートアジャスター付> | | | | | | | | | | | | | | | |
| | | | | | | 93.3-95.5 | 1 1/8 | | WK-814 | CUP | 89.10-93.3<br>93.3-95.5 | 1 1/8<br>1 1/8 | (R-1)WC-T676<br>(R-2)<br>(L-1)<br>(L-2) | WK-715<br>WK-835 | CUP<br>CUP | | | | | | | | | | | |
| | | | | | | <オートアジャスター付> | | | | | | | | | | | | | | | | | | | | |
| | | | | | | 89.10-93.3 | 1 1/8 | | WK-636 | CUP | | | | | | | | | | | | | | | | |
| | | | | | | 93.3-95.5 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-815 | CUP | | | | | | | | | | | | | | | | |
| (3700ディーゼル)<br>U－BU74(4WD) | 高床(Wタイヤ) | 89.10-95.5 | 1 | | TK-9452 | 89.10-93.3 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-634 | CUP | 89.10-93.3<br>93.3-95.5 | 1 1/8<br>1 1/8 | | WK-413<br>WK-812 | CUP<br>CUP | 89.10-95.5 | BH-31405 | BH-44212 | 89.10-95.5 | 5/8 | MC-T368 | MK-T206 | 89.10-94.8<br>94.8-95.5 | 3/4<br>3/4 | CC-70185<br>CC-70185 | CK-T218<br>CK-T218 |
| | | | | | | 93.3-95.5 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-811 | CUP | <オートアジャスター付><br>89.10-93.3<br>93.3-95.5 | 1 1/8<br>1 1/8 | | WK-641<br>WK-813 | CUP<br>CUP | | | | | | | | | | | |
| | | | | | | <オートアジャスター付> | | | | | | | | | | | | | | | | | | | | |
| | | | | | | 89.10-93.3 | 1 1/8 | | WK-639 | CUP | | | | | | | | | | | | | | | | |
| | | | | | | 93.3-95.5 | 1 1/8 | | WK-817 | CUP | | | | | | | | | | | | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| DYNA, TOYOACE : BU80-90 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | <ﾌﾞｰｽﾀｰ無> | | | | | | | |
| (3000ディーゼル) | | ジャストロー(Wタイヤ) | 84.9-95.5 | 1 | | TK-9452 | 84.9-93.3 | 1 1/8 | | WK-635 | CUP | 84.9-95.5 | 1 | | WK-637 | CUP | 84.9-95.5 | BH-02220 | BH-40012 | 84.9-87.8 | 5/8 | MC-10132 | MK-4328 | 84.9-85.8 | 13/16 | CC-70162 | CK-3136 |
| | N－BU80・83 | | | | | | 93.3-95.5 | 1 1/8 | | WK-814 | CUP | <ｵｰﾄｱｼﾞｬｽﾀｰ付> | | | | | | | | 87.8-95.5 | 5/8 | MC-T331 | MK-4351 | 85.8-88.8 | 13/16 | CC-70178 | CK-3144 |
| | P－BU81 | | | | | | <ｵｰﾄｱｼﾞｬｽﾀｰ付> | | | | | 84.9-95.5 | 1 | | WK-640 | CUP | | | | <ﾌﾞｰｽﾀｰ付> | | | | 88.8-94.8 | 3/4 | CC-70185 | CK-T218 |
| | U－BU83・84 | | | | | | 84.9-93.3 | 1 1/8 | | WK-636 | CUP | | | | | | | | | 84.9-87.8 | 5/8 | MC-10135 | MK-4320 | 94.8-95.5 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | 93.3-95.5 | 1 1/8 | | WK-815 | CUP | | | | | | | | | 87.8-88.11 | 5/8 | MC-10135 | MK-T200 | | | | |
| | | | | | | | | | | | | | | | | | | | | 88.11-89.10 | 5/8 | MC-10135 | MK-4353 | | | | |
| | | | | | | | | | | | | | | | | | | | | 89.10-95.5 | 5/8 | MC-T368 | MK-T206 | | | | |
| | | | | | | | | | | | | | | | | | | | | <ﾌﾞｰｽﾀｰ無> | | | | | | | |
| | | フルジャストロー(Wタイヤ) | 84.9-95.5 | 1 | | TK-9452 | 84.9-93.3 | 1 1/8 | | WK-635 | CUP | 84.9-95.5 | 1 | | WK-637 | CUP | 84.9-91.2 | BH-T527 | BH-40012 | 84.9-87.8 | 5/8 | MC-10132 | MK-4328 | 84.9-85.8 | 13/16 | CC-70162 | CK-3136 |
| | | ドラム車 | | | | | 93.3-95.5 | 1 1/8 | | WK-814 | CUP | <ｵｰﾄｱｼﾞｬｽﾀｰ付> | | | | | 91.2-92.10 | (R) | BH-40012 | 87.8-95.5 | 5/8 | MC-T331 | MK-4351 | 85.8-88.8 | 13/16 | CC-70178 | CK-3144 |
| | | | | | | | <ｵｰﾄｱｼﾞｬｽﾀｰ付> | | | | | 84.9-95.5 | 1 | | WK-640 | CUP | | (L) | | <ﾌﾞｰｽﾀｰ付> | | | | 88.8-94.8 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | 84.9-93.3 | 1 1/8 | | WK-636 | CUP | | | | | | 92.10-95.5 | (R) | BH-40012 | 84.9-87.8 | 5/8 | MC-10135 | MK-4320 | 94.8-95.5 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | 93.3-95.5 | 1 1/8 | | WK-815 | CUP | | | | | | | (L) | | 87.8-88.11 | 5/8 | MC-10135 | MK-T200 | | | | |
| | | | | | | | | | | | | | | | | | | | | 88.11-89.10 | 5/8 | MC-10135 | MK-4353 | | | | |
| | | | | | | | | | | | | | | | | | | | | 89.10-95.5 | 5/8 | MC-T368 | MK-T206 | | | | |
| | | | | | | | | | | | | | | | | | | | | <ﾌﾞｰｽﾀｰ無> | | | | | | | |
| | | ディスク車 | 86.8-95.5 | 1 | | TK-T027 | 86.8-95.5 | 66.6 | DISC | MP-17 | | 86.8-93.5 | 1 1/8 | | WK-715 | CUP | 86.8-88.8 | (1)BH-T681 | BH-02513 | 86.8-87.8 | 5/8 | MC-10132 | MK-4328 | 86.8-88.8 | 13/16 | CC-70178 | CK-3144 |
| | | | | | | | | | | | | 93.5-95.5 | 1 1/8 | (R-1)WC-T676 | WK-835 | CUP | | (2)BH-02516 | | 87.8-95.5 | 5/8 | MC-T331 | MK-4351 | 88.8-94.8 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | | | | | | | | (R-2) | | | 88.8-92.10 | (1)BH-T681 | BH-40012 | <ﾌﾞｰｽﾀｰ付> | | | | 94.8-95.5 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | | | | | | | | (L-1) | | | | (2)BH-02516 | | 86.8-87.8 | 5/8 | MC-10135 | MK-4320 | | | | |
| | | | | | | | | | | | | | | (L-2) | | | 92.10-95.5 | (1) | BH-40012 | 87.8-88.11 | 5/8 | MC-10135 | MK-T200 | | | | |
| | | | | | | | | | | | | | | | | | | (2)BH-02516 | | 88.11-89.10 | 5/8 | MC-10135 | MK-4353 | | | | |
| | | | | | | | | | | | | | | | | | | | | 89.10-95.5 | 5/8 | MC-T368 | MK-T206 | | | | |
| | | | | | | | | | | | | | | | | | | | | <ﾌﾞｰｽﾀｰ無> | | | | | | | |
| (3400ディーゼル) P－BU82(2t～3t) | | 高床(Wタイヤ) | 84.9-95.5 | 1 | | TK-9452 | 84.9-93.3 | 1 1/8 | | WK-634 | CUP | 84.9-93.3 | 1 1/8 | | WK-413 | CUP | 84.9-95.5 | BH-95002 | BH-40012 | 84.9-87.8 | 5/8 | MC-10132 | MK-4328 | 84.9-85.8 | 13/16 | CC-70162 | CK-3136 |
| (3700ディーゼル) U－BU87・87V | | バン(Wタイヤ) | | | | | 93.3-95.5 | 1 1/8 | | WK-811 | CUP | 93.3-95.5 | 1 1/8 | | WK-812 | CUP | | | | 87.8-95.5 | 5/8 | MC-T331 | MK-4351 | 85.8-88.8 | 13/16 | CC-70178 | CK-3144 |
| | | ドラム車 | | | | | <ｵｰﾄｱｼﾞｬｽﾀｰ付> | | | | | <ｵｰﾄｱｼﾞｬｽﾀｰ付> | | | | | | | | <ﾌﾞｰｽﾀｰ付> | | | | 88.8-94.8 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | 84.9-93.3 | 1 1/8 | | WK-639 | CUP | 84.9-93.3 | 1 1/8 | | WK-641 | CUP | | | | 84.9-87.8 | 5/8 | MC-10135 | MK-4320 | 94.8-95.5 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | 93.3-95.5 | 1 1/8 | | WK-817 | CUP | 93.3-95.5 | 1 1/8 | | WK-813 | CUP | | | | 87.8-88.11 | 5/8 | MC-10135 | MK-T200 | | | | |
| | | | | | | | | | | | | | | | | | | | | 88.11-89.10 | 5/8 | MC-10135 | MK-4353 | | | | |
| | | | | | | | | | | | | | | | | | | | | 89.10-95.5 | 5/8 | MC-T368 | MK-T206 | | | | |
| | | | | | | | | | | | | | | | | | | | | <ﾌﾞｰｽﾀｰ無> | | | | | | | |
| | | ディスク車 | 84.9-87.8 | 1 1/16 | | TK-9453 | 84.9-91.9 | 51.1 | DISC | MP-8 | CPM-8 | 84.9-93.3 | 1 1/8 | | WK-641 | CUP | 84.9-95.5 | (1)BH-T681 | BH-40012 | 84.9-87.8 | 5/8 | MC-10132 | MK-4328 | 84.9-85.8 | 13/16 | CC-70162 | CK-3136 |
| | | | 87.8-95.5 | 1 1/16 | | TK-T031 | 91.9-95.5 | 51.1 | DISC | MP-8 | CPM-8 | 93.3-95.5 | 1 1/8 | | WK-813 | CUP | | (2)BH-02431 | | 87.8-95.5 | 5/8 | MC-T331 | MK-4351 | 85.8-88.8 | 13/16 | CC-70178 | CK-3144 |
| | | | <ｱﾝﾁｽｷｯﾄﾞ付> | | | | | | | | | | | | | | <ｱﾝﾁｽｷｯﾄﾞ付> | | | <ﾌﾞｰｽﾀｰ付> | | | | 88.8-94.8 | 3/4 | CC-70185 | CK-T218 |
| | | | 93.9-95.5 | 1 1/8 | | TK-T352 | | | | | | | | | | | 93.9-95.5 | (1)BH-T681 | (R)BH-02192 | 84.9-87.8 | 5/8 | MC-10135 | MK-4320 | 94.8-95.5 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | | | | | | | | | | | | (2)BH-02431 | (L)BH-T684 | 87.8-88.11 | 5/8 | MC-10135 | MK-T200 | | | | |
| | | | | | | | | | | | | | | | | | | | | 88.11-89.10 | 5/8 | MC-10135 | MK-4353 | | | | |
| | | | | | | | | | | | | | | | | | | | | 89.10-95.5 | 5/8 | MC-T368 | MK-T206 | | | | |
| | | ジャストロー(Wタイヤ) | 87.8-95.5 | 1 | | TK-9452 | 87.8-93.3 | 1 1/8 | | WK-635 | CUP | 87.8-95.5 | 1 | | WK-637 | CUP | 87.8-95.5 | BH-02220 | BH-40012 | 87.8-88.11 | 5/8 | MC-10135 | MK-T200 | 87.8-88.8 | 13/16 | CC-70178 | CK-3144 |
| | | | | | | | 93.3-95.5 | 1 1/8 | | WK-814 | CUP | <ｵｰﾄｱｼﾞｬｽﾀｰ付> | | | | | | | | 88.11-89.10 | 5/8 | MC-10135 | MK-4353 | 88.8-94.8 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | <ｵｰﾄｱｼﾞｬｽﾀｰ付> | | | | | 87.8-95.5 | 1 | | WK-640 | CUP | | | | 89.10-95.5 | 5/8 | MC-T368 | MK-T206 | 94.8-95.5 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | 87.8-93.3 | 1 1/8 | | WK-636 | CUP | | | | | | | | | | | | | | | | |
| | | | | | | | 93.3-95.5 | 1 1/8 | | WK-815 | CUP | | | | | | | | | | | | | | | | |
| (3400ディーゼル) (3700ディーゼル) | | フルジャストロー(Wタイヤ) ドラム車 | 87.8-95.5 | 1 | | TK-9452 | 87.8-93.3 | 1 1/8 | | WK-635 | CUP | 87.8-95.5 | 1 | | WK-637 | CUP | 87.8-91.2 | BH-T527 | BH-40012 | 87.8-88.11 | 5/8 | MC-10135 | MK-T200 | 87.8-88.8 | 13/16 | CC-70178 | CK-3144 |
| | | | | | | | 93.3-95.5 | 1 1/8 | | WK-814 | CUP | <ｵｰﾄｱｼﾞｬｽﾀｰ付> | | | | | 91.2-93.5 | (R) | BH-40012 | 88.11-89.10 | 5/8 | MC-10135 | MK-4353 | 88.8-94.8 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | <ｵｰﾄｱｼﾞｬｽﾀｰ付> | | | | | 87.8-95.5 | 1 | | WK-640 | CUP | | (L) | | 89.10-95.5 | 5/8 | MC-T368 | MK-T206 | 94.8-95.5 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | 87.8-93.3 | 1 1/8 | | WK-636 | CUP | | | | | | 93.5-95.5 | (R) | BH-40012 | | | | | | | | |
| | | | | | | | 93.3-95.5 | 1 1/8 | | WK-815 | CUP | | | | | | | (L) | | | | | | | | | |
| | | ディスク車 | 87.8-95.5 | 1 | | TK-T027 | 87.8-95.5 | 66.6 | DISC | MP-17 | | 87.8-93.5 | 1 1/8 | | WK-715 | CUP | 87.8-92.10 | (1)BH-T681 | BH-40012 | 87.8-88.11 | 5/8 | MC-10135 | MK-T200 | 87.8-88.8 | 13/16 | CC-70178 | CK-3144 |
| | | | | | | | | | | | | 93.5-95.5 | 1 1/8 | (R-1)WC-T676 | WK-835 | CUP | | (2)BH-02516 | | 88.11-89.10 | 5/8 | MC-10135 | MK-4353 | 88.8-94.8 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | | | | | | | | (R-2) | | | 92.10-95.5 | (1) | BH-40012 | 89.10-95.5 | 5/8 | MC-T368 | MK-T206 | 94.8-95.5 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | | | | | | | | (L-1) | | | | (2)BH-02516 | | | | | | | | | |
| | | | | | | | | | | | | | | (L-2) | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | <ﾌﾞｰｽﾀｰ無> | | | | | | | |
| | | Wキャブ(Wタイヤ) ドラム車 | 84.9-95.5 | 1 | | TK-9452 | 84.9-93.3 | 1 1/8 | | WK-634 | CUP | 84.9-93.3 | 1 1/8 | | WK-413 | CUP | 84.9-87.8 | BH-02220 | BH-40012 | 84.9-87.8 | 5/8 | MC-10132 | MK-4328 | 84.9-85.8 | 13/16 | CC-70162 | CK-3136 |
| | | | | | | | 93.3-95.5 | 1 1/8 | | WK-811 | CUP | 93.3-95.5 | 1 1/8 | | WK-812 | CUP | 87.8-95.5 | BH-95002 | BH-40012 | <ﾌﾞｰｽﾀｰ付> | | | | 85.8-88.8 | 13/16 | CC-70178 | CK-3144 |
| | | | | | | | | | | | | | | | | | | | | 84.9-87.8 | 5/8 | MC-10135 | MK-4320 | 88.8-94.8 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | | | | | | | | | | | | | | 87.8-88.11 | 5/8 | MC-10135 | MK-T200 | 94.8-95.5 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | | | | | | | | | | | | | | 88.11-89.10 | 5/8 | MC-10135 | MK-4353 | | | | |
| | | | | | | | | | | | | | | | | | | | | 89.10-95.5 | 5/8 | MC-T368 | MK-T206 | | | | |
| | | | | | | | | | | | | | | | | | | | | <ﾌﾞｰｽﾀｰ無> | | | | | | | |
| | | ディスク車 | 84.9-87.8 | 1 1/16 | | TK-9453 | 84.9-91.9 | 51.1 | DISC | MP-8 | CPM-8 | 84.9-93.3 | 1 1/8 | | WK-641 | CUP | 84.9-95.5 | (1)BH-T681 | BH-40012 | 84.9-87.8 | 5/8 | MC-10132 | MK-4328 | 84.9-85.8 | 13/16 | CC-70162 | CK-3136 |
| | | | 87.8-95.5 | 1 1/16 | | TK-T031 | 91.9-95.5 | 51.1 | DISC | MP-8 | CPM-8 | 93.3-95.5 | 1 1/8 | | WK-813 | CUP | | (2)BH-02431 | | <ﾌﾞｰｽﾀｰ付> | | | | 85.8-88.8 | 13/16 | CC-70178 | CK-3144 |
| | | | | | | | | | | | | | | | | | | | | 84.9-87.8 | 5/8 | MC-10135 | MK-4320 | 88.8-94.8 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | | | | | | | | | | | | | | 87.8-88.11 | 5/8 | MC-10135 | MK-T200 | 94.8-95.5 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | | | | | | | | | | | | | | 88.11-89.10 | 5/8 | MC-10135 | MK-4353 | | | | |
| | | | | | | | | | | | | | | | | | | | | 89.10-95.5 | 5/8 | MC-T368 | MK-T206 | | | | |
| | | | | | | | | | | | | | | | | | | | | <ﾌﾞｰｽﾀｰ無> | | | | <除くﾀｰﾎﾞ車> | | | |
| (3400ディーゼル) P－BU85・85V | | 高床(Wタイヤ) | 84.9-95.5 | 1 | | TK-9452 | 84.9-93.3 | 1 1/8 | | WK-634 | CUP | 84.9-93.3 | 1 1/8 | | WK-413 | CUP | 84.9-87.8 | BH-95004 | BH-97003 | 84.9-87.8 | 5/8 | MC-10132 | MK-4328 | 84.9-85.8 | 13/16 | CC-70162 | CK-3136 |
| (3700ディーゼル) P－BU93・98 | | バン(Wタイヤ) | | | | | 93.3-95.5 | 1 1/8 | | WK-811 | CUP | 93.3-95.5 | 1 1/8 | | WK-812 | CUP | 87.8-95.5 | BH-02249 | BH-97003 | 87.8-88.8 | 5/8 | | MK-4351 | 85.8-88.8 | 13/16 | CC-70178 | CK-3144 |
| | U－BU88・94 | ドラム車 | | | | | <ｵｰﾄｱｼﾞｬｽﾀｰ付> | | | | | <ｵｰﾄｱｼﾞｬｽﾀｰ付> | | | | | | | | <ﾌﾞｰｽﾀｰ付> | | | | 88.8-94.8 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | 84.9-93.3 | 1 1/8 | | WK-639 | CUP | 84.9-93.3 | 1 1/8 | | WK-641 | CUP | | | | 84.9-87.8 | 5/8 | MC-10135 | MK-4320 | 94.8-95.5 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | 93.3-95.5 | 1 1/8 | | WK-817 | CUP | 93.3-95.5 | 1 1/8 | | WK-813 | CUP | | | | 87.8-88.11 | 5/8 | MC-10135 | MK-T200 | <ﾀｰﾎﾞ車> | | | |
| | | | | | | | | | | | | | | | | | | | | 88.11-89.10 | 5/8 | MC-10135 | MK-4353 | 84.9-85.8 | 3/4 | CC-70164 | CK-3137 |
| | | | | | | | | | | | | | | | | | | | | 89.10-95.5 | 5/8 | MC-T368 | MK-T206 | 85.8-94.8 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | | | | | | | | | | | | | | | | | | 94.8-95.5 | 3/4 | CC-70185 | CK-T218 |

| Models | TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | 高床(Wタイヤ) | | | | | | | | | | | | | | | | | | <ブースター無> | | | | <除くターボ車> | | | |
| | | ディスク車 | 84.9-87.8 | 1 1/16 | | TK-9453 | 84.9-91.9 | 51.1 | DISC | MP-8 | CPM-8 | 84.9-93.3 | 1 1/8 | | WK-413 | CUP | 84.9-87.8 | (1)BH-31404 | BH-97003 | 84.9-87.8 | 5/8 | MC-10132 | MK-4328 | 84.9-85.8 | 13/16 | CC-70162 | CK-3136 |
| | | | 87.8-95.5 | 1 1/16 | | TK-T031 | 91.9-95.5 | 51.1 | DISC | MP-8 | CPM-8 | 93.3-95.5 | 1 1/8 | | WK-812 | CUP | | (2)BH-02431 | | 87.8-88.8 | 5/8 | | MK-4351 | 85.8-88.8 | 13/16 | CC-70178 | CK-3144 |
| | | | | | | | | | | | | | | | | | 87.8-92.10 | (1)BH-02567 | BH-02518 | <ブースター付> | | | | 88.8-94.8 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | | | | | | | | | | | | (2)BH-02431 | | 84.9-87.8 | 5/8 | MC-10135 | MK-4320 | 94.8- | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | | | | | | | | | | | 92.10-95.5 | (1)BH-T678 | BH-02518 | 87.8-88.11 | 5/8 | MC-10135 | MK-T200 | <ターボ車> | | | |
| | | | | | | | | | | | | | | | | | | (2)BH-02431 | | 88.11-89.10 | 5/8 | MC-10135 | MK-4353 | 84.9-85.8 | 3/4 | CC-70164 | CK-3137 |
| | | | | | | | | | | | | | | | | | | | | 89.10-95.5 | 5/8 | MC-T368 | MK-T206 | 85.8-94.8 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | | | | | | | | | | | | | | | | | | 94.8-95.5 | 3/4 | CC-70185 | CK-T218 |
| | | ジャストロー(Wタイヤ) | 84.9-95.5 | 1 | | TK-9452 | 84.9-93.3 | 1 1/8 | | WK-635 | CUP | 84.9-95.5 | 1 | | WK-637 | CUP | 84.9-87.8 | BH-95004 | BH-97003 | <ブースター無> | | | | | | | |
| | | | | | | | 93.3-95.5 | 1 1/8 | | WK-814 | CUP | <オートアジャスター付> | | | | | 87.8-95.5 | BH-02249 | BH-97003 | 84.9-87.8 | 5/8 | MC-10132 | MK-4328 | 84.9-85.8 | 13/16 | CC-70162 | CK-3136 |
| | | | | | | | <オートアジャスター付> | | | | | 84.9-95.5 | 1 | | WK-640 | CUP | | | | 87.8-88.8 | 5/8 | | MK-4351 | 85.8-88.8 | 13/16 | CC-70178 | CK-3144 |
| | | | | | | | 84.9-93.3 | 1 1/8 | | WK-636 | CUP | | | | | | | | | <ブースター付> | | | | 88.8-94.8 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | 93.3-95.5 | 1 1/8 | | WK-815 | CUP | | | | | | | | | 84.9-87.8 | 5/8 | MC-10135 | MK-4320 | 94.8-95.5 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | | | | | | | | | | | | | | 87.8-88.11 | 5/8 | MC-10135 | MK-T200 | | | | |
| | | | | | | | | | | | | | | | | | | | | 88.11-89.10 | 5/8 | MC-10135 | MK-4353 | | | | |
| | | | | | | | | | | | | | | | | | | | | 89.10-95.5 | 5/8 | MC-T368 | MK-T206 | | | | |
| | | ダンプ | 88.8-95.5 | 1 1/16 | | TK-T031 | 88.8-95.5 | 1 1/8 | | WK-634 | CUP | 88.8-95.5 | | | WK-413 | CUP | 88.8-95.5 | (R)BH-02567 | BH-02518 | 88.8-89.10 | 5/8 | MC-10135 | MK-T200 | 88.8-95.5 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | | | | | | | | | | | | (L)BH-02567 | | 89.10-95.5 | 5/8 | MC-T368 | MK-T206 | | | | |
| (3400ディーゼル) P-BU85・85V | | フルジャストロー(Wタイヤ) | 87.8-95.5 | 1 | | TK-9452 | 87.8-93.3 | 1 1/8 | | WK-634 | CUP | 87.8-93.3 | 1 1/8 | | WK-413 | CUP | 87.8-95.5 | BH-02249 | BH-97003 | 87.8-88.11 | 5/8 | MC-10135 | MK-T200 | 87.8-88.8 | 13/16 | CC-70178 | CK-3144 |
| (3700ディーゼル) P-BU93・98 | | ドラム車 | | | | | 93.3-95.5 | 1 1/8 | | WK-811 | CUP | 93.3-95.5 | 1 1/8 | | WK-812 | CUP | | | | 88.11-89.10 | 5/8 | MC-10135 | MK-4353 | 88.8-94.8 | 3/4 | CC-70185 | CK-T218 |
| U-BU88・94 | | | | | | | <オートアジャスター付> | | | | | <オートアジャスター付> | | | | | | | | 89.10-95.5 | 5/8 | MC-T368 | MK-T206 | 94.8-95.5 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | 87.8-93.3 | 1 1/8 | | WK-639 | CUP | 87.8-93.3 | 1 1/8 | | WK-641 | CUP | | | | | | | | | | | | |
| | | | | | | | 93.3-95.5 | 1 1/8 | | WK-817 | CUP | 93.3-95.5 | 1 1/8 | | WK-813 | CUP | | | | | | | | | | | | |
| | | ディスク車 | 87.8-95.5 | 1 1/16 | | TK-T031 | 87.8-91.9 | 51.1 | DISC | MP-8 | CPM-8 | 87.8-93.3 | 1 1/8 | | WK-641 | CUP | 87.8-92.10 | (1)BH-02567 | BH-02518 | 87.8-88.11 | 5/8 | MC-10135 | MK-T200 | 87.8-88.8 | 13/16 | CC-70178 | CK-3144 |
| | | | | | | | 91.9-95.5 | 51.1 | DISC | MP-8 | CPM-8 | 93.3-95.5 | 1 1/8 | | WK-813 | CUP | | (2)BH-02431 | | 88.11-89.10 | 5/8 | MC-10135 | MK-4353 | 88.8-94.8 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | | | | | | | | | | | 92.10-95.5 | (1)BH-T678 | BH-02518 | 89.10-95.5 | 5/8 | MC-T368 | MK-T206 | 94.8-95.5 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | | | | | | | | | | | | (2)BH-02431 | | | | | | | | | |
| | | Wキャブ(Wタイヤ) | 84.9-95.5 | 1 | | TK-9452 | 84.9-93.3 | 1 1/8 | | WK-634 | CUP | 84.9-93.3 | 1 1/8 | | WK-413 | CUP | 84.9-87.8 | BH-95004 | BH-97003 | <ブースター無> | | | | | | | |
| | | ドラム車 | | | | | 93.3-95.5 | 1 1/8 | | WK-811 | CUP | 93.3-95.5 | 1 1/8 | | WK-812 | CUP | 87.8-95.5 | BH-02249 | BH-97003 | 84.9-87.8 | 5/8 | MC-10132 | MK-4328 | 84.9-85.8 | 13/16 | CC-70162 | CK-3136 |
| | | | | | | | | | | | | | | | | | | | | <ブースター付> | | | | 85.8-88.8 | 13/16 | CC-70178 | CK-3144 |
| | | | | | | | | | | | | | | | | | | | | 84.9-87.8 | 5/8 | MC-10135 | MK-4320 | 88.8-94.8 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | | | | | | | | | | | | | | 87.8-88.11 | 5/8 | MC-10135 | MK-T200 | 94.8-95.5 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | | | | | | | | | | | | | | 88.11-89.10 | 5/8 | MC-10135 | MK-4353 | | | | |
| | | | | | | | | | | | | | | | | | | | | 89.10-95.5 | 5/8 | MC-T368 | MK-T206 | | | | |
| | | ディスク車 | 87.8-95.5 | 1 1/16 | | TK-T031 | 87.8-91.9 | 51.1 | DISC | MP-8 | CPM-8 | 87.8-93.3 | 1 1/8 | | WK-641 | CUP | 87.8-92.10 | (1)BH-02567 | BH-02518 | 87.8-88.11 | 5/8 | MC-10135 | MK-T200 | 87.8-88.8 | 13/16 | CC-70178 | CK-3144 |
| | | | | | | | 91.9-95.5 | 51.1 | DISC | MP-8 | CPM-8 | 93.3-95.5 | 1 1/8 | | WK-813 | CUP | | (2)BH-02431 | | 88.11-89.10 | 5/8 | MC-10135 | MK-4353 | 88.8-94.8 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | | | | | | | | | | | 92.10-95.5 | (1)BH-T678 | BH-02518 | 89.10-95.5 | 5/8 | MC-T368 | MK-T206 | 94.8-95.5 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | | | | | | | | | | | | (2)BH-02431 | | | | | | | | | |
| (3400ディーゼル) P-BU90・95 | | 高床(Wタイヤ) | 84.9-95.5 | 1 1/8 | | TK-9454 | 84.9-95.5 | 1 5/16 | | WK-585 | CUP | 84.9-95.5 | 1 1/4 | | WK-412 | CUP | 84.9-87.8 | BH-95004 | BH-97003 | 84.9-87.8 | 5/8 | MC-10135 | MK-4320 | 84.9-85.8 | 3/4 | CC-70164 | CK-3137 |
| (3700ディーゼル) U-BU91・96 | | フルジャストロー(Wタイヤ) | | | | | | | | | | | | | | | 87.8-95.5 | BH-95000 | BH-97003 | 87.8-88.11 | 5/8 | MC-10135 | MK-T200 | 85.8-94.8 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | | | | | | | | | | | | | | 88.11-89.10 | 5/8 | MC-10135 | MK-4353 | 94.8-95.5 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | | | | | | | | | | | | | | 89.10-95.5 | 5/8 | MC-T368 | MK-T206 | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| DYNA, TOYOACE : WU70-90 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (4000ディーゼル) | | 高床(Wタイヤ) | 84.9-95.5 | 1 1/8 | | TK-9454 | 84.9-95.5 | 1 5/16 | | WK-585 | CUP | 84.9-95.5 | 1 1/4 | | WK-412 | CUP | 84.9-87.8<br>87.8-95.5 | BH-95004<br>BH-95000 | BH-97003<br>BH-97003 | <ブースター無><br>84.9-87.8<br><ブースター付><br>84.9-87.8<br>87.8-88.11<br>88.11-89.10<br>89.10-91.8<br>91.8-95.5 | 5/8<br><br>5/8<br>5/8<br>5/8<br>5/8 | MC-10132<br><br>MC-10135<br>MC-10135<br>MC-10135<br>MC-T368 | MK-4328<br><br>MK-4320<br>MK-T200<br>MK-4353<br>MK-T206<br>MK-T229 | 84.9-87.8<br>87.8-89.10<br>89.10-94.8<br>94.8-95.5 | 3/4<br>3/4<br>3/4 | CC-70163<br>CC-70190 | CK-3135<br>CK-3135<br>CK-3135 |
| | P-WU75D・90・95<br>U-WU75D・90・95<br><U-は89. 10~> | フルジャストロー(Wタイヤ)<br>標準ダンプ(Wタイヤ) | | | | | | | | | | | | | | | | | | | | | | | | | |
| | U-WU85・93 | 高床(Wタイヤ)<br>フルジャストロー(Wタイヤ)<br>ドラム車 | 89.10-95.5 | 1 | | TK-9452 | 89.10-93.3<br>93.3-95.5<br><オートアジャスター付><br>93.9-95.5 | 1 1/8<br>1 1/8<br><br>1 1/8 | | WK-634<br>WK-811<br><br>WK-817 | CUP<br>CUP<br><br>CUP | 89.10-93.3<br>93.3-95.5<br><オートアジャスター付><br>93.9-95.5 | 1 1/8<br>1 1/8<br><br>1 1/8 | | WK-413<br>WK-812<br><br>WK-813 | CUP<br>CUP<br><br>CUP | 89.10-95.5 | BH-02249 | BH-97003 | 89.10-91.8<br>91.8-95.5 | 5/8 | MC-T368 | MK-T206 | 89.10-94.8<br>94.8-95.5 | 3/4 | CC-70185 | CK-T218<br>CK-T218 |
| | | ディスク車 | 89.10-95.5 | 1 1/16 | | TK-T031 | 89.10-91.9<br>91.9-95.5 | 51.1<br>51.1 | DISC<br>DISC | MP-8<br>MP-8 | CPM-8<br>CPM-8 | 89.10-93.3<br>93.3-95.5 | 1 1/8<br>1 1/8 | | WK-641<br>WK-813 | CUP<br>CUP | 89.10-95.5 | (1)BH-02567<br>(2)BH-02431 | BH-02518 | 89.10-91.8<br>91.8-95.5 | 5/8 | MC-T368 | MK-T206 | 89.10-94.8<br>94.8-95.5 | 3/4 | CC-70185 | CK-T218<br>CK-T218 |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| DYNA, TOYOACE : RZU100 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| GB－RZU100・100H・140<br><GEｰは99．5～><br>(3RZ－FE)<br>(3RZ－FP)<br>(15B－FP) | 高 床2t・3t<br>(ドラム車) | <2t><br>95.5-00.5<br><ｵﾌﾟｼｮﾝ><br><3t><br>95.5-00.5 | 1<br><br><br>1 1/16 | | TK-T372<br><br><br>TK-T373 | 95.5-00.5 | 1 1/8 | | WK-811 | CUP | <2t><br>95.5-00.5<br><ｵﾌﾟｼｮﾝ><br><3t><br>95.5-00.5 | 1<br><br><br>1 1/8 | | WK-863<br><br><br>WK-812 | CUP<br><br><br>CUP | 95.5-98.12<br>98.12-99.5<br>99.5-00.5 | BH-T675<br>BH-T675<br>BH-31365 | BH-40012<br>BH-T938<br>BH-T938 | 95.5-00.5 | 5/8 | | MK-T244 | 95.5-00.5 | 7/8 | | CK-3122 |
| | 高 床2t・3t<br>(ディスク車) | 95.5-98.5<br>98.5-00.5 | 1 1/8<br>1 1/8 | | TK-T374<br>TK-T433 | 95.5-00.5 | 51.1 | DISC | MP-8 | CPM-8 | 95.5-00.5 | 1 1/8 | | WK-813 | CUP | 95.5-98.12<br><br>98.12-99.5<br><br>99.5-00.5 | (1)BH-02492<br>(2)BH-02431<br>(1)BH-T863<br>(2)BH-02431<br>(1)BH-T863<br>(2)BH-02431 | BH-40012<br><br>BH-T938<br><br>BH-T938 | 95.5-00.5<br><15Bｴﾝｼﾞﾝ><br>99.5-00.5 | 5/8<br><br>5/8 | | MK-T244<br><br>MK-T206 | 95.5-00.5<br><15Bｴﾝｼﾞﾝ><br>99.5-00.5 | 7/8<br><br>3/4 | | CK-3122<br><br>CK-T216 |
| | ジャストロー | 95.5-00.5 | 1 | | TK-T372 | 95.5-00.5 | 1 1/8 | | WK-814 | CUP | 95.5-00.5 | 1 1/8 | | WK-816 | CUP | 95.5-98.12<br>98.12-99.5<br>99.5-00.5 | BH-95002<br>BH-95002 | BH-97001<br>BH-T938<br>BH-T938 | 95.5-00.5 | 5/8 | | MK-T244 | 95.5-00.5 | 7/8 | | CK-3122 |
| | フルジャストロー<br>(ドラム車) | 95.5-00.5 | 1 | | TK-T372 | 95.5-00.5 | 1 1/8 | | WK-814 | CUP | 95.5-00.5 | 1 1/8 | | WK-816 | CUP | 95.5-98.12<br><br>98.12-99.5<br><br>99.5-00.5 | (R)<br>(L)<br>(R)<br>(L)<br>(R)<br>(L) | BH-40012<br><br>BH-T938<br><br>BH-T938 | 95.5-00.5 | 5/8 | | MK-T244 | 95.5-00.5 | 7/8 | | CK-3122 |
| | フルジャストロー<br>(ディスク車) | 95.5-00.5<br><15Bｴﾝｼﾞﾝ><br>99.5-00.5 | 1<br><br>1 1/8 | | TK-T372<br><br>TK-T433 | 95.5-00.5<br><15Bｴﾝｼﾞﾝ><br>99.5-00.5 | 66.6<br><br>51.1 | DISC<br><br>DISC | MP-17<br><br>MP-8 | <br><br>CPM-8 | 95.5-00.5<br><br><br><15Bｴﾝｼﾞﾝ><br>99.5-00.5 | 1 1/8<br><br><br><br>1 1/8 | (R-1)WC-T676<br>(R-2)<br>(L-1)<br>(L-2) | WK-835<br><br><br><br>WK-813 | CUP<br><br><br><br>BH-T938 | 95.5-98.12<br><br>98.12-00.5<br><br>99.5-00.5 | (1)BH-02576<br>(2)BH-T686<br>(1)BH-T888<br>(2)BH-T686<br>(1)BH-T863<br>(2)BH-T686 | BH-40012<br><br>BH-T938 | 95.5-00.5<br><15Bｴﾝｼﾞﾝ><br>99.5-00.5 | 5/8<br><br>5/8 | | MK-T244<br><br>MK-T206 | 95.5-00.5<br><15Bｴﾝｼﾞﾝ><br>99.5-00.5 | 7/8<br><br>3/4 | | CK-3122<br><br>CK-T216 |
| GB－RZU100A<br><GEｰは99．5～><br>(3RZ－FE)<br>(3RZ－FP)<br>(15B－FP) | TWMMK | 97.8-00.5 | 1 | | TK-T372 | 97.8-00.5 | 1 1/8 | | WK-816 | CUP | 97.8-00.5 | 1 1/8 | | WK-816 | CUP | 97.8-98.12<br><br>98.12-99.5<br><br>99.5-00.5 | (R)<br>(L)<br>(R)<br>(L)<br>(R)<br>(L) | BH-97001<br><br>BH-97001<br><br>BH-97001 | 97.8-00.5 | 5/8 | | MK-T244 | 97.8-00.5 | 7/8 | | CK-3122 |
| | TYMMK・TYMMC<br>(ドラム車) | 95.5-00.5 | 1 1/16 | | TK-T373 | 95.5-00.5 | 1 1/8 | | WK-811 | CUP | 95.5-00.5 | 1 1/8 | | WK-812 | CUP | 95.5-99.5<br>99.5-00.5 | BH-T675<br>BH-31365 | BH-40012<br>BH-T938 | 95.5-00.5 | 5/8 | | MK-T244 | 95.5-00.5 | 7/8 | | CK-3122 |
| | TYMMK・TYMMC・TYMMP<br>(ディスク車) | 95.5-98.5<br>98.5-00.5 | 1 1/8<br>1 1/8 | | TK-T374<br>TK-T433 | 95.5-00.5 | 51.1 | DISC | MP-8 | CPM-8 | 95.5-00.5 | 1 1/8 | | WK-813 | CUP | 95.5-98.12<br><br>98.12-99.5<br><br>99.5-00.5 | (1)BH-02492<br>(2)BH-02431<br>(1)BH-T863<br>(2)BH-02431<br>(1)BH-T863<br>(2)BH-02431 | BH-40012<br><br>BH-T938<br><br>BH-T938 | 95.5-00.5<br><TYMMP><br>99.5-00.5 | 5/8<br><br>5/8 | | MK-T244<br><br>MK-T206 | 95.5-00.5<br><TYMMP><br>99.5-00.5 | 7/8<br><br>3/4 | | CK-3122<br><br>CK-T216 |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| DYNA, TOYOACE : BU100 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| KC－BU100・120V<br>KC－BU102・122V<br>(3B)<br>(15B－F) | Sタイヤ | 95.5-99.5 | 1 | | TK-T372 | 95.5-99.5 | 1 1/8 | (R)WC-T017<br>(L)WC-T078 | WK-814 | CUP | 95.5-99.5 | 1 | (R-1)WC-T500<br>(R-2)WC-T501<br>(L-1)WC-T502<br>(L-2)WC-T503 | WK-637 | CUP | 95.5-98.12<br>98.12-99.5 | BH-95002<br>BH-95002 | BH-40012<br>BH-T938 | <BU100,120><br>95.5-99.5<br><BU102,122><br>95.5-99.5 | 5/8<br>5/8 | MC-T445<br>MC-T473 | MK-T244<br>MK-T206 | 95.5-99.5 | 3/4 | CC-70185 | CK-T218 |
| | 高 床Wタイヤ<br>（ドラム車）<br><ｵﾌﾟｼｮﾝ> | 95.5-99.6<br>95.5-99.6 | 1<br>1 1/16 | | TK-T372<br>TK-T373 | 95.5-99.6 | 1 1/8 | (R)WC-T028<br>(L)WC-T773 | WK-811 | CUP | 95.5-99.6<br><ｵﾌﾟｼｮﾝ><br>95.5-99.6 | 1<br>1 1/8 | | WK-863<br>WK-812 | CUP<br>CUP | 95.5-98.12<br>98.12-99.6 | BH-T675<br>BH-T675 | BH-40012<br>BH-T938 | <BU100><br>95.5-99.6<br><BU102><br>95.5-99.6 | 5/8<br>5/8 | MC-T445<br>MC-T473 | MK-T244<br>MK-T206 | 95.5-99.6 | 3/4 | CC-70185 | CK-T218 |
| | 高 床Wタイヤ<br>（ディスク車） | 95.5-98.5<br>98.5-99.6 | 1 1/8<br>1 1/8 | | TK-T374<br>TK-T433 | 95.5-99.6 | 51.1 | DISC | MP-8 | CPM-8 | 95.5-99.6 | 1 1/8 | | WK-813 | CUP | 95.5-98.12<br>98.12-99.6 | (1)BH-02492<br>(2)BH-02431<br>(1)BH-T863<br>(2)BH-02431 | BH-40012<br>BH-T938 | <BU100><br>95.5-99.6<br><BU102><br>95.5-99.6 | 5/8<br>5/8 | MC-T445<br>MC-T473 | MK-T244<br>MK-T206 | 95.5-99.6 | 3/4 | CC-70185 | CK-T218 |
| | ジャストローWタイヤ | 95.5-99.6 | 1 | | TK-T372 | <MT車><br>95.5-99.6<br><AT車><br>95.5-99.5<br><ﾔﾏﾄ運輸仕様><br>95.5-96.10 | 1 1/8<br>1 1/8<br>1 1/8 | (R)WC-T017<br>(L)WC-T078<br>(R)WC-T019<br>(L)WC-T080<br>(R)WC-T019<br>(L)WC-T080 | WK-814<br>WK-815<br>WK-815 | CUP<br>CUP<br>CUP | <MT車><br>95.5-99.6<br><AT車><br>95.5-99.5<br><ﾔﾏﾄ運輸仕様><br>95.5-96.10 | 1 1/8<br>1 1/8<br>1 1/8 | (R-1)WC-T676<br>(R-2)<br>(L-1)<br>(L-2)<br>(R-1)WC-T676<br>(R-2)<br>(L-1)<br>(L-2) | WK-816<br>WK-835<br>WK-835 | CUP<br>CUP<br>CUP | 95.5-98.12<br>98.12-99.6 | BH-95002<br>BH-95002 | BH-97001<br>BH-97001 | <BU100><br>95.5-99.6<br><BU102><br>95.5-99.6 | 5/8<br>5/8 | MC-T445<br>MC-T473 | MK-T244<br>MK-T206 | 95.5-99.6 | 3/4 | CC-70185 | CK-T218 |
| | フルジャストローWタイヤ<br>（ドラム車） | 95.5-99.6 | 1 | | TK-T372 | <MT車><br>95.5-99.6<br><AT車><br>95.5-99.6 | 1 1/8<br>1 1/8 | (R)WC-T017<br>(L)WC-T078<br>(R)WC-T019<br>(L)WC-T080 | WK-814<br>WK-815 | CUP<br>CUP | <MT車><br>95.5-99.6<br><AT車><br>95.5-99.6 | 1 1/8<br>1 1/8 | (R-1)WC-T676<br>(R-2)<br>(L-1)<br>(L-2) | WK-816<br>WK-835 | CUP<br>CUP | 95.5-98.12<br>98.12-99.6 | (R)<br>(L)<br>(R)<br>(L) | BH-40012<br>BH-T938 | <BU100><br>95.5-99.6<br><BU102><br>95.5-99.6 | 5/8<br>5/8 | MC-T445<br>MC-T473 | MK-T244<br>MK-T206 | 95.5-99.6 | 3/4 | CC-70185 | CK-T218 |
| | フルジャストローWタイヤ<br>（ディスク車） | 95.5-99.6 | 1 | | TK-T372 | 95.5-99.6 | 66.6 | DISC | MP-17 | | 95.5-99.6 | 1 1/8 | (R-1)WC-T676<br>(R-2)<br>(L-1)<br>(L-2) | WK-835 | CUP | 95.5-98.12<br>98.12-99.6 | (1)BH-02576<br>(2)BH-T686<br>(1)BH-T888<br>(2)BH-T686 | BH-40012<br>BH-T938 | <BU100><br>95.5-99.6<br><BU102><br>95.5-99.6 | 5/8<br>5/8 | MC-T445<br>MC-T473 | MK-T244<br>MK-T206 | 95.5-99.6 | 3/4 | CC-70185 | CK-T218 |
| KC－BU100A<br>KC－BU102A・102D<br>(3B)<br>(15B－F)<br>(15B－FP) | 強化ダンプ<br>三転ダンプ<br>（ドラム車） | 95.5-99.5 | 1 1/16 | | TK-T373 | 95.5-99.5 | 1 1/8 | | WK-811 | CUP | 95.5-99.5 | 1 1/8 | | WK-812 | CUP | 95.5-98.12<br>98.12-99.5 | BH-T675<br>BH-T675 | BH-40012<br>BH-T938 | <BU100><br>95.5-99.5<br><BU102><br>95.5-99.5 | 5/8<br>5/8 | MC-T445<br>MC-T473 | MK-T244<br>MK-T206 | 95.5-99.5<br><LPG車><br>97.8-99.5 | 3/4<br>3/4 | CC-70185<br>CC-T382 | CK-T218<br>CK-T216 |
| | 強化ダンプ<br>（ディスク車） | 95.5-98.5<br>98.5-99.5 | 1 1/8<br>1 1/8 | | TK-T374<br>TK-T433 | 95.5-99.5 | 51.1 | DISC | MP-8 | CPM-8 | 95.5-99.5 | 1 1/8 | | WK-813 | CUP | 95.5-98.12<br>98.12-99.5 | (1)BH-02492<br>(2)BH-02431<br>(1)BH-T863<br>(2)BH-02431 | BH-40012<br>BH-T938 | <BU100><br>95.5-99.5<br><BU102><br>95.5-99.5 | 5/8<br>5/8 | MC-T445<br>MC-T473 | MK-T244<br>MK-T206 | 95.5-99.5<br><LPG車><br>97.8-99.5 | 3/4<br>3/4 | CC-70185<br>CC-T382 | CK-T218<br>CK-T216 |
| | ジャストローダンプ | 95.5-99.5 | 1 | | TK-T372 | 95.5-99.5 | 1 1/8 | | WK-816 | CUP | 95.5-99.5 | 1 1/8 | | WK-816 | CUP | 95.5-98.12<br>98.12-99.5 | BH-95002<br>BH-95002 | BH-97001<br>BH-97001 | 95.5-99.5 | 5/8 | MC-T473 | MK-T206 | 95.5-99.5 | 3/4 | CC-70185 | CK-T218 |
| | フルジャストローダンプ | 95.5-99.5 | 1 | | TK-T372 | 95.5-99.5 | 1 1/8 | | WK-816 | CUP | 95.5-99.5 | 1 1/8 | | WK-816 | CUP | 95.5-98.12<br>98.12-99.5 | (R)<br>(L)<br>(R)<br>(L) | BH-97001<br>BH-97001 | 95.5-99.5 | 5/8 | MC-T473 | MK-T206 | 95.5-99.5 | 3/4 | CC-70185 | CK-T218 |
| KC－BU102H<br>(15B－F)<br>(15B－FP) | ドラム車 | 95.5-99.5 | 1 1/16 | | TK-T373 | <MT車><br>95.5-99.5<br><AT車><br>97.8-99.5 | 1 1/8<br>1 1/8 | | WK-811<br>WK-817 | CUP<br>CUP | <MT車><br>95.5-99.5<br><AT車><br>97.8-99.5 | 1 1/8<br>1 1/8 | | WK-812<br>WK-813 | CUP<br>CUP | 95.5-98.12<br>98.12-99.5 | BH-T675<br>BH-T675 | BH-40012<br>BH-T938 | 95.5-99.5 | 5/8 | MC-T473 | MK-T206 | 95.5-99.5 | 3/4 | CC-T382 | CK-T216 |
| | ディスク車 | 95.5-98.5<br>98.5-99.5 | 1 1/8<br>1 1/8 | | TK-T374<br>TK-T433 | 95.5-99.5 | 51.1 | DISC | MP-8 | CPM-8 | 95.5-99.5 | 1 1/8 | | WK-813 | CUP | 95.5-98.12<br>98.12-99.5 | (1)BH-02492<br>(2)BH-02431<br>(1)BH-T863<br>(2)BH-02431 | BH-40012<br>BH-T938 | 95.5-99.5 | 5/8 | MC-T473 | MK-T206 | 95.5-99.5 | 3/4 | CC-T382 | CK-T216 |
| KC－BU105・107<br>(3B)<br>(15B－F) | 高 床 | 97.8-98.5<br>98.5-99.5 | 1 1/8<br>1 1/8 | | TK-T374<br>TK-T433 | 97.8-99.5 | | DISC | MP-81 | CPM-81 | 97.8-99.5 | 1 1/8 | | WK-813 | CUP | 97.8-98.12<br>98.12-99.5 | (R)<br>(L)<br>(R)<br>(L) | BH-40012<br>BH-T938 | <BU105><br>97.8-99.5<br><BU107><br>97.8-99.5 | 5/8<br>5/8 | MC-T445<br>MC-T473 | MK-T244<br>MK-T206 | 97.8-99.5 | 3/4 | CC-70185 | CK-T218 |
| | ジャストロー | 96.10-99.5 | 1 1/16 | | TK-T373 | 96.10-99.5 | | DISC | MP-81 | CPM-81 | 96.10-99.5 | 1 1/8 | (R-1)WC-T676<br>(R-2)<br>(L-1)<br>(L-2) | WK-835 | CUP | 96.10-98.12<br>98.12-99.5 | (R)<br>(L)<br>(R)<br>(L) | BH-97001<br>BH-97001 | <BU105><br>96.10-99.5<br><BU107><br>96.10-99.5 | 5/8<br>5/8 | MC-T445<br>MC-T473 | MK-T244<br>MK-T206 | 96.10-99.5 | 3/4 | CC-70185 | CK-T218 |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| KC－BU105・107<br>(3B)<br>(15B－F) | フルジャストロー | 96.10-99.5 | 1 1/16 | | TK-T373 | 96.10-99.5 | | DISC | MP-81 | CPM-81 | 96.10-99.5 | 1 1/8 | (R-1)WC-T676<br>(R-2)<br>(L-1)<br>(L-2) | WK-835 | CUP | 96.10-98.12<br><br><br>98.12-99.5 | (R)<br>(L)<br>(R)<br>(L) | BH-40012<br><br><br>BH-T938 | <BU105><br>96.10-99.5<br><BU107><br>96.10-99.5 | 5/8<br><br><br>5/8 | MC-T445<br><br><br>MC-T473 | MK-T244<br><br><br>MK-T206 | 96.10-99.5 | 3/4 | CC-70185 | CK-T218 |
| KC－BU112<br>(15B－F) | ドラム車 | 95.5-99.5 | 1 | | TK-T372 | <MT車><br>95.5-99.5<br><AT車><br>95.5-99.5 | 1 1/8<br><br>1 1/8 | | WK-811<br><br>WK-817 | CUP<br><br>CUP | <MT車><br>95.5-99.5<br><AT車><br>95.5-99.5 | 1<br><br>1 | | WK-863<br><br>WK-882 | CUP<br><br>CUP | 95.5-98.12<br>98.12-99.5 | BH-95002<br>BH-95002 | BH-36212<br>BH-36212 | 95.5-99.5 | 5/8 | MC-T473 | MK-T206 | 95.5-99.5 | 3/4 | CC-70185 | CK-T218 |
| | ディスク車 | 95.5-98.5<br>98.5-99.5 | 1 1/8<br>1 1/8 | | TK-T374<br>TK-T433 | 95.5-99.5 | 51.1 | DISC | MP-8 | CPM-8 | 95.5-99.5 | 1 1/8 | | WK-813 | CUP | 95.5-98.12<br><br>98.12-99.5 | (1)BH-02492<br>(2)BH-02431<br>(1)BH-T863<br>(2)BH-02431 | BH-36212<br><br>BH-36212 | 95.5-99.5 | 5/8 | MC-T473 | MK-T206 | 95.5-99.5 | 3/4 | CC-70185 | CK-T218 |
| KC－BU112A・112D<br>(15B－F) | | 95.5-99.5 | 1 1/16 | | TK-T373 | <MT車><br>95.5-99.5<br><AT車><br>95.5-99.5 | 1 1/8<br><br>1 1/8 | | WK-811<br><br>WK-817 | CUP<br><br>CUP | <MT車><br>95.5-99.5<br><AT車><br>95.5-99.5 | 1 1/8<br><br>1 1/8 | | WK-812<br><br>WK-813 | CUP<br><br>CUP | 95.5-98.12<br>98.12-99.5 | BH-95002<br>BH-95002 | BH-36212<br>BH-36212 | 95.5-99.5 | 5/8 | MC-T473 | MK-T206 | <BU112A><br>96.10-99.5<br><BU112D><br>95.5-99.5 | 3/4<br><br>3/4 | CC-T382<br><br>CC-70185 | CK-T216<br><br>CK-T218 |
| KC－BU132<br>(15B－F) | 高 床<br>(ドラム車) | 95.5-99.5 | 1 1/16 | | TK-T373 | <MT車><br>95.5-99.5<br><AT車><br>95.5-99.5 | 1 1/8<br><br>1 1/8 | | WK-811<br><br>WK-817 | CUP<br><br>CUP | <MT車><br>95.5-99.5<br><AT車><br>95.5-99.5 | 1 1/8<br><br>1 1/8 | | WK-812<br><br>WK-813 | CUP<br><br>CUP | 95.5-99.5 | BH-T675 | BH-T689 | 95.5-99.5 | 5/8 | MC-T473 | MK-T206 | 95.5-99.5 | 3/4 | CC-T382 | CK-T216 |
| | 高 床<br>(ディスク車) | 95.5-98.5<br>98.5-99.5 | 1 1/8<br>1 1/8 | | TK-T374<br>TK-T433 | 95.5-99.5 | 51.1 | DISC | MP-8 | CPM-8 | 95.5-99.5 | 1 1/8 | | WK-813 | CUP | 95.5-98.12<br><br>98.12-99.5 | (1)BH-02492<br>(2)BH-02431<br>(1)BH-T863<br>(2)BH-02431 | BH-T689<br><br>BH-T689 | 95.5-99.5 | 5/8 | MC-T473 | MK-T206 | 95.5-99.5 | 3/4 | CC-T382 | CK-T216 |
| | 低キャブ | 97.2-99.5 | 1 1/16 | | TK-T373 | <MT車><br>97.2-99.5<br><AT車><br>97.2-99.5 | 1 1/8<br><br>1 1/8 | | WK-811<br><br>WK-817 | CUP<br><br>CUP | <MT車><br>97.2-99.5<br><AT車><br>97.2-99.5 | 1 1/8<br><br>1 1/8 | | WK-812<br><br>WK-813 | CUP<br><br>CUP | 97.2-99.5 | BH-02249 | BH-T689 | 97.2-99.5 | 5/8 | MC-T473 | MK-T206 | 97.2-99.5 | 3/4 | CC-T382 | CK-T216 |
| | フルジャストロー<br>(ドラム車) | 95.5-99.5 | 1 | | TK-T372 | 95.5-99.5 | 1 1/8 | | WK-814 | CUP | 95.5-99.5 | 1 1/8 | | WK-816 | CUP | 95.5-99.5 | (R)<br>(L) | BH-T689 | 95.5-99.5 | 5/8 | MC-T473 | MK-T206 | 95.5-99.5 | 3/4 | CC-70185 | CK-T218 |
| | フルジャストロー<br>(ディスク車) | 95.5-99.5 | 1 | | TK-T372 | 95.5-99.5 | 66.6 | DISC | MP-17 | | 95.5-99.5 | 1 1/8 | (R-1)WC-T676<br>(R-2)<br>(L-1)<br>(L-2) | WK-835 | CUP | 95.5-98.12<br><br>98.12-99.5 | (1)BH-02576<br>(2)BH-T686<br>(1)BH-T888<br>(2)BH-T686 | BH-T689<br><br>BH-T689 | 95.5-99.5 | 5/8 | MC-T473 | MK-T206 | 95.5-99.5 | 3/4 | CC-70185 | CK-T218 |
| KC－BU137<br>(15B－F) | | 96.10-99.5 | 1 1/16 | | TK-T373 | 96.10-99.5 | | DISC | MP-81 | CPM-81 | 96.10-99.5 | 1 1/8 | (R-1)WC-T676<br>(R-2)<br>(L-1)<br>(L-2) | WK-835 | CUP | 96.10-99.5 | (R)<br>(L) | BH-T689 | 96.10-99.5 | 5/8 | MC-T473 | MK-T206 | 96.10-99.5 | 3/4 | CC-70185 | CK-T218 |
| KC－BU140・142<br>(3B)<br>(15B－F)<br>(15B－FP) | 高 床2t・3t<br>(ドラム車) | <2t><br>95.5-99.6<br><3t><br>95.5-99.6 | 1<br><br>1 1/16 | | TK-T372<br><br>TK-T373 | <MT車><br>95.5-99.6<br><AT車><br>95.5-99.5<br><ヤマト運輸仕様><br>95.5-99.6 | 1 1/8<br><br>1 1/8<br><br>1 1/8 | <br><br><br><br>(R)WC-T028<br>(L) | WK-811<br><br>WK-817<br><br>WK-817 | CUP<br><br>CUP<br><br>CUP | <MT車><br>95.5-99.6<br><AT車><br>95.5-99.5<br><ヤマト運輸仕様><br>95.5-99.6 | 1 1/8<br><br>1 1/8<br><br>1 1/8 | <br><br><br><br>(R-1)WC-T679<br>(R-2)WC-T782<br>(L-1)WC-T783<br>(L-2)WC-T784 | WK-812<br><br>WK-813<br><br>WK-813 | CUP<br><br>CUP<br><br>CUP | <BU140><br><BU142 ABS無><br>95.5-98.12<br><br><br>98.12-99.6<br><br><br><BU142 ABS付><br>95.5-98.12<br><br><br>98.12-99.6<br><br> | <br>(R)BH-T675<br>(L)BH-T675<br>(R)BH-T675<br>(L)BH-T675<br><br>(R)BH-T675<br>(L)BH-T675<br>(R)BH-T675<br>(L)BH-T675 | <br>BH-40012<br><br>BH-T938<br><br><br>(R)<br>(L)BH-02192<br>(R)<br>(L)BH-02192 | <BU140><br><BU142 ABS無><br><BU142><br>95.5-99.6<br><br><br><BU142 ABS付><br><br><br><br><br><br><br> | 5/8<br><br>5/8 | MC-T445<br><br>MC-T473 | MK-T244<br><br>MK-T206 | <2t><br>95.5-99.6<br><3t><br>95.5-99.6 | 3/4<br><br>3/4 | CC-70185<br><br>CC-T382 | CK-T218<br><br>CK-T216 |
| | 高 床2t・3t<br>(ディスク車) | 95.5-98.5<br>98.5-99.6<br><アンチスキッド付><br>95.5-99.6 | 1 1/8<br>1 1/8<br><br>1 1/8 | | TK-T374<br>TK-T433<br><br>TK-T375 | 95.5-99.6 | 51.1 | DISC | MP-8 | CPM-8 | 95.5-99.6 | 1 1/8 | | WK-813 | CUP | <BU140><br><BU142 ABS無><br>95.5-98.12<br><br><br><br>98.12-99.6<br><br><br><br><BU142 ABS付><br>95.5-98.12<br><br><br><br>98.12-99.6<br><br><br> | <br>(R-1)BH-02492<br>(R-2)BH-02431<br>(L-1)BH-02492<br>(L-2)BH-02431<br>(R-1)BH-T863<br>(R-2)BH-02431<br>(L-1)BH-T863<br>(L-2)BH-02431<br><br>(R-1)BH-02492<br>(R-2)BH-02431<br>(L-1)BH-02492<br>(L-2)BH-02431<br>(R-1)BH-T863<br>(R-2)BH-02431<br>(L-1)BH-T863<br>(L-2)BH-02431 | <br>BH-40012<br><br>BH-T938<br><br><br>(R)<br>(L)BH-02192<br>(R)<br>(L)BH-02192 | <BU140><br><BU142 ABS無><br><BU142><br>95.5-99.6<br><br><br><br><br><br><br><br><br><br><br> | 5/8<br><br>5/8 | MC-T445<br><br>MC-T473 | MK-T244<br><br>MK-T206 | <2t><br>95.5-99.6<br><3t><br>95.5-99.6 | 3/4<br><br>3/4 | CC-70185<br><br>CC-T382 | CK-T218<br><br>CK-T216 |
| | ジャストロー | 95.5-99.6 | 1 | | TK-T372 | 95.5-99.6 | 1 1/8 | | WK-814 | CUP | 95.5-99.6 | 1 1/8 | | WK-816 | CUP | <BU140><br><BU142 ABS無><br>95.5-98.12<br><br><br>98.12-99.6<br><br><br><BU142 ABS付><br>95.5-98.12<br><br><br> | <br>(R)BH-95002<br>(L)BH-95002<br>(R)BH-95002<br>(L)BH-95002<br><br>(R)BH-95002<br>(L)BH-95002<br> | <br>BH-40012<br><br>BH-T938<br><br><br>(R)<br>(L)BH-02192<br> | <BU140><br><BU142 ABS無><br><BU142><br>95.5-99.6<br><br><br><br><br><br><br><br><br><br><br> | 5/8<br><br>5/8 | MC-T445<br><br>MC-T473 | MK-T244<br><br>MK-T206 | 95.5-99.6 | 3/4 | CC-70185 | CK-T218 |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | | | | | | | | 98.12-99.6 | (R)BH-95002<br>(L)BH-95002 | (R)<br>(L)BH-02192 | | | | | | | | |
| KC－BU140・142<br>(3B)<br>(15B－F)<br>(15B－FP) | フルジャストロー2<br>(ドラム車) | <2t><br>95.5-99.6<br><3t><br>97.8-99.5 | 1<br><br>1 1/16 | | TK-T372<br><br>TK-T373 | <2tMT車><br>95.5-99.6<br><3tMT車><br>97.8-99.5<br><AT車><br>95.5-99.5 | 1 1/8<br><br>1 1/8<br><br>1 1/8 | | WK-814<br><br>WK-811<br><br>WK-815 | CUP<br><br>CUP<br><br>CUP | <2tMT車><br>95.5-99.6<br><3tMT車><br>97.8-99.5<br><AT車><br>95.5-99.5 | 1 1/8<br><br>1 1/8<br><br>1 1/8 | (R-1)WC-T676<br>(R-2)<br>(L-1)<br>(L-2) | WK-816<br><br>WK-812<br><br>WK-835 | CUP<br><br>CUP<br><br>CUP | <2t ABS無><br>95.5-98.12<br><br>98.12-99.6<br><2t ABS付><br>95.5-98.12<br><br>98.12-99.6<br><br><3t ABS無><br>97.8-98.12<br><br>98.12-99.5<br><3t ABS付><br>97.8-98.12<br><br>98.12-99.5 | (R)<br>(L)<br>(R)<br>(L)<br>(R)<br>(L)<br>(R)<br>(L)<br>(R)BH-T675<br>(R)BH-T675<br>(R)BH-T675<br>(R)BH-T675<br>(R)BH-T675<br>(R)BH-T675<br>(R)BH-T675<br>(R)BH-T675 | BH-40012<br><br>BH-T938<br><br>(R)<br>(L)BH-02192<br>(R)<br>(L)BH-02192<br>BH-40012<br><br>BH-T938<br><br>(R)<br>(L)BH-02192<br>(R)<br>(L)BH-02192 | 95.5-99.6 | 5/8 | MC-T473 | MK-T206 | <2t><br>95.5-99.6<br><3t><br>97.8-99.5 | 3/4<br><br>3/4 | CC-70185<br><br>CC-T382 | CK-T218<br><br>CK-T216 |
| | フルジャストロー2<br>(ディスク車) | <2t><br>95.5-99.6<br><3t><br>97.8-98.5<br>98.5-99.5 | 1<br><br>1 1/8<br>1 1/8 | | TK-T372<br><br>TK-T374<br>TK-T433 | <2t・ヤマト運輸仕様><br>95.5-99.6<br><3t><br>97.8-99.5 | 66.6<br><br>51.1 | DISC<br><br>DISC | MP-17<br><br>MP-8 | <br><br>CPM-8 | <2t><br>95.5-99.6<br><br><3t><br>97.8-99.5 | 1 1/8<br><br><br><br>1 1/8 | (R-1)WC-T676<br>(R-2)<br>(L-1)<br>(L-2) | WK-835<br><br><br><br>WK-813 | CUP<br><br><br><br>CUP | <2t ABS無><br>95.5-98.12<br><br><br><br>98.12-99.6<br><2t ABS付><br>95.5-98.12<br><br><br><br>98.12-99.6<br><br><br><br><3t ABS無><br>97.8-98.12<br><br><br><br>98.12-99.5<br><3t ABS付><br>97.8-98.12<br><br><br><br>98.12-99.5 | (R-1)BH-02576<br>(R-2)BH-T719<br>(L-1)BH-02576<br>(L-2)BH-T719<br>(R-1)BH-T888<br>(R-2)BH-T719<br>(L-1)BH-T888<br>(L-2)BH-T719<br>(R-1)BH-02576<br>(R-2)BH-T719<br>(L-1)BH-02576<br>(L-2)BH-T719<br>(R-1)BH-T888<br>(R-2)BH-T719<br>(L-1)BH-T888<br>(L-2)BH-T719<br>(R-1)BH-02492<br>(R-2)BH-02431<br>(L-1)BH-02492<br>(L-2)BH-02431<br>(R-1)BH-T863<br>(R-2)BH-02431<br>(L-1)BH-T863<br>(L-2)BH-02431<br>(R-1)BH-02492<br>(R-2)BH-02431<br>(L-1)BH-02492<br>(L-2)BH-02431<br>(R-1)BH-T863<br>(R-2)BH-02431<br>(L-1)BH-T863<br>(L-2)BH-02431 | BH-40012<br><br><br><br>BH-T938<br><br><br><br>(R)<br>(L)BH-02192<br><br><br><br>(R)<br>(L)BH-02192 | 95.5-99.6 | 5/8 | MC-T473 | MK-T206 | <2t><br>95.5-99.6<br><3t><br>97.8-99.5 | 3/4<br><br>3/4 | CC-70185<br><br>CC-T382 | CK-T218<br><br>CK-T216 |
| KC－BU145・147<br>(3B)<br>(15B－F) | 高 床 | 97.8-98.5<br>98.5-99.5<br><アンチスキッド付><br>97.8-99.5 | 1 1/8<br>1 1/8<br><br>1 1/8 | | TK-T374<br>TK-T433<br><br>TK-T375 | 97.8-99.5 | | DISC | MP-81 | CPM-81 | 97.8-99.5 | 1 1/8 | | WK-813 | CUP | 97.8-98.12<br><br>98.12-99.5<br><br><アンチスキッド付><br>97.8-98.12<br><br>98.12-99.5 | (R)<br>(L)<br>(R)<br>(L)<br>(R)<br>(L)<br>(R)<br>(L) | BH-40012<br><br>BH-T938<br><br>(R)<br>(L)BH-02192<br>(R)<br>(L)BH-02192 | <BU145><br>97.8-99.5<br><BU147><br>97.8-99.5 | 5/8<br><br>5/8 | MC-T445<br><br>MC-T473 | MK-T244<br><br>MK-T206 | 97.8-99.5 | 3/4 | CC-70185 | CK-T218 |
| | ジャストロー<br>フルジャストロー | 96.10-99.5 | 1 1/16 | | TK-T373 | 96.10-99.5 | | DISC | MP-81 | CPM-81 | 96.10-99.5 | 1 1/8 | (R-1)WC-T676<br>(R-2)<br>(L-1)<br>(L-2) | WK-835 | CUP | 96.10-98.12<br><br>98.12-99.5 | (R)<br>(L)<br>(R)<br>(L) | BH-40012<br><br>BH-T938 | <BU145><br>96.10-99.5<br><BU147><br>96.10-99.5 | 5/8<br><br>5/8 | MC-T445<br><br>MC-T473 | MK-T244<br><br>MK-T206 | 96.10-99.5 | 3/4 | CC-70185 | CK-T218 |
| KC－BU162(4WD)<br>(15B－F) | | 95.5-99.6 | 1 | | TK-T372 | 95.5-99.6<br><ヤマト運輸仕様><br>95.5-99.6 | 1 1/8<br><br>1 1/8 | <br><br>(R)WC-T025<br>(L)WC-T086 | WK-814<br><br>WK-815 | CUP<br><br>CUP | 95.5-99.6<br><ヤマト運輸仕様><br>95.5-99.6 | 1 1/8<br><br>1 1/8 | <br><br>(R-1)WC-T676<br>(R-2)<br>(L-1)<br>(L-2) | WK-816<br><br>WK-835 | CUP<br><br>CUP | 95.5-98.12<br>98.12-99.6 | BH-T688<br>BH-31405 | BH-40012<br>BH-T938 | 95.5-99.6 | 5/8 | MC-T473 | MK-T206 | 95.5-99.6 | 3/4 | CC-70185 | CK-T218 |
| KC－BU162A・162D(4WD)<br>(15B－F) | | 95.5-99.5<br><BU162D><br>95.5-99.5 | 1 1/16<br><br>1 | | TK-T373<br><br>TK-T372 | 95.5-99.5<br><BU162D><br>95.5-99.5 | 1 1/8<br><br>1 1/8 | | WK-811<br><br>WK-816 | CUP<br><br>CUP | 95.5-99.5<br><BU162D><br>95.5-99.5 | 1 1/8<br><br>1 1/8 | | WK-812<br><br>WK-816 | CUP<br><br>CUP | 95.5-98.12<br>98.12-99.5 | BH-T688<br>BH-31405 | BH-40012<br>BH-T938 | 95.5-99.5 | 5/8 | MC-T473 | MK-T206 | 95.5-99.5 | 3/4 | CC-70185 | CK-T218 |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| KC－BU172(4WD)<br>(15B－F) | 高 床2t・3t | <2t><br>95.5-99.5<br><3t><br><消防車><br>95.5-99.5 | 1<br><br><br>1 1/16 | | TK-T372<br><br><br>TK-T373 | 95.5-99.5 | 1 1/8 | | WK-811 | CUP | <2t><br>95.5-99.5<br><3t><br><消防車><br>95.5-99.5 | 1<br><br><br>1 1/8 | | WK-863<br><br><br>WK-812 | CUP<br><br><br>CUP | 95.5-98.12<br>98.12-99.5<br><br><br> | BH-T688<br>BH-31405<br><br><br> | BH-T528<br>BH-T528<br><br><br> | 95.5-99.5 | 5/8 | MC-T473 | MK-T206 | 95.5-99.5 | 3/4 | CC-70185 | CK-T218 |
| | フルジャストロー | 97.8-99.5 | 1 | | TK-T372 | 97.8-99.5 | 1 1/8 | | WK-814 | CUP | 97.8-99.5 | 1 1/8 | | WK-816 | CUP | 97.8-98.12<br>98.12-99.5 | BH-T688<br>BH-31405 | BH-44212 | 97.8-99.5 | 5/8 | MC-T473 | MK-T206 | 97.8-99.5 | 3/4 | CC-70185 | CK-T218 |
| KC－BU182(4WD)<br>(15B－F) | 高 床 | 95.5-99.6 | 1 1/16 | | TK-T373 | 95.5-99.6<br><ヤマト運輸仕様><br>95.5-99.6 | 1 1/8<br><br>1 1/8 | <br><br>(R)<br>(L) | WK-811<br><br>WK-817 | CUP<br><br>CUP | 95.5-99.6<br><ヤマト運輸仕様><br>95.5-99.6 | 1 1/8<br><br>1 1/8 | <br><br>(R-1)WC-T679<br>(R-2)WC-T782<br>(L-1)WC-T783<br>(L-2)WC-T784 | WK-812<br><br>WK-813 | CUP<br><br>CUP | 95.5-98.12<br>98.12-99.6<br><br> | BH-T688<br>BH-31405<br><br> | BH-44212 | 95.5-99.6 | 5/8 | MC-T473 | MK-T206 | 95.5-99.6 | 3/4 | CC-70185 | CK-T218 |
| | フルジャストロー | 97.8-99.5 | 1 | | TK-T372 | 97.8-99.5 | 1 1/8 | | WK-814 | CUP | 97.8-99.5 | 1 1/8 | | WK-816 | CUP | 97.8-98.12<br>98.12-99.5 | BH-T688<br>BH-31405 | BH-44212 | 97.8-99.5 | 5/8 | MC-T473 | MK-T206 | 97.8-99.5 | 3/4 | CC-70185 | CK-T218 |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| DYNA, TOYOACE : XZU100 ser. | | | | | | | | | | | | | | | | | | | | | | | | | |
| KC－XZU130A (J05C) | 95.10-99.5 | 1 1/16 | | TK-T373 | 95.10-99.5 | 1 1/8 | | WK-811 | CUP | 95.10-99.5 | 1 1/8 | | WK-812 | CUP | 95.10-99.5 | BH-T675 | BH-T689 | 95.10-99.5 | 5/8 | MC-T473 | MK-T206 | 95.10-99.5 | 3/4 | CC-T382 | CK-T216 |
| KC－XZU140 (J05C) | 97.8-99.5 | 1 1/16 | | TK-T373 | 97.8-99.5 | 1 1/8 | | WK-811 | CUP | 97.8-99.5 | 1 1/8 | | WK-812 | CUP | 97.8-98.12<br>98.12-99.5 | BH-T675<br>BH-T675 | BH-40012<br>BH-T938 | 97.8-99.5 | 5/8 | MC-T473 | MK-T206 | 97.8-99.5 | 3/4 | CC-T382 | CK-T216 |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| DYNA, TOYOACE : BU200 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| KC－BU202<br>（15B－F） | ドラム車 | 95.5-99.5 | 1 | | TK-T372 | 95.5-99.5 | 1 1/8 | | WK-811 | CUP | 95.5-99.5 | 1 | | WK-863 | CUP | 95.5-98.12<br>98.12-99.5 | BH-02249<br>BH-T917 | BH-97003<br>BH-97003 | 95.5-99.5 | 5/8 | MC-T473 | MK-T206 | 95.5-99.5 | 3/4 | CC-70185 | CK-T218 |
| | ディスク車 | 95.5-98.5<br>98.5-99.5 | 1 1/8<br>1 1/8 | | TK-T374<br>TK-T433 | 95.5-99.5 | 51.1 | DISC | MP-8 | CPM-8 | 95.5-99.5 | 1 1/8 | | WK-813 | CUP | 95.5-99.5 | (1)BH-02567<br>(2)BH-02431 | BH-97003 | 95.5-99.5 | 5/8 | MC-T473 | MK-T206 | 95.5-99.5 | 3/4 | CC-70185 | CK-T218 |
| KC－BU212・212K・222<br>（15B－F）<br>（15B－FT） | 高 床<br>フルジャストロー<br>（ドラム車） | <2t><br>95.5-99.6<br><3t><br>97.12-99.6 | 1<br><br>1 1/16 | | TK-T372<br><br>TK-T373 | <MT車><br>95.5-99.6<br><AT車><br>95.5-99.5<br><ヤマト運輸仕様><br>95.5-99.6 | 1 1/8<br><br>1 1/8<br><br>1 1/8 | <br><br><br><br>(R)WC-T029<br>(L) | WK-811<br><br>WK-817<br><br>WK-817 | CUP<br><br>CUP<br><br>CUP | <MT車><br>95.5-99.6<br><AT車><br>95.5-99.5<br><ヤマト運輸仕様><br>95.5-99.6 | 1 1/8<br><br>1 1/8<br><br>1 1/8 | <br><br><br><br>(R-1)WC-T679<br>(R-2)WC-T782<br>(L-1)WC-T783<br>(L-2)WC-T784 | WK-812<br><br>WK-813<br><br>WK-813 | CUP<br><br>CUP<br><br>CUP | 95.5-98.12<br>98.12-99.6 | BH-02249<br>BH-T917 | BH-97003<br>BH-97003 | 95.5-99.6 | 5/8 | MC-T473 | MK-T206 | <5速・除くターボ車><br>95.5-97.8<br><5速・ターボ車><br>95.5-97.8<br><6速車><br>97.8-99.6 | 3/4<br><br>3/4<br><br>3/4 | CC-70185<br><br>CC-T382<br><br>CC-T388 | CK-T218<br><br>CK-T216<br><br>CK-T216 |
| | 高 床<br>フルジャストロー<br>（ディスク車） | 95.5-98.5<br>98.5-99.6<br><アンチスキッド付><br>95.5-99.6 | 1 1/8<br>1 1/8<br><br>1 1/8 | | TK-T374<br>TK-T433<br><br>TK-T375 | 95.5-99.6 | 51.1 | DISC | MP-8 | CPM-8 | 95.5-99.6 | 1 1/8 | | WK-813 | CUP | 95.5-99.6<br><br><アンチスキッド付><br>95.5-99.6 | (1)BH-02567<br>(2)BH-02431<br><br>(1)BH-02567<br>(2)BH-02431 | BH-97003<br><br>(R)<br>(L)BH-02192 | 95.5-99.6 | 5/8 | MC-T473 | MK-T206 | <5速・除くターボ車><br>95.5-97.8<br><5速・ターボ車><br>95.5-97.8<br><6速車><br>97.8-99.6 | 3/4<br><br>3/4<br><br>3/4 | CC-70185<br><br>CC-T382<br><br>CC-T388 | CK-T218<br><br>CK-T216<br><br>CK-T216 |
| | ジャストロー | 95.5-99.5 | 1 | | TK-T372 | <MT車><br>95.5-99.5<br><AT車><br>95.5-99.5 | 1 1/8<br><br>1 1/8 | | WK-814<br><br>WK-815 | CUP<br><br>CUP | <MT車><br>95.5-99.5<br><AT車><br>95.5-99.5 | 1 1/8<br><br>1 1/8 | | WK-816<br><br>WK-835 | CUP<br><br>CUP | 95.5-98.12<br>98.12-99.5 | BH-02249<br>BH-T917 | BH-97003<br>BH-97003 | 95.5-99.5 | 5/8 | MC-T473 | MK-T206 | <5速車><br>95.5-97.8<br><6速車><br>97.8-99.5 | 3/4<br><br>3/4 | CC-70185<br><br>CC-T388 | CK-T218<br><br>CK-T216 |
| KC－BU297（4WD）<br>（15B－FT） | | 97.1-98.5<br>98.5-99.5 | 1 1/8<br>1 1/8 | | TK-T374<br>TK-T433 | 97.1-99.5 | 54.4 | DISC | SP-265 | CPS-265 | 97.1-99.5 | | DISC | SP-217 | CPS-217+CPS-217B | 97.1-99.5 | | | | | (オートマチック) | | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| DYNA, TOYOACE : BU, BZU300 ser.(99.5-11.7) | | | | | | | | | | | | | | | | | | | | | | | | | | |
| KK－BU301<br>（4B） | Sタイヤ | 99.7-04.6 | 1 3/16 | | TK-T448 | 99.7-04.6 | | DISC | MP-83 | CPM-81 | 99.7-04.6 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 99.7-04.6 | (R)BH-T818<br>(L)BH-T819 | (R)BH-T839<br>(L)BH-T839 | 99.7-04.6 | 5/8 | MC-T473 | MK-T206 | 99.7-04.6 | 3/4 | CC-70185 | CK-T218 |
| | Wタイヤ | 00.5-04.6 | 1 3/16 | | TK-T448 | 00.5-04.6 | | DISC | MP-83 | CPM-81 | 00.5-04.6 | 1 1/8 | (R-1)WC-T791<br>(R-2)WC-T792<br>(L-1)WC-T793<br>(L-2)WC-T794 | WK-835 | CUP | 00.5-04.6 | (R)BH-T818<br>(L)BH-T819 | (R)BH-T820<br>(L)BH-T820 | 00.5-04.6 | 5/8 | MC-T473 | MK-T206 | 00.5-04.6<br>ﾔﾏﾄｳﾝﾕｼﾖｳ<br>00.11-04.6 | 3/4<br>3/4 | CC-70185<br>CC-T386 | CK-T218<br>CK-T218 |
| KK－BU301A<br>（4B） | | 99.7-02.6<br>02.6-04.6 | 1 3/16<br>1 3/16 | <br>TD-T929 | TK-T448<br>TK-T448 | 99.7-02.6 | | DISC | MP-83 | CPM-81 | 99.7-02.6 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 99.7-02.6 | (R)BH-T818<br>(L)BH-T819 | (R)BH-T840<br>(L)BH-T840 | 99.7-02.6 | 5/8 | MC-T473 | MK-T206 | 99.7-02.6 | 3/4 | CC-70185 | CK-T218 |
| KK－BU306・306V<br>KK－BU346<br>（4B） | 高 床 | 99.5-04.6 | 1 3/16 | | TK-T448 | 99.5-04.6 | | DISC | MP-83 | CPM-81 | 99.5-04.6 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 99.5-02.6<br><br>02.6-04.6 | (R)BH-T903<br>(L)BH-T904<br>(R)BH-T909<br>(L)BH-T915 | (R)BH-T820<br>(L)BH-T820<br>(R)BH-T820<br>(L)BH-T820 | 99.5-04.6 | 5/8 | MC-T473 | MK-T206 | 99.5-04.6 | 3/4 | CC-70185 | CK-T218 |
| | フルジャストロー<br>ルートバン | <ｱﾝﾁｽｷｯﾄﾞ無><br>99.5-02.6<br>02.6-04.6<br><br><ｱﾝﾁｽｷｯﾄﾞ付><br>03.6-04.6 | <br>1 3/16<br>1 3/16<br><br>1 3/16 | <br>TD-T929 | <br>TK-T448<br>TK-T448<br><br>TK-T448 | 99.5-04.6 | | DISC | MP-83 | CPM-81 | 99.5-04.6 | 1 1/8 | (R-1)WC-T791<br>(R-2)WC-T792<br>(L-1)WC-T793<br>(L-2)WC-T794 | WK-835 | CUP | 99.5-02.6<br><br>02.6-04.6 | (R)BH-T903<br>(L)BH-T904<br>(R)BH-T909<br>(L)BH-T915 | (R)BH-T820<br>(L)BH-T820<br>(R)BH-T820<br>(L)BH-T820 | 99.5-04.6 | 5/8 | MC-T473 | MK-T206 | 99.5-04.6 | 3/4 | CC-70185 | CK-T218 |
| | ジャストロー | 99.5-04.6 | 1 3/16 | | TK-T448 | 99.5-04.6 | | DISC | MP-83 | CPM-81 | 99.5-04.6 | 1 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-937 | CUP | 99.5-02.6<br><br>02.6-04.6 | (R)BH-T903<br>(L)BH-T904<br>(R)BH-T909<br>(L)BH-T915 | (R)BH-T820<br>(L)BH-T820<br>(R)BH-T820<br>(L)BH-T820 | 99.5-04.6 | 5/8 | MC-T473 | MK-T206 | 99.5-04.6<br>ﾔﾏﾄｳﾝﾕｼﾖｳ<br>99.5-04.6 | 3/4<br>3/4 | CC-70185<br>CC-T386 | CK-T218<br>CK-T218 |
| LD－BZU300<br>（1BZ－FPE）<br>（1BZ－FNE）<br>＜NBG－は07．5～＞ | 高 床 | 03.6-11.7 | 1 3/16 | | TK-T448 | 03.6-11.7 | | DISC | MP-83 | CPM-81 | 03.6-11.7 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 03.6-11.7 | | | 03.6-11.7 | 5/8 | MC-T473 | MK-T206 | 03.6-11.7 | 3/4 | CC-T388 | CK-T216 |
| | フルジャストロー | 03.6-11.7 | 1 3/16 | | TK-T448 | <2t><br>03.6-11.7<br><br><3t><br>03.6-11.7 | | DISC<br><br>DISC | MP-83<br><br>MP-83 | CPM-81<br><br>CPM-81 | <2t><br>03.6-11.7<br><br><3t><br>03.6-11.7 | 1 1/8<br><br>1 1/8 | (R-1)WC-T791<br>(R-2)WC-T792<br>(L-1)WC-T793<br>(L-2)WC-T794<br><br>(R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-835<br><br>WK-813 | CUP<br><br>CUP | 03.6-11.7 | | | 03.6-11.7 | 5/8 | MC-T473 | MK-T206 | 03.6-11.7 | 3/4 | CC-T388 | CK-T216 |
| LD－BZU300A<br>（1BZ－FPE）<br>（1BZ－FNE）<br>＜NBG－は07．5～＞ | ダンプ | 03.6-11.7 | 1 3/16 | | TK-T448 | 03.6-11.7 | | DISC | MP-83 | CPM-81 | 03.6-11.7 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 03.6-11.7 | | | 03.6-11.7 | 5/8 | MC-T473 | MK-T206 | 03.6-11.7 | 3/4 | CC-T388 | CK-T216 |
| LD－BZU340<br>（1BZ－FPE）<br>（1BZ－FNE）<br>＜NBG－は07．5～＞ | 高 床 | 03.6-11.7 | 1 3/16 | | TK-T448 | 03.6-11.7 | | DISC | MP-83 | CPM-81 | 03.6-11.7 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 03.6-11.7 | | | 03.6-11.7 | 5/8 | MC-T473 | MK-T206 | 03.6-11.7 | 3/4 | CC-T388 | CK-T216 |
| | フルジャストロー | 03.6-11.7 | 1 3/16 | | TK-T448 | 03.6-11.7 | | DISC | MP-83 | CPM-81 | 03.6-11.7 | 1 1/8 | (R-1)WC-T791<br>(R-2)WC-T792<br>(L-1)WC-T793<br>(L-2)WC-T794 | WK-835 | CUP | 03.6-11.7 | | | 03.6-11.7 | 5/8 | MC-T473 | MK-T206 | 03.6-11.7 | 3/4 | CC-T388 | CK-T216 |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| DYNA, TOYOACE : XZU300 ser.(99.5-11.7) | | | | | | | | | | | | | | | | | | | | | | | | | | |
| KK－XZU300H<br>（J05C） | 高 床 | 99.6-04.6 | 1 3/16 | | TK-T448 | 99.6-04.6 | | DISC | MP-83 | CPM-81 | 99.6-04.6 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 99.6-04.6 | (R)BH-T818<br>(L)BH-T819 | (R)BH-T820<br>(L)BH-T820 | 99.6-04.6 | 5/8 | MC-T473 | MK-T206 | <自動調整式><br>99.6-02.6<br>02.6-04.6<br><手動調整式><br>99.6-02.6 | 3/4<br>3/4<br><br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216<br><br>CK-T234 |
| | フルジャストロー | 99.6-04.6 | 1 3/16 | | TK-T448 | 99.6-04.6 | | DISC | MP-83 | CPM-81 | 99.6-04.6 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 99.6-04.6 | (R)BH-T818<br>(L)BH-T819 | (R)BH-T840<br>(L)BH-T840 | 99.6-04.6 | 5/8 | MC-T473 | MK-T206 | <自動調整式><br>99.6-02.6<br>02.6-04.6<br><手動調整式><br>99.6-02.6 | 3/4<br>3/4<br><br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216<br><br>CK-T234 |
| KK－XZU301<br>（S05D）<br><PB－は04．6～> | 高 床2t | 00.5-06.10 | 1 3/16 | | TK-T448 | 00.5-06.10 | | DISC | MP-83 | CPM-81 | 00.5-06.10 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 00.5-06.10 | (R)BH-T818<br>(L)BH-T819 | (R)BH-T820<br>(L)BH-T820 | 00.5-06.10 | 5/8 | MC-T473 | MK-T206 | 00.5-02.6<br>02.6-04.6 | 3/4<br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216 |
| | 高 床2．95・3t<br>フルジャストロー | 00.5-06.10 | 1 3/16 | | TK-T448 | 00.5-06.10 | | DISC | MP-83 | CPM-81 | 00.5-06.10 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 00.5-06.10 | (R)BH-T818<br>(L)BH-T819 | (R)BH-T840<br>(L)BH-T840 | 00.5-06.10 | 5/8 | MC-T473 | MK-T206 | 00.5-02.6<br>02.6-06.10 | 3/4<br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216 |
| | フルジャストロー2t<br>ジャストロー2t<br>ダンプ | <フルジャストロー2t><br>00.5-04.6<br>04.6-06.10<br><ジャストロー2t・ダンプ><br>00.5-06.10 | 1 3/16<br>1 3/16<br><br>1 3/16 | TD-T929 | TK-T448<br>TK-T448<br><br>TK-T448 | 00.5-06.10 | | DISC | MP-83 | CPM-81 | 00.5-04.6<br><br><br>04.6-06.10 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2)<br>(R-1)WC-T791<br>(R-2)WC-T792<br>(L-1)WC-T793<br>(L-2)WC-T794 | WK-813<br><br><br>WK-835 | CUP<br><br><br>CUP | 00.5-06.10 | (R)BH-T818<br>(L)BH-T819 | (R)BH-T820<br>(L)BH-T820 | 00.5-06.10 | 5/8 | MC-T473 | MK-T206 | 00.5-02.6<br>02.6-06.10 | 3/4<br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216 |
| KK－XZU301A・301D<br>（S05D）<br>（15B－CNG・LPG）<br><PB－は04．6～> | | 99.5-06.10 | 1 3/16 | | TK-T448 | 99.5-06.10 | | DISC | MP-83 | CPM-81 | 99.5-06.10 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 99.5-06.10 | (R)BH-T818<br>(L)BH-T819 | (R)BH-T840<br>(L)BH-T840 | 99.5-06.10 | 5/8 | MC-T473 | MK-T206 | 99.5-02.6<br>02.6-06.10<br><CNG,LPG><br>00.5-03.6 | 3/4<br>3/4<br><br>CC-T388 | CC-T382<br>CC-T385<br><br>CK-T216 | CK-T216<br>CK-T216<br><br>CK-T216 |
| KK－XZU301H<br>（S05D）<br>（15B－LPG）<br><PB－は04．6～> | 高 床<br>（高所作業車・ミキサー車・消防車含む） | 99.5-06.10 | 1 3/16 | | TK-T448 | 99.5-06.10 | | DISC | MP-83 | CPM-81 | 99.5-06.10 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 99.5-06.10<br><消防車><br>99.8-06.10 | (R)BH-T818<br>(L)BH-T819<br><br>(R)BH-T818<br>(L)BH-T819 | (R)BH-T820<br>(L)BH-T820<br><br>(R)BH-T840<br>(L)BH-T840 | 99.5-06.10 | 5/8 | MC-T473 | MK-T206 | 99.5-02.6<br>02.6-06.10<br><LPG><br>00.5-03.6 | 3/4<br>3/4<br><br>CC-T388 | CC-T382<br>CC-T385<br><br>CK-T216 | CK-T216<br>CK-T216<br><br>CK-T216 |
| | フルジャストロー<br>（高所作業車含む） | 99.5-03.6 | 1 3/16 | | TK-T448 | 99.5-03.6 | | DISC | MP-83 | CPM-81 | 99.5-03.6 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 99.5-03.6 | (R)BH-T818<br>(L)BH-T819 | (R)BH-T840<br>(L)BH-T840 | 99.5-03.6 | 5/8 | MC-T473 | MK-T206 | 99.5-02.6<br>02.6-06.10<br><LPG><br>00.5-03.6 | 3/4<br><br><br>CC-T388 | CC-T382<br>CC-T385<br><br>CK-T216 | CK-T216<br>CK-T216<br><br>CK-T216 |
| KK－XZU302<br>（S05C）<br>（15B－CNG・LPG） | 高 床2t Sタイヤ | 99.7-04.6 | 1 3/16 | | TK-T448 | 99.7-04.6 | | DISC | MP-83 | CPM-81 | 99.7-04.6 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 99.7-04.6 | (R)BH-T818<br>(L)BH-T819 | (R)BH-T839<br>(L)BH-T839 | 99.7-04.6 | 5/8 | MC-T473 | MK-T206 | 99.7-02.6<br>02.6-04.6<br><CNG,LPG><br>00.5-03.6 | 3/4<br>3/4<br><br>CC-T388 | CC-T382<br>CC-T385<br><br>CK-T216 | CK-T216<br>CK-T216<br><br>CK-T216 |
| | 高 床2t Wタイヤ | 00.5-04.6 | 1 3/16 | | TK-T448 | 00.5-04.6 | | DISC | MP-83 | CPM-81 | 00.5-04.6 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 00.5-04.6 | (R)BH-T818<br>(L)BH-T819 | (R)BH-T820<br>(L)BH-T820 | 00.5-04.6 | 5/8 | MC-T473 | MK-T206 | 00.5-02.6<br>02.6-04.6<br><CNG,LPG><br>00.5-03.6 | 3/4<br>3/4<br><br>CC-T388 | CC-T382<br>CC-T385<br><br>CK-T216 | CK-T216<br>CK-T216<br><br>CK-T216 |
| | 高 床3t | 00.5-04.6 | 1 3/16 | | TK-T448 | 00.5-04.6 | | DISC | MP-83 | CPM-81 | 00.5-04.6 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 00.5-04.6 | (R)BH-T818<br>(L)BH-T819 | (R)BH-T840<br>(L)BH-T840 | 00.5-04.6 | 5/8 | MC-T473 | MK-T206 | 00.5-02.6<br>02.6-04.6 | 3/4<br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216 |
| | フルジャストロー2t | 00.5-04.6 | 1 3/16 | TD-T929 | TK-T448 | 00.5-04.6 | | DISC | MP-83 | CPM-81 | 00.5-04.6 | 1 1/8 | (R-1)WC-T791<br>(R-2)WC-T792<br>(L-1)WC-T793<br>(L-2)WC-T794 | WK-835 | CUP | 00.5-04.6 | (R)BH-T818<br>(L)BH-T819 | (R)BH-T820<br>(L)BH-T820 | 00.5-04.6 | 5/8 | MC-T473 | MK-T206 | 00.5-02.6<br>02.6-04.6 | 3/4<br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216 |
| | フルジャストロー2．95・3t | 00.5-04.6 | 1 3/16 | | TK-T448 | 00.5-04.6 | | DISC | MP-83 | CPM-81 | 00.5-04.6 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 00.5-04.6 | (R)BH-T818<br>(L)BH-T819 | (R)BH-T840<br>(L)BH-T840 | 00.5-04.6 | 5/8 | MC-T473 | MK-T206 | 00.5-02.6<br>02.6-04.6 | 3/4<br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216 |
| KK－XZU302A・302D<br>（S05C） | | 99.5-04.6 | 1 3/16 | | TK-T448 | 99.5-04.6 | | DISC | MP-83 | CPM-81 | 99.5-04.6 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 99.5-04.6 | (R)BH-T818<br>(L)BH-T819 | (R)BH-T840<br>(L)BH-T840 | 99.5-04.6 | 5/8 | MC-T473 | MK-T206 | 99.5-02.6<br>02.6-04.6 | 3/4<br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216 |
| KK－XZU302H<br>（S05C） | 高 床 | 99.5-04.6 | 1 3/16 | | TK-T448 | 99.5-04.6 | | DISC | MP-83 | CPM-81 | 99.5-04.6 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 99.5-04.6 | (R)BH-T818<br>(L)BH-T819 | (R)BH-T820<br>(L)BH-T820 | 99.5-04.6 | 5/8 | MC-T473 | MK-T206 | 99.5-02.6<br>02.6-04.6 | 3/4<br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216 |
| | フルジャストロー | 99.5-02.6 | 1 3/16 | | TK-T448 | 99.5-02.6 | | DISC | MP-83 | CPM-81 | 99.5-02.6 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 99.5-02.6 | (R)BH-T818<br>(L)BH-T819 | (R)BH-T840<br>(L)BH-T840 | 99.5-02.6 | 5/8 | MC-T473 | MK-T206 | 99.5-02.6 | 3/4 | CC-T382 | CK-T216 |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| PB・PD－XZU304<br>(N04C)<br><BDG－は06．9～> | 高 床 | 03.10-11.7 | 1 3/16 | | TK-T448 | 03.10-11.7 | | DISC | MP-83 | CPM-81 | 03.10-11.7 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 03.10-11.7 | | | 03.10-11.7 | 5/8 | MC-T473 | MK-T206 | 03.10-11.7 | 3/4 | CC-T385 | CK-T216 |
| | フルジャストロー | 03.10-04.6<br>04.6-11.7 | 1 3/16<br>1 3/16 | <br>TD-T929 | TK-T448<br>TK-T448 | 03.10-11.7 | | DISC | MP-83 | CPM-81 | 03.10-11.7 | 1 1/8 | (R-1)WC-T791<br>(R-2)WC-T792<br>(L-1)WC-T793<br>(L-2)WC-T794 | WK-835 | CUP | 03.10-11.7 | | | 03.10-11.7 | 5/8 | MC-T473 | MK-T206 | 03.10-11.7 | 3/4 | CC-T385 | CK-T216 |
| PD－XZU304A<br>(N04C)<br><PH－は05．4～><br><BDG－は06．9～> | ダンプ | 03.10-11.7 | 1 3/16 | | TK-T448 | 03.10-11.7 | | DISC | MP-83 | CPM-81 | 03.10-11.7 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 03.10-11.7 | | | 03.10-11.7 | 5/8 | MC-T473 | MK-T206 | 03.10-11.7 | 3/4 | CC-T385 | CK-T216 |
| PB-XZU304H<br>(N04C)<br><BDG－は06．9～> | 高 床 | 03.10-11.7 | 1 3/16 | | TK-T448 | 03.10-11.7 | | DISC | MP-83 | CPM-81 | 03.10-11.7 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 03.10-11.7 | | | 03.10-11.7 | 5/8 | MC-T473 | MK-T206 | 03.10-11.7 | 3/4 | CC-T385 | CK-T216 |
| BDG－XZU304D | | 06.9-11.7 | 1 3/16 | | TK-T448 | 06.9-11.7 | | DISC | MP-83 | CPM-81 | 06.9-11.7 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 06.9-11.7 | | | 06.9-11.7 | 5/8 | MC-T473 | MK-T206 | 06.9-11.7 | 3/4 | CC-T385 | CK-T216 |
| KK－XZU306・306V<br>(S05D)<br><PB－は04．6～> | 高 床 | 99.5-06.10 | 1 3/16 | | TK-T448 | 99.5-06.10 | | DISC | MP-83 | CPM-81 | 99.5-06.10 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 99.5-02.6<br><br>02.6-06.10 | (R)BH-T903<br>(L)BH-T904<br>(R)BH-T909<br>(L)BH-T915 | (R)BH-T820<br>(L)BH-T820<br>(R)BH-T820<br>(L)BH-T820 | 99.5-06.10 | 5/8 | MC-T473 | MK-T206 | <自動調整式><br>99.5-02.6<br>02.6-06.10<br><手動調整式><br>99.5-02.6 | 3/4<br>3/4<br><br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216<br><br>CK-T234 |
| | フルジャストロー<br>ルートバン | 99.5-04.6<br>04.6-06.10 | 1 3/16<br>1 3/16 | <br>TD-T929 | TK-T448<br>TK-T448 | 99.5-06.10 | | DISC | MP-83 | CPM-81 | 99.5-06.10 | 1 1/8 | (R-1)WC-T791<br>(R-2)WC-T792<br>(L-1)WC-T793<br>(L-2)WC-T794 | WK-835 | CUP | 99.5-02.6<br><br>02.6-06.10 | (R)BH-T903<br>(L)BH-T904<br>(R)BH-T909<br>(L)BH-T915 | (R)BH-T820<br>(L)BH-T820<br>(R)BH-T820<br>(L)BH-T820 | 99.5-06.10 | 5/8 | MC-T473 | MK-T206 | 99.5-02.6<br>02.6-04.6 | 3/4<br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216 |
| | ジャストロー | 99.5-06.10 | 1 3/16 | | TK-T448 | 99.5-06.10 | | DISC | MP-83 | CPM-81 | 99.5-04.6<br><br><br><br>04.6-06.10 | 1 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2)<br>(R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-937<br><br><br><br>WK-1025 | CUP<br><br><br><br>CUP | 99.5-02.6<br><br>02.6-06.10 | (R)BH-T903<br>(L)BH-T904<br>(R)BH-T909<br>(L)BH-T915 | (R)BH-T820<br>(L)BH-T820<br>(R)BH-T820<br>(L)BH-T820 | 99.5-06.10 | 5/8 | MC-T473 | MK-T206 | 99.5-02.6<br>02.6-04.6 | 3/4<br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216 |
| KK－XZU307・307V<br>(S05C) | 高 床 | 99.5-06.10 | 1 3/16 | | TK-T448 | 99.5-06.10 | | DISC | MP-83 | CPM-81 | 99.5-06.10 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 99.5-02.6<br><br>02.6-06.10 | (R)BH-T903<br>(L)BH-T904<br>(R)BH-T909<br>(L)BH-T915 | (R)BH-T820<br>(L)BH-T820<br>(R)BH-T820<br>(L)BH-T820 | 99.5-06.10 | 5/8 | MC-T473 | MK-T206 | <自動調整式><br>99.5-02.6<br>02.6-06.10<br><手動調整式><br>99.5-02.6 | 3/4<br>3/4<br><br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216<br><br>CK-T234 |
| | フルジャストロー<br>ルートバン | <ｱﾝﾁｽｷｯﾄﾞ無><br>99.5-02.6<br>02.6-04.6<br><ｱﾝﾁｽｷｯﾄﾞ付><br>03.6-04.6 | <br>1 3/16<br>1 3/16<br><br>1 3/16 | <br>TD-T929 | TK-T448<br>TK-T448<br><br>TK-T448 | 99.5-06.10 | | DISC | MP-83 | CPM-81 | 99.5-06.10 | 1 1/8 | (R-1)WC-T791<br>(R-2)WC-T792<br>(L-1)WC-T793<br>(L-2)WC-T794 | WK-835 | CUP | 99.5-02.6<br><br>02.6-06.10 | (R)BH-T903<br>(L)BH-T904<br>(R)BH-T909<br>(L)BH-T915 | (R)BH-T820<br>(L)BH-T820<br>(R)BH-T820<br>(L)BH-T820 | 99.5-06.10 | 5/8 | MC-T473 | MK-T206 | 99.5-02.6<br>02.6-04.6 | 3/4<br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216 |
| | ジャストロー | 99.5-06.10 | 1 3/16 | | TK-T448 | 99.5-06.10 | | DISC | MP-83 | CPM-81 | 99.5-04.6<br><br><br><br>04.6-06.10 | 1 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2)<br>(R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-937<br><br><br><br>WK-1025 | CUP<br><br><br><br>CUP | 99.5-02.6<br><br>02.6-06.10 | (R)BH-T903<br>(L)BH-T904<br>(R)BH-T909<br>(L)BH-T915 | (R)BH-T820<br>(L)BH-T820<br>(R)BH-T820<br>(L)BH-T820 | 99.5-06.10 | 5/8 | MC-T473 | MK-T206 | 99.5-02.6<br>02.6-04.6 | 3/4<br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216 |
| PB－XZU308・308V<br><BDG－は06．9～> | 高 床 | 04.6-11.7 | 1 3/16 | | TK-T448 | 04.6-11.7 | | DISC | MP-83 | CPM-81 | 04.6-11.7 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 04.6-11.7 | | | 04.6-11.7 | 5/8 | MC-T473 | MK-T206 | 04.6-11.7 | 3/4 | CC-T385 | CK-T216 |
| | フルジャストロー<br>（ドラム車） | 04.6-11.7 | 1 3/16 | TD-T929 | TK-T448 | 04.6-11.7 | | DISC | MP-83 | CPM-81 | 04.6-11.7 | 1 1/8 | (R-1)WC-T791<br>(R-2)WC-T792<br>(L-1)WC-T793<br>(L-2)WC-T794 | WK-835 | CUP | 04.6-11.7 | | | 04.6-11.7 | 5/8 | MC-T473 | MK-T206 | 04.6-11.7 | 3/4 | CC-T385 | CK-T216 |
| | フルジャストロー<br>（ディスク車） | 06.10- | 1 3/16 | TD-T929 | TK-T448 | 06.10- | | DISC | MP-83 | CPM-81 | 06.10- | | DISC | C-721P | | 06.10- | (R)BH-T939<br>(L)BH-T940 | (R)BH-T886<br>(L)BH-T885 | 06.10- | 5/8 | MC-T473 | MK-T206 | 06.10- | 3/4 | CC-T385 | CK-T216 |
| | ジャストロー | 04.6-11.7 | 1 3/16 | | TK-T448 | 04.6-11.7 | | DISC | MP-83 | CPM-81 | 04.6-11.7 | 1 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-1025 | CUP | 04.6-11.7 | | | 04.6-11.7 | 5/8 | MC-T473 | MK-T206 | 04.6-11.7 | 3/4 | CC-T385 | CK-T216 |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| KK－XZU311A･311D<br>KK－XZU312D<br>(S05C･S05D)<br><PB－は04．6～> | 2t | 99.5-06.10 | 1 3/16 | | TK-T448 | 99.5-06.10 | | DISC | MP-83 | CPM-81 | 99.5-06.10 | 1 1/8 | (R-1)WC-T791<br>(R-2)WC-T792<br>(L-1)WC-T793<br>(L-2)WC-T794 | WK-835 | CUP | 99.5-02.6<br><br>02.6-06.10 | (R)BH-T818<br>(L)BH-T819<br>(R)BH-T818<br>(L)BH-T819 | (R)BH-T840<br>(L)BH-T840<br>(R)BH-T874<br>(L)BH-T874 | 99.5-06.10 | 5/8 | MC-T473 | MK-T206 | 99.5-02.6<br>02.6-06.10 | 3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216 |
| | 3t | 99.5-06.10 | 1 3/16 | | TK-T448 | 99.5-06.10 | | DISC | MP-83 | CPM-81 | 99.5-06.10 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 99.5-02.6<br><br>02.6-06.10 | (R)BH-T818<br>(L)BH-T819<br>(R)BH-T818<br>(L)BH-T819 | (R)BH-T840<br>(L)BH-T840<br>(R)BH-T874<br>(L)BH-T874 | 99.5-06.10 | 5/8 | MC-T473 | MK-T206 | 99.5-02.6<br>02.6-06.10 | 3/4<br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216 |
| PB－XZU314D<br><BDG－は06．9～> | | 04.6-11.7 | 1 3/16 | | TK-T448 | 04.6-11.7 | | DISC | MP-83 | CPM-81 | 04.6-11.7 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 04.6-11.7 | | | 04.6-11.7 | 5/8 | MC-T473 | MK-T206 | 04.6-11.7 | 3/4 | CC-T385 | CK-T216 |
| KK－XZU320A･321A<br>KK－XZU321D･322D<br>(J05C･S05C･S05D)<br><PB－は04．6～> | | 99.5-06.10 | 1 3/16 | | TK-T448 | 99.5-06.10 | | DISC | MP-83 | CPM-81 | 99.5-06.10 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 99.5-06.10 | (R)BH-T818<br>(L)BH-T819 | (R)BH-T816<br>(L)BH-T816 | 99.5-06.10 | 5/8 | MC-T473 | MK-T206 | 99.5-02.6<br>02.6-04.6 | 3/4<br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216 |
| KK－XZU322<br>(S05C) | | 99.5-04.6 | 1 3/16 | | TK-T448 | 99.5-04.6 | | DISC | MP-83 | CPM-81 | 99.5-04.6 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 99.5-04.6 | (R)BH-T818<br>(L)BH-T819 | (R)BH-T933<br>(L)BH-T933 | 99.5-04.6 | 5/8 | MC-T473 | MK-T206 | 99.5-02.6<br>02.6-04.6 | 3/4<br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216 |
| BDG－XZU324D<br><BKG－は09．12～> | | 06.9-11.7 | 1 3/16 | | TK-T448 | 06.9-11.7 | | DISC | MP-83 | CPM-81 | 06.9-11.7 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 06.9-11.7 | | | 06.9-11.7 | 5/8 | MC-T473 | MK-T206 | 06.9-11.7 | 3/4 | CC-T385 | CK-T216 |
| KK－XZU330<br>(J05C) | 3t | 99.5-04.6 | 1 3/16 | | TK-T448 | 99.5-04.6 | | DISC | MP-83 | | 99.5-04.6 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 99.5-04.6 | (R)BH-T818<br>(L)BH-T819 | (R)BH-T820<br>(L)BH-T820 | 99.5-04.6 | 5/8 | MC-T473 | MK-T206 | 99.5-02.6<br>02.6-04.6 | 3/4<br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216 |
| | 4t | 99.6-04.6 | 1 3/16 | | TK-T448 | 99.6-02.6<br><br>02.6-04.6 | 1 3/16<br><br>1 3/16 | | WK-936<br><br>WK-1035 | CUP<br><br>CUP | 99.6-02.6<br><br>02.6-04.6 | 1 3/16<br><br>1 3/16 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2)<br>(R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-938<br><br>WK-1036 | CUP<br><br>CUP | 99.6-04.6 | (R)<br>(L) | (R)BH-T820<br>(L)BH-T820 | 99.6-04.6 | 5/8 | MC-T473 | MK-T206 | 99.6-02.6<br>02.6-04.6 | 3/4<br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216 |
| KK－XZU331<br>(S05D)<br><PB－は04．6～> | | 99.5-06.10 | 1 3/16 | | TK-T448 | 99.5-06.10 | | DISC | MP-83 | CPM-81 | 99.5-06.10 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 99.5-06.10<br><br><消防車><br>99.8-06.10 | (R)BH-T818<br>(L)BH-T819<br><br>(R)BH-T818<br>(L)BH-T819 | (R)BH-T820<br>(L)BH-T820<br><br>(R)BH-T840<br>(L)BH-T840 | 99.5-06.10 | 5/8 | MC-T473 | MK-T206 | 99.5-02.6<br>02.6-06.10 | 3/4<br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216 |
| PB－XZU334<br><BDG－は06．9～><br><BKG－は10．3～> | 3t･フルジャストロー ドラム車 | 06.9-11.7 | 1 3/16 | | TK-T448 | 06.9-11.7 | | DISC | MP-83 | CPM-81 | 06.9-11.7 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | WC-31209 | 06.9-11.7 | (R)BH-T818<br>(L)BH-T819 | (R)BH-T820<br>(L)BH-T820 | 06.9-11.7 | 5/8 | MC-T473 | MK-T206 | 06.9-11.7 | 3/4 | CC-T385 | CK-T216 |
| | ディスク車 | 06.9-11.7 | 1 3/16 | | TK-T448 | 06.9-11.7 | | DISC | MP-83 | CPM-81 | 06.9-11.7 | | DISC | C-721P | | 06.9-11.7 | (R)BH-T818<br>(L)BH-T819 | (R)<br>(L) | 06.9-11.7 | 5/8 | MC-T473 | MK-T206 | 06.9-11.7 | 3/4 | CC-T385 | CK-T216 |
| | 3．5t･4t | 06.9-11.7 | 1 3/16 | | TK-T448 | 06.9-11.7 | | DISC | C-617AP | CPC-617AB | 06.9-11.7 | | DISC | C-617AP | CPC-617AB | 06.9-11.7 | (R)<br>(L)BH-T884 | (R-1)BH-T820<br>(R-2)BH-T887<br>(L-1)BH-T820<br>(L-2)BH-T895 | 06.9-11.7 | 5/8 | MC-T473 | MK-T206 | 06.9-11.7 | 3/4 | CC-T385 | CK-T216 |
| PB－XZU336 | フルジャストロー | 04.6-06.10 | 1 3/16 | | TK-T448 | 04.6-06.10 | | DISC | MP-83 | CPM-81 | 04.6-06.10 | 1 1/8 | (R-1)WC-T791<br>(R-2)WC-T792<br>(L-1)WC-T793<br>(L-2)WC-T794 | WK-835 | CUP | 04.6-06.10 | (R)BH-T909<br>(L)BH-T915 | (R)BH-T820<br>(L)BH-T820 | 04.6-06.10 | 5/8 | MC-T473 | MK-T206 | 04.6-06.10 | 3/4 | CC-T385 | CK-T216 |
| | ジャストロー | 04.6-06.10 | 1 3/16 | | TK-T448 | 04.6-06.10 | | DISC | MP-83 | CPM-81 | 04.6-06.10 | 1 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-1025 | CUP | 04.6-06.10 | (R)BH-T909<br>(L)BH-T915 | (R)BH-T820<br>(L)BH-T820 | 04.6-06.10 | 5/8 | MC-T473 | MK-T206 | 04.6-06.10 | 3/4 | CC-T385 | CK-T216 |
| KK－XZU337<br>(S05C) | フルジャストロー | 99.5-04.6 | 1 3/16 | | TK-T448 | 99.5-04.6 | | DISC | MP-83 | CPM-81 | 99.5-04.6 | 1 1/8 | (R-1)WC-T791<br>(R-2)WC-T792<br>(L-1)WC-T793<br>(L-2)WC-T794 | WK-835 | CUP | 99.5-02.6<br><br>02.6-04.6 | (R)BH-T903<br>(L)BH-T904<br>(R)BH-T909<br>(L)BH-T915 | (R)BH-T820<br>(L)BH-T820<br>(R)BH-T820<br>(L)BH-T820 | 99.5-04.6 | 5/8 | MC-T473 | MK-T206 | 99.5-02.6<br>02.6-04.6 | 3/4<br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216 |
| | ジャストロー | 99.5-04.6 | 1 3/16 | | TK-T448 | 99.5-04.6 | | DISC | MP-83 | CPM-81 | 99.5-04.6 | 1 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-937 | CUP | 99.5-02.6<br><br>02.6-04.6 | (R)BH-T903<br>(L)BH-T904<br>(R)BH-T909<br>(L)BH-T915 | (R)BH-T820<br>(L)BH-T820<br>(R)BH-T820<br>(L)BH-T820 | 99.5-04.6 | 5/8 | MC-T473 | MK-T206 | 99.5-02.6<br>02.6-04.6 | 3/4<br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216 |
| PB－XZU338<br><BDG－は06．9～> | フルジャストロー | 04.6-11.7 | 1 3/16 | | TK-T448 | 04.6-11.7 | | DISC | MP-83 | CPM-81 | 04.6-11.7 | 1 1/8 | (R-1)WC-T791<br>(R-2)WC-T792<br>(L-1)WC-T793<br>(L-2)WC-T794 | WK-835 | CUP | 04.6-11.7 | (R)BH-T909<br>(L)BH-T915 | (R)BH-T820<br>(L)BH-T820 | 04.6-11.7 | 5/8 | MC-T473 | MK-T206 | 04.6-11.7 | 3/4 | CC-T385 | CK-T216 |

| Models | TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | ジャストロー | 04.6-11.7 | 1 3/16 | | TK-T448 | 04.6-11.7 | | DISC | MP-83 | CPM-81 | 04.6-11.7 | 1 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-1025 | CUP | 04.6-11.7 | (R)BH-T909<br>(L)BH-T915 | (R)BH-T820<br>(L)BH-T820 | 04.6-11.7 | 5/8 | MC-T473 | MK-T206 | 04.6-11.7 | 3/4 | CC-T385 | CK-T216 |
| KK－XZU340<br>(J05C) | | 3t | 99.6-04.6 | 1 3/16 | | TK-T448 | 99.6-04.6 | | DISC | MP-83 | CPM-81 | 99.6-04.6 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 99.6-04.6 | (R)BH-T818<br>(L)BH-T819 | (R)BH-T820<br>(L)BH-T820 | 99.6-04.6 | 5/8 | MC-T473 | MK-T206 | 99.6-02.6<br>02.6-04.6 | 3/4<br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216 |
| | | 3．5t･4t | 99.6-04.6 | 1 3/16 | | TK-T448 | 99.6-02.6 | 1 3/16 | | WK-936 | CUP | 99.6-02.6 | 1 3/16 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-938 | CUP | 99.6-04.6 | (R)<br>(L) | (R)BH-T820<br>(L)BH-T820 | 99.6-04.6 | 5/8 | MC-T473 | MK-T206 | 99.6-02.6<br>02.6-04.6 | 3/4<br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216 |
| | | | | | | | 02.6-04.6 | 1 3/16 | | WK-1035 | CUP | 02.6-04.6 | 1 3/16 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-1036 | CUP | | | | | | | | | | | |
| KK－XZU341<br>(S05D)<br>(15B－LPG)<br><PB－は04．6～> | | 高 床 | 99.5-06.10 | 1 3/16 | | TK-T448 | 99.5-06.10 | | DISC | MP-83 | CPM-81 | 99.5-06.10 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 99.5-06.10 | (R)BH-T818<br>(L)BH-T819 | (R)BH-T820<br>(L)BH-T820 | 99.5-06.10 | 5/8 | MC-T473 | MK-T206 | 99.5-02.6<br>02.6-04.6<br><LPG><br>00.5-03.6 | 3/4<br>3/4 | CC-T382<br>CC-T385<br><br>CC-T388 | CK-T216<br>CK-T216<br><br>CK-T216 |
| | | フルジャストロー | 99.5-06.10 | 1 3/16 | | TK-T448 | 99.5-06.10 | | DISC | MP-83 | CPM-81 | 99.5-06.10 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 99.5-06.10 | (R)BH-T818<br>(L)BH-T819 | (R)BH-T820<br>(L)BH-T820 | 99.5-06.10 | 5/8 | MC-T473 | MK-T206 | 99.5-02.6<br>02.6-04.6<br><LPG><br>00.5-03.6 | 3/4<br>3/4 | CC-T382<br>CC-T385<br><br>CC-T388 | CK-T216<br>CK-T216<br><br>CK-T216 |
| PB－XZU341D | | | 04.6-06.10 | 1 3/16 | | TK-T448 | 04.6-06.10 | | DISC | MP-83 | CPM-81 | 04.6-06.10 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 04.6-06.10 | (R)BH-T818<br>(L)BH-T819 | (R)BH-T820<br>(L)BH-T820 | 04.6-06.10 | 5/8 | MC-T473 | MK-T206 | 04.6-06.10 | 3/4 | CC-T385 | CK-T216 |
| KK－XZU342<br>(S05C)<br>(15B－CNG･LPG) | | 高 床 | 00.5-04.6 | 1 3/16 | | TK-T448 | 00.5-04.6 | | DISC | MP-83 | CPM-81 | 00.5-04.6 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 00.5-04.6 | (R)BH-T818<br>(L)BH-T819 | (R)BH-T820<br>(L)BH-T820 | 00.5-04.6 | 5/8 | MC-T473 | MK-T206 | <自動調整式><br>00.5-02.6<br>02.6-04.6<br><手動調整式><br>00.5-02.6<br><CNG,LPG><br>00.5-03.6 | 3/4<br>3/4<br><br>3/4<br><br> | CC-T382<br>CC-T385<br><br><br>CC-T388 | CK-T216<br>CK-T216<br><br>CK-T234<br>CK-T216 |
| | | フルジャストロー | 00.5-04.6 | 1 3/16 | | TK-T448 | 00.5-04.6 | | DISC | MP-83 | CPM-81 | 00.5-04.6 | 1 1/8 | (R-1)WC-T791<br>(R-2)WC-T792<br>(L-1)WC-T793<br>(L-2)WC-T794 | WK-835 | CUP | 00.5-04.6 | (R)BH-T818<br>(L)BH-T819 | (R)BH-T820<br>(L)BH-T820 | 00.5-04.6 | 5/8 | MC-T473 | MK-T206 | 00.5-02.6<br>02.6-04.6 | 3/4<br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216 |
| PB･PD－XZU344<br>(N04C)<br><BDG－は06．9～> | 2tフルジャストロー<br>2tジャストロー | リヤードラム車 | 03.10-11.7 | 1 3/16 | | TK-T448 | 03.10-11.7 | | DISC | MP-83 | CPM-81 | 03.10-11.7 | 1 1/8 | (R-1)WC-T791<br>(R-2)WC-T792<br>(L-1)WC-T793<br>(L-2)WC-T794 | WK-835 | CUP | 03.10-11.7 | (R)BH-T818<br>(L)BH-T819 | (R)BH-T820<br>(L)BH-T820 | 03.10-11.7 | 5/8 | MC-T473 | MK-T206 | 03.10-11.7 | 3/4 | CC-T385 | CK-T216 |
| | | リヤディスク車 | 06.10-11.7 | 1 3/16 | | TK-T448 | 06.10-11.7 | | DISC | MP-83 | CPM-81 | 06.10-11.7 | | MD-349 | C-721P | CPC-617AB | 06.10-11.7 | (R)BH-T818<br>(L)BH-T819 | (R)<br>(L) | 06.10-11.7 | 5/8 | MC-T473 | MK-T206 | 06.10-11.7 | 3/4 | CC-T385 | CK-T216 |
| | 2t高床･3t | リヤードラム車 | 03.10-11.7 | 1 3/16 | | TK-T448 | 03.10-11.7 | | DISC | MP-83 | CPM-81 | 03.10-11.7 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 03.10-11.7 | (R)BH-T818<br>(L)BH-T819 | (R)BH-T820<br>(L)BH-T820 | 03.10-11.7 | 5/8 | MC-T473 | MK-T206 | 03.10-11.7 | 3/4 | CC-T385 | CK-T216 |
| | | リヤディスク車 | 04.6-11.7 | 1 3/16 | | TK-T448 | 04.6-11.7 | | DISC | C-617AP | CPC-617AB | 04.6-11.7 | | MD-325 | C-617AP | CPC-617AB | 04.6-11.7 | (R)BH-T818<br>(L)BH-T819 | (R-1)BH-T820<br>(R-2)<br>(L-1)BH-T820<br>(L-2) | 04.6-11.7 | 5/8 | MC-T473 | MK-T206 | 04.6-11.7 | 3/4 | CC-T385 | CK-T216 |
| | 3．5t･4t | | 04.6-11.7 | 1 3/16 | | TK-T448 | 04.6-11.7 | | DISC | C-617AP | CPC-617AB | 04.6-11.7 | | MD-325 | C-617AP | CPC-617AB | 04.6-11.7 | (R)<br>(L)BH-T884 | (R-1)BH-T820<br>(R-2)BH-T887<br>(L-1)BH-T820<br>(L-2)BH-T895 | 04.6-11.7 | 5/8 | MC-T473 | MK-T206 | 04.6-11.7 | 3/4 | CC-T385 | CK-T216 |
| KK－XZU346･347<br>(S05C･S05D)<br><PB－は04．6～> | | 高 床 | 99.5-06.10 | 1 3/16 | | TK-T448 | 99.5-06.10 | | DISC | MP-83 | CPM-81 | 99.5-06.10 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 99.5-02.6<br><br>02.6-06.10 | (R)BH-T903<br>(L)BH-T904<br>(R)BH-T909<br>(L)BH-T915 | (R)BH-T820<br>(L)BH-T820<br>(R)BH-T820<br>(L)BH-T820 | 99.5-06.10 | 5/8 | MC-T473 | MK-T206 | <自動調整式><br>99.5-02.6<br>02.6-06.10<br><手動調整式><br>99.5-02.6 | 3/4<br>3/4<br><br>3/4 | CC-T382<br>CC-T385<br><br> | CK-T216<br>CK-T216<br><br>CK-T234 |
| | | フルジャストロー | 99.5-06.10 | 1 3/16 | | TK-T448 | 99.5-06.10 | | DISC | MP-83 | CPM-81 | 99.5-06.10 | 1 1/8 | (R-1)WC-T791<br>(R-2)WC-T792<br>(L-1)WC-T793<br>(L-2)WC-T794 | WK-835 | CUP | 99.5-02.6<br><br>02.6-06.10 | (R)BH-T903<br>(L)BH-T904<br>(R)BH-T909<br>(L)BH-T915 | (R)BH-T820<br>(L)BH-T820<br>(R)BH-T820<br>(L)BH-T820 | 99.5-06.10 | 5/8 | MC-T473 | MK-T206 | 99.5-02.6<br>02.6-04.6 | 3/4<br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216 |
| | | ジャストロー | 99.5-06.10 | 1 3/16 | | TK-T448 | 99.5-06.10 | | DISC | MP-83 | CPM-81 | 99.5-06.10 | 1 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-937 | CUP | 99.5-02.6<br><br>02.6-06.10 | (R)BH-T903<br>(L)BH-T904<br>(R)BH-T909<br>(L)BH-T915 | (R)BH-T820<br>(L)BH-T820<br>(R)BH-T820<br>(L)BH-T820 | 99.5-06.10 | 5/8 | MC-T473 | MK-T206 | 99.5-02.6<br>02.6-04.6 | 3/4<br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216 |

| Models | TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| PB－XZU348<br><BDG－は06．9～><br><BKG－は10．3～> | | フルジャストロー | 04.6-11.7 | 1 3/16 | | TK-T448 | 04.6-11.7 | | DISC | MP-83 | CPM-81 | 04.6-11.7 | 1 1/8 | (R-1)WC-T791<br>(R-2)WC-T792<br>(L-1)WC-T793<br>(L-2)WC-T794 | WK-835 | CUP | 04.6-11.7 | | | 04.6-11.7 | 5/8 | MC-T473 | MK-T206 | 04.6-11.7 | 3/4 | CC-T385 | CK-T216 |
| | | ジャストロー | 04.6-11.7 | 1 3/16 | | TK-T448 | 04.6-11.7 | | DISC | MP-83 | CPM-81 | 04.6-11.7 | 1 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-1025 | CUP | 04.6-11.7 | | | 04.6-11.7 | | | | 04.6-11.7 | 3/4 | CC-T385 | CK-T216 |
| KK－XZU350H<br>(J05C) | | | 99.6-04.6 | 1 3/16 | | TK-T448 | 99.6-02.6 | 1 3/16 | | WK-936 | CUP | 99.6-02.6 | 1 3/16 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-938 | CUP | 99.6-04.6 | (R)<br>(L) | (R)BH-T820<br>(L)BH-T820 | 99.6-04.6 | 5/8 | MC-T473 | MK-T206 | 99.6-02.6<br>02.6-04.6 | 3/4<br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216 |
| | | | | | | | 02.6-04.6 | 1 3/16 | | WK-1035 | CUP | 02.6-04.6 | 1 3/16 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-1036 | CUP | | | | | | | | | | | |
| KK－XZU351D･352D<br>(S05C･S05D)<br><PB－は04．6～> | | フルジャストロー | 02.6-06.10 | 1 3/16 | TD-T929 | TK-T448 | 02.6-06.10 | | MD-327M | MP-83 | CPM-81 | 02.6-06.10 | 1 1/8 | (R-1)WC-T791<br>(R-2)WC-T792<br>(L-1)WC-T793<br>(L-2)WC-T794 | WK-835 | CUP | 02.6-06.10 | (R)BH-T818<br>(L)BH-T819 | (R)BH-T874<br>(L)BH-T874 | 02.6-06.10 | 5/8 | MC-T473 | MK-T206 | 02.6-06.10 | 3/4 | CC-T385 | CK-T216 |
| | | ジャストロー | 99.5-06.10 | 1 3/16 | | TK-T448 | 99.5-06.10 | | MD-319M | MP-83 | CPM-81 | <XZU351D><br>99.5-04.6 | 1 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-937 | WC-21406 | 99.5-02.6<br>02.6-06.10 | (R)BH-T818<br>(L)BH-T819<br>(R)BH-T818<br>(L)BH-T819 | (R)BH-T840<br>(L)BH-T840<br>(R)BH-T874<br>(L)BH-T874 | 99.5-06.10 | 5/8 | MC-T473 | MK-T206 | 99.5-02.6<br>02.6-06.10 | 3/4<br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216 |
| | | | | | | | | | | | | 04.6-06.10 | 1 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-1025 | WC-21414 | | | | | | | | | | | |
| | | | | | | | | | | | | <XZU352D><br>99.5-06.10 | 1 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-937 | WC-21406 | | | | | | | | | | | |
| PB－XZU354D･354H<br><BDG－は06．9～> | 2t･3t | リヤドラム車 | 04.6-11.7 | 1 3/16 | | TK-T448 | 04.6-11.7 | | MD-319M | MP-83 | CPM-81 | 04.6-11.7 | 1 1/8 | (R-1)WC-T791<br>(R-2)WC-T792<br>(L-1)WC-T793<br>(L-2)WC-T794 | WK-835 | WC-31209 | <ﾀﾞﾝﾌﾟ><br>04.6-06.10<br>06.10-11.7<br><除くﾀﾞﾝﾌﾟ><br>04.6-06.10<br>06.10-11.7 | (R)BH-T818<br>(L)BH-T819<br>(R)BH-T818<br>(L)BH-T819<br>(R)BH-T818<br>(L)BH-T819 | (R)BH-T874<br>(L)BH-T874<br>(R-1)BH-T874<br>(R-2)<br>(L-1)BH-T874<br>(L-2)<br>(R)BH-T820<br>(L)BH-T820<br>(R-1)BH-T887<br>(R-2)BH-T820<br>(L-1)BH-T895<br>(L-2)BH-T820 | 04.6-11.7 | 5/8 | MC-T473 | MK-T206 | 04.6-11.7 | 3/4 | CC-T385 | CK-T216 |
| | | リヤディスク車 | 06.10-11.7 | 1 3/16 | | TK-T448 | 06.10-11.7 | | MD-327M | MP-83 | CPM-81 | 06.10-11.7 | | MD-349 | C-721P | | <ﾀﾞﾝﾌﾟ><br>06.10-11.7<br><除くﾀﾞﾝﾌﾟ><br>06.10-11.7 | (R)<br>(L)BH-T884<br>(R)<br>(L)BH-T884 | (R-1)<br>(R-2)BH-T874<br>(L-1)<br>(L-2)BH-T874<br>(R-1)BH-T887<br>(R-2)BH-T820<br>(L-1)BH-T895<br>(L-2)BH-T820 | 06.10-11.7 | 5/8 | MC-T473 | MK-T206 | 06.10-11.7 | 3/4 | CC-T385 | CK-T216 |
| | 3．5t･4t | | 04.6-11.7 | 1 3/16 | | TK-T448 | 04.6-11.7 | | MD-325 | C-617AP | CPC-617AB | 04.6-11.7 | | MD-325 | C-617AP | CPC-617AB | <ﾀﾞﾝﾌﾟ><br>04.6-06.10<br>06.10-11.7<br><除くﾀﾞﾝﾌﾟ><br>04.6-06.10<br>06.10-11.7 | (R)<br>(L)BH-T884<br>(R)<br>(L)BH-T884<br>(R)<br>(L)BH-T884 | (R)BH-T874<br>(L)BH-T874<br>(R-1)<br>(R-2)BH-T874<br>(L-1)<br>(L-2)BH-T874<br>(R-1)BH-T887<br>(R-2)BH-T820<br>(L-1)BH-T895<br>(L-2)BH-T820 | 04.6-11.7 | 5/8 | MC-T473 | MK-T206 | 04.6-11.7 | 3/4 | CC-T385 | CK-T216 |
| KK－XZU362<br>(S05C) | (4WD) | | 99.7-04.6 | 1 3/16 | | TK-T448 | 99.7-04.6 | | DISC | MP-83 | CPM-81 | 99.7-04.6 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 99.7-04.6 | (R)BH-T889<br>(L)BH-T890 | (R)BH-T820<br>(L)BH-T820 | 99.7-04.6 | 5/8 | MC-T473 | MK-T206 | 99.7-02.6<br>02.6-04.6 | 3/4<br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216 |
| KK－XZU362A･362D<br>(S05C) | (4WD) | | 99.7-04.6 | 1 3/16 | | TK-T448 | 99.7-04.6 | | DISC | MP-83 | CPM-81 | 99.7-04.6 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 99.7-04.6 | (R)BH-T889<br>(L)BH-T890 | (R)BH-T907<br>(L)BH-T907 | 99.7-04.6 | 5/8 | MC-T473 | MK-T206 | 99.7-02.6<br>02.6-04.6 | 3/4<br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216 |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| PB－XZU368<br>＜BDG－は06．9～＞ | リヤドラム車 | 04.6-11.7 | 1 3/16 | | TK-T448 | 04.6-11.7 | | DISC | MP-83 | CPM-81 | 04.6-11.7 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | ＜ﾀﾞﾝﾌﾟ＞<br>04.6-11.7<br>＜除くﾀﾞﾝﾌﾟ＞<br>04.6-11.7 | (R)<br>(L)<br><br>(R)<br>(L) | (R)BH-T820<br>(L)BH-T820<br><br>(R)BH-T874<br>(L)BH-T874 | 04.6-11.7 | 5/8 | MC-T473 | MK-T206 | 04.6-11.7 | 3/4 | CC-T385 | CK-T216 |
| | リヤディスク車 | 06.10-11.7 | 1 3/16 | | TK-T448 | 06.10-11.7 | | DISC | MP-83 | CPM-81 | 06.10-11.7 | | MD-349 | C-721P | | ＜ﾀﾞﾝﾌﾟ＞<br>06.10-11.7<br>＜除くﾀﾞﾝﾌﾟ＞<br>06.10-11.7 | (R)<br>(L)<br><br>(R)<br>(L) | (R-1)<br>(R-2)BH-T820<br>(L-1)<br>(L-2)BH-T820<br><br>(R-1)BH-T885<br>(R-2)BH-T874<br>(L-1)BH-T886<br>(L-2)BH-T874 | 06.10-11.7 | 5/8 | MC-T473 | MK-T206 | 06.10-11.7 | 3/4 | CC-T385 | CK-T216 |
| PB－XZU368D<br>＜BDG－は06．9～＞ | リヤドラム車 | 04.6-11.7 | 1 3/16 | | TK-T448 | 04.6-11.7 | | DISC | MP-83 | CPM-81 | 04.6-11.7 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 04.6-11.7 | (R)<br>(L) | (R)BH-T874<br>(L)BH-T874 | 04.6-11.7 | 5/8 | MC-T473 | MK-T206 | 04.6-11.7 | 3/4 | CC-T385 | CK-T216 |
| | リヤディスク車 | 06.10-11.7 | | | TK-T448 | 06.10-11.7 | | DISC | MP-83 | CPM-81 | 06.10-11.7 | | MD-349 | C-721P | | 06.10-11.7 | (R)<br>(L) | (R-1)<br>(R-2)BH-T874<br>(L-1)<br>(L-2)BH-T874 | 06.10-11.7 | 5/8 | MC-T473 | MK-T206 | 06.10-11.7 | 3/4 | CC-T385 | CK-T216 |
| KK－XZU371<br>（S05D） | （4WD） | 99.8-04.6 | 1 3/16 | | TK-T448 | 99.8-04.6 | | DISC | MP-83 | CPM-81 | 99.8-04.6 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 99.8-04.6 | (R)BH-T889<br>(L)BH-T890 | (R)BH-T893<br>(L)BH-T893 | 99.8-04.6 | 5/8 | MC-T473 | MK-T206 | 99.8-02.6<br>02.6-04.6 | 3/4<br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216 |
| KK－XZU372<br>（S05C） | （4WD） | 99.7-04.6 | 1 3/16 | | TK-T448 | 99.7-04.6 | | DISC | MP-83 | CPM-81 | 99.7-04.6 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 99.7-04.6 | (R)BH-T889<br>(L)BH-T890 | (R)BH-T820<br>(L)BH-T820 | 99.7-04.6 | 5/8 | MC-T473 | MK-T206 | 99.7-02.6<br>02.6-04.6 | 3/4<br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216 |
| PB－XZU378<br>＜BDG－は06．9～＞ | | 04.6-11.7 | 1 3/16 | | TK-T448 | 04.6-11.7 | | DISC | MP-83 | CPM-81 | 04.6-11.7 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 04.6-11.7 | | | 04.6-11.7 | 5/8 | MC-T473 | MK-T206 | 04.6-11.7 | 3/4 | CC-T385 | CK-T216 |
| | ディスク車 | 06.10-11.6 | 1 3/16 | | TK-T448 | 06.10-11.6 | | DISC | MP-83 | CPM-81 | 06.10-11.6 | | DISC | C-721P | | 06.10-11.6<br>＜2t・3t＞<br>06.10-11.6 | (R)<br>(L)<br><br>(R)<br>(L) | (R)BH-T820<br>(L)BH-T820<br><br>(R)<br>(L) | 06.10-11.6 | 5/8 | MC-T473 | MK-T206 | 06.10-11.6 | 3/4 | CC-T385 | CK-T216 |
| KK－XZU382<br>（S05C） | （4WD標準キャブ） | 99.7-04.6 | 1 3/16 | | TK-T448 | 99.7-04.6 | | DISC | MP-83 | CPM-81 | 99.7-04.6 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 99.7-04.6 | (R)<br>(L) | (R)BH-T820<br>(L)BH-T820 | 99.7-04.6 | 5/8 | MC-T473 | MK-T206 | 99.7-02.6<br>02.6-04.6 | 3/4<br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216 |
| | （4WDワイドキャブ） | 99.8-04.6 | 1 3/16 | | TK-T448 | 99.8-04.6 | | DISC | MP-83 | CPM-81 | 99.8-04.6 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 99.8-04.6 | (R)<br>(L) | (R)BH-T820<br>(L)BH-T820 | 99.8-04.6 | 5/8 | MC-T473 | MK-T206 | 99.8-02.6<br>02.6-04.6 | 3/4<br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216 |
| PB－XZU388<br>＜BDG－は06．9～＞ | | 04.6-11.7 | 1 3/16 | | TK-T448 | 04.6-11.7 | | DISC | MP-83 | CPM-81 | 04.6-11.7 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 04.6-11.7 | | | 04.6-11.7 | 5/8 | MC-T473 | MK-T206 | 04.6-11.7 | 3/4 | CC-T385 | CK-T216 |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| DYNA, TOYOACE : RZU, TRU, XKU300 ser.(00.5-11.7) | | | | | | | | | | | | | | | | | | | | | | | | | | |
| GE－RZU300・300A<br>(3RZ－FE)<br>(3RZ－FPE)<br>＜LD－は03．6～＞ | 高 床 | 00.5-07.5 | 1 3/16 | | TK-T448 | 00.5-07.5 | | DISC | MP-83 | CPM-81 | 00.5-07.5 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 00.5-07.5 | (R)BH-T818<br>(L)BH-T819 | (R)BH-T820<br>(L)BH-T820 | 00.5-07.5 | 5/8 | MC-T473 | MK-T206 | 00.5-02.11<br>02.11-07.5 | 7/8 | CC-T387<br>CC-T387 | CK-3122<br>CK-T229 |
| | フルジャストロー2t | 00.5-02.6<br>02.6-04.6<br>04.6-07.5 | 1 3/16<br>1 3/16<br>1 3/16 | TD-T929 | TK-T448<br>TK-T448<br>TK-T448 | 00.5-07.5 | | DISC | MP-83 | CPM-81 | 00.5-07.5 | 1 1/8 | (R-1)WC-T791<br>(R-2)WC-T792<br>(L-1)WC-T793<br>(L-2)WC-T794 | WK-835 | CUP | 00.5-07.5 | (R)BH-T818<br>(L)BH-T819 | (R)BH-T820<br>(L)BH-T820 | 00.5-07.5 | 5/8 | MC-T473 | MK-T206 | 00.5-02.11<br>02.11-07.5 | 7/8 | CC-T387<br>CC-T387 | CK-3122<br>CK-T229 |
| | フルジャストロー3t | 00.5-07.5 | 1 3/16 | | TK-T448 | 00.5-07.5 | | DISC | MP-83 | CPM-81 | 00.5-07.5 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 00.5-07.5 | (R)BH-T818<br>(L)BH-T819 | (R)BH-T840<br>(L)BH-T840 | 00.5-07.5 | 5/8 | MC-T473 | MK-T206 | 00.5-02.11<br>02.11-07.5 | 7/8 | CC-T387<br>CC-T387 | CK-3122<br>CK-T229 |
| | ジャストロー | 00.5-07.5 | 1 3/16 | | TK-T448 | 00.5-07.5 | | DISC | MP-83 | CPM-81 | 00.5-07.5 | 1 1/8 | (R-1)WC-T791<br>(R-2)WC-T792<br>(L-1)WC-T793<br>(L-2)WC-T794 | WK-835 | CUP | 00.5-07.5 | (R)BH-T818<br>(L)BH-T819 | (R)BH-T820<br>(L)BH-T820 | 00.5-07.5 | 5/8 | MC-T473 | MK-T206 | 00.5-02.11<br>02.11-07.5 | 7/8 | CC-T387<br>CC-T387 | CK-3122<br>CK-T229 |
| LD-RZU301<br>(3RZ－FP) | フルジャストロー | 03.6-07.5 | 1 3/16 | TD-T929 | TK-T448 | 03.6-07.5 | | DISC | MP-83 | CPM-81 | 03.6-07.5 | 1 1/8 | (R-1)WC-T791<br>(R-2)WC-T792<br>(L-1)WC-T793<br>(L-2)WC-T794 | WK-835 | CUP | 03.6-07.5 | | | 03.6-07.5 | 5/8 | MC-T473 | MK-T206 | 03.6-07.5 | | CC-T387 | CK-T229 |
| GE－RZU340<br>(3RZ－FE)<br>＜LD－は03．6～＞ | | 00.5-07.5 | 1 3/16 | | TK-T448 | 00.5-07.5 | | DISC | MP-83 | CPM-81 | 00.5-07.5 | 1 1/8 | (R-1)WC-T791<br>(R-2)WC-T792<br>(L-1)WC-T793<br>(L-2)WC-T794 | WK-835 | CUP | 00.5-07.5 | (R)BH-T818<br>(L)BH-T819 | (R)BH-T820<br>(L)BH-T820 | 00.5-07.5 | 5/8 | MC-T473 | MK-T206 | 00.5-02.11<br>02.11-07.5 | 7/8 | CC-T387<br>CC-T387 | CK-3122<br>CK-T229 |
| ABG－TRU300<br>(2TR－FE) | | 07.5-11.7 | 1 3/16 | | TK-T448 | 07.5-11.7 | | DISC | MP-83 | CPM-81 | 07.5-11.7 | | DISC | C-721P | | 07.5-11.7 | | | 07.5-11.7 | 5/8 | MC-T473 | MK-T206 | 07.5-11.7 | 7/8 | CC-T387 | CK-T229 |
| ABG－TRU300A<br>(2TR－FE) | | 07.5-11.7 | 1 3/16 | | TK-T448 | 07.5-11.7 | | DISC | MP-83 | CPM-81 | 07.5-11.7 | | DISC | C-721P | | 07.5-11.7 | | | 07.5-11.7 | 5/8 | MC-T473 | MK-T206 | 07.5-11.7 | 7/8 | CC-T387 | CK-T229 |
| ABG－TRU340<br>(2TR－FE) | | 07.5-11.7 | 1 3/16 | | TK-T448 | 07.5-11.7 | | DISC | MP-83 | CPM-81 | 07.5-11.7 | | DISC | C-721P | | 07.5-11.7 | | | 07.5-11.7 | 5/8 | MC-T473 | MK-T206 | 07.5-11.7 | 7/8 | CC-T387 | CK-T229 |
| BJG－XKU304A<br>(N04C－TN) | | 06.10-11.7 | 1 3/16 | | TK-T448 | 06.10-11.7 | | DISC | MP-83 | CPM-81 | 06.10-11.7 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 06.10-11.7 | (R)BH-T818<br>(L)BH-T819 | (R-1)BH-T820<br>(L-1)BH-T820<br>(R-2)BH-T886<br>(L-2)BH-T885 | 06.10-11.7 | 5/8 | MC-T473 | MK-T206 | 06.10-11.7 | 3/4 | CC-T385 | CK-T216 |
| | | 06.10-11.7 | 1 3/16 | | TK-T448 | 06.10-11.7 | | DISC | MP-83 | CPM-81 | 06.10-11.7 | | DISC | C-721P | | 06.10-11.7 | (R)BH-T818<br>(L)BH-T819 | (R-1)BH-T820<br>(L-1)BH-T820<br>(R-2)BH-T886<br>(L-2)BH-T885 | 06.10-11.7 | 5/8 | MC-T473 | MK-T206 | 06.10-11.7 | 3/4 | CC-T385 | CK-T216 |
| VF－XKU304H<br>(N04C－TE) | | 03.10-06.10 | 1 3/16 | | TK-T448 | 03.10-06.10 | | DISC | MP-83 | CPM-81 | 03.10-06.10 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 03.10-06.10 | (R)BH-T818<br>(L)BH-T819 | (R)BH-T820<br>(L)BH-T820 | 03.10-06.10 | 5/8 | MC-T473 | MK-T206 | 03.10-06.10 | 3/4 | CC-T385 | CK-T216 |
| BJG－XKU308<br>(N04C－TN) | フルジャストロー | 06.10-11.7 | 1 3/16 | | TK-T448 | 06.10-11.7 | | DISC | MP-83 | CPM-81 | 06.10-11.7 | | DISC | C-721P | | 06.10-11.7 | (R)BH-T939<br>(L)BH-T940 | (R-1)BH-T820<br>(L-1)BH-T820<br>(R-2)BH-T886<br>(L-2)BH-T885 | 06.10-11.7 | 5/8 | MC-T473 | MK-T206 | 06.10-11.7 | 3/4 | CC-T385 | CK-T216 |
| | 除くフルジャストロー | 06.10-11.7 | | | | 06.10-11.7 | | DISC | MP-83 | CPM-81 | 06.10-11.7 | | DISC | C-721P | | 06.10-11.7 | (R)BH-T939<br>(L)BH-T940 | (R-1)BH-T820<br>(L-1)BH-T820<br>(R-2)BH-T886<br>(L-2)BH-T885 | 06.10-11.7 | 5/8 | MC-T473 | MK-T206 | 06.10-11.7 | 3/4 | CC-T385 | CK-T216 |
| BJG－XKU308H<br>(N04C－TN) | フルジャストロー | 06.10-11.7 | 1 3/16 | | TK-T448 | 06.10-11.7 | | DISC | MP-83 | CPM-81 | 06.10-11.7 | | DISC | C-721P | | 06.10-11.7 | (R)BH-T939<br>(L)BH-T940 | (R-1)BH-T820<br>(L-1)BH-T820<br>(R-2)BH-T886<br>(L-2)BH-T885 | 06.10-11.7 | 5/8 | MC-T473 | MK-T206 | 06.10-11.7 | 3/4 | CC-T385 | CK-T216 |
| | 除くフルジャストロー | 06.10-11.7 | 1 3/16 | | TK-T448 | 06.10-11.7 | | DISC | MP-83 | CPM-81 | 06.10-11.7 | | DISC | C-721P | | 06.10-11.7 | (R)BH-T939<br>(L)BH-T940 | (R-1)BH-T820<br>(L-1)BH-T820<br>(R-2)BH-T886<br>(L-2)BH-T885 | 06.10-11.7 | 5/8 | MC-T473 | MK-T206 | 06.10-11.7 | 3/4 | CC-T385 | CK-T216 |
| BJG－XKU338<br>(N04C－TN) | フルジャストロー | 06.10-11.7 | 1 3/16 | | TK-T448 | 06.10-11.7 | | DISC | MP-83 | CPM-81 | 06.10-11.7 | | DISC | C-721P | | 06.10-11.7 | (R)BH-T939<br>(L)BH-T940 | (R-1)BH-T820<br>(L-1)BH-T820<br>(R-2)BH-T886<br>(L-2)BH-T885 | 06.10-11.7 | 5/8 | MC-T473 | MK-T206 | 06.10-11.7 | 3/4 | CC-T385 | CK-T216 |
| | 除くフルジャストロー | 06.10-11.7 | | | | 06.10-11.7 | | DISC | MP-83 | CPM-81 | 06.10-11.7 | | DISC | C-721P | | 06.10-11.7 | (R)BH-T939<br>(L)BH-T940 | (R-1)BH-T820<br>(L-1)BH-T820<br>(R-2)BH-T886<br>(L-2)BH-T885 | 06.10-11.7 | 5/8 | MC-T473 | MK-T206 | 06.10-11.7 | 3/4 | CC-T385 | CK-T216 |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| VF－XKU344<br>(N04C－TE)<br>(N04C－TN)<br>＜BJG－は06．10～＞ | 03.10-11.7 | 1 3/16 | | TK-T448 | 03.10-11.7 | | DISC | MP-83 | CPM-81 | 03.10-11.7 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 03.10-06.10<br>06.10-11.7 | (R)BH-T818<br>(L)BH-T819<br>(R)BH-T818<br>(L)BH-T819 | (R)BH-T820<br>(L)BH-T820<br>(R-1)BH-T820<br>(L-1)BH-T820<br>(R-2)<br>(L-2) | 03.10-11.7 | 5/8 | MC-T473 | MK-T206 | 03.10-11.7 | 3/4 | CC-T385 | CK-T216 |
| | 03.10-11.7 | 1 3/16 | | TK-T448 | 03.10-11.7 | | DISC | MP-83 | CPM-81 | 03.10-11.7 | | DISC | C-721P | | 03.10-06.10<br>06.10-11.7 | (R)BH-T818<br>(L)BH-T819<br>(R)BH-T818<br>(L)BH-T819 | (R)BH-T820<br>(L)BH-T820<br>(R-1)BH-T820<br>(L-1)BH-T820<br>(R-2)<br>(L-2) | 03.10-11.7 | 5/8 | MC-T473 | MK-T206 | 03.10-11.7 | 3/4 | CC-T385 | CK-T216 |
| BJG－XKU348 フルジャストロー<br>(N04C－TN) | 06.10-11.7 | 1 3/16 | | TK-T448 | 06.10-11.7 | | DISC | MP-83 | CPM-81 | 06.10-11.7 | | DISC | C-721P | | 06.10-11.7 | (R)BH-T939<br>(L)BH-T940 | (R-1)BH-T820<br>(L-1)BH-T820<br>(R-2)<br>(L-2) | 06.10-11.7 | 5/8 | MC-T473 | MK-T206 | 06.10-11.7 | 3/4 | CC-T385 | CK-T216 |
| 除くフルジャストロー | 06.10-11.7 | 1 3/16 | | TK-T448 | 06.10-11.7 | | DISC | MP-83 | CPM-81 | 06.10-11.7 | | DISC | C-721P | | 06.10-11.7 | (R)BH-T939<br>(L)BH-T940 | (R-1)BH-T820<br>(L-1)BH-T820<br>(R-2)<br>(L-2) | 06.10-11.7 | 5/8 | MC-T473 | MK-T206 | 06.10-11.7 | 3/4 | CC-T385 | CK-T216 |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| DYNA, TOYOACE : BU, BZU400 ser.(99.8-07.5) | | | | | | | | | | | | | | | | | | | | | | | | | | |
| KK－BU400<br>（15B－FTE） | | 99.8-02.6 | 1 3/16 | | TK-T448 | 99.8-02.6 | | DISC | MP-83 | CPM-81 | 99.8-02.6 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 99.8-02.6 | (R)BH-T812<br>(L)BH-T813 | (R)BH-T816<br>(L)BH-T816 | 99.8-02.6 | 5/8 | MC-T473 | MK-T206 | 99.8-02.6 | 3/4 | CC-T388 | CK-T216 |
| KK－BU410・420<br>KK－BU430<br>（15B－FTE） | 2t | 99.8-04.6 | 1 3/16 | | TK-T448 | 99.8-04.6 | | DISC | MP-83 | CPM-81 | 99.8-04.6 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 99.8-04.6 | (R)BH-T812<br>(L)BH-T813 | (R)BH-T816<br>(L)BH-T816 | 99.8-04.6 | 5/8 | MC-T473 | MK-T206 | 99.8-04.6 | 3/4 | CC-T388 | CK-T216 |
| | 3t以上 | 99.8-04.6 | 1 3/16 | | TK-T448 | 99.8-02.6 | 1 3/16 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-936 | CUP | 99.8-02.6 | 1 3/16 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-938 | CUP | 99.8-04.6 | (R)BH-T814<br>(L)BH-T815 | (R)BH-T816<br>(L)BH-T816 | 99.8-04.6 | 5/8 | MC-T473 | MK-T206 | 99.8-04.6 | 3/4 | CC-T388 | CK-T216 |
| | | | | | | 02.6-04.6 | 1 3/16 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-1035 | CUP | 02.6-04.6 | 1 3/16 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-1036 | CUP | | | | | | | | | | | |
| LD－BZU410<br>（1BZ－FPE）<br>（1BZ－FNE） | 2t | 03.6-07.5 | 1 3/16 | | TK-T448 | 03.6-07.5 | | DISC | MP-83 | CPM-81 | 03.6-07.5 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 03.6-07.5 | (R)BH-T812<br>(L)BH-T813 | (R)BH-T816<br>(L)BH-T816 | 03.6-07.5 | 5/8 | MC-T473 | MK-T206 | 03.6-07.5 | 3/4 | CC-T388 | CK-T216 |
| | 3t以上 | 03.6-07.5 | 1 3/16 | | TK-T448 | 03.6-07.5 | 1 3/16 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-1035 | CUP | 03.6-07.5 | 1 3/16 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-1036 | CUP | 03.6-07.5 | (R)BH-T814<br>(L)BH-T815 | (R)BH-T816<br>(L)BH-T816 | 03.6-07.5 | 5/8 | MC-T473 | MK-T206 | 03.6-07.5 | 3/4 | CC-T388 | CK-T216 |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| DYNA, TOYOACE : XKU, XZU400 ser.(99.5-11.7) | | | | | | | | | | | | | | | | | | | | | | | | | | |
| VF－XKU414<br>(N04C－TE)<br>(N04C－TE)<br>＜BJG－は06．10～＞ | 2tリヤードラム車 | 03.10-11.7 | 1 3/16 | | TK-T448 | 03.10-11.7 | | DISC | MP-83 | CPM-81 | 03.10-11.7 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 03.10-11.7 | (R)BH-T812<br>(L)BH-T813 | (R)BH-T816<br>(L)BH-T816 | 03.10-11.7 | 5/8 | MC-T473 | MK-T206 | 03.10-11.7 | 3/4 | CC-T385 | CK-T216 |
| | 2tリヤーディスク車 | 03.10-11.7 | 1 3/16 | | TK-T448 | 03.10-11.7 | | DISC | MP-83 | CPM-81 | 03.10-11.7 | | DISC | C-721P | | 03.10-11.7 | (R)BH-T812<br>(L)BH-T813 | (R)BH-T887<br>(L)BH-T895 | 03.10-11.7 | 5/8 | MC-T473 | MK-T206 | 03.10-11.7 | 3/4 | CC-T385 | CK-T216 |
| | 3t･3．5t | 03.10-11.7 | 1 3/16 | | TK-T448 | 03.10-11.7 | | DISC | C-617AP | CPC-617AB | 03.10-11.7 | | DISC | C-617AP | CPC-617AB | 03.10-11.7 | (R)BH-T896<br>(L)BH-T897 | (R)BH-T887<br>(L)BH-T895 | 03.10-11.7 | 5/8 | MC-T473 | MK-T206 | 03.10-11.7 | 3/4 | CC-T385 | CK-T216 |
| VF－XKU424<br>(N04C－TE)<br>(N04C－TE)<br>＜BJG－は06．10～＞ | | 03.10-11.7 | 1 3/16 | | TK-T448 | 03.10-11.7 | | DISC | C-617AP | CPC-617AB | 03.10-11.7 | | DISC | C-617AP | CPC-617AB | 03.10-11.7 | (R)BH-T896<br>(L)BH-T897 | (R)BH-T887<br>(L)BH-T895 | 03.10-11.7 | 5/8 | MC-T473 | MK-T206 | 03.10-11.7 | 3/4 | CC-T385 | CK-T216 |
| KK－XZU400･400A<br>(J05C･S05D)<br>＜PB－は04．6～＞ | | 99.5-06.10 | 1 3/16 | | TK-T448 | 99.5-02.6 | 1 3/16 | | WK-936 | CUP | 99.5-02.6 | 1 3/16 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-938 | CUP | 99.5-06.10 | (R)BH-T814<br>(L)BH-T815 | (R)BH-T816<br>(L)BH-T816 | 99.5-06.10 | 5/8 | MC-T473 | MK-T206 | 99.5-02.6<br>02.6-06.10<br>＜超低床ﾀﾞﾝﾌﾟ＞<br>02.5-06.10 | 3/4<br>3/4<br><br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216<br><br>CK-T234 |
| | | | | | | 02.6-06.10 | 1 3/16 | | WK-1035 | CUP | 02.6-06.10 | 1 3/16 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-1036 | CUP | | | | | | | | | | | |
| KK－XZU401<br>(S05D)<br>＜PB－は04．6～＞ | ドラム車 | 99.5- | 1 3/16 | | TK-T448 | 99.5-02.6<br>02.6- | 1 3/16<br>1 3/16 | | WK-936<br>WK-1035 | CUP<br>CUP | 99.5-02.6<br>02.6-04.6<br>04.6- | 1 3/16<br>1 3/16 | | WK-938<br>WK-1036<br>WK-1025 | CUP<br>CUP | 99.5- | (R)BH-T814<br>(L)BH-T815 | (R)BH-T816<br>(L)BH-T816 | 99.5- | | MC-T473 | MK-T206 | ＜ﾌﾟｯｼｭﾛｯﾄﾞ現車確認＞<br>＜自動調整式＞<br>99.5-<br>＜手動調整式＞<br>99.5-02.6 | 3/4<br><br>3/4 | CC-T382 | CK-T216<br><br>CK-T234 |
| | ディスク車<br>2t | 04.6- | 1 3/16 | | TK-T448 | 04.6- | | DISC | MP-83 | CPM-81 | 04.6- | | | WK-813 | CUP | 04.6- | (R)BH-T812<br>(L)BH-T813 | (R)BH-T816<br>(L)BH-T816 | 04.6- | 5/8 | MC-T473 | MK-T206 | 04.6- | 3/4 | CC-T385 | CK-T216 |
| | ディスク車<br>3t以上 | 04.6- | 1 3/16 | | TK-T448 | 04.6- | | DISC | C-617AP | CPC-617AB | 04.6- | | MD-325 | C-617AP | CPC-617AB | 04.6- | (R)BH-T896<br>(L)BH-T897 | (R)BH-T887<br>(L)BH-T895 | 04.6- | 5/8 | MC-T473 | MK-T206 | 04.6- | 3/4 | CC-T385 | CK-T216 |
| KK－XZU402<br>(S05C) | フルジャストロー | 99.5-04.6 | 1 3/16 | | TK-T448 | 99.5-04.6 | | DISC | MP-83 | CPM-81 | 99.5-04.6 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 99.5-04.6 | (R)BH-T812<br>(L)BH-T813 | (R)BH-T816<br>(L)BH-T816 | 99.5-04.6 | 5/8 | MC-T473 | MK-T206 | 99.5-02.6<br>02.6-04.6<br>＜超低床ﾀﾞﾝﾌﾟ＞<br>02.5-04.6 | 3/4<br>3/4<br><br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216<br><br>CK-T234 |
| | ジャストロー | 99.5-04.6 | 1 3/16 | | TK-T448 | 99.5-04.6 | | DISC | MP-83 | CPM-81 | 99.5-04.6 | 1 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-937 | CUP | 99.5-04.6 | (R)BH-T812<br>(L)BH-T813 | (R)BH-T816<br>(L)BH-T816 | 99.5-04.6 | 5/8 | MC-T473 | MK-T206 | 99.5-02.6<br>02.6-04.6<br>＜超低床ﾀﾞﾝﾌﾟ＞<br>02.5-04.6 | 3/4<br>3/4<br><br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216<br><br>CK-T234 |
| PB－XZU404･404A<br>＜BDG－は06．10～＞ | 2t | 04.6-11.7 | 1 3/16 | | TK-T448 | 04.6-11.7 | | DISC | MP-83 | CPM-81 | 04.6-11.7 | | DISC | C-721P | | 04.6-11.7 | (R)BH-T812<br>(L)BH-T813 | (R-1)BH-T816<br>(R-2)<br>(L-1)BH-T816<br>(L-2) | 04.6-11.7 | 5/8 | MC-T473 | MK-T206 | 04.6-11.7 | 3/4 | CC-T385 | CK-T216 |
| | 3t以上 | 04.6-11.7 | 1 3/16 | | TK-T448 | 04.6-11.7 | | DISC | C-617AP | CPC-617AB | 04.6-11.7 | | DISC | C-617AP | CPC-617AB | 04.6-11.7 | (R)BH-T896<br>(L)BH-T897 | (R-1)BH-T816<br>(R-2)BH-T887<br>(L-1)BH-T816<br>(L-2)BH-T895 | 04.6-11.7 | 5/8 | MC-T473 | MK-T206 | 04.6-11.7 | 3/4 | CC-T385 | CK-T216 |
| KK－XZU410<br>(J05C) | 2t | 02.6-04.6 | 1 3/16 | | TK-T448 | 02.6-04.6 | | DISC | MP-83 | CPM-81 | 02.6-04.6 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 02.6-04.6 | (R)BH-T812<br>(L)BH-T813 | (R)BH-T816<br>(L)BH-T816 | 02.6-04.6 | 5/8 | MC-T473 | MK-T206 | 02.6-04.6<br>＜超低床ﾀﾞﾝﾌﾟ＞<br>02.6-04.6 | 3/4<br><br>3/4 | CC-T385 | CK-T216<br><br>CK-T234 |
| | 3t以上 | 99.5-04.6 | 1 3/16 | | TK-T448 | 99.5-02.6 | 1 3/16 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-936 | CUP | 99.5-02.6 | 1 3/16 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-938 | CUP | 99.5-04.6 | (R)BH-T814<br>(L)BH-T815 | (R)BH-T816<br>(L)BH-T816 | 99.5-04.6 | 5/8 | MC-T473 | MK-T206 | 99.5-02.6<br>02.6-04.6<br>＜超低床ﾀﾞﾝﾌﾟ＞<br>02.5-04.6 | 3/4<br>3/4<br><br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216<br><br>CK-T234 |
| | | | | | | 02.6-04.6 | 1 3/16 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-1035 | CUP | 02.6-04.6 | 1 3/16 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-1036 | CUP | | | | | | | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| KK－XZU411・412<br>(S05C・S05D)<br>(15B－CNG・LPG)<br>＜PB－は04．6～＞ | 2t高 床<br>2tフルジャストロー | 99.5-06.10 | 1 3/16 | | TK-T448 | 99.5-06.10 | | DISC | MP-83 | CPM-81 | 99.5-06.10 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 99.5-06.10 | (R)BH-T812<br>(L)BH-T813 | (R)BH-T816<br>(L)BH-T816 | 99.5-06.10 | 5/8 | MC-T473 | MK-T206 | ＜ｸﾞﾘｰﾝﾍﾟｲﾝﾄ＞<br>99.5-02.6<br>＜ｸﾞﾚｰﾍﾟｲﾝﾄ＞<br>02.6-06.10<br>＜ﾌﾞﾗｯｸﾍﾟｲﾝﾄ＞<br>02.6-04.6 | 3/4<br>3/4<br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216<br>CK-T234 |
| | 2tジャストロー | 99.5-06.10 | 1 3/16 | | TK-T448 | 99.5-06.10 | | DISC | MP-83 | CPM-81 | 99.5-06.10 | 1 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-937 | CUP | 99.5-06.10 | (R)BH-T812<br>(L)BH-T813 | (R)BH-T816<br>(L)BH-T816 | 99.5-06.10 | 5/8 | MC-T473 | MK-T206 | ＜ｸﾞﾘｰﾝﾍﾟｲﾝﾄ＞<br>99.5-02.6<br>＜ｸﾞﾚｰﾍﾟｲﾝﾄ＞<br>02.6-06.10<br>＜ﾌﾞﾗｯｸﾍﾟｲﾝﾄ＞<br>02.6-04.6 | 3/4<br>3/4<br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216<br>CK-T234 |
| | 2．95t以上 | 99.5-06.10 | 1 3/16 | | TK-T448 | 99.5-02.6<br><br><br><br>02.6-04.6<br><br><br><br>04.6-06.10 | 1 3/16<br><br><br><br>1 3/16 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2)<br>(R-1)<br>(R-2)<br>(L-1)<br>(L-2)<br>MD-325 | WK-936<br><br><br><br>WK-1035<br><br><br><br>C-617AP | CUP<br><br><br><br>CUP<br><br><br><br>CPC-617AB | 99.5-02.6<br><br><br><br>02.6-04.6<br><br><br><br>04.6-06.10 | 1 3/16<br><br><br><br>1 3/16 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2)<br>(R-1)<br>(R-2)<br>(L-1)<br>(L-2)<br>MD-325 | WK-938<br><br><br><br>WK-1036<br><br><br><br>C-617AP | CUP<br><br><br><br>CUP<br><br><br><br>CPC-617AB | 99.5-04.6<br><br><br><XZU411><br>04.6-06.10<br><br><br><XZU412><br>04.6-06.10 | (R)BH-T814<br>(L)BH-T815<br><br>(R)BH-T896<br>(L)BH-T897<br>(C)<br><br>(R)BH-T814<br>(L)BH-T815<br>(C) | (R)BH-T816<br>(L)BH-T816<br><br>(R-1)BH-T816<br>(R-2)BH-T887<br>(L-1)BH-T816<br>(L-1)BH-T895<br><br>(R)BH-T816<br>(L)BH-T816 | 99.5-06.10 | 5/8 | MC-T473 | MK-T206 | ＜ｸﾞﾘｰﾝﾍﾟｲﾝﾄ＞<br>99.5-02.6<br>＜ｸﾞﾚｰﾍﾟｲﾝﾄ＞<br>02.6-06.10<br>＜ﾌﾞﾗｯｸﾍﾟｲﾝﾄ＞<br>02.6-04.6 | 3/4<br>3/4<br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216<br>CK-T234 |
| PB－XZU413<br>(J05D－TB) | 2t | 04.6-06.10 | 1 3/16 | | TK-T448 | 04.6-06.10 | | DISC | MP-83 | CPM-81 | 04.6-06.10 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 04.6-06.10 | (R)BH-T812<br>(L)BH-T813 | (R)BH-T816<br>(L)BH-T816 | 04.6-06.10 | 5/8 | MC-T473 | MK-T206 | 04.6-06.10 | 3/4 | CC-T385 | CK-T216 |
| | 3t以上<br>リヤドラム車 | 04.6-06.10 | 1 3/16 | | TK-T448 | 04.6-06.10 | | DISC | C-617AP | CPC-617AB | 04.6-06.10 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 04.6-06.10 | (R)BH-T812<br>(L)BH-T813<br>(C) | (R-1)BH-T816<br>(R-2)BH-T887<br>(L-1)BH-T816<br>(L-1)BH-T895 | 04.6-06.10 | 5/8 | MC-T473 | MK-T206 | 04.6-06.10 | 3/4 | CC-T385 | CK-T216 |
| | 3t以上<br>リヤディスク車 | 03.10- | 1 3/16 | | TK-T448 | 03.10- | | DISC | C-617AP | CPC-617AB | 03.10- | | DISC | C-617AP | CPC-617AB | 03.10- | (R)BH-T812<br>(L)BH-T813<br>(C) | (R-1)BH-T816<br>(R-2)BH-T887<br>(L-1)BH-T816<br>(L-1)BH-T895 | 03.10- | | MC-T473 | MK-T206 | 03.10- | | CC-T385 | CK-T216 |
| PB・PD－XZU414・415<br>(N04C)<br>＜BDG－は06．10～＞<br>＜BKG－は08．1～＞ | 2t | 03.10-11.7 | 1 3/16 | | TK-T448 | 03.10-11.7 | | DISC | MP-83 | CPM-81 | 03.10-11.7 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 03.10-11.7 | (R)BH-T812<br>(L)BH-T813 | (R)BH-T816<br>(L)BH-T816 | 03.10-11.7 | 5/8 | MC-T473 | MK-T206 | 03.10-11.7 | 3/4 | CC-T385 | CK-T216 |
| | 2t<br>リヤディスク車 | 06.10- | 1 3/16 | | TK-T448 | 06.10- | | DISC | MP-83 | CPM-81 | 06.10- | | DISC | C-721P | | 06.10- | (R)BH-T812<br>(L)BH-T813 | (R)<br>(L) | 06.10- | 5/8 | MC-T473 | MK-T206 | 06.10- | 3/4 | CC-T385 | CK-T216 |
| | 3t以上<br>リヤドラム車 | 03.10-11.7 | 1 3/16 | | TK-T448 | 03.10-11.7 | | DISC | C-617AP | CPC-617AB | 03.10-11.7 | 1 3/16 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-1036 | CUP | 03.10-11.7 | (R)BH-T896<br>(L)BH-T897 | (R)BH-T894<br>(L)BH-T895 | 03.10-11.7 | 5/8 | MC-T473 | MK-T206 | 03.10-11.7 | 3/4 | CC-T385 | CK-T216 |
| | 3t以上<br>リヤディスク車 | 03.10-11.7 | | | | 03.10-11.7 | | DISC | C-617AP | CPC-617AB | 03.10-11.7 | | MD-325 | C-617AP | | 03.10-11.7 | (R)BH-T896<br>(L)BH-T897 | (R)BH-T887<br>(L)BH-T895 | 03.10-11.7 | | MC-T473 | MK-T206 | 03.10-11.7 | 3/4 | CC-T385 | CK-T216 |
| KK－XZU420<br>KK－XZU430<br>(J05C) | | 99.5-04.6 | 1 3/16 | | TK-T448 | 99.5-02.6<br><br><br><br>02.6-04.6 | 1 3/16<br><br><br><br>1 3/16 | | WK-936<br><br><br><br>WK-1035 | CUP<br><br><br><br>CUP | 99.5-02.6<br><br><br><br>02.6-04.6 | 1 3/16<br><br><br><br>1 3/16 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2)<br>(R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-938<br><br><br><br>WK-1036 | CUP<br><br><br><br>CUP | 99.5-04.6 | (R)BH-T814<br>(L)BH-T815 | (R)BH-T816<br>(L)BH-T816 | 99.5-04.6 | 5/8 | MC-T473 | MK-T206 | 99.5-02.6<br>02.6-04.6<br>＜超低床ﾀﾞﾝﾌﾟ＞<br>02.5-04.6 | 3/4<br>3/4<br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216<br>CK-T234 |
| KK－XZU421<br>(S05D)<br>＜PB－は04．6～＞ | 2t | 99.5-06.10 | 1 3/16 | | TK-T448 | 99.5-06.10 | | DISC | MP-83 | CPM-81 | 99.5-06.10 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 99.5-06.10 | (R)BH-T812<br>(L)BH-T813 | (R)BH-T816<br>(L)BH-T816 | 99.5-06.10 | 5/8 | MC-T473 | MK-T206 | 99.5-02.6<br>02.6-06.10<br>＜超低床ﾀﾞﾝﾌﾟ＞<br>02.5-06.10 | 3/4<br>3/4<br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216<br>CK-T234 |
| | 2．95t以上<br>ドラム車 | 99.5-06.10 | 1 3/16 | | TK-T448 | 99.5-02.6<br><br><br><br>02.6-06.10 | 1 3/16<br><br><br><br>1 3/16 | | WK-936<br><br><br><br>WK-1035 | CUP<br><br><br><br>CUP | 99.5-02.6<br><br><br><br>02.6-06.10 | 1 3/16<br><br><br><br>1 3/16 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2)<br>(R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-938<br><br><br><br>WK-1036 | CUP<br><br><br><br>CUP | 99.5-04.6<br><br><br>04.6-06.10 | (R)BH-T814<br>(L)BH-T815<br>(R)BH-T896<br>(L)BH-T897 | (R)BH-T816<br>(L)BH-T816<br>(R)BH-T887<br>(L)BH-T895 | 99.5-06.10 | 5/8 | MC-T473 | MK-T206 | 99.5-02.6<br>02.6-06.10<br>＜超低床ﾀﾞﾝﾌﾟ＞<br>02.5-06.10 | 3/4<br>3/4<br>3/4 | CC-T382<br>CC-T385 | CK-T216<br>CK-T216<br>CK-T234 |
| | 2．95t以上<br>リヤディスク車 | 04.6-06.10 | 1 3/16 | | TK-T448 | 04.6-06.10 | | DISC | C-617AP | CPC-617AB | 04.6-06.10 | | DISC | C-617AP | CPC-617AB | 04.6-06.10 | (R)BH-T896<br>(L)BH-T897 | (R)BH-T887<br>(L)BH-T895 | 04.6-06.10 | 5/8 | MC-T473 | MK-T206 | 04.6-06.10 | 3/4 | CC-T385 | CK-T216 |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| PB－XZU423<br>(J05D) | 2t | 04.6- | 1 3/16 | | TK-T448 | 04.6- | | DISC | MP-83 | CPM-81 | 04.6- | | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 04.6- | (R)BH-T812<br>(L)BH-T813 | (R)BH-T816<br>(L)BH-T816 | 04.6- | 5/8 | MC-T473 | MK-T206 | 04.6- | 3/4 | CC-T385 | CK-T216 |
| | 3t以上 | 04.6- | 1 3/16 | | TK-T448 | 04.6- | | DISC | C-617AP | CPC-617AB | 04.6- | | DISC | C-617AP | CPC-617AB | 04.6- | (R)BH-T896<br>(L)BH-T897 | (R)BH-T887<br>(L)BH-T895 | 04.6- | 5/8 | MC-T473 | MK-T206 | 04.6- | 3/4 | CC-T385 | CK-T216 |
| PB－XZU424<br>(N04C)<br><BDG－は06．10～><br><BKG－は08．1～> | 2t<br>リヤドラム車 | 04.6-11.7 | 1 3/16 | | TK-T448 | 04.6-11.7 | | DISC | MP-83 | CPM-81 | 04.6-11.7 | | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | WC-31209 | 04.6-06.10<br><br>06.10-11.7 | (R)BH-T812<br>(L)BH-T813<br>(C)<br>(R)BH-T812<br>(L)BH-T813<br>(C) | (R)BH-T816<br>(L)BH-T816<br><br>(R-1)BH-T816<br>(R-2)<br>(L-1)BH-T816<br>(L-2) | 04.6-11.7 | 5/8 | MC-T473 | MK-T206 | 04.6-11.7 | 3/4 | CC-T385 | CK-T216 |
| | 2t<br>リヤディスク車 | 06.10- | 1 3/16 | | TK-T448 | 06.10- | | DISC | MP-83 | CPM-81 | 06.10- | | DISC | C-721P | | 06.10-11.7 | (R)BH-T812<br>(L)BH-T813<br>(C) | (R-1)BH-T816<br>(R-2)<br>(L-1)BH-T816<br>(L-2) | 06.10-11.7 | 5/8 | MC-T473 | MK-T206 | 06.10-11.7 | 3/4 | CC-T385 | CK-T216 |
| | 3t以上 | 04.6- | 1 3/16 | | TK-T448 | 04.6- | | DISC | C-617AP | CPC-617AB | 04.6- | | DISC | C-617AP | CPC-617AB | 04.6- | (R)BH-T896<br>(L)BH-T897 | (R)BH-T887<br>(L)BH-T895 | 04.6- | 5/8 | MC-T473 | MK-T206 | | 3/4 | CC-T385 | CK-T216 |
| PB－XZU433<br>(J05D－TB) | | 04.6-06.10 | 1 3/16 | | TK-T448 | 04.6-06.10 | | DISC | C-617AP | CPC-617AB | 04.6-06.10 | | DISC | C-617AP | CPC-617AB | 04.6-06.10 | (R)BH-T896<br>(L)BH-T897<br>(C) | (R)BH-T887<br>(L)BH-T895 | 04.6-06.10 | 5/8 | MC-T473 | MK-T206 | 04.6-06.10 | 3/4 | CC-T385 | CK-T216 |
| BDG－XZU434<br>(N04C－TL) | | 06.10-11.7 | 1 3/16 | | TK-T448 | 06.10-11.7 | | DISC | C-617AP | CPC-617AB | 06.10-11.7 | | DISC | C-617AP | CPC-617AB | 06.10-11.7 | (R)BH-T896<br>(L)BH-T897 | (R)BH-T887<br>(L)BH-T895 | 06.10-11.7 | 5/8 | MC-T473 | MK-T206 | 06.10-11.7 | 3/4 | CC-T385 | CK-T216 |
| BDG－XZU454・488<br><BKG－は08．1～> | | 06.10-11.7 | 1 3/16 | | TK-T448 | 06.10-11.7 | | DISC | MP-83 | CPM-81 | 06.10-11.7 | | DISC | C-721P | | 06.10-11.7 | (R)<br>(L) | (R-1)<br>(L-1)<br>(R-2)<br>(L-2) | 06.10-11.7 | 5/8 | MC-T473 | MK-T206 | 06.10-11.7 | 3/4 | CC-T385 | CK-T216 |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| DYNA, TOYOACE : TRU, XKU, XZU500 ser.(06.10-11.7) | | | | | | | | | | | | | | | | | | | | | | | | | |
| ABG－TRU500<br>(2TR－FE) | 07.5-11.7 | 1 3/16 | | TK-T448 | 07.5-11.7 | | DISC | MP-83 | CPM-81 | 07.5-11.7 | | DISC | C-721P | | 07.5-11.7 | | | 07.5-11.7 | 5/8 | MC-T473 | MK-T206 | 07.5-11.7 | 7/8 | CC-T387 | CK-T229 |
| BJG－XKU508<br>(N04C－TN) | 06.10-11.7 | | | | 06.10-10.8<br>10.8-11.7 | | DISC<br>DISC | SP-137<br>SP-430 | CPS-137<br>CPS-137 | 06.10-11.7 | | DISC | SP-137 | CPS-137 | 06.10-11.7 | (R)BH-T939<br>(L)BH-T940 | (R-1)BH-T820<br>(L-1)BH-T820<br>(R-2)BH-T886<br>(L-2)BH-T885 | 06.10-11.7 | 5/8 | MC-T473 | MK-T206 | 06.10-11.7 | 3/4 | CC-T385 | CK-T216 |
| BJG－XKU508H<br>(N04C－TN) | 06.10-11.7 | | | | 06.10-10.8<br>10.8-11.7 | | DISC<br>DISC | SP-137<br>SP-430<br>SP-430 | CPS-137<br>CPS-137 | 06.10-11.7 | | DISC | SP-137 | CPS-137 | 06.10-11.7 | (R)BH-T939<br>(L)BH-T940 | (R-1)BH-T820<br>(L-1)BH-T820<br>(R-2)BH-T886<br>(L-2)BH-T885 | 06.10-11.7 | 5/8 | MC-T473 | MK-T206 | 06.10-11.7 | 3/4 | CC-T385 | CK-T216 |
| BDG－XZU504 Wタイヤ<br>(N04C－TH)<br>(N04C－TJ)<br>(N04C－UD)<br><BKG－は08. 1～> | 06.10-11.7 | | | | 06.10-10.8<br>10.8-11.7 | | DISC<br>DISC | SP-137<br>SP-430 | CPS-137<br>CPS-137 | 06.10-11.7 | | DISC | SP-137 | CPS-137 | 06.10-11.7 | | | 06.10-11.7 | 5/8 | MC-T473 | MK-T206 | 06.10-11.7 | 3/4 | CC-T385 | CK-T216 |
| Sタイヤ | 06.10-11.7 | 1 3/16 | | TK-T448 | 06.10-11.7 | | DISC | MP-83 | CPM-81 | 06.10-11.7 | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 06.10-11.7 | | | 06.10-11.7 | 5/8 | MC-T473 | MK-T206 | 06.10-11.7 | 3/4 | CC-T385 | CK-T216 |
| BDG－XZU508<br>(N04C－TH)<br>(N04C－TJ)<br>(N04C－UD)<br><BKG－は08. 1～> | 06.10-11.7 | | | | 06.10-10.8<br>10.8-11.7 | | DISC<br>DISC | SP-137<br>SP-430 | CPS-137<br>CPS-137 | 06.10-11.7 | | DISC | SP-137 | CPS-137 | 06.10-11.7 | | | 06.10-11.7 | 5/8 | MC-T473 | MK-T206 | 06.10-11.7 | 3/4 | CC-T385 | CK-T216 |
| BDG－XZU508V<br>(N04C－TH)<br>(N04C－TJ) | 06.10-11.7 | | | | 06.10-10.8<br>10.8-11.7 | | DISC<br>DISC | SP-137<br>SP-430 | CPS-137<br>CPS-137 | 06.10-11.7 | | DISC | SP-137 | CPS-137 | 06.10-11.7 | | | 06.10-11.7 | 5/8 | MC-T473 | MK-T206 | 06.10-11.7 | 3/4 | CC-T385 | CK-T216 |
| BDG－XZU524D<br>(N04C－TJ)<br>(N04C－UE)<br><BKG－は08. 1～> | 06.10-11.7 | | | | 06.10-10.8<br>10.8-11.7 | | DISC<br>DISC | SP-137<br>SP-430 | CPS-137<br>CPS-137 | 06.10-11.7 | | DISC | SP-137 | CPS-137 | 06.10-11.7 | | | 06.10-11.7 | 5/8 | MC-T473 | MK-T206 | 06.10-11.7 | 3/4 | CC-T385 | CK-T216 |
| BDG－XZU538<br>(N04C－TH)<br>(N04C－TJ)<br>(N04C－UD)<br>(N04C－UE)<br><BKG－は08. 1～> | 06.10-11.7 | | | | 06.10-10.8<br>10.8-11.7 | | DISC<br>DISC | SP-137<br>SP-430 | CPS-137<br>CPS-137 | 06.10-11.7 | | DISC | SP-137 | CPS-137 | 06.10-11.7 | | | 06.10-11.7 | 5/8 | MC-T473 | MK-T206 | 06.10-11.7 | 3/4 | CC-T385 | CK-T216 |
| BDG－XZU548<br>(N04C－TJ)<br>(N04C－UE)<br><BKG－は08. 1～> | 06.10-11.7 | | | | 06.10-10.8<br>10.8-11.7 | | DISC<br>DISC | SP-137<br>SP-430 | CPS-137<br>CPS-137 | 06.10-11.7 | | DISC | SP-137 | CPS-137 | 06.10-11.7 | | | 06.10-11.7 | 5/8 | MC-T473 | MK-T206 | 06.10-11.7 | 3/4 | CC-T385 | CK-T216 |
| BDG－XZU554D<br>(N04C－TJ)<br>(N04C－UE)<br><BKG－は08. 1～> | 06.10-11.7 | | | | 06.10-10.8<br>10.8-11.7 | | DISC<br>DISC | SP-137<br>SP-430 | CPS-137<br>CPS-137 | 06.10-11.7 | | DISC | SP-137 | CPS-137 | 06.10-11.7 | | | 06.10-11.7 | 5/8 | MC-T473 | MK-T206 | 06.10-11.7 | 3/4 | CC-T385 | CK-T216 |
| BDG－XZU568 4WD | 06.10-11.7 | 1 3/16 | | TK-T448 | 06.10-11.7 | | DISC | MP-83 | CPM-81 | 06.10-11.7 | | DISC | C-721P | | 06.10-11.7 | | | 06.10-11.7 | 5/8 | MC-T473 | MK-T206 | 06.10-11.7 | 3/4 | CC-T385 | CK-T216 |

| Models | TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| DYNA, TOYOACE : BZU600 ser.(11.7-) | | | | | | | | | | | | | | | | | | | | | | | | | | |
| NBG－BZU600<br>(LPG車)<br>(1BZ－FPE) | フルジャストロー<br>2t・3t | 11.7- | | | | 11.7- | | DISC | MP-126 | CPM-81 | 11.7- | | DISC | C-721P | | 11.7- | (R)BH-T818<br>(L)BH-T819 | (R-1)BH-T820<br>(R-2)BH-T886<br>(L-1)BH-T820<br>(L-2)BH-T885 | 11.7- | 5/8 | MC-T473 | MK-T206 | 11.7- | 3/4 | CC-T388 | CK-T216 |
| | 高床　Wタイヤ<br>2t・3t | 11.7- | | | | 11.7- | | DISC | MP-126 | CPM-81 | 11.7- | | DISC | C-721P | | 11.7- | (R)BH-T818<br>(L)BH-T819 | (R-1)BH-T820<br>(R-2)<br>(L-1)BH-T820<br>(L-2) | 11.7- | 5/8 | MC-T473 | MK-T206 | 11.7- | 3/4 | CC-T388 | CK-T216 |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| DYNA, TOYOACE : TRC, TRU600 ser.(11.7-) | | | | | | | | | | | | | | | | | | | | | | | | | |
| ABG－TRC600<br>ABG－TRC600A<br>（2TR－FE）　フルジャストロー<br>（Sキャブ・Wキャブ） | 11.7- | | | | 11.7- | | DISC | MP-126 | CPM-81 | 11.7- | | DISC | C-721P | | 11.7- | (R)BH-T818<br>(L)BH-T819 | (R-1)BH-T820<br>(R-2)BH-T886<br>(L-1)BH-T820<br>(L-2)BH-T885 | 11.7- | 5/8 | MC-T473 | MK-T206 | 11.7- | 7/8 | CC-T387 | CK-T229 |
| ABG－TRU600<br>（2TR－FE） | 11.7- | | | | 11.7- | | DISC | MP-126 | CPM-81 | 11.7- | | DISC | C-721P | | 11.7- | (R)BH-T818<br>(L)BH-T819 | (R-1)BH-T820<br>(R-2)BH-T886<br>(L-2)BH-T885<br>(L-1)BH-T820 | 11.7- | 5/8 | MC-T473 | MK-T206 | 11.7- | 7/8 | CC-T387 | CK-T229 |

| Models | TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| DYNA, TOYOACE : XKC, XKU, XZC, XZU 600 ser.(11.7-) | | | | | | | | | | | | | | | | | | | | | | | | | | |
| SJG-XKC605・645<br>(N04C-UL) | フルジャストロー<br>Wタイヤ<br>2t | 11.7- | | | | 11.7- | | DISC | | CPS-137 | 11.7- | | DISC | | CPS-137 | 11.7- | (R)BH-T939<br>(L)BH-T940 | (R-1)BH-T820<br>(R-2)BH-T886<br>(L-1)BH-T820<br>(L-2)BH-T885 | 11.7- | | | | 11.7- | 7/8 | | CK-T225 |
| | 高床<br>Wタイヤ | 11.7- | | | | 11.7- | | DISC | | CPS-137 | 11.7- | | DISC | | CPS-137 | 11.7- | (R)BH-T939<br>(L)BH-T940 | (R-1)BH-T820<br>(R-2)<br>(L-1)BH-T820<br>(L-2) | 11.7- | | | | 11.7- | 7/8 | | CK-T225 |
| SJG-XKC655 | Wタイヤ | 11.7- | | | | 11.7- | | DISC | | CPS-137 | 11.7- | | DISC | | CPS-137 | 11.7- | (R)BH-T939<br>(L)BH-T940 | (R-1)BH-T820<br>(R-2)<br>(L-1)BH-T820<br>(L-2) | 11.7- | | | | 11.7- | 7/8 | | CK-T225 |
| SJG-XKU600 | フルジャストロー<br>Wタイヤ | 11.7- | | | | <2t><br>11.7-<br><3t><br>11.7- | | DISC<br><br>DISC | MP-126<br><br>MP-126 | CPM-81<br><br>CPM-81 | 11.7- | | DISC | C-721P | | 11.7- | (R)BH-T818<br>(L)BH-T819 | (R-1)BH-T820<br>(R-2)BH-T886<br>(L-1)BH-T820<br>(L-2)BH-T885 | 11.7- | | | | 11.7- | 7/8 | | CK-T225 |
| | 高床<br>Wタイヤ | 11.7- | | | | 11.7- | | DISC | MP-126 | CPM-81 | 11.7- | | DISC | C-721P | | 11.7- | (R)BH-T818<br>(L)BH-T819 | (R-1)BH-T820<br>(R-2)BH-T886<br>(L-1)BH-T820<br>(L-2)BH-T885 | 11.7- | | | | 11.7- | 7/8 | | CK-T225 |
| SJG-XKU650 | フルジャストロー<br>Wタイヤ<br>2t | 11.7- | | | | <2t><br>11.7-<br><3t><br>11.7- | | DISC<br><br>DISC | MP-126<br><br>MP-126 | CPM-81<br><br>CPM-81 | 11.7- | | DISC | C-721P | | 11.7- | (R)BH-T818<br>(L)BH-T819 | (R-1)BH-T820<br>(R-2)<br>(L-1)BH-T820<br>(L-2) | 11.7- | | | | 11.7- | 7/8 | | CK-T225 |
| | 高床<br>Wタイヤ | 11.7- | | | | 11.7- | | DISC | MP-126 | CPM-81 | 11.7- | | DISC | C-721P | | 11.7- | (R)BH-T818<br>(L)BH-T819 | (R-1)BH-T820<br>(R-2)<br>(L-1)BH-T820<br>(L-2) | 11.7- | | | | 11.7- | 7/8 | | CK-T225 |
| SJG-XKU600A | | 11.7- | | | | 11.7- | | DISC | MP-126 | CPM-81 | 11.7- | | DISC | C-721P | | 11.7- | (R)BH-T818<br>(L)BH-T819 | (R-1)BH-T820<br>(R-2)BH-T886<br>(L-1)BH-T820<br>(L-2)BH-T885 | 11.7- | | | | 11.7- | 7/8 | | CK-T225 |
| SJG-XKU640<br><TQG-は12．4～> | | 11.7- | | | | 11.7- | | DISC | MP-126 | CPM-81 | 11.7- | | DISC | C-721P | | 11.7- | (R)BH-T818<br>(L)BH-T819 | (R-1)BH-T820<br>(R-2)<br>(L-1)BH-T820<br>(L-2) | 11.7- | | | | 11.7- | 7/8 | | CK-T225 |
| SJG-XKU650 | フルジャストロー<br>Wタイヤ<br>2t | 11.7- | | | | <2t><br>11.7-<br><3t><br>11.7- | | DISC<br><br>DISC | MP-126<br><br>MP-126 | CPM-81<br><br>CPM-81 | 11.7- | | DISC | C-721P | | 11.7- | (R)BH-T818<br>(L)BH-T819 | (R-1)BH-T820<br>(R-2)<br>(L-1)BH-T820<br>(L-2) | 11.7- | | | | 11.7- | 7/8 | | CK-T225 |
| | 高床<br>Wタイヤ | 11.7- | | | | 11.7- | | DISC | MP-126 | CPM-81 | 11.7- | | DISC | C-721P | | 11.7- | (R)BH-T818<br>(L)BH-T819 | (R-1)BH-T820<br>(R-2)<br>(L-1)BH-T820<br>(L-2) | 11.7- | | | | 11.7- | 7/8 | | CK-T225 |
| SJG-XKU605<br>SJG-XKU645<br>(N04C-UL) | フルジャストロー<br>Wタイヤ | 11.7- | | | | <2t><br>11.7-<br><3t><br>11.7- | | DISC<br><br>DISC | MP-126<br><br>MP-126 | CPM-81<br><br>CPM-81 | 11.7- | | DISC | C-721P | | 11.7- | (R)BH-T939<br>(L)BH-T940 | (R-1)BH-T820<br>(R-2)BH-T886<br>(L-1)BH-T820<br>(L-2)BH-T885 | 11.7- | | | | 11.7- | 7/8 | | CK-T225 |
| | 高床<br>Wタイヤ | 11.7- | | | | 11.7- | | DISC | MP-126 | CPM-81 | 11.7- | | DISC | C-721P | | 11.7- | (R)BH-T939<br>(L)BH-T940 | (R-1)BH-T820<br>(R-2)BH-T886<br>(L-1)BH-T820<br>(L-2)BH-T885 | 11.7- | | | | 11.7- | 7/8 | | CK-T225 |
| SJG-XKU655 | フルジャストロー<br>Wタイヤ<br>2t | 11.7- | | | | 11.7- | | DISC | MP-126 | CPM-81 | 11.7- | | DISC | C-721P | | 11.7- | (R)BH-T939<br>(L)BH-T940 | (R-1)BH-T820<br>(R-2)<br>(L-1)BH-T820<br>(L-2) | 11.7- | | | | 11.7- | 7/8 | | CK-T225 |
| | 高床<br>Wタイヤ<br>2t | 11.7- | | | | 11.7- | | DISC | MP-126 | CPM-81 | 11.7- | | DISC | C-721P | | 11.7- | (R)BH-T939<br>(L)BH-T940 | (R-1)BH-T820<br>(R-2)<br>(L-1)BH-T820<br>(L-2) | 11.7- | | | | 11.7- | 7/8 | | CK-T225 |

| Models | TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| SKG−XZC600<br><TKG−は12．4〜> | フルジャストロー<br>Wタイヤ<br>ディスク車 | 11.7− | | | | 11.7− | | DISC | | CPS−137 | 11.7− | | DISC | | CPS−137 | 11.7− | (R)BH−T818<br>(L)BH−T819 | (R−1)BH−T820<br>(L−1)BH−T820<br>(R−2)BH−T886<br>(L−2)BH−T885 | 11.7− | 5/8 | MC−T473 | MK−T206 | 11.7− | 3/4 | CC−T385 | CK−T216 |
| | 高床　Sタイヤ<br>リヤドラム車 | 11.7− | | | | 11.7− | | DISC | MP−126 | CPM−81 | 11.7− | 1 1/8 | | WK−813 | CUP | 11.7− | (R)BH−T818<br>(L)BH−T819 | (R)BH−T839<br>(L)BH−T839 | 11.7− | 5/8 | MC−T473 | MK−T206 | 11.7− | 3/4 | CC−T385 | CK−T216 |
| SKG−XZC605・645<br>SKG−XZC605V<br>(N04C) | Wタイヤ<br>2t | 11.7− | | | | 11.7− | | DISC | | CPS−137 | 11.7− | | DISC | | CPS−137 | 11.7− | (R)BH−T939<br>(L)BH−T940 | (R−1)BH−T820<br>(L−1)BH−T820<br>(R−2)BH−T886<br>(L−2)BH−T885 | 11.7− | 5/8 | MC−T473 | MK−T206 | 11.7− | 3/4 | CC−T385 | CK−T216 |
| SKG−XZC610D<br>(N04C) | | 11.7− | | | | 11.7− | | DISC | | CPS−137 | 11.7−16.5<br>16.5− | | DISC<br>(R−1)WC−T791<br>(R−2)WC−T792<br>(L−1)WC−T793<br>(L−2)WC−T794 | WK−835 | CPS−137<br>CUP | 11.7− | (R)BH−T818<br>(L)BH−T819 | (R−1)BH−T874<br>(L−1)BH−T874<br>(R−2)<br>(L−2) | 11.7− | 5/8 | MC−T473 | MK−T206 | 11.7− | 3/4 | CC−T385 | CK−T216 |
| SKG−XZC630D<br>(N04C) | | 11.7− | | | | 11.7− | | DISC | | CPS−137 | 11.7−16.5<br>16.5− | | DISC<br>(R−1)WC−T791<br>(R−2)WC−T792<br>(L−1)WC−T793<br>(L−2)WC−T794 | WK−835 | CPS−137<br>CUP | 11.7− | (R)BH−T818<br>(L)BH−T819 | (R−1)BH−T933<br>(L−1)BH−T933<br>(R−2)<br>(L−2) | 11.7− | 5/8 | MC−T473 | MK−T206 | 11.7− | 3/4 | CC−T385 | CK−T216 |
| SKG−XZC655 | Wタイヤ<br>2t | 11.7− | | | | 11.7− | | DISC | | CPS−137 | 11.7− | | DISC | | CPS−137 | 11.7− | (R)BH−T939<br>(L)BH−T940 | (R−1)BH−T820<br>(L−1)BH−T820<br>(R−2)<br>(L−2) | 11.7− | 5/8 | MC−T473 | MK−T206 | 11.7− | 3/4 | CC−T385 | CK−T216 |
| SKG−XZC675<br>(N04C) | 4WD<br>Wタイヤ | 11.7− | | | | 11.7− | | DISC | MP−126 | CPM−81 | 11.7− | | DISC | C−721P | | <ﾀﾞﾝﾌﾟ><br>11.7−<br><br><br>11.7− | (R)<br>(L)<br><br><br>(R)<br>(L) | (R−1)BH−T874<br>(R−2)<br>(L−1)BH−T874<br>(L−2)<br>(R−1)BH−T820<br>(L−1)BH−T820<br>(R−2)BH−T886<br>(L−2)BH−T885 | 11.7− | 5/8 | MC−T473 | MK−T206 | 11.7− | 3/4 | CC−T385 | CK−T216 |
| SKG−XZU600<br><TKG−は12．4〜> | 木製フルジャストロー（MT）<br>2t・3t | 11.7− | | | | 11.7− | | DISC | MP−126 | CPM−81 | 11.7− | | DISC | C−721P | | 11.7− | (R)BH−T818<br>(L)BH−T819 | (R−1)BH−T820<br>(L−1)BH−T820<br>(R−2)BH−T886<br>(L−2)BH−T885 | 11.7− | 5/8 | MC−T473 | MK−T206 | 11.7− | 3/4 | CC−T385 | CK−T216 |
| | 除く木製フルジャストロー（MT）<br>3．5t・4t | 11.7− | | | | 11.7− | | DISC | C−617AP | CPC−617AB | 11.7− | | DISC | C−617AP | CPC−617AB | 11.7− | (R)<br>(L)BH−T884 | (R−1)BH−T820<br>(L−1)BH−T820<br>(R−2)BH−T887<br>(L−2)BH−T895 | 11.7− | 5/8 | MC−T473 | MK−T206 | 11.7− | 3/4 | CC−T385 | CK−T216 |
| | ダンプ | 11.7− | | | | 11.7− | | DISC | MP−126 | CPM−81 | 11.7−16.5<br>16.5− | | DISC | C−721P<br>WK−813 | CUP | 11.7− | (R)BH−T818<br>(L)BH−T819 | (R−1)BH−T820<br>(L−1)BH−T820<br>(R−2)BH−T886<br>(L−2)BH−T885 | 11.7− | 5/8 | MC−T473 | MK−T206 | 11.7− | 3/4 | CC−T385 | CK−T216 |
| SKG−XZU600A・D・H<br><TKG−は12．4〜> | | 11.7− | | | | 11.7− | | DISC | MP−126 | CPM−81 | 11.7− | | DISC | C−721P | | 11.7− | (R)BH−T818<br>(L)BH−T819 | (R−1)BH−T820<br>(L−1)BH−T820<br>(R−2)BH−T886<br>(L−2)BH−T885 | 11.7− | 5/8 | MC−T473 | MK−T206 | 11.7− | 3/4 | CC−T385 | CK−T216 |
| SKG−XZU600W<br><TKG−は12．4〜> | | 11.7− | | | | 11.7− | | DISC | C−617AP | CPC−617AB | 11.7− | | DISC | C−617AP | CPC−617AB | 11.7− | (R)<br>(L)BH−T884 | (R−1)BH−T820<br>(L−1)BH−T820<br>(R−2)BH−T887<br>(L−2)BH−T895 | 11.7− | 5/8 | MC−T473 | MK−T206 | 11.7− | 3/4 | CC−T385 | CK−T216 |
| TKG−XZU602W | | 17.5− | | | ｷｯﾄｾｯﾃｲﾅｼ | 17.5−− | | MD−319M | MP−126 | CPM−81 | 17.5− | | MD−349 | C−721P | | 17.5− | (R)BH−T818<br>(L)BH−T819 | (R−1)BH−T820<br>(L−1)BH−T820<br>(R−2)BH−T886<br>(L−2)BH−T885 | 17.5− | 5/8 | MC−T473 | MK−T206 | 17.5− | 3/4 | CC−T385 | CK−T216 |
| SKG−XZU605<br>(N04C) | フルジャストロー<br>Wタイヤ<br>（Sキャブ・Wキャブ） | 11.7− | | | | <2t><br>11.7−<br><3t><br>11.7− | | DISC<br><br>DISC | MP−126<br><br>MP−126 | CPM−81<br><br>CPM−81 | 11.7− | | DISC | C−721P | | 11.7− | (R)BH−T939<br>(L)BH−T940 | (R−1)BH−T820<br>(L−1)BH−T820<br>(R−2)BH−T886<br>(L−2)BH−T885 | 11.7− | 5/8 | MC−T473 | MK−T206 | 11.7− | 3/4 | CC−T385 | CK−T216 |
| | ジャストロー<br>Wタイヤ<br>2t | 11.7− | | | | 11.7− | | DISC | MP−126 | CPM−81 | 11.7− | | DISC | C−721P | | 11.7− | (R)BH−T939<br>(L)BH−T940 | (R−1)BH−T820<br>(L−1)BH−T820<br>(R−2)BH−T886<br>(L−2)BH−T885 | 11.7− | 5/8 | MC−T473 | MK−T206 | 11.7− | 3/4 | CC−T385 | CK−T216 |
| | 高床　Wタイヤ<br>2t・3t | 11.7− | | | | 11.7− | | DISC | MP−126 | CPM−81 | 11.7− | | DISC | C−721P | | 11.7− | (R)BH−T939<br>(L)BH−T940 | (R−1)BH−T820<br>(L−1)BH−T820<br>(R−2)BH−T886<br>(L−2)BH−T885 | 11.7− | 5/8 | MC−T473 | MK−T206 | 11.7− | 3/4 | CC−T385 | CK−T216 |

| Models | TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| SKG－XZU640・650<br>（N04C） | フルジャストロー<br>2t | 11.7- | | | | 11.7- | | DISC | MP-126 | CPM-81 | 11.7- | | DISC | C-721P | | 11.7- | (R)BH-T818<br>(L)BH-T819 | (R-1)BH-T820<br>(L-1)BH-T820<br>(R-2)BH-T886<br>(L-2)BH-T885 | 11.7- | 5/8 | MC-T473 | MK-T206 | 11.7- | 3/4 | CC-T385 | CK-T216 |
| | フルジャストロー<br>3t<br>高床　Wタイヤ<br>2t・3t | 11.7- | | | | 11.7- | | DISC | MP-126 | CPM-81 | 11.7- | | DISC | C-721P | | 11.7- | (R)BH-T818<br>(L)BH-T819 | (R-1)BH-T820<br>(L-1)BH-T820<br>(R-2)<br>(L-2) | 11.7- | 5/8 | MC-T473 | MK-T206 | 11.7- | 3/4 | CC-T385 | CK-T216 |
| | 高床　Wタイヤ<br>3．5t・4t | 11.7- | | | | 11.7- | | DISC | C-617AP | CPC-617AB | 11.7- | | DISC | C-617AP | CPC-617AB | 11.7- | (R)<br>(L)BH-T884 | (R-1)BH-T820<br>(L-1)BH-T820<br>(R-2)BH-T887<br>(L-2)BH-T895 | 11.7- | 5/8 | MC-T473 | MK-T206 | 11.7- | 3/4 | CC-T385 | CK-T216 |
| SKG－XZU645 | フルジャストロー<br>2t | 11.7- | | | | 11.7- | | DISC | MP-126 | CPM-81 | 11.7- | | DISC | C-721P | | 11.7- | (R)BH-T939<br>(L)BH-T940 | (R-1)BH-T820<br>(L-1)BH-T820<br>(R-2)BH-T886<br>(L-2)BH-T885 | 11.7- | 5/8 | MC-T473 | MK-T206 | 11.7- | 3/4 | CC-T385 | CK-T216 |
| SKG－XZU650W<br>＜TKG－は12．4～＞ | | 11.7- | | | | 11.7- | | DISC | C-617AP | CPC-617AB | 11.7- | | DISC | C-617AP | CPC-617AB | 11.7- | (R)$$90947-0<br>(L)BH-T884 | (R-1)BH-T820<br>(L-1)BH-T820<br>(R-2)BH-T887<br>(L-2)BH-T895 | 11.7- | 5/8 | MC-T473 | MK-T206 | 11.7- | 3/4 | CC-T385 | CK-T216 |
| | フルジャストロー<br>高床<br>3t | 11.7- | | | | 11.7- | | DISC | MP-126 | CPM-81 | 11.7- | | DISC | C-721P | $$47831-37030 | 11.7- | (R)BH-T939<br>(L)BH-T940 | (R-1)BH-T820<br>(L-1)BH-T820<br>(R-2)<br>(L-2) | 11.7- | 5/8 | MC-T473 | MK-T206 | 11.7- | 3/4 | CC-T385 | CK-T216 |
| SKG－XZU655 | フルジャストロー<br>2t | 11.7- | | | | 11.7- | | DISC | MP-126 | CPM-81 | 11.7- | | DISC | C-721P | | 11.7- | (R)BH-T939<br>(L)BH-T940 | (R-1)BH-T820<br>(L-1)BH-T820<br>(R-2)<br>(L-2) | 11.7- | 5/8 | MC-T473 | MK-T206 | 11.7- | 3/4 | CC-T385 | CK-T216 |
| | ジャストロー<br>高床<br>Wタイヤ<br>2t | 11.7- | | | | 11.7- | | DISC | MP-126 | CPM-81 | 11.7- | | DISC | C-721P | | 11.7- | (R)BH-T939<br>(L)BH-T940 | (R-1)BH-T820<br>(L-1)BH-T820<br>(R-2)<br>(L-2) | 11.7- | 5/8 | MC-T473 | MK-T206 | 11.7- | 3/4 | CC-T385 | CK-T216 |
| SKG－XZU610D<br>＜TKG－は12．4～＞ | | 11.7- | | | | 11.7- | | DISC | MP-126 | CPM-81 | 11.7-16.5<br>16.5- | | MD-349<br>(R-1)WC-T791<br>(R-2)WC-T792<br>(L-1)WC-T793<br>(L-2)WC-T794 | C-721P<br>WK-835 | CUP | 11.7- | (R)BH-T818<br>(L)BH-T819 | (R-1)BH-T874<br>(L-1)BH-T874<br>(R-2)<br>(L-2) | 11.7- | 5/8 | MC-T473 | MK-T206 | 11.7- | 3/4 | CC-T385 | CK-T216 |
| SKG－XZU620D・630D<br>＜TKG－は12．4～＞ | | 11.7- | | | | 11.7- | | DISC | MP-126 | CPM-81 | 11.7- | | DISC | C-721P | | 11.7- | (R)BH-T818<br>(L)BH-T819 | (R-1)BH-T816<br>(L-1)BH-T816<br>(R-2)<br>(L-2) | 11.7- | 5/8 | MC-T473 | MK-T206 | 11.7- | 3/4 | CC-T385 | CK-T216 |
| SKG－XZU610D・620D | | 11.7- | | | | 11.7- | | DISC | MP-126 | CPM-81 | 11.7- | | DISC | C-721P | | 11.7- | (R)BH-T818<br>(L)BH-T819 | (R-1)BH-T874<br>(L-1)BH-T874<br>(R-2)<br>(L-2) | 11.7- | 5/8 | MC-T473 | MK-T206 | 11.7- | 3/4 | CC-T385 | CK-T216 |
| SKG－XZU630D | ダンプ | 11.7- | | | | 11.7- | | DISC | MP-126 | CPM-81 | 11.7- | | DISC | C-721P | | 11.7- | (R)BH-T818<br>(L)BH-T819 | (R-1)BH-T816<br>(L-1)BH-T816<br>(R-2)<br>(L-2) | 11.7- | 5/8 | MC-T473 | MK-T206 | 11.7- | 3/4 | CC-T385 | CK-T216 |
| SKG－XZU675D | ダンプ | 11.7- | | | | 11.7- | | DISC | MP-126 | CPM-81 | 11.7- | | DISC | C-721P | | 11.7- | (R)<br>(L) | (R-1)BH-T874<br>(L-1)BH-T874<br>(R-2)<br>(L-2) | 11.7- | 5/8 | MC-T473 | MK-T206 | 11.7- | 3/4 | CC-T385 | CK-T216 |
| SKG－XZU675 | フルジャストロー　Wタイヤ<br>2t・3t<br>4WD | 11.7- | | | | 11.7- | | DISC | MP-126 | CPM-81 | 11.7- | | DISC | C-721P | | 11.7- | (R)<br>(L) | (R-1)BH-T820<br>(L-1)BH-T820<br>(R-2)BH-T886<br>(L-2)BH-T885 | 11.7- | 5/8 | MC-T473 | MK-T206 | 11.7- | 3/4 | CC-T385 | CK-T216 |
| SKG－XZU600H | 高床　Wタイヤ<br>3t | 11.7- | | | | 11.7- | | DISC | MP-126 | CPM-81 | 11.7- | | DISC | C-721P | | 11.7- | (R)BH-T818<br>(L)BH-T819 | (R-1)BH-T820<br>(L-1)BH-T820<br>(R-2)<br>(L-2) | 11.7- | 5/8 | MC-T473 | MK-T206 | 11.7- | 3/4 | CC-T385 | CK-T216 |
| SKG－XZU685・695 | Wタイヤ　　リアディスク車<br>（Sキャブ・Wキャブ）<br>4WD<br>2t・3t | 11.7- | | | | 11.7- | | DISC | MP-126 | CPM-81 | 11.7- | | DISC | C-721P | | 11.7- | (R)<br>(L) | (R-1)BH-T820<br>(L-1)BH-T820<br>(R-2)<br>(L-2) | 11.7- | 5/8 | MC-T473 | MK-T206 | 11.7- | 3/4 | CC-T385 | CK-T216 |
| | リアドラム車 | 11.7- | | | | 11.7- | | DISC | MP-126 | CPM-81 | 11.7- | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 11.7- | (C)<br>(R)<br>(L) | (要現車確認 リアホース2本使用)<br>(R)BH-T820<br>(L)BH-T820<br>(要現車確認 リアホース4本使用)<br>(R-1)BH-T820<br>(L-1)BH-T820<br>(R-2)<br>(L-2) | 11.7- | 5/8 | MC-T473 | MK-T206 | 11.7- | 3/4 | CC-T385 | CK-T216 |

| Models | TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| DYNA, TOYOACE : XKU, XZC, XZU 700 ser.(11.7-) | | | | | | | | | | | | | | | | | | | | | | | | | | |
| SJG-XKU700<br><TQG-は12．4～><br><TSG-は15．5～> | 3t･3．5t･4t | 11.7- | | | | 11.7- | | DISC | C-617AP | CPC-617AB | 11.7- | | DISC | C-617AP | CPC-617AB | 11.7- | (C)<br>(R)BH-T896<br>(L)BH-T897 | (R-1)BH-T816<br>(L-1)BH-T816<br>(R-2)BH-T887<br>(L-2)BH-T895 | 11.7- | | | | 11.7- | 7/8 | | CK-T225 |
| TSG-XKU702 | ハイブリッド | 17.11- | | | | 17.11- | | DISC | C-617AP | CPC-617AB | <塵芥車><br>19.5-<br><br><除<塵芥車><br>17.11- | | (R-1)<br>(R-2)<br>(L-1)<br>(L-2)<br><br>DISC | | | 11.7- | (C)<br>(R)BH-T896<br>(L)BH-T897 | (R-1)BH-T816<br>(L-1)BH-T816<br>(R-2)BH-T887<br>(L-2)BH-T895 | 11.7- | | | | 11.7- | 7/8 | | CK-T225 |
| SJG-XKU710<br>(N04C-UL)<br><TQG-は12．6～><br><TSG-は15．5～><br><2SG-は19．5～> | フルジャストロー Wタイヤ<br>2t | 11.7- | | | | 11.7- | | DISC | MP-126 | CPM-81 | 11.7- | | DISC | C-721P | | 11.7- | (R)BH-T812<br>(L)BH-T813 | (R-1)BH-T816<br>(R-2)<br>(L-1)BH-T816<br>(L-2) | 11.7- | | | | 11.7- | 7/8 | | CK-T225 |
| | フルジャストロー Wタイヤ<br>3t･3．5t | 11.7- | | | | 11.7- | | DISC | C-617AP | CPC-617AB | 11.7- | | DISC | C-617AP | CPC-617AB | 11.7- | (R)BH-T896<br>(L)BH-T897 | (R-1)BH-T816<br>(L-1)BH-T816<br>(R-2)BH-T887<br>(L-2)BH-T895 | 11.7- | | | | 11.7- | 7/8 | | CK-T225 |
| | 高床 Wタイヤ<br>2t | 11.7- | | | | 11.7- | | DISC | MP-126 | CPM-81 | 11.7- | | DISC | C-721P | | 11.7- | (R)BH-T812<br>(L)BH-T813 | (R-1)BH-T816<br>(L-1)BH-T816<br>(R-2)<br>(L-2) | 11.7- | | | | 11.7- | 7/8 | | CK-T225 |
| | 高床 Wタイヤ<br>3t･3．5t･4t | 11.7- | | | | 11.7- | | DISC | C-617AP | CPC-617AB | 11.7- | | DISC | C-617AP | CPC-617AB | 11.7- | (R)BH-T896<br>(L)BH-T897 | (R-1)BH-T816<br>(L-1)BH-T816<br>(R-2)BH-T887<br>(L-2)BH-T895 | 11.7- | | | | 11.7- | 7/8 | | CK-T225 |
| SJG-XKU720<br><TQG-は12．6～><br><TSG-は15．5～> | 2t | 11.7- | | | | 11.7- | | DISC | MP-126 | CPM-81 | 11.7- | | DISC | C-721P | | 11.7- | (R)BH-T812<br>(L)BH-T813 | (R-1)BH-T816<br>(L-1)BH-T816<br>(R-2)<br>(L-2) | 11.7- | | | | 11.7- | 7/8 | | CK-T225 |
| | 3t･3．5t･4t | 11.7- | | | | 11.7- | | DISC | C-617AP | CPC-617AB | 11.7- | | DISC | C-617AP | CPC-617AB | 11.7- | (R)BH-T896<br>(L)BH-T897 | (R-1)BH-T816<br>(L-1)BH-T816<br>(R-2)BH-T887<br>(L-2)BH-T895 | 11.7- | | | | 11.7- | 7/8 | | CK-T225 |
| SKG-XZC710<br>(N04C) | フルジャストロー<br>2t | 11.7- | | | | 11.7- | | DISC | MP-126 | CPM-81 | 11.7- | | DISC | C-721P | | 11.7- | (R)BH-T812<br>(L)BH-T813 | (R-1)BH-T816<br>(L-1)BH-T816<br>(R-2)<br>(L-2) | 11.7- | 5/8 | MC-T473 | MK-T206 | 11.7- | 3/4 | CC-T385 | CK-T216 |
| SDG･SKG-XZU700･710･720<br>SDG-XZU700A<br>SDG-XZU730<br>(N04C)<br><TDG-は12．4～><br><TKG-は12．4～> | フルジャストロー Wタイヤ<br>2t<br>(Sキャブ･Wキャブ) | 11.7- | | | | 11.7- | | DISC | MP-126 | CPM-81 | 11.7- | | DISC | C-721P | | 11.7- | (R)BH-T812<br>(L)BH-T813 | (R-1)BH-T816<br>(L-1)BH-T816<br>(R-2)<br>(L-2) | 11.7- | 5/8 | MC-T473 | MK-T206 | 11.7- | 3/4 | CC-T385 | CK-T216 |
| | フルジャストロー Wタイヤ<br>3t･3．5t | 11.7- | | | | 11.7- | | DISC | C-617AP | CPC-617AB | 11.7- | | DISC | C-617AP | CPC-617AB | 11.7- | (R)BH-T896<br>(L)BH-T897 | (R-1)BH-T816<br>(L-1)BH-T816<br>(R-2)BH-T887<br>(L-2)BH-T895 | 11.7- | 5/8 | MC-T473 | MK-T206 | 11.7- | 3/4 | CC-T385 | CK-T216 |
| | 高床 Wタイヤ<br>2t<br>(Sキャブ･Wキャブ) | 11.7- | | | | 11.7- | | DISC | MP-126 | CPM-81 | 11.7- | | DISC | C-721P | | 11.7- | (R)BH-T812<br>(L)BH-T813 | (R-1)BH-T816<br>(L-1)BH-T816<br>(R-2)<br>(L-2) | 11.7- | 5/8 | MC-T473 | MK-T206 | 11.7- | 3/4 | CC-T385 | CK-T216 |
| | 高床 Wタイヤ<br>3t･3．5t･4t | 11.7- | | | | 11.7- | | DISC | C-617AP | CPC-617AB | 11.7- | | DISC | C-617AP | CPC-617AB | 11.7- | (R)BH-T896<br>(L)BH-T897 | (R-1)BH-T816<br>(L-1)BH-T816<br>(R-2)BH-T887<br>(L-2)BH-T895 | 11.7- | 5/8 | MC-T473 | MK-T206 | 11.7- | 3/4 | CC-T385 | CK-T216 |
| SKG-XZU775<br><TKG-は12．4～> | 4WD | 11.7- | | | | 11.7- | | DISC | MP-126 | CPM-81 | 11.7- | | DISC | C-721P | | 11.7- | (R)<br>(L) | (R-1)BH-T820<br>(L-1)BH-T820<br>(R-2)<br>(L-2) | 11.7- | 5/8 | MC-T473 | MK-T206 | 11.7- | 3/4 | CC-T385 | CK-T216 |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| DYNA, TOYOACE : FB5B, FB4J | | | | | | | | | | | | | | | | | | | | | | | | | | |
| KC－FB4J<br>KC－FB5B<br>(J05C)<br>(15B) | CAD・CAT<br>GAT・GAV | 95.5-99.5 | 1 1/8 | | TK-T416 | 95.5-99.5<br><オートアジャスター付><br>95.5-99.5 | 1 3/16<br><br>1 3/16 | | WK-831<br><br>WK-832 | CUP<br><br>CUP | 95.5-99.5<br><オートアジャスター付><br>95.5-99.5 | 1 3/16<br><br>1 3/16 | | WK-833<br><br>WK-880 | CUP<br><br>CUP | 95.5-99.5 | | BH-4543 | 95.5-99.5 | 3/4 | | MK-R201 | | | (ブースター) | |
| | EAT・EAV | 95.5-99.5<br><-DF3・EF3・UF3・VF3><br>97.2-98.5<br>98.5-99.5 | 1 1/8<br><br>1 1/8<br>1 1/8 | | TK-T416<br><br>TK-T374<br>TK-T433 | 95.5-99.5<br><オートアジャスター付><br>95.5-99.5 | 1 3/16<br><br>1 3/16 | | WK-831<br><br>WK-832 | CUP<br><br>CUP | 95.5-99.5<br><オートアジャスター付><br>95.5-99.5 | 1 3/16<br><br>1 3/16 | | WK-833<br><br>WK-880 | CUP<br><br>CUP | 95.5-99.5<br><-DF3・EF3・UF3・VF3><br>97.2-99.5 | <br><br>BH-4563 | BH-4543<br><br>BH-4543 | 95.5-99.5<br><-DF3・EF3・UF3・VF3><br>97.2-99.5 | 3/4 | | MK-R201 | | | (ブースター) | |
| | GAK | 95.5-99.5 | 1 1/8 | | TK-T416 | 95.5-99.5<br><オートアジャスター付><br>95.5-99.5 | 1 3/16<br><br>1 3/16 | | WK-831<br><br>WK-832 | CUP<br><br>CUP | 95.5-99.5<br><オートアジャスター付><br>95.5-99.5 | 1 3/16<br><br>1 3/16 | | WK-833<br><br>WK-880 | CUP<br><br>CUP | 95.5-99.5 | BH-4563 | BH-4543 | 95.5-99.5 | 3/4 | | MK-R201 | | | (ブースター) | |

| Models | TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| COASTER : 10 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2000)<br>(2500ディーゼル) | RU18<br>JU18 | 69.2-72.1 | 1 1/4 | | MK-661 | 69.2-72.1 | 1 3/8 | (R-1)WC-5145<br>(R-2)WC-5235<br>(L-1)WC-5345<br>(L-2)WC-5435 | WK-085 | CUP | 69.2-72.1 | 1 3/8 | (R-1)WC-5535<br>(R-2)WC-5625<br>(L-1)WC-5725<br>(L-2)WC-5825 | WK-086 | CUP | 69.2-72.1 | BH-02576 | BH-31440 | 69.2-72.1 | 3/4 | | MK-41400 | 69.2-72.1 | 15 | CC-70098 | FC-31480-B |
| (2000)<br>(3000ディーゼル) | RU19<br>BU19 | 72.2-77.7 | 1 1/8 | | TK-9321 | 72.2-74.10 | 1 1/4 | (R-1)WC-5146<br>(R-2)WC-5237<br>(L-1)WC-5346<br>(L-2)WC-5436 | WK-100 | CUP | 72.2-74.10 | 1 1/4 | (R-1)WC-5536<br>(R-2)WC-5626<br>(L-1)WC-5726<br>(L-2)WC-5826 | WK-101 | CUP | 72.2-76.2<br>76.2-77.7 | BH-T681<br>BH-T681 | BH-44212<br>BH-36212 | 72.2-77.7 | 3/4 | MC-10097 | MK-41400 | <RU19><br>72.2-77.5<br>77.5-77.7<br><BU19><br>72.2-77.7 | 3/4<br>13/16<br>3/4 | CC-70099<br>CC-70115<br>CC-70101 | CK-41480<br>CK-3115<br>CK-41480 |
| | | | | | | 74.10-77.7 | 1 1/4 | (R-1)WC-5146<br>(R-2)WC-5237<br>(L-1)WC-5346<br>(L-2)WC-5436 | WK-410 | CUP | 74.10-77.7 | 1 1/4 | (R-1)WC-5536<br>(R-2)WC-5626<br>(L-1)WC-5726<br>(L-2)WC-5826 | WK-412 | CUP | | | | | | | | | | |
| (2200)<br>(2400) | RB11・12<br>RB13 | 77.8-82.4 | 1 | | TK-9388 | 77.8-82.4 | 1 1/4 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | (77.8-80.9)<br>WK-410<br>(80.9-82.4)<br>WK-544 | <br>CUP<br><br>CUP | 77.8-82.4 | 1 1/4 | (R-1)<br>(R-2)WC-56014<br>(L-1)<br>(L-2)WC-58014 | WK-412 | CUP | 77.8-80.8<br>80.8-82.4 | BH-T681<br>BH-95002 | BH-36212<br>BH-36212 | 77.8-82.4 | 5/8 | MC-10080 | MK-4300 | 77.8-81.5<br>81.5-82.4 | 13/16<br>13/16 | CC-70115<br>CC-70115 | CK-3115<br>CK-3128 |
| (3200ディーゼル) | BB10<br>BB11 | 77.8-82.4 | 1 | | TK-9388 | 77.8-82.4 | 1 1/4 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | (77.8-80.9)<br>WK-410<br>(80.9-82.4)<br>WK-544 | <br>CUP<br><br>CUP | 77.8-82.4 | 1 1/4 | (R-1)<br>(R-2)WC-56014<br>(L-1)<br>(L-2)WC-58014 | WK-412 | CUP | 77.8-80.8<br>80.8-82.4 | BH-T681<br>BH-95002 | BH-36212<br>BH-36212 | 77.8-82.4 | 5/8 | MC-10080 | MK-4300 | 77.8-81.5<br>81.5-82.4 | 13/16<br>13/16 | CC-70118<br>CC-70118 | CK-3115<br>CK-3128 |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| COASTER : 20, 30 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (2400) | M－RB20・26V | ドラム車 | 82.5-84.8 | 1 | | TK-9388 | 82.5-84.8 | 1 1/8 | | WK-589 | CUP | 82.5-85.10 | 1 1/8 | (R-1)WC-55012 | WK-413 | CUP | 82.5-93.1 | BH-02220 | BH-40012 | 82.5-84.8 | 5/8 | | MK-4300 | 82.5-84.8 | 13/16 | CC-70115 | CK-3128 |
| | T－RB20 | | 84.8-93.1 | 1 | | TK-9455 | 84.8-93.1 | 1 1/8 | | WK-634 | CUP | | | (R-2)WC-56012 | | | | | | 84.8-86.11 | 5/8 | | MK-4321 | 84.8-85.10 | 13/16 | CC-70161 | CK-3136 |
| | ＜Tは90．1～＞ | | | | | | | | | | | | | (L-1)WC-57012 | | | | | | 86.11-90.1 | 5/8 | | MK-4341 | 85.10-93.1 | 13/16 | CC-70189 | CK-3144 |
| | | | | | | | | | | | | | | (L-2)WC-58012 | | | | | | 90.1-93.1 | 5/8 | MC-T333 | MK-T214 | | | | |
| | | | | | | | | | | | 85.10-93.1 | 1 1/8 | | WK-413 | CUP | | | | | | | | | | | | |
| | | ディスク車 | 82.5-84.8 | 1 | | TK-9433 | 82.5-93.1 | 51.1 | DISC | MP-8 | | 82.5-85.10 | 1 1/8 | | WK-413 | CUP | 82.5-93.1 | (1)BH-02220 | BH-40012 | 82.5-84.8 | 5/8 | | MK-4300 | 82.5-84.8 | 13/16 | CC-70115 | CK-3128 |
| | | | 84.8-93.1 | 1 | | TK-9456 | | | | | | 85.10-93.1 | 1 1/8 | | WK-641 | CUP | | (2)BH-02434 | | 84.8-86.11 | 5/8 | | MK-4321 | 84.8-85.10 | 13/16 | CC-70161 | CK-3136 |
| | | | | | | | | | | | | | | | | | | | | 86.11-90.1 | 5/8 | | MK-4341 | 85.10-93.1 | 13/16 | CC-70189 | CK-3144 |
| | | | | | | | | | | | | | | | | | | | | 90.1-93.1 | 5/8 | MC-T333 | MK-T214 | | | | |
| (3400ディーゼル) | | | <BB2#> | | | | | | | | | | | | | | | | | | | | | | | |
| | K－BB20・30 | ドラム車 | 82.5-84.8 | 1 | | TK-9388 | 82.5-84.8 | 1 1/8 | | WK-589 | CUP | 82.5-85.10 | 1 1/8 | (R-1)WC-55012 | WK-413 | CUP | 82.5-93.1 | BH-02220 | BH-40012 | 82.5-84.8 | 5/8 | | MK-4300 | 82.5-84.8 | 13/16 | CC-70118 | CK-3128 |
| | N－BB21・31・26V・36V | | 84.8-93.1 | 1 | | TK-9455 | 84.8-93.1 | 1 1/8 | | WK-634 | CUP | | | (R-2)WC-56012 | | | | | | 84.8-86.11 | 5/8 | | MK-4321 | 84.8-85.10 | 13/16 | CC-70162 | CK-3136 |
| | U－BB21・31・26V | | <BB3#> | | | | | | | | | | | (L-1)WC-57012 | | | | | | 86.11-90.1 | 5/8 | | MK-4341 | 85.10-93.1 | 13/16 | CC-70178 | CK-3144 |
| | T－BB21・31・26V | | 82.5-84.8 | 1 | | TK-9388 | | | | | | | | (L-2)WC-58012 | | | | | | 90.1-93.1 | 5/8 | MC-10132 | MK-T207 | | | | |
| | ＜Tは90．1～＞ | | 84.8-85.10 | 1 | | TK-9455 | | | | | | 85.10-93.1 | 1 1/8 | | WK-413 | CUP | | | | | | | | | | | |
| | | | 85.10-93.1 | 1 1/16 | | TK-T015 | | | | | | | | | | | | | | | | | | | | | |
| | | | <BB2#> | | | | | | | | | | | | | | | | | | | | | | | |
| | | ディスク車 | 82.5-84.8 | 1 | | TK-9433 | 82.5-93.1 | 51.1 | DISC | MP-8 | | 82.5-85.10 | 1 1/8 | | WK-413 | CUP | 82.5-93.1 | (1)BH-02220 | BH-40012 | 82.5-84.8 | 5/8 | | MK-4300 | 82.5-84.8 | 13/16 | CC-70118 | CK-3128 |
| | | | 84.8-93.1 | 1 | | TK-9456 | | | | | | 85.10-93.1 | 1 1/8 | | WK-641 | CUP | | (2)BH-02434 | | 84.8-86.11 | 5/8 | | MK-4321 | 84.8-85.10 | 13/16 | CC-70162 | CK-3136 |
| | | | <BB3#> | | | | | | | | | | | | | | | | | 86.11-90.1 | 5/8 | | MK-4341 | 85.10-93.1 | 13/16 | CC-70178 | CK-3144 |
| | | | 82.5-84.8 | 1 | | TK-9433 | | | | | | | | | | | | | | 90.1-93.1 | 5/8 | | MK-T207 | | | | |
| | | | 84.8-85.10 | 1 | | TK-9456 | | | | | | | | | | | | | | | | | | | | | |
| | | | 85.10-93.1 | 1 1/16 | | TK-9453 | | | | | | | | | | | | | | | | | | | | | |
| (3700ディーゼル) | | ドラム車 | 88.8-93.1 | 1 | | TK-9455 | 88.8-93.1 | 1 1/8 | | WK-634 | CUP | 88.8-93.1 | 1 1/8 | | WK-413 | CUP | 88.8-93.1 | BH-02220 | BH-40012 | 88.8-90.1 | 5/8 | | MK-4341 | 88.8-93.1 | 3/4 | CC-70185 | CK-T218 |
| | U－BB23・24 | | | | | | ＜DXオートマチック＞ | | | | | ＜DXオートマチック＞ | | | | | | | | 90.1-93.1 | 5/8 | | MK-T207 | | | | |
| | | | | | | | 88.8-93.1 | 1 1/8 | | WK-639 | CUP | 88.8-93.1 | 1 1/8 | | WK-641 | CUP | | | | | | | | | | | |
| | | ディスク車 | 88.8-93.1 | 1 | | TK-9456 | 88.8-93.1 | 51.1 | DISC | MP-8 | | 88.8-93.1 | 1 1/8 | | WK-641 | CUP | 88.8-93.1 | (1)BH-02220 | BH-40012 | 88.8-90.1 | 5/8 | | MK-4341 | 88.8-93.1 | 3/4 | CC-70185 | CK-T218 |
| | | | | | | | | | | | | | | | | | | (2)BH-02434 | | 90.1-93.1 | 5/8 | | MK-T207 | | | | |
| | | | | | | | | | | | | | | | | | <BB24> | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | 88.8-93.1 | (1)BH-02220 | BH-T528 | | | | | | | | |
| | | | | | | | | | | | | | | | | | | (2)BH-02434 | | | | | | | | | |
| (4000ディーゼル) | | ドラム車 | 82.5-84.8 | 1 | | TK-9388 | 82.5-84.8 | 1 1/8 | | WK-589 | CUP | 82.5-84.8 | 1 1/8 | (R-1)WC-55012 | WK-413 | CUP | 82.5-90.1 | BH-02220 | BH-40012 | 82.5-84.8 | 5/8 | | MK-4300 | 82.5-84.8 | 3/4 | CC-70160 | CK-3117 |
| | N－HB30・36V | | 84.8-85.10 | 1 | | TK-9455 | 84.8-90.1 | 1 1/8 | | WK-634 | CUP | | | (R-2)WC-56012 | | | | | | 84.8-86.11 | 5/8 | | MK-4321 | 84.8-85.10 | 3/4 | CC-70166 | CK-3135 |
| | | | 85.10-90.1 | 1 1/16 | | TK-T015 | | | | | | | | (L-1)WC-57012 | | | | | | 86.11-90.1 | 5/8 | | MK-4341 | 85.10-90.1 | 3/4 | | CK-T218 |
| | | | | | | | | | | | | | | (L-2)WC-58012 | | | | | | | | | | | | | |
| | | | | | | | | | | | 84.8-90.1 | 1 1/8 | | WK-413 | CUP | | | | | | | | | | | | |
| | | ディスク車 | 82.5-84.8 | 1 | | TK-9433 | 82.5-90.1 | 51.1 | DISC | MP-8 | | 82.5-85.10 | 1 1/8 | | WK-413 | CUP | 82.5-90.1 | (1)BH-02220 | BH-40012 | 82.5-84.8 | 5/8 | | MK-4300 | 82.5-84.8 | 3/4 | CC-70160 | CK-3117 |
| | | | 84.8-85.10 | 1 | | TK-9456 | | | | | | 85.10-90.1 | 1 1/8 | | WK-641 | CUP | | (2)BH-02434 | | 84.8-86.11 | 5/8 | | MK-4321 | 84.8-85.10 | 3/4 | CC-70166 | CK-3135 |
| | | | 85.10-90.1 | 1 1/16 | | TK-9453 | | | | | | | | | | | | | | 86.11-90.1 | 5/8 | | MK-4341 | 85.10-90.1 | 3/4 | | CK-T218 |
| (4000ディーゼル) | | ドラム車 | 85.10-90.1 | 1 1/16 | | TK-T015 | 85.10-90.1 | 1 1/8 | | WK-634 | CUP | 85.10-90.1 | 1 1/8 | | WK-413 | CUP | 85.10-90.1 | BH-02220 | BH-40012 | 85.10-90.1 | 5/8 | MC-T280 | MK-4330 | 85.10-90.1 | 3/4 | | CK-T218 |
| | P－HB31・32 | | | | | | ＜DXオートマチック＞ | | | | | ＜DXオートマチック＞ | | | | | | | | | | | | | | | |
| | | | | | | | 85.10-90.1 | 1 1/8 | | WK-639 | CUP | 85.10-90.1 | 1 1/8 | | WK-641 | CUP | | | | | | | | | | | |
| | | ディスク車 | 85.10-90.1 | 1 1/16 | | TK-9453 | 85.10-90.1 | 51.1 | DISC | MP-8 | | 85.10-90.1 | 1 1/8 | | WK-641 | CUP | 85.10-90.1 | (1)BH-02220 | BH-40012 | 85.10-90.1 | 5/8 | MC-T280 | MK-4330 | 85.10-90.1 | 3/4 | | CK-T218 |
| | | | | | | | | | | | | | | | | | | (2)BH-02434 | | | | | | | | | |
| | | | | | | | | | | | | | | | | | <HB32> | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | 88.8-90.1 | (1)BH-02220 | BH-T528 | | | | | | | | |
| | | | | | | | | | | | | | | | | | | (2)BH-02434 | | | | | | | | | |
| (4200ディーゼル) | U－HZB30・36V | ドラム車 | 90.1-93.1 | 1 1/16 | | TK-T015 | 90.1-93.1 | 1 1/8 | | WK-634 | CUP | 90.1-93.1 | 1 1/8 | | WK-413 | CUP | 90.1-93.1 | BH-02220 | BH-40012 | 90.1-93.1 | 5/8 | | MK-T207 | 90.1-93.1 | 3/4 | | CK-T210 |
| | | ディスク車 | 90.1-93.1 | 1 1/16 | | TK-9453 | 90.1-93.1 | 51.1 | DISC | MP-8 | | 90.1-93.1 | 1 1/8 | | WK-641 | CUP | 90.1-93.1 | (1)BH-02220 | BH-40012 | 90.1-93.1 | 5/8 | | MK-T207 | 90.1-93.1 | 3/4 | | CK-T210 |
| | | | | | | | | | | | | | | | | | | (2)BH-02434 | | | | | | | | | |
| | U－HZB31 | | 90.1-93.1 | 1 1/16 | | TK-9453 | 90.1-93.1 | 51.1 | DISC | MP-8 | | 90.1-93.1 | 1 1/8 | | WK-641 | CUP | 90.1-93.1 | (1)BH-02220 | BH-T528 | 90.1-93.1 | 5/8 | | MK-T207 | 90.1-93.1 | 3/4 | | CK-T210 |
| | | | | | | | | | | | | | | | | | | (2)BH-02434 | | | | | | | | | |
| (4200ディーゼル) | | | 90.1-93.1 | 1 | | TK-9456 | 90.1-93.1 | 51.1 | DISC | MP-8 | | 90.1-93.1 | 1 1/8 | | WK-641 | CUP | 90.1-93.1 | (1)BH-02220 | BH-40012 | | | (オートマチック) | | | | | |
| | U－HDB20 | | | | | | | | | | | | | | | | | (2)BH-02434 | | | | | | | | | |
| | U－HDB30 | | 90.1-93.1 | 1 1/16 | | TK-9453 | 90.1-93.1 | 51.1 | DISC | MP-8 | | 90.1-93.1 | 1 1/8 | | WK-641 | CUP | 90.1-93.1 | (1)BH-02220 | BH-40012 | 90.1-93.1 | 5/8 | | MK-T207 | 90.1-93.1 | 3/4 | | CK-T210 |
| | | | | | | | | | | | | | | | | | | (2)BH-02434 | | | | | | | | | |
| | U－HDB31 | | 90.1-93.1 | 1 1/16 | | TK-9453 | 90.1-93.1 | 51.1 | DISC | MP-8 | | 90.1-93.1 | 1 1/8 | | WK-641 | CUP | 90.1-93.1 | (1)BH-02220 | BH-T528 | 90.1-93.1 | 5/8 | | MK-T207 | 90.1-93.1 | 3/4 | | CK-T210 |
| | | | | | | | | | | | | | | | | | | (2)BH-02434 | | | | | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| COASTER : 40, 50 ser. | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (3400ディーゼル) | ドラム車 | 93.1-95.5 | 1 1/16 | | TK-T353 | 93.1-99.7 | 1 1/8 | | WK-811 | CUP | 93.1-99.7 | 1 1/8 | | WK-812 | CUP | 93.1-99.7 | BH-T695 | BH-38312 | 93.1-99.7 | 5/8 | MC-T352 | MK-4351 | 93.1-99.7 | 13/16 | CC-70178 | CK-3144 |
| U－BB40・46V | | 95.5-99.7 | 1 1/16 | | TK-T373 | | | | | | | | | | | | | | | | | | | | | |
| ＜KC－は95．5～＞ | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | ディスク車 | 93.1-99.7 | 1 1/16 | | TK-T354 | 93.1-99.7 | 51.1 | DISC | MP-81 | CPM-81 | 93.1-99.7 | | | WK-813 | CUP | 93.1-99.7 | | BH-38312 | 93.1-99.7 | 5/8 | MC-T352 | MK-4351 | 93.1-99.7 | 13/16 | CC-70178 | CK-3144 |
| (4000ディーゼル) | | ＜ｱﾝﾁｽｷｯﾄﾞ付＞ | | | | 04.8-16.12 | | DISC | MP-81 | CPM-81 | 04.8-16.12 | 1 1/8 | | WK-813 | CUP | 04.8-16.12 | (R)BH-T910 | | 04.8-16.12 | 5/8 | | MK-T246 | 04.8-16.12 | 3/4 | CC-T385 | CK-T216 |
| PB－XZB40 | | 04.8-16.12 | 1 1/16 | | TK-T448 | ＜ｱﾝﾁｽｷｯﾄﾞ付＞ | | | | | | | | | | | (L)BH-T910 | | | | | | | | | | |
| ＜BDG－は07．8～＞ | | ＜ｱﾝﾁｽｷｯﾄﾞ無＞ | | | | 04.8-16.12 | 51.1 | DISC | MP-81 | CPM-81 | | | | | | ＜ｱﾝﾁｽｷｯﾄﾞ付＞ | | | | | | | | | | |
| ＜PDG－は07．8～＞ | | 04.8-16.12 | 1 1/16 | TD-T928 | | | | | | | | | | | | 04.8-16.12 | (R)BH-T910 | (R) | | | | | | | | |
| | | | | | | | | | | | | | | | | | (L)BH-T910 | (L) | | | | | | | | |
| PB－XZB46V | | 04.8- | | | | 04.8- | 51.1 | DISC | MP-81 | CPM-81 | 04.8- | 1 1/8 | | WK-813 | CUP | 04.8- | (R)BH-T910 | | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| ＜PDG－は07．8～＞ | | ＜ｱﾝﾁｽｷｯﾄﾞ付＞ | | | | ＜ｱﾝﾁｽｷｯﾄﾞ付＞ | | | | | | | | | | | (L)BH-T910 | | | | | | | | | |
| | | 04.8- | 1 3/16 | | TK-T448 | 04.8- | 51.1 | DISC | MP-81 | CPM-81 | | | | | | ＜ｱﾝﾁｽｷｯﾄﾞ付＞ | | | | | | | | | | |
| | | | | | | | | | | | | | | | | 04.8- | (R)BH-T910 | (R) | | | | | | | | |
| | | | | | | | | | | | | | | | | | (L)BH-T910 | (L) | | | | | | | | |
| PB－XZB50 | | 04.8-16.12 | 1 3/16 | | TK-T448 | 04.8-16.12 | 51.1 | DISC | MP-81 | CPM-81 | 04.8-16.12 | 1 1/8 | | WK-813 | CUP | 04.8-16.12 | (R)BH-T910 | | 04.8-16.12 | 5/8 | | MK-T246 | 04.8- | 3/4 | CC-T385 | CK-T216 |
| ＜BDG－は07．8～＞ | | | | | | ＜ｱﾝﾁｽｷｯﾄﾞ付＞ | | | | | | | | | | | (L)BH-T910 | | | | | | | | | |
| ＜PDG－は07．8～＞ | | | | | | 04.8-16.12 | 51.1 | DISC | MP-81 | CPM-81 | | | | | | ＜ｱﾝﾁｽｷｯﾄﾞ付＞ | | | | | | | | | | |
| | | | | | | | | | | | | | | | | 04.8-16.12 | (R)BH-T910 | (R) | | | | | | | | |
| | | | | | | | | | | | | | | | | | (L)BH-T910 | (L) | | | | | | | | |
| PB－XZB51 | | 04.8-16.12 | 1 3/16 | | TK-T448 | 04.8-16.12 | 51.1 | DISC | MP-81 | CPM-81 | 04.8-16.12 | 1 1/8 | | WK-813 | CUP | 04.8-16.12 | (R)BH-T910 | BH-T911 | 04.8-16.12 | 5/8 | | MK-T246 | 04.8- | 3/4 | CC-T385 | CK-T216 |
| ＜BDG－は07．8～＞ | | | | | | | | | | | | | | | | | (L)BH-T910 | | | | | | | | | |
| ＜PDG－は07．8～＞ | | | | | | | | | | | | | | | | ＜ｱﾝﾁｽｷｯﾄﾞ付＞ | | | | | | | | | | |
| | | | | | | | | | | | | | | | | 04.8-16.12 | (R)BH-T910 | (R) | | | | | | | | |
| | | | | | | | | | | | | | | | | | (L)BH-T910 | (L)BH-T911 | | | | | | | | |
| PB－XZB56V | | 04.8- | 1 3/16 | | TK-T448 | 04.8- | 51.1 | DISC | MP-81 | CPM-81 | 04.8- | 1 1/8 | | WK-813 | CUP | 04.8- | (R)BH-T910 | | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| ＜PDG－は07．8～＞ | | | | | | ＜ｱﾝﾁｽｷｯﾄﾞ付＞ | | | | | | | | | | | (L)BH-T910 | | | | | | | | | |
| | | | | | | 04.8- | 51.1 | DISC | MP-81 | CPM-81 | | | | | | ＜ｱﾝﾁｽｷｯﾄﾞ付＞ | | | | | | | | | | |
| | | | | | | | | | | | | | | | | 04.8- | (R)BH-T910 | (R) | | | | | | | | |
| | | | | | | | | | | | | | | | | | (L)BH-T910 | (L) | | | | | | | | |
| (4100ディーゼル) | リヤードラム車 | 95.12-99.7 | 1 1/8 | | TK-T374 | 95.12- | 54.4 | DISC | SP-265 | CPS-265 | 95.12- | 1 1/8 | | WK-813 | CUP | 95.12-96.10 | | | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| KC－BB55・58(4WD) | | 99.7- | 1 1/16 | TD-T928 | | | | | | | | | | | | 96.10- | | BH-40012 | | | | | | | | |
| ＜KK－は99．7～＞ | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | 四輪ディスク車 | 95.12-97.5 | 1 1/8 | | TK-T374 | 95.12-97.5 | 54.4 | DISC | SP-265 | CPS-265 | 95.12-97.5 | | DISC | SP-217 | CPS-217+CPS-217B | 95.12-97.5 | | | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (4100LPG) | LD－BZB40・50 | 02.3- | 1 3/16 | | TK-T448 | 02.3- | 51.1 | DISC | MP-81 | CPM-81 | 02.3- | 1 1/8 | | WK-813 | CUP | 02.3- | (R)BH-T910 | (R) | 02.3- | 5/8 | MC-T369 | MK-T246 | 02.3- | 3/4 | CC-T382 | CK-T216 |
| | | | | | | | | | | | | | | | | | (L)BH-T910 | (L) | | | | | | | | |
| (4200ディーゼル) | | 93.1-99.7 | 1 1/16 | | TK-T354 | 93.1- | 51.1 | DISC | MP-81 | CPM-81 | 93.1- | 1 1/8 | | WK-813 | CUP | 93.1-99.7 | | BH-38312 | 93.1- | 5/8 | MC-T369 | MK-T246 | 93.1- | 3/4 | | |
| U－HZB40・46V | | 99.7- | 1 1/16 | TD-T928 | | ＜ｱﾝﾁｽｷｯﾄﾞ付＞ | | | | | | | | | | 99.7- | (R)BH-T910 | | | | | | | | | |
| ＜KC－は95．5～＞ | | ＜ｱﾝﾁｽｷｯﾄﾞ付＞ | | | | 97.5-01.8 | 51.1 | DISC | MP-81 | CPM-81 | | | | | | | (L)BH-T910 | | | | | | | | | |
| ＜KK－は99．7～＞ | | 99.7- | 1 3/16 | | TK-T448 | 01.8 | 51.1 | DISC | MP-81 | CPM-81 | | | | | | ＜ｱﾝﾁｽｷｯﾄﾞ付＞ | | | | | | | | | | |
| | | | | | | | | | | | | | | | | 99.7- | (R)BH-T910 | (R) | | | | | | | | |
| | | | | | | | | | | | | | | | | | (L)BH-T910 | (L) | | | | | | | | |
| U－HZB41 | | 93.1-95.5 | 1 1/8 | | TK-T355 | 93.1- | 51.1 | DISC | MP-81 | CPM-81 | 93.1- | 1 1/8 | | WK-813 | CUP | 93.1-99.7 | (R) | BH-38312 | 93.1- | 5/8 | MC-T369 | MK-T246 | 93.1- | 3/4 | | |
| U－HDB51 | | 95.5-99.7 | 1 1/8 | | TK-T374 | ＜ｱﾝﾁｽｷｯﾄﾞ付＞ | | | | | | | | | | | (L) | | | | | | | | | |
| ＜KC－は95．5～＞ | | ＜ｱﾝﾁｽｷｯﾄﾞ付＞ | | | | 93.1- | 51.1 | DISC | MP-81 | CPM-81 | | | | | | ＜ｱﾝﾁｽｷｯﾄﾞ付＞ | | | | | | | | | | |
| ＜KK－は99．7～＞ | | 93.1-95.5 | 1 1/8 | | TK-T352 | | | | | | | | | | | 93.1-99.7 | | (R)BH-T656 | | | | | | | | |
| | | 95.5-99.7 | 1 1/8 | | TK-T375 | | | | | | | | | | | | | (L) | | | | | | | | |
| | | 99.7- | 1 3/16 | | TK-T448 | | | | | | | | | | | 99.7- | (R)BH-T910 | (R) | | | | | | | | |
| | | | | | | | | | | | | | | | | | (L)BH-T910 | (L)BH-T911 | | | | | | | | |
| U－HZB50・56V | | 93.1-95.5 | 1 1/8 | | TK-T355 | 93.1- | 51.1 | DISC | MP-81 | CPM-81 | 93.1- | 1 1/8 | | WK-813 | CUP | 93.1-99.7 | (R) | BH-38312 | 93.1- | 5/8 | MC-T369 | MK-T246 | 93.1- | 3/4 | | |
| U－HDB50 | | 95.5-99.7 | 1 1/8 | | TK-T374 | | | | | | | | | | | | (L) | | | | | | | | | |
| ＜KC－は95．5～＞ | | ＜ｱﾝﾁｽｷｯﾄﾞ付＞ | | | | | | | | | | | | | | ＜ｱﾝﾁｽｷｯﾄﾞ付＞ | | | | | | | | | | |
| ＜KK－は99．7～＞ | | 97.5-99.7 | 1 1/8 | | TK-T375 | | | | | | | | | | | 97.5-99.7 | (R) | BH-38312 | | | | | | | | |
| | | 99.7- | 1 3/16 | | TK-T448 | | | | | | | | | | | | (L) | | | | | | | | | |
| | | | | | | | | | | | | | | | | 99.7- | (R)BH-T910 | (R) | | | | | | | | |
| | | | | | | | | | | | | | | | | | (L)BH-T910 | (L) | | | | | | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| COASTER : 60, 70, 80 ser. | | | | | | | | | | | | | | | | | | | | | | | | | |
| (4000ディーゼル)<br>SDG－XZB60・70<br>SPG－XZB60・70<br>SKG－XZB60・60V・70・70V<br>＜2KG－は19．7～＞<br>＜2PG－は19．7～＞ | 17.1- | | | ｷｯﾄｾｯﾃｲﾅｼ | 17.1- | | DISC | MP-81 | CPM-81 | 17.1- | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 17.1- | (R)<br>(L) | (R)<br>(L) | 17.1- | 5/8 | | MK-T246 | 17.1- | 3/4 | CC-T385 | CK-T216 |
| 2KG－XZB80 | 19.8- | | | ｷｯﾄｾｯﾃｲﾅｼ | 19.8- | | DISC | MP-81 | CPM-81 | 19.8- | 1 1/8 | (R-1)<br>(R-2)<br>(L-1)<br>(L-2) | WK-813 | CUP | 19.8- | (R)<br>(L) | (R)<br>(L) | 19.8- | | (ｵｰﾄﾏﾁｯｸ) | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| MASSY DYNA : | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (QC) | QC10・12D・15 | 69.9-72.8 | 1 3/8 | | MK-4410 | 69.9-75.1 | 1 1/2 | (R-1) | | CUP | 69.9-75.1 | 1 3/8 | (R-1) | | CUP | 69.9-75.1 | BH-02115 | BH-02116 | 69.9-75.1 | 3/4 | | MK-41400 | 69.9-75.1 | 20 | | CK-312 |
| (FC) | FC10 | 72.8-75.1 | 1 3/8 | | MK-4411 | | | (R-2)<br>(L-1)<br>(L-2) | | | | | (R-2)<br>(L-1)<br>(L-2) | | | | | | | | | | | | | |
| (EC) | EC20・22・23 | 75.2-80.2 | 1 3/8 | | MK-4412 | 75.2-80.2 | 1 3/8 | (R-1) | WK-316 | CUP | 75.2-80.2 | 1 3/8 | (R-1) | WK-173 | CUP | 75.2-80.2 | BH-02299 | BH-02116 | 75.2-80.2 | 5/8 | | MK-4300 | 75.2-80.2 | 3/4 | | CK-313 |
| (FC) | FC22 | | | | | | | (R-2)<br>(L-1)<br>(L-2) | | | | | (R-2)<br>(L-1)<br>(L-2) | | | | | | | | | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TRUCK : | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (FA) | FA100・110・115・101 | 64-83.5 | 1 1/2 | | MK-4622 | 64-70.3 | 1 1/4 | WC-55010 | | CUP | 64-70.3 | 1 1/2 | FD-063 | | CUP | 64-70.3 | BH-47282 | BH-47283 | 64-77.4 | 3/4 | | RS-31400-M | 64-77.4 | 7/8 | | CK-3104 |
| (DA) | DA100・110・115・116 | | | | | 70.3-73.2 | 1 3/8 | (R-1)WC-51024 | | CUP | 70.3-83.5 | 1 1/2 | (R-1)WC-55019 | | CUP | 70.3-74.3 | BH-02130 | BH-02142 | 77.4-83.5 | 3/4 | | MK-4311 | 77.4-83.5 | 15/16 | | CK-3130 |
| | DA118・120・125 | | | | | 73.2-82.5 | 1 1/4 | (R-2)WC-51024 | | CUP | | | (R-2)WC-56019 | | | <ツースピード> | | | | | | | | | | |
| | | | | | | | | (L-1)WC-53024 | | | | | (L-1)WC-55019 | | | 74.4-75.1 | BH-02130 | BH-02227 | | | | | | | | |
| | | | | | | | | (L-2)WC-53024 | | | | | (L-2)WC-56019 | | | 75.1-77.4 | BH-02130 | BH-02142 | | | | | | | | |
| | | | | | | 82.5-83.5 | 1 1/4 | | | | | | | | | 77.4-83.5 | BH-02411 | BH-02142 | | | | | | | | |
| | | | | | | | | | | | | | | | | <シングルスピード> | | | | | | | | | | |
| | | | | | | | | | | | | | | | | 74.4-77.4 | BH-02130 | BH-02142 | | | | | | | | |
| | | | | | | | | | | | | | | | | 77.4-83.5 | BH-02411 | BH-02142 | | | | | | | | |
| | | | | | | | | | | | | | | | | <DA115,118> | | | | | | | | | | |
| | | | | | | | | | | | | | | | | 70.3-74.3 | BH-02141 | BH-02142 | | | | | | | | |
| | | | | | | | | | | | | | | | | 74.4-75.1 | BH-02141 | BH-02227 | | | | | | | | |
| | | | | | | | | | | | | | | | | 75.1-80.2 | BH-02141 | BH-02142 | | | | | | | | |
| (FC) | FC100 | 69.3-75.1 | 1 1/2 | | MK-4622 | 69.3-71.2 | 1 1/4 | WC-55010 | | CUP | 69.3-75.1 | 1 1/2 | | | CUP | 69.3-70.3 | BH-47282 | BH-47282 | 69.3-75.1 | 3/4 | | RS-31400-M | 69.3-75.1 | 7/8 | | CK-3104 |
| | | | | | | 71.2-75.1 | 1 1/4 | | | CUP | | | | | | 70.3-75.1 | BH-02149 | BH-02148 | | | | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| BUS : | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (FB)<br>(DB) | FB100<br>DB100・102・105 | 69.3-70.2 | 1 1/2 | | MK-4622 | 69.3-70.2 | 1 1/4 | WC-55010 | | CUP | 69.3-70.2 | 1 1/2 | FD-063 | | CUP | 69.3-70.2 | BH-47282 | BH-47282 | 69.3-70.2 | 3/4 | | RS-31400-M | 69.3-70.2 | 7/8 | | CK-3104 |
| (DR) | DR10・11・15 | 69.3-77.3 | 45.5 | | MK-5622 | 69.3-70.3<br>70.3-73.2<br>73.2-77.3 | 1 1/4<br>1 3/8<br>1 1/4 | WC-55010<br>(R-1)WC-51024<br>(R-2)WC-51024<br>(L-1)WC-53024<br>(L-2)WC-53024 | | CUP<br>CUP<br>CUP | 69.3-70.3<br>70.3-77.3 | 1 1/2<br>1 1/2 | FD-063<br>(R-1)WC-55019<br>(R-2)WC-56019<br>(L-1)WC-55019<br>(L-2)WC-56019 | | CUP<br>CUP | 69.3-70.3<br>70.3-77.3 | BH-47282<br>BH-02140 | BH-47283<br>BH-02142 | 69.3-77.3 | 1 | | | 69.3-77.3 | 7/8 | | CK-3104 |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LEXUS : CT | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| CT200h (1800) | DAA－ZWA10 | ハイブリット | 10.12- | | | ｷｯﾄｾｯﾃｲﾅｼ | 10.12- | | DISC | MP-118 | | 10.12- | | DISC | TP-111 | | 10.12- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LEXUS : ES | | | | | | | | | | | | | | | | | | | | | | | | | |
| ES300h 6AA－AXZH10 ハイブリット (2500) | 18.10- | | | ｷｯﾄｾｯﾃｲﾅｼ | 18.10- | | DISC | | CPM-116 | 18.10- | | DISC | | | 18.10- | (R) (L) | (R) (L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LEXUS : GS, GS F | | | | | | | | | | | | | | | | | | | | | | | | | | |
| GS200系<br>(2000) | DBA－ARL10 | 16.9- | | | キットセッテイナシ | 16.9- | | DISC | SP-112 | CPS-112 | 16.9- | | DISC | SP-461 | CPM-117 | 16.9- | (R)<br>(L) | (R)<br>(L) | | | | | | | | |
| GS250系<br>(2500) | DBA－GRL11 | 11.12- | 7/8 | TD-T931 | キットセッテイナシ | 11.12-<br><F SPORT><br>11.12- | | DISC<br><br>DISC | SP-112<br><br>SP-112 | CPS-112<br><br>CPS-112 | 11.12- | | DISC | SP-461 | CPM-117 | 11.12- | | | | | | | | | | |
| GS300系 | DAA－AWL10 | 13.10- | | | キットセッテイナシ | 13.10- | | DISC | SP-112 | CPS-112 | 13.10- | | DISC | SP-461 | CPM-117 | 13.10- | (R)<br>(L) | (R)<br>(L) | | | | | | | | |
| GS350系<br>(3500) | DBA－GRL10 | 11.12- | 7/8 | TD-T931 | キットセッテイナシ | 11.12-<br><F SPORT><br>11.12- | | DISC<br><br>DISC | SP-112<br><br>SP-112 | CPS-112 | 11.12- | | DISC | SP-461 | CPM-117 | 11.12- | | | | | | | | | | |
| | DBA－GRL12 | 15.10- | | | キットセッテイナシ | <除く18インチホイール><br>15.10-<br><18インチホイール><br>15.10- | | DISC<br><br>DISC | SP-112<br><br>SP-112 | CPS-112 | 15.10- | | DISC | SP-461 | CPM-117 | <除く18インチホイール><br>15.10-<br><br><18インチホイール><br>15.10- | (R)<br>(L)<br><br>(R)<br>(L) | (R)<br>(L)<br><br>(R)<br>(L) | | | | | | | | |
| | DBA－GRL15 | 11.12- | 7/8 | TD-T931 | キットセッテイナシ | 11.12-<br><F SPORT><br>11.12- | | DISC<br><br>DISC | SP-112<br><br>SP-112 | CPS-112<br><br>CPS-112 | 11.12- | | DISC | SP-461 | CPM-117 | 11.12- | | | | | | | | | | |
| | DBA－GRL16 | 15.10- | | | キットセッテイナシ | 15.10- | | DISC | SP-112 | CPS-112 | 15.10- | | DISC | SP-461 | CPM-117 | 15.10- | (R)<br>(L) | (R)<br>(L) | | | | | | | | |
| | DBA－GRS191 | 05.8-12.1 | | | | 05.8-12.1 | | DISC | SP-112 | CPS-112 | 05.8-05.11<br>05.11-12.1 | | DISC<br>DISC | SP-412 | CPS-412<br>CPS-412 | 05.8-12.1 | (R)<br>(L) | (R)<br>(L) | 05.8-12.1 | | | | 05.8-12.1 | | | |
| | DBA－GRS196（4WD） | 05.8-12.1 | | | | 05.8-12.1 | | DISC | SP-112 | CPS-112 | 05.8-12.1 | | DISC | SP-412 | CPS-412 | 05.8-12.1 | (R)<br>(L) | (R)<br>(L) | 05.8-12.1 | | | | 05.8-12.1 | | | |
| GS450系<br>(3500) | DAA－GWL10 | 12.1- | | | | 12.1-<br><F SPORT><br>12.1- | | DISC<br><br>DISC | SP-112<br><br>SP-112 | CPS-112 | 12.1- | | DISC | SP-461 | CPM-117 | 12.1- | | | | | | | | | | |
| | DAA－GWS191（ハイブリット） | 06.2- | | | | 06.2- | | DISC | SP-112 | CPS-112 | 06.2- | | DISC | SP-412 | CPS-412 | 06.2- | (R)<br>(L) | (R)<br>(L) | 06.2- | | | | 06.2- | | | |
| GS430系<br>(4300) | DBA－UZS190 | 05.8- | | | | 05.8- | | DISC | SP-112 | CPS-112 | 05.8- | | DISC | SP-412 | CPS-412 | 05.8- | (R)<br>(L) | (R)<br>(L) | 05.8- | | | | 05.8- | | | |
| GS460系<br>(4600) | DBA－URS190 | 07.10- | | | | 07.10- | | DISC | SP-112 | CPS-112 | 07.10- | | DISC | SP-412 | CPS-412 | 07.10- | (R)<br>(L) | (R)<br>(L) | 07.10- | | | | 07.10- | | | |
| GS F<br>(5000) | DBA－URL10 | 15.10- | | | キットセッテイナシ | 15.10- | | DISC | | | 15.10- | | DISC | | | 15.10- | | | | | (オートマチック) | | | | | |

| Models TOYOTA | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LEXUS : HS | | | | | | | | | | | | | | | | | | | | | | | | | |
| HS250h<br>(2400) DAA－ANF10 | 09.7- | | | | 09.7- | | DISC | MP-114 | CPM-106 | 09.7-09.12<br>10.1-11.7<br>11.7- | | DISC<br>DISC<br>DISC | SP-134<br>SP-134<br>SP-422 | CPS-134<br>CPS-134<br>CPS-134 | 09.7- | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LEXUS : IS | | | | | | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | ＜AK NS542＞ | | | | | | | | | | | | | | | |
| IS 300<br>(2000) | 3BA－ASE30 2WD<br>＜3BA－は20. 9～＞ | 15.8- | | | ｷｯﾄｾｯﾃｲﾅｼ | 15.8- | | DISC | SP-112 | CPS-112 | 15.8-20.9<br>20.9- | | DISC<br>DISC | SP-461 | CPM-117 | 15.8- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | | | | | | | | | | | ＜NBK D6361＞<br>20.9-22.6 | | DISC | | | | | | | | | | | | |
| | | | | | | | | | | | ＜NBK D6360＞<br>22.6- | | DISC | | | | | | | | | | | | |
| (2500) | DAA－AVE30 ﾊｲﾌﾞﾘｯﾄ<br>＜6AA－は20. 9～＞ | 13.5- | | | ｷｯﾄｾｯﾃｲﾅｼ | 13.5-<br><F SPORT><br>13.5- | | DISC<br><br>DISC | MP-112<br><br>MP-121 | CPM-112<br><br>CPM-116 | 13.5- | | DISC | SP-461 | CPM-117 | 13.5- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | DBA－GSE20 | 05.9- | | | ｷｯﾄｾｯﾃｲﾅｼ | 05.9- | | DISC | MP-121 | CPM-116 | 05.9-05.11<br>05.11- | | DISC<br>DISC | SP-417<br>MP-113 | CPM-113<br>CPM-113 | 05.9-07.1<br><br>07.1- | (R)<br>(L)<br>(R)<br>(L) | (R)<br>(L)<br>(R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | DBA－GSE20 ｺﾝﾊﾞｰﾁﾌﾞﾙ | 09.4- | | | ｷｯﾄｾｯﾃｲﾅｼ | 09.4- | | DISC | MP-121 | CPM-116 | 09.4-13.8<br>13.8- | | DISC<br>DISC | MP-113<br>SP-462 | CPM-113<br>CPM-113 | 09.4- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | DBA－GSE25 4WD | 05.9- | | | ｷｯﾄｾｯﾃｲﾅｼ | 05.9- | | DISC | MP-121 | CPM-116 | 05.9-05.11<br>05.11- | | DISC<br>DISC | SP-417<br>MP-113 | | 05.9-07.1<br><br>07.1- | (R)<br>(L)<br>(R)<br>(L) | (R)<br>(L)<br>(R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | DBA－GSE30 | 13.5- | 7/8 | TD-T931 | ｷｯﾄｾｯﾃｲﾅｼ | 13.5-<br><F SPORT><br>13.5- | | DISC<br><br>DISC | MP-112<br><br>MP-121 | CPM-112<br><br>CPM-116 | 13.5- | | DISC | SP-461 | CPM-117 | 13.5- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | DBA－GSE35 4WD | 13.5- | 7/8 | TD-T931 | ｷｯﾄｾｯﾃｲﾅｼ | 13.5- | | DISC | MP-112 | CPM-112 | 13.5- | | DISC | SP-461 | CPM-117 | 13.5- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | | | | | | ＜NBK D6893H＞ | | | | | ＜AK NS542＞ | | | | | | | | | | | | | | | | |
| (3000) | DAA－AVE35 ﾊｲﾌﾞﾘｯﾄ<br>＜6AA－は20. 9～＞ | 15.8- | | | ｷｯﾄｾｯﾃｲﾅｼ | 15.8-20.9<br>20.9-<br><br>20.9- | | DISC<br>DISC<br><br>DISC | MP-112<br>SP-112<br><br>SP-112 | CPM-112<br>CPS-112<br><br>CPS-112 | 15.8-20.9<br>20.9-<br><br>20.9-22.6<br>＜NBK D6360＞<br>22.6- | | DISC<br>DISC<br><br>DISC<br><br>DISC | SP-461 | CPM-117 | 15.8- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | | | | | | ＜ADVICS VC115＞ | | | | | ＜NBK D6361＞ | | | | | | | | | | | | | | | | |
| (3500) | DBA－GSE21 | 05.9- | | | ｷｯﾄｾｯﾃｲﾅｼ | 05.9- | | DISC | SP-112 | CPS-112 | 05.9-05.11<br>05.11-13.8<br>13.8- | | DISC<br>DISC<br>DISC | SP-412 | CPS-412<br>CPS-412<br>CPS-412 | 05.9-07.1<br><br>07.1- | (R)<br>(L)<br>(R)<br>(L) | (R)<br>(L)<br>(R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | | | | | | | | | | | ＜AK NS542＞ | | | | | | | | | | | | | | | | |
| | DBA－GSE31<br>＜3BA－は20. 9～＞ | 13.5-16.10<br>16.10- | 7/8 | TD-T931 | ｷｯﾄｾｯﾃｲﾅｼ | 13.5-<br><F SPORT><br>13.5- | | DISC<br><br>DISC | SP-112<br><br>SP-112 | CPS-112<br><br>CPS-112 | 13.5-20.9<br>20.9-<br><br>20.9-22.6<br>＜NBK D6360＞<br>22.6- | | DISC<br>DISC<br><br>DISC<br><br>DISC | SP-461 | CPM-117 | 13.5- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | | | | | | | | | | | ＜NBK D6361＞ | | | | | | | | | | | | | | | | |
| (5000) | DBA－USE20 | 07.12-14.8 | | | ｷｯﾄｾｯﾃｲﾅｼ | 07.12-14.8 | | DISC | | | 07.12-14.8 | | DISC | | | 07.12-14.8 | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LEXUS : LS | | | | | | | | | | | | | | | | | | | | | | | | | | |
| LS460系<br>(4600) | DBA－USF40<br>DBA－USF41 | 06.8-17.10 | | | | ADVICS PV565H<br>06.8-17.10<br>TEXTAR T4146<br>06.8-09.9<br>PAGID 4668<br>09.9-12.9<br>12.9-17.10 | | DISC<br><br>DISC<br><br>DISC<br>DISC | SP-400<br><br>SP-400 | CPS-400<br><br>CPS-400<br><br>CPS-400 | ADVICS PV565H<br>06.8-17.10<br>TEXTAR T4146<br>06.8-17.10 | | DISC<br><br>DISC | SP-402<br><br>SP-402 | CPS-402<br><br>CPS-402 | 06.8-17.10 | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| | DBA－USF45 4WD<br>DBA－USF46 4WD | 08.9-17.10 | | | | 08.9-17.10 | | DISC | SP-400 | CPS-400 | 08.9-17.10 | | DISC | SP-402 | CPS-402 | 08.9-17.10 | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| LS500系<br>(3500) | DAA－GVF50 | 17.10- | | | キットセッテイナシ | <除くF SPORT><br>17.10-<br><F SPORT><br>17.10- | | DISC<br><br>DISC | | | <除くF SPORT><br>17.10-<br><F SPORT><br>17.10- | | DISC<br><br>DISC | | | 17.10- | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| | DAA－GVF55 4WD | 17.10- | | | キットセッテイナシ | <除くF SPORT><br>17.10-<br><F SPORT><br>17.10- | | DISC<br><br>DISC | | | <除くF SPORT><br>17.10-<br><F SPORT><br>17.10- | | DISC<br><br>DISC | | | 17.10- | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| | DBA－VXFA50 | <ブリクラッシュセーフティシステム無><br>17.12-<br><ブリクラッシュセーフティシステム付><br>17.12-<br><F SPORT><br>17.12- | | | キットセッテイナシ<br><br>キットセッテイナシ<br><br>キットセッテイナシ | <除くF SPORT><br>17.10-<br><F SPORT><br>17.10- | | DISC<br><br>DISC | | | <除くF SPORT><br>17.10-<br><F SPORT><br>17.10- | | DISC<br><br>DISC | | | 17.10- | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| | DBA－VXFA55 4WD | <ブリクラッシュセーフティシステム無><br>17.12-<br><ブリクラッシュセーフティシステム付><br>17.12-<br><F SPORT><br>17.12- | | | キットセッテイナシ<br><br>キットセッテイナシ<br><br>キットセッテイナシ | <除くF SPORT><br>17.10-<br><F SPORT><br>17.10- | | DISC<br><br>DISC | | | <除くF SPORT><br>17.10-<br><F SPORT><br>17.10- | | DISC<br><br>DISC | | | 17.10- | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| LS600系<br>(5000) | DAA－UVF45 4WDハイブリット<br>DAA－UVF46 4WDハイブリット | 07.5-17.10 | | | | ADVICS PV565H<br>07.5-17.10<br>TEXTAR T4146<br>07.5-17.10 | | DISC<br><br>DISC | SP-400<br><br>SP-400 | CPS-400<br><br>CPS-400 | ADVICS PV565H<br>07.5-17.10<br>TEXTAR T4146<br>07.5-17.10 | | DISC<br><br>DISC | SP-402<br><br>SP-402 | CPS-402<br><br>CPS-402 | 07.5-17.10 | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LEXUS : LX | | | | | | | | | | | | | | | | | | | | | | | | | | |
| LX600<br>(3500) | 3BA－VJA310W(4WD) | 21.12- | | | ｷｯﾄｾｯﾃｲﾅｼ | 21.12- | | DISC | SP-139 | | 21.12- | | DISC | | | 21.12- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| LX570<br>(5700) | DBA－URJ201W(4WD) | 15.9- | | | | 15.9- | | DISC | SP-139 | CPS-139 | 15.9- | | DISC | MP-128 | CPM-128 | 15.9- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LEXUS : NX | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| NX200t<br>(2000) | DBA－AGZ10<br>DBA－AGZ15(4WD) | | 14.7- | | | | 14.7- | | DISC | C-815P | | 14.7- | | DISC | | | 14.7- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| NX350<br>(2400) | 5BA－TAZA25(4WD) | | 21.11- | 15/16 | TD-T948 | ｷｯﾄｾｯﾃｲﾅｼ | 21.11- | | DISC | C-815P | | 21.11- | | DISC | | | 21.11- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| NX300h<br>(2500) | DAA－AYZ10<br>DAA－AYZ15(4WD) | | 14.7- | | | | 14.7- | | DISC | C-815P | | 14.7- | | DISC | | | 14.7- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| NX250･NX350h<br>(2500) | 5BA－AAZA20<br>5BA－AAZA25(4WD) | | 21.11- | 15/16 | TD-T948 | ｷｯﾄｾｯﾃｲﾅｼ | 21.11- | | DISC | C-815P | | 21.11- | | DISC | | | 21.11- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | 6AA－AAZH20<br>6AA－AAZH25(4WD) | ﾊｲﾌﾞﾘｯﾄ<br>ﾊｲﾌﾞﾘｯﾄ | 21.11- | 15/16 | TD-T948 | ｷｯﾄｾｯﾃｲﾅｼ | 21.11- | | DISC | C-815P | | 21.11- | | DISC | | | 21.11- | (R)<br>(L) | (R)<br>(L) | | | (電気式無段階変速機) | | | | | |
| NX450h＋<br>(2500) | 6LA－AAZH26(4WD) | | 21.11- | 15/16 | TD-T948 | ｷｯﾄｾｯﾃｲﾅｼ | 21.11- | | DISC | | | 21.11- | | DISC | | | 21.11- | (R)<br>(L) | (R)<br>(L) | | | (電気式無段階変速機) | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LEXUS : RC, RC F | | | | | | | | | | | | | | | | | | | | | | | | | | |
| RC200t・300<br>(2000) | DBA－ASC10 | 15.10- | | | キットセッテイナシ | <除く18インチホイール><br>15.10-<br><18インチホイール><br>15.10- | | DISC<br>DISC | SP-112<br>SP-112 | CPS-112 | 15.10- | | DISC | SP-461 | CPM-117 | 15.10- | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| RC300h<br>(2500) | DBA－AVC10 | 14.9- | | | キットセッテイナシ | 14.9- | | DISC | SP-112 | CPS-112 | 14.9- | | DISC | SP-461 | CPM-117 | 14.9- | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| RC350<br>(3500) | DBA－GSC10 | 14.9- | 7/8 | TD-T931 | キットセッテイナシ | <除く18インチホイール><br>14.9-<br><18インチホイール><br>14.9-<br><F SPORT><br>14.9- | | DISC<br>DISC<br>DISC | SP-112<br>SP-112<br>SP-112 | CPS-112 | 14.9- | | DISC | SP-461 | CPM-117 | 14.9- | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |
| RC F<br>(5000) | DBA－USC10 | 14.9- | | | キットセッテイナシ | 14.9- | | DISC | | (R)<br>(L) | 14.9- | | DISC | | (R)<br>(L) | 14.9- | (R)<br>(L) | (R)<br>(L) | | | (オートマチック) | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LEXUS : RX | | | | | | | | | | | | | | | | | | | | | | | | | | |
| RX200t・RX300<br>(2000) | DBA－AGL20W<br>DBA－AGL25W<br>＜3BA－は20．7～＞ | 15.9- | | | ｷｯﾄｾｯﾃｲﾅｲ | 15.9- | | DISC | C-815P | | 15.9- | | DISC | | | 15.9- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| RX270h<br>(2700) | DBA－AGL10 | 10.8-15.9 | | | ｷｯﾄｾｯﾃｲﾅｲ | 10.8-15.9 | | DISC | C-815P | | 10.8-15.9 | | DISC | | | 10.8-15.9 | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| RX350・RX350h<br>(2400) | 5BA－TALA10 | 22.11- | | | ｷｯﾄｾｯﾃｲﾅｲ | 22.11- | | DISC | | | 22.11- | | DISC | SP-482 | | 22.11- | (R) | (R) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | 5BA－TALA15 | 22.11- | | | ｷｯﾄｾｯﾃｲﾅｲ | 22.11- | | DISC | | | 22.11- | | DISC | SP-482 | | 22.11- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| (2500) | 6AA－AALH10 | 22.11- | | | ｷｯﾄｾｯﾃｲﾅｲ | 22.11- | | DISC | | | 22.11- | | DISC | SP-482 | | 22.11- | (R)<br>(L) | (R)<br>(L) | | | (電気式無段階変速機) | | | | | |
| | 6AA－AALH15 | 22.11- | | | ｷｯﾄｾｯﾃｲﾅｲ | 22.11- | | DISC | | | 22.11- | | DISC | SP-482 | | 22.11- | (R)<br>(L) | (R)<br>(L) | | | (電気式無段階変速機) | | | | | |
| (3500) | DBA－GGL10W<br>DBA－GGL15W(4WD)<br>DBA－GGL16W(4WD) | 08.12-15.9 | | | ｷｯﾄｾｯﾃｲﾅｲ | 08.12-15.9 | | DISC | C-815P | | 08.12-15.9 | | DISC | | | 08.12-15.9 | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| RX450・RX450h・RX450hL・RX450h＋<br>RX450h＋<br>(2500) | 6LA－AALH16 PHEV | 22.11- | | | ｷｯﾄｾｯﾃｲﾅｲ | 22.11- | | DISC | | | 22.11- | | DISC | SP-482 | | 22.11- | (R)<br>(L) | (R)<br>(L) | | | (電気式無段階変速機) | | | | | |
| (3500) | DAA－GYL10W(ﾊｲﾌﾞﾘｯﾄ)<br>DAA－GYL15W(4WD・ﾊｲﾌﾞﾘｯﾄ)<br>DAA－GYL16W(4WD・ﾊｲﾌﾞﾘｯﾄ) | 08.12-15.9 | | | ｷｯﾄｾｯﾃｲﾅｲ | 08.12-15.9 | | DISC | C-815P | | 08.12-15.9 | | DISC | | | 08.12-15.9 | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | DAA－GYL20W(ﾊｲﾌﾞﾘｯﾄ)<br>DAA－GYL25W(4WD・ﾊｲﾌﾞﾘｯﾄ)<br>＜6AA－は20．7～＞ | 15.9- | | | ｷｯﾄｾｯﾃｲﾅｲ | 15.9- | | DISC | C-815P | | 15.9- | | DISC | | | 15.9- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | DAA－GYL26W(4WD・ﾊｲﾌﾞﾘｯﾄ)<br>＜6AA－は20．7～＞ | 17.12- | | | ｷｯﾄｾｯﾃｲﾅｲ | 17.12- | | DISC | C-815P | | 17.12- | | DISC | | | 17.12- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| RX500h<br>(2400) | 5AA－TALH17 HEV | 22.11- | | | ｷｯﾄｾｯﾃｲﾅｲ | 22.11- | | DISC | | | 22.11- | | DISC | SP-482 | | 22.11- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |

| Models TOYOTA | | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LEXUS : SC | | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (4300) | DBA－UZZ40 | | 05.8- | | | | 05.8- | | DISC | MP-77 | CPM-77 | 05.8- | | DISC | MP-80 | | 05.8- | (R)BH-T753<br>(L)BH-T753 | (R)<br>(L) | 05.8- | | (オートマチック) | | 05.8- | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LEXUS : UX | | | | | | | | | | | | | | | | | | | | | | | | | | |
| UX200 (2000) | 6AA－MZAA10 | 18.10- | | | ｾｯﾃｲﾅｼ | 18.10- | | DISC | | CPM-116 | 18.10- | | DISC | | | 18.10- | (R) (L) | (R) (L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| UX250h (2000) | 6AA－MZAH10･15 | 18.10- | | | ｾｯﾃｲﾅｼ | 18.10- | | DISC | | CPM-116 | 18.10- | | DISC | | | 18.10- | (R) (L) | (R) (L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |

| Models TOYOTA | | Brake Master Year | Cyl. Dia. | Brake Master Assy | Brake Master Kit | Front Wheel Year | Cyl. Dia. | Front Wheel Assy | Front Wheel Kit | Front Wheel Cup Caliper Piston | Rear Wheel Year | Cyl. Dia. | Rear Wheel Assy | Rear Wheel Kit | Rear Wheel Cup Caliper Piston | Brake Hose Year | Brake Hose (Front) | Brake Hose (Rear) | Clutch Master Year | Cyl. Dia. | Clutch Master Assy | Clutch Master Kit | Clutch Operating Year | Cyl. Dia. | Cluch Operating Assy | Cluch Operating Kit |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| LEXUS : LBX | | | | | | | | | | | | | | | | | | | | | | | | | | |
| (1500) | 6AA－MAYH10 | 23.12- | | | ｾｯﾃｲﾅｼ | 23.12- | | DISC | | | 23.12- | | DISC | SP-502 | | 23.12- | (R)<br>(L) | (R)<br>(L) | | | (電気式無段階変速機) | | | | | |
| | 6AA－MAYH15 | 23.12- | | | ｾｯﾃｲﾅｼ | 23.12- | | DISC | | | 23.12- | | MD-462 | SP-502 | | 23.12- | (R)<br>(L) | (R)<br>(L) | | | (電気式無段階変速機) | | | | | |
| (1600) | 4BA－GAYA16 AT | 24.8- | 7/8 | TD-T942 | ｾｯﾃｲﾅｼ | 24.8- | | DISC | | | 24.8- | | MD-462 | SP-502 | | 24.8- | (R)<br>(L) | (R)<br>(L) | | | (ｵｰﾄﾏﾁｯｸ) | | | | | |
| | MT | 24.8- | 7/8 | TD-T943 | ｾｯﾃｲﾅｼ | 24.8- | | DISC | | | 24.8- | | DISC | | | 24.8- | | | 24.8- | | | ｾｯﾃｲﾅｼ | 24.8- | | | ｾｯﾃｲﾅｼ |